

Release Notes for SPA100 Series Analog Telephone Adapters Firmware Version 1.3.5p(XU)

First Published: May 5, 2015

Revised: July 7, 2015

These Release Notes provide information about SPA100 Series Analog Telephone Adapters firmware version 1.3.5p(XU).

IMPORTANT:

As with any firmware release, read these release notes before upgrading the firmware. Cisco also recommends backing up the configuration before any firmware upgrade.

Changes in Firmware Version 1.3.5p(XU) From 1.3.5(XU)

For the Cisco SPA112 and SPA122, the following changes are made in firmware version 1.3.5p(XU):

• Silicon Labs changed the voltage component supplier from Telefunken to Vanguard. The new Silicon Labs chip requires a small code change.

Hardware Change

To identify the new Silicon Labs chip, the new box HID format 1.1.x is used.

Software Changes

The following software changes apply to firmware release 1.3.5p(XU):

- Support for the new Silicon Labs chip is added, but compatibility with the old Silicon Labs chip is preserved.
- A downgrade limit applies to the new Silicon Labs chip.



Hardware and Firmware Compatibility Matrix

SPA112/SPA122 (3 types of devices)	SN Range	1.3.5p(XU), 1.3.5p, 1.3.2p	1.3.5(XU), 1.3.5, 1.3.4, 1.3.3, 1.3.2n	1.3.2(XU), 1.3.2 or earlier
Device 1	SPA112	Yes	No	No
(128MB Flash + New Si3217x-B SLIC)	CCQ18400001 to CCQ1841033K			
	After CCQ18500DAE			
	SPA122			
	• CCQ1834031U to CCQ1834037D			
	• CCQ1847066I to CCQ184707YA			
	CCQ184902ED to CCQ184904UL			
	• CCQ184904UM to CCQ184904Y3			
	• CCQ184904Y4 to CCQ184904Y5			
	After CCQ185001YH			
Device 2	SPA112	Yes	Yes	No
(128MB Flash +	CCQ175106J3 to CCQ175106OM			
Old Si3217x-B SLIC)	CCQ181607OO to CCQ181607U7			
	• CCQ18240E34 to CCQ18400000			
	• CCQ1841033L to CCQ18500D9K			
	SPA122			
	• CCQ174602V3 to CCQ1746030M			
	CCQ181502B7 to CCQ181502GQ			
	• CCQ182002W3 to CCQ1834031T			
	• CCQ1834037E to CCQ18470660			
	• CCQ184707YB to CCQ184902EC			
	CCQ184904UM to CCQ184904UL			
	• CCQ184904Y4 to CCQ184904Y3			
	• CCQ184904Y6 to CCQ185001YH			
Device 3	SPA112: Before CCQ182002W2	Yes	Yes	Yes
(32MB Flash + Old Si3217x-B SLIC)	SPA122: Before CCQ181805KR			



Do not upgrade any device to an unsupported firmware version as detailed in the Hardware and Firmware Compatibility Matrix table.



1.3.2p is identical to 1.3.2 and additionally supports 128MB flash and new SLIC.

1.3.2n is based on 1.3.2; both have the same feature set, except that 1.3.2n supports 128MB flash while 1.3.2 does not.

1.3.5p is based on 1.3.5; both have the same feature set, except that 1.3.5p supports new SLIC while 1.3.5 does not.

1.3.5p(XU), 1.3.5(XU), 1.3.2(XU): SRTP functionality has been removed, and it cannot be configured or provisioned in firmware versions that are designated with XU in the filename.



New devices have a label that reads S/W: Must use 1.3.5(004p) or later.

Resolved Issues

Firmware version 1.3.5p(XU) is based on 1.3.5(XU), and it resolves the following defect.

Tracking Number	Description	
CSCur99365	SPA100 and SPA232D require new firmware 1.3.2p 1.3.5p to support new SLIC.	

Known Issues



Note

1.3.5p(XU) and 1.3.5(XU) Known Issues are the same as stated in the 1.3.5 Release Notes.

Upgrade the Firmware

Follow these instructions to upgrade the phone adapter.

- **Step 1** Download the latest firmware by using the Firmware link on the following web page: www.cisco.com/go/smallbizvoicegateways
- **Step 2** Access the adapter Configuration Utility in one of the following two ways:
 - **a.** If the adapter is SPA112, connect one analog phone to its FXS port, press **** to access IVR, enter 110 to get SPA112 WAN IP address. Then, launch a web browser, and enter WAN IP address.
 - **b.** If the adapter is SPA122 or SPA232D, connect one PC to its LAN port. Then, launch a web browser, and enter the LAN IP address. The default value is 192.168.15.1.
- **Step 3** Log in to the Configuration Utility.
- Step 4 Click Administration in the menu bar, and then click Firmware Upgrade in the navigation tree.

- **Step 5** Click **Browse** and select the location of the upgrade file that you downloaded.
- **Step 6** Click the **Upgrade** button to upgrade the firmware.



Upgrading the firmware may take several minutes. Until the process is complete, DO NOT turn off the power, press the hardware reset button, or click the Back button in your current browser.

Behavior During Times of Network Congestion

Anything that degrades network performance can affect voice and video quality, and in some cases, can cause a call to drop. Sources of network degradation can include, but are not limited to, the following activities:

- · Administrative tasks, such as an internal port scan or security scan
- Attacks that occur on your network, such as a Denial of Service attack

To reduce or eliminate any adverse effects to the devices, schedule administrative network tasks during a time when the devices are not being used or exclude the devices from testing.

Related Information

Support			
Cisco Small Business Support Community	www.cisco.com/go/smallbizsupport		
Online Technical Support and Documentation (Login Required)	www.cisco.com/support		
Cisco Small Business Support and Resources	www.cisco.com/go/smallbizhelp		
Downloads and Documentation			
Firmware	www.cisco.com/go/software		
Cisco Small Business Voice Gateways Documentation	www.cisco.com/go/smallbizvoicegateways		
Open Source Documentation	Follow the Software Downloads, Release and General Information link at www.cisco.com/go/smallbizvoicegateways, then search in the Release Notes area.		
Cisco Small Business			
Cisco Partner Central for Small Business (Partner Login Required)	www.cisco.com/web/partners/sell/smb		
Cisco Small Business Home	www.cisco.com/smb		

Documentation, Service Requests, and Additional Information

For information on obtaining documentation, submitting a service request, and gathering additional information, see the monthly *What's New in Cisco Product Documentation*, which also lists all new and revised Cisco technical documentation, at:

http://www.cisco.com/c/en/us/td/docs/general/whatsnew/whatsnew.html

Subscribe to the *What's New in Cisco Product Documentation* as a Really Simple Syndication (RSS) feed and set content to be delivered directly to your desktop using a reader application. The RSS feeds are a free service and Cisco currently supports RSS Version 2.0.

entation, Ser	vice Requests, and Additional Information
	Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a l
	Cisco trademarks, go to this URL: www.cisco.com/go/trademarks . Third-party trademarks mentioned are the property of their respective ow use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)