

Release Notes for SPA100 Series Analog Telephone Adapters Firmware Version 1.3.2n

Firmware Released: October 10, 2014

Last Updated: July 18, 2015

These Release Notes provide information about SPA100 Series Analog Telephone Adapters firmware version 1.3.2n.

IMPORTANT

As with any firmware release, read these release notes before upgrading the firmware. Cisco also recommends backing up the configuration before any firmware upgrade.

Changes in Firmware Version1.3.2n from 1.3.2

• 1.3.2n release has the same feature set as 1.3.2 with the exception of support for 128MB flash.



Hardware and Software Compatibility Matrix

SPA112/SPA122 (3 types of devices)	SN Range	1.3.5p(XU), 1.3.5p, 1.3.2p	1.3.5(XU), 1.3.5, 1.3.4, 1.3.3, 1.3.2n	1.3.2(XU), 1.3.2 or earlier
Device 1	SPA112	Yes	No	No
(128MB Flash + New Si3217x-B SLIC)	• CCQ18400001 to CCQ1841033K			
	After CCQ18500DAE			
	SPA122			
	• CCQ1834031U to CCQ1834037D			
	• CCQ1847066I to CCQ184707YA			
	• CCQ184902ED to CCQ184904UL			
	• CCQ184904UM to CCQ184904Y3			
	• CCQ184904Y4 to CCQ184904Y5			
	After CCQ185001YH			
Device 2	SPA112	Yes	Yes	No
(128MB Flash + Old Si3217x-B SLIC)	• CCQ175106J3 to CCQ175106OM			
	• CCQ181607OO to CCQ181607U7			
	• CCQ18240E34 to CCQ18400000			
	• CCQ1841033L to CCQ18500D9K			
	SPA122			
	• CCQ174602V3 to CCQ1746030M			
	• CCQ181502B7 to CCQ181502GQ			
	• CCQ182002W3 to CCQ1834031T			
	• CCQ1834037E to CCQ18470660			
	• CCQ184707YB to CCQ184902EC			
	• CCQ184904UM to CCQ184904UL			
	• CCQ184904Y4 to CCQ184904Y3			
	• CCQ184904Y6 to CCQ185001YH			
Device 3	SPA112 : Before CCQ182002W2	Yes	Yes	Yes
(32MB Flash + Old Si3217x-B SLIC)	SPA122: Before CCQ181805KR			



Note

Do not upgrade any device to an unsupported firmware version as detailed in the Hardware and Firmware Compatibility Matrix table.



New devices have a label that reads S/W: Must use 1.3.5(004p) or later.



- 1.3.2p is identical to 1.3.2 and additionally supports 128MB flash and new SLIC.
- 1.3.2n is based on 1.3.2; both have the same feature set, except that 1.3.2n supports 128MB flash while 1.3.2 does not.
- 1.3.5p is based on 1.3.5; both have the same feature set, except that 1.3.5p supports new SLIC while 1.3.5 does not.
- 1.3.5p(XU), 1.3.5(XU), 1.3.2(XU): SRTP functionality has been removed, and it cannot be configured or provisioned in firmware versions that are designated with XU in the filename.

Resolved Issues

The 1.3.2 release is not compatible with 128MB. For a fix, refer to the following table.

Tracking Number	Description
CSCur18483	1.3.2 release not compatible with 128MB flash

Upgrade the Firmware

Follow these instructions to upgrade the phone adapter.

- Step 1 Download the latest firmware by using the Firmware link on the following web page: www.cisco.com/go/smallbizvoicegateways
- **Step 2** Launch a web browser, and enter the LAN IP addresses of the phone adapter.
- **Step 3** Log in to the Configuration Utility.
- Step 4 Click Administration in the menu bar, and then click Firmware Upgrade in the navigation tree.
- **Step 5** Click **Browse** and select the location of the upgrade file that you downloaded.
- **Step 6** Click the **Upgrade** button to upgrade the firmware.



Upgrading the firmware may take several minutes. Until the process is complete, DO NOT turn off the power, press the hardware reset button, or click the Back button in your current browser.

Behavior During Times of Network Congestion

Anything that degrades network performance can affect voice and video quality, and in some cases, can cause a call to drop. Sources of network degradation can include, but are not limited to, the following activities:

Administrative tasks, such as an internal port scan or security scan

Attacks that occur on your network, such as a Denial of Service attack

To reduce or eliminate any adverse effects to the devices, schedule administrative network tasks during a time when the devices are not being used or exclude the devices from testing.

Related Information

Support		
Cisco Small Business Support Community	www.cisco.com/go/smallbizsupport	
Online Technical Support and Documentation (Login Required)	www.cisco.com/support	
Cisco Small Business Support and Resources	www.cisco.com/go/smallbizhelp	
Downloads and Documentation		
Firmware	www.cisco.com/go/software	
Cisco Small Business Voice Gateways Documentation	www.cisco.com/go/smallbizvoicegateways	
Open Source Documentation	Follow the Release Notes link at www.cisco.com/go/smallbizvoicegateways	
Cisco Small Business		
Cisco Partner Central for Small Business (Partner Login Required)	www.cisco.com/web/partners/sell/smb	
Cisco Small Business Home	www.cisco.com/smb	

Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see *What's New in Cisco Product Documentation* at: http://www.cisco.com/c/en/us/td/docs/general/whatsnew/whatsnew.html.

Subscribe to *What's New in Cisco Product Documentation*, which lists all new and revised Cisco technical documentation as an RSS feed and delivers content directly to your desktop using a reader application. The RSS feeds are a free service.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2013 Cisco Systems, Inc. All rights reserved.

78-21259-01