



Release Notes for Cisco ASR 901 Series Aggregation Services Router for Cisco IOS Release 15.4(2)S2

Published Date: October 2014

This release notes is for the Cisco ASR 901 Series Aggregation Services Router for Cisco IOS Release 15.4(2)S2 and contains the following sections:

- [Introduction, page 1](#)
- [System Specifications and Memory Details, page 2](#)
- [New and Changed Information, page 3](#)
- [Supported Hardware, page 4](#)
- [Caveats, page 6](#)
- [Troubleshooting, page 15](#)
- [Related Documentation, page 15](#)
- [Services and Support, page 16](#)

Introduction

The Cisco ASR 901 Series Aggregation Services Router is a cell-site access platform specifically designed to aggregate and transport mixed-generation radio access network (RAN) traffic. The router is used at the cell site edge as a part of a 2G, 3G, or 4G RAN.

The Cisco ASR 901 router helps enable a variety of RAN solutions by extending IP connectivity to devices using Global System for Mobile Communications (GSM), General Packet Radio Service (GPRS), Node Bs using High Speed Packet Access (HSPA) or Long Term Evolution (LTE), base transceiver stations (BTSs) using Enhanced Data Rates for GSM Evolution (EDGE), Code Division Multiple Access (CDMA), CDMA-2000, EVDO, or WiMAX, and other cell-site equipment.

It transparently and efficiently transports cell-site voice, data, and signaling traffic over IP using traditional T1 and E1 circuits, as well as alternative backhaul networks such as Carrier Ethernet and DSL, Ethernet in the First Mile (EFM), and WiMAX. It also supports standards-based Internet



Engineering Task Force (IETF) Internet protocols over the RAN transport network, including those standardized at the Third-Generation Partnership Project (3GPP) for IP RAN transport. Custom designed for the cell site, the Cisco ASR 901 router features a small form factor, extended operating temperature, and cell-site DC input voltages.

[Table 1](#) lists the Cisco ASR 901 1G Router model versions.

Table 1 Cisco ASR 901 1G Router Models

Power Source	TDM + Ethernet Version	Ethernet Version
DC Power	<ul style="list-style-type: none"> A901-12C-FT-D A901-4C-FT-D 	<ul style="list-style-type: none"> A901-12C-F-D A901-4C-F-D
AC Power	<ul style="list-style-type: none"> none 	<ul style="list-style-type: none"> none

[Table 2](#) lists the Cisco ASR 901 10G Router model versions.

Table 2 Cisco ASR 901 10G Router Models

Power Source	TDM + Ethernet Version	Ethernet Version
DC Power	<ul style="list-style-type: none"> A901-6CZ-FT-D 	<ul style="list-style-type: none"> A901-6CZ-F-D A901-6CZ-FS-D
AC Power	<ul style="list-style-type: none"> A901-6CZ-FT-A 	<ul style="list-style-type: none"> A901-6CZ-F-A A901-6CZ-FS-A



Note

Some of the Cisco ASR 901 models have port based licensing. For more details, see the [Licensing](#) chapter in Cisco ASR 901 Series Aggregation Services Router Software Configuration Guide.

System Specifications and Memory Details

[Table 3](#) lists the supported system configurations and memory details for the Cisco ASR 901 Router:

Table 3 Cisco IOS Release 15.4(2)S2 Memory Details

Platform	Software Image	Flash Memory	DRAM Memory	Runs From
Cisco ASR 901 Series Aggregation Services Router TDM version	asr901-universalk9-mz	128 MB	512 MB	RAM
Cisco ASR 901 Series Aggregation Services Router, Ethernet version	asr901-universalk9-mz	128 MB	512 MB	RAM
Cisco ASR 901 Series Aggregation Services Router, IPsec enabled Ethernet version	asr901sec-universalk9.mz	256 MB	512 MB	RAM

Determining the Software Version

To determine the image and version of Cisco IOS software running on your Cisco ASR 901 router, log in to the router and enter the **show version** command in the EXEC mode:

The following example shows output from Cisco ASR 901 router that supports normal IOS software.

```
Router> show version
```

```
Cisco IOS Software, 901 Software (ASR901-UNIVERSALK9-M), Version 15.4(2)S2, RELEASE SOFTWARE (fc1)
```

```
Technical Support: http://www.cisco.com/techsupport
```

```
Copyright (c) 1986-2014 by Cisco Systems, Inc.
```

```
Compiled Tue 14-Oct-14 21:17 by prod_rel_team
```

```
ROM: System Bootstrap, Version 15.4(1r)S2, RELEASE SOFTWARE (fc1)
```

The following example shows output from Cisco ASR 901 Series Aggregation Services Router, IPsec enabled Ethernet version.

```
Router> show version
```

```
Cisco IOS Software, 901 Software (ASR901SEC-UNIVERSALK9-M), Version 15.4(2)S2, RELEASE SOFTWARE (fc1)
```

```
Technical Support: http://www.cisco.com/techsupport
```

```
Copyright (c) 1986-2014 by Cisco Systems, Inc.
```

```
Compiled Fri 17-Oct-14 06:20 by prod_rel_team
```

New and Changed Information

- [New Hardware Features in Release 15.4\(2\)S2, page 3](#)
- [New Software Features in Release 15.4\(2\)S2, page 3](#)
- [Modified Software Features in Release 15.4\(2\)S2, page 3](#)

New Hardware Features in Release 15.4(2)S2

There are no new hardware features in Cisco IOS Release 15.4(2)S2.

New Software Features in Release 15.4(2)S2

There are no new software features in Cisco IOS Release 15.4(2)S2.

Modified Software Features in Release 15.4(2)S2

There are no modified features in Cisco IOS Release 15.4(2)S2.

Supported Hardware

Table 4 and Table 5 shows the SFP modules supported on the Cisco ASR 901 Routers:



Note

- 10G SFPs inserted into 1GE port provides 1GE speed.
- 10G SFPs inserted into 10GE port without a valid license provides 1GE speed.
- 100M SFP works only with **no negotiation auto** command.
- Effective with Cisco IOS Release 15.4(1)S, if 1G SFP is used to connect a 10G port to a 1G port, you do not have to explicitly configure the **no negotiation auto** command to bring up the link.

Table 4 SFPs Supported on the Cisco ASR 901 1G and 10G Routers for 1G Mode

<ul style="list-style-type: none"> • CWDM-SFP-1470 • CWDM-SFP-1490 • CWDM-SFP-1510 • CWDM-SFP-1530 • CWDM-SFP-1550 • CWDM-SFP-1570 • CWDM-SFP-1590 • CWDM-SFP-1610 • DWDM-SFP-XXXX¹ • GLC-BX-U and GLC-BX-D² • GLC-EX-SMD • GLC-LH-SMD • GLC-LX-SM-RGD • GLC-SX-MMD 	<ul style="list-style-type: none"> • GLC-SX-MM-RGD • GLC-T • GLC-ZX-SM • GLC-ZX-SMD • GLC-ZX-SM-RGD • SFP-GE-L • SFP-GE-S • SFP-GE-T • SFP-GE-Z • GLC-BX40-D-I • GLC-BX40-DA-I • GLC-BX40-U-I • GLC-BX80-D-I • GLC-BX80-U-I
---	---

1. 40 wavelengths

2. These SFPs (GLC-BX-U and GLC-BX-D) should be connected back to back to bring the interface link up.

Table 5 SFPs Supported on the Cisco ASR 901 10G Router for 10G Mode

<ul style="list-style-type: none"> • SFP-10G-ER • SFP-10G-LR • SFP-10G-LR-X • DWDM-SFP+ • SFP-H10GB-CU1M • SFP-H10GB-CU3M • SFP-H10GB-CU5M 	<ul style="list-style-type: none"> • SFP-10G-SR • SFP-10G-SR-X • SFP-10G-ZR • SFP-10G-LRM • SFP-H10GB-ACU7M • SFP-H10GB-ACU10M
---	--

**Note**

For information on how to configure SFPs, see the [Cisco ASR 901 Series Aggregation Services Router Software Configuration Guide](#).

Supported MIBs

The Cisco ASR 901 Router supports the following MIBs:

- BGP4-MIB
- BRIDGE-MIB
- CISCO-ACCESSENVMON-MIB
- CISCO-CAR-MIB
- CISCO-CDP-MIB
- CISCO-CEF-MIB
- CISCO-CLASS-BASED-QOS-MIB
- CISCO-CONFIG-COPY-MIB
- CISCO-CONFIG-MAN-MIB
- CISCO-DATA-COLLECTION-MIB
- CISCO-DOT3-OAM-MIB
- CISCO-EIGRP-MIB
- CISCO-ENHANCED-MEMPOOL-MIB
- CISCO-ENTITY-ASSET-MIB
- CISCO-ENTITY-VENDORTYPE-OID-MIB
- CISCO-ENVMON-MIB
- CISCO-FLASH-MIB
- CISCO-IETF-PW-MIB
- CISCO-IETF-PW-TC-MIB
- CISCO-IF-EXTENSION-MIB
- CISCO-IMAGE-MIB
- CISCO-STP-EXTENSIONS-MIB
- CISCO-SYSLOG-MIB
- CISCO-TC
- ENTITY-MIB
- ETHERLIKE-MIB
- HCNUM-TC
- IANAifType-MIB
- IEEE8021-CFM-MIB
- IF-MIB
- IMA-MIB
- INT-SERVE-MIB
- IP-FORWARD-MIB
- IP-MIB
- MPLS-LDP-MIB
- MPLS-LSR-MIB
- MPLS-VPN-MIB
- NOTIFICATION-LOG-MIB
- OLD-CISCO-CHASSIS-MIB
- OLD-CISCO-FLASH-MIB
- OLD-CISCO-INTERFACES-MIB
- OLD-CISCO-IP-MIB

- CISCO-IPSLA-ETHERNETMIB
- CISCO-MEMORY-POOL-MIB
- CISCO-NETSYNC-MIB
- CISCO-NTP-MIB
- CISCO-OSPF-MIB
- CISCO-PING-MIB
- CISCO-PROCESS-MIB
- CISCO-PRODUCTS-MIB
- CISCO-PTP-MIB
- CISCO-QUEUE-MIB
- CISCO-RESILIENT-ETHERNET-PROTOCOL-MIB
- CISCO-RTTMON-MIB
- CISCO-SENSOR-ENTITY-MIB
- CISCO-SMI-MIB
- CISCO-SNAPSHOT-MIB
- CISCO-SNMP-TARGET-EXT-MIB
- OLD-CISCO-SYS-MIB
- OLD-CISCO-TS-MIB
- OSPF-MIB
- OSPFv3-MIB
- PerfHist-TC-MIB
- RFC1213-MIB
- RMON2-MIB
- RMON-MIB
- SNMP-FRAMEWORKMIB
- SNMP-TARGET-MIB
- SNMPv2-MIB
- SNMPv2-SMI
- SNMPV2-TC
- TCP-MIB
- UDP-MIB
- CISCO-IPSEC-FLOW-MONITOR-MIB
- CISCO-IPSEC-MIB

Caveats

Caveats describe unexpected behavior in Cisco IOS software releases. Severity 1 caveats are the most serious caveats, severity 2 caveats are less serious, and severity 3 caveats are the least serious of these three severity levels. Only select severity 3 caveats are listed.

This section contains the following topics:

- [Bug Search Tool](#)
- [Open Caveats](#)
- [Resolved Caveats](#)

Bug Search Tool

The Caveats section only includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a particular bug you must use the Bug Search Tool.

Use the following link to access the tool: <https://tools.cisco.com/bugsearch/search>

You will be prompted to log into Cisco.com. After successful login, the Bug Search Tool page opens. Use the Help link in the Bug Search Tool to obtain detailed help.

Open Caveats

This section provides information about the open caveats for the Cisco ASR 901 Router running Cisco IOS Release 15.4(2)S2.

Bug ID	Description
CSCsd58192	Multicast MAC entry is formed on a Layer 2 VLAN without a querier.
CSCtn18900	Service policy classification based on inner Virtual LAN p-bits is not working.
CSCtn71094	The no interface vlan 1 command deletes VLAN 1.
CSCtn79746	The show ethernet service instance statistics command is not displaying any statistics.
CSCto96840	A command restriction is required for Dual Rate Three Color (2R3C) on parent class in Hierarchical Quality of Service (HQoS).
CSCtq26793	Some ports are not getting bundled with the port channel because of attribute mismatch, such as flow-control.
CSCtr05566	The Multiprotocol Label Switching (MPLS) traffic fails when port channel encapsulation is not equal to the bridge domain on the core.
CSCtr70228	High CPU utilization is observed while performing save or copy operation.
CSCts66081	Ingress VLAN translation failure occurs when entries exceed 3000.
CSCts80090	The reserved VLANs are not blocked on the router.
CSCts84679	The circuit emulation (CEM) interface displays wrong configuration in the show running-configuration command output, when pw-class is configured.
CSCts85484	Traceback occurs after executing rep preempt segment segid command.
CSCts92808	Weighted Random Early Detection (WRED) counters are not working for discard class 0.
CSCtw52497	The interface drops all ingress packets when you reload the router with write, erase, and copy the saved configuration to the running configuration.
CSCtw69021	Maximum bandwidth guarantee for Multilink Point-to-Point Protocol (MLPPP) interface is not working for 64-byte size frames in Low Latency Queuing (LLQ).
CSCtx12366	The servo is accepting more than 64PPS Sync in static unicast.

Bug ID	Description
CSCtx22010	SyncE is not supported for the Copper SFPs: GLC-T and SFP-GE-T
CSCtx54735	High CPU utilization and traceback is observed while doing copy and paste of 16 E1 controllers unconfigurations.
CSCtx77374	Input errors are increasing when serial interface flaps. This issue is observed on a serial interface that is part of a multilink interface, when keepalive is disabled.
CSCty95886	The file copy function is not detecting errors properly.
CSCtz16522	The Two-Way Active Measurement Protocol (TWAMP) session-reflector packet truncation fails.
CSCtz38207	Router is rebooting continuously due to failed fans.
CSCtz48755	The write operation triggers the flaps for Hot Standby Router Protocol (HSRP). We recommend the use of minimum 1 sec (or above) hello timer for HSRP and Virtual Redundancy Router Protocol (VRRP). With this configuration, we support a maximum of 50 sessions.
CSCtz69403	IPv6 traffic is not getting dropped with link-local as source address.
CSCtz81384	The Layer 2 ATM/IMA interface and its permanent virtual circuits (PVCs) are not coming up when operations, administration and maintenance (OAM) is configured.
CSCua19178	Packet drops are seen with IPv6 fragmentation.
CSCua34320	The OSPFv3 keeps old router-id even after changing the loopback address.
CSCua34389	<p>Manual tunnel having MPLS configuration with dynamic option in the following sequence does not set up targeted ldp session resulting in tunnel staying down. shut/no shut of the tunnel brings back the targeted Label Distribution Protocol (LDP) session up.</p> <pre>interface Tunnel108 ip unnumbered Loopback0 mpls label protocol ldp mpls ip tunnel source Loopback0 tunnel destination 36.36.36.36 tunnel mode mpls traffic-eng tunnel mpls traffic-eng path-option 1 dynamic</pre> <p>The issue is not observed when tunnel mode is configured ahead of tunnel destination,</p>
CSCua40707	<p>The commands related to MPLS and MPLS-TE/FRR are applicable only to SVI interfaces though they can be enabled globally.</p> <p>Thus configuring the MPLS commands on the GigabitEthernet interface or port-channel is not supported.</p>
CSCua49491	The MPLS traffic engineering counters are not supported.
CSCua51628	The OSPFv3 bidirectional forwarding detection (BFD) flaps after an interface is shut in a port-channel bundle.
CSCua81678	The following error message is displayed for /128 prefix: "Reached Maximum Number of IPv6 Hosts".
CSCua82917	In remote LFA FRR, the recovery takes more than 80 ms.

Bug ID	Description
CSCua84571	Load balancing is not working with different streams having symmetrical addresses.
CSCua88693	The verify command is not supported for the USB flash in the Cisco ASR 901 10G router.
CSCua98165	The IPv6 BFD packets should be mapped to Queue 6 on egress interface.
CSCua99910	MAC address table (MAC learning) failures can be seen with more than 31000 MAC Addresses in certain conditions. So it is safe to assume the platform supports 31000 MAC addresses.
CSCub12715	The “pura_cef_ipv6_route_create_update:Reached Maximum Number of Prefixes supported by platform.Additional Prefixes will not be programmed” message is displayed when the primary path is shut/unshut in a redundant convergent setup.
CSCub71746	Alarm Indication Signal (AIS) is visible momentarily at T1 controller of CE1 while reverting back to primary.
CSCuc15639	Connectivity Fault Management (CFM) is not supported with 100 ms interval.
CSCuc22630	The router fails to recognize USB when its removed immediately after insertion.
CSCuc25878	The UBR transmits at a lower rate when all five class of service (CoS) Private Virtual Circuits (PVCs) are configured.
CSCuc39560	IPv6 traffic drop occurs globally when IPv4 VRF is configured on the same SVI with ip vrf definition .
CSCuc85033	The untagged Ethernet Virtual Circuit (EVC) port is not supported for spanning tree.
CSCuc95900	Traffic is receiving two VLAN tags, instead of three for QinQ with pop 2.
CSCud04703	In Zero Touch Provisioning, the Cisco ASR 901 series router is not able to connect to the CE server using option-43 template, when source interface is passed as a parameter.
CSCud05125	In traffic generator, the receiver (Rx) counter is incrementing even after the EVC mismatch.
CSCud14278	Border Gateway Protocol (BGP) flap is observed between PEs when traffic from CE side is oversubscribed towards PE.
CSCud16558	High convergence time is observed when “shut” operation is performed on fast re-route (FRR) configured with port channels. This issue can be resolved with BFD.
CSCud20997	The Ethernet Over MPLS (EoMPLS) pseudowire redundancy fails when backup pseudowire is active in TE-FRR backup path.
CSCud24655	CPU hog is observed when primary path is “shut” in an LFA FRR set up with 1000 prefixes.
CSCud29184	The show version command is not giving the image name when the boot system variable is set as: boot system flash image-name .
CSCud32961	Error occurs when any label entry is crossing the 3500 range.

Bug ID	Description
CSCud33913	In Zero Touch Provisioning, the VLAN discovery is not supported for encapsulation dot1ad.
CSCud37655	The xconnect MTU is not used for traffic filtering.
CSCud71334	The mac-address flap control is putting all ports into “err-disabled” state, in some cases.
CSCud75293	The show rom-monitor command is not showing upgraded ROMMON version in IOS mode.
CSCud79202	The show inventory command is displaying the PID of SFP-SX-MM as GLC-SX-MM.
CSCud89083	The router displays “soc_counter_sync: counter thread not responding” error, under heavy CPU usage.
CSCue11410	The incremental-SPF configuration is causing micro loops during convergence, in IGP IS-IS.
CSCue11688	The VRF routes are leaked from the adjacent VRF with a particular IP:nn pattern.
CSCue45003	ASR901 storm control filter does not support current counters value in show storm output.
CSCue54634	Traffic outage and pstorm errors are observed when port channel is configured and unconfigured multiple times.
CSCue94536	The port channel interface flaps when lacp max-bundle is configured and unconfigured.
CSCuf21682	High reconvergence is observed for global traffic in Remote Loop Free Alternate (RLFA).
CSCuf48503	Higher latency is observed for middle priority queue.
CSCuf49860	Configuration of backup peer on primary xconnect, after bringing up remote peer backup results in flap.
CSCug61006	Auto-select is not working on the Gigabit Ethernet (0/4) port. For combo ports, shutdown or no shutdown on the interface is mandatory while changing the media type from RJ45 to auto-select and auto-select to RJ45 respectively.
CSCug91477	Storm control filter for the port channel does not show the discarded counters.
CSCug92777	On Layer 3, multicast traffic are punted to CPU even when storm control drops all the packets.
CSCuh37393	100M SFP support is not available for auto-select medium feature.
CSCuh46724	Sometimes, port-channel with 10G interfaces have high convergence numbers for REP.
CSCuh54827	Layer 2 control protocol forwarding and tunneling is not following the Spanning Tree Group (STG) states updated by Resilient Ethernet Protocol (REP)/Multiple Spanning Tree Protocol (MSTP).
CSCuh69916	The ASR 901 router does not support Multicast Route entry based counters.

Bug ID	Description
CSCuh81074	The ASR 901 router does not support Multicast Route entry based rate counters. The output of show ip mroute active and show ip mfib active commands are showing incorrect traffic rate.
CSCuh84139	The ASR 901 router is experiencing very high Fast Reroute (FRR) cutover downtime when port-channel core-facing interface is down.
CSCui28984	If the accept interface and forward interface are in the same BD, multicast traffic is not forwarded.
CSCui35642	Multicast traffic in the ASR 901 router is getting forwarded based on physical interface MTU instead of SVI MTU.
CSCui85659	Layer 2 control packets (Tx) cannot be spanned.
CSCui88126	Traceback and error message <i>ReachedMaximumNumberIPv6 Hosts</i> is observed during core link flap.
CSCui88126	“ReachedMaximumNumberIPv6 Hosts” error message and traceback is observed on core link flap. The ASR901 router allows lesser than MAX Multicast Routes due to HASH COLLISION LIMITATION in certain Source and Group Combination.
CSCuj33687	Node failure in open ring results in high convergence time for REP.
CSCuj49502	Multiprotocol Label Switching (MPLS) EXP classification is not working in P router for plain IP, L2VPN and L3VPN traffic flowing from one Ingress MLPPP to another Egress MLPPP/Egress GigabitEthernet.
CSCuj65823	Router console session or telnet session hangs after deleting IMA group.
CSCuj65984	FRR egress objects for L2VPN pseudowires may get leaked on flapping all IP routes multiple times.
CSCuj86953	Static NAT entries are not created in the translation table unless there is traffic for that translation.
CSCuj98996	After installing AdvancedMetroIPAccess license, router is setting it for next reboot level even though no license is set at boot level.
CSCuj99184	Router fails to trigger Protocol-Independent Multicast (PIM) assert resulting in duplicate traffic for 2-3mins.
CSCul04332	Unknown IP multicast packet flooding is observed when snooping is enabled.
CSCul06056	All config-reg values are accepting “break”.
CSCul12225	On a 10G router, when 10G interface is used in 1G mode, traffic switching from one member of port-channel to another takes more time.
CSCul14767	Process thrashing on IP multicast table shows 300 groups.
CSCul22030	Duplicate traffic is received for sometime on the receiver which is directly connected on RP after RPF shut/no-shut operation.
CSCul30014	Traceback is observed while removing <i>ppp multilink group</i> from serial interfaces which are bundled in BCP over MLPPP.
CSCul41152	Layer 3 traffic drop is observed after REP preemption, in REP setup with VLAN load balancing (VLB).

Bug ID	Description
CSCul47423	During heavy traffic, some of the links stop transmitting traffic and link goes down with the error message <i>WP_ERR_MP_CHANNEL_NOT_DISABLED</i> .
CSCul58461	IGMPv3 Snooping Explicit Host Tracking (EHT) is not working.
CSCul60965	Internet Security Association and Key Management Protocol (ISAKMP) profile is not working with inside global address from outside.
CSCul67908	Internet Group Management Protocol (IGMP) snooping cannot be enabled on specific BDs.
CSCul71854	Traceback is observed at REP LSL Hello PP Process while trying to replace the configuration with G8032 configuration saved in the flash memory.
CSCum04946	For Internet Key Exchange Version 2 (IKEv2), though the tunnel is coming up, the traffic fails to pass through the IPsec tunnel.
CSCum09333	Multicast traffic is looped by Protocol Independent Multicast (PIM) rendezvous point (RP) if traffic is received on a different VLAN.
CSCum20414	High convergence numbers are observed for multicast traffic when Remote Loop-free Alternate (RLFA) - Fast Reroute (FRR) is configured.
CSCum23734	G8032 is not notified for Connectivity Fault Management (CFM) error when static remote MEP (RMEP) is configured.
CSCum40529	Traffic is not flooded to other interface when IGMP report is stopped on one interface.
CSCum43027	For IGMP and MLD snooping, the PIM neighbourship flaps when Resilient Ethernet Protocol (REP) is configured and <i>pim query-interval</i> is set to a value less than 10.
CSCum53244	High CPU usage is observed after configuring multiple segments on the same router with REP Edge No-Neighbor configuration.
CSCum53280	IPsec traffic is not getting encrypted, if Authentication Header (AH) Hashed Message Authentication Codes (HMAC) is used with Encapsulating Security Payload (ESP) encryption algorithm.
CSCum54897	Reduced throughput is observed for non-TCP/UDP IPsec traffic.
CSCum54904	When IPsec traffic breaches 500 Mbps (approximate) for uni-directional traffic and 250 Mbps (approximate) for bi-directional traffic, drastic drop in traffic is observed.
CSCum59363	Ethernet ring flap is observed when the topology has 3 to 4 rings.
CSCun02393	CPU spike is observed for 10 to 20 seconds when IGMP snooping or MLD snooping is configured with REP or G8032 or MSTP.
CSCun13361	Traffic is not flowing to the IGMP hosts after adding or removing the port-channel member interfaces.
CSCun14432	Router crashes when GigabitEthernet interface is selected as the default interface.
CSCun14606	After configuring the no ipv6 mld snooping vlan num listener-message-suppression command, the running configuration shows no ipv6 mld snooping vlan num report-suppression . After reboot, the configuration is not accepted and the configuration is lost.

Bug ID	Description
CSCun25855	IPsec counters are doubled when re-keying is enabled.
CSCun27273	MPLS Label Distribution Protocol (LDP) bindings are being created for virtual console IP.
CSCun30789	Router crashes after adding new class with match on QoS group.
CSCun33689	IPsec tunnel ping fails, with repeated removal and addition of tunnel protection from the tunnel interface.
CSCun29980	Sometimes, CFM is not sending failure notification to G8032.
CSCun41738	Traceback is observed on route processor while 500 MLD groups are used.
CSCun42385	CPU process is running even after IPSLA is disabled.
CSCun42436	Ethernet loopback failure is noticed during service performance testing on both sender and responder.
CSCun44319	If more than 100 IGMP joins or leaves occur in a single burst, some entries might get dropped. It works fine up to a maximum of 100 joins or leaves in a single burst.
CSCun48620	Neighbor solicitation (NS) bit is not cleared for IPv4 multicast groups.
CSCun51336	Open Shortest Path First (OSPF) remains active even after configuring Access Control List (ACL) deny any on the interface.
CSCun52296	Validblock_diagnose crash with code 2 and 8 on Soak with triggers.
CSCun52716	Egress policy counters are not working after applying on the port-channel interface.
CSCun58346	The clear ip nat translation command is not clearing translation entries.
CSCun70313	Micro loop is observed with Multiple Spanning Tree Protocol (MSTP), when the port channel is in no shut mode.
CSCun76522	The Bit Error Rate Test (BERT) sync counter is not getting reset from one test to another.
CSCun81002	The ACL slices are showing double wide in the Cisco ASR 901 10G IPsec/NAT router.
CSCun86086	The show environment command is showing inconsistent speeds for different fans (fan 1 and 2 are having same speed, while fan 3 shows a different speed).
CSCu138240	Data packets are not getting spanned with port-channel as source port on PE having xconnect.
CSCum09471	Traffic drop is observed on other receiver in the scale scenario. When leave is sent from the host connected on DR side, drop occurs on receiver connected on querier.
CSCun96531	The show license command output always shows the ipsecnatpat license as 'not in use'.
CSCun03965	IOS time does not synchronize with Linux time.
CSCun25150	High convergence number is observed when G.8032 is configured with port-channel interfaces.
CSCup07476	After reload, the traffic generator over Xconnect does not start.

Bug ID	Description
CSCug36837	Dynamic change of queue limit is not supported on Cisco ASR 901 Router.
CSCup08176	The show logging onboard voltage command does not display the relevant output.
CSCun07003	Traceback is observed while enabling multicast.
CSCun83950	IP and Connectionless Network Service (CLNS) routers flap, and traceback is observed on xconnect.
CSCun99104	Traceback is observed while configuring offload CFM sessions.
CSCuo08953	Cisco ASR 901 Router crashes when the core interface flaps and the debug platform software qos all command is enabled.
CSCuo28247	Remote MEP is not discovered since router in the remote complains incorrect CFM packets.
CSCuj38194	Cisco ASR 901 Router hangs while writing about the keystone initialization crash information.
CSCuo59587	SFP is not getting detected.
CSCuq07013	Traffic is not flowing from Cisco ASR 901 router running the IPsec software to other routers.
CSCuq56943	Router crashes with <code>%SYS-6-STACKLOW</code> message while configuring Precision Time Protocol (PTP) using Zero-Touch deployment.
CSCuo29736	Crafted IP packets are causing BGP neighbors to flap.
CSCup74175	Link flap is observed while shutting down a port that is adjacent to another port where SFP is present and link is up. Also, while doing OIR, inserting SFP in one port is flapping another port.

Resolved Caveats

This section provides information about the resolved caveats for the Cisco ASR 901 Router running Cisco IOS Release 15.4(2)S2.

Bug ID	Description
CSCup15135	SyncE is not working when port-channel is enabled on the same interface.
CSCup77821	The VTP-Generic Bridge PDU Tunneling (GBPT) packet is getting stuck at the input-queue of an EVC interface.
CSCup23925	IP multicast (IPmc) process memory leak is observed.
CSCun83713	Layer 2 VPN traffic drops after clearing ARP and Xconnect.
CSCup12415	The show platform hardware cef ipv4 command shows only the information for the first label.
CSCum84172	Incorrect Next Hop Resolution Protocol (NHRP) mapping information for a hub can be propagated throughout the Dynamic Multipoint VPN (DMVPN) network and cause data packet forwarding through a spoke-hub-spoke path even when a spoke-spoke direct path has been built and the sending nodes <i>thinks</i> it is sending on the direct path.

Bug ID	Description
CSCum95421	IGMP snooping or MLD snooping entries are not getting updated correctly, when there is a topology change with REP, G8032, or MSTP.
CSCup93961	The Cisco ASR 901 1G and 10G Router versions are rebooting continuously after 70 Celsius.
CSCuh07579	Router configured in a DMVPN setup may fail to create SA's during a rekey or new tunnel establishment.
CSCuq38939	IPmc IPv6 table entry is not getting created on the RP for the second receiver.

Troubleshooting

The following sections describe troubleshooting commands you can use with the Cisco ASR 901 Series Aggregation Services Router.

Collecting Data for Router Issues

To collect data for reporting router issues, issue the following command:

- **show tech-support**—Displays general information about the router if it reports a problem.

Collecting Data for ROMMON Issues

To collect data for ROMMON issues, issue the following command while in the EXEC mode:

- **show rom-monitor**—Displays currently selected ROM monitor.



Note

If you contact Cisco support for assistance, we recommend that you provide any crashinfo files stored in flash memory. For more information about crashinfo files, see http://www.cisco.com/en/US/products/hw/routers/ps167/products_tech_note09186a00800a6743.shtml.

Related Documentation

Documents related to the Cisco ASR 901 Series Aggregation Services Router include the following:

- *Cisco ASR 901 Series Aggregation Services Router Hardware Installation Guide*
- *Cisco ASR 901 Series Aggregation Services Router Software Configuration Guide*
- *Regulatory Compliance and Safety Information for Cisco ASR 901 Series Aggregation Services Routers*
- *Cisco ASR 901 Series Aggregation Services Router Series MIB Specifications Guide*

To access the related documentation on Cisco.com, go to:

Cisco ASR 901 1G Router home page:

http://www.cisco.com/en/US/partner/products/ps12077/tsd_products_support_series_home.html

Cisco ASR 901 10G Router home page:

<http://www.cisco.com/c/en/us/support/routers/asr-901-10g-series-aggregation-services-routers/tsd-products-support-series-home.html>

Services and Support

For information on obtaining documentation, obtaining support, providing documentation feedback, security guidelines, and also recommended aliases and general Cisco documents, see the monthly *What's New* in Cisco Product Documentation, which also lists all new and revised Cisco technical documentation, at:

<http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html>

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Release Notes for Cisco ASR 901 Aggregation Series Router for Cisco IOS Release 15.4(2)S2

© 2014, Cisco Systems, Inc All rights reserved.