

# Catalyst, Cisco Embedded Wireless

## Controller



**Cisco SA-[IOSXE-EWC-DOS-G6JRUHRT](#)**

**[CVE-2021-1615](#)**

**Published:** 2021-09-22 16:00

**Version:** 1.0 : Final

**CVSS:** 8.6

**Workarounds:** No workarounds available

**Cisco ID:** [CSCvy04449](#)

**Summary:** A Denial of Service (DoS) vulnerability exists in the Catalyst Embedded Wireless Controller (EWC) software. An attacker can exploit this vulnerability to cause a denial of service on the affected devices.

### Details

Catalyst Embedded Wireless Controller (EWC) software, versions 1.0 through 1.0, is affected by a Denial of Service (DoS) vulnerability.

The vulnerability is located in the `iosxe-ewc-dos-g6JruHRT` component of the software. It is a Denial of Service (DoS) vulnerability that can be exploited to cause a denial of service on the affected devices.

The vulnerability is caused by a buffer overflow in the `iosxe-ewc-dos-g6JruHRT` component. An attacker can exploit this vulnerability to cause a denial of service on the affected devices.

The vulnerability is caused by a buffer overflow in the `iosxe-ewc-dos-g6JruHRT` component. An attacker can exploit this vulnerability to cause a denial of service on the affected devices.

For more information, please refer to the [Cisco Security Advisory](#) for this vulnerability.

<https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-iosxe-ewc-dos-g6JruHRT>

Cisco IOS XE software, versions 16.12 through 17.0, is affected by a Denial of Service (DoS) vulnerability.

The vulnerability is located in the `iosxe-ewc-dos-g6JruHRT` component of the software. It is a Denial of Service (DoS) vulnerability that can be exploited to cause a denial of service on the affected devices.

[Response: September 2021 Semiannual Cisco IOS and IOS XE Software Security Advisory Bundled](#)

[Publication](#)

### References

[Cisco Security Advisory](#)

[Cisco Security Advisory](#)

[Cisco Security Advisory](#)

è,,†â¼±æ€šãⓂã, Cisco

ã,½ãf•ãf^ã,|ã,šã,çãfãfãf¼ã,¹ã«ãⓂã,,ã|ã\_ãã"ã®ã,çãf%ããfã,Ⓜã,¶ãfãã®ãã€ã

è,,†â¼±æ€šã,'ã«ã,"ãšã,,ã^ã,,ã"ã\_ããçç°è^ãã•ã,ããYèf½ã"

ã"ã®ã,çãf%ããfã,Ⓜã,¶ãfãã«è,,†â¼±æ€šã®ãã,ã,èf½ã"ã,»ã,\_ã,ãfšãf³ã«è~è¼%ãã•ã

ã,ã,¹ã,³ã\_ãã"ã®è,,†â¼±æ€šãã»ã,ãã®ã,ã,¹ã,³èf½ã"ãã«ã\_ã½±éY;ã,'ã,Žã^ãã

- Catalyst 9800 ã,ãfãf¼ã,°ãf\_ã,ⓂãfⓂãf\_ã,¹ã,³ãf³ãf^ãfãf¼ãf©
- IOS ã,½ãf•ãf^ã,|ã,šã,ç
- IOS XR ã,½ãf•ãf^ã,|ã,šã,ç
- Meraki èf½ã"
- NX-OS ã,½ãf•ãf^ã,|ã,šã,ç
- ãf\_ã,ⓂãfⓂãf\_ã,¹ LAN ã,³ãf³ãf^ãfãf¼ãf©i¼^WLCi¼%ããfã,½ãf•ãf^ã,|ã,šã,ç

## ã,»ã,ãfYãfãf†ã,£ã¾ã®ãç—•è·j

ã"ã®è,,†â¼±æ€šããã,ã,¹ãf—ãfã,Ⓜãf^ãã,ããã,ãã\_ããèè²ã½ããTMã,ãfããfãã,Ⓜã,¹ãšã

Sep 22 16:00:00.000 UTC: %IOSXE\_INFRA-3-GET\_BUFFER\_ERR: Interrupt processing of Punt received packets ov

## ã>žéç-

ã"ã®è,,†â¼±æ€šãã«ã¾ã†|ãTMã,ã>žéçã\_ãã,ã,šã¾ããã,ãã,ã€,

## ã;®æ£æ,^ãçã,½ãf•ãf^ã,|ã,šã,ç

ã,ã,¹ã,³ã\_ãã"ã®ã,çãf%ããfã,Ⓜã,¶ãfãã«è~è¼%ãã•ã,ããYè,,†â¼±æ€šãã«ã¾ã†|ãTMã,ãç,,j

ãfãf¼ã,ãfšãf³ã\_ãfã,£ãf¼ãfãfE

ã,»ãfãf^ãã«ã¾ã—ã|ã®ããçã\_ããã,šã¾ããTMãã,ãããã®ãã®,^ããããã,½ãf•ãf^ã,|ã,šã,ç

<https://www.cisco.com/c/en/us/products/end-user-license-agreement.html>

ã¾ããYãããšã®çæšãããã,½ãf•ãf^ã,|ã,šã,çã,'ãfãã,|ãf³ãfãf¼ãf%ããšãããã,ãã®ãã\_ããã,

ã,çãfãf—ã,°ãf\_ãf¼ãf%ããšããTMãã,ç,,ã;Yãã®ã,»ã,ãfããããããã,£ã,½ãf•ãf^ã,|ã,šã,ç

ã,çãfãf—ãfããf¼ãf^ãã«ã,^ãã£ãã|ããããšã®çæšããã«°ãã—ã,,ã,½ãf•ãf^ã,|ã,šã,ç

ãf©ã,Ⓜã,»ãf³ã,¹ããèè½ãšã,½ãf•ãf^ã,|ã,šã,çãfã,£ãf¼ããfããfE

ã,»ãfãf^ããã¾ããYããããfãã,ãf£ãf¼ãããããã,ãfšãf³





ã¼ãÿã€ã,ã,¹ã³ãæœ-ãf%ã,ãfãfjãf³ãf^ã®ãt...ã®¹ã,'ã^ãšãªã—ã«ã%ãæ'ã—ã  
æœ-ã,ããf%ããfãã,ãã,ããfãã®è"~è¿ãt...ã®¹ã«é-ãã—ãã!æf...ã±é...ãã¿ãã® URL  
ã,ãœãç•ãã—ã€ãããç<-ãã®è»çè¼%ãã,,æ,,è"³ã,'æ-½ãã—ããÿã'ãã^ã€ãã½"çã¼ããœç®;çç  
ã"ãã®ãf%ãã,ãfããfjãf³ãf^ãã®æf...ã±ããæã,ã,¹ã,³è½ã"ãã®ã,"ãf³ãf%ããf!ãf¼ã,ãã,ã³¼è±jã

## 翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。