



Release Notes for Cisco 3600 Series for Cisco IOS Release 12.2 XT

June 13, 2002

Cisco IOS Release 12.2(2) XT3

OL-1979-01 Rev. D1



Note

Cisco IOS Release 12.2(2) XT introduces the Cisco 3631.



Note

You need to purchase a feature license to turn on the Cisco Survivable Remote Site Telephony (SRS Telephony) and Cisco IOS Telephony Service Version 2.0 features. You also need an account on Cisco.com to access the CiscoIPphone firmware versions.

These release notes for the Cisco 3600 series describe the enhancements provided in Cisco IOS Release 12.2(2) XT3. These release notes are updated as needed.

For a list of the software caveats that apply to Cisco IOS Release 12.2(2) XT3, see the [“Caveats for Cisco IOS Release 12.2 XT” section on page 19](#) and *Caveats for Cisco IOS Release 12.2 T*. This caveats document is updated for every maintenance release and is also located on Cisco.com and the Documentation CD-ROM.

Use these release notes with *Cross-Platform Release Notes for Cisco IOS Release 12.2 T* located on Cisco.com and the Documentation CD-ROM.

Contents

These release notes describe the following topics:

- [Introduction, page 2](#)
- [System Requirements, page 2](#)
- [New and Changed Information, page 13](#)



Corporate Headquarters:

Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

Copyright © 2002. Cisco Systems, Inc. All rights reserved.

- [MIBs, page 17](#)
- [Important Notes, page 18](#)
- [Caveats for Cisco IOS Release 12.2 XT, page 19](#)
- [Related Documentation, page 29](#)
- [Obtaining Technical Assistance, page 35](#)

Introduction

The Cisco 3600 series includes the Cisco 3620, Cisco 3631, Cisco 3640, and Cisco 3660 routers. As modular solutions, the Cisco 3600 series routers enable corporations to increase dialup density and take advantage of current and emerging WAN technologies and networking capabilities. The Cisco 3600 series routers are fully supported by Cisco IOS software, which includes dialup connectivity, LAN-to-LAN routing, data and access security, WAN optimization, and multimedia features.

Cisco 3631

The Cisco 3631 is a new midrange router for Data Communication Networks (DCN) applications that provides two network modules and two WICs, one fast ethernet port, one console port, and an auxiliary port. The Cisco 3631 is two rack units high in an 11-inch NEBS/ETSI compliant chassis that functions at 70,000 pps.

For information on new features and Cisco IOS commands supported by Cisco IOS Release 12.2(2) XT3, see the [“New and Changed Information” section on page 13](#) and the [“Related Documentation” section on page 29](#).

System Requirements

This section describes the system requirements for Cisco IOS Release 12.2 XT and includes the following sections:

- [Memory Recommendations, page 3](#)
- [Supported Hardware, page 4](#)
- [Determining the Software Version, page 9](#)
- [Upgrading to a New Software Release, page 9](#)
- [Feature Set Tables, page 9](#)

Memory Recommendations

Table 1 Memory Recommendations for the Cisco 3600 Series Routers

Platform	Feature Set	Image Name	Recommended Flash Memory	Recommended DRAM Memory	Runs from
Cisco 3620	IP	c3620-i-mz	8MB	32MB	RAM
	IP Plus (is)	c3620-is-mz	16MB	64MB	RAM
	IP Plus IPSec 3DES (ik9s)	c3620-ik9s-mz	16MB	64MB	RAM
	IP/FW/IDS Plus IPSec 3DES	c3620-ik9o3s-mz	16MB	64MB	RAM
	IP/IPX/AT/DEC Plus	c3620-ds-mz	16MB	64MB	RAM
	Enterprise Plus	c3620-js-mz	32MB	96MB	RAM
Cisco 3631	Telco Feature Set	c3631-telco-mz	32MB	64MB	RAM
	Telco Plus Feature Set	c3620-telconet-mz	32MB	96 MB	RAM
Cisco 3640	IP	c3640-i-mz	8MB	32MB	RAM
	IP Plus	c3640-is-mz	16MB	64MB	RAM
	IP Plus IPSec 3DES	c3640-ik9s-mz	16MB	64 MB	RAM
	IP/FW/IDS Plus IPSec 3DES	c3640-ik9o3s-mz	16MB	64MB	RAM
	IP/IPX/AT/DEC Plus	c3640-ds-mz	16MB	64MB	RAM
	Enterprise Plus	c3640-js-mz	32MB	96MB	RAM
	Enterprise Plus IPSec 3DES	c3640-jk9s-mz	32MB	96 MB	RAM
	Enterprise Plus/H.323 MCM	c-3640-jsx-mz	32MB	96MB	RAM
	Enterprise/FW/IDS Plus IPSec 3DES	c3640-jk9o3s-mz	32MB	96MB	RAM
Cisco 3660 ¹	IP	c3660-i-mz	8MB	64MB	RAM
	IP Plus	c3660-is-mz	16MB	64MB	RAM
	IP Plus IPSec 3DES	c3660-ik9s-mz	32MB	64 MB	RAM
	IP/FW/IDS Plus IPSec 3DES	c3660-ik9o3s-mz	32MB	64MB	RAM
	IP/IPX/AT/DEC Plus	c3660-ds-mz	16MB	64MB	RAM
	Enterprise Plus	c3660-js-mz	32MB	96MB	RAM
	Enterprise Plus IPSec 3DES	c3660-jk9s-mz	32MB	96MB	RAM
	Enterprise Plus/H.323 MCM	c-3660-jsx-mz	32MB	96 MB	RAM
	Enterprise/FW/IDS Plus IPSec 3DES	c3660-jk9o3s-mz	32MB	96MB	RAM

1. The Cisco 3660 uses SDRAM.

Supported Hardware

Cisco IOS Release 12.2 T supports the following Cisco 3600 series routers:

- Cisco 3620
- Cisco 3631
- Cisco 3640
- Cisco 3660 (3661 and 3662)

For detailed descriptions of the new hardware features, see the [“New and Changed Information” section on page 13](#).

Table 2 Supported Interfaces for the Cisco 3600 Series Routers

Interface, Network Module, or Data Rate	Platforms Supported	
Dial Access Network Modules	16- and 32-port asynchronous (NM-16A and NM-32A)	All Cisco 3600 series platforms
	4- and 8-port synchronous/asynchronous (NM-4A/S and NM-8A/S)	All Cisco 3600 series platforms
	6- to 30-port integrated digital modems network modules (NM-6DM, NM-12-DM, NM-18DM, NM-24DM, NM-40DM)	All Cisco 3600 series platforms except Cisco 3631
	6 digital modem upgrade (MICA-6MOD)	All Cisco 3600 series platforms except Cisco 3631
	8- or 16-port integrated analog network modules (NM-8AM and NM16AM)	All Cisco 3600 series platforms except Cisco 3631
LAN Interfaces	1- and 4-port Ethernet (AUI and 10BASE-T, NM-1E, and NM-4E)	All Cisco 3600 series platforms except Cisco 3631
	1-port Fast Ethernet (100BASE-TX and 100BASE-FX, NM-1FE-TX and NM-1FE-FX)	All Cisco 3600 series platforms except Cisco 3631

Table 2 Supported Interfaces for the Cisco 3600 Series Routers (continued)

Interface, Network Module, or Data Rate	Platforms Supported
Mixed Media Network Modules	
1-port 10/100BASE-TX with 1-port channelized/PRI/E1 balanced mode (NM-1FE1CE1B)	All Cisco 3600 series platforms except Cisco 3631
1-port 10/100BASE-TX with 1-port channelized/PRI/E1 unbalanced mode (NM-1FE1CE1U)	All Cisco 3600 series platforms except Cisco 3631
1-port 10/100BASE-TX with 1-port channelized/PRI/T1 (NM-1FE1CT1)	All Cisco 3600 series platforms except Cisco 3631
1-port 10/100BASE-TX with 1-port channelized/PRI/T1 with CSU (NM-1FE1CT1-CSU)	All Cisco 3600 series platforms except Cisco 3631
1-port 10/100BASE-TX with 2-port channelized/PRI/E1 balanced mode (NM-1FE2CE1B)	All Cisco 3600 series platforms except Cisco 3631
1-port 10/100BASE-TX with 2-port channelized/PRI/E1 unbalanced mode (NM-1FE2CE1U)	All Cisco 3600 series platforms except Cisco 3631
1-port 10/100BASE-TX with 2-port channelized/PRI/T1 (NM-1FE2CT1)	All Cisco 3600 series platforms except Cisco 3631
1-port 10/100BASE-TX with 2-port channelized/PRI/T1 with CSU (NM-1FE2CT1-CSU)	All Cisco 3600 series platforms except Cisco 3631
1 Ethernet and 2 WAN card slots (NM-1E2W)	All Cisco 3600 series platforms except Cisco 3631
1 Ethernet, 1 Token Ring, and 2 WAN card slots (NM-1E1R2W)	All Cisco 3600 series platforms except Cisco 3631
2 Ethernet and 2 WAN card slots (NM-2E2W)	All Cisco 3600 series platforms except Cisco 3631
1-port fast Ethernet, 1-port Token Ring with 2 WAN card slots (NM-1FE1R2W[=])	All Cisco 3600 series platforms except Cisco 3631
1-port Fast Ethernet with 2 WAN card slots (NM-1FE2W[=])	All Cisco 3600 series platforms except Cisco 3631
2-port Fast Ethernet with 2 WAN card slots (NM-2FE2W[=])	All Cisco 3600 series platforms except Cisco 3631
16-Port Ethernet Switch Module for 2600 or 3600 (NM-16ESW)	All Cisco 2600 and 3600 series platforms
2 WAN card slots (NM-2W[=])	All Cisco 3600 series platforms except Cisco 3631
Multipoint T1/E1 ATM Network Modules with Inverse Multiplexing over ATM (IMA)¹	
1-port ATM-25 network modules (NM-1ATM-25) ¹	All Cisco 3600 series platforms except Cisco 3631
1-port ATM T3 network module (NM-1A-T3) ¹	All Cisco 3600 series platforms except Cisco 3631
4-port T1 ATM network module with IMA (NM-4T1-IMA)	All Cisco 3600 series platforms
4-port E1 ATM network module with IMA (NM-4E1-IMA)	All Cisco 3600 series platforms
8-port T1 ATM network module with IMA (NM-8T1-IMA)	All Cisco 3600 series platforms
8-port E1 ATM network module with IMA (NM-8E1-IMA)	All Cisco 3600 series platforms

Table 2 Supported Interfaces for the Cisco 3600 Series Routers (continued)

Interface, Network Module, or Data Rate	Platforms Supported	
Multiprot T1/E1 ATM Network Modules with Inverse Multiplexing over ATM (IMA)¹ (Continued)	1-port ATM E3 network module (NM-1A-E3) ¹	All Cisco 3600 series platforms except Cisco 3631
	1-port ATM OC-3 network module with multimode fiber (NM-1A-OC3MM)	All Cisco 3600 series platforms except Cisco 3631
	1-port ATM OC-3 network module with single-mode intermediate reach fiber (NM-1A-OC3SMI)	All Cisco 3600 series platforms except Cisco 3631
	1-port ATM OC-3 network module with single-mode long reach fiber (NM-1A-OC3SML)	All Cisco 3600 series platforms except Cisco 3631
	1-port ATM OC-3 multimode network module and circuit emulation service (NM-1A-OC3MM-1V) ²	All Cisco 3600 series platforms except Cisco 3631
	1-port ATM OC-3 single-mode, intermediate reach network module and circuit emulation service (NM-1A-OC3SMI-1V) ²	All Cisco 3600 series platforms except Cisco 3631
	1-port ATM OC-3 single-mode, long reach network module and circuit emulation service (NM-1A-OC3SML-1V) ²	All Cisco 3600 series platforms except Cisco 3631
Digital T1/E1 Packet Voice Trunk Network Modules and Spare Components	1-port, 24-channel T1 voice/fax module supports 24 channels of medium-complexity codecs: G.729a/b, G.726, G.711, and fax; or 12 channels of G.726, G.729, G.723.1, G.728, G.729a/b, G.711, and fax. Consists of one NM-HDV, two PVDM-12s, and one VWIC-1MFT-T1. ³ Part number: NM-HDV-1T1-24.	All Cisco 3600 series platforms except Cisco 3631
	1-port, enhanced 24-channel T1 voice/fax module, supports 24 channels of high- and medium-complexity codecs: G.729a/b, G.726, G.729, G.728, G.723.1, G.711, and fax. Consists of one NM-HDV, four PVDM-12s, and one VWIC-1MFT-T1. ² Part number: NM-HDV-1T1-24E.	All Cisco 3600 series platforms except Cisco 3631
	2-port, 48-channel T1 voice/fax module supports add/drop multiplexing (drop and insert); 48 channels of medium-complexity codecs: G.729a/b, G.726, G.711, and fax; or 24 channels of G.726, G.729, G.723.1, G.728, G.729a/b, G.711, and fax. Consists of one NM-HDV, four PVDM-12, and one VWIC-2MFT-T1-DI. ² Part number: NM-HDV-2T1-48.	All Cisco 3600 series platforms except Cisco 3631
	1-port, 30-channel E1 voice/fax module, supports 30 channels of G.729a/b, G.726, G.711 and fax or 18 channels of G.726, G.729, G.723.1, G.728, G.729a/b, G.711, and fax. Consists of one NM-HDV, three PVDM-12s, and one VWIC-1MFT-E1. ³ Part number: NM-HDV-1E1-30(=)	All Cisco 3600 series platforms except Cisco 3631

Table 2 Supported Interfaces for the Cisco 3600 Series Routers (continued)

Interface, Network Module, or Data Rate	Platforms Supported	
Digital T1/E1 Packet Voice Trunk Network Modules and Spare Components (continued)	1-port, enhanced 30-channel E1 voice/fax module supports 30 channels of G.729a/b, G.726, G.729, G.728, G.723.1, G.711, and fax. Consists of one NM-HDV, five PVDM-12s, and one VWIC-1MFT-E1. ³ (NM-HDV-1E1-30E(=)).	All Cisco 3600 series platforms except Cisco 3631
	2-port, 60-channel E1 voice/fax module supports add/drop multiplexing (drop and insert); 60 channels of G.729a/b, G.726, G.711, and fax or 30 channels of G.726, G.729, G.723.1, G.728, G.729a/b, G.711, and fax. Consists of one NM-HDV, five PVDM-12s, and one VWIC-2MFT-E1-D1. ³ Part number NM-HDV-2E1-60(=)	All Cisco 3600 series platforms except Cisco 3631
	High-density voice/fax network module spare. Part number: NM-HDV.	Digital T1 packet voice trunk network modules spare component
	12-channel packet voice DSP module upgrade spare. Part number: PVDM-12=.	Digital T1 packet voice trunk network modules spare component
	1-port RJ-48 multiflex trunk—T1 (VWIC-1MFT-T1) ²	Digital T1 packet voice trunk network modules spare component
	2-port RJ-48 multiflex trunk—T1 (VWIC-2MFT-T1) ²	Digital T1 packet voice trunk network modules spare component
	2-port RJ-48 multiflex trunk with drop and insert—T1 (VWIC-2MFT-T1-DI(=)) ²	Digital T1 packet voice trunk network modules spare component
T1/E1 Multiflex Voice/WAN Interface Cards	1-port T1 multiflex trunk interface (VWIC-1MFT-T1)	All Cisco 3600 series platforms
	1-port E1 multiflex trunk interface (VWIC-1MFT-E1)	All Cisco 3600 series platforms
	2-port T1 multiflex trunk interface (VWIC-2MFT-T1)	All Cisco 3600 series platforms
	2-port T1 multiflex trunk interface with drop and insert (VWIC-2MFT-T1-DI) ⁴	All Cisco 3600 series platforms
	2-port E1 multiflex trunk interface with drop and insert (VWIC-2MFT-E1-DI)	All Cisco 3600 series platforms
Voice/Fax Interfaces and Network Modules¹	1- and 2-port voice/fax network module (NM-1V and NM-2V)	All Cisco 3600 series platforms except Cisco 3631
	2-port E&M voice interface card (VIC-2E/M)	All Cisco 3600 series platforms with voice/fax network module except Cisco 3631
	2-port FXO voice interface card (VIC-2FXO, VIC-2FXO-M3, and VIC-2FXO-EU)	All Cisco 3600 series platforms with voice/fax network module except Cisco 3631
	2-port FXS voice interface card	All Cisco 3600 series platforms with voice/fax network module except Cisco 3631
	2-port BRI voice interface card (VIC-2BRI-S/T-TE)	Cisco 3620 and 3640 platforms with voice/fax network module

Table 2 Supported Interfaces for the Cisco 3600 Series Routers (continued)

Interface, Network Module, or Data Rate	Platforms Supported	
WAN Data Rates	48/56/64 kbps	All Cisco 3600 series platforms except Cisco 3631
	1.544/2.048 Mbps	All Cisco 3600 series platforms except Cisco 3631
	Up to 8 Mbps on 4-port serial network module	All Cisco 3600 series platforms except Cisco 3631
	52 Mbps max using HSSI network module	All Cisco 3600 series platforms except Cisco 3631
	Up to 100 Mbps on ATM OC3 network modules	All Cisco 3600 series platforms except Cisco 3631
ISDN Channelized and Serial Network Modules	1- and 2-port channelized T1 modules without CSUs (NM-1CT1 and NM-1CT1)	All Cisco 3600 series platforms
	1- and 2-port channelized T1 network modules with CSUs (NM-1CT1-CSU and NM-2CT1-CSU)	All Cisco 3600 series platforms
	1- and 2-port E1 network modules unbalanced mode (NM-1CE1U and NM-2CE1U)	All Cisco 3600 series platforms
	1- and 2-port E1 network modules balanced mode (NM-1CE1B and NM-2CE1B)	All Cisco 3600 series platforms
	1-port high-speed serial interface (HSSI) network module	All Cisco 3600 series platforms
	4- and 8-port BRI network module with NT-1 (NM-4B-U and NM-8B-U)	All Cisco 3600 series platforms
	4- and 8-port BRI network module with S/T interface (NM-4B-S/T and NM-8B-S/T)	All Cisco 3600 series platforms
	4-port serial (NM-4T)	All Cisco 3600 series platforms except Cisco 3631
Other Network Modules	Compression network module (NM-COMPR)	Cisco 3620 and 3640 series platforms
	Contact Closure Network Module (NM-AIC-64)	All Cisco 2600 and 3600 series platforms
	4 E1 data compression Advanced Integration Module (AIM-COMPR4)	Cisco 3660 series platforms
	Hardware encryption network module	All Cisco 3620 and 3640 series platforms
	Hardware encryption Advanced Integration Module (AIM)	All Cisco 3600 series platforms except Cisco 3631

Table 2 Supported Interfaces for the Cisco 3600 Series Routers (continued)

Interface, Network Module, or Data Rate	Platforms Supported
WAN Interface Cards	1-Port ADSL WAN Interface Card All Cisco 3600 series platforms except Cisco 3631
	1-port T1/fractional T1/DSU/CSU WAN interface card (WIC-1DSU-T1) All Cisco 3600 series platforms except Cisco 3631
	1-port T1/fractional T1 56/64-kbps DSU/CSU WAN interface card (WIC-1DSU-56K4) All Cisco 3600 series platforms
	1-port ISDN with NT-1 WAN interface card (WIC-1B-U) All Cisco 3600 series platforms
	1-port ISDN WAN interface card (WIC-1B-S/T) All Cisco 3600 series platforms
	1-port serial WAN interface card (WIC-1T) All Cisco 3600 series platforms except Cisco 3631
	1- and 2-Port V.90 Modem WICs (WIC-1AM and WIC-2AM) All Cisco 2600 and 3600 series platforms
	2-port serial (WIC-2T[=]) ⁵ All Cisco 3600 series platforms
	2-port asynchronous/synchronous (WIC-2A/S[=]) All Cisco 3600 series platforms

1. Requires the Cisco IOS Plus feature sets.
2. For the Cisco 3660 series only, online insertion and removal (OIR) is now supported in Cisco IOS Release 12.2 T.
3. See T1/E1 multiflex voice/WAN interface cards in this table.
4. For Cisco 3660 series, only supported in T1/E1 digital packet voice trunk network modules and new Fast Ethernet mixed media network modules: NM-1FE2W, NM-2FE2W, NM-1FE1R2W, NM-2W. For Cisco 3620 and 3640, supported in T1/E1 digital packet voice trunk network modules or in 1- or 2-port Ethernet and Fast Ethernet network modules (NM-1E2W, NM-2E2W, NM-1E1R2W, NM-1FE2W, NM-2FE2W, NM-1FE1R2W, NM-2W).
5. Supported in Fast Ethernet mixed media network modules: NM-1FE2W, NM-2FE2W, NM-1FE1R2W, NM-2W.

Determining the Software Version

To determine the version of Cisco IOS software running on your Cisco 3600 series, log in to the Cisco 3600 series and enter the **show version EXEC** command:

```
Router> show version
Cisco Internetwork Operating System Software
IOS (tm) 12.2 XT Software c3660-js-mz, Version 12.2(2) XT3, RELEASE SOFTWARE
```

Upgrading to a New Software Release

For general information about upgrading to a new software release, refer to *Upgrading the Cisco IOS Software Release in Cisco Routers and Modems* located at the following URL:
http://www.cisco.com/warp/public/130/upgrade_index.shtml

Feature Set Tables

The Cisco IOS software is packaged in feature sets consisting of software images—depending on the platform. Each feature set contains a specific set of Cisco IOS features.

Cisco IOS Release 12.2(2) XT3 supports the same feature sets as Cisco IOS Release 12.2(2) T, but Cisco IOS Release 12.2(2) XT3 can include new features supported by the Cisco 3600 series.

**Caution**

Cisco IOS images with strong encryption (including, but not limited to, 168-bit Triple Data Encryption Standard [3DES] data encryption feature sets) are subject to United States government export controls and have limited distribution. Strong encryption images to be installed outside the United States are likely to require an export license. Customer orders may be denied or subject to delay because of United States government regulations. When applicable, purchaser and user must obtain local import and use authorizations for all encryption strengths. Please contact your sales representative or distributor for more information, or send an e-mail to export@cisco.com.

Table 3 lists the features and feature sets supported by the Cisco 3620 router in Cisco IOS Release 12.2(2) XT3. Table 4 lists the features and feature sets supported by the Cisco 3631 router in Cisco IOS Release 12.2 XT. Table 5 and Table 6 list the features and feature sets supported by the Cisco 3640 router in Cisco IOS Release 12.2(2) XT3. Table 7 and Table 8 list the features and feature sets supported by the Cisco 3660 routers in Cisco IOS Release 12.2(2) XT3. These tables all use the following conventions:

- Yes—The feature is supported in the software image.
- No—The feature is not supported in the software image.
- In—The number in the “In” column indicates the Cisco IOS release in which the feature was introduced.

Table 3 Feature List by Feature Set for the Cisco 3620 Series Routers

Features	In	Software Images by Feature Sets					
		IP	IP Plus	IP Plus IPSec 3DES	IP/FW/IDS Plus IPSec 3DES	IP/IPX/AT/ DEC Plus	Enterprise Plus
Interfaces (LAN, Serial, Logical)							
16 Port Ethernet Switch Module for 2600 or 3600 (NM-16ESW)	12.2(2) XT	No	Yes	No	No	No	Yes
Multiservice Applications - Voice							
Cisco IOS Telephony Service Version 2.0¹	12.2(2) XT	No	Yes	Yes	Yes	Yes	Yes
Survivable Remote Site Telephony Version 2.0	12.2(2) XT	No	Yes	Yes	Yes	Yes	Yes

1. The feature name “Cisco IP Keyswitch Version 2.0” has changed to “Cisco IOS Telephony Service Version 2.0” in Cisco IOS Release 12.2(2) XT. The command mode has changed from keyswitch configuration mode to telephony-service configuration mode.

Table 4 Feature List by Feature Set for the Cisco 3631 Routers

Features	In	Software Images by Feature Sets	
		Telco	Telco Plus
Interfaces (LAN, Serial, Logical)			
16 Port Ethernet Switch Module for 2600 or 3600 (NM-16ESW)	12.2(2) XT	No	No
Multiservice Applications - Voice			
Survivable Remote Site Telephony Version 2.0	12.2(2) XT	No	No

Table 5 Feature List by Feature Set for the Cisco 3640 Series Routers, Part 1 of 2

Features	In	Software Images by Feature Sets			
		IP	IP Plus	IP Plus IPsec 3DES	IP/FW/IDS Plus IPsec 3DES
Interfaces (LAN, Serial, Logical)					
16 Port Ethernet Switch Module for 2600 or 3600 (NM-16ESW)	12.2(2) XT	No	Yes	No	No
Multiservice Applications - Voice					
4-Port FXO Voice/Fax Expansion Module (for the NM-HDA Network Module)	12.2(2) XT	No	Yes	No	No
Cisco IOS Telephony Service Version 2.0¹	12.2(2) XT	Yes	Yes	Yes	Yes
Survivable Remote Site Telephony Version 2.0	12.2(2) XT	Yes	Yes	Yes	Yes

1. The feature name "Cisco IP Keyswitch Version 2.0" has changed to "Cisco IOS Telephony Service Version 2.0" in Cisco IOS Release 12.2(2) XT. The command mode has changed from keyswitch configuration mode to telephony-service configuration mode.

Table 6 Feature List by Feature Set for the Cisco 3640 Routers, Part 2 of 2

Features	In	Software Images by Feature Sets				
		IP/IPX/AT/DEC Plus	Enterprise Plus	Enterprise Plus IPsec 3DES	Enterprise Plus/H.323 MCM	Enterprise FW/IDS Plus IPsec 3DEs
Interfaces (LAN, Serial, Logical)						
16 Port Ethernet Switch Module for 2600 or 3600 (NM-16ESW)	12.2(2) XT	No	Yes	No	Yes	No
Multiservice Applications - Voice						
4-Port FXO Voice/Fax Expansion Module (for the NM-HDA Network Module)	12.2(2) XT	No	Yes	No	Yes	No
Cisco IOS Telephony Service Version 2.0¹	12.2(2) XT	Yes	Yes	Yes	Yes	Yes
Survivable Remote Site Telephony Version 2.0	12.2(2) XT	Yes	Yes	Yes	Yes	Yes

1. The feature name "Cisco IP Keyswitch Version 2.0" has changed to "Cisco IOS Telephony Service Version 2.0" in Cisco IOS Release 12.2(2) XT. The command mode has changed from keyswitch configuration mode to telephony-service configuration mode.

Table 7 Feature List by Feature Set for the Cisco 3660 Series Routers, Part 1 of 2

Features	In	Software Images by Feature Sets			
		IP	IP Plus	IP Plus IPSec 3DES	IP/FW/IDS Plus IPSec 3DES
Interfaces (LAN, Serial, Logical)					
16 Port Ethernet Switch Module for 2600 or 3600 (NM-16ESW)	12.2(2) XT	No	Yes	No	No
Multiservice Applications - Voice					
4-Port FXO Voice/Fax Expansion Module (for the NM-HDA Network Module)	12.2(2) XT	No	Yes	No	No
Cisco IOS Telephony Service Version 2.0 ¹	12.2(2) XT	No	Yes	Yes	Yes
Survivable Remote Site Telephony Version 2.0	12.2(2) XT	No	Yes	Yes	Yes

1. The feature name "Cisco IP Keyswitch Version 2.0" has changed to "Cisco IOS Telephony Service Version 2.0" in Cisco IOS Release 12.2(2) XT. The command mode has changed from keyswitch configuration mode to telephony-service configuration mode.

Table 8 Feature List by Feature Set for the Cisco 3660 Routers, Part 2 of 2

Features	In	Software Images by Feature Sets				
		IP/IPX/AT/ DEC Plus	Enterprise Plus	Enterprise Plus IPSec 3DES	Enterprise Plus/H.323 MCM	Enterprise FW/IDS Plus IPSec 3DEs
Interfaces (LAN, Serial, Logical)						
16 Port Ethernet Switch Module for 2600 or 3600 (NM-16ESW)	12.2(2) XT	No	Yes	No	Yes	No
Multiservice Applications - Voice						
4-Port FXO Voice/Fax Expansion Module (for the NM-HDA Network Module)	12.2(2) XT	No	Yes	No	Yes	No
Cisco IOS Telephony Service Version 2.0 ¹	12.2(2) XT	Yes	Yes	Yes	Yes	Yes
Survivable Remote Site Telephony Version 2.0	12.2(2) XT	Yes	Yes	Yes	Yes	Yes

1. The feature name "Cisco IP Keyswitch Version 2.0" has changed to "Cisco IOS Telephony Service Version 2.0" in Cisco IOS Release 12.2(2) XT. The command mode has changed from keyswitch configuration mode to telephony-service configuration mode.

New and Changed Information

The following sections list the new hardware and software features supported by the Cisco 3600 series for Cisco IOS Release 12.2(2) XT3.

New Hardware and Software Features in Cisco IOS Release 12.2(2) XT3

No new hardware and software features are supported by the Cisco 3600 series for Cisco IOS Release 12.2(2) XT3.

New Hardware and Software Features in Cisco IOS Release 12.2(2) XT2

No new hardware and software features are supported by the Cisco 3600 series for Cisco IOS Release 12.2(2) XT2.

New Hardware and Software Features in Cisco IOS Release 12.2(2) XT1

No new hardware and software features are supported by the Cisco 3600 series for Cisco IOS Release 12.2(2) XT1.

New Hardware Features in Cisco IOS Release 12.2(2) XT

The following new hardware features are supported by the Cisco 3600 series for Cisco IOS Release 12.2(2) XT:

16 Port Ethernet Switch Module for 2600 or 3600 (NM-16ESW)

This feature provides layer 2 switching on Network Modules (NMs) on Cisco 2600 and Cisco 3600 platforms. This feature can be one of the following:

- A singlewide NM with 16 10/100BaseTX ports and one optional 10/100/1000BaseT Gigabit Ethernet port
- A doublewide NM with 36 10/100BaseTX ports and up to two optional 10/100/1000BaseT Gigabit Ethernet ports

Both network modules have the capability to provide inline power for IP telephones by adding an optional (singlewide or doublewide) power daughtercard.

Refer to the following document for additional information:

http://www.cisco.com/univercd/cc/td/doc/product/software/ios122/122newft/122limit/122x/122xt/122xt_2/ft1636nm.htm

4-Port FXO Voice/Fax Expansion Module (for the NM-HDA Network Module)

The EM-HDA-4FXO is a 4-port FXO expansion module for the NM-HDA network module for Cisco 2600 and Cisco 3600 series routers. Using a combination of ports on the base board and optional expansion modules, the NM-HDA supports up to 12 FXS + 4 FXO ports or 4 FXS + 8 FXO ports.

Refer to the following document for additional information:

http://www.cisco.com/univercd/cc/td/doc/product/software/ios122/122newft/122limit/122x/122xt/122xt_2/ft_hdanm.htm

New Software Features in Cisco IOS Release 12.2(2) XT

The following new software features are supported by the Cisco 3600 series for Cisco IOS Release 12.2(2) XT:

Cisco IOS Telephony Service Version 2.0



Note

The feature name “Cisco IP Keyswitch Version 2.0” has changed to “Cisco IOS Telephony Service Version 2.0” in Cisco IOS Release 12.2(2)XT. The command mode has changed from keyswitch configuration mode to telephony-service configuration mode.



Note

You need to purchase a feature license to turn on the Cisco IOS Telephony Service feature. You also need an account on Cisco.com to access the CiscoIPphone firmware versions.



Note

Cisco IOS Telephony Service Version 2.0 is not supported on the Cisco 3631.

The Cisco IOS Telephony Service, under the IP Telephony services umbrella, provides basic Cisco IP phone call-handling capabilities in a LAN environment on the Cisco routers. This feature enables the Cisco multiservice routers to act as the Cisco IOS Telephony Service for the Cisco IP Phone 7960, Cisco IP Phone 7940, Cisco IP Phone 7910, and Cisco IP Conference Station 7935 and helps download phone software images, configures, and manages the Cisco IP phones in your LAN. The Cisco IOS Telephony Service provides you with a telephony system perfect for a small office with a small number of extensions.

Refer to the following document for additional information:

Cisco IOS Telephony Service Version 2.0

http://www.cisco.com/univercd/cc/td/doc/product/access/ip_ph/ip_ks/ipkey2.htm



Note

If you installed Cisco IOS Telephony Service Version 1.0 using Cisco IOS Release 12.1.5YD or 12.2.2XB, some commands have changed. You need to perform the following steps before you can upgrade your router image to 12.2(2)XT:

Step 1

Download the Cisco IOS 12.2(2)XT image to the Cisco IOS Telephony Service by entering the **copy tftp flash** command at the enabled prompt. Follow the instructions to download the image from the tftp server.

Step 2

Configure the Cisco IOS Telephony Service to boot from this new image by entering the following at the enabled prompt:

```
Router# configure terminal
Router(config)# boot system flash new image name
```

- Step 3** Remove the configuration for booting from the original image, if configured, by entering the following:

```
Router(config)# no boot system flash original image name
Router(config)# end
```

- Step 4** Save the configuration by entering **write memory** at the enabled prompt.
- Step 5** Upload the running configuration on the Cisco IOS Telephony Service to a tftp server by entering the **copy running-config tftp** command at the enabled prompt and following the instructions.
- Step 6** Edit the running configuration file on the tftp server by using a text editor to change the word “keyswitch” to “telephony-service.”
- Step 7** Download the edited running configuration file to the Cisco IOS Telephony Service by entering **copy tftp startup-config** at the enabled prompt and following the instructions.
- Step 8** Reload the Cisco IOS Telephony Service by entering **reload** at the enabled prompt. Enter **no** if you are prompted to save the configuration.

If the configuration register is not set to x2 or x2102, but is set to 0x0 instead, you need to boot the router from ROMMON by performing the following steps:

-
- Step 1** Upload the running configuration on the Cisco IOS Telephony Service to a tftp server by entering **copy running-config tftp** at the enabled prompt and following the instructions.
- Step 2** Edit the running configuration file on the tftp server by using a text editor to change the word “keyswitch” to “telephony-service.”
- Step 3** Download the edited running configuration file to the Cisco IOS Telephony Service by entering **copy tftp startup-config** at the enabled prompt and following the instructions.
- Step 4** Download the Cisco IOS 12.2(2)XT image to the Cisco IOS Telephony Service by entering the **copy tftp flash:/slot0** command at the enabled prompt. Follow the instructions to download the image from the tftp server.
- Step 5** Reload the Cisco IOS Telephony Service by entering **reload** at the enabled prompt. Enter **no** if you are prompted to save the configuration.
- Step 6** Boot the Cisco IOS Telephony Service by entering the **boot flash:/slot0:image-name** command at ROMMON prompt.

Survivable Remote Site Telephony Version 2.0

The Survivable Remote Site (SRS) Telephony feature, under the IP Telephony services umbrella, provides the Cisco CallManager with fallback support for the Cisco IP phones attached to the Cisco router on your local Ethernet. The SRS Telephony feature enables the routers to provide call handling support for the Cisco IP phones when the Cisco IP phones lose connection to the remote primary, secondary, or tertiary Cisco CallManager or when the WAN connection is down.

Cisco CallManager 3.0 supports Cisco IP phones at remote sites attached to Cisco branch office multiservice routers across the WAN. Prior to the SRS Telephony feature, when the WAN connection between the remote branch office router and the Cisco CallManager failed or connectivity with the Cisco CallManager was lost for some reason, the Cisco IP phones at the branch office became unusable for the duration of the failure. The SRS Telephony feature overcomes this problem and enables the basic features of the Cisco IP phones by providing call-handling support on the branch office router for its attached Cisco IP phones. The system automatically detects the failure and uses the Simple Network Auto Provisioning (SNAP) technology to autoconfigure the branch office router to provide call processing for the local Cisco IP phones. When the WAN link or connection to the primary Cisco CallManager is restored, call-handling capabilities for the Cisco IP phones switch back to the primary

Cisco CallManager. During a failure when SRS Telephony feature is enabled, the Cisco IP phone displays a message to inform you that the Cisco IP phones are in the Cisco CallManager fallback mode and are able to perform limited functions.

Refer to the following document for additional information:

http://www.cisco.com/univercd/cc/td/doc/product/access/ip_ph/srs/fallbak2.htm

MIBs

Current MIBs

To obtain lists of supported MIBs by platform and Cisco IOS release, and to download MIB modules, go to the Cisco MIB website on Cisco.com at <http://www.cisco.com/public/sw-center/netmgmt/cmtk/mibs.shtml>.

Deprecated and Replacement MIBs

Old Cisco MIBs will be replaced in a future release. Currently, OLD-CISCO-* MIBs are being converted into more scalable MIBs without affecting existing Cisco IOS products or network management system (NMS) applications. You can update from deprecated MIBs to the replacement MIBs as shown in [Table 9](#).

Table 9 *Deprecated and Replacement MIBs*

Deprecated MIB	Replacement
OLD-CISCO-CHASSIS-MIB	ENTITY-MIB
OLD-CISCO-CPUK-MIB	To be determined
OLD-CISCO-ENV-MIB	CISCO-ENVMON-MIB
OLD-CISCO-FLASH-MIB	CISCO-FLASH-MIB
OLD-CISCO-INTERFACES-MIB	IF-MIB CISCO-QUEUE-MIB
OLD-CISCO-IP-MIB	To be determined
OLD-CISCO-MEMORY-MIB	CISCO-MEMORY-POOL-MIB
OLD-CISCO-NOVELL-MIB	NOVELL-IPX-MIB
OLD-CISCO-SYS-MIB	(Compilation of other OLD* MIBs)
OLD-CISCO-SYSTEM-MIB	CISCO-CONFIG-COPY-MIB
OLD-CISCO-TCP-MIB	CISCO-TCP-MIB
OLD-CISCO-TS-MIB	To be determined

Limitations and Restrictions

Caveat CSCdr91706 and IOS HTTP Vulnerability

A defect in multiple releases of Cisco IOS software will cause a Cisco router or switch to halt and reload if the IOS HTTP service is enabled, browsing to `http://router-ip/anytext?/` is attempted, and the enable password is supplied when requested. This defect can be exploited to produce a denial of service (DoS) attack.

The vulnerability, identified as Cisco bug ID CSCdr91706, affects virtually all mainstream Cisco routers and switches running Cisco IOS software releases 12.0 through 12.1, inclusive. This is not the same defect as CSCdr36952.

The vulnerability has been corrected and Cisco is making fixed releases available for free to replace all affected IOS releases. Customers are urged to upgrade to releases that are not vulnerable to this defect.

This vulnerability can only be exploited if the enable password is known or not set.

You are strongly encouraged to read the complete advisory, which is available at

<http://www.cisco.com/warp/public/707/ioshttpserverquery-pub.shtml>.

Important Notes

The following sections contain important notes about Cisco IOS Release 12.2(2) XT that can apply to the Cisco 3600 series.

Addition of squeeze Command for Cisco 2600 and Cisco 3600 Series Routers

The **squeeze** command, which is used to erase all files marked for deletion on a Flash file system, is now available on Cisco 2600 and Cisco 3600 series routers.

Changes to output attenuation Command

In Cisco IOS Release 12.2(2), the range of the output attenuation command for voice ports has changed. The old range was 0 to 14. The new range is -6 to 14.

Changes to Feature Support with Cisco IOS Release 12.2(2) XT

Cisco IOS Release 12.2(2)XT does not support the following features:

- Remote Source-Route Bridging (RSRB)
- AppleTalk
- Apollo Domain
- Banyan Virtual Integrated Network Service (VINES)
- DECnet
- Xerox Network Systems (XNS)

- LAN Emulation
- LAT
- XRemote

Caveats for Cisco IOS Release 12.2 XT

Caveats describe unexpected behavior in Cisco IOS software releases. Severity 1 caveats are the most serious caveats; severity 2 caveats are less serious. Severity 3 caveats are moderate caveats, and only select severity 3 caveats are included in the caveats document.

This section contains only open and resolved caveats for the current Cisco IOS maintenance release.

All caveats in Cisco IOS Release 12.2 and Cisco IOS Release 12.2 T are also in Cisco IOS Release 12.2(2) XT3.

For information on caveats in Cisco IOS Release 12.2, see *Caveats for Cisco IOS Release 12.2*.

For information on caveats in Cisco IOS Release 12.2 T, see *Caveats for Cisco IOS Release 12.2 T*, which lists severity 1 and 2 caveats and select severity 3 caveats and is located on Cisco.com and the Documentation CD-ROM.



Note

If you have an account with Cisco.com, you can use Bug Navigator II to find caveats of any severity for any release. To reach Bug Navigator II, **log in** to Cisco.com and click **Service and Support: Technical Assistance Center: Select & Download Software: Jump to a software resource: Software Bug Toolkit/Bug Watcher**. Another option is to go to the following URL:
http://www.cisco.com/cgi-bin/Support/Bugtool/launch_bugtool.pl

Open Caveats—Cisco IOS Release 12.2(2) XT3

This section documents possible unexpected behavior by Cisco IOS Release 12.2(2) XT3 and describes only severity 1 and 2 caveats and select severity 3 caveats.

- CSCdx04374

If CLNS is configured on the SVI interface (Vlan), the SNPA/MAC is not learned correctly by the router in which the SVI is present. This results in the router sending packets to a non-existent destination MAC address.

There is no workaround.

- CSCdw46537

Symptom:

SPAN doesn't work after moving one port from multi span src ports. Disabling a source interface from a monitor session results in disabling the entire monitor session, not just the specified port.

Workaround:

If a particular source port is required to be removed from a SPAN session, stop the entire SPAN session and re-configure with only the required source ports.

- CSCdw29549
Symptom:
Port security failed when configuring secure MAC addresses on an irrelevant port. When Port Security is configured on two interfaces P1 & P2, and secure MAC addresses M1 & M2 are configured on interfaces P1 & P2 respectively, P1 should only allow packets with source MAC address M1 and P2 should only allow M2. But if a packet with secure MAC address M1 ingresses port P1, then the switch treats it like a station movement and allows the packet to be switched.
Workaround:
Cisco Systems recommends that when station movement takes place, the MAC addresses associated with the port should be cleared in the switch's tables before moving them to another port.
- CSCdw14813
Symptom:
The command **show mac count** shows the wrong number of MAC addresses when compared to the count of addresses shown by the **show mac** command.
There is no workaround.
- CSCdw20431
Symptom:
Traceback is seen on configuring the duplex and speed.
There is no workaround.

Resolved Caveats—Cisco IOS Release 12.2(2) XT3

This section documents possible unexpected behavior by Cisco IOS Release 12.2(2) XT3 and describes only severity 1 and 2 caveats and select severity 3 caveats.

- CSCdv24152
Symptom:
A Cisco router that is running Cisco IOS Release 12.0(17)S and later 12.0 S releases may reset if Frame Relay has been incorrectly configured. If you apply the same data link control (DLC) value on an interface and on its subinterface twice in a row, the router may reset.
There is no workaround.
- CSCdw14262
Symptom:
Cisco Voice over IP (VoIP) gateways that are running a Cisco IOS Release 12.2(1a) IP plus image may experience a high central processing unit (CPU) memory utilization condition at the CCH323_CT process.
There is no workaround.

- CSCin02687
Symptom:
When using the Cisco 7200 series router as a Survivable Remote Site Telephony (SRST) and IOS telephony service router and making more than 30 three-party conference calls, the router crashes. The tracebacks point to the fast-ethernet interface that is being used to connect the router to the IP phones or rather the IP phone simulator.
Workaround:
Restrict the number of three-party conference calls.
- CSCdv62649
Symptom:
The command **ip tacacs source-interface** does not work properly.
Workaround:
If configured to use loopback interface for tacacs packets, the router may still use the interface address.
- CSCdw08182
Symptom:
The VWIC installed in NM-1FE2W appears in **show diag** response but not in the configuration. The router is recognizing that it has a VWIC-1MFT-T1 in a NM-1FE2W in the show diag. The problem is that the T1 controller doesn't appear in the configuration. The FastEthernet is present. There is no work-around.
- CSCdw26331
Symptom:
A call to a busy FXS port produces an incorrect release cause code. Calls may receive a "no route to destination" message and an incorrect clearing cause code (instead of a user busy cause code) when calls are placed to a Foreign Exchange Station (FXS) on a busy interface. Depending on the equipment that is used, the caller may receive a "number unobtainable" message or fast busy tones instead of a busy tone when this condition occurs.
Workaround:
Add a huntstop on the dial peer that is assigned to the FXS interface.
- CSCdw38767
Symptom:
Some ports on the NM-16ESW / NMD-36-ESW may not be assigned MAC addresses properly.
Conditions:
This occurs when the last digit of the base MAC address burnt in the NM cookie is in the range 0xF0-0xFF for NM-16ESW and range 0xDA-0xFF for NMD-36-ESW.
Workaround:
None.

- CSCdw46803

Symptom:

After a Cisco 1751 router that is running Cisco IOS Release 12.2(2)XT and that has a BRI network termination/traffic engineering (NT/TE) is reloaded, Layers 1 and 2 may become deactivated.

Workaround:

Enter the **shutdown** interface configuration command followed by the **no shutdown** interface configuration command on the BRI interface.
- CSCdw51152

Symptom:

PCI Fatal Error on DMA CH1

When access to Flash/NVRAM occurs as a result of **write memory** or **show run** commands, and the CPU utilization is high due to heavy packet traffic, this error message can sometimes occur.

This is due to the PCI device timing out on the PCI bus waiting for DMA access to memory.

Workaround:
- CSCdu53333

Symptom:

A Cisco router that is running Cisco IOS Release 12.2(1) or 12.2(0.5g) may experience digital signal processor (DSP) reloads or fail to respond after the following DSP Timeout error messages are displayed:

```
%VTSP-3-DSP_TIMEOUT: DSP timeout on event 6: DSP ID=0x1: DSP error stats, chnl
info(5, 13, 0) %VTSP-3-MSGSNDFAIL: channel:5/0:15 (54516) DSP ID:0x1 Message
ID:0x47
```

The problem is intermittent, and DSPs may hang indefinitely as rarely as only once every few weeks. The problem is likely to appear when T.38 fax mode is used and is likely to appear when "codec complexity medium" is configured for the voice card and there is frequent switching between the fax and voice modes.

Workaround:

This DSP firmware defect is fixed in DSP Release 3.6.15 / VCWare Release 9.19 and DSP Release 3.4.49 / VCWare Release 7.38, as well as newer versions of these firmware releases.
- CSCdw54986

Symptom:

A router with primary-ni switctype will not be able to interoperate with switches that sends CLID/CLIP/CLIR information in FACILITY messages. The router does not accept the FACILITY and disconnects the call.

Workaround:

None
- CSCdw57198

Symptom:

SRST router with FXO ports typically has a connection plan (opx) to route an incoming call on the port to an extension in the router. With this problem, the incoming call cannot be transferred.

There is no workaround.

- CSCdw62829

Symptom:

The High-Density Analog Voice/Fax Network Modules (NM-HDA) for the Cisco 2600 series and Cisco 3600 series routers support Local Voice Busyout (LVBO) features. The **busyout monitor** command can be configured under NM-HDA voice-ports to permit busyout monitoring of local interfaces or remote IP interfaces via Service Assurance Agent (SAA) probes. These features can be configured and can be saved to Non-Volatile RAM (NVRAM) successfully, but on a router reload, the boot-time parser rejects the **busyout monitor** commands.

Any **busyout monitor** command configured under a voice-port on a NM-HDA will disappear from the running-configuration if the router is rebooted. This problem does not occur on VIC-2E/M, VIC-2FXS, and VIC-2FXO voice-ports housed on the NM-1V and NM-2V products.

Workaround:

Issue a **copy startup-config running-config** to re-assert the missing commands.

- CSCdw70410

Symptom:

A Cisco router may reload after a high-density analog voice or fax network module (NM-HDA) that is installed in a slot is replaced by another NM-HDA that has a different hardware configuration.

Workaround:

Use a replacement card that is the same as the original card. This condition will not occur if a card that is the same as the original is used or if a differently configured card is placed in a different slot.

- CSCdw71436

Symptom:

Under rare circumstances, a Cisco router may reload because of a segmentation violation (SegV) when fax calls are present.

There is no workaround.

- CSCdw73302

Symptom:

When using a TCL IVR 2.0 application on a Cisco voice gateway for 2-stage calls, the configured translation rule may be applied for each received digit, instead of only for the initial digit.

Workaround:

None

- CSCdw73507

Symptom:

Ringback is not available for calls coming in from a PSTN. IP phones do not ringback on the network side. When a call comes in from a PSTN, the call should tell the PSTN end so that it can generate ringback on behalf of the IP phones by sending progress ind as 3.

Workaround:

None

- CSCdw75065

Symptom:

Alignment traceback when transfer and conference call. Tracebacks are observed during conference and at times, during regular calls. The tracebacks are on misaligned accesses to memory.

Workaround:

They are subsequently corrected by the hardware but prints to console are annoying and can be viewed as serious potential issues.
- CSCdw82677

Symptom:

Bad voice-quality during conference call. This happens when a Survivable Remote Site Telephony (SRST) ITS GW with loop-back-dns is used in conferencing with a remote GW and where a mis-match of codec types results if the GWs do not have the same codec type configured. Conferencing a-law and u-law mixes doesn't work as some legs in ITS end up with a-law and some with u-law which gives bad voice quality.

Workaround:

This fix is only applicable for a network that has a mixture of A-law and U-law codecs configured in the network. Configure all gateways in the network to use same codec type of either A-law or U-law.
- CSCdw84594

Symptom:

Show diag for Cisco 2600 series routers gives wrong values for NMs which uses TLV_IDPROM. This problem is only on Cisco 2600 series platform

Conditions:

While issuing **sh diag <slot>** command, HDA uses TLV_IDPROM. The hardware version, revision information, and other conditions are displayed wrongly.

Workaround:

None
- CSCdw85359

Symptom:

Caller ID is discarded when an incoming PSTN call through FXO-M1/FXS-M1 is transferred to another number. The Caller-ID displayed after the transfer is "From Private....".

Workaround:

None:
- CSCdx01445

Symptom:

The port does not go on-hook when a supervisory disconnect tone is sent from the PSTN. When call comes in through FXO port to IP Phone, the IP Phone goes into Alerting state. If the caller hangs up at this point, the PSTN sends a supervisory disconnect tone to the FXO where no action is taken which results in not freeing up the port immediately.

Workaround:

None

- CSCuk31298

Symptom:

The IP phone locks during a call to a call forward busy number. This condition occurs in a setup whereby the call forward busy feature is configured using the Cisco IOS Telephony Service (ITS) on an IP phone (phone A) to a second IP phone (phone B). When a call is made from phone A to another phone (phone C), the call can be answered normally.

When a second call is placed from another phone to phone A via a loopback-directory number (loopback-dn), the call is forwarded to phone B. As this call is received, the original call is incorrectly cleared by the node on phone C while the call is still shown as “up” on phone A. When this condition occurs, phone A is no longer able to place or receive calls and has to be powered down to be restored to working condition.

Workaround:

This condition affects only the first IP phone in the internal control table on the router. The first IP phone is typically indicated as “ephone 1” when the **show ephone EXEC** command is issued.

To prevent this condition from occurring when the router is operating in the ITS mode, add a dummy phone entry as the first IP phone or “ephone 1” in the internal control table on the router to prevent an active phone from being listed as the first IP phone in the internal control table of the router.

Reload the router to ensure that the dummy phone occupies the first position in the control table. There is currently no workaround to this condition if the router is operating in the Survivable Remote Site Telephony (SRST) mode (call manager fall back).

- CSCuk31300

Symptom:

Ringling presented to caller before state of called number is known.

When using loopback-dns for outgoing calls, the router presents a ringing tone to the IP phone caller as soon as the call has been routed and before the state of the called number is known.

If the called number is busy, this can result in a ringing and then busy tone being played to the caller. This does not happen if loopback-dns are not used, or if they are used for incoming calls.

Workaround:

Do not use loopback-dns for outgoing calls.

- CSCuk31512

Symptom:

On a miss dialed call transfer, a new call shows previously dialed digits.

When a Keyswitch IP phone user receives an incoming call, and they then attempt to transfer that call, but while dialling they realize they are dialling a wrong number, the transferrer has two options. If they incorrectly select "New Call", the phone displays the previous dialed digits. If the caller then dials more digits, these appear after the previous digits. The phone however only dials the digits presented after the "New Call" button was pressed, and the call is successful.

Workaround:

None

- CSCuk31658

Symptom:

On three-way calls setup by a Survivable Remote Site Telephony / Keyswitch IP phone, if the second call leg to be setup clears their call, the speech path from the IP phone where the conference was setup to the other phone is lost. The problem is observed only when the second call clears, and only if another IP phone is used in addition to the IP phone which set the conference up. Voice path is re-established if the phone that initiated the conference temporarily places the remaining caller on-hold and then immediately resumes the call.

Workaround:

None

- CSCdw62185

This release integrates the DSPware 3.6.15 release. Upgrading to the DSPware 3.6.15 release to fix [CSCdu53333](#) (dsp timeout) remedies the voice quality problem in this caveat.

Open Caveats—Cisco IOS Release 12.2(2) XT2

There are no open caveats specific to Cisco IOS Release 12.2(2)XT2 that require documentation in the release notes.

Resolved Caveats—Cisco IOS Release 12.2(2) XT2

All the caveats listed in this section are resolved in Cisco IOS Release 12.2(2)XT2. This section describes only severity 1 and 2 caveats and select severity 3 caveats.

- CSCdw65903

An error can occur with management protocol processing. Please use the following URL for further information:

<http://www.cisco.com/cgi-bin/bugtool/onebug.pl?bugid=CSCdw65903>

Open Caveats—Cisco IOS Release 12.2(2) XT1

There are no open caveats specific to Cisco IOS Release 12.2(2) XT1 that require documentation in the release notes.

Resolved Caveats—Cisco IOS Release 12.2(2) XT1

All the caveats listed in this section are resolved in Cisco IOS Release 12.2(2) XT1. This section describes only severity 1 and 2 caveats and select severity 3 caveats.

- CSCdu12254

Problem: Lane client does not become operational. First Lane packet is dropped because of the CRC check failed.

Work around: Increase the LANE timer values then LANE client becomes operational. All the AAL5 connections are going to have the same problem of losing first packet.

- CSCdv28001

The Cisco 3640 and Cisco 3620 routers return the wrong power supply type when using with the `ciscoEnvMonSupplySource snmp` query.

- CSCdv48261

The IOS Firewall Feature set, also known as Cisco Secure Integrated Software, also known as Context Based Access Control (CBAC), and introduced in IOS version 11.2P, has a vulnerability that permits traffic normally expected to be denied by the dynamic access control lists.

This vulnerability is documented as Cisco Bug ID CSCdv48261.

No other Cisco product is vulnerable.

There is no workaround.

This advisory is available at

<http://www.cisco.com/warp/public/707/IOS-cbac-dynacl-pub.shtml>

- CSCdv60987

A Cisco router that is running Cisco IOS Release 12.2(1) or a later release may reload when the **show flash all EXEC** command is entered. Since Cisco IOS Release 12.2(2), the **show flash all EXEC** command has become part of the **show tech EXEC** command. This condition is noticeable only on low end systems that support multiple banksizes for internal flash.

Workaround: Replace multiple banksize flash with uniform banksize flash.

- CSCdv65985

Traceback seen on configuring ISIS, IGRP and RIP.

- CSCdv76445

Problem: The 3660 configured as a voice gateway will not register to it's gatekeeper after a reload. This can be an intermittent problem, and may not occur on all 3660's.

Symptom: If you do a debug ras on the gateway there are no ras messages being sent to the gatekeeper.

Workaround: If you do a shut, no shut on the fastethernet interface, the gateway will register to the gatekeeper.

- CSCdv90919

Problem is occurring when the customer is attempting to receive dial-tone on ISDN trunks. The method that the customer uses to obtain this dial-tone is to configure the ISDN trunks for overlap-receiving, and send in a setup message with no called party number. The connected PBX then allows the calling party to hear this dial-tone, but continues to collect digits, which will be sent over the ISDN link as INFO messages. In this case, if the router has an incoming dial-peer that has an exact match to the calling party number, a PI value is not returned in the SETUP_ACK message. This causes the dial-tone from the router to not be heard.

There is no workaround.

- CSCdv91454

Can not do inter-vlan ping after the 16 Port Ethernet Switch Module is OIRed (online removed and inserted).

- CSCdw16395

When a loopback DN is configured using wildcard “.” characters in the number field under ephone-dn, the caller id for calls that are transferred via the loopback dn (such that the outbound transfer-to call comes from the side of the loopback-DN pair that has wildcards in it's number field) then the caller-id at the transfer-to phone shows “Private” instead of showing the caller-id of the transferee (original caller).

Workaround: do not put “.” wildcard characters in the (primary) number field of the loopback-dn, instead put this in the secondary number field. For example replace number 40.. with number 4000 secondary 40.. under ephone-dn for loopback DN configurations.

- CSCdw19173

On MGCP 0.1 voaal2 calls, the Cisco 3660 stops working with 'Memory allocation failed' message There is no workaround for this problem.

- CSCdw21999

Symptom: The Cisco 3600 **sh diag** displays wrong cookie values for HDA EM cards.

Conditions: sh diag <slot>

Workaround: None

Open Caveats—Cisco IOS Release 12.2(2) XT

This section documents possible unexpected behavior by Cisco IOS Release 12.2(2) XT and describes only severity 1 and 2 caveats and select severity 3 caveats.

- CSCdw04503

Call-forward commands not entered for E164 dial-peers.

When dialplan pattern is configured for the local IP Phones, the existing call-forward commands under ephone-dn are not entered under the E.164 dial-peers created by the dialplan pattern command. This can cause a call not getting forwarded if you dial the entire E164 number.

This problem happens only if you add or edit the existing dialplan pattern with call-forward commands already in place. One way to avoid this problem is to configure the right dialplan pattern before configuring the call-forward commands. Additionally, if you modify the dialplan pattern commands, configure the call forward commands again under ephone-dn. This creates the call-forward commands under the E164 dial-peers created.

- CSCdv78130

Inconsistent music on hold (MOH) during conference.

Music on hold works inconsistently in certain conditions. A calls B and conferences to C. B puts the conference on hold. Both A and C hear the MOH. B resumes the call and after a while puts the conference on hold again. Now only A (initiator) hears the MOH.

There is no workaround.

- CSCdv72916

Remote branch Analog Phone to IP Phone call disconnected during CM reconnect.

Calls from Analog Phone to IP Phone during call-manager-fallback mode may get disconnected when the WAN link to CM comes back up. If a call is made in “normal mode” and the WAN link fails, the call stays up even though the WAN link failed. If the WAN link comes back up during the call and the call is between two IP phones or two analog phones, the call is not dropped. However, if the call is between an IP phone and an analog phone, the call is dropped.

There is no workaround.

Resolved Caveats—Cisco IOS Release 12.2(2) XT

There are no resolved caveats specific to Cisco IOS Release 12.2(2) XT that require documentation in the release notes.

Related Documentation

The following sections describe the documentation available for the Cisco 3600 series. These documents consist of hardware and software installation guides, Cisco IOS configuration guides and command references, system error messages, feature modules, and other documents.

Documentation is available as printed manuals or electronic documents, except for feature modules, which are available online on Cisco.com and the Documentation CD-ROM.

Use these release notes with these documents:

- [Release-Specific Documents, page 29](#)
- [Platform-Specific Documents, page 30](#)
- [Feature Modules, page 30](#)
- [Cisco IOS Software Documentation Set, page 30](#)

Release-Specific Documents

The following documents are specific to Cisco IOS Release 12.2 and are located on Cisco.com and the Documentation CD-ROM:

- *Cross-Platform Release Notes for Cisco IOS Release 12.2 T*

On Cisco.com at:

Technical Documents: Cisco IOS Software: Cisco IOS Release 12.2: Release Notes: Cross-Platform Release Notes

On the Documentation CD-ROM at:

Cisco Product Documentation: Cisco IOS Software Configuration: Cisco IOS Release 12.2: Release Notes: Cross-Platform Release Notes

- Product bulletins, field notices, and other release-specific documents on Cisco.com at:

Technical Documents

- Section “[Caveats for Cisco IOS Release 12.2 XT](#)” in these release notes

As a supplement to the caveats listed in “[Caveats for Cisco IOS Release 12.2 XT](#)” in these release notes, see *Caveats for Cisco IOS Release 12.2*. and *Caveats for Cisco IOS Release 12.2 T*, which contain caveats applicable to all platforms for all maintenance releases of Cisco IOS Release 12.2 and Cisco IOS Release 12.2 T.

On Cisco.com at:

Technical Documents: Cisco IOS Software: Cisco IOS Release 12.2: Release Notes: Caveats

On the Documentation CD-ROM at:

Cisco Product Documentation: Cisco IOS Software Configuration: Cisco IOS Release 12.2: Caveats

**Note**

If you have an account with Cisco.com, you can use Bug Navigator II to find caveats of any severity for any release. To reach Bug Navigator II, log in to Cisco.com and click **Service & Support: Technical Assistance Center: Select & Download Software: Jump to a software resource: Software Bug Toolkit/Bug Watcher**. Another option is to go to <http://www.cisco.com/support/bugtools/bugtool.shtml>.

Platform-Specific Documents

These documents are available for the Cisco 3600 series on Cisco.com and the Documentation CD-ROM:

- *Cisco 3600 Series Modular Routers Quick Start Guide*
- Hardware Installation Documents for Cisco 3600 Series
- Software Configuration Documents for Cisco 3600 Series
- Regulatory Compliance and Safety Documents for Cisco 3600 Series

On Cisco.com at the following location:

Technical Documents: Cisco Product Documentation: Access Servers and Access Routers: Modular Access Routers: Cisco 3600 Series Routers

On the Documentation CD-ROM at the following location:

Cisco Product Documentation: Access Servers and Access Routers: Modular Access Routers: Cisco 3600 Series Routers

Feature Modules

Feature modules describe new features supported by Cisco IOS Release 12.2(2) XT3 and are updates to the Cisco IOS documentation set. A feature module consists of a brief overview of the feature, benefits, configuration tasks, and a command reference. As updates, the feature modules are available online only. Feature module information is incorporated in the next printing of the Cisco IOS documentation set.

On Cisco.com at:

Technical Documents: Cisco IOS Software: Cisco IOS Release 12.2: New Feature Documentation

On the Documentation CD-ROM at:

Cisco Product Documentation: Cisco IOS Software Configuration: Cisco IOS Release 12.2: New Feature Documentation

Cisco IOS Software Documentation Set

The Cisco IOS software documentation set consists of the Cisco IOS configuration guides, Cisco IOS command references, and several other supporting documents. The Cisco IOS software documentation set is shipped with your order in electronic form on the Documentation CD-ROM—unless you specifically ordered the printed versions.

Documentation Modules

Each module in the Cisco IOS documentation set consists of one or more configuration guides and one or more corresponding command references. Chapters in a configuration guide describe protocols, configuration tasks, and Cisco IOS software functionality, and contain comprehensive configuration examples. Chapters in a command reference provide complete command syntax information. Use each configuration guide with its corresponding command reference.

On Cisco.com at:

Technical Documents: Cisco IOS Software: Cisco IOS Release 12.2: Configuration Guides and Command References

On the Documentation CD-ROM at:

Cisco Product Documentation: Cisco IOS Software Configuration: Cisco IOS Release 12.2: Configuration Guides and Command References

Cisco IOS Release 12.2 Documentation Set Contents

[Table 10](#) lists the contents of the Cisco IOS Release 12.2 software documentation set, which is available in electronic form and in printed form if ordered.



Note

You can find the most current Cisco IOS documentation on Cisco.com and the Documentation CD-ROM. These electronic documents may contain updates and modifications made after the hard-copy documents were printed.

On Cisco.com at:

Technical Documents: Cisco IOS Software: Cisco IOS Release 12.2

On the Documentation CD-ROM at:

Cisco Product Documentation: Cisco IOS Software Configuration: Cisco IOS Release 12.2

Table 10 Cisco IOS Release 12.2 Documentation Set

Books	Major Topics
<ul style="list-style-type: none"> <i>Cisco IOS Configuration Fundamentals Configuration Guide</i> <i>Cisco IOS Configuration Fundamentals Command Reference</i> 	Cisco IOS User Interfaces File Management System Management
<ul style="list-style-type: none"> <i>Cisco IOS Bridging and IBM Networking Configuration Guide</i> <i>Cisco IOS Bridging and IBM Networking Command Reference, Volume 1 of 2</i> <i>Cisco IOS Bridging and IBM Networking Command Reference, Volume 2 of 2</i> 	Transparent Bridging SRB Token Ring Inter-Switch Link Token Ring Route Switch Module RSRB ¹ DLSW+ Serial Tunnel and Block Serial Tunnel LLC2 and SDLC IBM Network Media Translation SNA Frame Relay Access NCI/Client/Server Airline Product Set DSPU and SNA Service Point SNA Switching Services Cisco Transaction Connection Cisco Mainframe Channel Connection CLAW and TCP/IP Offload CSNA, CMPC, and CMPC+ TN3270 Server
<ul style="list-style-type: none"> <i>Cisco IOS Dial Technologies Configuration Guide: Dial Access</i> <i>Cisco IOS Dial Technologies Configuration Guide: Large-Scale Dial Applications</i> <i>Cisco IOS Dial Technologies Command Reference, Volume 1 of 2</i> <i>Cisco IOS Dial Technologies Command Reference, Volume 2 of 2</i> 	Dial Access Modem and Dial Shelf Configuration and Management ISDN Configuration Signaling Configuration Point-to-Point Protocols Dial-on-Demand Routing Dial Backup Dial Related Addressing Service Network Access Solutions Large-Scale Dial Solutions Cost-Control Solutions Internetworking Dial Access Scenarios
<ul style="list-style-type: none"> <i>Cisco IOS Interface Configuration Guide</i> <i>Cisco IOS Interface Command Reference</i> 	LAN Interfaces Serial Interfaces Logical Interfaces
<ul style="list-style-type: none"> <i>Cisco IOS IP Configuration Guide</i> <i>Cisco IOS IP Command Reference, Volume 1 of 3: Addressing and Services</i> <i>Cisco IOS IP Command Reference, Volume 2 of 3: Routing Protocols</i> <i>Cisco IOS IP Command Reference, Volume 3 of 3: Multicast</i> 	IP Addressing IP Services IP Routing Protocols IP Multicast
<ul style="list-style-type: none"> <i>Cisco IOS AppleTalk and Novell IPX Configuration Guide</i> <i>Cisco IOS AppleTalk and Novell IPX Command Reference</i> 	AppleTalk ¹ Novell IPX

Table 10 Cisco IOS Release 12.2 Documentation Set (continued)

Books	Major Topics
<ul style="list-style-type: none"> • <i>Cisco IOS Voice, Video, and Fax Configuration Guide</i> • <i>Cisco IOS Voice, Video, and Fax Command Reference</i> 	Voice over IP Call Control Signaling Voice over Frame Relay Voice over ATM Telephony Applications Trunk Management Fax, Video, and Modem Support
<ul style="list-style-type: none"> • <i>Cisco IOS Quality of Service Solutions Configuration Guide</i> • <i>Cisco IOS Quality of Service Solutions Command Reference</i> 	Packet Classification Congestion Management Congestion Avoidance Policing and Shaping Signaling Link Efficiency Mechanisms
<ul style="list-style-type: none"> • <i>Cisco IOS Security Configuration Guide</i> • <i>Cisco IOS Security Command Reference</i> 	AAA Security Services Security Server Protocols Traffic Filtering and Firewalls IP Security and Encryption Passwords and Privileges Neighbor Router Authentication IP Security Options Supported AV Pairs
<ul style="list-style-type: none"> • <i>Cisco IOS Switching Services Configuration Guide</i> • <i>Cisco IOS Switching Services Command Reference</i> 	Cisco IOS Switching Paths NetFlow Switching Multiprotocol Label Switching Multilayer Switching Multicast Distributed Switching Virtual LANs LAN Emulation ¹
<ul style="list-style-type: none"> • <i>Cisco IOS Wide-Area Networking Configuration Guide</i> • <i>Cisco IOS Wide-Area Networking Command Reference</i> 	ATM Frame Relay SMDS X.25 and LAPB
<ul style="list-style-type: none"> • <i>Cisco IOS Mobile Wireless Configuration Guide</i> • <i>Cisco IOS Mobile Wireless Command Reference</i> 	General Packet Radio Service

Table 10 Cisco IOS Release 12.2 Documentation Set (continued)

Books	Major Topics
<ul style="list-style-type: none"> • <i>Cisco IOS Terminal Services Configuration Guide</i> • <i>Cisco IOS Terminal Services Command Reference</i> 	ARA LAT ¹ NASI Telnet TN3270 XRemote ¹ X.28 PAD Protocol Translation
<ul style="list-style-type: none"> • <i>Cisco IOS Configuration Guide Master Index</i> • <i>Cisco IOS Command Reference Master Index</i> • <i>Cisco IOS Debug Command Reference</i> • <i>Cisco IOS Software System Error Messages</i> • <i>New Features in 12.2-Based Limited Lifetime Releases</i> • <i>New Features in Release 12.2 T</i> • <i>Release Notes</i> (Release note and caveat documentation for 12.2-based releases and various platforms) 	

1. Not supported in Cisco IOS Release 12.2(2)XT.

Obtaining Documentation

The following sections provide sources for obtaining documentation from Cisco Systems.

World Wide Web

You can access the most current Cisco documentation on the World Wide Web at the following sites:

- <http://www.cisco.com>
- <http://www-china.cisco.com>
- <http://www-europe.cisco.com>

Documentation CD-ROM

Cisco documentation and additional literature are available in a CD-ROM package, which ships with your product. The Documentation CD-ROM is updated monthly and may be more current than printed documentation. The CD-ROM package is available as a single unit or as an annual subscription.

Ordering Documentation

Cisco documentation is available in the following ways:

- Registered Cisco Direct Customers can order Cisco Product documentation from the Networking Products MarketPlace:
http://www.cisco.com/cgi-bin/order/order_root.pl
- Registered Cisco.com users can order the Documentation CD-ROM through the online Subscription Store:
<http://www.cisco.com/go/subscription>
- Nonregistered Cisco.com users can order documentation through a local account representative by calling Cisco corporate headquarters (California, USA) at 408 526-7208 or, in North America, by calling 800 553-NETS(6387).

Documentation Feedback

If you are reading Cisco product documentation on the World Wide Web, you can submit technical comments electronically. Click **Feedback** in the toolbar and select **Documentation**. After you complete the form, click **Submit** to send it to Cisco.

You can e-mail your comments to bug-doc@cisco.com.

To submit your comments by mail, use the response card behind the front cover of your document, or write to the following address:

Attn Document Resource Connection
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-9883

We appreciate your comments.

Obtaining Technical Assistance

Cisco provides Cisco.com as a starting point for all technical assistance. Customers and partners can obtain documentation, troubleshooting tips, and sample configurations from online tools. For Cisco.com registered users, additional troubleshooting tools are available from the TAC website.

Cisco.com

Cisco.com is the foundation of a suite of interactive, networked services that provides immediate, open access to Cisco information and resources at anytime, from anywhere in the world. This highly integrated Internet application is a powerful, easy-to-use tool for doing business with Cisco.

Cisco.com provides a broad range of features and services to help customers and partners streamline business processes and improve productivity. Through Cisco.com, you can find information about Cisco and our networking solutions, services, and programs. In addition, you can resolve technical issues with online technical support, download and test software packages, and order Cisco learning materials and merchandise. Valuable online skill assessment, training, and certification programs are also available.

Customers and partners can self-register on Cisco.com to obtain additional personalized information and services. Registered users can order products, check on the status of an order, access technical support, and view benefits specific to their relationships with Cisco.

To access Cisco.com, go to the following website:

<http://www.cisco.com>

Technical Assistance Center

The Cisco TAC website is available to all customers who need technical assistance with a Cisco product or technology that is under warranty or covered by a maintenance contract.

Contacting TAC by Using the Cisco TAC Website

If you have a priority level 3 (P3) or priority level 4 (P4) problem, contact TAC by going to the TAC website:

<http://www.cisco.com/tac>

P3 and P4 level problems are defined as follows:

- P3—Your network performance is degraded. Network functionality is noticeably impaired, but most business operations continue.
- P4—You need information or assistance on Cisco product capabilities, product installation, or basic product configuration.

In each of the above cases, use the Cisco TAC website to quickly find answers to your questions.

To register for Cisco.com, go to the following website:

<http://www.cisco.com/register/>

If you cannot resolve your technical issue by using the TAC online resources, Cisco.com registered users can open a case online by using the TAC Case Open tool at the following website:

<http://www.cisco.com/tac/caseopen>

Contacting TAC by Telephone

If you have a priority level 1 (P1) or priority level 2 (P2) problem, contact TAC by telephone and immediately open a case. To obtain a directory of toll-free numbers for your country, go to the following website:

<http://www.cisco.com/warp/public/687/Directory/DirTAC.shtml>

P1 and P2 level problems are defined as follows:

- P1—Your production network is down, causing a critical impact to business operations if service is not restored quickly. No workaround is available.
- P2—Your production network is severely degraded, affecting significant aspects of your business operations. No workaround is available.

This document is to be used in conjunction with the documents listed in the [“Obtaining Documentation”](#) section on page 34.

CCIP, the Cisco *Powered* Network mark, the Cisco Systems Verified logo, Cisco Unity, Fast Step, Follow Me Browsing, FormShare, Internet Quotient, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ Logo, iQ Net Readiness Scorecard, Networking Academy, ScriptShare, SMARTnet, TransPath, and Voice LAN are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Discover All That’s Possible, The Fastest Way to Increase Your Internet Quotient, and iQuick Study are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherSwitch, GigaStack, IOS, IP/TV, LightStream, MGX, MICA, the Networkers logo, Network Registrar, *Packet*, PIX, Post-Routing, Pre-Routing, RateMUX, Registrar, SlideCast, StrataView Plus, Stratum, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0201R)

Copyright © 2000–2002, Cisco Systems, Inc.
All rights reserved.