



# Release Notes for Cisco Emergency Responder 2.0(2)

---

Updated December, 2007

These release notes describe the feature enhancement and caveats for Cisco Emergency Responder (Cisco ER) 2.0(2).

## Contents

These release notes provide the following information:

- [Hardware and Software Requirements, page 1](#)
- [Related Documentation, page 11](#)
- [Installation Notes, page 11](#)
- [Caveats, page 11](#)
- [Obtaining Documentation and Submitting a Service Request, page 13](#)

## Hardware and Software Requirements

Cisco ER 2.0 supports a variety of hardware and software components, as shown in the following tables.



**Note**

The type of support can differ between types of hardware; read the tables carefully to determine how Cisco ER will work with the devices you use.

---



---

**Americas Headquarters:**  
**Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA**

© 2007 Cisco Systems, Inc. All rights reserved.

Table 1 lists other software that you must install to use Cisco ER 2.0.

**Table 1** Required Software

Item	Supported Software Version	Description
Data Migration Assistant (DMA)	<ul style="list-style-type: none"> <li>Release 6.0(1)</li> </ul>	Before you can upgrade from Cisco ER 1.3 to Cisco ER 2.0, you must use the Data Migration Assistant (DMA) tool to create a migration file containing your Cisco ER 1.3 configuration information. As part of the upgrade process, you will be prompted to provide the location of this migration file.
Cisco Unified CallManager and Cisco Unified Communications Manager	<ul style="list-style-type: none"> <li>Cisco Unified CallManager 4.2</li> <li>Cisco Unified CallManager 4.3</li> <li>Cisco Unified Communications Manager 5.0</li> <li>Cisco Unified Communications Manager 5.1</li> <li>Cisco Unified Communications Manager 6.0</li> <li>Cisco Unified Communications Manager 6.1</li> </ul>	<p>The software that runs the telephony network.</p> <p><b>Note</b> When you configure Cisco ER in support of Cisco Unified Communications Manager 6.1, choose Cisco Unified Communications Manager 6.0 as the supported version when prompted during the installation of Cisco ER or choose Cisco Unified Communications Manager 6.0 as the Cisco Unified Communications Manager version in Cisco ER Administration Utility.</p>
Web browser	Microsoft Internet Explorer 6.0	

Table 2 contains optional software that is recommended for use with Cisco ER 2.0.

**Table 2** Recommended Software

Item	Minimum Software Version	Description
E-mail server	Any SMTP e-mail server	Used to send e-mail notifications to onsite alert (security) personnel. If you use an SMTP e-mail paging server, personnel are paged instead of e-mailed.
Cisco Unified Operations Manager	Version 1.0	Used to monitor the health and functionality of Cisco ER.
<b>Note</b> CiscoWorks IP Telephony Environment Monitor (ITEM) 2.0 is also supported.		

Table 3 lists the different types of phones that support Cisco ER 2.0. The type of support Cisco ER 2.0 supplies differs depending on the type of phone and the type of switch port to which the phone is attached.

**Table 3**      **Supported Phones**

Phones	Description
<p><b>Phones automatically tracked using CDP</b></p> <ul style="list-style-type: none"> <li>• SCCP protocol on Cisco Unified IP Phone 7975, 7971, 7970, 7965, 7962, 7961, 7960, 7945, 7942, 7941, 7940, 7937, 7936, 7935, 7931, 7912, 7911, 7910, 7906, 7905, 7902, 7985</li> <li>• All other SCCP phones with CDP support, with the exception of ATA devices</li> <li>• SIP protocol on Cisco Unified IP Phone 7975, 7971, 7970, 7965, 7962, 7961, 7960, 7945, 7942, 7941, 7940, 7931, 7912, 7911, 7906, 7905, 3911</li> <li>• Cisco IP Communicator</li> </ul>	<p>These phones do not require special Cisco ER configuration. However, ensure that you enable Cisco Discovery Protocol (CDP) on the switches.</p> <p><b>Note</b> Although ATA phones support CDP and SCCP, Cisco ER cannot automatically track them. You can add ATA phones manually and assign them to an Emergency Response Location (ERL). Cisco ER will route calls from ATA phones based on the assigned ERL.</p>
<p><b>Phones automatically tracked using CAM tables</b></p> <ul style="list-style-type: none"> <li>• Cisco Unified IP Phone 12 SP+ and VIP 30</li> </ul>	<p>To automatically track these phones, you must enable content-addressable memory (CAM) tracking when you add the switches to the Cisco ER configuration. Phones that do not use CDP are tracked using the CAM table on all supported switch platforms for Native and AUX VLANs.</p>

**Table 3 Supported Phones (continued)**

Phones	Description
<p><b>Phones that you can track using IP subnet</b></p> <ul style="list-style-type: none"> <li>Wireless phones, such as Cisco Unified Wireless IP Phone 7920/7921, and Cisco IP SoftPhones running on 802.11b</li> <li>Supported Cisco Unified IP Phones connected to Cisco or third-party switches that are not discovered or recognized by Cisco ER</li> <li>Cisco Unified Personal Communicator</li> <li>Third-party SIP phones</li> </ul>	<p>To track these phones, you must configure the subnet and then assign ERLs to the configured subnets.</p> <p><b>Note</b> The use of CAM table tracking can result in the inadvertent discovery and unsupported use of wireless IP phone MACs for tracking purposes. To avoid mis-tracking of wireless IP phones, if CAM table tracking is enabled for a switch, the ERL configured for any switch port connected to a wireless access point must agree with the ERL configured for the IP subnet that will contain the phones connected to that access point.</p>
<p><b>Phones that you can manually define</b></p> <ul style="list-style-type: none"> <li>Analog phones, for example, phones connected to VG 224/248 and ATA devices</li> <li>Generic H.323 or SIP endpoints. Supported H.323 phones include Microsoft NetMeeting and video-enabled H.323 endpoints</li> <li>Any phone otherwise supported for automatic tracking that is connected to an unsupported switch port</li> </ul>	<p>These phones are only supported if their calls are routed by Cisco Unified Communications Manager.</p>



**Note** Cisco ER supports SNMP version 1, version 2, and version 2c of a LAN switch.

Table 4 lists the switches that are supported for automatic tracking. You can use other switches, but you might have to manually define phones attached to those switches.

**Table 4 Supported Voice-Ready LAN Switches**

Series (Ethernet ports only)	Notes	Device Supported	System Object ID from CISCO-PRODUCTS-MIB
Catalyst 500 Express Switch		500-24TT	1.3.6.1.4.1.9.1.724
		500-24LC	1.3.6.1.4.1.9.1.725
		500-24PC	1.3.6.1.4.1.9.1.726
		500G-12TC	1.3.6.1.4.1.9.1.727

**Table 4** Supported Voice-Ready LAN Switches (continued)

Series (Ethernet ports only)	Notes	Device Supported	System Object ID from CISCO-PRODUCTS-MIB
Catalyst 2900 XL	12.01.5.WE12 and higher	2908 XL	1.3.6.1.4.1.9.1.170
		2916 MXL	1.3.6.1.4.1.9.1.171
		2924 XL	1.3.6.1.4.1.9.1.183
		2924 CXL	1.3.6.1.4.1.9.1.184
		2924 XLV	1.3.6.1.4.1.9.1.217
		2924 CXLV	1.3.6.1.4.1.9.1.218
		2912 XL	1.3.6.1.4.1.9.1.219
		2924 MXL	1.3.6.1.4.1.9.1.220
		2912 MXFL	1.3.6.1.4.1.9.1.221
		2900	1.3.6.1.4.1.9.5.12
		2926	1.3.6.1.4.1.9.5.35
		2948 G	1.3.6.1.4.1.9.5.42
Catalyst 2940	Cisco IOS 12.1(22)EA1	2940-8TT-S	1.3.6.1.4.1.9.1.540
		2940-8TF-S	1.3.6.1.4.1.9.1.542
Catalyst 2948	CatOS	2948G-GE-TX	1.3.6.1.4.1.9.5.62
Catalyst 2950	12.1.9.EA1 and higher	2950-12	1.3.6.1.4.1.9.1.323
		2950-24	1.3.6.1.4.1.9.1.324
		2950-24SX	1.3.6.1.4.1.9.1.480
		2950-48SX	1.3.6.1.4.1.9.1.560
		2950-48T	1.3.6.1.4.1.9.1.559
		2950C-24	1.3.6.1.4.1.9.1.325
		2950T-24	1.3.6.1.4.1.9.1.359
		2950G-12	1.3.6.1.4.1.9.1.427
		2950G-24	1.3.6.1.4.1.9.1.428
		2950G-48	1.3.6.1.4.1.9.1.429
		2950S-24	1.3.6.1.4.1.9.1.430
		2950G-24DC	1.3.6.1.4.1.9.1.472
Catalyst 2960	Cisco IOS 12.2(25)SED	2960-24TC-L	1.3.6.1.4.1.9.1.694
		2960-48TC-L	1.3.6.1.4.1.9.1.695
		2960G-24TC-L	1.3.6.1.4.1.9.1.696
		2960G-48TT-L	1.3.6.1.4.1.9.1.697
		2960-24TT-L	1.3.6.1.4.1.9.1.716
		2960-48TT-L	1.3.6.1.4.1.9.1.717
		2960-8TC-L	1.3.6.1.4.1.9.1.798
		2960G-8TC-L	1.3.6.1.4.1.9.1.799

**Table 4 Supported Voice-Ready LAN Switches (continued)**

<b>Series (Ethernet ports only)</b>	<b>Notes</b>	<b>Device Supported</b>	<b>System Object ID from CISCO-PRODUCTS-MIB</b>
Catalyst 3500 XL	Cisco IOS 12.0(5)XU or higher  If you are using Catalyst 3500 clusters, you must assign an IP address to each Catalyst 3500 switch.	3508 GXL	1.3.6.1.4.1.9.1.246
		3512 XL	1.3.6.1.4.1.9.1.247
		3524 XL	1.3.6.1.4.1.9.1.248
		3548 XL	1.3.6.1.4.1.9.1.278
		3524 PWR XL	1.3.6.1.4.1.9.1.287
Catalyst 3550	12/1/6/EA1a or higher	3550-24	1.3.6.1.4.1.9.1.366
		3550-24PWR	1.3.6.1.4.1.9.1.485
		3550-48	1.3.6.1.4.1.9.1.367
		3550-12T	1.3.6.1.4.1.9.1.368
		3550-12G	1.3.6.1.4.1.9.1.431
		3550-24DC	1.3.6.1.4.1.9.1.452
Catalyst 3560	Cisco IOS 12.2(20)SE or higher	3560-24PS	1.2.6.1.4.1.9.1.563
		3560-48PS	1.2.6.1.4.1.9.1.564
		3560-24TS-S/-E	1.2.6.1.4.1.9.1.633
		3560-48TS-S/-E	1.2.6.1.4.1.9.1.615
		3560G-24TS-S/-E	1.2.6.1.4.1.9.1.634
		3560G-48TS-S/-E	1.2.6.1.4.1.9.1.617
		3560G-24PS-S/-E	1.2.6.1.4.1.9.1.614
		3560G-48PS-S/-E	1.2.6.1.4.1.9.1.616
		3560-8PC-S	1.3.6.1.4.1.9.1.797
Catalyst 3560E	Cisco IOS Release 12.2(35)SE2 or higher	3560E-48TD-S	1.3.6.1.4.1.9.1.794
		3560E-48TD-E	1.3.6.1.4.1.9.1.794
		3560E-48PD-SF	1.3.6.1.4.1.9.1.796
		3560E-48PD-S	1.3.6.1.4.1.9.1.796
		3560E-48PD-EF	1.3.6.1.4.1.9.1.796
		3560E-48PD-E	1.3.6.1.4.1.9.1.796
		3560E-24TD-S	1.3.6.1.4.1.9.1.793
		3560E-24TD-E	1.3.6.1.4.1.9.1.793
		3560E-24PD-S	1.3.6.1.4.1.9.1.795
		3560E-24PD-E	1.3.6.1.4.1.9.1.795

**Table 4** Supported Voice-Ready LAN Switches (continued)

Series (Ethernet ports only)	Notes	Device Supported	System Object ID from CISCO-PRODUCTS-MIB
Catalyst 3750	Cisco IOS 12.2(20)SE or higher	3750-24	1.3.6.1.4.1.9.1.511
		3750-24FS-S	1.3.6.1.4.1.9.1.656
		3750-48	1.3.6.1.4.1.9.1.512
		3750-24TS	1.3.6.1.4.1.9.1.513
		3750-24T	1.3.6.1.4.1.9.1.514
		37XX Stack	1.3.6.1.4.1.9.1.516
		3750G-12Sfp	1.3.6.1.4.1.9.1.530
		3750-48PS	1.3.6.1.4.1.9.1.535
		3750-24PS	1.3.6.1.4.1.9.1.536
		3750G-16TD	1.3.6.1.4.1.9.1.591
		3750G-24PS	1.3.6.1.4.1.9.1.602
		3750G-48PS	1.3.6.1.4.1.9.1.603
		3750G-48TS	1.3.6.1.4.1.9.1.604
		3750G-24TS1U	1.3.6.1.4.1.9.1.624
3750G-24TS1U/-EIU	1.3.6.1.4.1.9.1.624		
Catalyst 3750E	Cisco IOS Release 12.2(35)SE2 or higher	3750E-48TD-S	1.3.6.1.4.1.9.1.790
		3750E-48TD-E	1.3.6.1.4.1.9.1.790
		3750E-48PD-SF	1.3.6.1.4.1.9.1.791
		3750E-48PD-S	1.3.6.1.4.1.9.1.791
		3750E-48PD-EF	1.3.6.1.4.1.9.1.791
		3750E-48PD-E	1.3.6.1.4.1.9.1.791
		3750E-24TD-S	1.3.6.1.4.1.9.1.789
		3750E-24TD-E	1.3.6.1.4.1.9.1.789
		3750E-24PD-S	1.3.6.1.4.1.9.1.792
		3750E-24PD-E	1.3.6.1.4.1.9.1.792
Catalyst 3750ME	Cisco IOS 12.2(25)EY	3750-24TE-M	1.3.6.1.4.1.9.1.574
Catalyst 4000	Cisco IOS 12.1(13)EW	4000 C	1.3.6.1.4.1.9.1.448
		4503	1.3.6.1.4.1.9.1.503
		4506	1.3.6.1.4.1.9.1.502
		4507	1.3.6.1.4.1.9.1.501
		4510R	1.3.6.1.4.1.9.1.537
		4948-S-S/-E	1.3.6.1.4.1.9.1.626
		4948-10GE-S/-E	1.3.6.1.4.1.9.1.627

**Table 4 Supported Voice-Ready LAN Switches (continued)**

<b>Series (Ethernet ports only)</b>	<b>Notes</b>	<b>Device Supported</b>	<b>System Object ID from CISCO-PRODUCTS-MIB</b>
Catalyst 4000/4500	Catalyst OS 5.5 or higher	4003	1.3.6.1.4.1.9.5.40
		4912 G	1.3.6.1.4.1.9.5.41
		4006	1.3.6.1.4.1.9.5.46
		4500	1.3.6.1.4.1.9.1.14
		4503	1.3.6.1.4.1.9.5.58
		4506	1.3.6.1.4.1.9.5.59
Catalyst 4900 Metro		ME-4924-10GE	1.3.6.1.4.1.9.1.706
Catalyst 4948	Cisco IOS 12.2(20)EWA	4948	1.3.6.1.4.1.9.1.626
		4948-10GE	1.3.6.1.4.1.9.1.627
Catalyst 5000	Catalyst OS 6.x	5000	1.3.6.1.4.1.9.5.7
		5002	1.3.6.1.4.1.9.5.29
Catalyst 5500		5500	1.3.6.1.4.1.9.5.17
		5505	1.3.6.1.4.1.9.5.34
		5509	1.3.6.1.4.1.9.5.36
Catalyst 6500	Catalyst OS	6503	1.3.6.1.4.1.9.5.56
		6509 NEB-A chassis	1.3.6.1.4.1.9.5.61
	Catalyst OS 5.5 or higher If using an MSFC module, Cisco IOS 12.1(3a)XL	6006	1.3.6.1.4.1.9.5.38
		6009	1.3.6.1.4.1.9.5.39
		6509	1.3.6.1.4.1.9.5.44
		6506	1.3.6.1.4.1.9.5.45
		6509 SP	1.3.6.1.4.1.9.5.47
6513	1.3.6.1.4.1.9.5.50		
Catalyst 6500	Cisco IOS	6503	1.3.6.1.4.1.9.1.449
		6006	1.3.6.1.4.1.9.1.280
		6009	1.3.6.1.4.1.9.1.281
		6506	1.3.6.1.4.1.9.1.282
		6509	1.3.6.1.4.1.9.1.283
		6509 NEB-A chassis	1.3.6.1.4.1.9.1.534
		6509 SP	1.3.6.1.4.1.9.1.310
		6513	1.3.6.1.4.1.9.1.400
Cisco 2800 Integrated Services Routers	Cisco IOS 12.3(8)T4	Cisco 2811	1.3.6.1.4.1.9.1.576
		Cisco 2821	1.3.6.1.4.1.9.1.577
		Cisco 2851	1.3.6.1.4.1.9.1.578
Cisco 3725 Multiservice Access Router	Image version: IOS 12.2(8)T5		1.3.6.1.4.1.9.1.414

**Table 4** Supported Voice-Ready LAN Switches (continued)

Series (Ethernet ports only)	Notes	Device Supported	System Object ID from CISCO-PRODUCTS-MIB
Cisco 3745 Multiservice Access Router	Image version: IOS 12.2(13)T		1.3.6.1.4.1.9.1.436
Cisco 3800 Integrated Services Routers	Cisco IOS	Cisco 3825	1.3.6.1.4.1.9.1.543
		Cisco 3845	1.3.6.1.4.1.9.1.544

Cisco ER 2.0 supports the Cisco MCS Unified Communications Manager Appliance platforms shown in [Table 5](#); [Table 7](#) lists capacity for these platforms.

**Note**

The number of ERLs that can be deployed is determined by the number of route patterns and translation patterns configurable in Cisco Unified Communications Manager.

**Note**

Cisco ER does not support Cisco Integrated Communications System (ICS) 7750 servers.

[Table 5](#) lists the supported Media Convergence Server (MCS) platforms.

**Note**

You must upgrade servers with less than 2 GB memory or less than 72 GB hard disk drive space.

**Table 5** Supported MCS Platforms

Cisco MCS Server	Equivalent OEM Server	CPU
MCS-7816-H3-IPC1		3.2 GHz
MCS-7816-I3-IPC1		3.2 GHz
MCS-7825H-2.2-EVV1	HP DL320-G2	2.26 GHz
MCS-7825H-3.0-IPC1	HP DL320-G2	3.06 GHz
MCS-7825H-3.0-IPC2	HP DL320-G2	3.06 GHz
MCS 7825I-3.0-IPC1	IBM x306	3.06 GHz
MCS-7825-H1-IPC1	HP DL320-G3	3.4 GHz
MCS-7825-I1-IPC1	IBM x306	3.4 GHz
MCS-7825-H2-IPC1	HP DL320-G4	2.8 GHz
MCS-7825-I2-IPC1	IBM x306m	2.8 GHz
MCS-7825-H2-IPC2	HP DL320-G4	3.4 GHz
MCS-7825-I2-IPC2	IBM x306m	3.4 GHz
MCS-7825-H3-IPC1	HP DL320-G5	2.13 GHz
MCS-7825-I3-IPC1	IBM x3250	2.13 GHz
MCS-7835H-2.4-EVV1	HP DL380-G3 (1 CPU)	2.4 GHz
MCS-7835I-2.4-EVV1	IBM x345 (1 CPU)	2.4 GHz
MCS-7835H-3.0-IPC1	HP DL380-G3 (1 CPU)	3.06 GHz

**Table 5 Supported MCS Platforms (continued)**

MCS-7835I-3.0-IPC1	IBM x345 (1 CPU)	3.06 GHz
MCS-7835-H1-IPC1	HP DL380-G4 (1 CPU)	3.4 GHz
MCS-7835-I1-IPC1	IBM x346 (1 CPU)	3.4 GHz
MCS-7835-H2-IPC1	HP DL380-G5 (1 CPU)	2.33 GHz
MCS-7835-I2-IPC1	IBM x3650 (1 CPU)	2.33 GHz
MCS-7845H-2.4-EVV1	HP DL380-G3 (2 CPUs)	2.4 GHz
MCS-7845H-3.0-IPC1	HP DL380-G3 (2 CPUs)	3.06 GHz
MCS-7845I-3.0-IPC1	IBM x345 (2 CPUs)	3.06 GHz
MCS-7845-H1-IPC1	HP DL380-G4 (2 CPUs)	3.4 GHz
MCS-7845-I1-IPC1	IBM x346 (2 CPUs)	3.4 GHz
MCS-7845-H2-IPC1	HP DL380-G5 (2 CPUs)	2.33 GHz
MCS-7845-I2-IPC1	IBM x3650 (2 CPUs)	2.33 GHz

Table 6 lists the supported Media Convergence Server (MCS) platforms for upgrades from Cisco ER 1.3 only. These servers are not supported for new installations.

**Table 6 Supported MCS Platforms for Upgrades from Cisco ER 1.3 Only**

Cisco MCS Server	Equivalent OEM Server	CPU
MCS-7815I-3.0-IPC1		3.06 GHz
MCS-7815I-3.0-IPC2		3.06 GHz
MCS-7815-I1-IPC1		3.4 GHz
MCS-7815-I1-IPC2		3.4 GHz
MCS-7815-I1-IPC3		3.4 GHz
MCS-7815-I1-IPC4		3.4 GHz
MCS-7815-I2-IPC1		2.8 GHz

Table 7 gives capacity information for Cisco Emergency Responder, assuming one synthetic voice alert per emergency call.

**Table 7 System Capacity**

	Cisco 7816	Cisco 7825	Cisco 7835	Cisco 7845
Automatically tracked phones	6,000	12,000	20,000	30,000
Manually configured phones	1,000	2,500	5,000	10,000
Roaming phones (per Cisco Emergency Responder cluster)	600	1,200	2,000	3,000
Switches	200	500	1,000	2,000
Switch ports	12,000	30,000	60,000	120,000
ERLs	1,000	3,000	7,500	10,000

## Related Documentation

### Cisco Emergency Responder Documentation

Refer to the publications for Cisco ER 2.0. Navigate from the following documentation URL:

[http://www.cisco.com/en/US/products/sw/voicesw/ps842/tsd\\_products\\_support\\_series\\_home.html](http://www.cisco.com/en/US/products/sw/voicesw/ps842/tsd_products_support_series_home.html)

### Cisco Unified Communications Manager Documentation

Refer to the Cisco Unified Communications Manager Documentation Guide and other publications specific to your Cisco Unified Communications Manager release. Navigate from the following URL:

[http://www.cisco.com/en/US/products/sw/voicesw/ps556/tsd\\_products\\_support\\_series\\_home.html](http://www.cisco.com/en/US/products/sw/voicesw/ps556/tsd_products_support_series_home.html)

### Cisco Unified Communications Manager Business Edition Documentation

Refer to the Cisco Unified Communications Manager Business Edition Documentation Guide and other publications that are specific to your Cisco Unified Communications Manager release. Navigate from the following URL:

[http://www.cisco.com/en/US/products/ps7273/tsd\\_products\\_support\\_series\\_home.html](http://www.cisco.com/en/US/products/ps7273/tsd_products_support_series_home.html)

## Installation Notes

This section describes upgrade information for Cisco ER 2.0(2) and includes these topics:

- [Supported Upgrades, page 11](#)
- [Important Upgrade Notes, page 11](#)

## Supported Upgrades

You must upgrade to Cisco ER 1.3.x or later, including Cisco ER 2.0(1). You cannot upgrade directly to Cisco ER 2.0(2) from earlier versions of Cisco ER.

## Important Upgrade Notes

Once you upgrade your system to Cisco ER 2.0(2), you can downgrade to Cisco ER 2.0(1) only.



### Note

It is not recommended to downgrade your system from Cisco ER 2.0(2) to Cisco ER 2.0(1) because of known issues in Cisco ER 2.0(1).

If you have a Cisco ER version earlier than 2.0(2) on your system, you cannot downgrade your system to earlier Cisco ER versions.

## Caveats

This section includes these topics:

- [Using Bug Toolkit, page 12](#)

- [Open Caveats, page 12](#)
- [Resolved Caveats, page 13](#)

## Using Bug Toolkit

Known problems (bugs) are graded according to severity level. These release notes contain descriptions of:

- All severity level 1 or 2 bugs.
- Significant severity level 3 bugs.

You can search for problems by using the Cisco Software Bug Toolkit.

To access Bug Toolkit, you need the following items:

- Internet connection
- Web browser
- Cisco.com user ID and password

To use the Software Bug Toolkit, follow these steps:

### Procedure

- 
- Step 1** To access the Bug Toolkit, go to <http://tools.cisco.com/Support/BugToolKit/action.do?hdnAction=searchBugs>.
- Step 2** Log in with your Cisco.com user ID and password.
- Step 3** To look for information about a specific problem, enter the bug ID number in the "Search for Bug ID" field, then click **Go**.
- 

## Open Caveats

[Table 8](#) lists Severity 1, 2 and 3 defects that are open for Cisco ER 2.0(2).

For more information about an individual defect, you can access the online record for the defect by clicking the Identifier or going to the URL shown. You must be a registered Cisco.com user to access this online information.

Because defect status continually changes, be aware that [Table 8](#) reflects a snapshot of the defects that were open at the time this report was compiled. For an updated view of open defects, access Bug Toolkit as described in the [Using Bug Toolkit, page 12](#).

**Table 8** *Open Caveats for Cisco ER 2.0(2)*

Identifier	Headline and Bug Toolkit Link
<a href="#">CSCsk27392</a>	Computer Telephony Interface (CTI) ports do not re-register with Primary Cisco ER after failover or fallback  <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk27392">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk27392</a>

## Resolved Caveats

Table 9 lists Severity 1, 2 and 3 defects that are resolved for Cisco ER 2.0(2).

For more information about an individual defect, you can access the online record for the defect by clicking the Identifier or going to the URL shown. You must be a registered Cisco.com user to access this online information.

Because defect status continually changes, be aware that Table 9 reflects a snapshot of the defects that were resolved at the time this report was compiled. For an updated view of resolved defects, access Bug Toolkit as described in the [Using Bug Toolkit, page 12](#).

**Table 9** Resolved Caveats for Cisco ER 2.0(2)

Identifier	Headline and Bug Toolkit Link
<a href="#">CSCsj24030</a>	Unable to upload public license because of hostname mismatch after Windows-to-Linux upgrade <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsj24030">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsj24030</a>
<a href="#">CSCsj28850</a>	Cisco ER does not boot up and shows kernel panic after Linux-to-Linux upgrade <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsj28850">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsj28850</a>
<a href="#">CSCsk00917</a>	Cannot log into Cisco ER publisher after deleting the publisher from GUI <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk00917">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk00917</a>
<a href="#">CSCsk01164</a>	Logging fails and eventually causes the Cisco ER server to crash <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk01164">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk01164</a>
<a href="#">CSCsk19645</a>	No audio on emergency call alert to onsite security for Cisco ER 2.0(2) <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk19645">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk19645</a>
<a href="#">CSCsk42033</a>	ERL name greater than 20 characters cannot be assigned to IPSubnets, manual, or synthetic IP Phones <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk42033">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk42033</a>

## Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, submitting a service request, and gathering additional information, see the monthly *What's New in Cisco Product Documentation*, which also lists all new and revised Cisco technical documentation, at:

<http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html>

Subscribe to the *What's New in Cisco Product Documentation* as a Really Simple Syndication (RSS) feed and set content to be delivered directly to your desktop using a reader application. The RSS feeds are a free service and Cisco currently supports RSS version 2.0.

---

CCVP, the Cisco logo, and Welcome to the Human Network are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn is a service mark of Cisco Systems, Inc.; and Access Registrar, Aironet, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, LightStream, Linksys, MeetingPlace, MGX, Networkers, Networking Academy, Network Registrar, PIX, ProConnect, ScriptShare, SMARTnet, StackWise, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0711R)

Any Internet Protocol (IP) addresses used in this document are not intended to be actual addresses. Any examples, command display output, and figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses in illustrative content is unintentional and coincidental.

© 2007 Cisco Systems, Inc. All rights reserved.