


# Cisco 3640 Router - PBX Interoperability: Nortel Meridian Option 11 Rel. 24 PBX with Analog FXS and FXO interfaces to an MGCP Gateway

#### Introduction

- This note describes interoperability of the Nortel Meridian Option 11 PBX with Cisco Call Manager using Cisco C3640 Analog FXS/FXO interfaces as an MGCP Gateway.
- The Network Topology diagram shows the test set-up for end-to-end interoperability between the Cisco Call Manager connected to the PBX via Cisco 3640 analog FXS and FXO voice ports linked as an MGCP gateway.
- Connectivity is achieved first by using the analog FXS loop start voice port on the MGCP gateway to a loop start CO Trunk port on the Nortel Meridian Option 11 PBX. Then by using the analog FXO loop start voice port on the MGCP gateway to a loop start phone line (POTS) port on a Nortel Meridian PBX.
- Loop Start is used because the gateway FXS port does not support Ground Start in MGCP mode and with the gateway FXO configuration the PBX POTS circuit does not support Ground Start.
- The FXO port connected to the PBX POTS line answers the call (goes off-hook) before the dialed phone is answered, which stops the PBX from forwarding a call if the target phone does not answer.

#### **Network Topology**

## **Basic Call Setup End-to-End Configuration**



## Limitations

• FXS Ground\_Start Signaling.



- FXS Ground Start Signaling type is not supported on CCM MGCP Gateway configuration GUI.
- FXO Ground\_Start Signaling.
  - FXS Ground Start Signaling type is not supported on a PBX POTS Line.
- FXO Loop\_Start Signaling
  - The FXO gateway voice port goes off-hook on the first ring of an incoming seizure, before the targeted phone has answered. This disables the PBX from forwarding the incoming call on a ring-no-answer to voice-mail or other forward target. The PBX Analog extension does not support disconnect supervision which causes trunk hang issues and long ring-no answer times.

## System Components

#### **Hardware Requirements**

- Cisco C3640 Gateway with analog FXS & FXO Ports
- Cisco Cat6K switch
- Cisco Call Manager 3.2
- Nortel Meridian Option 11 Release 24 PBX.

## **Software Requirements**

- Cisco IOS Software Release
- • IOS software releases "c3640-js-mz.122-2.XN".
- • PBX Software Option 11 Release 24
- Cisco Call Manager 3.2
- PBX Software Release
- Cisco CallManager Release

## Configuration

## Configuring the Nortel Meridian Option 11 Rel. 24 PBX

```
CO Trunk Configuration
 >1d 20
DT0000
MARP NOT ACTIVATED
REQ: prtTYPE: tnbTN
                    10 01DATE PAGE DES
TN 010 0 00 01
TYPE COT
CDEN 8D
CUST 0
XTRK XUT
TIMP 600
BIMP 3COM
TRK ANLG
NCOS 0
RTMB 10 2
ATDN 2601
SIGL LOP
SUPN NO
AST NO
IAPG 0
CLS UNR DTN CND WTA LPR APN THFD
    P10 NTC LOL
TKID
DATE 19 MAY 2002
```



```
NACT ****
OVL000
>ld 21PT1000
REQ: prtTYPE: rdbCUST 0ROUT 10
TYPE RDB
CUST 00
DMOD
ROUT 10
DES ANALOG_LOOP_COT
TKTP COT
PRIV NO
SAT NO
RCLS EXT
DTRK NO
ISDN NO
PTYP ACO
AUTO YES
ICOG IAO
RANX NO
SRCH LIN
TRMB YES
STEP
ACOD 610
CPP NO
TARG 01
CLEN 1
BILN NO
OABS
TIMR ICF 512
OGF 512
     EOD 13952
     DSI 34944
     NRD 10112
     DDL 70
ODT 4096
     RGV 640
     FLH 510
     GRD 896
     SFB 3
     CRD 512
     TFD 0
     LEXT 100
SST 3 0
NEDC ETH
FEDC ORG
CPDC NO
SPCT IMM
HOLD 02 02 40
SEIZ 02 02
RGFL 02 02
RVSD 08 31
ILLR 02 02
DRNG NO
CDR NO
MUS NO
MR NO
MANO NO
EQAR NO
OHQ NO
OHQT 00
TTBL 0
OHTD NO
PLEV 2
MCTS NO
ALRM NO
ART 0
SGRP 0
```



PAGE 002

AACR NO

REQ: \*\*\*\*

OVL000

```
1d 10
PBX000
MARP NOT ACTIVATED
MEM AVAIL: (U/P): 1275886 USED U P: 104457 94216
                                                                 TOT: 1474559
DISK RECS AVAIL: 478
TISK RECS AVAIL: 478
TINS AVAIL: 73 USED: 127 TOT: 200
ACD AGENTS AVAIL: 300 USED: 0 TOT: 300
ANALOGUE TELEPHONES AVAIL: 2498 USED: 2 TO
AST AVAIL: 100 USED: 0 TOT: 100
WIRELESS TELEPHONES AVAIL: 2500 USED: 0 TO
                                                             TOT: 2500
                                                       0 TOT: 2500
REQ: prt
TYPE: 500
MARP NOT ACTIVATED
TN
     02
CDEN CUST TEN DATE PAGE DES
DES TEST1
TN 002 0 00 00
TYPE 500
CDEN 4D
CUST 0
WRLS NO
DN 2100 0
                  MARP
        NAME Nortel 500Phone 1
        XPLN 27
       DISPLAY_FMT FIRST, LAST
AST NO
IAPG 0
HUNT
TGAR 0
LDN NO
NCOS 0
SGRP 0
RNPG 0
XLST
SCI 0
CLS CTD DTN FBD XFD WTA THFD FND HTD ONS
      LPR XRD CWD SWD MWD RMMD SMWD LPD XHD CCSD LND TVD
      CFTD SFD MRD C6D CNID CLBD AUTU
      ICDD CDMD LLCN EHTD MCTD
      GPUD DPUD CFXD ARHD OVDD AGTD CLTD LDTD ASCD
      MBXD CPFA CPTA DDGA NAMA
      MCRD
      EXRO SHL ABDD CFHD DNDY DNO3
      CWND USMD USRD BNRD RTDD RBDD RBHD FAXD CNUD CNAD PGND FTTC
PLEV 02
AACS NO
MLWU_LANG 0
DATE 5 SEP 2000
```




```
DES TEST2
TN 002 0 00 01
TYPE 500
CDEN 4D
CUST 0
WRLS NO
DN 2101 0
                MARP
       NAME Nortel 500Phone 2
       XPLN 27
       DISPLAY_FMT FIRST,LAST
AST NO
IAPG 0
HUNT
TGAR 0
LDN NO
NCOS 0
SGRP 0
RNPG 0
XLST
CLS CTD DTN FBD XFD WTA THFD FND HTD ONS
LPR XRD CWD SWD MWD RMMD SMWD LPD XHD CCSD LND TVD
     CFTD SFD MRD C6D CNID CLBD AUTU
     ICDD CDMD LLCN EHTD MCTD
     GPUD DPUD CFXD ARHD OVDD AGTD CLTD LDTD ASCD
     MBXD CPFA CPTA DDGA NAMA
     MCRD
     EXRO SHL ABDD CFHD DNDY DNO3
     CWND USMD USRD BNRD RTDD RBDD RBHD FAXD CNUD CNAD PGND FTTC
PLEV 02
AACS NO
MLWU_LANG 0
DATE 5 SEP 2000
```


NACT



## **Configuring Cisco CallManager**











# **FXO Port Configuration**





## **Route Pattern Configuration**





#### Cisco C3640 Router Configuration

```
MGCP 3640#show ver
Cisco Internetwork Operating System Software
IOS (tm) 3600 Software (C3640-JS-M), Version 12.2(2)XN, EARLY DEPLOYMENT RELEASE
SOFTWARE (fc2)
TAC Support: http://www.cisco.com/tac
Copyright (c) 1986-2002 by cisco Systems, Inc.
Compiled Sat 02-Mar-02 17:12 by eaarmas
Image text-base: 0x600089A8, data-base: 0x61668000
TWARE (fc2)
MGCP_3640 uptime is 10 minutes
System returned to ROM by power-on
System image file is "flash:c3640-js-mz.122-2.XN"
cisco 3640 (R4700) processor (revision 0x00) with 58368K/7168K bytes of memory.
Processor board ID 10620494
R4700 CPU at 100Mhz, Implementation 33, Rev 1.0
Channelized E1, Version 1.0.
Bridging software.
X.25 software, Version 3.0.0.
SuperLAT software (copyright 1990 by Meridian Technology Corp).
TN3270 Emulation software.
Primary Rate ISDN software, Version 1.1.
2 Ethernet/IEEE 802.3 interface(s)
55 Serial network interface(s)
2 Channelized E1/PRI port(s)
2 Channelized T1/PRI port(s)
2 Voice FXO interface(s)
2 Voice FXS interface(s)
DRAM configuration is 64 bits wide with parity disabled.
125K bytes of non-volatile configuration memory.
16384K bytes of processor board System flash (Read/Write)
16384K bytes of processor board PCMCIA Slot0 flash (Read/Write) 20480K bytes of processor board PCMCIA Slot1 flash (Read/Write)
Configuration register is 0x2102
MGCP 3640#show running
Building configuration...
Current configuration: 2546 bytes
version 12.2
no parser cache
no service single-slot-reload-enable
service timestamps debug uptime
service timestamps log uptime
no service password-encryption
no service dhcp
hostname MGCP_3640
logging rate-limit console 10 except errors
voice-card 1
voice-card 3
ip subnet-zero
no ip domain-lookup
no ip dhcp-client network-discovery
mgcp call-agent 10.1.1.2 2427 service-type mgcp version 0.1
mgcp dtmf-relay voip codec all mode out-of-band
mgcp rtp unreachable timeout 1000 action notify
```



```
mgcp modem passthrough voip mode cisco
mgcp sdp simple
mgcp package-capability rtp-package
mgcp package-capability sst-package
no mgcp timer receive-rtcp
no mgcp explicit hookstate
isdn switch-type primary-ni
call rsvp-sync
ccm-manager mgcp
ccm-manager music-on-hold
ccm-manager config server 10.1.1.2
ccm-manager config
controller E1 1/0
 framing NO-CRC4
pri-group timeslots 1-31 service mgcp
controller E1 1/1
controller T1 3/0
framing esf
 linecode b8zs
 cablelength short 133
pri-group timeslots 1-24 service mgcp
controller T1 3/1
 framing sf
linecode ami
interface Ethernet0/0
 ip address 10.1.1.230 255.255.255.0
half-duplex
interface Ethernet0/1
no ip address
 shutdown
half-duplex
interface Serial1/0:15
no ip address
no logging event link-status
 isdn switch-type primary-net5
 isdn protocol-emulate network
 isdn incoming-voice voice
 isdn bind-13 ccm-manager
no cdp enable
interface Serial3/0:23
no ip address
 no logging event link-status
 isdn switch-type primary-dms100
 isdn incoming-voice voice
 isdn bind-13 ccm-manager
no cdp enable
ip classless
no ip http server
snmp-server manager
voice-port 2/0/0
voice-port 2/0/1
voice-port 2/1/0
timing hookflash-out 50
voice-port 2/1/1
 timing hookflash-out 50
```



```
dial-peer cor custom
dial-peer voice 201 pots
application mgcpapp
port 2/0/1
dial-peer voice 200 pots
application mgcpapp
port 2/0/0
dial-peer voice 210 pots
application mgcpapp
port 2/1/0
dial-peer voice 999200 pots
application mgcpapp
port 2/0/0
dial-peer voice 999201 pots
application mgcpapp
port 2/0/1
dial-peer voice 999210 pots
application mgcpapp
port 2/1/0
dial-peer voice 999211 pots
application mgcpapp
port 2/1/1
line con 0
line aux 0
line vty 0 4
login
end
```

## Important Information

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.







**Corporate Headquarters** 

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-4000

800 553-NETS (6387)

Fax: 408 526-4100

**European Headquarters** 

Cisco Systems International BVHaarlerbergpark

Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands www-europe.cisco.com

Tel: 31 0 20 357 1000 Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706

USA

www.cisco.com Tel: 408 526-7660 Fax: 408 527-0883 Asia Pacific Headquarters

Cisco Systems, Inc. Capital Tower 168 Robinson Road #22-01 to #29-01 Singapore 068912 www.cisco.com

Tel: +65 317 7777 Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at www.cisco.com/go/offices.

Argentina • Australia • Australia • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico• The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright 2003 Cisco Systems, Inc. All rights reserved. Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries. All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0301R)