

# Cisco 3640 Router - PBX Interoperability: Lucent/Avaya Definity G3si V9 PBX Interoperability with an E1 ISDN PRI Interface

## Introduction

- This note describes interoperability of the Cisco 3640 router connected to a Lucent/Avaya Definity G3si V9 PBX via E1 ISDN PRI interface.
- The Network Topology diagram shows the test set-up for end-to-end interoperability between Cisco 2651XM and Cisco 3640 connected to
  the PBX through an analog E&M signaling (2 wire audio operation with immediate start) voice port (VIC 2E/M) on one router
  (Cisco 2651XM) and E1 ISDN PRI interface on another router (Cisco 3640) with Alcatel 4400 R3.2 and Lucent/Avaya Definity G3si V9
  PBXs connected at each end.
- Connectivity is achieved by using the ETSI standard PRI protocol. The Lucent/Avaya Definity G3si can be configured as either network or
  user side.

Network Topology Figure 1. Network Topology

#### Basic Call Setup End-to-End Configuration ISDN Type: E&M (2 EMTL Trunk (E&M) wire audio PBX2: Lucent/Avaya ISDN PRI operatoin) -Definity G3si V9 **QSIG** 5001 3640 2651XM Phone A Phone C x3006 VolP x4001 Ш PBX #1 **PBX #2 PBX1:Alcatel 4400 R3.2** Phone B Phone E Phone D x3002 x 2000 x 3000 x4002



## Limitations

To place a VoIP call from analog phone on the Cisco 3640 router through the Cisco 2651XM router's E&M signaling (2 wire audio operation with immediate start) voice port to the Alcatel 4400 R3.2 PBX's EMTL Trunk and ring the Alcatel digital phone , "dtmf relay h245-alphanumeric" has to be enabled on the Cisco 3640 router.

## System Components

## **Hardware Requirements**

- Cisco 2651XM Gateway with VIC 2E/M, 800-02497-02B0
- Cisco 3640 Gateway with E1 interface cards
- Lucent/Avaya Definity G3si V9 PBX, TN464F, DS1 INTFC 24/32

## **Software Requirements**

- Cisco IOS Software Release 12.2(11)T
- •

# Configuration


## **Configuration Tasks**

- Configure DS1 Circuit Pack
- Configuring Signaling Group
- Configure Trunk Group
- Configure Trunk Features
- Configure Trunk Group
- Configure Dial Plan Record




# Configuring the Lucent/Avaya Definity G3si V9 PBX Configuration

**DS1 Circuit Pack** 





# Signaling Group






# Trunk Group

DEFINITY® Site Administration - [AvayaV9 GEDI]     The Fifth Norw Control Antique Tools Nordern Links	
File Edit View System Action Iools Window Help	
[	
change trunk-group 14 💌 send (return) help (f5) cancel (esc) enter (f3) schedule (f9) next (f7) pre-	vious (f8) next form (f6)
1 2 3 4 5 6 7 8 9 10	
TRUNK GROUP	
Group Number: 14 Group Type: isdn CDR Reports: y	
Group Name: E1 ISDN COR: 1 TN: 1 TAC: 669	
Direction: two-way Outgoing Display? y Dial Access? y Busy Threshold: 99 Night Service:	۱
Queue Length: 0	_
Service Type: tandem TestCall ITC: rest	
Far End Test Line No:	
TestCall BCC: 4	
TRUNK PARAMETERS	
Codeset to Send Display: 7 Codeset to Send National IEs: 7  Max Message Size to Send: 260 Charge Advice: none	
Supplementary Service Protocol: c Digit Handling (in/out): enbloc/enbloc	7
Trunk Hunt: ascend	
Digital Loss Group: 13	_
Calling Number - Delete: Insert: Numbering Format: Bit Rate: 1200 Synchronization: async Duplex: Full	J
Disconnect Supervision - In? y Out? y	
Answer Supervision Timeout: 0	
<u></u>	
Right-click in a field to see a list of valid entries or help text	
Ready	NUM //




## **Trunk Features**






## Trunk Group










## Dial Plan Record





## Configuring the Cisco 3640 Router

```
3640_Analog#sh run
Building configuration...
Current configuration: 2298 bytes
version 12.2
no parser cache
service timestamps debug uptime service timestamps log uptime
no service password-encryption
no service dhcp
hostname 3640_Analog
no logging buffered
voice-card 1
ip subnet-zero
no ip domain lookup
isdn switch-type primary-net5
isdn voice-call-failure 0
voice call carrier capacity active
{\tt mta} receive {\tt maximum-recipients} 0
controller E1 1/0
 framing NO-CRC4
 ds0-group 1 timeslots 1 type e&m-immediate-start
controller E1 1/1
pri-group timeslots 1-31
interface Ethernet0/0
 ip address 10.10.10.102 255.255.255.0
 no ip mroute-cache
 shutdown
 full-duplex
no cdp enable
interface Ethernet0/1
 ip address 1.1.1.1 255.255.255.0
 no ip mroute-cache
 full-duplex
no cdp enable
interface Serial1/1:15
 no ip address
no logging event link-status isdn switch-type primary-net5
 isdn overlap-receiving
 isdn protocol-emulate network
 isdn incoming-voice voice
 no cdp enable
interface BRI2/0
 no ip address
 isdn switch-type basic-qsig
isdn protocol-emulate network
 isdn layer1-emulate network
```



```
isdn incoming-voice voice
 isdn static-tei 0
 isdn skipsend-idverify
interface BRI2/1
no ip address
 shutdown
 isdn switch-type basic-qsig
 isdn overlap-receiving
isdn incoming-voice voice
ip classless
no ip http server
no cdp run
snmp-server manager
call rsvp-sync
voice-port 1/0:1
shutdown
voice-port 1/1:15
voice-port 2/0/0
voice-port 2/0/1
voice-port 3/0/0
voice-port 3/0/1
voice-port 3/1/0
voice-port 3/1/1
no mgcp timer receive-rtcp
mgcp profile default
dial-peer cor custom
dial-peer voice 1 pots
 shutdown
 destination-pattern 5...
direct-inward-dial
port 2/0/0
forward-digits all
dial-peer voice 2 voip
destination-pattern 2...
 session target ipv4:1.1.1.2
dial-peer voice 3 pots
destination-pattern 3000
port 3/0/0
dial-peer voice 4 pots
destination-pattern 3001
port 3/0/1
dial-peer voice 5 pots
 shutdown
destination-pattern 3...
progress_ind setup enable 1
direct-inward-dial
port 2/0/1
 forward-digits all
```



```
dial-peer voice 6 pots
destination-pattern 4...
port 1/1:15
prefix 4
dial-peer voice 7 voip
destination-pattern 5...
 session target ipv4:1.1.1.2
dtmf-relay h245-alphanumeric
line con 0
line aux 0
line vty 0 4
login
end
```

## Important Information

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE, ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.



# **Corporate Headquarters**

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-4000 800 553-NETS (6387) Fax: 408 526-4100

## **European Headquarters**

Cisco Systems International BVHaarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands www-europe.cisco.com Tel: 31 0 20 357 1000 Fax: 31 0 20 357 1100

# Americas Headquarters

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com

Tel: 408 526-7660 Fax: 408 527-0883

# Asia Pacific Headquarters

Cisco Systems, Inc. Capital Tower 168 Robinson Road #22-01 to #29-01 Singapore 068912 www.cisco.com

Tel: +65 317 7777 Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at www.cisco.com/go/offices.

Argentina • Australia • Australia • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico• The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright 2003 Cisco Systems, Inc. All rights reserved. Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries. All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0301R)