


Cisco 3745 Gateway - PBX Interoperability: Avaya Definity G3 PBX using Q.931 PRI User Side Interfaces to an H.323 Gateway

Introduction

- This Application Note describes the interoperability of a Cisco 3745 gateway and an Avaya Definity G3 PBX using Q.931 PRI user-side interfaces.
- The network topology diagram shows the end-to-end interoperability when configured for back-to-back VoIP operation.

Network Topology

Basic Test Configuration



System Components

Hardware Requirements

- Cisco 3745 modular access router with a 1MFT-T1 interface card
- Avaya Definity G3r PBX

Software Requirements

- Cisco IOS Software Release 12.2(15)ZJ
- Avaya Definity G3r G3V7i.01.0.343.7




Configuration

Configuring the Avaya Definity G3r

Configure the PBX in the following sequence:


- CO Trunk
- Trunk Group
- Signaling Group
- Dial Plan Record
- Optional Features

Configuring the CO Trunk






Configuring the CO Trunk (2 of 2)






Configuring the Trunk Group (1 of 3)






Configuring the Trunk Group (2 of 3)






Configuring the Trunk Group (3 of 3)






Configuring the Signaling Group






Configuring the Dial Plan Record (1 of 2)






Configuring the Dial Plan Record (2 of 2)






Configuring Optional Features (1 of 2)





Configuring Optional Features (2 of 2)



Configuring the Cisco 3745

```
C3745XM#show running-config
Building configuration...

Current configuration: 1986 bytes!

version 12.2

service timestamps debug uptime
service timestamps log uptime
no service password-encryption!
hostname c3745!
boot system flash:c3745-jsx-mz-v122_15_zj_throttle.0.5.0
logging queue-limit 100
logging buffered 1000000 debugging!
ip subnet-zero!
no ip domain lookup!
mpls ldp logging neighbor-changes
```



```
isdn switch-type primary-ni
voice-card 2
no dspfarm
voice-card 3
no dspfarm
voice-card 4
no dspfarm
!
!
no voice hpi capture buffer
no voice hpi capture destination
mta receive maximum-recipients 0
controller T1 2/0
 framing esf
 linecode b8zs
pri-group timeslots 1-5,24
controller T1 2/1
 framing esf
 linecode b8zs
pri-group timeslots 1-5,24
interface FastEthernet0/0
 ip address 172.16.1.1 255.255.255.0
 duplex auto
 speed auto
interface FastEthernet0/1
 ip address 172.20.8.20 255.255.255.0
 duplex auto
 speed auto
interface Serial2/0:23
 no ip address
 no logging event link-status
 isdn switch-type primary-ni
 isdn incoming-voice voice
 isdn bchan-number-order ascending
no cdp enable
interface Serial2/1:23
 no ip address
 no logging event link-status
 isdn switch-type primary-ni
 isdn incoming-voice voice
 isdn bchan-number-order ascending
 no cdp enable
ip default-gateway 10.1.1.2
ip http server
ip classless
ip route 0.0.0.0 0.0.0.0 FastEthernet0/1
call rsvp-sync
voice-port 2/0:23
```



```
voice-port 2/1/0
voice-port 2/1/1
!
voice-port 2/1:23
!
voice-port 4/1/0
no battery-reversal
voice-port 4/1/1
mgcp profile default
dial-peer cor custom
dial-peer voice 1 pots
 destination-pattern 20...
 direct-inward-dial
 port 2/1:23
prefix 20
dial-peer voice 3 voip
 destination-pattern 26..
 session target ipv4:172.16.1.2
dial-peer voice 4 voip
 destination-pattern 4000
 session target ipv4:172.16.1.2
dial-peer voice 2 pots
 destination-pattern 3000
port 2/1/1
line con 0
line aux 0
line vty 0 4
login
end
```

Important Information

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.





Corporate Headquarters

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA

www.cisco.com

800 553-NETS (6387)

Fax: 408 526-4100

Tel: 408 526-4000

European Headquarters

Cisco Systems International BV Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam

The Netherlands www-europe.cisco.com

Fax: 31 0 20 357 1100

Tel: 31 0 20 357 1000

Cisco Systems, Inc.

170 West Tasman Drive San Jose, CA 95134-1706

Americas Headquarters

USA

www.cisco.com Tel: 408 526-7660 Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc. Capital Tower 168 Robinson Road #22-01 to #29-01 Singapore 068912 www.cisco.com

Tel: +65 317 7777 Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at www.cisco.com/go/offices.

Argentina • Australia • Australia • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico• The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright 2003 Cisco Systems, Inc. All rights reserved. Cisco, Cisco Systems, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries. All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0301R)