

# Mitel 3300 ICP Release 7.1 Using SIP to Cisco Unified Communications Manager 6.1

# June 18, 2008 - Initial Version

## **Table of Contents**

Introduction	2
Network Longlogy	
Limitations	3
System Components	
Hardware Requirements	4
Software Requirements Features	<del>(</del>
Features Supported	<i>6</i>
Features Supported	<del>(</del>
Configuration.	
Configuring the Mitel 3300 ICP Release 7.1	
Configuring the Cisco Unified Communications Manager 6.1	
Configuring Mailboxes on Cisco Unity	
Acronyms	




#### Introduction

- This application note provides interoperability information and documented configurations for a SIP trunk connection between a Mitel 3300 ICP Release 7.1 and Cisco Unified Communications Manager 6.1. End-to-end calls were made to verify basic calls and other features. Figure 1 shows the integration topology.
- The following basic call and supplementary services features were verified: proper establishing and disconnecting of calls; calling name and number presentation and restriction; alerting name; call transfer (consultation and early-attended); call forwarding (all, busy, and no reply); call hold; call conference; and voicemail access with MWI activation and deactivation. Please note that this document does not address performance and scalability, which are part of a broader criteria for a deployment-ready solution.

# **Network Topology**

Figure 1. Basic Call Setup





## Limitations

These are the known limitations, caveats, or integration issues with the specified configuration:

- The Mitel 3300 ICP SIP Session Timer value must equal or exceed the Cisco Unified Communications Manager 6.1 SIP Min-SE Value service parameter. The Min-SE Value can be found under the Cisco Unified Communications Manager Service Parameters form. The Mitel SIP Session Timer can be found on the SIP Peer Profile form. Screenshots of both of these forms are provided on pages 11and 126, respectively.
- The Cisco Unified IP Phones and Mitel IP phones depicted in this integration do not support a true blind transfer, but rather, an "early attended" transfer. The difference is that a party initiating a blind transfer drops out before the final destination starts ringing. To do a blind transfer, the IP phones must have a specific button or soft key. An early attended transfer initiates the transfer, gets ringback, and then completes the transfer before the final destination answers. Some Cisco Unified IP Phones (for example, 7940 and 7960 with SIP loads) do support blind transfer.
- The Mitel 3300 ICP did not have a MoH source, so MoH was not verified in this configuration. Cisco Unified Communications Manager did have a MoH source, and it worked properly with both Cisco and Mitel extensions.
- A call from a Mitel extension to a Cisco Unified IP Phone that is forwarded to voice mail hits the "open greeting" and not the proper voice mailbox. This is due to the diversion header difference between Cisco Unified Communications Manager and the Mitel 3300 ICP. Therefore, a full voice mail integration using the Mitel 3300 ICP voice mail system was not possible.
- A full voice mail integration using Cisco Unity was possible, and Message Waiting Indication (MWI) works properly. However, the
  Mitel 5220 IP handset has a feature where a "message" soft key appears, and the user can use it to go directly to voice mail. This soft key
  does not appear for voice mail and/or MWI from Unity. The Mitel user has to dial the VM pilot number to access voicemail. This could
  easily be programmed into a button on the Mitel handset.
- Differences between the SIP implementations of Calling / Connected Line Identification on the Mitel 3300 ICP Release 7.1 and Cisco Unfied Communications Manager 6.1 affect a variety of interoperability test cases. Cisco Unfied Communications Manager 6.1 uses Remote Party ID for calling party information, and the Mitel 3300 ICP does not. Diversion headers are structured differently between the two systems. The following points summarize the differences and the limitations that arise from these differences.
  - The Mitel 3300 ICP does not use P-Asserted Identity (PAI) or Remote-Party-ID (RPID) for Caller ID information. The calling party information (both name and number) is in the "From" and "Contact" fields in the INVITE message. The called party information is in the "To" (number only) and "Contact" (both name and number) fields in the 180 Ringing message. The connected party information is in the "To" (number only) and "Contact" (both name and number) fields in the 200 OK message.
  - Cisco Unified Communications Manager 6.1 uses Remote-Party-ID (RPID) in addition to the the "From" and "Contact" fields for Caller ID information. The calling party information (both name and number) is in the "From" field and RPID in the INVITE message. The calling number is also in the "Contact" field. The called party information is in the "To" (number only) and "Contact" fields (number only) and in the RPID (both name and number) in the 180 Ringing and in 183 Session Progress messages. The connected party information is in the "To" (number only) and "Contact" fields (number only) and in the RPID (both name and number) in the 200 OK message.
  - The Mitel 3300 ICP Release 7.1 and Cisco Unified Communications Manager 6.1 both send forwarding info in a Diversion header. However the Mitel diversion header has the structure: Diversion:<sip:15221@172.20.220.254>;reason=unconditional;counter=1, while the Cisco Unified Communications Manager diversion header has this structure: Diversion: "Alert-C2" <sip:6013 @172.20.214.254>;reason=user-busy;privacy=off,screen=yes. This issue impacts Calling Name/Number ID on forwarded calls and voice mail scenarios where a Mitel extension calls a Cisco Unified IP Phone that forwards to Mitel voice mail. This causes the originating Mitel extension to hit the "open greeting" in Mitel voice mail, instead of the proper voice mailbox for the Cisco Unified IP Phone.
  - Connected Name and Number are not supported between the two systems.
  - Calling Line ID is not supported on Network/External Transfers.



- Original calling number is not displayed on the final destination on calls originating from a Cisco Unified IP Phone to a Mitel extension and forwarded locally to another Mitel extension (for example, C1 calls A1 and A1 forwards to B1.) The originator's name is displayed, however, after answer. This is not an issue for the reverse call flow (for example, A1 calls C1, and C1 forwards to D1). The Mitel IP phones display the originator information after a forwarded call is answered, even if all parties are local.
- Neither forwarding name nor number is displayed on the final destination on calls originating from a Mitel extension to a Cisco Unified IP Phone and forwarded externally to another Mitel extension (for example, A1 calls C1, and C1 forwards to B1). This is not an issue for the reverse call flow (for example, C1 calls A1, and A1 forwards to D1). In those cases, forwarding number is displayed. This is likely due to the different structures in the diversion header.
- For Local Call Conferences originated from a network/external call (for example, C1 calls A1, and A1 conferences in B1; A1 calls C1, and C1 conferences in D1), the Caller ID was not updated properly. The conferencing phone and the third phone properly displayed "conference" during a three-way conference call, but the originating phone displayed the dialed number. After the conferencing phone dropped out, the third phone displayed the originator's name (and number, if the third phone was a Cisco Unified IP Phone), but the originator still displayed dialed number.
- For Network/External Call Conferences originating from a local call (for example, C1 calls A1, and A1 calls D1; A1 calls C1, and C1 conferences in B1), the Caller ID was not properly updated. The conferencing phone properly displayed "conference" during a three-way conference call, but the originating phone displayed the dialed number, and the third phone displayed the conferencing party's name (and number, if the third phone was a Cisco Unified IP Phone). These disaplays did not change when the conferencing phone dropped out.



# **System Components**

# **Hardware Requirements**

The following hardware is required:

- Two Cisco Media Convergence Servers 7800
- Catalyst 3560 PoE switch
- Two Cisco Unified IP Phones 7961
- Two Cisco Unified IP Phones 7960
- Mitel 3300 MX Controller
- Two Mitel 5220 IP phones

# **Software Requirements**

The following software is required:

- Cisco Unified Communications Manager Release 6.1
- Cisco Unity Release 5.0(1)
- Mitel 3300 ICP Release 7.1 UR2



#### **Features**

This section lists supported and unsupported features.

# **Features Supported**

- Basic Call
- Disconnect Supervision
- Calling Line (Number) Identification Presentation (CLIP)
- Calling Line (Number) Identification Restriction (CLIR)
- Calling Name Identification Presentation (CNIP)
- Calling Name Identification Restriction (CNIR)
- Consultation Transfer Local and Network/External
- Early-Attended Transfer Local and Network/External
- Call Forward Unconditional Local and Network/External
- Call Forward on Busy Local and Network/External
- Call Forward on No Answer Local and Network/External
- Call Hold and Resume with MoH See Limitations section on page 3.
- Call Conference Local and Network/External See Limitations section on page 3.
- Voice Mail integration with Cisco Unity, including MWI

## **Features Not Supported**

- Connected Line (Number) Identification Presentation (COLP)
- Connected Name Identification Presentation (CONP)
- Alerting Name
- Blind Transfer
- Voice Mail Integration with the Mitel 3300 ICP as Message Center PINX



# Configuration

This section contains configuration menus and commands and describes configuration sequences and tasks.


## Configuring the Mitel 3300 ICP Release 7.1

Software Version

The specific software version was 7.1.5.13.

# System IP Configuration


## System IP Configuration - 1 of 1.






## SIP Trunk Setup

## Network Element Assignment – 1 of 2.






#### **Network Element Assignment – 2 of 2.**






# System IP Port Assignment – 1 of 1.






#### SIP Peer Profile - 1 of 2.

Note: The Mitel 3300 ICP SIP Session Timer value must equal or exceed the Cisco Unified Communications Manager 6.1 SIP Min-SE Value. The range for the Mitel 3300 ICP SIP Session Timer is 90 – 9999 seconds, and the default is 90 seconds. The range for the Cisco Unified Communications Manager 6.1 SIP Min-SE Value is 60 – 86400 seconds, and the default is 1800 seconds. The value shown here is 240 seconds, because that was the value on Cisco Unified Communications Manager 6.1 at the time of testing. However, if the Cisco Unified Communications Manager 6.1 SIP Min-SE Value had been set to default, the Mitel SIP Session Timer value would have been set to 1800 – 9999. See note on page 126.






#### SIP Peer Profile - 2 of 2.






# SIP Peer Profile Assignment by Incoming DID-1 of 1.






### Trunk Service Assignment-1 of 1.






## Routing

## ARS Digits Dialed Assignment - 1 of 1.






## ARS Leading Digits Assignment – 1 of 1.






Route Assignment: Route 1 to Cisco Unified Communications Manager 6.1 – 1 of 1.






# Digit Modification Assignment - 1 of 1.






#### Classes of Service

## Main COS Form - 1 of 1.






#### COS-Trunks - 1 of 6.






#### COS-Trunks - 2 of 6.






#### COS-Trunks - 3 of 6.






#### COS-Trunks - 4 of 6.






#### COS-Trunks - 5 of 6.






#### COS-Trunks - 6 of 6.






#### COS-Phones - 1 of 6.






#### COS-Phones - 2 of 6.






#### COS-Phones - 3 of 6.






#### COS-Phones - 4 of 6.






#### COS-Phones - 5 of 6.






#### COS-Phones - 6 of 6.





#### Interconnect Restriction


#### Interconnect Restriction - 1 of 1.






## Feature Access Codes

#### Feature Access Codes - 1 of 6.






# Feature Access Codes - 2 of 6.






#### Feature Access Codes - 3 of 6.






#### Feature Access Codes - 4 of 6.






### Feature Access Codes - 5 of 6.






### Feature Access Codes - 6 of 6.






### System Options

### System Options - 1 of 2.






### System Options – 2 of 2.





### Caller ID Restriction


### CLIR on SIP Peer Profile form - 1 of 1.






#### Extensions

### IP Telephones – 1 of 1.






# User Configurations - 1 of 1.






### User 15221 Configuration - 1 of 2.






### User 15222 Configuration - 2 of 2.






Voice Mail

### **Hunt Groups – 1 of 3.**






#### **Hunt Groups – 2 of 3.**






#### **Hunt Groups – 3 of 3.**






## **Voice Mail Options Assignment – 1 of 1.**






#### **Voice Mail Port Assignment – 1 of 1.**






### Voice Mailbox Configuration - 1 of 2.






## Voice Mailbox Configuration - 2 of 2.






#### **Voice Mailbox 15221 Configuration – 1 of 2.**





## Voice Mailbox 15221 Configuration - 2 of 2.






## Configuring the Cisco Unified Communications Manager 6.1

Software Version

#### Software Version - 1 of 1.




This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at: <a href="http://www.cisco.com/wwl/export/crypto/tool/stqrq.html">http://www.cisco.com/wwl/export/crypto/tool/stqrq.html</a>. If you require further assistance please contact us by sending email to export@cisco.com.




## SIP Profile

## Default SIP Profile - 1 of 2.






### Default SIP Profile - 2 of 2.






SIP Trunk

### SIP Trunk - 1 of 2.






### SIP Trunk - 2 of 2.






### Route Patterns

### Route Patterns - 1 of 1.






#### 152XX Route Pattern - 1 of 2.






#### 152XX Route Pattern - 2 of 2.

**Note:** There is no prefix digit "1" in this route pattern, because a 5-digit route pattern (1522X) was used to map directly from Cisco Unified Communications Manager 6.1 to the Mitel 3300 ICP.






### 66XX Route Pattern (with Calling Party Transform Mask) for Mitel 3300 ICP Voice Mail - 1 of 2.





### 1522X Route Pattern (with Calling Party Transform Mask) for Mitel 3300 ICP Voice Mail - 2 of 2.


Note: The prefix digit "1" was used to adapt the Cisco Unified Communications Manager number plan, which contained 4 digits, to the Mitel 3300 ICP number plan, which contained 5 digits. The Mitel voice mailboxes can not vary in length, and they are set up to match the length of the Mitel extensions, which are 5 digits. Voice mailboxes for Cisco Unified Communications Manager extensions were set up on the Mitel 3300 ICP with an additional "1". For instance, voice mailbox "16024" corresponds to Cisco Unified Communications Manager extension "6024". The prefix digit "1" in this route pattern exists so that the correct number will be sent to the Mitel 3300 ICP in the SIP INVITE.





# Calling Line ID Restriction


### CLIR on 522X Route Pattern - 1 of 1.






### **Translation Patterns**

## Translation Patterns - 1 of 1.






### Translation Pattern 60XX for Cisco Unified IP Phones - 1 of 1.






#### IP Phones

# IP Phones – 1 of 1.






### Cisco Unified IP Phone 7960, x6024, SCCP - 1 of 4.






Cisco Unified IP Phone 7960, x6024, SCCP - 2 of 4.






Cisco Unified IP Phone 7960, x6024, SCCP - 3 of 4.






Cisco Unified IP Phone 7960, x6024, SCCP - 4 of 4.






### Line 6024 - 1 of 4.






### Line 6024 - 2 of 4.

Line is currently forwarded to x15222 on Busy or No Answer.






### Line 6024 - 3 of 4.






### Line 6024 - 4 of 4.






# Cisco Unified IP Phone 7961, x6013, SIP - 1 of 5.






### Cisco Unified IP Phone 7961, x6013, SIP - 2 of 5.






### Cisco Unified IP Phone 7961, x6013, SIP – 3 of 5.






Cisco Unified IP Phone 7961, x6013, SIP - 4 of 5.






### Cisco Unified IP Phone 7961, x6013, SIP - 5 of 5.






### Line 6013 - 1 of 4.






### Line 6013 - 2 of 4.

Line is currently forwarded to x15222 on Busy or No Answer.






### Line 6013 - 3 of 4.






### Line 6013 - 4 of 4.






Voice Mail Integration (with Cisco Unity)

# List Hunt Pilots – 1 of 1.






### Hunt Pilot 3000 - 1 of 2.






### **Hunt Pilot 3000 - 2 of 2.**






### Hunt Lists – 1 of 1.






# Hunt List for Cisco Unity - 1 of 1.






# Line Groups - 1 of 1.






# Line Group for Cisco Unity - 1 of 2.






# Line Group for Cisco Unity - 2 of 2.






# Line Group Member 3001 – 1 of 2.






### Line Group Member 3001 – 2 of 2.






### Voice Mail Profiles - 1 of 1.






### Unity Voice Mail Profile - 1 of 1.






### Voice Mail Pilots - 1 of 1.






Voice Mail Pilot 3000 (for Cisco Unity) - 1 of 1.






#### Voice Mail Ports - 1 of 1.






### Voice Mail Port 3001 - 1 of 1.






### MWI Numbers - 1 of 1.






#### MWI On Number – 1 of 1.




# MWI Off Number - 1 of 1.






### Resources

Media Resource Group Lists - 1 of 1.






# Media Resource Group List Details - 1 of 1.






### Media Resource Groups - 1 of 1.






### Media Resource Group Details-1 of 1.






# Conference Bridges - 1 of 1.






### Conference Bridge Details - 1 of 1.






### Media Termination Points - 1 of 1.






### Media Termination Point Details - 1 of 1.






### MoH Audio Sources - 1 of 1.






#### MoH Audio Source Details-1 of 1.






### MoH Servers - 1 of 1.






### MoH Server Details-1 of 1.






### Fixed MoH Audio Source Configuration - 1 of 1.






### Service Parameters

### Service Parameters - 1 of 19.






#### Service Parameters – 2 of 19.






### Service Parameters - 3 of 19.






#### Service Parameters - 4 of 19.






#### Service Parameters - 5 of 19.






### Service Parameters - 6 of 19.






# Service Parameters - 7 of 19.






### Service Parameters - 8 of 19.






### Service Parameters - 9 of 19.






#### Service Parameters – 10 of 19.

Note: The Mitel 3300 ICP SIP Session Timer value must equal or exceed the Cisco Unified Communications Manager 6.1 SIP Min-SE Value. The range for the Mitel SIP Session Timer is 90 – 9999 seconds, and the default is 90 seconds. The range for the Cisco Unified Communications Manager 6.1 SIP Min-SE Value is 60 – 86400 seconds, and the default is 1800 seconds. The value shown here is 240 seconds, because that reflects the value on Cisco Unified Communications Manager 6.1 at the time of testing. However, if the Cisco Unified Communications Manager 6.1 SIP Min-SE Value had been set to default, the Mitel SIP Session Timer value would have been set to 1800 – 9999. In general, it is recommended to follow the default values on Cisco Unified Communications Manager Service Parameters. See note on page 11.






# Service Parameters – 11 of 19.






#### Service Parameters – 12 of 19.






#### Service Parameters – 13 of 19.






#### Service Parameters – 14 of 19.






# Service Parameters – 15 of 19.






#### Service Parameters – 16 of 19.






# Service Parameters – 17 of 19.






### Service Parameters - 18 of 19.






# Service Parameters - 19 of 19.






# **Configuring Mailboxes on Cisco Unity**

Subscriber Profile - 1 of 1.





### Subscriber Messages - 1 of 1.





# Acronyms

Acronym	Definition
CUCM	Cisco Unified Communications Manager
CCBS	Call Completion to Busy Subscriber
CCNR	Call Completion on No Reply
CFB	Call Forwarding on Busy
CFNR	Call Forwarding No Reply
CFU	Call Forwarding Unconditional
CLIP	Calling Line (Number) Identification Presentation
CLIR	Calling Line (Number) Identification Restriction
CNIP	Calling Name Identification Presentation
CNIR	Calling Name Identification Restriction
COLP	Connected Line (Number) Identification Presentation
COLR	Connected Line (Number) Identification Restriction
CONP	Connected Line (Name) Identification Presentation
CONR	Connected Line (Name) Identification Restriction
MWI	Message Waiting Indication
PAI	P-Asserted Identity
RPID	Remote Party ID
SCCP	Skinny Client Control Protocol
SIP	Session Initiation Protocol



#### Important Information

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.



# Corporate Headquarters

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA www.cisco.com Tel: 408 526-4000

800 553-NETS (6387)

Fax: 408 526-4100

# European Headquarters

Cisco Systems International BV

Haarlerbergpark Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands www-europe.cisco.com

Tel: 31 0 20 357 1000 Fax: 31 0 20 357 1100

# Americas Headquarters

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706

www.cisco.com Tel: 408 526-7660 Fax: 408 527-0883

# Asia Pacific Headquarters

Cisco Systems, Inc. Capital Tower 168 Robinson Road #22-01 to #29-01 Singapore 068912 www.cisco.com Tel: +65 317 7777 Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at <a href="https://www.cisco.com/go/offices">www.cisco.com/go/offices</a>.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

© 2008 Cisco Systems, Inc. All rights reserved.

CCDE, CCENT, Cisco Eos, Cisco Lumin, Cisco Nexus, Cisco StadiumVision, the Cisco logo, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn is a service mark; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0805R)