



# Cisco Unified IP Conference Station 7935 Release Notes for Firmware Release 3.2(19) (SCCP)

---

**July 7, 2008**

Use these release notes with a Cisco Unified IP Conference Station 7935 running SCCP firmware release 3.2(19).

The SCCP version of firmware release 3.2(19) is compatible with Cisco Unified Communications Manager releases 6.1, 6.0, 5.1, 5.0, 4.3, 4.2, 4.1, 4.0, 3.3, 3.2, and 3.1.

## Contents

These release notes provide the following information:

- [Related Documentation, page 1](#)
- [New and Changed Information, page 2](#)
- [Installation Notes, page 2](#)
- [Caveats, page 3](#)
- [Obtaining Documentation and Submitting a Service Request, page 6](#)

## Related Documentation

### **Cisco Unified IP Phone Documentation**

Refer to publications that are specific to your language, phone model and Cisco Unified Communications Manager release. Navigate from the following documentation URL:

[http://www.cisco.com/en/US/products/sw/voicesw/tsd\\_products\\_support\\_category\\_home.html](http://www.cisco.com/en/US/products/sw/voicesw/tsd_products_support_category_home.html)



---

**Americas Headquarters:**  
**Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA**

© 2008 Cisco Systems, Inc. All rights reserved.

**Cisco Unified Communications Manager Documentation**

Refer to the Cisco Unified Communications Manager Documentation Guide and other publications specific to your Cisco Unified Communications Manager release. Navigate from the following URL:

[http://www.cisco.com/en/US/products/sw/voicesw/ps556/tsd\\_products\\_support\\_series\\_home.html](http://www.cisco.com/en/US/products/sw/voicesw/ps556/tsd_products_support_series_home.html)

**Cisco Unified Communications Manager Business Edition Documentation**

Refer to the Cisco Unified Communications Manager Business Edition Documentation Guide and other publications that are specific to your Cisco Unified Communications Manager release. Navigate from the following URL:

[http://www.cisco.com/en/US/products/ps7273/tsd\\_products\\_support\\_series\\_home.html](http://www.cisco.com/en/US/products/ps7273/tsd_products_support_series_home.html)

## New and Changed Information

There is no new or changed information for firmware release 3.2(19).

## Installation Notes

To load and install the required firmware image for the Cisco Unified IP Conference Station 7935 on Cisco Unified Communications Manager 6.1, 6.0, 5.1, 5.0, 4.3, 4.2, 4.1, 4.0, 3.3, 3.2, and 3.1, follow these steps:

**Procedure**

- 
- Step 1** Go to the following URL:
- <http://tools.cisco.com/support/downloads/pub/Redirect.x?mdfid=278875240>
- Step 2** To download the firmware for Cisco Unified IP Conference Station 7935, click one of the following hyperlinks and follow the prompts:
- For Cisco Unified CallManager 4.3 and earlier:  
**cmterm-7935-sccp.3-2-19.exe**
  - For Cisco Unified CallManager 5.0(1) to 5.0(3):  
**cmterm-7935-sccp.3-2-19.cop**
  - For Cisco Unified CallManager 5.0(4) and higher:  
**cmterm-7935-sccp.3-2-19.cop.sgn**
- Step 3** To download the Readme file, which contains installation instructions for the corresponding firmware, go back to the URL shown in Step 1 and click the appropriate hyperlink.
- cmterm-7935-sccp.3-2-19-readme.htm**
- Step 4** Follow the instructions in the Readme file to install the firmware.
-

## Registering the Cisco Unified IP Conference Station with Cisco Unified Communications Manager

For more information about configuring the Cisco Unified IP Conference Station and directory numbers, refer to the *Cisco Unified Communications Manager Administration Guide*, Phone Configuration and Directory Number configuration chapters.

To register the Cisco Unified IP Conference Station 7935 with Cisco Unified Communications Manager release 6.1, 6.0, 5.1, 5.0, 4.3, 4.2, 4.1, 4.0, 3.3, 3.2, and 3.1, follow these steps:

### Procedure

- 
- Step 1** Log in to the Cisco Unified Communications Manager Administration application.
- Step 2** For Cisco Unified Communications Manager 4.3 and earlier:
- From the menu bar, choose **Device > Add a New Device**
- For Cisco Unified Communications Manager 5.0 and later:
- From the menu bar, choose **Device > Phone > Add New**
- The Add a New Device window appears.
- Step 3** Select **Phone** from the Device Type drop-down menu and click **Next**.
- The Add a New Phone window appears.
- Step 4** Select the Cisco 7935 phone type from the drop-down menu and click **Next**.
- The Phone Configuration window appears.
- Step 5** In the Phone Configuration window, enter information in the mandatory fields, denoted with an ‘\*’, such as MAC and Device Pool.
- Step 6** For Cisco Unified Communications Manager 4.3 and earlier:
- Click **Insert**
- For Cisco Unified Communications Manager 5.0 and later:
- Click **Save**
- The Cisco Unified Communications Manager Administration application asks if you want to assign a directory number.
- Step 7** Enter the required fields.
- 

## Caveats

This section contains these topics:

- [Using Bug Toolkit, page 4](#)
- [Open Caveats, page 4](#)
- [Resolved Caveats, page 4](#)

## Using Bug Toolkit

Known problems (bugs) are graded according to severity level. These release notes contain descriptions of:

- All severity level 1 or 2 bugs.
- Significant severity level 3 bugs.

You can search for problems by using the Cisco Software Bug Toolkit.

To access Bug Toolkit, you need the following items:

- Internet connection
- Web browser
- Cisco.com user ID and password

To use the Software Bug Toolkit, follow these steps:

### Procedure

---

- Step 1** To access the Bug Toolkit, go to <http://tools.cisco.com/Support/BugToolKit/action.do?hdnAction=searchBugs>.
- Step 2** Log on with your Cisco.com user ID and password.
- Step 3** To look for information about a specific problem, enter the bug ID number in the “Search for bug ID” field, then click **Go**.
- 

## Open Caveats

There are no open defects for the Cisco Unified IP Conference Station 7935 using the SCCP version of firmware release 3.2(19).

## Resolved Caveats

[Table 1](#) lists Severity 1, 2 and 3 defects that are resolved for the Cisco Unified IP Conference Station 7935 using the SCCP version of firmware release 3.2(19).

For more information about an individual defect, you can access the online record for the defect by clicking the Identifier or going to the URL shown. You must be a registered Cisco.com user to access this online information.

Because defect status continually changes, be aware that [Table 1](#) reflects a snapshot of the defects that were resolved at the time this report was compiled. For an updated view of resolved defects, access Bug Toolkit as described in the “[Using Bug Toolkit](#)” section on page 4.

**Table 1**      **Resolved Caveats for the Cisco Unified IP Conference Station 7935**

Identifier	Headline and Bug Toolkit Link
<a href="#">CSCsi71403</a>	Cisco Unified IP Conference Station 7935 and 7936 do not retrieve their configuration file on restart <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsi71403">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsi71403</a>
<a href="#">CSCsk90301</a>	Softkey template is not shown during 'Call Forward All' <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk90301">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk90301</a>
<a href="#">CSCsk90331</a>	Cisco Unified IP Conference Station rings continuously even when it is set to ring once <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk90331">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk90331</a>
<a href="#">CSCsk92516</a>	Answer softkey is not displayed for second incoming call a scenario <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk92516">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk92516</a>
<a href="#">CSCsk94269</a>	Cisco Unified IP Conference Station is not able to play bell ringer for an external call <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk94269">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsk94269</a>
<a href="#">CSCsl03913</a>	Cisco Unified IP Conference Station does not ring with the ring tone set in a scenario <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsl03913">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsl03913</a>
<a href="#">CSCsl03926</a>	Display goes blank in a scenario involving translation pattern <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsl03926">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsl03926</a>
<a href="#">CSCsl07815</a>	Cisco Unified IP Conference Station is not able to end the call in a scenario <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsl07815">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsl07815</a>
<a href="#">CSCsl77050</a>	Sluggish web server behavior in Cisco Unified IP Conference Station 7936 and 7935 <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsl77050">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsl77050</a>
<a href="#">CSCsm12646</a>	Shared line preempts Cisco Unified IP Conference Station 7936 and 7935 dialing <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsm12646">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsm12646</a>
<a href="#">CSCso04948</a>	One-way audio on Cisco Unified IP Conference Station 7936 and 7935 when incoming Real-Time Transport Protocol (RTP) sequence number changes <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCso04948">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCso04948</a>
<a href="#">CSCso40611</a>	Unable to enter characters in the corporate directory search fields <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCso40611">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCso40611</a>

**Table 1 Resolved Caveats for the Cisco Unified IP Conference Station 7935 (continued)**

Identifier	Headline and Bug Toolkit Link
<a href="#">CSCsq14435</a>	Cisco Unified IP Conference Station locks up during conference call <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsq14435">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsq14435</a>
<a href="#">CSCsq37703</a>	On a Cisco Unified IP Conference Station 7936 and 7935, TFTP ‘NextServer’ option takes precedence over TFTP option 66 <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsq37703">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsq37703</a>
<a href="#">CSCsq70097</a>	Cisco Unified IP Conference Station reboots when reading Corporate Directory with more than 48 entries <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsq70097">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsq70097</a>
<a href="#">CSCsq76966</a>	One-way audio on Cisco Unified IP Conference Station 7936 and 7935 when incoming RTP sequence and synchronization source (ssrc) changes <a href="http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsq76966">http://tools.cisco.com/Support/BugToolKit/search/getBugDetails.do?method=fetchBugDetails&amp;bugId=CSCsq76966</a>

## Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, submitting a service request, and gathering additional information, see the monthly *What’s New in Cisco Product Documentation*, which also lists all new and revised Cisco technical documentation, at:

<http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html>

Subscribe to the *What’s New in Cisco Product Documentation* as a Really Simple Syndication (RSS) feed and set content to be delivered directly to your desktop using a reader application. The RSS feeds are a free service and Cisco currently supports RSS version 2.0.

CCDE, CCENT, Cisco Eos, Cisco HealthPresence, the Cisco logo, Cisco Lumin, Cisco Nexus, Cisco StadiumVision, Cisco TelePresence, Cisco WebEx, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn and Cisco Store are service marks; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0812R)

Any Internet Protocol (IP) addresses used in this document are not intended to be actual addresses. Any examples, command display output, and figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses in illustrative content is unintentional and coincidental.

© 2008 Cisco Systems, Inc. All rights reserved.