



Release Notes for Cisco Aironet Access Points for Cisco IOS Release 12.3(8)JEC1

March 21, 2008

These release notes describe caveats and features for maintenance release Cisco IOS Release 12.3(8)JEC1. This release supports 16-Mb Cisco autonomous access points, including Cisco Aironet 1100, 1200, and 1230 series autonomous access points. The Cisco Aironet 350 series is no longer supported in this release or any future release.

Contents

These release notes contain the following sections:

- [Introduction, page 2](#)
- [System Requirements, page 2](#)
- [Installation Notes, page 6](#)
- [New Features, page 8](#)
- [Important Notes, page 10](#)
- [Caveats, page 18](#)
- [Troubleshooting, page 23](#)
- [Obtaining Documentation, Obtaining Support, and Security Guidelines, page 23](#)



Americas Headquarters:
Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

© 2008 Cisco Systems, Inc. All rights reserved.

Introduction

The Cisco Aironet Access Point is a wireless LAN transceiver that acts as the connection point between wireless and wired networks or as the center point of a standalone wireless network. In large installations, the roaming functionality provided by multiple access points enables wireless users to move freely throughout the facility while maintaining uninterrupted access to the network.

You can configure and monitor 1100, 1200, and 1230, series access points using the command-line interface (CLI), the web-browser interface, or Simple Network Management Protocol (SNMP).

System Requirements

Cisco IOS Release 12.3(8)JEC1 is a general maintenance release that concentrates on bug fixes and includes minor features. You can install Cisco IOS Release 12.3(8)JEC1 on any Cisco Aironet 1100, 1210, or 1230 series access point.



Note

Software upgrades fail when you use the web-browser interface to install Cisco IOS Release 12.3(8)JEC1 on 1200 series access points. The image size exceeds the access point's 4-MB restriction for software upgrades. Use TFTP to upgrade your access point to this release. For complete instructions on using TFTP to upgrade access point software, see the "Working with Software Images" section in the *Cisco IOS Software Configuration Guide for Cisco Aironet Access Points*. Click this link to browse to that document:

http://www.cisco.com/en/US/products/hw/wireless/ps4570/tsd_products_support_configure.html

You can also install this release on 1200 series access points that have been converted to run Cisco IOS software. You can verify that an access point runs VxWorks or Cisco IOS software by looking at the GUI: the GUI on an access point running VxWorks has a yellow and red color scheme, and the GUI on an access point running Cisco IOS software has a green, light-green, and black color scheme.

Your 1200 series access point must run one of these VxWorks releases before you can convert to Cisco IOS software: 12.03T, 12.02T1, 12.01T1, 12.00T, 11.56, or 11.54T. If your access point runs version 12.04, you must downgrade to a supported VxWorks release before upgrading to Cisco IOS software.

The conversion upgrade image for 1200 series access points installs Cisco IOS Release 12.2(13)JA2 on your 1200 series access point.



Caution

Do not attempt to load a Cisco IOS image on 1200 series access points that have not been converted. Doing so can disable the access point.

Finding the Cisco IOS Software Version

To find the version of Cisco IOS software running on your access point, use a Telnet session to log into the access point, and enter the **show version EXEC** command. This example shows command output from an access point running Cisco IOS Release 12.3(8)JA:

```
ap1200>show version
Cisco Internetwork Operating System Software
IOS (tm) C1200 Software (C1200-K9W7-M), Version 12.3(8)JA
Copyright (c) 1986-2006 by Cisco Systems, Inc.
```

On access points running Cisco IOS software, you can also find the software version on the System Software Version page in the access point's web-browser interface. If your access point does not run Cisco IOS software, the software version appears at the top left of most pages in the web-browser interface.

Upgrading to a New Software Release

For instructions on installing access point software for your access point:

-
- Step 1** Follow this link to the Cisco home page:
<http://www.cisco.com>
 - Step 2** Click **Product & Services**. A drop-down menu appears.
 - Step 3** Click **Wireless**. The Wireless Introduction page appears.
 - Step 4** Scroll down to the Product Portfolio section.
 - Step 5** In the Access Point section, select the access point model for which you need the information. The Introduction page for the model you selected appears.
 - Step 6** Under the Support section, click **Configure**. A list of configuration documents appears.
 - Step 7** Click **Configuration Guides**. The Configuration Guides page appears.
 - Step 8** Click **Cisco IOS Software Configuration Guide for Cisco Aironet Access Points, 12.4(10b)JA and 12.3(8)JEC**.
-

For information on Cisco IOS software, click this link to browse to the Cisco IOS Software Center on Cisco.com:

<http://www.cisco.com/cisco/software/navigator.html>


Disable Radios to Prevent Unexpected Reboot When Upgrading System Software

If your access point runs Cisco IOS Release 12.2(11)JA, 12.2(11)JA1, or 12.2(11)JA2, your access point might unexpectedly reboot after you upgrade to a later Cisco IOS release. Because of a rare timing condition that affects the radios, the access point sometimes reboots immediately after the upgrade when the radios are enabled. However, after the access point reboots, the upgrade is complete, and the access point operates normally. To prevent the access point from rebooting unexpectedly, disable the radio interfaces before upgrading software.

Follow these steps to disable the radio interfaces using the web-browser interface:

- Step 1** Browse to the Network Interfaces: Radio Settings page. [Figure 1](#) shows the top portion of the Network Interfaces: Radio Settings page.

Figure 1 Network Interfaces: Radio Settings Page



- Step 2** Select **Disable** to disable the radio.
- Step 3** Click **Apply** at the bottom of the page.
- Step 4** If your access point has two radios, repeat these steps for the second radio.

Beginning in privileged EXEC mode, follow these steps to disable the access point radios using the CLI:

	Command	Purpose
Step 1	configure terminal	Enter global configuration mode.
Step 2	interface dot11radio {0 1}	Enter interface configuration mode for the radio interface. The 2.4-GHz radio is radio 0, and the 5-GHz radio is radio 1.
Step 3	shutdown	Disable the radio port.
Step 4	end	Return to privileged EXEC mode.
Step 5	copy running-config startup-config	(Optional) Save your entries in the configuration file.

If your access point has two radios, repeat these steps for the second radio. Use the **no** form of the **shutdown** command to enable the radio.

Converting to Cisco IOS Software

If your 1200 series access point does not run Cisco IOS software, you can use the conversion utility or the conversion upgrade image to convert the access point system to Cisco IOS software. Use the conversion utility to maintain the current configuration after the conversion, or load the upgrade image to convert to Cisco IOS software without saving the current configuration. Your 1200 series access point must be running VxWorks firmware versions 12.03T, 12.02T1, 12.01T1, 12.00T, 11.56, or 11.54T before you can convert to Cisco IOS software.

The conversion upgrade image for 1200 series access points installs Cisco IOS Release 12.2(13)JA2 on your 1200 series access point.

**Note**

The upgrade image and the conversion tool do not support VxWorks version 12.04. Access points running version 12.04 must be downgraded to a supported operating system version before you can use the upgrade image or the conversion tool.

**Caution**

The upgrade to Cisco IOS software is permanent; you cannot revert to non-IOS software. Product warranties do not cover unintended upgrades.

For complete instructions on using the conversion utility, refer to the *Cisco Aironet Conversion Tool for Cisco IOS Software, 2.1 Administrator Guide for Windows*. Click this link to browse to the Administrator Guide:

http://www.cisco.com/en/US/docs/wireless/access_point/conversion/ios/administration/guide/tool3ios.html

To download the conversion utility or the upgrade image, click this link to browse to the Cisco IOS Software Center on Cisco.com:

<http://www.cisco.com/cisco/software/navigator.html>

On the Cisco IOS Software Center page, enter your Cisco.com username and password to use the Feature Navigator or the Cisco IOS Upgrade Planner, or click **Wireless Software** to go to the Wireless LAN Software page. Download the conversion utility or the upgrade image for 1200 series access points. You can also download instructions for using the utility and the image.

Some Fields Not Updated During Upgrade to Cisco IOS Software

When you upgrade an access point to run Cisco IOS software, some fields that are reported in the console messages during the upgrade are blank or are populated with zeros. However, blank or zero fields are normal after a successful upgrade because 1200 series access points do not support some information. This example shows fields that might appear blank or populated with zeros:

```
32K bytes of flash-simulated non-volatile configuration memory.
Base Ethernet MAC Address: 00:05:9A:38:42:91
Part Number: 0-0000-00
PCA Assembly Number: 000-00000-00
PCA Revision Number:
PCB Serial Number:
Top Assembly Part Number: 000-00000-00
Top Assembly Serial Number:
Top Revision Number:
Product/Model Number: AIR-AP352-IOS-UPGRD
```

Installation Notes

This section contains information that you should keep in mind when installing Cisco Aironet autonomous access points.

Installation in Environmental Air Space

This section provides information on installing 1100 and 1200 series access points in environmental air space, such as above suspended ceilings.

Cisco Aironet 1100 and 1200 series access points provide adequate fire resistance and low smoke-producing characteristics suitable for operation in a building's environmental air space, such as above suspended ceilings, in accordance with Section 300-22(C) of the *National Electrical Code* (NEC) and Sections 2-128, 12-010(3) and 12-100 of the *Canadian Electrical Code*, Part 1, C22.1.

**Caution**

The power injector does not provide fire resistance and low smoke-producing characteristics and is not intended for use in extremely high or low temperatures or in environmental air spaces such as above suspended ceilings.

**Note**

If you plan to mount a 1200 series access point with a 5-GHz radio in an area subject to environmental air space, we recommend that you mount the access point horizontally so that its antennas point down. Doing so ensures that the access point complies with regulatory requirements for environmental air space with the 5-GHz radio installed.

Power Considerations

This section describes issues that you should consider before applying power to an access point.

**Caution**

The operational voltage range for 1100 series access points is 35 to 57 VDC, and the nominal voltage is 48 VDC. Voltages higher than 60 VDC can damage the equipment.

**Caution**

The nominal voltage for 1200 series access points is 48 VDC, and the access point is operational up to 60 VDC. Voltages higher than 60 VDC can damage the equipment.


**Caution**

Cisco Aironet power injectors are designed for use only with Cisco Aironet access points and bridges. *Do not use the power injector with any other Ethernet-ready device.* Using the power injector with other Ethernet-ready devices can damage the equipment.

Use Only One Power Option

You cannot provide redundant power to 1100 and 1200 series access points with both DC power to its power port and inline power from a patch panel or powered switch to the access point Ethernet port. If you apply power to the access point from both sources, the switch or power patch panel might shut down the port to which the access point is connected. [Figure 2](#) shows the power configuration that can shut down the port on the patch panel or powered switch.

Figure 2 *Improper Power Configuration Using Two Power Sources*



Using the AC Power Adapter

If you use the AC power adapter to provide power to the access point, you do not need to adjust the access point configuration.

Using a Switch Capable of IEEE 802.3af Power Negotiation

If you use a switch to provide Power over Ethernet (PoE) to the access point and the switch supports the IEEE 802.3af power negotiation standard, select **Power Negotiation** on the System Software: System Configuration page.

Using a Switch That Does Not Support IEEE 802.3af Power Negotiation

If you use a switch to provide Power over Ethernet (PoE) to the access point and the switch does not support the IEEE 802.3af power negotiation standard, select **Pre-Standard Compatibility** on the System Software: System Configuration page.

Using a Power Injector

If you use a power injector to provide power to the access point, select **Power Injector** on the System Software: System Configuration page, and enter the MAC address of the switch port to which the access point is connected.

Operating 5-GHz Radio Requires Power Injector, Power Module, or Catalyst 3550-24 PWR Switch

The 1200 series power injector and the 1200 series power module support operation of the 5-GHz radio in the access point. The Catalyst 3550-24 PWR switch supports power for both the 2.4-GHz radio and the 5-GHz radio. Other switches and power patch panels might not provide enough power for the 5-GHz radio.

Access Point Requires 1200 Series Universal Power Supply and Power Injector

If you use a power injector or a power module to provide power to a 1200 series access point, you must use a 1200 series universal power supply. If you need to use a power injector to inject power into the access point's Ethernet port, you must use a 1200 series power injector.

Unpowered 1100 Series Access Points Cause Loopback When Connected to Switches Without Loopback Detection

When you connect an unpowered 1100 series access point to a switch without loopback detection, the access point causes a loopback. To avoid this problem, make sure loopback detection is enabled on the switch to which the access point is connected. If your switch does not have loopback detection, disconnect the access point from the switch when the access point power is off.

Antenna Installation

For instructions on the proper installation and grounding of external antennas for 1200 series access points, refer to the National Fire Protection Association's *NFPA 70, National Electrical Code*, Article 810, and the Canadian Standards Association's *Canadian Electrical Code*, Section 54.



Warning

Do not install the antenna near overhead power lines or other electric light or power circuits, or where it can come into contact with such circuits. When installing the antenna, take extreme care not to come into contact with such circuits, as they may cause serious injury or death.

New Features

The following new feature is included in Cisco IOS Release 12.3(8)JEC1:

- System log messages

System Log Messages

With this release, the IOS command **logging facility** is available that allows users to customize the severity level of system error messages by determining the severity levels of system error messages that are reported or discarded. The command is supported on 1100, 1130, 1200, 1240, 1250, and 1300 series access points and 1400 series bridges. The events covered by this command are:

- Interfaces up/down (includes all interfaces)
- Interface link change
- Radius down/up

- Access point going down (rebooting)
- Uplink down
- Uplink failed
- Radio failed
- Rogue access point found.

The command syntax is as follows:

logging facility <facility name> event <event name> severity <severity level>

The **facility name** option has 4 options:

- 1. system
- 2. dot11
- 3. radius
- 4. link

The command is available only if one of the facility names is selected.

The **event name** selections depends on the facility name selected. Supported events and subevents for the respective facilities are shown in the following table:

Facility Name	Event	Subevent
system	reload	–
dot11	uplink	failed, down
	radio	failed
	rogue ap	–
rogue ap	–	–
radius	down	–
	up	–
link	interface	up-down, link-changed

The severity level specifies the maximum severity level to report and print a system logging message. There are 8 severity levels available, which are shown in the following table:

Severity Level	Logging Severity Level Description
0. emergencies	System is unusable
1 alerts	Immediate action needed
2. critical	Critical conditions
3. errors	Error conditions
4. warnings	Warning conditions
5. notifications	Normal but significant conditions
6. informational	Informational messages
7. debugging	Debugging messages

The following example configures severity level 3 (error conditions) for the facility *system*, event *reload* error messages:

```
ap(config)# logging facility system event reload severity errors
```

The following example configures severity level 1 (*immediate action needed*) for the facility *dot11*, event *radio failed* error messages:

```
ap(config)# logging facility dot11 radio failed severity alerts
```

Using the **no** form of the command removes the configured severity level from the configuration and reverts to the default severity for the event.

Important Notes

This section describes important information about the access point.

CCKM and Fast Roaming on Cisco 7921/7925 IP Phones

When a 7921 or 7925 wireless associates to an access point in a WDS with CCKM, it cannot fast roam because call admission control is not enabled. To work around this issue you must enable admission control by issuing the **admit-traffic** command in the access point SSID configuration as shown in the following example:

```
dot11 ssid voice
vlan 21
authentication open eap eap_methods
authentication network-eap eap_methods
authentication key-management wpa cckm
admit-traffic
```

Access Point Creates File When Radar is Detected on a DFS Channel

When an access point detects a radar on a DFS channel, the access point creates a file in its flash memory. The file is based on the 802.11a radio serial number and contains the channel numbers on which the radar is detected. This is an expected behavior and you should not remove this file. See the caveat CSCsv36602 in the [“Open Caveats” section on page 18](#).

Access Points Send Multicast and Management Frames at Highest Basic Rate

Access points running recent Cisco IOS versions are transmitting multicast and management frames at the highest configured basic rate, and is a situation that could cause reliability problems.

Access points running LWAPP or autonomous IOS should transmit multicast and management frames at the lowest configured basic rate. This is necessary in order to provide for good coverage at the cell's edge, especially for unacknowledged multicast transmissions where multicast wireless transmissions may fail to be received.

Since multicast frames are not retransmitted at the MAC layer, stations at the edge of the cell may fail to receive them successfully. If reliable reception is a goal, then multicasts should be transmitted at a low data rate. If support for high data rate multicasts is required, then it may be useful to shrink the cell size and to disable all lower data rates.

Depending on your specific requirements, you can take the following action:

- If you need to transmit the multicast data with the greatest reliability and if there is no need for great multicast bandwidth, then configure a single basic rate, one that is low enough to reach the edges of the wireless cells
- If you need to transmit the multicast data at a certain data rate in order to achieve a certain throughput, then configure that rate as the highest basic rate. You can also set a lower basic rate for coverage of non-multicast clients.

Interpreting the Show Controller Dot11Radio Active Power Level Output

A portion of the output of the **show controller dot11radio** CLI command displays the active power levels by rate as shown in the example below:

```
1.0 to 11.0 , 20 dBm, changed due to regulatory maximum
6.0 to m15. , 17 dBm, changed due to regulatory maximum
m0.-4 to m15.-4, 14 dBm, changed due to regulatory maximum
```

The -4 in the third line indicates 40-MHz.

Layer 3 Not supported with NAC for MBSSID

Layer 3 is not supported with NAC for MBSSID in this release.

DFS Enabled by Default on 5-GHz Radios in North America

In this release, Dynamic Frequency Selection (DFS) is automatically enabled on 5-GHz radios configured for use in North America. The 5-GHz radios use DFS to detect radar signals and avoid interfering with them. Radios configured for use in Europe and Singapore also use DFS. Other regulatory domains do not use DFS. Refer to the [“DFS Enabled by Default on 5-GHz Radios in North America” section on page 11](#) for detailed information.

Change to Default IP Address Behavior

Cisco IOS Releases 12.3(2)JA and later change the default behavior of access points requesting an IP address from a DHCP server:

- When you connect a 1200 or 1230 series access point with a default configuration to your LAN, the access point requests an IP address from your DHCP server and, if it does not receive an address, continues to send requests indefinitely.
- When you connect an 1100 series access point with a default configuration to your LAN, the 1100 series access point makes several attempts to get an IP address from the DHCP server. If it does not receive an address, it assigns itself the IP address 10.0.0.1 for 5 minutes. During this 5-minute window, you can browse to the default IP address and configure a static address. If after 5 minutes the access point is not reconfigured, it discards the 10.0.0.1 address and reverts to requesting an address from the DHCP server. If it does not receive an address, it sends requests indefinitely. If you miss the 5-minute window for browsing to the access point at 10.0.0.1, you can power-cycle the access point to repeat the process.

Save Interface Level Configuration Before Upgrading to Releases 12.3(8)JEC1

If the access points have SSIDs configured at the interface level (rather than at the global level), before upgrading to Cisco IOS Release 12.3(7)JA and above, upgrade to Cisco IOS Release 12.3(4)JA, save the configurations, and then upgrade to Release 12.3(8)JEC1. This procedure must be followed to make sure that the SSID configurations are converted from the interface level to global level.

Changes to the Default Configuration—Radios Disabled and No Default SSID

In this release, the radio or radios are disabled by default, and there is no default SSID. You must create an SSID and enable the radio or radios before the access point allows wireless associations from other devices. These changes to the default configuration improve the security of newly installed access points.

Clients Using WPA/WPA2 and Power Save Might Fail to Authenticate

Certain clients using WPA/WPA2 key management and power save might take many attempts to authenticate or, in some cases, fail to authenticate. Any SSID defined to use authentication key-management WPA, coupled with clients using power save mode and authenticating using WPA/WPA2 may experience this problem.

A hidden configure level command, **dot11 wpa handshake timeout**, can be used to increase the timeout between sending the WPA key packets from the default value (100 ms) to a value between 101 and 2000 ms. The command stores its value in the configuration across device reloads.

Default Username and Password Are *Cisco*

When you open the access point interface, you must enter a username and password. The default username for administrator login is *Cisco*, and the default password is *Cisco*. Both the username and password are case sensitive.

Some Client Devices Cannot Associate When QoS Is Configured

Some wireless client devices, including Dell Axim handhelds and Hewlett-Packard iPaq HX4700 handhelds, cannot associate to an access point when the access point is configured for quality of service (QoS). To allow these clients to associate, disable QoS on the access point. You can use the QoS Policies page on the access point GUI to disable QoS, or enter this command on the CLI:

```
ap(config-if) #no dot11 qos mode
```

Some Devices Disassociate When Multiple BSSIDs Are Added or Deleted

Devices on your wireless LAN that are configured to associate to a specific access point based on the access point MAC address (such as client devices, repeaters, hot standby units, or workgroup bridges) might lose their association when you add or delete a multiple BSSID. When you add or delete a multiple BSSID, check the association status of devices configured to associate to a specific access point. If necessary, reconfigure the disassociated device to use the BSSID new MAC address.

Enabling MBSSIDs Without VLANs Disables Radio Interface

If you use the **mbssid** configuration interface command to enable multiple BSSIDs on a specific radio interface but VLANs are not configured on the access point, the access point disables the radio interface. To re-enable the radio, you must shut down the radio, disable multiple BSSIDs, and re-enable the radio. This example shows the commands you use to re-enable the radio:

```
AP1134(config)# interface d1
AP1134(config-if)# shut
AP1134(config-if)# no mbssid
AP1134(config-if)# no shut
```

After you re-enable the radio, you can enable VLANs on the access point and enable multiple BSSIDs.

Cannot Set Channel on DFS-Enabled Radios in Some Regulatory Domains

Access points with 5-GHz radios configured at the factory for use in Europe, Singapore, Korea, Japan, Taiwan, and Israel now comply with regulations that require radio devices to use Dynamic Frequency Selection (DFS) to detect radar signals and avoid interfering with them. You cannot manually set the channel on DFS-enabled radios configured for these regulatory domains.

Cisco 7920 Phones Require Firmware Version 1.09 or Later When Multiple BSSIDs Are Enabled

When multiple BSSIDs are configured on the access point, Cisco 7920 wireless IP phones must run firmware version 1.09 or later.

AIR-RM21A/AIR-RM22A Radio Modules Usually Set to Max Transmit Power

AIR-RM21A and AIR-RM22A radio modules measure transmit power in decibels per milliwatt (dBm), but earlier versions of 802.11a radios in Cisco Aironet access points measure power in milliwatts (mW). Because power settings in mW do not translate directly to settings in dBm, the access point usually uses the default power setting of maximum when you install a new AIR-RM21A or AIR-RM22A radio module.

[Table 1](#) lists 802.11a transmit power settings in mW and the power settings that the access point assigns to a new radio module.

Table 1 Transmit Power Settings Assigned to New Radio Modules

Power Settings in mW	Power Setting Assigned to New Radio Module
5	5 dBm (approximately 3 mW)
10	maximum (17 dBm)
20	maximum
40	maximum

GRE Tunnelling Through WLSM Sometimes Requires MTU Setting Adjustments

If client devices on your wireless LAN cannot use certain network applications or cannot browse to Internet sites, you might need to adjust the MTU setting on the client devices or other network devices. For more information, refer to the Tech Note at this URL:

http://www.cisco.com/en/US/tech/tk827/tk369/technologies_tech_note09186a0080093f1f.shtml

TACACS+ and DHCP IP Address Sometimes Locks Out Administrators

When you configure an access point for TACACS+ administration and to receive an IP address from the DHCP server, administrators might be locked out of the access point after it reboots if the administrator does not have a local username and password configured on the access point. This problem does not affect access points configured with a static IP address. Administrators who have been locked out must regain access by resetting the unit to default settings.

Access Points Do Not Support Loopback Interface

You must not configure a loopback interface on the access point.



Caution

Configuring a loopback interface might generate an IAPP GENINFO storm on your network and disrupt network traffic.

Non-Cisco Aironet 802.11g Clients Might Require Firmware Upgrade

Some non-Cisco Aironet 802.11g client devices require a firmware upgrade before they can associate to the 802.11g radio in the access point. If your non-Cisco Aironet 802.11g client device does not associate to the access point, download and install the latest client firmware from the manufacturer's website.

Throughput Option for 802.11g Radio Blocks Association by 802.11b Clients

When you configure the 802.11g access point radio for **best throughput**, the access point sets all data rates to basic (required). This setting blocks association from 802.11b client devices. The **best throughput** option appears on the web-browser interface Express Setup and Radio Settings pages and in the **speed** CLI configuration interface command.

Transmit Power Set to Maximum When You Install 802.11g Radio

When you replace the 802.11b radio in a 1200 series access point with an 802.11g radio, the 802.11g radio is set to the maximum transmit power allowed in your regulatory domain, regardless of the power setting configured on the 802.11b radio. After you install the 802.11g radio and the access point reboots, configure the 802.11g radio to the preferred transmit power.

Use Auto for Ethernet Duplex and Speed Settings

Cisco recommends that you use **auto**, the default setting, for both the speed and duplex settings on the access point Ethernet port. When your access point receives inline power from a switch, any change in the speed or duplex settings that resets the Ethernet link reboots the access point. If the switch port to which the access point is connected is not set to **auto**, you can change the access point port to **half** or **full** to correct a duplex mismatch, and the Ethernet link is not reset. However, if you change from **half** or **full** back to **auto**, the link is reset, and, if your access point receives inline power from a switch, the access point reboots.



Note The speed and duplex settings on the access point Ethernet port must match the Ethernet settings on the port to which the access point is connected. If you change the settings on the port to which the access point is connected, change the settings on the access point Ethernet port to match.

Use force-reload Option with archive download-sw Command

When you upgrade access point or bridge system software by entering the **archive download-sw** command on the CLI, you must use the **force-reload** option. If the access point or bridge does not reload the flash memory after the upgrade, the pages in the web-browser interface might not reflect the upgrade. This example shows how to upgrade system software using the **archive download-sw** command:

```
AP# archive download-sw /force-reload /overwrite tftp://10.0.0.1/image-name
```

Radio MAC Address Appears in ACU

When a Cisco Aironet client device associates to an access point running IOS software, the access point MAC address that appears on the Status page in the Aironet Client Utility (ACU) is the MAC address for the access point radio. The MAC address for the access point Ethernet port is on the label on the back of the access point.

Radio MAC Address Appears in Access Point Event Log

When a client device roams from an access point (such as access point *alpha*) to another access point (access point *bravo*), a message appears in the event log on access point alpha stating that the client roamed to access point bravo. The MAC address that appears in the event message is the MAC address for the radio in access point bravo. The MAC address for the access point Ethernet port is printed on the label on the back of the access point.

Mask Field on IP Filters Page Behaves the Same As in CLI

In Cisco IOS Release 12.2(8)JA and later, the mask that you enter in the Mask field on the IP Filters page in the access point GUI behaves the same way as a mask that you enter in the CLI. If you enter 255.255.255.255 as the mask, the access point accepts any IP address. If you enter 0.0.0.0, the access point looks for an exact match with the IP address that you entered in the IP Address field.

Repeater Access Points Running Cisco IOS Software Cannot Associate to Parent Access Points Running VxWorks

1200 series repeater access points running Cisco IOS software cannot associate to parent access points that do not run Cisco IOS software (1200 series access points that have not been converted to run Cisco IOS software).

Repeater Access Points Cannot Be Configured as WDS Access Points

Repeater access points can participate in WDS, but they cannot provide WDS. You cannot configure a repeater access point as a main WDS access point, and if a root access point becomes a repeater in fallback mode, it cannot provide WDS.

Crossover Cable Sometimes Needed When Ethernet Speed and Duplex Set to Fixed on 1100 Series Access Points

If you change the speed and duplex settings from auto to fixed on an 1100 series access point Ethernet port, the auto-MDIX feature on the port is disabled. When auto-MDIX is disabled, you must determine whether to use a straight-through or a crossover cable to connect the access point Ethernet port to another device. If the Ethernet link goes down after you set the speed and duplex to fixed, try changing the Ethernet cable from crossover to straight-through or from straight-through to crossover.

Cannot Perform Link Tests on Non-Cisco Aironet Client Devices and on Cisco Aironet 802.11g Client Devices

The link test feature on the web-browser interface does not support non-Cisco Aironet client devices nor Cisco Aironet 802.11g client devices.

1100 Series Access Points with Boot Loader Version 12.2(4)JA Boot into Monitor Mode

When the Ethernet port is disabled on an 1100 series access point running boot loader version 12.2(4)JA, the access point boots into monitor mode when it reboots. To avoid this problem, connect the access point Ethernet port to one of the following:

- a wired LAN
- the Ethernet port on a PC

Remove power from the access point, and reapply power to reboot the unit. When the access point senses an Ethernet connection, it boots normally.

Corrupt EAP Packet Sometimes Causes Error Message

During client authentication, the access point sometimes receives a corrupt EAP packet and displays this error message:

```
Oct  1 09:00:51.642 R: %SYS-2-GETBUF: Bad getbuffer, bytes= 28165
-Process= "Dot11 Dot1x process", ipl= 0, pid= 32
-Traceback= A2F98 3C441C 3C7184 3C604C 3C5E14 3C5430 124DDC
```

You can ignore this message.

When Cipher Is TKIP Only, Key Management Must Be Enabled

When you configure **TKIP-only** cipher encryption (not **TKIP + WEP 128** or **TKIP + WEP 40**) on any radio interface or VLAN, every SSID on that radio or VLAN must be set to use WPA or CCKM key management. If you configure TKIP on a radio or VLAN but you do not configure key management on the SSIDs, client authentication fails on the SSIDs.

Cisco CKM Supports Spectralink Phones

Cisco CKM (CCKM) key management is designed to support voice clients that require minimal roaming times. CCKM supports only Spectralink and Cisco 7920 Version 2.0 Wireless Phones.

Non-Cisco Aironet Clients Sometimes Fail 802.1x Authentication

Some non-Cisco Aironet client adapters do not perform 802.1x authentication to the access point unless you configure **Open authentication with EAP**. To allow both Cisco Aironet clients using LEAP and non-Cisco Aironet clients using LEAP to associate using the same SSID, you might need to configure the SSID for both **Network EAP** authentication and **Open authentication with EAP**.

Pings and Link Tests Sometimes Fail to Clients with Both Wired and Wireless Network Connections

When you ping or run a link test from an access point to a client device installed in a PC running Microsoft Windows 2000, the ping or link test sometimes fails when the client has both wired and wireless connections to the LAN. Microsoft does not recommend this configuration. For more information, refer to Microsoft Knowledge Base article 157025 at this URL:

<http://support.microsoft.com/default.aspx?scid=kb;en-us;157025&Product=win2000>

Layer 3 Mobility Not Supported on Repeaters and Workgroup Bridges

Repeater access points and workgroup bridges cannot associate to an SSID configured for Layer 3 mobility. Layer 3 mobility is not supported on repeaters and workgroup bridges.

WLSM Required for Layer 3 Mobility

You must use a Wireless LAN Services Module (WLSM) as your WDS device to configure Layer 3 mobility. If you enable Layer 3 mobility for an SSID and your WDS device does not support Layer 3 mobility, client devices cannot associate using that SSID.

Caveats

This section lists open and resolved caveats for access points.

Open Caveats

These caveats are open in Cisco IOS Release 12.3(8)JEC1:

- CSCsv36602—Files appearing on access point flash with 5-GHz serial number as filename
 These files are created when radar is detected on a DFS channel. The files are created with the filename consisting of the serial number of the radio that detected the radar and include the DFS channel on which the radar was detected. The file is used when the access point is reset to ensure that the radar detected channels are not immediately selected after the reset.
 Conditions: When radar is detected on a DFS channel.
 Workaround: None. This is an expected behavior. The file should not be removed.
- CSCsm12509—DOT11-4-MAXRETRIES increase exponentially after upgrade
 After upgrading from Cisco IOS version 12.3(7)JA or a rebuild to either 12.3(8)JEB or 12.3(11)JA1, the following system log message appears:
 DOT11-4-MAXRETRIES
 This message is seen with much greater frequency than before. Quantity of these messages have increased by a factor of 10 to 15. This increase in messages can overflow the syslog server, and changing the logging level less than 4 is unacceptable as other significant system messages will be missed.
 Workaround—Downgrade to a previous version.
- CSCsk80813—Vista's anonymous provisioning does not work with access point local AAA server
- CSCsm62622—Applying access-group to physical int modifies ACL in running-config
 Applying access-group to physical interfaces modifies ACL in running-config when using bridge mode on the physical interfaces.
 When making a physical interface part of a bridge group and the physical interface has an ip access-group <list> [in/out] assigned from a corresponding Access List (ACL) and if this ACL has the logging labeled, the running-config gets modified at the first list match that hits any of the bridged interfaces in such a way that the logging is removed from the ACL.
 Workaround—Instead of assigning the ACL to a physical interface, create a BVI interface for the bridge group and assign the ACL to the BVI.

- CSCsm71956—Radius Server Failover causes WDS process to hold memory

When using the local radius server on a WDS master AP for infrastructure AP authentication and using other radius servers for client authentications, if the primary radius server for client authentication is down and the WDS master AP is rebooted, when the WDS master AP comes back online, you may find that no infrastructure AP's or clients authentications will pass and the WLCCP WDS process may start to hold onto memory.

Workaround—Remove the Radius server that is no longer responding from the configuration. This will cause issues if you are trying to use radius server failover but will allow client and infrastructure authentications to pass.
- CSCsm94076—WLCCP link fails with 1130 running 12.4 software

The output of show wlccp wnm status reflecting the status of the WLCCP link between an AP and WLSE is showing NOT AUTHENTICATED. This is observed on AP1130 after upgrading to Cisco IOS Software 12.4(10b)JA or 12.4(3g)JA1 and using WLSE 2.13 or 2.15.

Using the local radius server of the WDS or WLSE radius server gives the same results.

Workaround—None.
- CSCsh84949—Wireless client fails to receive multicast data stream.

Workaround—Configure **no ip igmp snooping** on the access point.
- CSCsi10705—The throughput on dual-radio 1200 series access points is sometimes lower than the throughput on a single-radio 1200 series access points.

Workaround: None.
- CSCsj86643—When you use the a workgroup bridge (WGB) to simulate a WMM/TSPEC client, the WGB/pagent-sourced UP 6 traffic (followed by a TSPEC) is downgraded to best effort when ACM is enabled. This downgrade occurs because the access point and WGB shared driver code assumes that the workgroup bridge is an access point and the uplink traffic is invalid, and thus downgrades all packets.

Workaround: None.
- CSCsk13961—The following MIB objects display incorrect values for 802.11n radios in 1250 series access points:
 - cd11IfAssignedSta
 - cd11IfPhyMacSpecification
 - cd11IfPhyDsssMaxCompatibleRate
 - cd11IfErpOfdmTxPowerLevel5
 - cd11IfClientCurrentTxPowerLevel1

Workaround: None.
- CSCsk58820—Station roles have different possible RTS threshold values (some 4000 some 2347).

Workaround: None.

- CSCs158293—1242 access point failed to associate using Authentication Shared

1242 fails to associate via authentication shared using 12.4(10b)JA release image. The same behavior occurs on C3202/C3205 Wireless MICs when they try to associate via authentication shared on their 12.4(3)JK release images.

Conditions—Configure AP1242 (or C3202/C3205 Wireless MICs) to be root and client devices with authentication method to be authentication shared under the SSID configuration.

Workaround—Configure a more secure method by using authentication open with WPA-PSK key management.
- CSCs176740—Access point crashes after SNMP query

An Access point may crash when an SNMP query is performed over an interface where a QoS policy is configured.

Workaround: None.
- CSCsm24495—Configuration change for adding data rate does not reflect in running config
- CSCsm31801—TKIP+ WPAV2+CCKM does not work

When combination of authentication key-management WPA version 2 CCKM + encryption mode ciphers TKIP is configured, an association failure occurs.

Workaround—None.
- CSCsm34905—Wrong dynamic VLAN assigned after re-authentication

After re-association, Wireless-Client gets access to wrong VLAN (Different VLAN then assigned via AAA)

Conditions—IOS AP, VLAN assignment via AAA, WPAv2 (AES encryption).

Workaround—Disable PMK caching on wireless client site.
- CSCsm38303—Coverage display on WLSE does not display correctly

The problem occurs when the coverage display in the location manager on WLSE changes to red, causing an incorrect display. This issue seems to occur on software versions later than 12.4(3g)JA. It does not appear to occur on older versions such as 12.3(11)JA2. The problem has been observed on the following platforms and versions:

 - CWWLSE-1133-K9,1130 / version 2.15
 - - AP1130AG: 12.3(11)JA, 12.4(10b)JA
 - - AP1240AG: 12.4(3g)JA, 12.4(10b)JA

Workaround—Use an older access point image.
- CSCsm80730—1240 access point does not send a re-association response to client

When a client tries to roam from one access point to another, during one of the roams the client sends a re-association request, the WDS 1240 Responds with an ACK but does not send a re-association response. The client then sends a deauthentication request and tries to do a full reauthentication.
- CSCsm97867—Autonomous workgroup bridge does not send out bad MIC on broadcast frame

The autonomous workgroup bridge is used to generate bad MIC TKIP frames for testing access points for proper MIC countermeasures operation. However, when a radio is configured as a workgroup bridge or a repeater, it will not send out the bad MIC frame on a broadcast packet. The radio sends the bad MIC out if it is in root mode, but not workgroup bridge or repeater mode.

This issue occurs on versions 12.3(8)JA, 12.3(11)JA, 12.4(3g)JA, and 12.4(10b)JA.

This issue occurs on versions 12.3(8)JA, 12.3(11)JA, 12.4(3g)JA, and 12.4(10b)JA.

- CSCso02086—Unable to apply QoS settings on a standalone access point using the GUI
QoS settings cannot be applied on a standalone access point using the GUI regardless of which Internet browser used.
Workaround—Create the QoS policy and apply it to an interface using the command line interface.
- CSCsg80305—When 16 SSIDs are configured, client devices sometimes fail to associate to the 16th SSID.
Workaround: Save the configuration and reload the UC520.
- CSCso07171—Fast roaming fails when CCKM is enabled on an access point in workgroup bridge mode.
When CCKM is enabled in infra-root access points in workgroup bridge mode, fast roaming fails. This issue also seen on ADU CB21AG/PI21AG card clients. It is working correctly with ACU 11a card clients.
- CSCsd99067—AVVID priority map incorrectly maps CoS 5 to CoS 7 within same VLAN.
THE AVVID priority mapping in the CoS advanced parameters is incorrectly mapping the CoS value to 7 when making a call to a wired phone in same VLAN. This situation occurs in an 802.11g network running one 7921 and one access point.
Workaround—None.
- CSCse34644—Shared authentication with a non-native VLAN does not operate properly.
This situation occurred on
flash:/c1130-k9w7-mx.v123_8_ja.20060520/c1130-k9w7-mx.v123_8_ja
Workaround—Save the configuration, and reload the access point. When the access point comes up and the clients get authenticated, edit the shared authentication SSID as follows:
 1. Add open authentication.
 2. Removed shared authentication.
 3. Remove open and add shared authentication. The client should associate.
 4. Reload the access point.
- CSCsk05871—Sometimes packets are not marked as voice to 7921 phones.
Condition: A 7921 phone talking to a non-WMM client (a 7920 phone, for example), a wired client, or another 7921 client with WMM disabled.
Workaround: None.

Resolved Caveats

These caveats are resolved in Cisco IOS Release 12.3(8)JEC1:

- CSCsj56438—Crafted EAP response identity packet may cause device to reload.
This Cisco Bug ID identifies a vulnerability in Cisco's implementation of Extensible Authentication Protocol (EAP) that exists when processing a crafted EAP Response Identity packet. This vulnerability affects several Cisco products that have support for wired or wireless EAP implementations.
This vulnerability is documented in the following Cisco bug IDs:
Wireless EAP - CSCsj56438
Wired EAP - CSCsb45696 and CSCsc55249
This Cisco Security Response is available at <http://tools.cisco.com/security/center/content/CiscoSecurityResponse/cisco-sr-20071019-eap>.
- CSCsg39295—Syslog Displays Password if SCP or FTP Selected in CISCO-COPY-CONFIG-MIB
- CSCsm54952—Access point GUI support needed for adding and displaying local user with “secret.”
- CSCsj85065—A Cisco IOS device may crash while processing an SSL packet. This can happen during the termination of an SSL-based session. The offending packet is not malformed and is normally received as part of the packet exchange.
Cisco has released free software updates that address this vulnerability.
Aside from disabling affected services, there are no available workarounds to mitigate an exploit of this vulnerability.
This advisory is posted at <http://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20080924-ssl>.
- CSCsj97493—Access point GUI home page is not loading properly and displays JavaScript errors.
- CSCsb85791—1130 access point crashes just after installation of ew image.
- CSCsk63882—Bad ID error with traceback seen when 12.4-Based 802.11 access point starts up.
- CSCsm15944—Non root bridge shows env: WARNING: No reading temperature monitoring is at INITIALIZE state.
- CSCsl49277—1310 outdoor access point/bridge crashes when attempting to associate using authentication shared.
- CSCsj68025—Roaming between 1242 access point bridged on radio 1 fails due to WPA-PSK authentication failure.
- CSCsl95464—Access point crashes on WLCCP WDS process.
- CSCsk28551—Root bridge does not update bridge table.
- CSCsl84045—Traceback and bad refcount in datagram_done errors seen on 1230 and 1240 series access points.
- CSCsk44106—SNMP returns incorrect cipher values for some clients in cDot11ClientUnicastCipher when multiple ciphers are defined on an interface.
- CSCsl95939—An access point may log a misleading message when a client attempts to associate.
- CSCsk52584—Misleading no SSID warning reported on access point when no VLAN is configured.
- CSCsl72417—Workgroup bridge association problem with WPA-TKIP-CCKM security type.
- CSCsk85945—Workgroup bridge running WPA1 cannot associate to a WPA1+WPA2 WLAN.

- CSCsm70942—Access point sends invalid MAC address in unicast IAPP.
- CSCsl17857—1231 access point running Cisco IOS Release 12.3(8)JEC is unable to set transmit/receive antenna options.
- CSCsl85798—After a DFS event, workgroup bridge does not rescan.
- CSCsl39499—Access point displays “%SYS-3-BADLIST_DESTROY” traceback and reloads.
- CSCsk70798—Access point does not transmit ppp negotiation and Microsoft VPN stops working

If You Need More Information

If you need information about a specific caveat that does not appear in these release notes, you can use the Cisco Bug Toolkit to find select caveats of any severity. Click this URL to browse to the Bug Toolkit:

<http://tools.cisco.com/Support/BugToolKit/>

(If you request a defect that cannot be displayed, the defect number might not exist, the defect might not yet have a customer-visible description, or the defect might be marked Cisco Confidential.)

Troubleshooting

For the most up-to-date, detailed troubleshooting information, refer to the Cisco TAC website at <http://www.cisco.com/cisco/web/support/index.html>. Click **Technology Support**, choose **Wireless** from the menu on the left, and click **Wireless LAN**.

Obtaining Documentation, Obtaining Support, and Security Guidelines

For information on obtaining documentation, obtaining support, providing documentation feedback, security guidelines, and also recommended aliases and general Cisco documents, see the monthly *What's New* in Cisco Product Documentation, which also lists all new and revised Cisco technical documentation, at:

<http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html>

CCDE, CCENT, Cisco Eos, Cisco HealthPresence, the Cisco logo, Cisco Lumin, Cisco Nexus, Cisco StadiumVision, Cisco TelePresence, Cisco WebEx, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn and Cisco Store are service marks; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MeetingPlace Chime Sound, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0812R)