

Release Notes for the Cisco 350XG Series and the Cisco 550XG Series Switches, Version 2.0.0.73

Contents

This document includes the following topics:

- “Cisco 350XG and 550XG Switches, Version 2.0.0.73” on page 1
- “Related Information” on page 5

Cisco 350XG and 550XG Switches, Version 2.0.0.73

Version 2.0.0.73

September 2015

These release notes describe the open issues for the Cisco 350XG Series and the Cisco 550XG Series Switches.

Requirements

A computer with Browser support for:

- Internet Explorer v9.0.8112.16421 or later
- Chrome v39.0.2171.65 or later
- Firefox v34.05 or later
- Safari v5.1.7 or later

Release Notes

Resolved Issues

This is a new release.

Open Caveats

These are the open caveats for firmware version 2.0.0.73.

Table 1 Open Caveats for Firmware Version 2.0.0.73

Ref Number	Description
CSCuu65516	<p>Symptom: If a language file fails to download (for example, due to a network problem), your Internet browser may display “incomplete/error information.”</p> <p>Workaround: Delete your browser cookies and try again. The device can still be managed using Telnet.</p>
CSCuu65557	<p>Symptom: If the management session is using the device’s IPv6 address, and this is a secure session (HTTPS), the device cannot be managed using the Safari browser.</p> <p>Workaround: Either use a different browser (such as Internet Explorer) or set up an insecure session (HTTP).</p>
CSCur86883	<p>Symptom: When using the web-based configuration interface to set up queue scheduling, you may have a lengthy response time if the system includes a stack of four or more units.</p> <p>Workaround: After about one minute, the web-based configuration interface becomes responsive again, and the setting takes effect. Use the command line interface (CLI) commands for a quicker response time.</p>
CSCuu65577	<p>Symptom: When using the web-based configuration interface to set a new keychain for RIP, include an accept-lifetime. If you don’t include an accept-lifetime, the configuration doesn't take effect.</p> <p>Workaround: Use a CLI to enter the keychain, or on the user interface, enter both an accept lifetime and a send lifetime.</p>
CSCuu65593	<p>Symptom: On fiber-only ports, negotiation is always enabled; however, the show command displays negotiation as disabled. If the link partner’s negotiation is disabled, the link might not come up.</p> <p>Workaround: Verify that the link partner’s negotiation is enabled.</p>

Table 1 Open Caveats for Firmware Version 2.0.0.73

Ref Number	Description
CSCUu65595	<p>Symptom: MLD Snooping mode on IPv6 interfaces is always (*, G), even if you set the mode to (S, G).</p> <p>Workaround: There is no workaround.</p>
CSCUq03628	<p>Symptom: An ISATAP client sends RS packets only when the tunnel interface is disabled, and then enabled.</p> <p>Workaround: As long as the tunnel endpoints are both SG350XG/ SG550XG, the tunnel works. In mixed devices applications, manually disable and enable the tunnel interface.</p>
CSCUu60989 CSCUu61046	<p>Symptom: Enabling an 802.1X guest VLAN or a Voice VLAN on a port is forbidden, if the port is a static member of the VLAN and it is in switchport mode (including inactive modes).</p> <p>Workaround: Change the port VLAN membership that use switchport modes so that the port is not a static member in the desired VLAN.</p> <p>Note that in switchport mode Trunk, the port is a member of all the VLANs by default. Remove the membership in the desired VLANs, or in all VLANs, prior to configuring the 802.1X guest VLAN or the Voice VLAN.</p>
CSCUu61100	<p>Symptom: Link partner shows that the link is up, even if the device interface is administratively shut down.</p> <p>Workaround: This is a display issue. The link is actually down and does not forward traffic.</p>
CSCUu61125	<p>Symptom: The show VLAN command, for VLAN 1, shows non-present interfaces (port and stack units).</p> <p>Workaround: This is a display issue only.</p>
CSCUu61088	<p>Symptom: The show qos interface command displays info for interfaces that are not present.</p> <p>Symptom: This is a display issue only.</p>
CSCUu61084	<p>Symptom: IPv6 Routes always display a metric value of “0.”</p> <p>Workaround: This is display issue. The correct metric is used for IPv6 L3 forwarding decisions.</p>

Release Notes

Table 1 Open Caveats for Firmware Version 2.0.0.73

Ref Number	Description
CSCuu61080	<p>Symptom: DHCP router option (Option 3) is sent by the switch DHCP server, even if the option is not configured for this pool</p> <p>Workaround: There is no workaround.</p>
CSCuu61061	<p>Symptom: If short reach is enabled on a port, the cable length test using a Cat6a cable fails.</p> <p>Workaround: Disable short reach when running the cable length test on an interface.</p>
CSCuu61008	<p>Symptom: Agreed Auto Voice VLAN cannot be defined as a primary VLAN, even after the voice VLAN is disabled.</p> <p>Workaround: There is no workaround.</p>
CSCuu60986	<p>Symptom: When enabling flow control on the LAG using the user interface, the port LEDs will not light even if link is up.</p> <p>Workaround: This is a LED display issue. The functions work as expected. If needed, enable flow control using the command line interface.</p>
CSCuu60983	<p>Symptom: If VRRP is enabled on a device, DHCP relay using Option 82 fails.</p> <p>Workaround: If VRRP is enabled on device, use DHCP relay without activating Option 82.</p>
CSCuu60958	<p>Symptom: When configuring a MAC ACE using the web-based configuration interface, creation of new ACE may fail with an error message of “Entry Already Exists,” even though it does not exist.</p> <p>Workaround: Configure the ACE again and it will be accepted, or use the CLI to configure the ACE.</p>
CSCuu60952	<p>Symptom: When changing an ACE action using the configuration interface, (for example, from deny to shutdown) ACE may be removed from the ACL.</p> <p>Workaround: Reconfigure the ACE, or use the CLI to remove the ACE and then configure it with the new action.</p>

Related Information

Support	
Cisco Support Community	www.cisco.com/go/smallbizsupport
Cisco Support and Resources	www.cisco.com/go/smallbizhelp
Phone Support Contacts	www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html
Cisco Open Source Requests	<p>To receive a copy of the source code to which you are entitled under the applicable free/open source license(s) (such as the GNU Lesser/General Public License), please send your request to: externalopensource-requests@cisco.com</p> <p>In your requests please include the Cisco product name, version, and the 18 digit reference number (for example: 7XEEX17D99-3X49X081) found in the product open source documentation.</p>
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Product Documentation	
Cisco Switch documentation	www.cisco.com/go/350switches www.cisco.com/go/550switches
Cisco Small Business	
Cisco Partner Central for Small Business (Partner Login Required)	www.cisco.com/web/partners/sell/smb
Cisco Small Business Home	www.cisco.com/smb

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2015 Cisco Systems, Inc. All rights reserved.