



# Cisco C880 M4 with E7-8800 v3 CPU Release Notes (1.2.8)

Firmware Revision: BB18111

First Published: December 15, 2015

Last Updated: Oct. 15, 2019

## Introduction

Cisco C880 M4 with E7-8800 v3 CPU is an 8-Socket x86 Rack servers. It is based on eight Intel® Xeon® E7-8880 v3 series processors with max memory of 2TB or 6TB. SAP HANA Certifications are performed by Cisco on the Cisco C880 M4 rack server and the server can be managed by UCS Director.

## System Requirements

There are no specific system requirements for this release of firmware.

## New and Changed Features

There is no specific change in any of the software features.

## Changes in Behavior

There is no specific change in any of the software feature and their behavior.

## Scalability Improvements

There is no specific change in any of scalability requirements.

## Related Documentation

The documents specifically for Cisco C880 M4 server with E7-8800 v3 CPU are located at specified link:

<http://www.cisco.com/c/en/us/products/servers-unified-computing/c880-m4-server/index.html>

## Installation and Upgrade Notes

The installation module and upgrade notes are located in the released firmware bundle. The following table maps firmware release versions with individual components.

Release Version	Firmware Version	BIOS Version	BMC Version	MMB Version
1.2.1	BB15114	1.48	2.08	20.45
1.2.2	BB16021	1.52	2.09	20.48
1.2.3	BB16036	1.58	2.13	20.91
1.2.4	BB16053	1.59	2.14	20.57 (*)
1.2.5	BB17034	1.69	2.22	30.41
1.2.6	BB18031	1.77	2.23	30.46
1.2.7	BB18061	1.82	2.23	30.47
1.2.8	BB18111	1.83	2.24	30.51

(\*) Even though revision number is smaller than previous one, revision „20.57“ is newer.

## Upgrade Paths

The firmware release package can be downloaded from specified link:

<http://www.cisco.com/cisco/web/support/index.html>

## Open and Resolved Bugs

The open and resolved bugs for this release are accessible through the Cisco Bug Search Tool. This web-based tool provides you with access to the Cisco bug tracking system, which maintains information about bugs and vulnerabilities in this product and other Cisco hardware and software products.

Note: You must have a Cisco.com account to log in and access the Cisco Bug Search Tool. If you do not have one, you can [register for an account](#). For more information about the Cisco Bug Search Tool, see the [Bug Search Tool Help & FAQ](#).

## Open Bugs for This Release

All open bugs for this release are available in the Cisco Bug Search Tool through the open bug search <http://tools.cisco.com/bugsearch/>.

That search includes workarounds for the following open bugs, if any, and any additional open bugs.

Bug ID	Headline
--------	----------

Open and Resolved Bugs

<p>CSCur60300</p>	<p><u>[Description]</u>          When you go to MMB Web-UI:          &gt;System &gt;DU &gt; DU#x, or          &gt;Disk Enclosure &gt; Disk Enclosure#x,          The latest status of RAID card, Physical Drives, and Logical Drives shown in the table does not appear immediately.</p> <p><u>[Workaround]</u>          Status of RAID card, Physical Drives, and Logical Drives is polled every 1 minute, so it will take maximum 1 minute to show the latest status.          Note: If "Disk Enclosure#x" does not appear, please click "System" in the navigation bar to refresh display after the system enters boot state.</p>
<p>CSCuy48445</p>	<p><u>Description</u>          [MMB Web-UI]          The page of "Disk Enclosure" is not displayed in MMB Web-UI in case that no logical drive is configured on the RAID controller..</p> <p><u>Workaround</u>          No plan to solve.</p>
<p>CSCuy48536</p>	<p><u>[Description]</u>          [Video Redirection]          Unable to open the video redirection after firmware update.</p> <p><u>[Workaround]</u>          No plan to solve.</p> <p>Execute the following CLI command.  <i>set bmcccontrol reset VR &lt;sb#&gt;</i></p>

Resolved Bugs for This Release

Bug ID	Headline
<p>CSCuy41727</p>	<p><u>Description</u>          [Network Configuration]          C880-M4 - Alarm E-Mail gives HTTP 500 error if FQDN is used for SMTP srv</p> <p><u>Workaround</u>          Use IP address instead of FQDN.</p>

<p>CSCve49104</p>	<p><u>[Phenomenon]</u>  Video redirection function of C880 M4 (with E7-8800 v2/v3/v4 CPU) can not be started with a client PC which Java version shown below is installed on.  - Java 8 update131 or later</p> <p><u>[Cause]</u>  Modifications below are applied in Java 8 update131.  Authentication method of MD5-signed JAR file is changed at Java 8 update 131.  Because video redirection function of C880 M4 uses MD5 signature, this Java modification causes the problem.</p> <p><u>[Workaround]</u>  (1) Please do not update to this version if you use Video redirection of C880 M4.  OR  (2) If you have already installed Java 8 update 1.31 or later, please follow the below.  Please modify the Java related file on a PC.</p> <p>It is not necessary to reboot PC after editing the file.  - Windows PC (*)      C:\Program Files\Java\jre1.8.0_131\lib\security\java.security  - Linux client (*)      /usr/java/jre1.8.0_131/lib/security/java.security</p> <p>(*) This example above is in case of default installation path</p> <p>- edit a line: 573 as shown  Before editing:  jdk.jar.disabledAlgorithms=MD2, MD5, RSA keySize &lt; 1024  After editing:  jdk.jar.disabledAlgorithms=MD2, RSA keySize &lt; 1024</p>
<p>-----</p>	<p>Security issues related to CVE-IDs listed below are fixed at this Release 1.2.5 (Firmware BB17034).</p> <p>Vulnerabilities related to OpenSSL  CVE-2016-0797, CVE-2016-2105, CVE-2016-2106, CVE-2016-2108, CVE-2016-2109,  CVE-2015-1789, CVE-2015-1790, CVE-2015-1792, CVE-2015-1791, CVE-2014-8176,  CVE-2016-2183</p> <p>Vulnerabilities related to ntpd  CVE-2015-8138, CVE-2016-1550, CVE-2016-2516, CVE-2016-2517, CVE-2016-2519,  CVE-2016-2518, CVE-2015-8139, CVE-2015-7973, CVE-2015-8140, CVE-2016-1549,  CVE-2015-7978, CVE-2015-8158, CVE-2015-7977, CVE-2015-7979, CVE-2016-1547</p>
<p>-----</p>	<p>Security issues related to CVE-IDs listed below are fixed at this Release 1.2.6 (Firmware BB18031).</p> <p>Vulnerabilities related to MMB firmware OS kernel  CVE-2011-1076, CVE-2012-3552, CVE-2011-1927, CVE-2011-1581, CVE-2011-4087</p> <p>Vulnerabilities related to MMB firmware  - glibc: CVE-2016-10228  - logrotate: CVE-2011-1154, CVE-2011-1155, CVE-2011-1098  - net-snmp: CVE-2015-5621, CVE-2014-2284, CVE-2012-6151</p>
<p>-----</p>	<p>This fix is related to MMB Configuration backup/restore function on MMB Web-UI.  MMB Configuration backup/restore function did not backup/restore setting items of "Remote Server Management".  Firmware BB18031 resolves this.</p>

CSCvh66783	<p>A security issue related to CVE listed below is mitigated at this Release 1.2.6 (Firmware BB18031).</p> <p>Cisco C880 M4 servers are based on Intel® Xeon® E7-8800 v3 series processors that are vulnerable to exploits that use CPU speculative processing and data cache timing to potentially identify privileged information. These exploits are collectively known as Spectre and Meltdown.</p> <ul style="list-style-type: none"><li>• CVE-2017-5753 (Spectre/Variant 1) is addressed by applying relevant Operating System and Hypervisor patches from the appropriate vendors.</li><li>• CVE-2017-5715 (Spectre/Variant 2) is addressed by applying the updated microcode included in the C880 M4 servers as well as the relevant Operating System and Hypervisor patches from the appropriate vendors.</li><li>• CVE-2017-5754 (Meltdown) is addressed by applying the relevant Operating System patches from the appropriate vendors.</li></ul> <p>This release includes BIOS revisions for Cisco C880 M4 generation server. These BIOS revisions include the updated microcode that is a required part of the mitigation for CVE-2017-5715 (Spectre/Variant 2).</p>
CSCvj59127	<p>A security issue related to CVE listed below is mitigated at this Release 1.2.7 (BIOS 1.82).</p> <p>SpectreNG</p> <ul style="list-style-type: none"><li>• CVE-2018-3639 – Speculative Store Bypass (SSB) – also known as Variant 4</li><li>• CVE-2018-3640 – Rogue System Register Read (RSRE) – also known as Variant 3a</li></ul> <p>This release includes BIOS revisions for Cisco C880 M4 generation server. These BIOS revisions include the updated microcode that is a required part of the mitigation for CVE-2018-3639 and 3640 (Variant 4 and 3a).</p>
CSCvr63509	<p>[Description]</p> <p>If frequently DIMM CE (correctable error) are detected, the MMB firmware marks the DIMM as “DIMM CE limit reach”, and the MMB firmware treats this as “DIMM is in error state”. In this case, a SEL event like the example below is recorded in SEL.</p> <p>0002 Warning  2019-04-20 06:54:17 SB#0  DIMM#0D4  B0DE4BFF 'DIMM#0D4' Memory: Error logging limit reached</p> <p>When a system is AC-OFF and AC-ON during “DIMMs are in error state”, the MMB firmware treats DIMMs as not-installed and DIMM configuration error. When this happens, the server cannot be powered-on any longer.</p> <p>This MMB firmware operation is unexpected and considered to be a bug.</p> <p>[Workaround]</p> <p>(1) Replace the DIMMs in error state before AC-OFF. OR (2) If AC-OFF and ON is performed before replacing the DIMMs, execute one of bellows: (a) Remove all SBs, wait for a minute, and reinstall all SBs (b) Perform “SB Status Clear” operation for all SBs on MMB Web-UI</p> <p>This bug was fixed in the revision of 1.2.8.</p>

## Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see *What's New in Cisco Product Documentation*, at: <http://www.cisco.com/c/en/us/td/docs/general/whatsnew/whatsnew.html>.

Subscribe to *What's New in Cisco Product Documentation*, which lists all new and revised Cisco technical documentation, as an RSS feed and deliver content directly to your desktop using a reader application. The RSS feeds are a free service.

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies are considered un-Controlled copies and the original on-line version should be referred to for latest version.

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2018 Cisco Systems, Inc. All rights reserved.