



# Release Notes for Cisco D9865 Satellite Receiver Software Version 2.22

**First Published:** March 25, 2015

## Contents

This document describes the new features, improvements, resolved caveats, and open caveats in software Version 2.22 for the Cisco D9865 Satellite Receiver.

- [New Features, page 1](#)
- [Improvements, page 1](#)
- [Caveats, page 1](#)
- [Obtaining Documentation and Submitting a Service Request, page 2](#)

## New Features

There are no new features for Version 2.22.

## Improvements

The following improvement is included in Version 2.22:

- New language codes added for the subtitle feature: Albanian (alb), Estonian (est), Croatian (hrv), Latvian (lav), and Macedonian (mac).

## Caveats

This section includes open and resolved caveats for this release. This section includes the following topics.

- [Open Caveats - Version 2.22, page 2](#)
- [Resolved Caveats - Version 2.22, page 2](#)

## Open Caveats - Version 2.22

The following is a list of open caveats in Version 2.22. The caveat ID can be searched using the Cisco Bug Search Tool (<https://tools.cisco.com/bugsearch>), where you can find details about the caveat and workarounds.

### ■ CSCuh09794

When the unit powers on, it reverts to Safe App, instead of the selected Erasable App. This may occur after you power cycle the unit. The probability of this occurrence is extremely low. No customer reports of this issue have been received.

### ■ CSCuh55798

Low speed data PID may drop packets under specific conditions (D9865-D only):

- 720P video services and high bit rate serial data (19200 bps or higher)
- low speed data stream contains successive back-to-back packets

### ■ CSCul63158

The unit may discard all settings after an uncontrolled power cycle during Non-Volatile Memory (NVM) storage activity. If this occurs, you must manually re-configure the unit. During lab validation, one unit out of 14,000 units reported this issue. No customer reports of this issue have been received.

## Resolved Caveats - Version 2.22

There are no resolved caveats for Version 2.22.

## Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see *What's New in Cisco Product Documentation* at: <http://www.cisco.com/c/en/us/td/docs/general/whatsnew/whatsnew.html>.

Subscribe to *What's New in Cisco Product Documentation*, which lists all new and revised Cisco technical documentation, as an RSS feed and deliver content directly to your desktop using a reader application. The RSS feeds are a free service.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2015 Cisco Systems, Inc. All rights reserved.