



Firmware Release Notes

Cisco Ultra Reliable Wireless Backhaul (formerly Fluidmesh) FM1000 and FM10000 (Generation 1) gateways

First Published: April 27, 2021

Last Updated: : April 27, 2021

Applicability

These firmware release notes are applicable to FM1000 and first-generation FM10000 gateways only.

This document contains important change information regarding the most current device firmware version (1.4.1).

Firmware changelog

The following device-specific changes were introduced for firmware version 1.4.1:

- **FM-QUADRO (second release).** This includes the following new features:
 - The FM-QUADRO user interface no longer needs Adobe Flash Player or Apache Flex to function.
 - FMQuadro 1.0 and Fluidity Quadro were previously two separate tools that needed users to toggle between them to effectively manage stationary and Fluidity networks. In contrast, FM-QUADRO 2.0 combines the functionality of both tools into a simpler, easier-to-use interface.
 - Operation of all aspects of the FM-QUADRO functionality has been streamlined and made more intuitive.
 - Visual cues have been incorporated that allow users to immediately distinguish between wired and wireless links and between stationary and mobile radios, and to immediately interpret the functional status of all components in the network cluster.
 - The user is only ever two clicks away from all functional information regarding individual radios and radio links.
 - The FM-QUADRO 2.0 view is completely customizable, and radio link information can be shown or suppressed as needed.
 - A representation file of the current network layout can be exported, allowing Fluidmesh Technical Support to visualize the network for troubleshooting purposes.
- **Telemetry:** A new telemetry protocol has been introduced, featuring support for FM-QUADRO 2.0.
- **Fluidity:**
 - An access-point coloring feature has been introduced to distinguish between Fluidmesh APs installed on different train tracks, in open sections of railway.
 - A pole-proximity safe MCS feature has been added.
 - A combined pole-proximity protocol has been added. This combines the established pole-ban functionality with LER detection: if a current pole to which it is possible to connect has been banned, and the LER at the currently connected pole is too high, the banned pole is unbanned, and the safe-mcs parameter is set to allow pole proximity.

Bug fix changelog

- A pole-proximity dynamic duration feature has been added, allowing radios to automatically estimate pole ban durations.
- The Webserver functionality has been updated with support for FM-QUADRO 2.0 and various security fixes.

Bug fix changelog

The following bug fix was introduced for firmware version 1.4.1:

- A potential memory leak involving packet fragmentation was fixed.
- A bug was fixed whereby Native VLAN tags were not preserved across the wireless network if radios are in Bridge Mode.

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies are considered uncontrolled copies and the original on-line version should be referred to for latest version.

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2021 Cisco Systems, Inc. All rights reserved.