


Troubleshoot FTD Unable to Ping Upstream Device despite Having an ARP Entry

Contents

Issue

The Firewall Threat Defense (FTD) was unable to ping the upstream device IP address, despite the firewall being able to observe the ARP entry for the upstream IP address. The ARP table showed the expected entries, indicating that Layer 2 connectivity was functioning but Layer 3 ping traffic was being blocked.

Topology



FTD CLI Symptoms

Ping to the upstream IP address is failing:

```
<#root>
```

```
device#
```

```
ping 192.0.2.250
```

```
Type escape sequence to abort.
```

```
Sending 5, 100-byte ICMP Echos to 192.0.2.250, timeout is 2 seconds:
```

```
?????
```

```
Success rate is 0 percent (0/5)
```

There is an ARP entry for the upstream IP address:

```
<#root>
```

```
device#
```

```
show arp
```

```
NET200 192.0.2.250 0000.5e00.5301
```

```
47
```

Enable a capture with trace on the FTD interface:

```
<#root>
```

```
device#
```

```
capture CAPI interface NET200 trace match icmp host 192.0.2.200 host 192.0.2.250
```

FTD LINA syslogs during the ping test:

```
<#root>
```

```
device#
```

```
show log | include 192.0.2.250
```

```
May 15 2026 09:46:26: %FTD-6-302020: Built outbound ICMP connection for faddr 192.0.2.250/0 gaddr 192.0
```

```
May 15 2026 09:46:26: %FTD-3-313001:
```

```
Denied ICMP type=0, code=0 from 192.0.2.250 on interface NET200
```

```
May 15 2026 09:46:26: %FTD-6-302021: Teardown ICMP connection for faddr 192.0.2.250/0 gaddr 192.0.2.200
```

```
...
```

Packet capture shows ICMP echo replies arriving:

```
<#root>
```

device#

show capture CAPI

10 packets captured

```
1: 09:46:26.649456      802.1Q vlan#200 P0 192.0.2.200 > 192.0.2.250 icmp: echo request
2: 09:46:26.649883      802.1Q vlan#200 P0 192.0.2.250 > 192.0.2.200 icmp:
```

echo reply

```
3: 09:46:28.642621      802.1Q vlan#200 P0 192.0.2.200 > 192.0.2.250 icmp: echo request
4: 09:46:28.643002      802.1Q vlan#200 P0 192.0.2.250 > 192.0.2.200 icmp:
```

echo reply

...

Packet trace of the ICMP echo reply shows that the packet is matching an existing connection as expected and the output interface is the FTD interface (NP Identity Ifc):

<#root>

device#

show capture CAPI packet-number 2 trace

10 packets captured

```
2: 09:46:26.649883      802.1Q vlan#200 P0 192.0.2.250 > 192.0.2.200 icmp:
```

echo reply

...

```
Phase: 3
Type: FLOW-LOOKUP
Subtype:
Result: ALLOW
Elapsed time: 4096 ns
Config:
Additional Information:
```

Found flow with id 1400, using existing flow

...

```
Result:
input-interface: NET200(vrfid:0)
```

```
input-status: up
input-line-status: up
```

```
output-interface: NP Identity Ifc
```

```
Action: allow
Time Taken: 28672 ns
```

Debug ICMP trace shows that the ICMP echo reply is being denied:

```
<#root>
```

```
FTD220-5#
```

```
debug icmp trace
```

```
debug icmp trace enabled at level 1
```

```
FTD220-5#
```

```
ping 192.0.2.250
```

```
Type escape sequence to abort.
```

```
Sending 5, 100-byte ICMP Echos to 192.0.2.250, timeout is 2 seconds:
```

```
ICMP echo request from self:192.0.2.200 to NET200:192.0.2.250 ID=49503 seq=15001 len=72
```

```
ICMP echo reply
```

```
from NET200:192.0.2.250 to self:192.0.2.200
```

```
ID=49503 seq=15001 len=72
```

```
Denied ICMP type = 0, code = 0 from 192.0.2.250 on interface 4
```

```
?
```

```
...
```

```
Success rate is 0 percent (0/5)
```



Caution: Use debugs with caution!

To turn off the ICMP debug:

```
<#root>
```

```
device#
```

```
no debug icmp trace
```

```
debug icmp trace disabled.
```

Environment

FTD 10.x. Other software versions are also affected.

Resolution

The issue was resolved by identifying and correcting an ICMP rule configuration in the platform settings that was denying ping traffic. The resolution involved these steps:

Step 1. Verify ARP Table Entries

Confirm that the ARP entries for the upstream IP address are visible in the ARP table of the firewall, which indicates Layer 2 connectivity is functioning properly:

```
<#root>
```

```
device#
```


```
show arp
```

Step 2. Check Platform Settings for ICMP Rules

Navigate to the platform settings configuration and examine the ICMP rule policies that can affect ping traffic. Look specifically for rules that could be blocking or denying ICMP echo request/reply packets.

Step 3. Identify and Modify Blocking ICMP Rule

Locate the ICMP rule in the platform settings that is configured to deny ping traffic.



In this example the ICMP rule permits only ICMP echo requests to be accepted by the FTD interface.

FTD CLI verification:

```
<#root>
```

```
device#
```

```
show run icmp
```

```
icmp unreachable rate-limit 1 burst-size 1
```

```
icmp permit any echo NET200
```

Step 4. Update ICMP Rule Configuration

Modify the identified ICMP rule to allow ping traffic or remove the blocking configuration as appropriate for the network security requirements and operational needs.

Action	ICMP Service	Interface	Network
Permit	ICMP_echo_request	NET200	any ipv4
Permit	ICMP_echo_reply	NET200	net,192.0.2.0

The resulted ICMP rule:

```
<#root>
```

```
device#
```

```
show run icmp
```

```
icmp unreachable rate-limit 1 burst-size 1
icmp permit any echo NET200
```

```
icmp permit 192.0.2.0 255.255.255.0 echo-reply NET200
```

Step 5. Test Connectivity

After making the configuration changes, test the ping connectivity to the upstream IP address to verify that the issue has been resolved and that ICMP traffic is now flowing properly:

```
<#root>
```

```
device#
```

```
ping 192.0.2.250
```

Type escape sequence to abort.

```
Sending 5, 100-byte ICMP Echos to 192.0.2.250, timeout is 2 seconds:
!!!!!
```

```
Success rate is 100 percent (5/5)
```

```
, round-trip min/avg/max = 1/1/1 ms
```

Cause

The root cause of this issue was an ICMP rule configured in the platform settings that was explicitly denying ICMP echo replies traffic. While the firewall maintained proper Layer 2 connectivity (evidenced by the visible ARP entries), the platform-level ICMP rule was blocking Layer 3 ICMP echo reply packets, preventing successful ping operations to the upstream IP address. This type of configuration can occur when security policies are implemented to restrict ICMP traffic but can inadvertently affect legitimate network connectivity testing and monitoring.

Related Content

- https://www.cisco.com/c/en/us/td/docs/security/secure-firewall/management-center/device-config/100/management-center-device-config-10-0/interfaces-settings-platform.html#task_42BBA666CD604517ADA18B32CA162F62
- <https://www.cisco.com/c/en/us/td/docs/security/asa/asa-cli-reference/I-R/asa-command-ref-I-R/ia-inr-commands.html#wp1366339900>
- [Cisco Technical Support & Downloads](#)