

# Contents

[Introduction](#)

[Prerequisites](#)

[Requirements](#)

[Components Used](#)

[Problem: Unexpected outages of the SAP HANA scale-out environment](#)

[Solution](#)

[Related Information](#)

## Introduction

This document describes how SAP High Performance Analytic Appliance (HANA) scale-out solutions with Electromagnetic Compatibility (EMC) VNX storage and applies to the Cisco SAP HANA appliance as well as to SAP HANA Tailored Datacenter Integration (TDI) implementations. It also explains how multipath configuration changes to mitigate unexpected outages of the environment.

## Prerequisites

### Requirements

There are no specific requirements for this document.

### Components Used

This document is not restricted to specific software and hardware versions.

The information in this document was created from the devices in a specific lab environment. All of the devices used in this document started with a cleared (default) configuration. If your network is live, make sure that you understand the potential impact of any command.

## Problem: U

For SAP HANA the required data and log file systems are mounted via fiber channel from the EMC VNX storage. Mounting and unmounting of the devices is controlled by the SAP HANA storage API and is based on the Linux Device Mapper Multipath (DM-MP) module. The configuration consists of eight paths (active/passive) to each storage device.

With SUSE Linux Enterprise System 11.3, Linux kernel 3.0.101-0.40 a bug in the multipathing logic has been detected

This may result in unexpected outages of the SAP HANA scale-out environment.

The bug is not encountered as long as the hardware and cabling is error free.

# Solution

Update the SUSE Linux Enterprise System 11.3 kernel to version

```
rr_min_io  
flush_on_last_del  
fast_io_fail_tmo  
dev_loss_tmo
```

The resulting configuration file must look like this:

```
defaults {  
user_friendly_names    no  
}  
devices {  
    device {  
        vendor          "DGC"  
        product         ".*"   
        product_blacklist "LUNZ"  
        features        "0"  
        hardware_handler "1 emc"  
        path_selector   "round-robin 0"  
        path_grouping_policy group_by_prio  
        failback        immediate  
        rr_weight        uniform  
        no_path_retry    5  
        rr_min_io        1000  
        path_checker     emc_clariion  
        prio             emc  
        flush_on_last_del yes  
        fast_io_fail_tmo off  
        dev_loss_tmo     120  
    }  
}
```

**Note:** The EMC white paper [VNX Configuration Recommendations for SAP HANA TDI](#), page 20, does not mention these changes because the white paper had been created before the kernel bug was detected.

## Related Information

- [EMC KB article 203541 - "SUSE Linux DM-MPIO on VNX storage losing paths randomly in a SAP HANA TDI environment"](#)
- [Technical Support & Documentation - Cisco Systems](#)