



Cisco Application Policy Infrastructure Controller Release Notes, Release 4.2(4)

The Cisco Application Centric Infrastructure (ACI) is an architecture that allows the application to define the networking requirements in a programmatic way. This architecture simplifies, optimizes, and accelerates the entire application deployment lifecycle. Cisco Application Policy Infrastructure Controller (APIC) is the software, or operating system, that acts as the controller.

This document describes the features, issues, and limitations for the Cisco APIC software. For the features, issues, and limitations for the Cisco NX-OS software for the Cisco Nexus 9000 series switches, see the [Cisco Nexus 9000 ACI-Mode Switches Release Notes, Release 14.2\(4\)](#).

For more information about this product, see [Related Content](#).

Note: The documentation set for this product strives to use bias-free language. For the purposes of this documentation set, bias-free is defined as language that does not imply discrimination based on age, disability, gender, racial identity, ethnic identity, sexual orientation, socioeconomic status, and intersectionality. Exceptions may be present in the documentation due to language that is hardcoded in the user interfaces of the product software, language used based on RFP documentation, or language that is used by a referenced third-party product.

Date	Description
December 9, 2022	In the Open Bugs section, added bug CSCvw33061.
November 18, 2022	In the Open Issues section, added bug CSCwc66053.
August 1, 2022	In the Miscellaneous Compatibility Information section, added: <ul style="list-style-type: none">4.2(2a) CIMC HUU ISO (recommended) for UCS C220/C240 M5 (APIC-L3/M3)4.1(2k) CIMC HUU ISO (recommended) for UCS C220/C240 M4 (APIC-L2/M2)
June 30, 2022	In the section Miscellaneous Compatibility, added information about Cisco Nexus Dashboard Insights creating the cisco_SN_NI user.
March 21, 2022	In the Miscellaneous Compatibility Information section, added: <ul style="list-style-type: none">4.1(3f) CIMC HUU ISO (recommended) for UCS C220/C240 M5 (APIC-L3/M3)
February 23, 2022	In the Miscellaneous Compatibility Information section, added: <ul style="list-style-type: none">4.1(2g) CIMC HUU ISO (recommended) for UCS C220/C240 M4 (APIC-L2/M2)
November 2, 2021	In the Miscellaneous Compatibility Information section, added: <ul style="list-style-type: none">4.1(3d) CIMC HUU ISO (recommended) for UCS C220/C240 M5 (APIC-L3/M3)
August 9, 2021	In the Open Issues section, added bug CSCvw33277, CSCvu84392, and CSCvu36682.

Contents

Date	Description
August 4, 2021	In the Open Issues section, added bugs CSCvy30453, CSCvy44940, CSCv18827, CSCvx54410, CSCvx74210, CSCvx90048, and CSCvy30683.
July 26, 2021	In the Miscellaneous Compatibility Information section, the CIMC 4.1(3c) release is now recommended for UCS C220/C240 M5 (APIC-L3/M3).
May 17, 2021	In the Open Issues section, added bugs CSCvt23284 and CSCvx79980.
March 25, 2021	In the Open Issues section, added bug CSCvu74478.
March 11, 2021	<p>In the Miscellaneous Compatibility Information section, for CIMC HUU ISO, added:</p> <ul style="list-style-type: none"> ■ 4.1(3b) CIMC HUU ISO (recommended) for UCS C220/C240 M5 (APIC-L3/M3) <p>Changed:</p> <ul style="list-style-type: none"> ■ 4.1(2b) CIMC HUU ISO (recommended) for UCS C220/C240 M4 (APIC-L2/M2) and M5 (APIC-L3/M3) <p>To:</p> <p>4.1(2b) CIMC HUU ISO (recommended) for UCS C220/C240 M4 (APIC-L2/M2)</p>
February 9, 2021	In the Resolved Issues section, added bug CSCvt07565.
February 3, 2021	<p>In the Miscellaneous Compatibility Information section, for CIMC HUU ISO, added:</p> <ul style="list-style-type: none"> ■ 4.1(2b) CIMC HUU ISO (recommended) for UCS C220/C240 M4 (APIC-L2/M2) and M5 (APIC-L3/M3)
October 6, 2020	In the Open Issues section, added bug CSCvu67494.
September 29, 2020	In the Miscellaneous Compatibility Information section, specified that the 4.1(1f) CIMC release is deferred. The recommended release is now 4.1(1g).
September 16, 2020	<p>In the Known Issues section, added the issue that begins with:</p> <p>Beginning in Cisco APIC release 4.1(1), the IP SLA monitor policy validates the IP SLA port value.</p>
August 7, 2020	Release 4.2(4p) became available. Added the resolved and open bugs for this release.
July 3, 2020	Release 4.2(4o) became available. Added support for VMware vSphere 7.0 with the VMware vSphere Distributed Switch (VDS) and Cisco ACI Virtual Edge.
June 10, 2020	Release 4.2(4k) became available. Added the resolved bugs for this release.
April 23, 2020	Release 4.2(4i) became available.

Contents

- New Software Features
- New Hardware Features
- Changes in Behavior
- Open Issues
- Resolved Issues
- Known Issues
- Compatibility Information
- Related Content
- Documentation Feedback
- Legal Information

New Software Features

Feature	Description	Guidelines and Restrictions
Enhancements for remote leaf switches	<p>Starting with release 4.2(4), the following enhancements have been introduced for remote leaf switches:</p> <ul style="list-style-type: none"> ■ Support for 10 Mbps as a minimum bandwidth in the IPN ■ Support to create an 802.1Q tunnel between the remote leaf switch and the ACI main datacenter <p>For more information, see the chapter "Remote Leaf Switches" in the Cisco APIC Layer 3 Networking Configuration Guide, Release 4.2(x).</p>	<ul style="list-style-type: none"> ■ The IPN path is only used for managing remote leaf switches (management functions such as downgrades, discovery, COOP, and policy pushes). ■ All traffic from the Cisco ACI datacenter and remote leaf switches is through the local L3Out. ■ The EPG or bridge domain are not stretched between the remote leaf switch and the ACI main datacenter.
IGMP snooping version 2 group scale increase	IGMP snooping now supports 32k groups.	None.
Layer 3 multicast VRF scale increase	Layer 3 multicast now supports 300 VRF tables fabric-wide.	None.
Multipod leaf switch scale increase	A multipod environment now supports up to 400 leaf switches per pod.	None.
Network Insights Base app is now prepackaged with Cisco APIC	The Network Insights Base app is now prepackaged with the Cisco APIC software.	None.

New Hardware Features

Feature	Description	Guidelines and Restrictions
Support for 25 SCVMM domains with 10k endpoints	A Cisco ACI fabric can now have up to 25 SCVMM domains with 10k endpoints in pre-provisioned mode.	None.
Support for custom EPG names for VMM domains	You can give EPGs a custom name that carries over to a VMware vCenter port group or a Microsoft VM network. The feature is available for VMware vSphere Distributed Switch, Microsoft System Center Virtual Machine Manager (SCVMM), and Cisco ACI Virtual Edge. If you do not provide a custom name, the domain association assigns one. For more information, see the "Custom EPG Names and Cisco ACI" chapter in the Cisco ACI Virtualization Guide, Release 4.2(x) .	Giving an EPG a custom name—a beta preview feature in the Cisco APIC 4.2(3) release—is in general availability in this release.
Support for VMware vSphere 7.0 with VMware vSphere Distributed Switch and Cisco ACI Virtual Edge	The 4.2(4o) release adds support for VMware vSphere 7.0 with the VMware vSphere Distributed Switch (VDS) and Cisco ACI Virtual Edge.	None.
User lockout after continuous failed attempts to login	You can block a user from being able to log in after the user fails a configured number of login attempts. You can specify how many failed login attempts the user can have within a specific time period. If the user fails to log in too many times, then that user becomes unable to log in for a specified period of time. For more information, see the section "User Lockout After Continuous Failed Attempts to Log in" in the chapter "Access, Authentication, and Accounting" in the Cisco APIC Security Configuration Guide, Release 4.2(x) .	None.

New Hardware Features

For new hardware features, see the [Cisco Nexus 9000 ACI-Mode Switches Release Notes, Release 14.2\(4\)](#).

Changes in Behavior

For the changes in behavior, see the [Cisco ACI Releases Changes in Behavior](#) document.

Open Issues

Click the bug ID to access the [Bug Search Tool](#) and see additional information about the bug. The "Exists In" column of the table specifies the 4.2(4) releases in which the bug exists. A bug might also exist in releases other than the 4.2(4) releases.

Open Issues

Bug ID	Description	Exists in
CSCvw26319	After upgrading from a pre-3.2(7) release to a post-3.2(7) release, there is ERSPAN traffic loss on Cisco ACI Virtual Edge domains.	4.2(4p) and later
CSCvw01908	APIC fabricId is incorrectly reported as 1 by topSystem MO , even if APIC fabricId is configured as a different value at initial setup.	4.2(4o) and later
CSCvw19666	The default firmware policy is not displayed in the GUI after setting the policy, logging out, and logging in again. The field will be blank and there is no area detailing the current default policy.	4.2(4o) and later
CSCvw55905	The configuration from the GUI is accepted, but is reverted back after submission. The underlying problem is that the Cisco APIC policy distributor process continues to retry the same tasks after 4 to 5 minutes because there is no ACK for the completion by the Cisco APIC policy manager. Because of this issue, any recently-implemented configuration (using the GUI or REST API) is not processed, but gets stuck in the queue.	4.2(4o) and later
CSCvw88974	When a route-map is configured using match rules (prefix-list), the CLI output of show running-config shows the wrong prefix length. Only "le 32 128" is displayed in the CLI regardless of the actual range configured in GUI.	4.2(4o) and later
CSCvx79980	In a setup with 3 hosts from the same domain that have some number of virtual machines under them and the reserve host and other parameters are selected, after starting the "Migrate to ACI Virtual Edge" process, all hosts start to move at same time, causing a resource crunch. This issue occurs only once in a while. In a normal scenario, the hosts migrate one by one.	4.2(4o) and later
CSCvy30683	The "show" and "fabric" commands on the Cisco APIC CLI become unresponsive.	4.2(4o) and later
CSCvw08969	After a Cisco APIC upgrade from a pre-4.0 release to a post-4.0 release, connectivity issues occur for devices behind Cisco Application Virtual Edge Switches running on VMWare.	4.2(4o)
CSCvw86355	The Logical Interface Profiles (Folder) shows different IP addresses assigned to each interface than what is configured in the interface profile. This is a cosmetic issue because the interfaces are programmed correctly.	4.2(4k) and later
CSCvw33173	The message " Faults/health summary disabled due to max limit reached" is visible under Fabric -> Inventory -> Topology -> Summary, even when the user has not reached the documented limit.	4.2(4k) and later

Open Issues

Bug ID	Description	Exists in
CSCVy44940	<p>APIC symptoms: After a Cisco APIC has finished upgrading and has reloaded, the ifc_reader crashes about 6 times in 7 minutes. Afterward, the ifc_reader service stops, which causes Cisco APIC communication issues. ifc_reader DME issues are not reflected in the AV health values, rvcad, nor the Cisco APIC GUI. aci diag avread, rvcad, and the Cisco APIC GUI report a fully fit cluster. Cisco APIC GUI alarms raise a "split fabric" alert, and crashes in the NGINX process may be observed.</p> <p>Switch Symptoms: After the Cisco APICs have been upgraded, all switches start seeing NGINX DME crashes every few minutes. The rate of crashes increases with the rate of uribv4NextHop.type API queries that result in switch queries. After the NGINX process has received 250 instances of the offending query, the switch will cut off the interfaces, as it has reached a failed state. This will lead to a loss of network connectivity on the affected devices.</p>	4.2(4k) and later
CSCvd66359	The Port ID LLDP Neighbors panel displays the port ID when the interface does not have a description. Example: Ethernet 1/5, but if the interface has description, the Port ID property shows the Interface description instead of the port ID.	4.2(4i) and later
CSCvf70362	<p>This enhancement is to change the name of "Limit IP Learning To Subnet" under the bridge domains to be more self-explanatory.</p> <p>Original :</p> <p style="padding-left: 40px;">Limit IP Learning To Subnet: <input type="checkbox"/></p> <p>Suggestion :</p> <p style="padding-left: 40px;">Limit Local IP Learning To BD/EPG Subnet(s): <input type="checkbox"/></p>	4.2(4i) and later
CSCvg00627	A tenant's flows/packets information cannot be exported.	4.2(4i) and later
CSCvg35344	Requesting an enhancement to allow exporting a contract by right clicking the contract itself and choosing "Export Contract" from the right click context menu. The current implementation of needing to right click the Contract folder hierarchy to export a contract is not intuitive.	4.2(4i) and later
CSCvg81020	For strict security requirements, customers require custom certificates that have RSA key lengths of 3072 and 4096.	4.2(4i) and later
CSCvi20535	When a VRF table is configured to receive leaked external routes from multiple VRF tables, the Shared Route Control scope to specify the external routes to leak will be applied to all VRF tables. This results in an unintended external route leaking. This is an enhancement to ensure the Shared Route Control scope in each VRF table should be used to leak external routes only from the given VRF table.	4.2(4i) and later
CSCvj56726	The connectivity filter configuration of an access policy group is deprecated and should be removed from GUI.	4.2(4i) and later
CSCvk18014	The action named 'Launch SSH' is disabled when a user with read-only access logs into the Cisco APIC.	4.2(4i) and later

Open Issues

Bug ID	Description	Exists in
CSCvm42914	This is an enhancement request to add policy group information to the properties page of physical interfaces.	4.2(4i) and later
CSCvm56946	Support for local user (admin) maximum tries and login delay configuration.	4.2(4i) and later
CSCvm64933	The Cisco APIC setup script will not accept an ID outside of the range of 1 through 12, and the Cisco APIC cannot be added to that pod. This issue will be seen in a multi-pod setup when trying add a Cisco APIC to a pod ID that is not between 1 through 12.	4.2(4i) and later
CSCvn12839	Error " mac.add.ress not a valid MAC or IP address or VM name" is seen when searching the EP Tracker.	4.2(4i) and later
CSCvo24284	Fault delegates are raised on the Cisco APIC, but the original fault instance is already gone because the affected node has been removed from the fabric.	4.2(4i) and later
CSCvo41153	We do not support a bridge domain in hardware proxy mode for flood in encapsulation. However, there is no warning or validation in the GUI. This bug is to add validation and a warning message when the user is trying to configure flood in encapsulation.	4.2(4i) and later
CSCvo87667	Post reload, the IGMP snooping table is not populated even when the IGMP report is sent by the receiver.	4.2(4i) and later
CSCvp26694	A leaf switch gets upgraded when a previously-configured maintenance policy is triggered.	4.2(4i) and later
CSCvp62048	New port groups in VMware vCenter may be delayed when pushed from the Cisco APIC.	4.2(4i) and later
CSCvq54761	The application EPG or the corresponding bridge domain's public subnet may be advertised out of an L3Out in another VRF instance without a contract with the L3Out under certain conditions.	4.2(4i) and later
CSCvq57942	In a RedHat OpenStack platform deployment running the Cisco ACI Unified Neutron ML2 Plugin and with the CompHosts running OVS in VLAN mode, when toggling the resolution immediacy on the EPG<->VMM domain association (fvRsDomAtt.reslmedcyc) from Pre-Provision to On-Demand, the encap VLANs (vlanCktEp mo's) are NOT programmed on the leaf switches. This problem surfaces sporadically, meaning that it might take several reslmedcyc toggles between PreProv and OnDemand to reproduce the issue.	4.2(4i) and later
CSCvq63415	Disabling dataplane learning is only required to support a policy-based redirect (PBR) use case on pre-" EX" leaf switches. There are few other reasons otherwise this feature should be disabled. There currently is no confirmation/warning of the potential impact that can be caused by disabling dataplane learning.	4.2(4i) and later
CSCvq80820	A previously-working traffic is policy dropped after the subject is modified to have the " no stats" directive.	4.2(4i) and later

Open Issues

Bug ID	Description	Exists in
CSCVq95687	<p>Currently, under Fabric > Inventory > Pod > Leaf Switch > General, the memory usage takes in consideration the MemFree field rather than the MemAvailable, which would be a more accurate representation of the usable memory in the system.</p> <p>In some cases, the GUI might show that the memory utilization is around 90% while in reality it's 50%, because there is still the cached/buffered memory to take into account. This buffered/cached memory will free up a big chunk of memory in case more memory is needed.</p>	4.2(4i) and later
CSCVq96516	There is an event manager process crash.	4.2(4i) and later
CSCVr10020	Fault alarms get generated at a higher rate with a lower threshold. There is no functional impact.	4.2(4i) and later
CSCVr12971	The Cisco APIC GUI produces the following error messages when opening an EPG policy: Received Invalid Json String. The server returned an unintelligible response. This issue might affect backup/restore functionality.	4.2(4i) and later
CSCVr19693	When configuring local SPAN in access mode using the GUI or CLI and then running the "show running-config monitor access session<session>" command, the output does not include all source span interfaces.	4.2(4i) and later
CSCVr62453	When a Cisco ACI fabric upgrade is triggered and a scheduler is created and associated to the maintenance group, the scheduler will remain associated to the maintenance group. If the version is changed in the maintenance group, it will trigger the upgrade. This enhancement is to avoid unwanted fabric upgrades. Post-upgrade, the association of the scheduler should be removed from the maintenance group after the node upgrade reaches 100%.	4.2(4i) and later
CSCVr85945	There should be a description field in the subnet IP address tables.	4.2(4i) and later
CSCVs01864	This bug is an enhancement to add an option to configure an interface description for subport blocks in the Cisco APIC GUI.	4.2(4i) and later
CSCVs03055	While configuring a logical node profile in any L3Out, the static routes do not have a description.	4.2(4i) and later
CSCVs10339	This is an enhancement to add columns in "Fabric > Inventory> Fabric Membership" to show BGP Route Reflectors for within pod and across pods (external BGP RR).	4.2(4i) and later
CSCVs11202	After exiting Maintenance (GIR) mode, the switch reloads automatically after 5 minutes without warning. This enhancement will provide messaging in the GUI to indicate that the reload is expected.	4.2(4i) and later
CSCVs13857	L3Out encapsulated routed interfaces and routed interfaces do not have any monitoring policy attached to them. As a result, there is no option to change the threshold values of the faults that occur due to these interfaces.	4.2(4i) and later

Open Issues

Bug ID	Description	Exists in
CSCvs15870	Fibre Channel conversion is allowed on an unsupported switch. The only switch that supports Fibre Channel conversion is the Cisco N9K-C93180YC-FX.	4.2(4i) and later
CSCvs15964	The GUI does not provide a "Revert" option for interfaces that are converted to Fibre Channel.	4.2(4i) and later
CSCvs16317	An app does not get fully removed from all Cisco APICs.	4.2(4i) and later
CSCvs29556	When logging into the Cisco APIC using "apic#fallback\user", the "Error: list index out of range" log message displays and the lastlogin command fails. There is no operational impact.	4.2(4i) and later
CSCvs49777	Cisco Application Policy Infrastructure Controller (APIC) includes a version of SQLite that is affected by the vulnerabilities identified by the following Common Vulnerability and Exposures (CVE) IDs: CVE-2019-5018 This bug was opened to address the potential impact on this product.	4.2(4i) and later
CSCvs51137	Creating a new interface policy group with a different LACP policy or LLDP/CDP policy results in changes in the VMM vSwitch policy of the AEP, which brings down the DVS.	4.2(4i) and later
CSCvs56642	This is an enhancement request for schedule-based Tech Support for leaf and spine switches.	4.2(4i) and later
CSCvs64425	"*.G" got created in both MRIB and MFDM, is present for nearly 9 minutes, and then got expired.	4.2(4i) and later
CSCvs78996	The policy manager (PM) may crash when use testapi to delete MO from policymgr db.	4.2(4i) and later
CSCvs81944	The following example shows UNIX time in the subject header: Subject: Configuration import/export job 2020-01-27T09-00-16 finished with status: success Created: 1580144423366 ContentType: plain/text	4.2(4i) and later
CSCvt00629	After upgrading to APIC release 4.2(3i), the remote leaf switch does not rejoin the fabric.	4.2(4i) and later
CSCvt18530	The paths list in UCSM Integration Tab->Policy is empty. There are no paths and therefore no VLANs listed. The Leaf-Enforced mode on UCSM Integration filters out all VLANs, resulting in traffic loss.	4.2(4i) and later
CSCvt23284	If the DVS version is 6.6 or later or the VMware vCenter version is 7.0, using basic LACP will raise errors on the VMware vCenter, as these releases of DVS and VMware vCenter no longer support LACP.	4.2(4i) and later
CSCvt30716	UCSM Integration shows an old topology when the connection between the fabric interconnect and leaf switch pair is removed, because LooseNode information is not updated when LLDP connections go away. This persists even after you delete the integration and add the UCSM as a new integration.	4.2(4i) and later

Open Issues

Bug ID	Description	Exists in
CSCvt31539	The UCSM app fails to configure a native VLAN on the UCSM if you configure an EPG with the native VLAN set. The app sets the VLAN as a normal trunk-tagged VLAN on the UCSM. This causes the blackholing of traffic.	4.2(4i) and later
CSCvt34925	This bug is an enhancement to enable the configuring of SNMPv3 with SHA2 and AES256. This configuration is needed for as a security enhancement.	4.2(4i) and later
CSCvt36402	The global QoS class congestion algorithm is always incorrectly shown as 'Tail Drop' even though it changed as WRED. The managed object shows correctly when it changed; this is a cosmetic issue.	4.2(4i) and later
CSCvt38676	Route-map entry on the Cisco ACI Multi-Site speaker spine node to change the BGP next-hop from PTEP to R-TEP for routes advertised by the border leaf node is absent. Routes will be advertised with PTEP to the other site.	4.2(4i) and later
CSCvt39746	Cisco APIC interfaces e2/3 and 2/4 persist in the GUI and the MIT after disabling and enabling the port channel on the VIC.	4.2(4i) and later
CSCvt40736	The login history of local users is not updated in Admin > AAA > Users > (double click on local user) Operational > Session.	4.2(4i) and later
CSCvt44854	<p>- Leaf or spine switch is stuck in 'downloading-boot-script' status. The node never fully registers and does not become active in the fabric.</p> <p>- You can check the status by running 'cat /mit/sys/summary grep state' on the CLI of the spine or leaf:</p> <p>If the state is set to 'downloading-boot-script' for a long period of time (> 5 minutes), you may be running into this issue.</p> <p>- Checking policy element logs on the spine or leaf switch will confirm if the bootscript file cannot be found on the Cisco APIC:</p> <ol style="list-style-type: none"> 1. Change directory to /var/log/dme/log. 2. Grep all svc_ifc_policyelem.log files for "downloadUrl - failed, error=HTTP response code said error". <p>If you see this error message, check to make sure all Cisco APICs have the node bootscript files located in /firmware/fwrepos/fwrepo/boot.</p>	4.2(4i) and later
CSCvt44940	Fault F1298 raised and states that "Delivered,Node belongs to different POD". Actually, the node belongs to the correct POD and fault is misleading.	4.2(4i) and later
CSCvt48790	There is a stale fvIfConn entry after physically removing the ESXi host after a host is removed from the datacenter or VMware vCenter.	4.2(4i) and later
CSCvt49260	The 'Primary VLAN for Micro-Seg' field does not show without putting a check in the Allow Micro-Segmentation check box.	4.2(4i) and later
CSCvt50251	CloudSec encryption may not function when certain features are enabled, such as remote leaf switches and Cisco ACI Multi-Site intersite L3Outs.	4.2(4i) and later

Open Issues

Bug ID	Description	Exists in
CSCvt55566	In the Cisco APIC GUI, after removing the Fabric Policy Group from " System > Controllers > Controller Policies > show usage" , the option to select the policy disappears, and there is no way in the GUI to re-add the policy.	4.2(4i) and later
CSCvt58389	When you have a single VMM domain deployed in 2 different VMware vCenters in same SSO domain and you uninstall all Cisco ACI Virtual Edge virtual machines on one of the VMware vCenters by using VCPlugin for the VMM domain, then the VCPlugin on the other VMware vCenter for the same VMM domain shows the existing Cisco ACI Virtual Edge as " not installed" . This happens because the cisco-ave and cisco-ave-<vmm-domain> tags are removed on the other VMware vCenter for the Cisco ACI Virtual Edge virtual machines.	4.2(4i) and later
CSCvt64925	Changes to a Cisco APIC configuration are no longer pushed to the Cisco APIC.	4.2(4i) and later
CSCvt65329	The Cisco APIC GUI does not expose the 'destName' property of the vnsRedirectDest managed object.	4.2(4i) and later
CSCvt67097	In the Cisco APIC GUI, external EPGs under L2Out and L3Out in tenants are called " External Network Instance Profile" . This is the official name for object (I2extInstP and I3extInstP). However, these are typically referred to as external EPGs. This is an enhancement to update the GUI label from " External Network Instance Profile" to " External EPG" .	4.2(4i) and later
CSCvt67279	After VMware vCenter generates a huge amount of events and after the eventId increments beyond 0xFFFFFFFF, the Cisco APIC VMM manager service may start ignoring the newest event if the eventId is lower than the last biggest event ID that Cisco APIC received. As a result, the changes to virtual distributed switch or AVE would not reflect to the Cisco APIC, causing required policies to not get pushed to the Cisco ACI leaf switch. For AVE, missing those events could put the port in the WAIT_ATTACH_ACK status.	4.2(4i) and later
CSCvt68267	With DHCP in which the node is not properly decommissioned, the DHCP process released the IP address and allocated the IP address to another TEP, which caused a duplicate TEP and caused an outage.	4.2(4i) and later
CSCvt68314	Fault F0948 is raised in the fabric, where the child-most affected object is " rsBDToProfile" .	4.2(4i) and later
CSCvt70316	SNMP poll/walk to the Cisco APIC does not work . The error message " unknown username" is received.	4.2(4i) and later
CSCvt70397	After decommissioning/removing a node ID from the Cisco APIC, wait for 10 minutes before re-adding the same node back into fabric. Re-adding the node too early can result in unexpected behavior, such as the node that is being decommissioned does not get wiped properly and ends up retaining the TEP address that was allocated by the Cisco APIC.	4.2(4i) and later
CSCvt72773	The Authentication Type displays as " Use SSH Public/Private Files." However, Cisco APIC acts as a client to the (outside) server, and so " Private" should be the only configurable key in the " SSH Key Contents" area.	4.2(4i) and later
CSCvt72778	Editing a remote location with a private key that doesn't have a passphrase is blocked due to form validation.	4.2(4i) and later

Open Issues

Bug ID	Description	Exists in
CSCvt79906	After creating a BGP-peer connectivity profile with the loopback option (no presence loopback on L3Out node) in a vPC setup, the BGP session is getting established with a secondary IP address.	4.2(4i) and later
CSCvt87506	SSD lifetime can be exhausted prematurely if unused Standby slot exists	4.2(4i) and later
CSCvt91540	<ul style="list-style-type: none"> - After decommissioning a fabric node, it is not displayed in the maintenance group configuration anymore. - Due to the lingering configuration pointing to the decommissioned node, F1300 gets raised with the description: " A Fabric Node Group (fabricNodeGrp) configuration was not deployed on the fabric node <#> because: Node Not Registered for Node Group Policies" - The dn mentioned in the fault will point to a maintenance group (maintgrp). 	4.2(4i) and later
CSCvt92961	A TEP endpoint can expire on the leaf switch if the host does not respond on a unicast ARP refresh packet initiated by the leaf switch.	4.2(4i) and later
CSCvt93482	<p>The per feature container for techsupport "objectstore_debug_info" fails to collect on spines due to invalid filepath.</p> <p>Given filepath: more /debug/leaf/nginx/objstore*/mo cat</p> <p>Correct filepath: more /debug/spine/nginx/objstore*/mo cat</p> <p>TAC uses this file/data to collect information about excessive DME writes.</p>	4.2(4i) and later
CSCvt94286	Deploy the TACACS server for in-band management. When adding or modifying the TACACS+ provider key, the Cisco APIC can be reached only through SSH and the login fails on the fabric. After deleting the provider entry and reconfiguring, the fabric can be logged into.	4.2(4i) and later
CSCvt96250	After creating a Global Alias Field on an EPG in a user tenant and submitting the change, the tag can be seen as successfully created on the EPG. However, operations such as renaming or deleting do not update the tag after submitting the change.	4.2(4i) and later
CSCvt98738	Code F1527 occurs in /data/log on a Cisco APIC. After collecting the "show tech file" for the Cisco APIC, the percentage is shown as only 71%.	4.2(4i) and later
CSCvu01259	AAEP gets deleted while changing some other policy in the policy group. This only happens when using Firefox and changing a value in the leaf access port policy group. The issue is not seen when using other browsers.	4.2(4i) and later
CSCvu01452	The MD5 checksum for the downloaded Cisco APIC images is not verified before adding it to the image repository.	4.2(4i) and later
CSCvu01711	Traffic from newly added subnet(s) is allowed on one or more Cisco APIC(s) and blocked on the other one or more Cisco APIC(s). As Ext Mgmt NW Inst Prof Subnets are applied/programmed on all Cisco APICs, traffic should work on all Cisco APICs.	4.2(4i) and later

Open Issues

Bug ID	Description	Exists in
CSCvu05213	Enhancement request to provide a warning prompt to users if they do a configuration export without enabling AES Encryption.	4.2(4i) and later
CSCvu05236	In the Cisco APIC GUI, under Fabric -> Inventory -> Pod 1 -> Leaf/Spine -> Summary -> Hardware Usage -> Memory, a memory usage value over 80% is colored red.	4.2(4i) and later
CSCvu06061	A switch entered into a bootloop and an upgrade is triggered multiple times if the maintenance policy is pushed with a REST API call that has the incorrect version.	4.2(4i) and later
CSCvu08233	Inside the /firmware/fwrepos/fwrepo/boot directory, there is a Node-0 bootscript that seemingly points to a random leaf SN, depending on the Cisco APIC from which you're viewing the directory.	4.2(4i) and later
CSCvu08274	The Smart Licensing GUI page fails to load due to the JavaScript function erroring out while trying to parse an invalid LicenseManager object. The JavaScript error can be seen in the browser developer tools - console logs.	4.2(4i) and later
CSCvu12092	AVE is not getting the VTEP IP address from the Cisco APIC. The logs show a "pending pool" and "no free leases".	4.2(4i) and later
CSCvu12478	Fabric > Inventory > Topology > Topology shows the wrong Cisco APIC counts (Active + Standby) in different pods.	4.2(4i) and later
CSCvu18072	The Cisco APIC setup script will not accept an ID outside of the range of 1 through 12, and the Cisco APIC cannot be added to that pod. This issue will be seen in a multi-pod setup when trying add a Cisco APIC to a pod ID that is not between 1 through 12. CSCvm64933 was filed for similar issue.	4.2(4i) and later
CSCvu21530	Protocol information is not shown in the GUI when a VRF table from the common tenant is being used in any user tenant.	4.2(4i) and later
CSCvu26167	Physical Interface Configuration's VLAN tab shows incorrect VLAN assignments on all ports. Ports with no EPGs deployed will show the entire switch VLAN assignment instead of no assigned VLANs.	4.2(4i) and later
CSCvu26586	<p>When the productSpec of a DVS is changed from Cisco Systems to Vmware Inc as a workaround for bug CSCvr86180, if the VMware vCenter is reloaded after that point, that will result in a change of the object type at the VMware vCenter (DistributedVirtualSwitch to VmwareDistributedVirtualSwitch). That has the effect of the Cisco APIC deleting the hvslNode the next time it pulls inventory from the VMware vCenter after the VMware vCenter comes back up.</p> <p>When the productSpec is switched back to Cisco Systems, a new hvslNode is created with most of the fields left as uninitialized, which raises faults on the DVS. Lnode(DVS) gets deleted on the external VMM controller and the MTU on the DVS is different than the MTU in the policy.</p> <p>This is a cosmetic issue. There is no functionality impact.</p>	4.2(4i) and later
CSCvu26840	The following error message is seen when configuring: Prepend AS: Error 400 - Invalid lastnum: 1. lastnum must be 0 when criteria is prepend.	4.2(4i) and later

Open Issues

Bug ID	Description	Exists in
CSCvu28019	A spine switch doesn't advertise the bridge domain or host routes to the GOLF router via BGP, and the bgpPfxLeakP managed object is missing for all bridge domain subnets	4.2(4i) and later
CSCvu34069	APIC ->System- >Controller -> topology displays that APIC2 is connected to both pod1 and pod2	4.2(4i) and later
CSCvu36573	When a multi-pod environment is deployed in a non-home pod, the hyper-v servers cannot establish a successful connection to the leaf switch, and the opflexODev and OpflexIDep objects are not created on the leaf switch. This results in a traffic outage, as the on-demand EPGs will be removed from the setup.	4.2(4i) and later
CSCvu36682	After upgrading to release 4.2(3q), the Event Manger generates a core and crashes continuously, leading to a diverged cluster.	4.2(4i) and later
CSCvu39569	The following error is encountered when accessing the Infrastructure page in the ACI vCenter plugin after inputting vCenter credentials. " The Automation SDK is not authenticated" VMware vCenter plug-in is installed using powerCLI. The following log entry is also seen in vsphere_client_virgo.log on the VMware vCenter: /var/log/vmware/vsphere-client/log/vsphere_client_virgo.log [ERROR] http-bio-9090-exec-3314 com.cisco.aciPluginServices.core.Operation sun.security.validator.ValidatorException: PKIX path validation failed: java.security.cert.CertPathValidatorException: signature check failed	4.2(4i) and later
CSCvu41160	VMware vCenter is offline according to the Cisco APIC. The Cisco APIC is unable to push port groups into VMware vCenter. The leader Cisco APIC for VMware vCenter connections shows as disconnected. There are faults on the VMM domain related to incorrect credentials, but the credentials are actually correct. The same credentials can be used to log in to the VMware vCenter GUI successfully. The " administrator@vsphere.local" account does not work either, so permissions should not be a problem.	4.2(4i) and later
CSCvu44604	- The configuration is not pushed from the Cisco APIC to RHVM. For example, when attaching a VMM domain to an EPG, the EPG is not created as a logical network in RHVM. - vmmmgr logs indicate that Worker Q is at 300 with Max Q of 300. - When the Q reaches 300, it appears this is caused by the class definition 'ifc:vmmmgr:taskCompHvGetHpNicAdjQualCb' using up the entire worker Q. - There are numerous logs indicating that the sendtoController failed and the Worker is busy.	4.2(4i) and later

Open Issues

Bug ID	Description	Exists in
CSCvu44730	<p>Associating an EPG to a FEX interface from Fabric->Inventory->Pod1->leaf->interface in the Cisco APIC GUI creates an unexpected tDn.</p> <p>As a side effect, this type of static EPG association will cause the following error if you use Cisco APIC CLI to verify the leaf node configuration:</p> <p>Error while processing mode: configure</p> <p>Error: Key [eh101/1/218] is in FEX format, we expect in extpath format</p>	4.2(4i) and later
CSCvu49080	Periodically, the OpFlex session disconnects. This Issue was seen in K8 integration with Cisco ACI due to an ARP refresh issue for the host VTEP address.	4.2(4i) and later
CSCvu49644	A tunnel endpoint doesn't receive a DHCP lease. This occurs with a newly deployed or upgraded Cisco ACI Virtual Edge.	4.2(4i) and later
CSCvu50088	When trying to assign a description to a FEX downlink/host port using the Config tab in the Cisco APIC GUI, the description will get applied to the GUI, but it will not propagate to the actual interface when queried using the CLI or GUI.	4.2(4i) and later
CSCvu51617	When changing the SNMP policy from policy1 to policy2 and if policy2 has the same SNMP v3 user configured with a different authentication key, the pod policy reports fault F2194 for all switches. The Cisco APICs in the cluster will accept the new policy; however, the switches in the fabric will not and will continue using the older policy1.	4.2(4i) and later
CSCvu56364	Cisco APIC accepts the "_" (underscore) symbol as delimiter for VMware VMM Domain Association, even though it is not a supported symbol. This is an enhancement request to implement a check in the Cisco APIC GUI to not accept "_" .	4.2(4i) and later
CSCvu58269	DHCP clients in the Cisco ACI fabric fail to obtain addresses from a DHCP server if inter-VRF DHCP is being used and the DHCP provider is an L3Out in a different VRF table than the client.	4.2(4i) and later
CSCvu60050	Traffic drops between select EPGs involved in shared-service contract. The shared routes gets programmed with a ptag of 0 which causes traffic from the source EPG to the destination to get dropped.	4.2(4i) and later
CSCvu62127	<p>A new APIC-L3 or M3 server will not be able to complete fabric discovery. LLDP, "acidiag verifyapic," and other general checks will not exhibit a problem.</p> <p>When you check the appliancedirector logs of a Cisco APIC within the cluster to which you are trying to add the affected controller, there will be messages indicating that the rejection is happening due to being unable to parse the certificate subject.</p>	4.2(4i) and later
CSCvu62465	<p>For an EPG containing a static leaf node configuration, the Cisco APIC GUI returns the following error when clicking the health of Fabric Location:</p> <p>Invalid DN topology/pod-X/node-Y/local/svc-policyelem-id-0/ObservedEthlf, wrong rn prefix ObservedEthlf at position 63</p>	4.2(4i) and later

Open Issues

Bug ID	Description	Exists in
CSCvu67110	<p>This defect covers a patch for a condition similar to CSCvn15769 but not covered in the patch for it.</p> <p>There are recurring crashes and core dumps on different Cisco APICs (which are VMM domain shard leaders), as well as high CPU utilization (around 200% so to 2x maxed out CPU cores) for the VMMMGr process, as well as multiple inv sync issues.</p> <p>These issues are preventing the VMMMGr process from processing any operational/configuration changes that are made on the RHVs.</p> <p>This can be resolved these by repeatedly restarting the vmmgr process (the aforementioned cores are NOT caused by the process restarts). However, restarting a DME is not a recommended workaround.</p>	4.2(4i) and later
CSCvu67388	<p>When creating a VMware VMM domain and specifying a custom delimiter using the character _ (underscore), it is rejected, even though the help page says it is an acceptable character.</p>	4.2(4i) and later
CSCvu67494	<p>Logging in using TACACS to 1 or multiple Cisco APICs can intermittently fail while showing fault F0023. TCPDump shows that the Cisco APIC is resetting the 3-way-handshake. Sometimes, the following error message displays:</p> <p>The server is temporarily busy due to higher than usual request volume. Please try again later.</p> <p>Unable to deliver the message, Resolve timeout from (type/num/svc/shard) =</p>	4.2(4i) and later
CSCvu67941	<p>TACACS+ users are unable to login to a Cisco APIC when an AV pair is in use with a dot '.' character in the domain portion. Users may be able to login with minimal permissions if the "Remote user login policy" allows it. The following example shows an AV pair that causes the issue:</p> <pre>shell:domains = aci.domain/admin/</pre> <p>Additionally, NGINX logs on the Cisco APIC show the following log line:</p> <pre>23392 2020-06-16T21:04:56.534944300+00:00 aaa INFO Failed to parse AVPair string (shell:domains = aci.domain/admin/) into required data components - error was Invalid shell:domains string (shell:domains = aci.domain/admin/) received from AAA server .../svc/extXMLApi/src/gen/ifc/app/.pam/PamRequest.cc 813</pre> <p>This log can be found at /var/log/dme/log/nginx.bin.log on the Cisco APIC.</p>	4.2(4i) and later
CSCvu69651	<p>VMM floating L3Out basic functionality does not work. The L3Out port group on a VMware vCenter does not match the configuration in the Cisco APIC. For example, there can be a VLAN mismatch.</p> <p>Cisco APIC visore will show missing compEpPConn, and the port-group's hvsExtPol managed object will not form hvsRsEpPD to the L3Out compEpPD.</p>	4.2(4i) and later

Open Issues

Bug ID	Description	Exists in
CSCvu69932	This product includes a version of Third-party Software that is affected by the vulnerabilities identified by the following Common Vulnerability and Exposures (CVE) IDs: CVE-2020-11022 This bug was opened to address the potential impact on this product.	4.2(4i) and later
CSCvu70621	The /data2 partition is filled up with docker temporary files. Output of "df -hu /data2" will indicate 100% usage. Login as root and check the usage under /data2/docker/tmp. Confirm that this is the folder causing the partition to be full.	4.2(4i) and later
CSCvu72345	When using the Visibility & Troubleshooting tool for the reachability of two endpoints, there are errors such as "Bad Gateway" and "The server is temporarily busy due to a higher than usual request volume. Please try again later."	4.2(4i) and later
CSCvu74478	A prefix with an aggregate entry gets removed from Cisco APIC when downgrading the Cisco APIC from 4.2(5) to an earlier release. Due to this, the route map does not get created on the switches, and so routes are not advertised externally.	4.2(4i) and later
CSCvu74566	There is a BootMgr memory leak on a standby Cisco APIC. If the BootMgr process crashes due to being out of memory, it continues to crash, but system will not be rebooted. After the standby Cisco APIC is rebooted by hand, such as by power cycling the host using CIMC, the login prompt of the Cisco APIC will be changed to localhost and you will not be able to log into the standby Cisco APIC.	4.2(4i) and later
CSCvu84392	The policy-mgr crashes on multiple Cisco APICs during an upgrade.	4.2(4i) and later
CSCvu85463	When Tenant has large amount of EPGs configured, such as over one thousand, when navigating to the network exporters pane, when clicking the policy, it takes several seconds for the application EPG to be displayed. When a lower number of EPGs are present, there is no delay in the EPG being populated. This is a cosmetic defect due to scale.	4.2(4i) and later
CSCvv00341	After a switch replacement, the Cisco APIC will no longer be able to run show commands on it, such as "fabric 101 show int bri", where "101" is the Node ID of the replaced switch. The Cisco APIC will be able to send the command to the switch, but the return will be empty due to an old SSH key (the key of the old switch).	4.2(4i) and later
CSCvv08475	When using the command "show run vpc context," some of the leaf switch pairs are not included in the output.	4.2(4i) and later
CSCvv10668	Using the filter feature for application profiles always returns all of the application profiles.	4.2(4i) and later
CSCvv15139	The "Locator LED" and "Indicator LED Color" fields in the Cisco APIC GUI for a physical interface do not accurately reflect the state of the locator LED. If you change the state of the Locator LED, the change will not be reflected in the GUI, but will be pushed to the switch correctly.	4.2(4i) and later
CSCvv15930	Visibility & Troubleshooting tool returns "Internal query error:list index out of range" followed by "Server API calls return error. Please click OK to go back to the first page.".	4.2(4i) and later

Open Issues

Bug ID	Description	Exists in
CSCwv17139	Cisco ACI snapshots cannot be compared and the following error is generated: File SNAPSHOT_NAME is not a valid snapshot. Could not parse NAPSHOT_NAME_1.json: Invalid control character at: line 1 column X	4.2(4i) and later
CSCwv18827	The data in the Cisco APIC database may get deleted during an upgrade from a 3.0 or 3.1 release to a 4.0 or 4.1 release if the target release is rolled back to current running release within 2 minutes after the upgrade was started. The upgrade will continue anyway, but the Cisco APIC will lose all data in the database and a user with admin credentials cannot log in. Only the rescue-user/admin can log in. All shards for a process show as unexpected, and the database files are removed. The last working pre-upgrade database files are copied to the purgatory directory.	4.2(4i) and later
CSCwv20398	VMware vCenter Event logs in the Cisco APIC are not visible in release 4.2(4i).	4.2(4i) and later
CSCwv21442	The Cisco APIC does not allow an upgrade to be cancelled. Rolling back the target version after an upgrade is started does not stop the upgrade and may cause Cisco APIC database loss. This enhancement is filed to block a Cisco APIC target version change unless the following conditions are met: 1. All Cisco APICs are online and the cluster is fully fit. 2. The upgrade job (maintUpgJob) for all Cisco APICs are completed. 3. The Installer.py process is not running on any of the Cisco APICs.	4.2(4i) and later
CSCwv22932	An SNMPD process crash is observed on two of the Cisco APICs in three Cisco APIC cluster.	4.2(4i) and later
CSCwv24758	For a tenant name starting with "infra," such as "infratest," the L3Out create wizard does not allow the user to select a particular VRF. Only overlay-1 is allowed, which is the default for infra. Another issue is the Add Pod option does not work in this scenario.	4.2(4i) and later
CSCwv25475	After a delete/add of a Cisco ACI-managed DVS, dynamic paths are not programmed on the leaf switch and the compRsDIPol managed object has a missing target. The tDn property references the old DVS OID instead of the latest value. # moquery -c compRsDIPol	4.2(4i) and later
CSCwv25620	When "global EP Listen Policy" is enabled on Cisco APIC, the following faults might be raised: F1190: if the policy is enforced on a Layer3 port on switch F0532: if the policy is enforced on a port which is operationally down The fix for this bug will ensure that the policy will not be enforced on the following types of ports: 1. Layer 3 ports. 2. Ports that are operationally down.	4.2(4i) and later
CSCwv27158	The VMM process crashes and produces core files when looking in Admin -> Import/Export -> Export Policies -> Core -> default -> Operational tab.	4.2(4i) and later

Open Issues

Bug ID	Description	Exists in
CSCvw28749	A bridge domain subnet is explicitly marked as public. The same EPG subnet has the shared flag enabled and has an implicit private scope. The private scope should take precedence over the public scope and should not get advertised. However, the bridge domain subnet does get advertised through the L3Out.	4.2(4i) and later
CSCvw30303	The configuration of a bridge domain subnet scope as " public" and an EPG scope as " private" should not be allowed.	4.2(4i) and later
CSCvw32302	During a policy upgrade, the upgrade fails for some of the Cisco APICs with the Traceback error " Exception while waiting for turn" .	4.2(4i) and later
CSCvw37322	In the Common tenant, clicking on an FHS policy for the first time generates a POST and that gets sent from the GUI as the logged in user to create the child raguardpol. There is no confirmation or notification. However, in the audit logs, there is an entry to log this configuration. Location in GUI: First Hop Security policy under Common tenant ----> Policies ----> Protocol ----> First Hop Security ----> Feature Policies --> Default	4.2(4i) and later
CSCvw38458	Interface counters are cleared successfully in the CLI, but the original CRC stomped value is still observed in the GUI.	4.2(4i) and later
CSCvw41784	EIGRP summary routes are not advertised from one of the many interfaces under same interface profile.	4.2(4i) and later
CSCvw46447	The following errors are seen on a Cisco APIC. GUI: Error the messaging layer was unable to deliver the stimulus (connection error, Address already in use) CLI: apic# show controller Bind failed. Error Code : 98 Message: Address already in use	4.2(4i) and later
CSCvw50268	Port-groups named " " may be created in VMware vCenter when a vmmEpPD MO (VMM port group) is not present when the l3extRsDynPathAtt (L3Out dynamic attachment) associated with a vmmDom is deleted. L3Out dynamic attachments in VMM are created when the floating SVI feature is implemented on the L3Outs. The port-groups named " " that get installed in VMware vCenter can cause bug CSCvu41160 to occur, where the Cisco APIC is unable to properly parse the port group names. Bug CSCvu41160 prevents the parsing issue, while this bug aims to prevent the " " port-group creation in the first place.	4.2(4i) and later
CSCvw50789	Configuring Logical Interface Profile in L3Out, " Forwarding IP Address" box may or may not show up.	4.2(4i) and later

Open Issues

Bug ID	Description	Exists in
CSCvw52392	When executing "show running-config" or "show running-config vpc" from the Cisco APIC while running a 4.2 release, the following errors can be seen: Error while processing mode: vpc Error while processing mode: configure Error: Incorrect Pod ID 3 for node 3201 in dn	4.2(4i) and later
CSCvw62861	A leaf switch reloads due to an out-of-memory condition after changing the contract scope to global.	4.2(4i) and later
CSCvw64745	An SNMP v3 trap is sent 2 minutes after a PSU is removed from the Cisco APIC.	4.2(4i) and later
CSCvw68416	vAPIC does not take the latest passphrase from the GUI when sending a certificate request.	4.2(4i) and later
CSCvw70570	A standby Cisco APIC doesn't upgrade during a Cisco APIC cluster upgrade and raises fault F1824.	4.2(4i) and later
CSCvw82431	The policy manager crashes consistently and eventually stops running. The Cisco APIC cluster becomes diverged.	4.2(4i) and later
CSCvw85990	In the L3Out creation wizard, the node profile and interface profile name changes to default if you change the node profile and interface profile names on page 2, then you return to page 1. The values of the other fields retain their configured values. For the interface profile name, this issue is only seen with an SVI vPC.	4.2(4i) and later
CSCvw87993	Some configuration is missing on a switch node due to the corresponding policies not being pushed to the switch from the Cisco APIC. This may manifest as a vast variety of symptoms depending on which particular policies weren't pushed.	4.2(4i) and later
CSCvw95671	The appliance element DME fails to subscribe to the policy from policymgr DME, which prevents the Cisco APIC from being able to configure the inband interface.	4.2(4i) and later
CSCvw99002	If a Cisco APIC is accidentally powered off while the initial setup script running, the initial setup will not start at next boot time. The previous admin password can be used to log in, and the Cisco APIC boots with the last running configuration.	4.2(4i) and later
CSCvw00513	The Cisco APIC fails to start the audtd service and the following message is displayed on the console when apic boots up: [FAILED] Failed to start Security Auditing Service.	4.2(4i) and later
CSCvw05302	+ ACI reports fault F1419. + The processes show process ID zero from the scheduler. + The processes are actually running when checked using systemctl with root access.	4.2(4i) and later
CSCvw33061	Traffic loss is observed from multiple endpoints deployed on two different vPC leaf switches.	4.2(4i) and later
CSCvw33277	The fault F3227 "ACI failed processing an already accepted configuration change" continuously gets raised.	4.2(4i) and later

Resolved Issues

Bug ID	Description	Exists in
CSCvw37981	Selecting an external IP address that is reachable from a single L3Out, the Cisco APIC shows the following error: " Not Supported: External address <External-IP> is reachable from GOLF interface" .	4.2(4i) and later
CSCvw69692	If a service graph gets attached to the inter-VRF contract after it was already attached to the intra-VRF contract, the pctag for the shadow EPG gets reprogrammed with a global value. The zoning-rule entries that matched the previous pctag as the source and EPG1 and EPG2 as the destination do not get reprogrammed and they remain in a stale status in the table. Traffic between EPG1 and EPG2 gets broken as the packets flowing from the PBR get classified with the new global pctag.	4.2(4i) and later
CSCvx54410	An endpoint move from a microsegmentation EPG to a base EPG causes the endpoint to disconnect for tag-based microsegmentation.	4.2(4i) and later
CSCvx74210	One Cisco APIC experiences high Java CPU utilization, reaching over 400%.	4.2(4i) and later
CSCvx90048	The load time of the operational tab of an interface under a node is significantly longer the first time it is viewed. After this initial load, going to other interfaces under that same switch is comparatively faster.	4.2(4i) and later
CSCvy30453	For a Cisco ACI fabric that is configured with fabricId=1, if APIC3 is replaced from scratch with an incorrect fabricId of "2," APIC3's DHCPd will set the nodeRole property to "0" (unsupported) for all dhcpClient managed objects. This will be propagated to the appliance director process for all of the Cisco APICs. The process then stops sending the AV/FNV update for any unknown switch types (switches that are not spine nor leaf switches). In this scenario, commissioning/decommissioning of the Cisco APICs will not be propagated to the switches, which causes new Cisco APICs to be blocked out of the fabric. Another symptom is that the "acidag fnvread" command's output has a value of "unknown" in the role column.	4.2(4i) and later
CSCwa58709	The GIPo address is only visible on APIC 1 when using the command " cat /data/data_admin/sam_exported.config" . The command output from the other APICs outputs do not show the GIPo address.	4.2(4i) and later
CSCwc66053	Preconfiguration validations for L3Outs that occur whenever a new configuration is pushed to the Cisco APIC might not get triggered.	4.2(4i) and later
CSCvu01818	There is a message in the Cisco APIC GUI saying that vleaf_lem has restarted several times and may not have recovered, and there are core files of the vleaf_lem process.	4.2(4i)

Resolved Issues

Click the bug ID to access the [Bug Search Tool](#) and see additional information about the bug. The " Fixed In" column of the table specifies whether the bug was resolved in the base release or a patch release.

Bug ID	Description	Fixed in
--------	-------------	----------

Resolved Issues

Bug ID	Description	Fixed in
CSCvv08969	After a Cisco APIC upgrade from a pre-4.0 release to a post-4.0 release, connectivity issues occur for devices behind Cisco Application Virtual Edge Switches running on VMWare.	4.2(4p)
CSCvu01818	There is a message in the Cisco APIC GUI saying that vleaf_elem has restarted several times and may not have recovered, and there are core files of the vleaf_elem process.	4.2(4k)
CSCvh52046	This is an enhancement to allow for text-based banners for the Cisco APIC GUI login screen.	4.2(4i)
CSCvh54578	For a client (browser or ssh client) that is using IPv6, the Cisco APIC aaaSessionLR audit log shows "0.0.0.0" or some bogus value.	4.2(4i)
CSCvq22658	Description fields are not available for resource pools (VLAN, VSAN, Mcast, VXLAN etc).	4.2(4i)
CSCvq88632	This is an enhancement request for allowing DVS MTU to be configured from a VMM domain policy and be independent of fabricMTU.	4.2(4i)
CSCvr73902	The GUI allows the target version to be changed in an existing upgrade group even when an upgrade is in progress.	4.2(4i)
CSCvr82224	A leaf switch port flaps without raising a warning.	4.2(4i)
CSCvr85515	When trying to track an AVE endpoint IP address, running the "show endpoint ip x.x.x.x" command in the Cisco APIC CLI to see the IP address and checking the IP address on the EP endpoint in the GUI shows incorrect or multiple vPC names.	4.2(4i)
CSCvr85821	The API query /api/class/compCtrlr.json?rsp-subtree=full? returns a malformed JSON file.	4.2(4i)
CSCvr86018	Some endpoints in the Cisco APIC GUI endpoint tracker have no state transitions, even when they have moved. When using icurl to get data on the same endpoints, state transitions are shown.	4.2(4i)
CSCvr94305	When a user logs into the Cisco APIC GUI and selects the SAL login domain, the authorization fails and the user gets thrown back to the initial login screen. The Cisco APIC NGINX logs show a failure to parse the AVPair value that is sent back by the SAML IDP. When checking the AVPair value returned by the Okta SAML IDP " <inRole value=" shell:domains=all//read-all" /> ", the value seems to have correct syntax.	4.2(4i)
CSCvr94614	There is a minor memory leak in svc_ifc_policydist when performing various tenant configuration removals and additions.	4.2(4i)
CSCvs03648	Cisco ACI UCSM integration does not work as expected. The Cisco APIC cannot discover a loose node UCS Fabric interconnect 6400 series when it is connected to the Cisco ACI fabric with a 100G interface.	4.2(4i)
CSCvs04899	When you run the 'show vpc map' command in the APIC CLI, it only prints the column headers, but none of the vPC information. If you go to the leaf switch CLI and run the 'show vpc extended' command, it will show the vPCs there.	4.2(4i)
CSCvs06139	Dynamic VLANs are programmed on interfaces that are not associated to the VLAN pool/AEP. This behaviour is seen when a UCS Fabric Interconnect blade switch has multiple uplinks to the fabric. Although some of those uplinks are mapped to a different AEP and the is EPG set for pre-provision, dynamic EPGs still are reported for that EPG.	4.2(4i)

Resolved Issues

Bug ID	Description	Fixed in
CSCvs12118	After removing and re-applying the IP SLA monitoring policy on a PBR policy, tracking does not work correctly.	4.2(4i)
CSCvs13980	Upgrading to the 4.2(1i) release, Layer 3 packet drops are no longer seen, but Layer 3 drop flows are still seen. However, Layer 3 drop flows do not give as much information.	4.2(4i)
CSCvs16565	An endpoint is unreachable from the leaf node because the static pervasive route (toward the remote bridge domain subnet) is missing.	4.2(4i)
CSCvs17431	A native VLAN for a VMM domain does not work if resolution immediacy is set to pre-provision. In this case, the untag policy is pushed to VMware vCenter and a port group is created (this is expected). However, the policy is programmed as trunk on switch side, which prevents the ESXi vmkernel and switch from communicating.	4.2(4i)
CSCvs21834	Randomly, the Cisco APIC GUI alert list shows an incorrect license expiry time. Sometimes it is correct, while at others times it is incorrect.	4.2(4i)
CSCvs22023	If pre-provision is not in place, there can be a complete outage to VMM integrated endpoints. If the host discovery is not successful, the policy will not be dynamically pushed to the leaf switches because virtual machines are attached.	4.2(4i)
CSCvs22599	RADIUS authentication cannot be configured from the Cisco APIC GUI.	4.2(4i)
CSCvs29281	An SNMP v3 trap is sent 2 minutes after a PSU is removed from the Cisco APIC, and a core file for the eventmgr is generated.	4.2(4i)
CSCvs29366	For a DVS with a controller, if another controller is created in that DVS using the same host name, the following fault gets generated: "hostname or IP address conflicts same controller creating controller with same name DVS".	4.2(4i)
CSCvs29375	The Cisco APIC GUI hangs on a loading screen when trying to configure interfaces policies from the following location: Fabric -> Inventory -> Pod -> Leaf switch -> Interface tab -> Configuration mode.	4.2(4i)
CSCvs30567	A Cisco ACI Virtual Edge host configured with Protective HA on the cluster might not come out of Quarantine mode.	4.2(4i)
CSCvs30837	In a Fabric Interconnect topology, a vPC may not be detected by the OpflexAgent on a HyperV host.	4.2(4i)
CSCvs31335	App techsupport collection does not work sometimes when triggered from the Cisco APIC GUI.	4.2(4i)
CSCvs32589	In Cisco ACI Virtual Edge, there are faults related to VMNICs. On the Cisco ACI Virtual Edge domain, there are faults related to the HpNic, such as "Fault F2843 reported for AVE Uplink portgroup marked as invalid".	4.2(4i)
CSCvs39652	Host subnets (/32) that are created under an SCVMM-integrated EPG get pushed as a virtual machine subnet under the virtual machine network in SCVMM. Virtual machine networks on SCVMM do not support /32 virtual machine subnets and fail to come up. Virtual machines that were previously associated to the virtual machine networks lose connectivity.	4.2(4i)

Resolved Issues

Bug ID	Description	Fixed in
CSCvs42229	A leaf switch crashes with the following reason: Reason: reset-triggered-due-to-ha-policy-of-reset Service:vleaf_elem hap reset	4.2(4i)
CSCvs42756	Configuration rollback fails with the following error: VRF Validation failed for VRF = : - ARP policy default in uni/tn-Prod/out-PROD_L3OUT/Inodep - L3OUT_PROD_LEAF103/lifp-PROD_L3OUT_INTERFACE/rsArplfPol is currently not supported on the interface	4.2(4i)
CSCvs46872	An admin read-only user can not see the System Settings tab in the Cisco APIC GUI.	4.2(4i)
CSCvs47757	The plnghandler process crashes on the Cisco APIC, which causes the cluster to enter a data layer partially diverged state.	4.2(4i)
CSCvs48552	When physical domains and external routed domains are attached to a security domain, these domains are mapped as associated tenants instead of associated objects under Admin > AAA > security management > Security domains.	4.2(4i)
CSCvs49411	Special characters are not allowed in the GUI for the SNMP community string, but you can still post a configuration that has special characters in the string by using the REST API.	4.2(4i)
CSCvs50986	When the PSU is powered off, a fault indicates that it is in a failed state.	4.2(4i)
CSCvs52100	In the Cisco APIC GUI, go to Admin->Firmware->Infrastructure->Nodes. Open an existing update group. While the group loads, the following text appears: "Click on + to add nodes to Node Upgrade Group". The text disappears after the nodes are loaded. The update groups cannot be edited (there is no "+" or "trash" symbol).	4.2(4i)
CSCvs53247	OpenStack supports more named IP protocols for service graph rules than are supported in the Cisco APIC OpenStack Plug-in.	4.2(4i)
CSCvs53468	A Cisco APIC-generated CSR contains the "unstructuredName" field, which does not work with some CA certificates.	4.2(4i)
CSCvs53480	When toggling between "Configured and Operational" under Tenants > Tenant_name > Contracts > Contract_name > Topology, contract lines are not visible when the toggle is on operational mode even though contracts are still operational.	4.2(4i)
CSCvs55246	Clicking on Fabric --> Access Policies --> Interfaces --> Leaf Interfaces --> Profiles --> <any_profile> --> "Show Usage" --> "Nodes using this policy" --> "Usage details of node" results in logging off the user and freezing the GUI screen.	4.2(4i)
CSCvs55753	A Cisco ACI leaf switch does not have MP-BGP route reflector peers in the output of "show bgp session vrf overlay-1". As a result, the switch is not able to install dynamic routes that are normally advertised by MP-BGP route reflectors. However, the spine switch route reflectors are configured in the affected leaf switch's pod, and pod policies have been correctly defined to deploy the route reflectors to the leaf switch. Additionally, the bgpPeer managed objects are missing from the leaf switch's local MIT.	4.2(4i)

Resolved Issues

Bug ID	Description	Fixed in
CSCvs57061	In a GOLF configuration, when an L3Out is deleted, the bridge domains stop getting advertised to the GOLF router even though another L3Out is still active.	4.2(4i)
CSCvs62693	The Name column of the the output of the " show zoning-rule" CLI command that is executed on a leaf switch running a 14.x release does not populate all of the expected contracts names. This issue makes it difficult to identify which rule ID is associated to which contract from the "show zoning-rule" command that is executed on a given leaf switch.	4.2(4i)
CSCvs66244	The CLI command " show interface x/x switchport" shows VLANs configured and allowed through a port. However, when going to the GUI under Fabric > Inventory > node_name > Interfaces > Physical Interfaces > Interface x/x > VLANs, the VLANs do not show.	4.2(4i)
CSCvs68074	When viewing leaf switch interface profiles in access policies, the list cannot be sorted by name or description.	4.2(4i)
CSCvs69370	The following fault is raised on a Cisco ACI fabric that has VMM/UCS integration: F609530 ([FSM:FAILED]: Send configuration update to External Device Manager Regarding the Dom Def(TASK:ifc:polycmgr:ExtdevRsDomDefConfigDomDef).	4.2(4i)
CSCvs69458	Immediately after a Cisco APIC cluster upgrade, all EPG SCVMM networks are marked for deletion. Networks not attached to virtual machines are deleted. Networks that are attached to virtual machines fail to get deleted, as they are being used and the following fault gets raised on the Cisco APIC cluster for each network: F1471EPG deployment failed due to Powershell call failed. Error Message: Cannot Delete VmNetwork	4.2(4i)
CSCvs71669	Time zone/local time on a Cisco APIC and switches differ when set to the EET timezone.	4.2(4i)
CSCvs74120	Selecting the RADIUS login domain from the GUI results in the following error: Error: 400 - unknown property value test, name realm, class aaaConsoleAuth [(Dn0)] Dn0=uni/userext/authrealm/consoleauth,	4.2(4i)
CSCvs76244	The tmpfs file system that is mounted on /data/log becomes 100% utilized.	4.2(4i)
CSCvs76272	The Ciphers drop-down list is not visible in a management access policy.	4.2(4i)
CSCvs76285	The SSL Cipher Configuration table is too small. Second row is cut off even when scrolling to the bottom of the table.	4.2(4i)
CSCvs81421	It is difficult to configure interface selectors in the GUI, because "interface policy group" window is too narrow.	4.2(4i)
CSCvs81429	It is difficult to configure interface selectors, because there is no search option available for the interface policy group window.	4.2(4i)
CSCvs81881	The Cisco APIC PSU voltage and amperage values are zero.	4.2(4i)
CSCvs81907	SNMP does not respond to GETs or sending traps on one or more Cisco APICs despite previously working properly.	4.2(4i)

Resolved Issues

Bug ID	Description	Fixed in
CSCvs82098	When navigating to System -> Controllers -> Cluster as Seen by Node for any Cisco APIC, the following error displays: The Request failed due to a server-side error.	4.2(4i)
CSCvs84984	Fault F3243 will be raised when changing the VMM configuration if the VMM domain has already been associated to the EPG, even though the change is not related to the current configuration.	4.2(4i)
CSCvs90607	The L3Out wizard shows the incorrect router_id from another VRF table.	4.2(4i)
CSCvs92041	Service Graph rendering fails if a service graph is attached to a unidirectional filter in a contract subject. For example: filter chain for provider to consumer: use service graph with PBR filter chain for consumer to provider: no service graph	4.2(4i)
CSCvs92682	OID "1.3.6.1.4.1.9.9.117.2.0.0.2" in v1 SNMP trap cefcPowerStatusChange by Cisco APIC is observed.	4.2(4i)
CSCvs94112	Cisco APIC apps do not have connectivity using an inband network.	4.2(4i)
CSCvs94915	If a FEX hardware model is N2K-C2348UPO-10GE, this FEX does not consume a FEX_48_10G license.	4.2(4i)
CSCvs96622	You might not be able to log in to a Cisco ACI leaf or spine switch.	4.2(4i)
CSCvs97474	TACACS external logging is not supported at the tenant level.	4.2(4i)
CSCvt00078	Hosts that require a DHCP-obtained address (Hyper-V, for example) from the Cisco APIC do not work. Checking the DHCP logs shows the DHCP discovers coming in frequently.	4.2(4i)
CSCvt00796	The policymgr DME process can crash because of an OOM issue, and there are many pcons.DelRef managed objects in the DB.	4.2(4i)
CSCvt01558	A Cisco APIC might report high memory utilization when polling through SNMP.	4.2(4i)
CSCvt03360	Zookeeper creates transactions files when the cluster is converging. During long periods of network unreachability, these files may get created at a more frequent rate, leading to space filling up.	4.2(4i)
CSCvt03664	The following symptoms are present: - The event manager generates a core - The APIC cluster is in a diverged state - The event manager is not running on APIC 1 and 2 - Service 3 shards are impacted	4.2(4i)
CSCvt04855	After upgrading the leaf switch, the "Allowed VLANs" list in the UCSM integration is no longer updated with the current list of VLANs deployed along the associated paths.	4.2(4i)

Resolved Issues

Bug ID	Description	Fixed in
CSCvt07565	The eventmgr database size may grow to be very large (up to 7GB). With that size, the Cisco APIC upgrade will take 1 hour for the Cisco APIC node that contains the eventmgr database. In rare cases, this could lead to a failed upgrade process, as it times out while working on the large database file of the specified controller.	4.2(4i)
CSCvt07825	After removing a configuration from Cisco ACI Multi-Site, the fabric nodes started reloading. The "show system reset-reason" command shows the following: Reason: reset-triggered-due-to-ha-policy-of-reset Service:policy_mgr hap reset	4.2(4i)
CSCvt08833	In a transit L3Out, after adding one new static route (a subnet of a summary route) on a border leaf switch, the OSPF summary route disappears from the route table of the border leaf switch because the route is deleted.	4.2(4i)
CSCvt10029	This is an enhancement to include the managed object class name and isPersisted attribute in the DME log line.	4.2(4i)
CSCvt13978	VPC protection created in prior to the 2.2(2e) release may not to recover the original virtual IP address after fabric ID recovery. Instead, some of vPC groups get a new vIP allocated, which does not get pushed to the leaf switch. The impact to the dataplane does not come until the leaf switch had a clean reboot/upgrade, because the rebooted leaf switch gets a new virtual IP that is not matched with a vPC peer. As a result, both sides bring down the virtual port channels, then the hosts behind the vPC become unreachable.	4.2(4i)
CSCvt16604	In a Cisco vAPIC environment in which the administrative state of Eth1/2 is down, fault F0106 is presented for Eth1/2 of the Cisco vAPIC nodes.	4.2(4i)
CSCvt19061	Updating the interface policy group breaks LACP if eLACP is enabled on a VMM domain. If eLACP was enabled on the domain, Creating, updating, or removing an interface policy group with the VMM AEP deletes the basic LACP that is used by the domain.	4.2(4i)
CSCvt20647	When shutting down a leaf switch interface that is connected a Cisco APIC node, even if the Cisco APIC interface shows as down, the status in the GUI is not changed. You can view the interface status by going to: Admin > Controllers > APIC > controller-APIC	4.2(4i)
CSCvt28235	Fault F1527 is raised when the /data/log directory is over 75% full. The /data/log directory contains a large amount of gzipped 21M svc_ifc_licensemgr.bin.warnplus.log files. The /data/log directory does not reach 80% or 90% full.	4.2(4i)
CSCvt28411	Fault F0135 is raised when using an AVE VMM domain, stating "Unsupported remote operation detected on EPG: detected in controller: controller-ip with name controller-name in datacenter dc-name in domain vmm-domain-name, error [VLAN is set to none for port group on vcenter but untagged access is not enabled for EPG]"	4.2(4i)
CSCvt29894	A switch entered into a bootloop and an upgrade is triggered multiple times if the maintenance policy is pushed with a REST API call that has the incorrect version.	4.2(4i)

Known Issues

Bug ID	Description	Fixed in
CSCvt31814	The VMM endpoint data plane verification function does not work well when a blade switch is in the middle. This might cause an unexpected DVS detach, or the VMM EPG VLAN might be removed on the leaf switch interface.	4.2(4i)
CSCvt37066	When migrating an EPG from one VRF table to a new VRF table, and the EPG keeps the contract relation with other EPGs in the original VRF table. Some bridge domain subnets in the original VRF table get leaked to the new VRF table due to the contract relation, even though the contract does not have the global scope and the bridge domain subnet is not configured as shared between VRF tables. The leaked static route is not deleted even if the contract relation is removed.	4.2(4i)
CSCvt37793	Packet loss is observed across the spine switches for unicast traffic.	4.2(4i)
CSCvt40498	For Cisco APIC, snmpwalk/get returns unexpected values for object cpmCPUMemoryUsed and cpmCPUMemoryUsed.	4.2(4i)
CSCvt41397	The CSSM receives an extremely high number of entitlement requests from a Cisco ACI fabric, in upwards of 25,000 over a 48-hour period.	4.2(4i)
CSCvt41841	A stale prefix entry remains that is associated with an old VRF table.	4.2(4i)
CSCvt42596	A VMmMgr crash maybe observed in a scaled environment with 20+ Floating L3Outs.	4.2(4i)
CSCvt48819	When using the Internet Explore browser, there is console error. This error will break some pages under Fabric -> Inventory -> [ANY POD] -> [ANY LEAF] / [ANY SPINE] -> Interfaces -> Physical, PC, VPC, FC, FC PC.	4.2(4i)
CSCvt59121	Legacy mode bridge domain is intended for a specific use case that requires higher bridge domain (VLAN) numbers per switch. As of Cisco APIC release 4.2, ~2000 normal bridge domains can be deployed on the same leaf switch, while 3500 legacy mode bridge domains can be deployed on the same leaf switch. However, as a trade-off for the bridge domain (VLAN) numbers, legacy mode bridge domains lose various Cisco ACI-specific capabilities, such as contracts, pervasive gateway (bridge domain subnet). This is an enhancement to update the name of Legacy Mode for a bridge domain to reflect its functionality and purpose in the Cisco APIC GUI. With this enhancement, Legacy Mode is presented as Scaled L2 Only Mode.	4.2(4i)
CSCvt63880	A Cisco vAPIC running release 4.2(3i) goes into a sh-4.2# prompt. Runing any command returns " Admin cookie not found".	4.2(4i)
CSCvt68786	A Cisco ACI Virtual Edge EPG is not programmed on a port channel toward the blade switch after it is deleted and recreated.	4.2(4i)
CSCvt72452	When using Cisco APIC release 4.2(2i), the UCSM integration icon is broken in the GUI.	4.2(4i)

Known Issues

Click the Bug ID to access the [Bug Search Tool](#) and see additional information about the bug. The "Exists In" column of the table specifies the 4.2(4) releases in which the known behavior exists. A bug might also exist in releases other than the 4.2(4) releases.

Known Issues

Bug ID	Description	Exists in
CSCvj26666	The "show run leaf spine <nodeId>" command might produce an error for scaled up configurations.	4.2(4i) and later
CSCvj90385	With a uniform distribution of EPs and traffic flows, a fabric module in slot 25 sometimes reports far less than 50% of the traffic compared to the traffic on fabric modules in non-FM25 slots.	4.2(4i) and later
CSCvq39764	When you click Restart for the Microsoft System Center Virtual Machine Manager (SCVMM) agent on a scaled-out setup, the service may stop. You can restart the agent by clicking Start.	4.2(4i) and later
CSCvq58953	One of the following symptoms occurs: <ul style="list-style-type: none"> ■ App installation/enable/disable takes a long time and does not complete. ■ Nomad leadership is lost. The output of the acidiag scheduler logs members command contains the following error: Error querying node status: Unexpected response code: 500 (rpc error: No cluster leader) 	4.2(4i) and later
CSCvr89603	The CRC and stomped CRC error values do not match when seen from the APIC CLI compared to the APIC GUI. This is expected behavior. The GUI values are from the history data, whereas the CLI values are from the current data.	4.2(4i) and later
CSCvs19322	Upgrading Cisco APIC from a 3.x release to a 4.x release causes Smart Licensing to lose its registration. Registering Smart Licensing again will clear the fault.	4.2(4i) and later
CSCvs77929	In the 4.x and later releases, if a firmware policy is created with different name than the maintenance policy, the firmware policy will be deleted and a new firmware policy gets created with the same name, which causes the upgrade process to fail.	4.2(4i) and later
N/A	Beginning in Cisco APIC release 4.1(1), the IP SLA monitor policy validates the IP SLA port value. Because of the validation, when TCP is configured as the IP SLA type, Cisco APIC no longer accepts an IP SLA port value of 0, which was allowed in previous releases. An IP SLA monitor policy from a previous release that has an IP SLA port value of 0 becomes invalid if the Cisco APIC is upgraded to release 4.1(1) or later. This results in a failure for the configuration import or snapshot rollback. The workaround is to configure a non-zero IP SLA port value before upgrading the Cisco APIC, and use the snapshot and configuration export that was taken after the IP SLA port change.	4.2(4i) and later
N/A	If you use the REST API to upgrade an app, you must create a new firmware.OSource to be able to download a new app image.	4.2(4i) and later

Compatibility Information

Bug ID	Description	Exists in
N/A	In a multipod configuration, before you make any changes to a spine switch, ensure that there is at least one operationally " up" external link that is participating in the multipod topology. Failure to do so could bring down the multipod connectivity. For more information about multipod, see the Cisco Application Centric Infrastructure Fundamentals document and the Cisco APIC Getting Started Guide.	4.2(4i) and later
N/A	With a non-english SCVMM 2012 R2 or SCVMM 2016 setup and where the virtual machine names are specified in non-english characters, if the host is removed and re-added to the host group, the GUID for all the virtual machines under that host changes. Therefore, if a user has created a micro segmentation endpoint group using " VM name" attribute specifying the GUID of respective virtual machine, then that micro segmentation endpoint group will not work if the host (hosting the virtual machines) is removed and re-added to the host group, as the GUID for all the virtual machines would have changed. This does not happen if the virtual name has name specified in all english characters.	4.2(4i) and later
N/A	A query of a configurable policy that does not have a subscription goes to the policy distributor. However, a query of a configurable policy that has a subscription goes to the policy manager. As a result, if the policy propagation from the policy distributor to the policy manager takes a prolonged amount of time, then in such cases the query with the subscription might not return the policy simply because it has not reached policy manager yet.	4.2(4i) and later
N/A	When there are silent hosts across sites, ARP glean messages might not be forwarded to remote sites if a leaf switch without -EX or a later designation in the product ID happens to be in the transit path and the VRF is deployed on that leaf switch, the switch does not forward the ARP glean packet back into the fabric to reach the remote site. This issue is specific to transit leaf switches without -EX or a later designation in the product ID and does not affect leaf switches that have -EX or a later designation in the product ID. This issue breaks the capability of discovering silent hosts.	4.2(4i) and later

Compatibility Information

Virtualization Compatibility Information

This section lists virtualization compatibility information for the Cisco APIC software.

- For a table that shows the supported virtualization products, see the [ACI Virtualization Compatibility Matrix](#).
- For information about Cisco APIC compatibility with Cisco UCS Director, see the appropriate [Cisco UCS Director Compatibility Matrix](#) document.
- This release supports the following additional virtualization products:

Product	Supported Release	Information Location
---------	-------------------	----------------------

Compatibility Information

Product	Supported Release	Information Location
Microsoft Hyper-V	<ul style="list-style-type: none"> ■ SCVMM 2019 RTM (Build 10.19.1013.0) or newer ■ SCVMM 2016 RTM (Build 4.0.1662.0) or newer ■ SCVMM 2012 R2 with Update Rollup 9 (Build 3.2.8145.0) or newer 	N/A
VMM Integration and VMware Distributed Virtual Switch (DVS)	6.5, 6.7, and 7.0 (beginning with 4.2(4o))	Cisco ACI Virtualization Guide, Release 4.2(x)

Hardware Compatibility Information

This release supports the following Cisco APIC servers:

Product ID	Description
APIC-L1	Cisco APIC with large CPU, hard drive, and memory configurations (more than 1000 edge ports)
APIC-L2	Cisco APIC with large CPU, hard drive, and memory configurations (more than 1000 edge ports)
APIC-L3	Cisco APIC with large CPU, hard drive, and memory configurations (more than 1200 edge ports)
APIC-M1	Cisco APIC with medium-size CPU, hard drive, and memory configurations (up to 1000 edge ports)
APIC-M2	Cisco APIC with medium-size CPU, hard drive, and memory configurations (up to 1000 edge ports)
APIC-M3	Cisco APIC with medium-size CPU, hard drive, and memory configurations (up to 1200 edge ports)

The following list includes general hardware compatibility information:

- For the supported hardware, see the [Cisco Nexus 9000 ACI-Mode Switches Release Notes, Release 14.2\(4\)](#).
- Contracts using matchDscp filters are only supported on switches with "EX" on the end of the switch name. For example, N9K-93108TC-EX.
- When the fabric node switch (spine or leaf) is out-of-fabric, the environmental sensor values, such as Current Temperature, Power Draw, and Power Consumption, might be reported as "N/A." A status might be reported as "Normal" even when the Current Temperature is "N/A."
- First generation switches (switches without -EX, -FX, -GX, or a later suffix in the product ID) do not support Contract filters with match type "IPv4" or "IPv6." Only match type "IP" is supported. Because of this, a contract will match both IPv4 and IPv6 traffic when the match type of "IP" is used.

The following table provides compatibility information for specific hardware:

Hardware	Information
----------	-------------

Hardware	Information
Cisco UCS M4-based Cisco APIC	The Cisco UCS M4-based Cisco APIC and previous versions support only the 10G interface. Connecting the Cisco APIC to the Cisco ACI fabric requires a same speed interface on the Cisco ACI leaf switch. You cannot connect the Cisco APIC directly to the Cisco N9332PQ ACI leaf switch, unless you use a 40G to 10G converter (part number CVR-QSFP-SFP10G), in which case the port on the Cisco N9332PQ switch auto-negotiates to 10G without requiring any manual configuration.
Cisco UCS M5-based Cisco APIC	The Cisco UCS M5-based Cisco APIC supports dual speed 10G and 25G interfaces. Connecting the Cisco APIC to the Cisco ACI fabric requires a same speed interface on the Cisco ACI leaf switch. You cannot connect the Cisco APIC directly to the Cisco N9332PQ ACI leaf switch, unless you use a 40G to 10G converter (part number CVR-QSFP-SFP10G), in which case the port on the Cisco N9332PQ switch auto-negotiates to 10G without requiring any manual configuration.
N2348UPQ	To connect the N2348UPQ to Cisco ACI leaf switches, the following options are available: <ul style="list-style-type: none"> ■ Directly connect the 40G FEX ports on the N2348UPQ to the 40G switch ports on the Cisco ACI leaf switches ■ Break out the 40G FEX ports on the N2348UPQ to 4x10G ports and connect to the 10G ports on all other Cisco ACI leaf switches. <p>Note: A fabric uplink port cannot be used as a FEX fabric port.</p>
N9K-C9348GC-FXP	This switch does not read SPROM information if the PSU is in a shut state. You might see an empty string in the Cisco APIC output.
N9K-C9364C-FX	Ports 49-64 do not support 1G SFPs with QSA.
N9K-C9508-FM-E	The Cisco N9K-C9508-FM-E2 and N9K-C9508-FM-E fabric modules in the mixed mode configuration are not supported on the same spine switch.
N9K-C9508-FM-E2	The Cisco N9K-C9508-FM-E2 and N9K-C9508-FM-E fabric modules in the mixed mode configuration are not supported on the same spine switch. The locator LED enable/disable feature is supported in the GUI and not supported in the Cisco ACI NX-OS switch CLI.
N9K-C9508-FM-E2	This fabric module must be physically removed before downgrading to releases earlier than Cisco APIC 3.0(1).
N9K-X9736C-FX	The locator LED enable/disable feature is supported in the GUI and not supported in the Cisco ACI NX-OS Switch CLI.
N9K-X9736C-FX	Ports 29 to 36 do not support 1G SFPs with QSA.

Adaptive Security Appliance (ASA) Compatibility Information

This section lists ASA compatibility information for the Cisco APIC software.

- This release supports Adaptive Security Appliance (ASA) device package version 1.2.5.5 or later.

Compatibility Information

- If you are running a Cisco Adaptive Security Virtual Appliance (ASA) version that is prior to version 9.3(2), you must configure SSL encryption as follows:

```
(config)# ssl encryption aes128-sha1
```

Miscellaneous Compatibility Information

This release supports the following products:

Product	Supported Release
Cisco NX-OS	14.2(4)
Cisco AVS	5.2(1)SV3(4.10) For more information about the supported AVS releases, see the AVS software compatibility information in the Cisco AVS Release Notes, Release 5.2(1)SV3(4.10) .
Cisco UCS Manager	2.2(1c) or later is required for the Cisco UCS Fabric Interconnect and other components, including the BIOS, CIMC, and the adapter.

Product	Supported Release
CIMC HUU ISO	<ul style="list-style-type: none"> ■ 4.2(3e) CIMC HUU ISO (recommended) for UCS C220/C240 M5 (APIC-L3/M3) ■ 4.2(3b) CIMC HUU ISO for UCS C220/C240 M5 (APIC-L3/M3) ■ 4.2(2a) CIMC HUU ISO for UCS C220/C240 M5 (APIC-L3/M3) ■ 4.1(3f) CIMC HUU ISO for UCS C220/C240 M5 (APIC-L3/M3) ■ 4.1(3d) CIMC HUU ISO for UCS C220/C240 M5 (APIC-L3/M3) ■ 4.1(3c) CIMC HUU ISO for UCS C220/C240 M5 (APIC-L3/M3) ■ 4.1(2k) CIMC HUU ISO (recommended) for UCS C220/C240 M4 (APIC-L2/M2) ■ 4.1(2g) CIMC HUU ISO for UCS C220/C240 M4 (APIC-L2/M2) ■ 4.1(2b) CIMC HUU ISO for UCS C220/C240 M4 (APIC-L2/M2) ■ 4.1(1g) CIMC HUU ISO for UCS C220/C240 M4 (APIC-L2/M2) and M5 (APIC-L3/M3) ■ 4.1(1f) CIMC HUU ISO for UCS C220 M4 (APIC-L2/M2) (deferred release) ■ 4.1(1d) CIMC HUU ISO for UCS C220 M5 (APIC-L3/M3) ■ 4.1(1c) CIMC HUU ISO for UCS C220 M4 (APIC-L2/M2) ■ 4.0(4e) CIMC HUU ISO for UCS C220 M5 (APIC-L3/M3) ■ 4.0(2g) CIMC HUU ISO for UCS C220/C240 M4 and M5 (APIC-L2/M2 and APIC-L3/M3) ■ 4.0(1a) CIMC HUU ISO for UCS C220 M5 (APIC-L3/M3) ■ 3.0(4l) CIMC HUU ISO (recommended) for UCS C220/C240 M3 (APIC-L1/M1) ■ 3.0(4d) CIMC HUU ISO for UCS C220/C240 M3 and M4 (APIC-L1/M1 and APIC-L2/M2) ■ 3.0(3f) CIMC HUU ISO for UCS C220/C240 M4 (APIC-L2/M2) ■ 3.0(3e) CIMC HUU ISO for UCS C220/C240 M3 (APIC-L1/M1) ■ 2.0(13i) CIMC HUU ISO ■ 2.0(9c) CIMC HUU ISO ■ 2.0(3i) CIMC HUU ISO

Related Content

Product	Supported Release
Network Insights Base, Network Insights Advisor, and Network Insights for Resources	For the release information, documentation, and download links, see the Cisco Network Insights for Data Center page. For the supported releases, see the Cisco Day-2 Operations Apps Support Matrix .

- This release supports the partner packages specified in the [L4-L7 Compatibility List Solution Overview](#) document.
- A known issue exists with the Safari browser and unsigned certificates, which applies when connecting to the Cisco APIC GUI. For more information, see the [Cisco APIC Getting Started Guide, Release 4.2\(x\)](#).
- For compatibility with OpenStack and Kubernetes distributions, see the [Cisco Application Policy Infrastructure Controller Container Plugins Release 4.2\(3\), Release Notes](#).
- For compatibility with Day-2 Operations apps, see the [Cisco Day-2 Operations Apps Support Matrix](#).
- Cisco Nexus Dashboard Insights creates a user in Cisco APIC called cisco_SN_NI. This user is used when Nexus Dashboard Insights needs to make any changes or query any information from the Cisco APIC. In the Cisco APIC, navigate to the Audit Logs tab of the System > History page. The cisco_SN_NI user is displayed in the User column.

Related Content

See the [Cisco Application Policy Infrastructure Controller \(APIC\)](#) page for the documentation.

You can watch videos that demonstrate how to perform specific tasks in the Cisco APIC on the [Cisco ACI YouTube channel](#).

Temporary licenses with an expiry date are available for evaluation and lab use purposes. They are strictly not allowed to be used in production. Use a permanent or subscription license that has been purchased through Cisco for production purposes. For more information, go to [Cisco Data Center Networking Software Subscriptions](#).

The documentation includes installation, upgrade, configuration, programming, and troubleshooting guides, technical references, release notes, and knowledge base (KB) articles, as well as other documentation. KB articles provide information about a specific use case or a specific topic.

By using the "Choose a topic" and "Choose a document type" fields of the APIC documentation website, you can narrow down the displayed documentation list to make it easier to find the desired document.

The following table provides links to the release notes, verified scalability documentation, and new documentation:

Document	Description
Cisco ACI Virtual Edge Release Notes, Release 2.2(4a)	The release notes for Cisco ACI Virtual Edge.
Cisco ACI Virtual Pod Release Notes, Release 4.2(4)	The release notes for Cisco ACI Virtual Pod.
Cisco Application Centric Infrastructure Simulator Appliance Release Notes, Release 4.2(4)	The release notes for the Cisco ACI Simulator Appliance.

Cisco AVS Release Notes, Release 5.2(1)SV3(4.20)	The release notes for Cisco AVS.
Cisco Nexus 9000 ACI-Mode Switches Release Notes, Release 14.2(4)	The release notes for Cisco NX-OS for Cisco Nexus 9000 Series ACI-Mode Switches.
<i>Verified Scalability Guide for Cisco APIC, Release 4.2(4), Multi-Site, Release 2.2(4), and Cisco Nexus 9000 Series ACI-Mode Switches, Release 14.2(4)</i>	This guide contains the maximum verified scalability limits for Cisco Application Centric Infrastructure (ACI) parameters for Cisco APIC, Cisco ACI Multi-Site, and Cisco Nexus 9000 Series ACI-Mode Switches. Note: This document will be available in the near future.

Documentation Feedback

To provide technical feedback on this document, or to report an error or omission, send your comments to apic-docfeedback@cisco.com. We appreciate your feedback.

Legal Information

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2020-2022 Cisco Systems, Inc. All rights reserved.