

# Cisco MDS 9000 Series Release Notes

Release 9.4(2a)

This document describes the features, issues, and deployment guidelines for the Cisco MDS NX-OS software for use on the Cisco MDS 9000 Series Switches.

**Note:**

- The documentation set for this product strives to use bias-free language. For this documentation set, bias-free is defined as language that does not imply discrimination based on age, disability, gender, racial identity, ethnic identity, sexual orientation, socioeconomic status, and intersectionality. Exceptions may be present in the documentation due to language that is hardcoded in the user interfaces of the product software, language used based on RFP documentation, or language that is used by a referenced third-party product.
- Release notes are updated on an as needed basis with new information on restrictions and issues. See the following website for the most recent version of the [Cisco MDS 9000 Series Release Notes](#).

Date	Description
August 29, 2025	Upgrading and Downgrading Cisco MDS NX-OS Software Image sections are moved to Cisco MDS 9000 NX-OS Software Upgrade and Downgrade Guide, Release 9.x. Added <a href="#">CSCwm79623</a> , <a href="#">CSCwo41374</a> to the Open Issues section.
August 21, 2025	Added <a href="#">CSCwn10124</a> to the Open Issues section.
August 18, 2025	Added <a href="#">CSCwn37613</a> , <a href="#">CSCwn94165</a> to the Open Issues section.
March 25, 2025	Added <a href="#">CSCwo03706</a> to the Open Issues section.
March 03, 2025	Added <a href="#">CSCwn58100</a> to the Open Issues section.
August 12, 2024	Added <a href="#">CSCwk33644</a> to the Open Issues section.
July 26,2024	Initial Release

## Introduction

The Cisco MDS 9000 Series of Multilayer Directors and Fabric Switches provide best-in-class high availability, scalability, security, and management that enables to deploy high-performance storage area networks. Layering a rich set of intelligent features onto a high-performance switch fabric, the Cisco MDS 9000 Series has the flexibility to fit small deployments and to address the stringent requirements of large data center storage environments: high availability, security, scalability, sustainability, ease of management, and seamless integration of new technologies.

### About Software Images

The Cisco MDS NX-OS operating system is shipped with the Cisco MDS 9000 Series Switches. The Cisco MDS NX-OS software consists of two images: the kickstart image and the system image. These images can be upgraded or downgraded to different versions. The versions of both images must match for the system to boot.

Each model of the Cisco MDS switch has unique kickstart and system images. For more information on the image names for each Cisco MDS switch, see the [Cisco MDS 9000 NX-OS Software Upgrade and Downgrade Guide, Release 9.x](#).

---

To download the new Cisco MDS 9000 Series Switches NX-OS software, go to the Storage Networking Software download website at <https://software.cisco.com/download/find/MDS>.

## Upgrade and Downgrade Paths

Cisco MDS NX-OS Release 9.4(2a) supports non-disruptive upgrade and downgrade to other Cisco MDS NX-OS Releases. For upgrade and downgrade paths, and guidelines that are recommended for upgrading or downgrading Cisco MDS NX-OS software images, see [Cisco MDS 9000 NX-OS Software Upgrade and Downgrade Guide, Release 9.x](#).

**Note:** If you have the SAN analytics feature enabled, ensure that you disable the SAN analytics feature using the **no feature analytics** command before upgrading. For detailed instructions, see *Preventing SAN Analytics Corruption during ISSU* section in the [Cisco MDS 9000 NX-OS Software Upgrade and Downgrade Guide, Release 9.x](#).

## About Firmware Images

Cisco MDS 9000 Series Switches contain a number of hardware components with updatable firmware. The Transceiver Firmware bundle contains updates for various port transceivers. The EPLD Firmware bundle contains updates for programmable logic devices in the system.

These updates can be disruptive and so are not part of the Cisco NX-OS software image. They are released with every Cisco NX-OS release but do not frequently contain changes. Refer to the specific Release Notes for any recommended fixes.

For more information on Transceiver Firmware, see the *Cisco MDS 9000 Series Transceiver Firmware Release Notes, Release 9.4(2a)*.

For more information on EPLD bundles, see the *Cisco MDS 9000 Series EPLD Release Notes, Release 9.4(2a)*.

## Choosing Between Cisco MDS NX-OS Open Systems Releases

Cisco uses release numbering to indicate the maturity of a Cisco MDS NX-OS release train. Cisco MDS NX-OS major versions are incremented when significant software features or hardware support are added. Because of the focus on new features and hardware, all bugs may not yet have been fixed. After an initial release, minor version numbers of the release train are incremented as bugs are resolved, and minor feature enhancements and security patches are integrated. This provides increased stability to the new features and updated security.

For Cisco recommended MDS NX-OS releases for each type of hardware, see [Recommended Releases for Cisco MDS 9000 Series Switches](#) document.

## Components Supported

For information on supported software and hardware components, see [Cisco MDS 9000 Series Compatibility Matrix](#).

## IBM FICON Qualification Status

Cisco MDS NX-OS Release 9.4(2a) is not IBM FICON qualified.

## Cisco TrustSec FC Link Encryption

For more information about which set of interfaces on each module support FC-SP, see the [Configuring Cisco TrustSec Fibre Channel Link Encryption](#) chapter of the *Cisco MDS 9000 Series Security Configuration Guide, Release 9.x*.

---

## New Hardware Features

There are no new hardware features in Cisco MDS NX-OS Release 9.4(2a).

## New and Enhanced Software Features

There are no new software features in Cisco MDS NX-OS Release 9.4(2a).

## Unsupported Features

### MD5 Hash in FCoE

From Cisco MDS NX-OS Release 9.4(2) and later releases, do not support the MD5 hash algorithm in Fibre Channel Security Protocol (FSCP) as it is no longer considered secure. The default hash algorithm has been changed to SHA1.

### 10G and 40G FCoE linecards

From Cisco MDS NX-OS Release 9.4(2) and later releases, do not support the following FCoE linecards:

- DS-X9848-480K9 – 48-port 10-Gbps FCoE Switching Module
- DS-X9824-960K9 – MDS 9700 24-port 40-Gbps FCoE Switching Module

For more information, see the [Cisco MDS 9700 Series Multilayer Directors Hardware Installation Guide](#).

### SDV feature

Cisco MDS NX-OS Release 9.3(2) and later releases do not support Cisco SAN device virtualization (SDV).

### Traditional and Smart Licensing Version 1.0 Licenses

Cisco MDS NX-OS Release 9.2(2) and later releases does not support installation of Product Authorization Key (PAK) or Smart Licensing version 1.0 licenses. Licenses are now managed through Smart License using Policy (SLP).

For more information such as how to migrate licenses, see Smart Licensing Using Policy chapter in [Cisco MDS 9000 Series Licensing Guide, Release 9.x](#).

### Python 2

Support for Python 2 is deprecated from Cisco MDS NX-OS Release 9.2(2). Python 3 remains supported instead. Python 2 scripts should be checked for compatibility with Python 3 to ensure they continue to function as expected.

For more information, see the Python API chapter in the [Cisco MDS 9000 Series Programmability Guide, Release 9.x](#).

### Zoning Features

LUN zoning, read-only zones, and broadcast zones are no longer supported.

If these features are already configured, completely remove all the configurations that include these features before attempting to boot any module. In addition, you cannot configure these features after you bring up any module.

### XRC Acceleration License

From Cisco MDS NX-OS Release 8.1(1a), the Cisco Extended Remote Copy (XRC) acceleration license is obsoleted on all Cisco MDS 9000 Series Switches due to improvements in z/OS® Global Mirror feature

---

(formally known as XRC). Cisco MDS continues to support z/OS® Global Mirror (formally known as XRC) over all supported FICON cascade topologies (FC, FC over DWDM, and FCIP).

### **Virtual Router Redundancy Protocol (VRRP)**

From Cisco MDS NX-OS Release 8.3(1) and later, the VRRP feature is not supported on Cisco MDS 9000 Series Switches.

### **Data Encryption Standard (DES) for SNMP**

From Cisco MDS NX-OS Release 8.5(1), AES-128 is the default encryption mechanism for SNMPv3. DES encryption for SNMP is supported only for DES users who upgrade from previous releases to Cisco MDS NX-OS Release 8.5(1). Ensure that you delete all the SNMPv3 users configured with DES encryption before upgrading to Cisco MDS NX-OS Release 8.5(1) and later releases. Any downgrades from Cisco MDS NX-OS Release 8.5(1) will be restricted if any of the SNMPv3 users have DES encryption configured as the privacy protocol. All such users will either need to be deleted or reconfigured to use no privacy protocol or AES128 encryption before downgrading.

For more information, see [Cisco MDS 9000 Series System Management Configuration Guide, Release 9.x](#).

### **Fabric Performance Impact Notifications (FPIN)**

- FPIN is not supported on switches that are operating in NPV mode.
- FPIN notifications for oversubscription-based congestion are not supported.

### **FCWA, XRC, DMM, SME**

FCWA, XRC, DMM, and SME features are not supported from Release 8.x.

### **SAN Extension Tuner**

SAN Extension Tuner (SET) is not supported on Cisco MDS 9220i switches in Cisco MDS NX-OS Release 8.5(1) or later.

### **Fibre Channel Read Diagnostic Parameters**

Fibre Channel RDP querying is not supported on NP, Port Channel, or FCoE links.

### **Slow Drain Detection and Congestion Isolation**

ER\_RDY is not supported on FC interfaces running at 10 Gbps.

### **FCIP Support**

- In Cisco MDS NX-OS Release 9.2(2) and later releases, simultaneous use of IVR and FCIP Write Acceleration features is not supported on FCIP tunnels configured on Cisco MDS 9700 Director switches.
- On Cisco MDS 24/10 Port SAN Extension Module, configuring multiple FSPF equal cost paths (ECMP) port channels with FCIP members in the same VSAN is not a valid configuration. If this is configured, then the traffic flows through only one of the port channels.

### **iSCSI Support**

iSCSI is not supported on Cisco MDS 9700 Directors with Cisco MDS 24/10 port SAN Extension Modules and Cisco MDS 9220i multiservice fabric switch.

## Resolved Issues

### Severity 2 (Severe) Issues

Bug ID	Headline	Known Impacted Releases
<a href="#">CSCwi81679</a>	analytics_client crash when trying to do bulk disable	9.4(2), 9.4(1a), 9.4(1) 9.3(2a), 9.3(2), 9.3(1)
<a href="#">CSCwi18866</a>	Internal buffers leaked by TACACS service even though TACACS service is not enabled	9.4(1) 9.3(2a)
<a href="#">CSCwj97007</a>	Cisco NX-OS Software CLI Command Injection Vulnerability	9.4(2), 9.4(1a), 9.4(1) 9.3(2a), 9.3(2), 9.3(1) 9.2(2), 9.2(1a), 9.2(1) 8.5(1) 8.4(2f), 8.4(2e), 8.4(2d), 8.4(2c), 8.4(2b), 8.4(2a), 8.4(2), 8.4(1a), 8.4(1) 8.3(2), 8.3(1) 8.2(2), 8.2(1), 8.1(1b), 8.1(1a), 8.1(1) 7.3(1)DY(1), 7.3(1)D1(1), 7.3(0)DY(1), 7.3(0)D1(1) 6.2(9c), 6.2(9b), 6.2(9a), 6.2(9), 6.2(7), 6.2(5b), 6.2(5a), 6.2(5), 6.2(33), 6.2(31), 6.2(3), 6.2(29), 6.2(27), 6.2(25), 6.2(23), 6.2(21), 6.2(19), 6.2(17), 6.2(15), 6.2(13b), 6.2(13a), 6.2(13), 6.2(11e), 6.2(11d), 6.2(11c), 6.2(11b), 6.2(11), 6.2(1)
<a href="#">CSCwk14579</a>	TACACS authentication fails after ISSU to Cisco MDS NX-OS 9.4(2)	9.4(2)
<a href="#">CSCwk62258</a>	Evaluation of mds-infra for OpenSSH regreSSHion vulnerability	9.4(2)
<a href="#">CSCwk65461</a>	ISSD compatibility check failure from NX-OS 9.4(2)	9.4(2)
<a href="#">CSCwk67211</a>	FDMI service crash while executing 'show fdmi database detail' command	9.4(2)

### Severity 4 (Minor) Issues

Bug ID	Headline	Known Impacted Releases
<a href="#">CSCwk76913</a>	9250i/9148S/9396S switches missing `show ssh version` command.	9.4(2)

## Open Issues

### Severity 1 (Catastrophic) Issues

Bug ID	Headline	Known Impacted Releases
<a href="#">CSCwo03706</a>	An FC interface will not come up / switch to soft zoning	9.4(2a), 9.4(2), 9.4(1a), 9.4(1)  9.3(2a), 9.3(2), 9.3(1)  9.2(2), 9.2(1a), 9.2(1)  8.5(1)

### Severity 2 (Severe) Issues

Bug ID	Headline	Known Impacted Releases
<a href="#">CSCwm79623</a>	'pixmc' service crash when multiple interfaces flap in a port-channel	9.4(3b), 9.4(3a), 9.4(3), 9.4(2a)
<a href="#">CSCwn10124</a>	Device unable to log into fabric due to maximum FLOGIs already on the port	9.4(2a), 9.4(2), 9.4(1a), 9.4(1) 9.3(1) 9.2(1) 8.5(1) 8.4(1) 8.3(1) 8.2(1) 8.1(1)
<a href="#">CSCwn58100</a>	Hosts losing paths due to FSPF instability due to LSRs reaching Max Age after upgrading to 9.4(2a)	9.4(3), 9.4(2a), 9.4(2), 9.4(1a), 9.4(1)
<a href="#">CSCwn94165</a>	Linecard 'acltcam' service crashes with signal 6	9.4(2a), 9.4(2), 9.4(1a), 9.4(1)
<a href="#">CSCwo41374</a>	Switch hangs after CPU stall, control plane and management interface not responding	9.4(3b), 9.4(3a), 9.4(3), 9.4(2a)

### Severity 3 (Moderate) Issues

Bug ID	Headline	Known Impacted Releases
<a href="#">CSCwn37613</a>	ISSU error 0x40930015 'BIOS/loader/bootrom of above module may be in corrupted state'	9.4(2a)
<a href="#">CSCwi20078</a>	fwd-flow validation CC fails in 9132T after ISSU from NX-OS 8.4(2f)	9.4(2a), 9.4(2), 9.4(1a), 9.4(1) 9.3(2a), 9.3(2), 9.3(1)
<a href="#">CSCwj80322</a>	FCSP service crash after reload or enabling the FCSP feature	9.4(2a), 9.4(2), 9.4(1a), 9.4(1) 9.3(2a), 9.3(2), 9.3(1)
<a href="#">CSCwk85712</a>	Vport entries not deleted after FC LOGO	9.4(2a)

## Severity 4 (Minor) Issues

Bug ID	Headline	Known Impacted Releases
<a href="#">CSCvf08416</a>	'show tech details' triggers 'pam_ftp(ftp:auth): conversation failed-ftp' syslogs	9.4(2a), 9.4(2), 9.4(1a) 8.5(1) 8.4(1), 8.4(2), 8.4(2a), 8.4(2b), 8.4(2c), 8.4(2d). 8.4(2e) 8.3(2), 8.3(1) 8.2(2), 8.2(1)
<a href="#">CSCvj93031</a>	IPv6 source address not displayed in log in failure logs	9.4(2a), 9.4(2), 9.4(1a) 8.5(1) 8.4(1), 8.4(2), 8.4(2a), 8.4(2b), 8.4(2c), 8.4(2d), 8.4(2e) 8.3(2), 8.3(1)
<a href="#">CSCvs23106</a>	SCSI target discovery service running even after removal of last DS-X9334-K9 module from switch	9.4(2a), 9.4(2), 9.4(1a) 8.5(1) 8.4(1), 8.4(1a), 8.4(2), 8.4(2a), 8.4(2b), 8.4(2c), 8.4(2d), 8.4(2e) 8.3(1), 8.3(2) 8.2(1), 8.2(2) 8.1(1), 8.1(1a), 8.1(1b)
<a href="#">CSCvt15761</a>	Nondisruptive reload causes reinitialization of error disabled ports on other linecards	9.4(2a), 9.4(2), 9.4(1a) 8.5(1) 8.4(2), 8.4(2a), 8.4(2b), 8.4(2c), 8.4(2d), 8.4(2e)
<a href="#">CSCvw00538</a>	Remove misleading ficon stat 'merge failed' message in non-FICON VSAN	9.4(2a), 9.4(2), 9.4(1a) 8.5(1) 8.4(2b), 8.4(2c), 8.4(2d), 8.4(2e)
<a href="#">CSCwc61263</a>	Linecard fails to boot up with '%PORT-5-MODULE_BRINGUP_NOT_ALLOWED' error	9.4(2a), 9.4(2), 9.4(1a) 8.4(2e), 8.4(2c) 8.1(1)
<a href="#">CSCwk33644</a>	Power Supply status of "Powered-dn" causes Amber System Status LED	9.4(2a), 9.4(2) 9.4(1a), 9.4(1)



## Severity 6 (Enhancement) Issues

Bug ID	Headline	Known Impacted Releases
<a href="#">CSCvo22835</a>	All flows are briefly suspended while moving an IOA flow between 2 clusters	9.4(2a), 9.4(2), 9.4(1a) 8.5(1) 8.4(1), 8.4(2), 8.4(2a), 8.4(2b), 8.4(2c), 8.4(2d), 8.4(2e) 8.3(2), 8.3(1) 8.2(2), 8.2(1) 8.1(1b), 8.1(1a), 8.1(1)
<a href="#">CSCvp70681</a>	Streaming to telemetry receiver stops, receiver stays in "idle" state	9.4(2a), 9.4(2), 9.4(1a) 8.5(1) 8.4(1), 8.4(2), 8.4(2a), 8.4(2b), 8.4(2c), 8.4(2d), 8.4(2e)
<a href="#">CSCvw77444</a>	Need to automatically sync bootflash:/scripts directory between active and standby sups	9.4(2a), 9.4(2), 9.4(1a), 9.4(1) 8.1(1a)
<a href="#">CSCvx37657</a>	Need to save nonvolatile logs about BIOS programming errors	9.4(2a), 9.4(2), 9.4(1a) 8.5(1) 8.4(2c), 8.4(2d), 8.4(2e) 8.3(2)
<a href="#">CSCwb13413</a>	A fabric module with a faulty link to a linecard is not powered down	9.4(2a), 9.4(2), 9.4(1a) 8.4(1)
<a href="#">CSCwe86920</a>	Add option to 'show tech-support' to exclude and include subcommands	9.4(2a), 9.4(2), 9.4(1a), 9.4(1) 8.1(1)
<a href="#">CSCwf48167</a>	Span tx is not working in NPV mode on all platforms, rx is working	9.4(2a), 9.4(2), 9.4(1a), 9.4(1)
<a href="#">CSCwf66251</a>	Need a syslog warning when number of zone members exceeds maximum supported	9.4(2a), 9.4(2), 9.4(1a) 8.4(2d)

## Related Documentation

The documentation set for the Cisco MDS 9000 Series includes the documents that are listed in this section. To find a document online, access the following URL:

[http://www.cisco.com/en/US/products/ps5989/tsd\\_products\\_support\\_series\\_home.html](http://www.cisco.com/en/US/products/ps5989/tsd_products_support_series_home.html)

---

## Cisco Nexus Dashboard Fabric Controller (Formerly DCNM)

[https://www.cisco.com/en/US/products/ps9369/tsd\\_products\\_support\\_series\\_home.html](https://www.cisco.com/en/US/products/ps9369/tsd_products_support_series_home.html)

### Release Notes

<https://www.cisco.com/c/en/us/support/storage-networking/mds-9000-nx-os-san-os-software/products-release-notes-list.html>

### Licensing Information

<https://www.cisco.com/c/en/us/td/docs/dcn/mds9000/sw/9x/configuration/licensing/cisco-mds-9000-nx-os-licensing-guide-9x.html>

### Regulatory Compliance and Safety Information

<https://www.cisco.com/c/en/us/td/docs/switches/datacenter/mds9000/hw/regulatory/compliance/RCSI.html>

### Compatibility Information

<https://www.cisco.com/c/en/us/support/storage-networking/mds-9000-nx-os-san-os-software/products-device-support-tables-list.html>

### Installation and Upgrade

<https://www.cisco.com/c/en/us/support/storage-networking/mds-9000-nx-os-san-os-software/products-installation-guides-list.html>

### Configuration Guides

<https://www.cisco.com/c/en/us/support/storage-networking/mds-9000-nx-os-san-os-software/products-installation-and-configuration-guides-list.html>

### CLI

<https://www.cisco.com/c/en/us/support/storage-networking/mds-9000-nx-os-san-os-software/products-command-reference-list.html>

### Troubleshooting and Reference

<https://www.cisco.com/c/en/us/support/storage-networking/mds-9000-nx-os-san-os-software/tsd-products-support-troubleshoot-and-alerts.html>

### Statement of Volatility

<https://www.cisco.com/c/en/us/support/storage-networking/mds-9000-nx-os-san-os-software/tsd-products-support-troubleshoot-and-alerts.html>

### Documentation Roadmap

[https://www.cisco.com/c/en/us/td/docs/storage/san\\_switches/mds9000/roadmaps/rel90.html](https://www.cisco.com/c/en/us/td/docs/storage/san_switches/mds9000/roadmaps/rel90.html)

## Documentation Feedback

To provide technical feedback on this document, or to report an error or omission, send your comments to [mds-docfeedback@cisco.com](mailto:mds-docfeedback@cisco.com). We appreciate your feedback.

---

## Legal Information

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL:

<https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2024 Cisco Systems, Inc. All rights reserved.