



Cisco Nexus 9000 Series NX-OS Release Notes, Release 10.1(1)

Introduction

This document describes the features, issues, and exceptions of Cisco NX-OS Release 10.1(1) software for use on Cisco Nexus 9000 Series switches.

Note: The documentation set for this product strives to use bias-free language. For the purposes of this documentation set, bias-free is defined as language that does not imply discrimination based on age, disability, gender, racial identity, ethnic identity, sexual orientation, socioeconomic status, and intersectionality. Exceptions may be present in the documentation due to language that is hardcoded in the user interfaces of the product software, language used based on RFP documentation, or language that is used by a referenced third-party product.

The following table lists the changes to this document.

Date	Description
April 25, 2024	Added CSCwh50989 and CSCwe53655 to Open Issues.
July 18, 2023	Added flex link to the Enhanced Features section.
May 05, 2023	Added PTP in Unsupported Features on N9K-C92348GC section.
April 09, 2023	Added caveat CSCwe67205 in Open Issues table.
January 25, 2023	Updated the Unsupported Features on N9K-C92348GC section.
February 16, 2021	Cisco NX-OS Release 10.1(1) became available.

New and Enhanced Software Features

New Features	
Feature	Description
64-bit NX-OS Image	<p>Introduced a new 64-bit image of the Cisco NX-OS software for Cisco Nexus C9316D-GX, C93600CD-GX, C9364C-GX, Cisco Nexus N9K-X9716D-GX I/O modules, and Cisco Nexus C9504-FM-G, C9508-FM-G fabric modules.</p> <p>For more information see, <i>Cisco Nexus 9000 Series NX-OS Software Upgrade and Downgrade Guide, Release 10.1(x)</i>.</p>
ITD Subsecond Convergence	<p>Introduced the ability to add nodes from the same device group to a cluster.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS Intelligent Traffic Director Configuration Guide, Release 10.1(x)</i>.</p>
Network Operations Interface (gNOI)	<p>gRPC Network Operations Interface (gNOI) defines a set of gRPC-based micro-services for executing operational commands on network devices.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS Programmability Guide, Release 10.1(x)</i>.</p>

The enhanced features listed below are existing features introduced in earlier releases but enhanced to support new platforms in Cisco NX-OS Release 10.1(1).

Enhanced Features	
Feature	Description
Telemetry	<p>Introduced the following:</p> <ul style="list-style-type: none"> • trustpoint keyword for the Certificate Trustpoint Certificate • Commands for Telemetry transport sessions • A new sensor path query-condition to support ephemeral event • Support for destination host name • Support for Node ID • gRPC asynchronous mode feature • New FT event types - receiveWindowZero, ipDf, tos, ttlMatchValue • FT Analytics - Interface-level filtering <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS Programmability Guide, Release 10.1(x)</i>.</p>
Guest Shell 3.0	<p>Added support for Guest Shell 3.0 based on CentOS 8 and Python 3.6. Upgraded the version of the docker on the switch.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS Programmability Guide, Release 10.1(x)</i>.</p>
Linux Kernel Upgrade	<p>Introduced a long lived kernel version - 4.19.x. Also introduced Yocto 2.6 distribution for third-party binaries and libraries. This improves overall third-party software and kernel quality and contains fixes for a lot of security vulnerabilities.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS Programmability Guide, Release 10.1(x)</i>.</p>
Client Based Certificate for gNMI	<p>Enhanced support for gNMI client certificate authentication. This enhancement provides password-less authentication for different clients.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS Programmability Guide, Release 10.1(x)</i>.</p>
Port-group Support for GX Switches	<p>For N9K-C93600CD-GX: For ports 1-24, every four ports (1-4, 5-8, 9-12, and so on, referred to as a "port-group") operate at the same speed. All the ports in a port-group operate in 10G, or 40G or 100G. Mixed speed is not supported within the same port-group. With QSA, all ports in a port-group can operate at 10G speed.</p> <p>For N9K-C9364C-GX: For ports 1-64, every four ports (1-4, 5-8, 9-12, and so on, referred to as a "port-group") operate at the same speed. Limitations for this port-group speed mismatch for N9K-C93600CD-GX are applicable for N9K-C9364C-GX too.</p> <p>For N9K-C9316D-GX: Ports 1-16 support 400G/100G/40G and 10G with QSA and there are no port limitations.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS Interfaces Configuration Guide, Release 10.1(x)</i>.</p>
Per-Interface Unicast Bandwidth Reservation	<p>In IP Fabric for Media support has been added for configuring unicast bandwidth reservation per port. On configuring the per-port unicast BW percentage (%) reservation, the switch will check for the bandwidth to set aside for unicast purpose on both the ingress and egress directions.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS IP Fabric for Media Solution Guide, Release 10.1(x)</i>.</p>
Multicast Consistency Checker	<p>Added support for the following:</p> <ul style="list-style-type: none"> • IPv6 L2 Multicast Consistency Checker

Enhanced Features	
Feature	Description
	<ul style="list-style-type: none"> • IPv6 L3 Multicast Consistency Checker • Multicast NLB Consistency Checker • Multicast MAC Lookup mode Consistency Checker • Multicast NLB L3 unicast configuration Consistency Checker • Multicast GRE Consistency Checker <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS Troubleshooting Guide, Release 10.1(x)</i>.</p>
OpenConfig Model Additions	<p>Added support for the following:</p> <ul style="list-style-type: none"> • state containers for the OpenConfig ACL at interface-ref level • system config containers for domain-name, login banner and motd banner models <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS Programmability Guide, Release 10.1(x)</i>.</p>
Third-party RPM Validation	<p>Introduced a restriction on installation of unsigned or non-Cisco signed third-party RPMs, with an option to bypass the restriction.</p> <p>For more information see, <i>Cisco Nexus 9000 Series NX-OS Software Upgrade and Downgrade Guide, Release 10.1(x)</i>.</p>
LLFC Watchdog Interval	<p>Link Level Flow Control (LLFC) watchdog interval is triggered when an LLFC packet is seen on a Priority Flow Control (PFC)/PFC watchdog configured interface which doesn't have LLFC configured. LLFC Watchdog Interval is now supported on Cisco Nexus 9300-FX3 platform switches.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS Quality of Service Configuration Guide, Release 10.1(x)</i>.</p>
Logging Support for IPv6 Egress ACL	<p>Added support for IPv6 egress ACL logs with IPv6 addresses.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS Security Configuration Guide, Release 10.1(x)</i>.</p>
DHCP Relay with DAI	<p>Added support for enabling DHCP Relay with DAI. This is supported on the Cisco Nexus 9200, 9300-EX, and 9300-FX, 9300-FX2, 9300-FX3, and -GX TOR platform switches.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series Security Configuration Guide, Release 10.1(x)</i>.</p>
Critical Authentication	<p>From Cisco NX-OS Release 10.1(1), the 802.1X critical authentication on a port, accommodates 802.1X users that failed authentication when RADIUS servers were not reachable.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series Security Configuration Guide, Release 10.1(x)</i>.</p>
MACsec with QSA	<p>Added MACsec support when QSA is enabled in Cisco Nexus N9K-C9336C-FX2, N9K-C9336C-FX2-E, and N9K-C9364C platform switches.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series Security Configuration Guide, Release 10.1(x)</i>.</p>
DSCP Wildcard Mask	<p>Added support for creating an ACL that matches or filters traffic based on a DSCP bit mask in Cisco Nexus 9300 - EX/FX/FX2/FX3 Platform switches.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series Security Configuration Guide, Release 10.1(x)</i>.</p>

Enhanced Features	
Feature	Description
Policy-Based Routing Fast Convergence	Achieves sub-second traffic convergence in the case of failure of a next-hop PBR address. For more information, see the <i>Cisco Nexus 9000 Series Unicast Configuration Guide, Release 10.1(x)</i> .
Range AS Support for BGP Interface Peering	Expands BGP interface peering configuration by allowing a route map, which can contain AS lists and ranges. For more information, see the <i>Cisco Nexus 9000 Series Unicast Configuration Guide, Release 10.1(x)</i> .
BGP Replace ASNs in AS Path	Added support to replace specific AS numbers in the AS-path attribute with custom AS numbers, or remove the AS-path completely. For more information, see the <i>Cisco Nexus 9000 Series Unicast Configuration Guide, Release 10.1(x)</i> .
Suppress Link Prefixes in IS-IS	Added support to suppress or selectively advertise interface prefixes in system link-state packets (LSPs). For more information, see the <i>Cisco Nexus 9000 Series Unicast Configuration Guide, Release 10.1(x)</i> .
SRTE Explicit-Path Endpoint Substitution	Allows you to define an explicit path as a series of MPLS labels, like a regular explicit path, but allows a placeholder to be added in the series that represents the policy endpoint label. For more information, see the <i>Cisco Nexus 9000 Series NX-OS Label Switching Configuration Guide, Release 10.1(x)</i> .
SRTE over Default VRF	This feature uses the route colour that exists as an extended community attribute, to incorporate segment routing traffic engineering to achieve traffic steering benefits in your network. For more information, see the <i>Cisco Nexus 9000 Series NX-OS Label Switching Configuration Guide, Release 10.1(x)</i> .
FC/FCoE Switch Mode	Added FC FCoE switch mode support for Cisco Nexus N9K-C93360YC-FX2 platform switches. For more information, see the <i>Cisco Nexus 9000 Series NX-OS SAN Switching Configuration Guide, Release 10.1(x)</i> .
Redesign of the install deactivate CLI	Added support for options to either downgrade to the base version of RPM or to uninstall RPM. For more information see, <i>Cisco Nexus 9000 Series NX-OS Software Upgrade and Downgrade Guide, Release 10.1(x)</i> .
Enhanced ISSU with FC/FCoE	Added support for Enhanced ISSU on both FC/FCoE switch mode and NPV mode for Cisco Nexus N9K-C93360YC-FX2, N9K-C93180YC-FX platform switches. For more information see, <i>Cisco Nexus 9000 Series NX-OS Software Upgrade and Downgrade Guide, Release 10.1(x)</i> .
Standard ISSU	Added support for Standard ISSU on 9300-GX platform switches. For more information see, <i>Cisco Nexus 9000 Series NX-OS Software Upgrade and Downgrade Guide, Release 10.1(x)</i> .
ITD	Added support for Cisco Nexus N9K-X96136YC-R, N9K-X9636Q-R, N9K-X9636C-R, and

Enhanced Features	
Feature	Description
	<p>N9K-X9636C-RX line cards.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS Intelligent Traffic Director Configuration Guide, Release 10.1(x)</i>.</p>
Nondisruptive Addition/Removal of Node with Exclude and Include ACL	<p>Added support for non-disruptive addition and removal of nodes with Multi Include and Exclude ACLs. This minimizes the traffic disruption, which can occur when you shut down the ITD service.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS Intelligent Traffic Director Configuration Guide, Release 10.1(x)</i>.</p>
Ability to Change Weight without Disruption for ITD	<p>Added support for non-disruptive addition or deletion of nodes in a ITD session with weights and change of weights in a device group. You can assign a weight to the newly added node or modifies the weight of an existing node in a ITD session.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS Intelligent Traffic Director Configuration Guide, Release 10.1(x)</i>.</p>
ITD Fail-Action Drop on Node Failure	<p>Fail-action for ITD enables traffic to the failed nodes to be reassigned to one or more active nodes. Once the failed node becomes active again, it resumes serving connections. If all the nodes are down, the packets are routed automatically.</p> <p>Support is added now for a new drop-on-fail fail-action option for all fail actions.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS Intelligent Traffic Director Configuration Guide, Release 10.1(x)</i>.</p>
Vagrant Sync Folder	<p>Added support for Vagrant Sync Folder on Cisco Nexus 9300v platform. With this feature, a directory/folder on a host machine can be shared with a Cisco Nexus 9300v machine.</p> <p>For more information, see the <i>Cisco Nexus 9000v (9300v/9500v) Guide, Release 10.1(x)</i>.</p>
vPC Fabric Peering	<p>Added support for vPC Fabric Peering on Cisco Nexus 9300v and 9500v platforms.</p> <p>For more information, see the <i>Cisco Nexus 9000v (9300v/9500v) Guide, Release 10.1(x)</i>.</p>
Event Log Auto Collection and Backup	<p>Added support for the following:</p> <ul style="list-style-type: none"> • Support for test_folder where more than one YAML file can be present. • Rate of collection can be regulated using a maximum number of triggers option. • LC core file includes the log-snapshot bundle. <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS System Management Configuration Guide, Release 10.1(x)</i>.</p>
Multiple LLDP Neighbors per Physical Interface	<p>Added support for multiple LLDP neighbors per physical interface for the following line cards- N9K-C93180YC-FX3S, N9K-C93108TC-FX3P, N9K-C93180YC-FX3.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS System Management Configuration Guide, Release 10.1(x)</i>.</p>
FlashMIB SNMP Walk	<p>Added support for up to 10000 flash files for snmpwalk request.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS System Management Configuration Guide, Release 10.1(x)</i>.</p>
VXLAN Header Stripping for NDB	<p>Added support for VXLAN and IVXLAN header strip for all Cisco Nexus 9000 Series switches.</p> <p>For more information, see the <i>Cisco Nexus 9000 Series NX-OS System Management Configuration Guide, Release 10.1(x)</i>.</p>

Enhanced Features	
Feature	Description
ITD and ePBR over VXLAN	Added support for N9K-X9716D-GX TOR and N9K-C93180YC-FX3S platform switches. For more information, see the <i>Cisco Nexus 9000 Series NX-OS VXLAN Configuration Guide, Release 10.1(x)</i> .
VXLAN EVPN Loop Detection and Mitigation	Added support for Cisco Nexus 9300-FX3 and -GX platform switches. For more information, see the <i>Cisco Nexus 9000 Series NX-OS VXLAN Configuration Guide, Release 10.1(x)</i> .
VXLAN over Parent Interface that Carries Subinterfaces	Added support for Cisco Nexus 9300-FX3 platform switches. For more information, see the <i>Cisco Nexus 9000 Series NX-OS VXLAN Configuration Guide, Release 10.1(x)</i> .
VXLAN Static Tunnels	Added support for Cisco Nexus 9300-FX3 platform switches. For more information, see the <i>Cisco Nexus 9000 Series NX-OS VXLAN Configuration Guide, Release 10.1(x)</i> .
Selective Q-in-VNI and VXLAN VLAN on Same Port	Added support for Cisco Nexus 9300-FX3 platform switches. For more information, see the <i>Cisco Nexus 9000 Series NX-OS VXLAN Configuration Guide, Release 10.1(x)</i> .
Selective Q-in-VNI and Advertise PIP on a VTEP	Added support for Cisco Nexus 9300-FX3 platform switches. For more information, see the <i>Cisco Nexus 9000 Series NX-OS VXLAN Configuration Guide, Release 10.1(x)</i> .
VXLAN Tunnel Encryption	Secure VXLAN EVPN Multi-Site using CloudSec is supported on Cisco Nexus 9300-FX3 platform switches. For more information, see the <i>Cisco Nexus 9000 Series NX-OS VXLAN Configuration Guide, Release 10.1(x)</i> .
IPv4/IPv6 MIB Support	Added support for Cisco Nexus EoR platform switches with -FX line cards. For more information, see the <i>Cisco Nexus 9000 Series NX-OS Interfaces Configuration Guide, Release 10.1(x)</i> .
ECMP Hashing based on GRE Inner IP Header	Added support for Cisco Nexus 9300-FX3 platform switches. For more information, see the <i>Cisco Nexus 9000 Series NX-OS Interfaces Configuration Guide, Release 10.1(x)</i> .
ECMP Symmetric Hashing	Added support for Cisco Nexus 9300-FX3 platform switches. For more information, see the <i>Cisco Nexus 9000 Series NX-OS Interfaces Configuration Guide, Release 10.1(x)</i> .
Unidirectional Ethernet (UDE)	Added support for Cisco Nexus 9000 -EX/FX/FX2/FX3 platform switches platforms. For more information, see the <i>Cisco Nexus 9000 Series NX-OS Interfaces Configuration Guide, Release 10.1(x)</i> .
vPC Fabric Peering and FEX Support	Added support for Cisco Nexus 9000-EX/FX/FX2/FX3/GX platform switches. For more information, see the <i>Cisco Nexus 9000 Series NX-OS VXLAN Configuration Guide, Release 10.1(x)</i> .

Enhanced Features	
Feature	Description
VXLAN EVPN with Downstream VNI	Added support for Cisco Nexus 9300-FX3 platform switches and for N9K-C9316D-GX, N9K-C93600CD-GX, and N9K-C9364C-GX TOR switches. For more information, see the <i>Cisco Nexus 9000 Series NX-OS VXLAN Configuration Guide, Release 10.1(x)</i> .
VXLAN PBR	Added support for N9K-C9316D-GX, N9K-C93600CD-GX, and N9K-C9364C-GX TOR switches. For more information, see the <i>Cisco Nexus 9000 Series NX-OS VXLAN Configuration Guide, Release 10.1(x)</i> .
IPv6 Underlay	Added support for N9K-C9316D-GX, N9K-C93600CD-GX, and N9K-C9364C-GX TOR switches. For more information, see the <i>Cisco Nexus 9000 Series NX-OS VXLAN Configuration Guide, Release 10.1(x)</i> .
VXLAN Flood and Learn	Added support for N9K-C9316D-GX, N9K-C93600CD-GX, and N9K-C9364C-GX TOR switches. For more information, see the <i>Cisco Nexus 9000 Series NX-OS VXLAN Configuration Guide, Release 10.1(x)</i> .
ePBR Exclude ACL	Added support for three action types (redirect, drop, and exclude) for each match statement under ePBR policy. For more information, see the <i>Cisco Nexus 9000 Series NX-OS ePBR Configuration Guide, Release 10.1(x)</i> .
Flex Link	Added support for flex link on Cisco N9K-C93180YC-FX3 platform switch. For more information, see <i>Cisco Nexus 9000 Series NX-OS Layer 2 Switching Configuration Guide, Release 10.1(x)</i> .

New Hardware Features

The following new hardware are introduced in Cisco NX-OS Release 10.1(1):

- N9K-X9716D-GX, a 16-port 400-Gigabit Ethernet QSFP line card for Cisco Nexus 9500 family switches.
- N9K-C9504-FM-G fabric module
- N9K-C9504-FAN2 Fan tray for Cisco Nexus 9504 Chassis
- N9K-C9508-FM-G fabric module
- N9K-C9508-FAN2 Fan tray for Cisco Nexus 9508 Chassis
- The Cisco Nexus 9336C-FX2-E switch (N9K-C9336C-FX2-E) is a 1-rack unit (RU), fixed-port switch designed for deployment in data centers.

This switch has the following ports:

- 36 40/100-Gigabit QSFP28 ports
- Two management ports (one 10/100/1000BASE-T port and one SFP port)

- o One console port (RS-232)
- o One USB port

This switch includes the following user-replaceable components:

- Fan modules (six) with the following airflow choices:

- o Port-side exhaust fan module with blue coloring (NXA-FAN-35CFM-PE)
- o Port-side intake fan module with burgundy coloring (NXA-FAN-35CFM-PI)

- Power supply modules (two—One for operations and one for redundancy [1+1]) with the following choices:

- o 750-W port-side exhaust AC power supply with blue coloring (NXA-PAC-750W-PE)
- o 750-W port-side intake AC power supply with burgundy coloring (NXA-PAC-750W-PI)
- o 1100-W port-side exhaust AC power supply with blue coloring NXA-PAC-1100W-PE2
- o 1100-W port-side intake AC power supply with burgundy coloring NXA-PAC-1100W-PI2
- o 1100-W port-side exhaust DC power supply with blue coloring NXA-PDC-1100W-PE
- o 1100-W port-side intake DC power supply with burgundy coloring NXA-PDC-1100W-PI
- o 1100-W port-side exhaust HV power supply with blue coloring NXA-PHV-1100W-PE
- o 1100-W port-side intake HV power supply with burgundy coloring NXA-PHV-1100W-PI

- The N9K-C93180YC-FX3 switch is a 1-rack unit (RU), fixed-port switch with:

- o 48 1/10/25 Gigabit Ethernet SFP28 ports (ports 1-48)
- o 6 10/25/40/50/100-Gigabit QSFP28 ports (ports 49-54)

Unsupported Hardware

Beginning with Cisco NX-OS Release 10.1(1), the following hardware are not supported.

- Third-party Switches or Whitebox
- N9K-C92304QC
- N9K-C9236C
- N9K-C92300YC-X
- N9K-C9272Q
- N9K-C92160YC-X

-
- N9K-C9372PX
 - N9K-C9372TX
 - N9K-C9332PQ
 - N9K-C93120TX
 - N9K-C9396PX
 - N9K-C9396TX
 - N9K-93180LC-EX
 - N9K-C93128TX
 - N9K-C9372PX-E
 - N9K-C9372TX-E
 - N9K-M6PQ
 - N9K-M4PC-CFP2
 - N9K-M12PQ
 - N9K-M6PQ-E
 - N9K-X9464TX
 - N9K-X9408PC-CFP2
 - N9K-X9536PQ
 - N9K-X9564PX
 - N9K-X9564TX
 - N9K-X9636PQ
 - N9K-X9736PQ
 - N9K-X9432PQ
 - N9K-X9464PX
 - N9K-X9464TX2
 - N9K-C9504-FM
 - N9K-C9508-FM
 - N9K-C9516-FM
 - N9K-C9516-FM-E

Unsupported Features on N9K-C92348GC

Beginning with Cisco NX-OS Release 10.1(1), the following features are not supported on N9K-C92348GC.

- VXLAN
- SW/HW Telemetry

- NetFlow/Analytics
- iCAM
- PTP
- NX-SDK
- DME, Device YANG, OpenConfig YANG, gRPC, NETCONF, and RESTCONF

Note: NXAPI CLI and XML Agent (NETCONF over SSH) are supported on this platform.

Release Image

Cisco Nexus 9000 Series switches require 32-bit or 64-bit NX-OS image depending on the Cisco Nexus 9000 platforms.

Open Issues

Bug ID	Description
CSCvu05760	<p>Headline: N9K/N3K ATA Micron_M500IT_MT Bootflash goes read only</p> <p>Symptoms: N9K/N3K bootflash goes read only with M500IT Drive</p> <p>Workarounds: Reload will correct read only condition</p>
CSCvw70948	<p>Headline: vPC BGW : multisite bgp-if is up for 30s after peer-link failure on vpc secondary</p> <p>Symptoms: After peer-link failure on VPC secondary, the following happens:</p> <p>The NVE source interface is immediately brought down</p> <p>NVE is kept UP for additional 30s</p> <p>The “multisite bgp-if” (dedicated loopback for multisite) is kept up for 30s (not tuneable “Source Interface hold-up-time”). This causes the traffic from DCI side to still be attracted possibly causing some deferred convergence.</p> <p>Workarounds: None at this point, connectivity will be re-established after 30s</p>
CSCvw73084	<p>Headline: SVI Isolation in Maintenance mode does not work after a reload</p> <p>Symptoms: When using maintenance mode on a Nexus HW: 93180YC-EX running a software version of 9.2(2) with VPC isolation and VPC domain shutdown, after the reboot, the SVIs are in an 'UP' state.</p> <p>Workarounds: N/A</p>
CSCvw99262	<p>Headline: ETHPM Lock seen with PCM/MACSEC race condition</p> <p>Symptoms: ETHPM lock may be seen when doing configuration change on MACSEC enabled Po</p> <p>Workarounds: Reload of the device is needed to clear the lock.</p>

Bug ID	Description
CSCvx16206	<p>Headline: N9k/VXLAN/IR: BUM traffic dropped after ND-ISSU - MET not set (0xfffff)</p> <p>Symptoms: BUM traffic dropped for L2 VNI with IR (Ingress Replication). Traffic is dropped in source VTEP that should encapsulate traffic. There is no specific error seen in syslog.</p> <p>ELAM capture will show result as MET0 and result DROP</p> <p>The command "show forwarding internal nve vlan-floodlist" shows vlans with IR MET index as "MET: 0xffffffff" as shown below.</p> <p>Vlan : XXXX</p> <p>Flags: None, Vlan Met: 0xc next_met 0x1d last_met 0x2</p> <p>[0, 0] Peer: X.X.X.X.X (ID: 1), MET: 0xffffffff , ENCAP_IDX: 0x3001[hwidx:3000, hwenry:1], MCIDX: 4000, port-channelYY, DCI: FALSE, DSVNI: FALSE</p> <p>The command "show forwarding internal nve ir-peer" shows some MET INDEX as "-1" as shown below.</p> <p>Node 0x1156fe6c: met_ptr [29], refcnt [4], met_ent [0x1156fe7c]</p> <pre>peer list [count=2] 1,19 MET PTR: 29 MET Entries: LTL: 2, BD: 16382, MET INDEX , SLICE: (-1, 0) (-1, 1) MCIDX: 4099 , LTL: 3, BD: 16382, MET INDEX , SLICE: (-1, 0) (-1, 1) MCIDX: 4098</pre> <p>Workarounds: No non-disruptive workaround - reload or disruptive upgrade will resolve the issue.</p>
CSCvx18993	<p>Headline: ON portfast enabled interface STP goes through BLK-LRN-FWD convergence after VPC sec turns Op. Prim</p> <p>Symptoms: On portfast enabled interface, STP goes through BLK-LRN-FWD convergence after VPC secondary turns to operational primary.</p> <p>Workarounds: Shut/ no shut interface bring it back without convergence wait.</p>
CSCvx20120	<p>Headline: Burst-detect cannot work on N9K-C93216TC-FX2, N9K-C93360YC-FX2, N9K-C9336C-FX2-E, N9K-C93180YC-FX3</p> <p>Symptoms: Burst-detect cannot work on N9K-C93216TC-FX2, N9K-C93360YC-FX2, N9K-C9336C-FX2-E, N9K-C93180YC-FX3</p> <p>Workarounds: None</p>
CSCvx21858	<p>Headline: N9K-X9788TC-FX: port LEDs turn on orange after switchover</p> <p>Symptoms: On primary vpc, link not connected ports that belongs to vpc will turn on orange LED after switchover.</p> <p>Workarounds: N/A</p>
CSCvx23114	<p>Headline: Breakout interface flaps on certain ports</p> <p>Symptoms: Breakout interfaces may flap unexpectedly on certain ports for no apparent reason.</p> <p>Workarounds: Breakout configuration is required - consider using other interfaces/ports on the switch/line card.</p>

Bug ID	Description
CSCvx23913	<p>Headline: Clock protocol configured with NTP is not reflected in the running-config</p> <p>Symptoms: When configuring the clock protocol with NTP, the configuration will not be seen under the running configuration. This problem cause automation tools (i.e. DCNM) to see discrepancy in the configuration and declare the Nexus out-of-sync</p> <p>Workarounds:</p> <ul style="list-style-type: none"> • First configure the clock protocol to other than ntp (i.e. ptp) • Configure the clock protocol ntp
CSCvx25283	<p>Headline: msdp owned (s,g) mroute not inherite pim oif from (*,g)</p> <p>Symptoms: On further checking, we found :MSDP S,G mroute (10.163.50.87/32, 239.191.81.80/32) sync'd by MSDP RP/Catalyst to RP/svcx001 does not inherit PIM OIF from (*,G) does not inherit PIM oif from (*,g). There are other groups are well which do not inherit OIFL from (*,G) Entry, whereas some groups are working fine.</p> <p>Workarounds: Adding static OIF (S,G) for outgoing interface.interface Ethernet x/y ip igmp static-oif <multicast_group> source <multicast_source_ip></p>
CSCvx25671	<p>Headline: Generate syslog for Interface Inbound Discard (Buffer full) condition</p> <p>Symptoms: Packet loss seen for traffic passing through the device due to " Interface Inbound Discard (Buffer full)" as below:N9508# show hardware internal errors allslot 1===== ----- ----- Device: Sugarbowl Role:MAC Mod: 1 Last cleared @ Wed Jan 13 12:05:22 2021 Device Statistics Category :: ERROR ----- Instance:OID Name Value Ports-- ---- ---- Instance:1ID Name Value Ports-- ---- ---- -----1245201 Interface Inbound Discard (Buffer full) 0000000660501648 17:0 <-----</p> <p>Workarounds: For silent packet loss condition, verify " show hardware internal errors all" output for all the modules to determine if any of the counters incrementing heavily.</p>
CSCvx26057	<p>Headline: Unicast traffic punted to CPU due to HW ADJ pointing to global glean adj</p> <p>Symptoms: Unicast traffic punted to CPU and dropped by COPP.HW adj is pointed to global glean adj after route flap or change.</p> <p>Workarounds: None</p>
CSCvx27433	<p>Headline: Switch crashes due BMP configuration</p> <p>Symptoms: Symptom: After a migration to 9.3.6, BGP crashes multiple times due to SIG 6 and triggers the HAP policy leading to a reload of the switch.</p> <p>Workarounds: Disable BMP server configuration.</p>
CSCvx03176	<p>Headline: N9K-C9364C:100G copper link flaps continuously in MacSec mode</p> <p>Symptoms: Link continues to flap when you have 100G copper cable on N9K-C9364C running macsec.</p> <p>Workarounds: If macsec is needed, use fibre connection instead.</p> <p>If macsec and copper connection is needed, disable auto negotiation. However, in this case, link will still not come up after ascii reload. No issue with binary reload.</p>
CSCvx23143	<p>Headline: N9K-C9364C: 40g copper link is not up after placing in place of QSA with macsec config</p> <p>Symptoms: Link not coming up.</p> <p>Workarounds: After you replace QSA with a 40G copper cable, you will need a reload to bring the link back.</p>

Bug ID	Description
CSCvx27216	<p>Headline: EOR:Snmpbulkwalk timeouts on CISCO-PFC-EXT-MIB even with -t 10sec timeout</p> <p>Symptoms: SNMP bulk walk on CISCO-PFC-EXT-MIB(iso.3.6.1.4.1.9.9.813) may timeout when attempting to poll on a fully loaded 9500 device with shorter timeouts</p> <p>Workarounds: Admin down interfaces that are not being used on the platform</p>
CSCvx29049	<p>Headline: v1.5 apps not running and resulting in core</p> <p>Symptoms:</p> <p>Workarounds:</p>
CSCvx38049	<p>Headline: " show queuing burst-detect detail" cli getting stuck when interface or queue is not given</p> <p>Symptoms: In NXOS 10.1(1) release, Python applications developed by the user and started on the switch via " nxsdk service " will fail to start, and a core file will be generated for the service.</p> <p>Workarounds: If the Python application only requires use of the CliMgr module, the application may be started from bash. There is no application level change that will impact this issue.</p>
CSCvx37003	<p>Headline: HMM core seen after vpc-link up , some svi are suspended</p> <p>Symptoms: Some SVI (Interface vlan xx) interfaces remain in suspended state after switch reload. A crash of the hmm process is also observed. Core should be saved ideally.</p> <p>Workarounds: Remove and reconfigure arp suppression on the suspended vlan/vni.</p>
CSCvx29518	<p>Headline: Crash is seen with process "snmpd"</p> <p>Symptoms: SNMPD process crash has been observed intermittently after reload of the device</p> <p>Workarounds: There is no workaround. However, SNMPD process will be re-spawned after crash and SNMP process will work as normal.</p>
CSCvx44024	<p>Headline: " Telemetry Transport" in " Transmit Error" state when DUT loaded with 10.1.1 release image</p> <p>Symptoms: " show telemetry transport" shows " Transmit Error" in the status column for all streaming telemetry sessions.</p> <p>Workarounds: Use addresses that are palindromes (eg 1.1.1.1 or 1.2.2.1) as source-interface in telemetry destination-profile.</p>
CSCwe67205	<p>Headline: Credit Loss Recovery is not triggered for FC interface with no transmit credits.</p> <p>Symptom: A Fibre Channel interface that stays at 0 transmit credits is not recovered by the Credit Loss Recovery agent.</p> <p>Workaround: If the interface has switchport ignore bit-errors configured, then remove it with the no switchport ignore bit-errors interface configuration command.</p>
CSCwe53655	<p>Headline: Revert reserved MAC blocking behavior for VRRP macs on SVIs</p> <p>Symptoms: User not able to configure VRRP VMAC on SVI interfaces.</p> <p>Workarounds: None.</p>

Bug ID	Description
CSCwh50989	<p>Headline: Custom COPP causing transit traffic to be punted to the CPU on Nexus 9300-GX2</p> <p>Symptoms: When custom-COPP policy contains ACL rules which match on Layer 4 destination or source port, transit traffic also hits the COPP and the packets are copied to CPU. This causes duplication of traffic as CPU also routes the copied packets to the destination.</p> <p>Workarounds: Custom COPP policy using src/dst match mitigates punt for transit traffic.</p>

Resolved Issues

Bug ID	Description
CSCva80686	<p>Headline: Enhancement: New command 'show tech-support core'</p> <p>Symptoms: This is an enhancement request for a new show command to expedite the gathering and decoding of core files.</p> <p>Workarounds: Gather the following files separately.core files</p>
CSCvi85331	<p>Headline: Application vsh.bin on slot 28 vdc 1 SUP sap 65489 did not drop MTS_OPC_CLISH</p> <p>Symptoms: After an upgrade or booting up an affected NX-OS release the following may be reported in the log just after entering a show command: `show logging log` 2018 Apr 5 16:41:29 %\$ VDC-1 %\$ Apr 5 16:41:28 %KERN-2-SYSTEM_MSG: [8891.460963] Application vsh.bin on slot 28 vdc 1 SUP sap 65489 did not drop MTS_OPC_CLISH with msg_id 0x1ecfd from sender sap 65531 in 180 sec, please contact the application owner - kernel</p> <p>Workarounds: None</p>
CSCvk45018	<p>Headline: BFD is blocked over Unnumbered Interfaces</p> <p>Symptoms: BFD would not come up over L3 interfaces if configured as unnumbered.</p> <p>Workarounds: None</p>
CSCvo90653	<p>Headline: Graceful SPT switch-over</p> <p>Symptoms: The incoming interface for an (S,G) entry is immediately set to the source RPF, with forwarding on the shortest path tree, and pruning the source off the shared tree. If there is no route for the source, this causes forwarding to stop for the source.</p> <p>Workarounds: No workaround, although one could consider configuring the routers to not switch to shortest path tree.</p>
CSCvs10216	<p>Headline: TRM drops first multicast packet</p> <p>Symptoms: In a tenant routed multicast EVPN network the first packet of a multicast stream is used to create the (S,G) and is subsequently dropped. This is regardless of whether ip routing multicast software-replicate is configured.</p> <p>Workarounds: configure ip pim sg-expiry-timer high so that the (S,G) does not need to be recreated.</p>

Bug ID	Description
CSCvu01334	<p>Headline: Unable to delete PBR under Physical Interface</p> <p>Symptoms: This was on a N9K-C9336C-FX2 running 9.3(3).[+] Unable to remove the PBR configured under Physical interface.[+] Getting Following Error message when tried to remove it. switch(config)# interface ethernet 1/5switch(config-if)# no ip policy route-map rm_webcache4There are no ip policy configured on this interface <<<switch(config-if)# end switch# sh accounting logFri Apr 17 07:03:37 2020:type=update:id=10.10.10.49@pts/0:user=test.s:cmd=configure terminal ; interface Ethernet1/5 (REDIRECT)Fri Apr 17 07:03:37 2020:type=update:id=10.10.10.49@pts/0:user=test.s:cmd=configure terminal ; interface Ethernet1/5 (SUCCESS)Fri Apr 17 07:03:49 2020:type=update:id=10.10.10.49@pts/0:user=test.s:cmd=configure terminal ; interface Ethernet1/5 ; no ip policy route-map rm_webcache4 (REDIRECT)Fri Apr 17 07:03:49 2020:type=update:id=10.10.10.49@pts/0:user=test.s:cmd=configure terminal ; interface Ethernet1/5 ; no ip policy route-map rm_webcache4 (FAILURE) Nothing shown up in logging log and nvram :switch# sh logging nvram last 2020 Apr 14 10:12:07 switch %\$ VDC-1 %\$ %VDC_MGR-2-VDC_ONLINE: vdc 1 has come online 2020 Apr 14 10:12:05 switch %\$ VDC-1 %\$ %CARDCLIENT-2-FPGA_BOOT_PRIMARY: MIFPGA booted from Primary switch# sh logging last 2020 Apr 17 06:56:08 switch %AUTHPRIV-3-SYSTEM_MSG: pam_aaa:Authentication failed from 10.10.10.49 - login2020 Apr 17 07:03:52 switch %VSHD-5-VSHD_SYSLOG_CONFIG_I: Configured from vty by test.s on 10.10.10.49@pts/02020 Apr 17 07:06:35 switch last message repeated 1 time</p> <p>Workarounds: reload ascii binary reload might not help</p>
CSCvu36528	<p>Headline: Files are written with no read privilege for admin user</p> <p>Symptoms: unable to copy files from n9k bootflash; below error message will be seen<snip>n9k1# copy bootflash:capture_00001_20200522212705.pcap ftp:Enter vrf (If no input, current vrf 'default' is considered): managementEnter hostname for the ftp server: 172.18.108.26Enter username: caloPassword: local: /bootflash/capture_00001_20200522212705.pcap: Permission denied</snip></p> <p>Workarounds: drop to bash and change the permission for the respective file</p>
CSCvu67445	<p>Headline: N9k switches ending with EX/FX/FX2/FX3/GX- Flood list missing member port - broadcast traffic loss</p> <p>Symptoms: Broadcast may not Tx an Ethernet port for VLAN's allowed for one of the port-channel member links. ARP request or any other form of ethernet broadcast may not reach destination. This would lead to no connectivity for affected hosts. Consistency check will report failure for VLAN membership: Example: show consistency-checker membership vlan 442hecking hardware for Module 1 Unit 0No FEX interfaces to validate Consistency Check: FAILED >>> Vlan:442, Hardware state consistent for: Ethernet1/41 Ethernet1/49 Ethernet1/50 Ethernet1/53 Vlan:442, Hardware state inconsistent for: Ethernet1/54</snip></p> <p>Workarounds: Enter shut/no shut (flap) the affected interface. Do not use the " port-channel port load-defer" command.</p>
CSCvu72378	<p>Headline: Nexus 9K/3K - QDD-400-CUXM Copper Cable Init Sequence Error - EEPROM Corruption</p> <p>Symptoms: A 400G interface may be stuck in Initializing state.The log may display the following message:%ETHPORT-5-IF_DOWN_INITIALIZING: Interface Ethernet1/XX is down (Initializing)The transceiver may be reported as "not supported" in the output of `show interface ethernet x/y transceiver`</p> <p>Workarounds: TAC can reprogram the EEPROM</p>
CSCvu73849	<p>Headline: PTP corrections field (CF) received from transparent clock device not processed by N9000</p> <p>Symptoms: Nexus 9000 reports and propagates high PTP corrections downstream.</p> <p>Workarounds: Use all devices in BC mode.</p>

Bug ID	Description
CSCvu84315	<p>Headline: Commit Failure after we create a checkpoint with an existing name - N9K-C93108TC-EX</p> <p>Symptoms: When we try to create a checkpoint with the same name as an existing one you can't commit config sessions until you either delete that checkpoint or create a new checkpoint.</p> <p>Workarounds: Delete the old checkpoint with the same name as the new one or do any checkpoint /rollback operation</p>
CSCvu90939	<p>Headline: N9364 - Mgmt0 sending out signals when force admin Shut</p> <p>Symptoms: When 9364C mgmt0 connects to 93108TC-FX eth port directly, the 93108TC-FX Ethernet port shows Up when remote mgmt0 of Cisco Nexus 9364C is admin down.</p> <p>Workarounds: No workaround</p>
CSCvw00706	<p>Headline: Need to add a cli to view SFP details on N9K Mgmt0 port</p> <p>Symptoms: No user friendly cli available to view if SFP is inserted or not on N9K mgmt port</p> <p>Workarounds: Need to go into bash and get the info, reachout to TAC</p>
CSCvw01406	<p>Headline: EIGRP Neighbor flapped when adjust the time to past</p> <p>Symptoms: # show clock 09:01:36.172 UTC Wed Jul 15 2020 <<<<<<<< Time source is Hardware Calendar# clock set 05:00:00 15 july 2020 <<<<<<< modify the time to the past cause the eigrp neighbor flappingWed Jul 15 05:00:00 UTC 2020# terminal monitor 2020 Jul 15 05:00:12 SWITCH %EIGRP-5-NBRCHANGE_DUAL: eigrp-1 [3813] (default-base) IP-EIGRP(0) 1: Neighbor 10.x.x.x (Ethernet1/XX) is down: Interface Goodbye received2020 Jul 15 05:00:17 SWITCH %EIGRP-5-NBRCHANGE_DUAL: eigrp-1 [3813] (default-base) IP-EIGRP(0) 1: Neighbor 10.x.x.x (Ethernet1/XX) is up: new adjacency</p> <p>Workarounds: None</p>
CSCvw09729	<p>Headline: Cisco Nexus 92348 back pressure results in PSU fan spinning wrong direction</p> <p>Symptoms: The power supply exhaust fan may spin in the wrong direction on the Cisco Nexus 92348.</p> <p>Workarounds: None</p>
CSCvw09753	<p>Headline: BGP mass prefix withdrawal causing high CPU spikes for event_manager and policyelem</p> <p>Symptoms: # sh processes cpu exclude 0.00PID Runtime(ms) Invoked uSecs 1Sec Process-----</p> <pre> 317691941 721 1.00% ksm28182 1027 290 3543 31.25% event_manager28183 1948 523 3726 8.75% policyelem28341 1286455 10566658 121 1.50% vman28389 263 208 1266 0.50% confelem28466 12223331 12799864 954 0.50% diagmgr28531 183686 9203510 19 0.50% nginx28535 290028 5637064 51 15.75% device_test28689 275 123 2240 0.50% adjmgr30088 231051 4497027 51 0.50% l2rib30269 2085655 7006841 297 0.50% diag_port_lb30270 79629350 558705133 142 1.50% ethp30409 365 364 1004 5.00% bgp30429 353 284 1245 0.50% ospf31735 183889131 2147483647 16 1.50% mts-sync- thrPID Runtime(ms) Invoked uSecs 1Sec Process----- -----11833 187091199 2147483647 17 2.00% mts-sync-thr27844 996 282 3532 30.25% event_manager27845 1928 541 3564 8.75% policyelemPID Runtime(ms) Invoked uSecs 1Sec Process-----27844 996 282 3532 34.25% event_manager27845 1928 541 3564 23.00% policyelem28048 287 921 311 2.00% confelem </pre> <p>Workarounds: NA</p>

Bug ID	Description
CSCwv12119	<p>Headline: N9K EOR / N9K-SUP-A+ / Acl-mgr crash</p> <p>Symptoms: Reason: Reset triggered due to HA policy of Reset</p> <p>Workarounds: N/A</p>
CSCwv21551	<p>Headline: Memory leak in "ascii-cfg" process due to "write-memory" command in archive config</p> <p>Symptoms: There is a memory leak in the "ascii-cfg" process. It happens when customers use the archive feature with the "write-memory" command. The leak happens when entering the "copy run start" command which also triggers the archive to automatically run in parallel and backup will be performed.</p> <p>Workarounds: Remove the "write-memory" command.</p>
CSCwv21797	<p>Headline: no vpc domain 20 removes previously configure vpc domain 10 without any warning</p> <p>Symptoms: On a Nexus 9000 switch one can remove an existing vpc domain with the wrong vpc id number. I.e example vpc domain 10 is configured but the executed command is: no vpc domain 20 this will remove domain 10 without any further warning, despite that we tried to remove domain 20 which does not exist in this example.</p> <p>Workarounds: None</p>
CSCwv22452	<p>Headline: Cisco NX-OS HSRP stuck in "Initial" state after reload with static HSRP MAC configured</p> <p>Symptoms: - For Nexus broken VLAN 2251 with static HSRP MAC is configured, after reload HSRP gets stuck in "Initial" state, but should move to next states as seen for working VLAN 2250.</p> <p>Workarounds: -Shutdown/no shutdown SVI VLAN 2251 (or impacted HSRP VLAN) will move the HSRP state out of "Initial" and continue to next state eventually transitioning to Standby or Active as expected. -Temporary fix would be to use any MAC not in this range 0000.0C9F.xxxx. However, HSRP MAC range is 0000.0C9F.Fxxx which we anyway cannot configure statically for a group.</p>
CSCwv28535	<p>Headline: error: mkstemp failed when applying switchport host</p> <p>Symptoms: error: mkstemp failed when applying switchport host to an interface switch(config-if)# int e 1/6 switch(config-if)# switchport host error: mkstemp failed This is only happening on 9.3(5).9.3(2) and 9.3(4) are not showing this behavior and command is applied properly</p> <p>Workarounds: None</p>
CSCwv28681	<p>Headline: Cisco Nexus 9500-R heavy RPF failure traffic congesting CPU pipeline causing IGMP drops</p> <p>Symptoms: IGMP groups time out due to dropping of IGMP packets in CoPP.</p> <p>Workarounds: Fixing the RPF failure causing congestion.</p>

Bug ID	Description
CSCvv29453	<p>Headline: Line card PFM going out of sync, extraneous "Module is undergoing ISSU" in XML output</p> <p>Symptoms: One, or more, line cards on a Cisco Nexus 9500 may become stuck in 'initializing' or 'powered-dn' state after switch boots up. The following messages may be reported in the log for the affected module(s): 2020 Jul 28 03:46:45 %ETHPORT-5-IF_SEQ_ERROR: Error ("sequence timeout") communicating with MTS_SAP_VLAN_MGR for opcode MTS_OPC_VLAN_MGR_GET_PORT_TRUNKING_MEMBERSHIP_2 (RID_MODULE: 5) 2020 Jul 28 03:47:05 %VMM-2-VMM_SERVICE_ERR: VDC1: Service SAP Ethpm SAP for slot 5 returned error 0x408c0008 (sequence timeout) in if_bind sequence</p> <p>Workarounds: Power cycle/Reload the line card.</p>
CSCvv29703	<p>Headline: Error occurred while trying to read database when recreating an object-group</p> <p>Symptoms: When attempting to recreate or modify an object-group on the N9K the following error gets displayed: "Error occurred while trying to read database"</p> <p>Workarounds: None</p>
CSCvv35402	<p>Headline: Support for as-path replace under route-map for BGP as-path manipulation</p> <p>Symptoms: as-path replace under route-map for BGP as-path manipulation is not supported.</p> <p>Workarounds: NA</p>
CSCvv47247	<p>Headline: N9k with 3rd party optics link down when FEC is enabled</p> <p>Symptoms: When using 3rd party Optics with FEC enables, link remains down</p> <p>Workarounds: None, need to downgrade to 9.3(3) or 9.3(4)</p>
CSCvv48289	<p>Headline: Unable to upgrade from Cisco NX-OS 9.3(2) to 9.3(5) via install all for N9K-C92348GC-X</p> <p>Symptoms: Upgrade from 9.3.2 to 9.3.5 fails via ISSU</p> <p>Workarounds: NA</p>
CSCvv49105	<p>Headline: Control-Plane Tx will get dropped due to incorrect namespace ID</p> <p>Symptoms: ICMP Tx will get dropped due to incorrect namespace ID</p> <p>Workarounds:</p> <ol style="list-style-type: none"> 1. Kill KIM process using kill -6 <process ID> and Delete the interface VLAN/recreate it. 2. Reload of the switch - Preferred way
CSCvv60665	<p>Headline: ISSU ports with QSFP-100G40G-BIDI remain not connected after a flap</p> <p>Symptoms: Port remains stuck in (Link not connected) after port flap or admin shut/no shut.</p> <p>Workarounds: Reloading the switch clears the issue.</p>
CSCvv61335	<p>Headline: N9300 does not respond and register PTP delay-request received from PTP client</p> <p>Symptoms: PTP client runs in uncalibrated mode.</p> <p>Workarounds: N/A</p>

Bug ID	Description
CSCvv65667	<p>Headline: MAC ACL + MAC packet classification could not let IPv6 NS/NA pass through in N9K-C93600CD-GX</p> <p>Symptoms: With the configuration of MAC ACL + MAC packet classification, the port will deny IPv6 NS/NA packets. It caused the IPv6 traffic could not go through the port. Example configuration: mac access-list test statistics per-entry 10 permit any any 0x86dd <<<<< ethertype of IPv6 interface Ethernet2/1 switchport mac port access-group test mac packet-classify no shutdown</p> <p>Workarounds: None</p>
CSCvv66928	<p>Headline: Cannot retrieve port-channel rate statistics via SNMP</p> <p>Symptoms: Customer can't get aggregated port-channel statistics via SNMP that is how this device will be deployed.</p> <p>Workarounds: No workarounds.</p>
CSCvv70929	<p>Headline: NXOS: MFDM service crashes in mfdm_fib_process_v4_route_response</p> <p>Symptoms: A Cisco Nexus datacenter switch may experience a service crash within MFDM on the supervisor due to a signal 11 / segmentation fault. In some cases, multiple crashes within MFDM may trigger a HA reset and bring the supervisor down (or cause a failover). %\$ %SYSMGR-2-SERVICE_CRASHED: Service "mfdm" (PID #####) hasn't caught signal 11 (core will be saved).</p> <p>Workarounds: The workaround in this case is to scale back down if a particular group is displaying large number of OIFs per source. In some cases the offending isolating the multicast group can be blocked using a RACL policy.</p>
CSCvv75490	<p>Headline: NFM process crashes leads to hap-reset</p> <p>Symptoms: A Nexus device is seeing multiple nfm (netflow) process crashes. This results in the system getting reloaded due to a hap-reset.</p> <p>Workarounds: Remove netflow if possible. Downgrading to a version bellow 9.2(4) or 9.3(1) should also stop the crash</p>
CSCvv82134	<p>Headline: N9K CDP EEM not working - Max Limit for CDP EEM events reached !! with single event</p> <p>Symptoms: When attempting to create CDP neighbor-discovery event under EEM applet, system will throw error indicating limit is reached even if no previous events are defined and you are only configuring a single port for event:n9k(config-applet)# event neighbor-discovery interface e1/1Max Limit for CDP EEM events reached !!</p> <p>Workarounds: No workarounds available.</p>
CSCvv94794	<p>Headline: SNMPd crash at mtrack_int_free, probably due to corrupt ptr</p> <p>Symptoms: SNMPd process crashes:%SYSMGR-2-SERVICE_CRASHED: Service "snmpd" (PID 29464) hasn't caught signal 11 (core will be saved).</p> <p>Workarounds: None.</p>
CSCvv99888	<p>Headline: Default routed pbr-statistics not counted if more than one object-group in ACL</p> <p>Symptoms: Traffic that matches the default routing of a PBR will not be counted by pbr-statistics.</p> <p>Workarounds: Use the command `show system internal access-list interface [interface_name] input entries detail` to display statistics for the PBR applied to the interface specified. Use only 1 object group per ACE</p>

Bug ID	Description
CSCvw06114	<p>Headline: Post-routing flood will use L3VNI instead of user VLAN when MAC is not learnt in L2RIB/MAC table</p> <p>Symptoms: when MAC gets deleted during TCN the remote VTEP flood arriving in local VTEP will get flooded in L3VNI VLAN instead of user VLAN even though routes exist in L2RIB/HMM.</p> <p>Workarounds: L3VNI VLAN should never get allowed in the downstream VLAN this will prevent the un-necessary flooding.</p>
CSCvw24004	<p>Headline: SVI goes down as soon as access interfaces goes down and only flex link stays up</p> <p>Symptoms: SVI interface can go down when corresponding VLAN is active (forwarded by) on FlexLink only.</p> <p>Workarounds: In order to restore SVI state, you will need to shutdown/no shutdown it.</p>
CSCvw34161	<p>Headline: Deleted port-profiles appear in CLI with show port-profile name command</p> <p>Symptoms: You can see deleted port-profiles with " show port-profile name ?" command</p> <p>Workarounds: software downgrade to 7.x</p>
CSCvw34566	<p>Headline: NXOS rfc1583compatibility not consistent with IOS/XE implementation</p> <p>Symptoms: NXOS by default supports rfc2328. To support inter-op with the devices which supports rfc1583 NXOS provides configuration option " rfc1583compatibility" . This makes NXOS to follow rfc1583. When NXOS devices operating in rfc1583compatibility mode it may choose a different path to ASBR compare to IOS/XE. There is no concern if " rfc1583compatibility" is not configured.</p> <p>Workarounds: Use RFC2328 throughout the network instead</p>
CSCvw41524	<p>Headline: LACP hot-standby after exiting maintenance-mode</p> <p>Symptoms: When exiting from maintenance-mode to normal-mode, a subset of port-channels on the switch may be stuck in hot-standby state.</p> <p>Workarounds: Shut / no shut affected ports.</p>
CSCvw43139	<p>Headline: after changing VPC HIF ports to orphan, Flood traffic crossing MCT does not egress HIF</p> <p>Symptoms: + HIF ports are configured as VPCs members.+ after changing the config in a certain way to be orphan ports.+ broadcast traffic are not egressing hif ports and causing disconnection.+ any broadcast traffic ingressing peer-link will not forwarded to orphan ports which were members of vpcs before</p> <p>Workarounds: Reconfigure the ports.</p>
CSCvw43442	<p>Headline: VXLAN: MAC address learned on Fabric Layer3 interfaces</p> <p>Symptoms: MAC address learnt on a L3 Fabric interface of VXLAN EVPN Border Gateway (BGW) switch. As result, MAC address may move between the L3 interface and NVE interface and eventually gets `Permanently-Frozen` on one of the leaf.</p> <p>Workarounds: None. Excessive MAC move will cause software to permanently keep the MAC in frozen state. On L3 interface MAC learning shouldn't happen and MAC frozen state doesn't impact L3 forwarding</p>

Bug ID	Description
CSCvw48498	<p>Headline: N9K - NXAPI : %SAFE_STR CONSTRAINT: strncpy_s: slen is zero, error code=401</p> <p>Symptoms: Viewing following error message : ?%SAFE_STR CONSTRAINT: strncpy_s: slen is zero, error code=401? into /var/sysmgr_nxapi/logs/error.log file</p> <p>Workarounds: From bash mode, clear the content of the error.log manually by echo-ing empty string inside the file.(To get into bash mode - have the bash feature enabled and run bash to get inside)bash-4.3\$ echo "" > /var/sysmgr_nxapi/logs/error.log</p>
CSCvw49456	<p>Headline: Nexus switch " ipfib" crash</p> <p>Symptoms: A Nexus switch might experience an IPFIB crash</p> <p>Workarounds: No known workaround</p>
CSCvw50234	<p>Headline: NX93180LC - GLC-TEs not working after upgrade to 9.3.5 (not connected) on even ports only</p> <p>Symptoms: GLC-TE transceiver stays in not connected state after upgrade to 9.3.5 on even ports (i.e. eth1/20). Odd ports are working fine (i.e. eth1/19)513E-C.06-N9K-C93180LC-EX# sh int eth1/20Ethernet1/20 is down (Link not connected)513E-C.06-N9K-C93180LC-EX# sh int eth1/20 transceiver Ethernet1/20 transceiver is present type is 1000base-T name is CISCO part number is SBCU-5740ARZ-CS1 revision is G3.1 serial number is AVC204822X4 nominal bitrate is 1300 MBit/sec Link length supported for copper is 100 m cisco id is 3 cisco extended id number is 4 cisco part number is 30-1475-01 cisco product id is GLC-TE cisco version id is V01</p> <p>Workarounds: downgrade to nxos.7.0.3.17.X</p>
CSCvw51632	<p>Headline: N9K-C93180YC-FX3S: Observing PTP port flap which is connected to STU(GM)</p> <p>Symptoms: In scale environment, customer is facing port flap issue and due to this their cell site operation got impacted.</p> <p>Workarounds: Reduce the no.of master ports below 25 and do fine tuning of policer operation, so that policer wont discard ptp pkts.</p>
CSCvw53323	<p>Headline: CAP_FEATURE_MULTIHOP_BFD capability is not getting removed from the system after disabling BFD</p> <p>Symptoms: Switch gives an error during downgrade if BFD feature is directly disabled, instead of removing the multihop BFD configuration. CAP_FEATURE_MULTIHOP_BFD capability is not getting removed from the system and hence causing error. Ideally all the BFD related capabilities should have been deleted when feature is disabled.</p> <p>Workarounds: Following workaround can be used by customer to overcome this1.Enable BFD " feature bfd" 2.Add Multihop BFD configuration " bfd multihop interval 500 min_rx 500 multiplier 5" 3.*Delete Multihop BFD configuration " no bfd multihop interval 500 min_rx 500 multiplier 5" 4.Disable BFD " no feature bfd".</p>
CSCvw53976	<p>Headline: Incorrect Forwarding on Hardware. VXLAN Flood & Learn. IPFIB process stuck and MTS queue build up.</p> <p>Symptoms: Traffic forwarded incorrectly to other interfaces. Traffic that should be punted to CPU is getting VXLAN encapsulated. show forwarding commands do not work. show tech I3 forwarding generates no output. show ip mroute for underlay mcast shows pending routes. Messages stuck on queue for ipfib.</p> <p>Workarounds: Passive-interface for SVIs shared between spines to avoid creating an IGP adjacency between SPINES over VXLAN and reload if mts suck in queue.</p>

Bug ID	Description																												
CSCvw56696	<p>Headline: NXOS: VLAN Manager crashes with VLAN mapping configuration change</p> <p>Symptoms: The VLAN Manager (vlan_mgr) service reports a crash and a core file is saved.</p> <p>Workarounds: None</p>																												
CSCvw59799	<p>Headline: Hairpin of L2 multicast NLB KA frames on the same interface it was received</p> <p>Symptoms: NLB KA packets, received on a VPC Po are hair-pining and exiting the same interface they were received on.</p> <p>Workarounds: - Disable IGMP snooping</p>																												
CSCvw60409	<p>Headline: HSRP vmac is not cleared and remains as static entry after shutting down SVI.</p> <p>Symptoms: On N9k switch running HSRP, when SVI is shut down on active HSRP switch, HSRP vmac is not cleared and remains as static entry. This may cause traffic disruption.</p> <p>Workarounds: remove HSRP configurations from SVI then shut down SVI. switch(config-if)# no hsrp 1 ipv4switch(config-if)# no hsrp 1 ipv6</p>																												
CSCvw60736	<p>Headline: N9K-C9348GC link up delay after reloaded</p> <p>Symptoms: After vPC peer reloaded, vPC member port linkup delay than the other end, which lead to packet loss when using channel group mode on.</p> <p>Workarounds: none</p>																												
CSCvw65224	<p>Headline: N9K-PAC-650W for N9k reporting Fail/Shut status</p> <p>Symptoms: The below Syslog will be seen on the switch: %KERN-3-SYSTEM_MSG: [6960403.222450] cctrlib_tor2_get_psu_env_info.557: PSU 1 failed to read CCTRL_PSU_READ_VIN (3 =>2.58.88.2) - kernelSyslog can be seen also for PSU 0 slot. The output of show environment will be as follows with either one or both of the PSUs showing the fail/shut state:# sh env powerPower Supply:Voltage: 12 VoltsPower Actual</p> <table><thead><tr><th>Actual</th><th>TotalSupply</th><th>Model</th><th>Output</th><th>Input</th><th>Capacity</th><th>Status</th></tr><tr><th>(Watts)</th><th>(Watts)</th><th>(Watts)</th><th>-----</th><th>-----</th><th>-----</th><th>-----</th></tr></thead><tbody><tr><td>-----1</td><td></td><td>N9K-PAC-650W</td><td>0 W</td><td>0 W</td><td>0 W</td><td>0 W Fail/Shut2</td></tr><tr><td>N9K-PAC-650W</td><td>0 W</td><td>0 W</td><td>0 W</td><td>Fail/Shut</td><td></td><td></td></tr></tbody></table> <p>Workarounds: None</p>	Actual	TotalSupply	Model	Output	Input	Capacity	Status	(Watts)	(Watts)	(Watts)	-----	-----	-----	-----	-----1		N9K-PAC-650W	0 W	0 W	0 W	0 W Fail/Shut2	N9K-PAC-650W	0 W	0 W	0 W	Fail/Shut		
Actual	TotalSupply	Model	Output	Input	Capacity	Status																							
(Watts)	(Watts)	(Watts)	-----	-----	-----	-----																							
-----1		N9K-PAC-650W	0 W	0 W	0 W	0 W Fail/Shut2																							
N9K-PAC-650W	0 W	0 W	0 W	Fail/Shut																									
CSCvw66557	<p>Headline: EOR - default v6 route not correctly programmed in hw with template-service-provider</p> <p>Symptoms: Traffic that hitting default v6 route is forwarded in software. This can cause packet drop for traffic using v6 default route due to sw switching and CoPP</p> <p>Workarounds: If using IPv6 static route:* Add and remove static route after device reload. If using IPv6 dynamic route:* Add a more specific IPv6 route for the affected prefix(es)</p>																												
CSCvw66611	<p>Headline: N9k: Incrementing IntMacRx-Er Errors</p> <p>Symptoms: IntMacRx-Er errors are being incremented on the N9k interfaces when receiving frames with the actual number of bytes in the payload not being equal to the value in their Ethernet Length field.</p> <p>Workarounds:</p>																												

Bug ID	Description
CSCvw66700	<p>Headline: N3600/N9500-R does not send arp request for glean vxlan encapsulated IP traffic</p> <p>Symptoms: Missing ARP entry for connected NSX vtep.</p> <p>Workarounds: Use ping from nxos switch towards connected NSX host to resolve its ARP.</p>
CSCvw68897	<p>Headline: segmentation fault on call home service turn on after enabling smart license</p> <p>Symptoms: + Below logs</p> <pre> 2020 Dec 2 19:42:14 R3-USFWT-05-LF1 %LICMGR-5-LOG_SMART_LIC_EVAL_START: (pid=2294) Entering evaluation period 2020 Dec 2 19:42:16 R3-USFWT-05-LF1 last message repeated 1 time 2020 Dec 2 19:42:16 R3-USFWT-05-LF1 %SYSMGR-2-SERVICE_CRASHED: Service "licmgr" (PID 2294) hasn't caught signal 11 (core will be saved). 2020 Dec 2 19:42:16 R3-USFWT-05-LF1 %CALLHOME-2-EVENT: SW_CRASH 2020 Dec 2 19:42:16 R3-USFWT-05-LF1 %LICMGR-5-LOG_SMART_LIC_EVAL_START: (pid=26014) Entering evaluation period 2020 Dec 2 19:42:17 R3-USFWT-05-LF1 last message repeated 1 time 2020 Dec 2 19:42:17 R3-USFWT-05-LF1 %LICMGR-5-LOG_SMART_LIC_COMM_RESTORED: (pid=26014) Communications with the Cisco Smart Software Manager or satellite restored 2020 Dec 2 19:43:36 R3-USFWT-05-LF1 %SYSMGR-2-SERVICE_CRASHED: Service "licmgr" (PID 26014) hasn't caught signal 6 (core will be saved). 2020 Dec 2 19:43:37 R3-USFWT-05-LF1 %LICMGR-5-LOG_SMART_LIC_EVAL_START: (pid=6479) Entering evaluation period 2020 Dec 2 19:43:38 R3-USFWT-05-LF1 last message repeated 1 time 2020 Dec 2 19:43:38 R3-USFWT-05-LF1 %LICMGR-5-LOG_SMART_LIC_COMM_RESTORED: (pid=6479) Communications with the Cisco Smart Software Manager or satellite restored 2020 Dec 2 19:43:44 R3-USFWT-05-LF1 %VSHD-5-VSHD_SYSLOG_CONFIG_I: Configured from vty by <user> on <ip>@pts/4 2020 Dec 2 19:44:47 R3-USFWT-05-LF1 %UFD-3-FIB_IPv4_ADJ_CONSISTENCY_CHECKER_PASS: FIB IPv4 adjacency consistency checker PASSED on slot 1 2020 Dec 2 19:44:47 R3-USFWT-05-LF1 %UFD-3-FIB_IPv4_ROUTE_CONSISTENCY_CHECKER_PASS: FIB IPv4 route consistency checker PASSED on slot 1 2020 Dec 2 19:45:16 R3-USFWT-05-LF1 %CALLHOME-2-EVENT: SW_CRASH licmgr in slot 1 crashed with crash type : stateful crash 2020 Dec 2 20:24:48 R3-USFWT-05-LF1 %VSHD-5-VSHD_SYSLOG_CONFIG_I: Configured from vty by A1264370-3 on <ip>@pts/4 2020 Dec 2 20:28:32 R3-USFWT-05-LF1 %LICMGR-3-LOG_SMART_LIC_AGENT_REG_FAILED: (pid=6479) Smart Agent for Licensing Registration with the Cisco Smart Software Manager or satellite failed: Response error: The product '<id>' and sudi { udi_pid: nil+licmgr cores generated show core VDC Module Instance Process-name PID Date(Year-Month-Day Time)--- -----1 1 1 licmgr 2294 2020-12-02 19:42:43 1 1 licmgr 26014 2020-12-02 19:43:54 </pre> <p>Workarounds: None</p>
CSCvw69648	<p>Headline: 'vpc orphan-port suspend' configuration can't be removed on interfaces associated to vPC PO</p> <p>Symptoms: 'vpc orphan-port suspend' configuration can't be removed on interfaces associated to vPC port-channel.</p> <p>Workarounds:</p> <ol style="list-style-type: none"> 1) the physical interface needs to be removed from the vPC PO 2) the " vpc orphan-port suspend" command can now be removed from the physical interface 3) Re-add the physical interface to the vPC PO
CSCvw73129	<p>Headline: N9k switches ending with EX/FX/FX2/FX3/GX / ASICs ELAM - Unknown Unicast brief report doesn't indicate L2 miss</p> <p>Symptoms: ELAM outgoing interface may print an index giving an impression of unicast forwarding while traffic is L2 flood</p> <p>Workarounds: Refer to ELAM full report for FLOOD MISS bit set:report detail egrep " FLOOD MISS"</p>

Bug ID	Description
CSCvw73676	<p>Headline: Nexus 9K - Unable To Boot NXOS Version 9.x From USB</p> <p>Symptoms: + On Nexus 9K, when attempting to boot NXOS version 9.x from USB via the loader prompt you may see the output below, followed by getting kicked back to the loader prompt.=====Bootable Disk is detected. Device Name: Micron_1100_MTFDDAV256TBNVersion 2.18.1260. Copyright (C) 2020 American Megatrends, Inc. FPGA SPI Flash Micron(Numonyx) N25Q128Board type 4IOFPGA @ 0xd8000000SLOT_ID @ 0xfSet fan speed to 60% Filesystem type is ext2fs, partition type 0x83ACI chassisTrying to read config file /boot/grub/menu.lst.local from (hd0,0) Filesystem type is fat, partition type 0xcTrying to read config file /boot/grub/menu.lst.local from (hd1,4) Filesystem type is ext2fs, partition type 0x83Trying to read config file /boot/grub/menu.lst.local from (hd1,5) Filesystem type is ext2fs, partition type 0x83Auto boot configuration file is absent.Autoboot image boot failed. Trying recovery imageTrying to read config file /boot/grub/menu.lst.recovery from (hd1,4) Filesystem type is ext2fs, partition type 0x83Trying to read config file /boot/grub/menu.lst.recovery from (hd1,5) Filesystem type is ext2fs, partition type 0x83Auto boot configuration file is absent.No autoboot or failed autoboot. falling to loader=====</p> <p>Workarounds:</p> <ol style="list-style-type: none"> 1. Have 7.x and 9.x NXOS versions on USB 2. In loader, boot 7.x version from USB 3. Once successfully booted in 7.x, copy the 9.x image file from USB to bootflash via the "copy" command 4. Modify the boot statements from the 7.x image to the 9.x image using the "boot" command 5. Reload the switch to boot to the 9.x image
CSCvw76165	<p>Headline: N9500:other end port of mgmt port with shutdown force is up</p> <p>Symptoms: Other end port of mgmt port on N9500 SUP is up even though shutdown force is configured on mgmt port.</p> <p>Workarounds: Remove "shutdwon force" and configure "shutdown force" again on mgmt 0</p>
CSCvw76953	<p>Headline: ip routing multicast holddown 0 does not propagate in running config</p> <p>Symptoms: When trying to configure "ip routing multicast holddown 0" command, it does not propagate to running config.</p> <p>Workarounds: It looks like problem is happening only for fresh configuration. Remove/Re-apply of the 'ip routing multicast holddown 0' should solve the problem.</p>
CSCvw78632	<p>Headline: N9K-C93180YC-FX3S: Wrong delivery order and incorrect Timestamp(T1) carried by Follow-up pkt</p> <p>Symptoms: TOR switch(BC) port that the T1 timestamps carried in Follow-up pkts towards O-DU are behind in time w.r.t the Delay Response packets which are received before Follow-up pkt. Because of this the end offset computed by ptp4l servo goes high and this is screwing up the time and impacting the cell operations/sectors on O-DU.</p> <p>Workarounds: No workaround, Dev is debugging the issue.</p>
CSCvw80210	<p>Headline: On N9K-C9332C - 100G macsec links stop forwarding traffic</p> <p>Symptoms: On N9K-C9332C - 100G macsec links stop forwarding traffic after some time (depending on the traffic rate)which results in LACP suspend and connectivity loss</p> <p>Workarounds:</p> <ol style="list-style-type: none"> 1) Configure XPN Cipher-suite instead of non-xpnWorkaound 2) Configure "sak-rekey-time 300" under macsec security policy

Bug ID	Description
CSCvw81106	<p>Headline: STOMP generated on 9300-FX2 when using 1G xcvr</p> <p>Symptoms: In a VxLAN fabric with -FX2 devices as leaf, packets over 740 bytes are not correctly forwarded over the fabric.</p> <p>Workarounds: Use 10G xcvr in between Leaf and Spine</p>
CSCvw83503	<p>Headline: Nexus 9000 forwards ARP traffic received on suspended interface, causing Layer 2 loop</p> <p>Symptoms: A Nexus 9000 switch running NX-OS software release 9.3(6) may begin forwarding ARP traffic received on a physical interface that is configured to be a member of an LACP port-channel, even though the physical interface is suspended from the port-channel for not receiving LACPDUs.</p> <p>Workarounds:</p> <ol style="list-style-type: none"> 1. Administratively shut down the suspended port-channel member. 2. Reconfigure the remote network device such that the remote network device's interface sends LACPDUs as expected. This will bring the suspended port-channel member out of a suspended state.
CSCvw84453	<p>Headline: src_mac is 00:00:00:00:00:00 after PBR routing after rebooting of one Nexus in VPC pair</p> <p>Symptoms: src_mac is 00:00:00:00:00:00 after PBR routing after rebooting of one Nexus in VPC pair</p> <p>Workarounds:</p> <ol style="list-style-type: none"> 1. Link shutdown/no shutdown 2.Delete/create static MAC
CSCvw86078	<p>Headline: N9k switches ending with EX/FX/FX2/FX3/GX - DHCP Binding lease will not refresh</p> <p>Symptoms: If have approximate 2000 dhcp snooping entries in N9K after reloading the dhcp snooping binding will not refresh.</p> <p>Workarounds: Remove DHCP binding and re-configure</p>
CSCvw92365	<p>Headline: Next Hop v6 Filter does not work properly on the show ip route output.</p> <p>Symptoms: show ip route next-hop-v6 X:X:X:X not only shows ipv6 next-hop routes but also ipv4 routes.</p> <p>Workarounds: NA</p>
CSCvw92732	<p>Headline: Vfc interface mode can't be set to E</p> <p>Symptoms: VFC interface port mode config is not configurable as E. This is the expected behaviour. Currently, there is no support for PORT mode E for vfc links.</p> <p>Workarounds: There is no workaround. This is expected behaviour.</p>
CSCvw94313	<p>Headline: N9k: port-security does not effect on the VPC port-channel</p> <p>Symptoms: N9k: Port-security does not effect on the VPC port-channel. Violated traffic can pass though</p> <p>Workarounds: NA</p>

Bug ID	Description
CSCvx01231	<p>Headline: Enh: Add more debug capability for N9K EOR PSU flap</p> <p>Symptoms: N9K EOR PSU went down and came up in 1-2 sec. Randomly happens 1 flap in months or a year.</p> <p>Workarounds: None</p>
CSCvx02717	<p>Headline: After upgrade 9.x N9k cannot be downgraded via install all</p> <p>Symptoms: Upgrade from 9.3(3) to 9.3(6) then when testing downgrade back via "install all" there are incompatibilities that prevent the downgrade: N9K-C9336-FX2-Z-PI</p> <p>Workarounds: Write erase, reload, then downgrade of the N9k via "install all"</p>
CSCvx04061	<p>Headline: Incorrect NIV programming after changing from VPC HIF to orphan port</p> <p>Symptoms: Traffic traversing vPC peer-link in communication with orphan host connected behind single homed FEX is dropped. ELAM report will show the following drop reason: UC_DF_CHECK_FAILURE</p> <p>Workarounds: None</p>
CSCvx07013	<p>Headline: no negotiate auto command missing after upgrade to 7.0(3)I7(9)</p> <p>Symptoms: When upgrading from 7.0(3)I7(6) to 7.0(3)I7(9), the command "no negotiate auto" is missing from the interfaces: version 7.0(3)I7(6) Bios: version 08.36 interface Ethernet1/2 switchport speed 1000 no negotiate auto no shutdown BRU-N9K5-7# show run int eth2/1! Command: show running-config interface Ethernet2/1! No configuration change since last restart! Time: Mon Nov 30 00:46:00 2020 version 7.0(3)I7(9) Bios: version 08.36 interface Ethernet2/1 switchport speed 1000 no shutdown This caused the interfaces in customer setup to go down and we have to manually configure "no negotiate auto" under the interface configuration to recover.</p> <p>Workarounds: We have to manually configure "no negotiate auto" under the interface configuration to recover.</p>
CSCvx09137	<p>Headline: Nexus 9K Linecard Memory Leak in /tmp/logs/l2mcast_lib.log</p> <p>Symptoms: A Nexus 9k switch running NX-OS 9.3(6) may begin printing the below logs indicating one of the linecards has high memory usage in a tmp directory: %SYSMGR-SLOTX-2-TMP_DIR_FULL: System temporary directory usage is unexpectedly high at 100%. In addition, if you attach into the impacted linecard and run "show system internal flash", the "aufs" filesystem will be fully used: SWITCH# attach module x module-x# show system internal flash <snip> aufs 2097152 2097152 0 100% /lc Finally, when checking the filesystem more thoroughly via the bash shell, a file at "/tmp/logs/l2mcast_lib.log" will be growing abnormally large (replace "x" in "login lc" with the slot number of the impacted linecard): SWITCH# conf t SWITCH(config)# feature bash SWITCH(config)# exit SWITCH# run bash bash-4.2\$ sudo bash bash-4.2# rlogin lc root@lc:/# ls -la /tmp/logs total 15400 drwxr-xr-x 2 root floppy 60 Jan 1 12:22 . drwxrwxrwx 3 root floppy 600 Jan 1 15:22 .. -rw-rw-rw- 1 root root 15766000 Jan 1 15:44 l2mcast_lib.log <=====</p> <p>Workarounds: The offending file can be periodically deleted, eg: every 24 hours, via a very basic shell script (replace the "x" in "lc" with the slot number of the impacted linecard): conf t feature bash exit run bash rlogin lc while [True]; do echo "Deleting l2mcast_lib.log..."; rm /tmp/logs/l2mcast_lib.log; sleep 86400; done & exit</p>

Bug ID	Description
CSCvx19094	<p>Headline: 36180 may experience system power loss during ATS switchover</p> <p>Symptoms: On 36180, during ATS switchover, the system may reload during the momentarily loss of power as ATS is finishing the switch.</p> <p>Workarounds: None (issue is only seen during ATS switch)</p>

Known Issues

Bug ID	Description
CSCvi73973	<p>Error message is seen rarely when a huge file (greater than 1GB) is copied to the USB first time after reload.</p> <p>There is no functional impact to the copy command itself.</p>
CSCvj74453	<p>If you enable and disable a feature using a script in one VSH terminal session and execute those feature related commands in another terminal session, the behavior is unpredictable. Configuring and deleting the same parser chain in multiple VSH sessions is not supported. You must refrain from entering feature specific show CLI commands from a different VSH session when the same feature is being disabled in another terminal session.</p> <p>Doing so might even result in a VSH crash. There is no functional impact or SSO or reload due to this crash.</p>
CSCvp19886	During re-key when conf_offset for a macsec policy is updated dynamically, packet drop for ~100ms is observed. This is a known hardware limitation.
CSCvx05248	When running debug tool, ethanalyzer autostop duration does not work and does not automatically stop the packet capture. This is an expected behavior.
N/A	LXC ISSU will not be supported for N9K-C92348GC switch.

Device Hardware

The following tables list the Cisco Nexus 9000 Series hardware that Cisco NX-OS Release 10.1(1) supports. For additional information about the supported hardware, see the Hardware Installation Guide for your Cisco Nexus 9000 Series device.

Table 1.	Cisco Nexus 9500 Switches	29
Table 2.	Cisco Nexus 9500 Cloud Scale Line Cards	29
Table 3.	Cisco Nexus 9500 R-Series Line Cards	29
Table 4.	Cisco Nexus 9500 Cloud Scale Fabric Modules	30
Table 5.	Cisco Nexus 9500 R-Series Fabric Modules	30
Table 6.	Cisco Nexus 9500 Supervisor Modules	30
Table 7.	Cisco Nexus 9500 System Controller	31
Table 8.	Cisco Nexus 9500 Fans and Fan Trays	31
Table 9.	Cisco Nexus 9500 Fabric Module Blanks with Power Connector	31
Table 10.	Cisco Nexus 9500 Power Supplies	31
Table 11.	Cisco Nexus 9200 and 9300 Switches	32
Table 12.	Cisco Nexus 9200 and 9300 Fans and Fan Trays	33
Table 13.	Cisco Nexus 9200 and 9300 Power Supplies	34

Table 14. Cisco Nexus 9500 Cloud Scale Line Cards.....	36
Table 15. Cisco Nexus 9500 R-Series Line Cards.....	37

Table 1. Cisco Nexus 9500 Switches

Product ID	Description
N9K-C9504	7.1-RU modular switch with slots for up to 4 line cards in addition to two supervisors, 2 system controllers, 3 to 6 fabric modules, 3 fan trays, and up to 4 power supplies.
N9K-C9508	13-RU modular switch with slots for up to 8 line cards in addition to two supervisors, 2 system controllers, 3 to 6 fabric modules, 3 fan trays, and up to 8 power supplies.
N9K-C9516	21-RU modular switch with slots for up to 16 line cards in addition to two supervisors, 2 system controllers, 3 to 6 fabric modules, 3 fan trays, and up to 10 power supplies.

Table 2. Cisco Nexus 9500 Cloud Scale Line Cards

Product ID	Description	Maximum Quantity		
		Cisco Nexus 9504	Cisco Nexus 9508	Cisco Nexus 9516
N9K-X9716D-GX	Cisco Nexus 9500 16-port 400-Gigabit Ethernet QSFP line card	4	8	N/A
N9K-X9736C-FX	Cisco Nexus 9500 36-port 40/100 Gigabit Ethernet QSFP28 line card	4	8	16
N9K-X9788TC-FX	Cisco Nexus 9500 48-port 1/10-G BASE-T Ethernet and 4-port 40/100 Gigabit Ethernet QSFP28 line card	4	8	16
N9K-X97160YC-EX	Cisco Nexus 9500 48-port 10/25-Gigabit Ethernet SFP28 and 4-port 40/100 Gigabit Ethernet QSFP28 line card	4	8	16
N9K-X9732C-FX	Cisco Nexus 9500 32-port 40/100 Gigabit Ethernet QSFP28 line card	4	8	16
N9K-X9732C-EX	Cisco Nexus 9500 32-port 40/100 Gigabit Ethernet QSFP28 line card	4	8	16
N9K-X9736C-EX	Cisco Nexus 9500 36-port 40/100 Gigabit Ethernet QSFP28 line card	4	8	16

Table 3. Cisco Nexus 9500 R-Series Line Cards

Product ID	Description	Maximum Quantity	
		Cisco Nexus 9504	Cisco Nexus 9508
N9K-X9636C-R	Cisco Nexus 9500 36-port 40/100 Gigabit Ethernet QSFP28 line card	4	8

Product ID	Description	Maximum Quantity	
		Cisco Nexus 9504	Cisco Nexus 9508
N9K-X9636C-RX	Cisco Nexus 9500 36-port 40/100 Gigabit Ethernet QSFP28 line card	4	8
N9K-X9636Q-R	Cisco Nexus 9500 36-port 40 Gigabit Ethernet QSFP line card	4	8
N9K-X96136YC-R	Cisco Nexus 9500 16-port 1/10 Gigabit, 32-port 10/25 Gigabit, and 4-port 40/100 Gigabit Ethernet line card	4	8

Table 4. Cisco Nexus 9500 Cloud Scale Fabric Modules

Product ID	Description	Minimum	Maximum
N9K-C9504-FM-E	Cisco Nexus 9504 100-Gigabit cloud scale fabric module	4	5
N9K-C9504-FM-G	Cisco Nexus 9500 4-slot 1.6Tbps cloud scale fabric module	4	5
N9K-C9508-FM-E	Cisco Nexus 9508 100-Gigabit cloud scale fabric module	4	5
N9K-C9508-FM-E2	Cisco Nexus 9508 100-Gigabit cloud scale fabric module	4	5
N9K-C9508-FM-G	Cisco Nexus 9500 8-slot 1.6Tbps cloud-scale fabric module	4	5
N9K-C9516-FM-E2	Cisco Nexus 9516 100-Gigabit cloud scale fabric module	4	5

Table 5. Cisco Nexus 9500 R-Series Fabric Modules

Product ID	Description	Minimum	Maximum
N9K-C9504-FM-R	Cisco Nexus 9504 100-Gigabit R-Series fabric module	4	6
N9K-C9508-FM-R	Cisco Nexus 9508 100-Gigabit R-Series fabric module	4	6

Table 6. Cisco Nexus 9500 Supervisor Modules

Supervisor	Description	Quantity
N9K-SUP-A	1.8-GHz supervisor module with 4 cores, 4 threads, and 16 GB of memory	2
N9K-SUP-A+	1.8-GHz supervisor module with 4 cores, 8 threads, and 16 GB of memory	2
N9K-SUP-B	2.2-GHz supervisor module with 6 cores, 12 threads, and 24 GB of memory	2

Supervisor	Description	Quantity
N9K-SUP-B+	1.9-GHz supervisor module with 6 cores, 12 threads, and 32 GB of memory	2

Note: N9K-SUP-A and N9K-SUP-A+ are not supported on Cisco Nexus 9504 and 9508 switches with -R line cards.

Table 7. Cisco Nexus 9500 System Controller

Product ID	Description	Quantity
N9K-SC-A	Cisco Nexus 9500 Platform System Controller Module	2

Table 8. Cisco Nexus 9500 Fans and Fan Trays

Product ID	Description	Quantity
N9K-C9504-FAN	Fan tray for 4-slot modular chassis	3
N9K-C9504-FAN2	Fan tray that supports the Cisco N9K-C9504-FM-G fabric module	3
N9K-C9508-FAN	Fan tray for 8-slot modular chassis	3
N9K-C9508-FAN2	Fan tray that supports the Cisco N9K-C9508-FM-G fabric module	3
N9K-C9516-FAN	Fan tray for 16-slot modular chassis	3

Table 9. Cisco Nexus 9500 Fabric Module Blanks with Power Connector

Product ID	Description	Minimum	Maximum
N9K-C9504-FAN-PWR	Nexus 9500 4-slot chassis 400G cloud scale fan tray power connector	1	2
N9K-C9508-FAN-PWR	Nexus 9500 4-slot chassis 400G cloud scale fan tray power connector	1	2

Table 10. Cisco Nexus 9500 Power Supplies

Product ID	Description	Quantity	Cisco Nexus Switches
N9K-PAC-3000W-B	3 KW AC power supply	Up to 4 Up to 8 Up to 10	Cisco Nexus 9504 Cisco Nexus 9508 Cisco Nexus 9516
N9K-PDC-3000W-B	3 KW DC power supply	Up to 4 Up to 8 Up to 10	Cisco Nexus 9504 Cisco Nexus 9508 Cisco Nexus 9516
N9K-PUV-3000W-B	3 KW Universal AC/DC power supply	Up to 4 Up to 8 Up to 10	Cisco Nexus 9504 Cisco Nexus 9508 Cisco Nexus 9516

Product ID	Description	Quantity	Cisco Nexus Switches
N9K-PUV2-3000W-B	3.15-KW Dual Input Universal AC/DC Power Supply	Up to 4 Up to 8 Up to 10	Cisco Nexus 9504 Cisco Nexus 9508 Cisco Nexus 9516

Table 11. Cisco Nexus 9200 and 9300 Switches

Cisco Nexus Switch	Description
N9K-C9316D-GX	1-RU switch with 16x400/100/40-Gbps ports.
N9K-C9364C-GX	2-RU fixed-port switch with 64 100-Gigabit SFP28 ports.
N9K-C93600CD-GX	1-RU fixed-port switch with 28 10/40/100-Gigabit QSFP28 ports (ports 1-28), 8 10/40/100/400-Gigabit QSFP-DD ports (ports 29-36)
N9K-C9364C	2-RU Top-of-Rack switch with 64 40-/100-Gigabit QSFP28 ports and 2 1-/10-Gigabit SFP+ ports. <ul style="list-style-type: none"> - Ports 1 to 64 support 40/100-Gigabit speeds. - Ports 49 to 64 support MACsec encryption. Ports 65 and 66 support 1/10 Gigabit speeds.
N9K-C9332C	1-RU fixed switch with 32 40/100-Gigabit QSFP28 ports and 2 fixed 1/10-Gigabit SFP+ ports.
N9K-C93180YC-FX3	48 1/10/25 Gigabit Ethernet SFP28 ports (ports 1-48) 6 10/25/40/50/100-Gigabit QSFP28 ports (ports 49-54)
N9K-C93180YC-FX3S	48 1/10/25 Gigabit Ethernet SFP28 ports (ports 1-48) 6 10/25/40/50/100-Gigabit QSFP28 ports (ports 49-54)
N9K-C9336C-FX2-E	1- RU switch with 36 40-/100-Gb QSFP28 ports
N9K-C9336C-FX2	1-RU switch with 36 40-/100-Gb Ethernet QSFP28 ports
N9K-C93360YC-FX2	2-RU switch with 96 10-/25-Gigabit SFP28 ports and 12 40/100-Gigabit QSFP28 ports
N9K-C93240YC-FX2	1.2-RU Top-of-Rack switch with 48 10-/25-Gigabit SFP28 fiber ports and 12 40-/100-Gigabit Ethernet QSFP28 ports.
N9K-C93216TC-FX2	2-RU switch with 96 100M/1G/10G RJ45 ports, 12 40/100-Gigabit QSFP28 ports, 2 management ports (one RJ-45 and one SFP port), 1 console, port, and 1 USB port.
N9K-C93180YC-FX	1-RU Top-of-Rack switch with 10-/25-/32-Gigabit Ethernet/FC ports and 6 40-/100-Gigabit QSFP28 ports. You can configure the 48 ports as 1/10/25-Gigabit Ethernet ports or as FCoE ports or as 8-/16-/32-Gigabit Fibre Channel ports.
N9K-C93180YC-FX-24	1-RU 24 1/10/25-Gigabit Ethernet SFP28 front panel ports and 6 fixed 40/100-Gigabit Ethernet QSFP28 spine-facing ports. The SFP28 ports support 1-, 10-, and 25-Gigabit Ethernet connections and 8-, 16-, and 32-Gigabit Fibre Channel connections.
N9K-C93108TC-FX	1-RU Top-of-Rack switch with 48 100M/1/10GBASE-T (copper) ports and 6 40-/100-Gigabit QSFP28 ports

Cisco Nexus Switch	Description
N9K-C93108TC-FX-24	1-RU 24 1/10GBASE-T (copper) front panel ports and 6 fixed 40/100-Gigabit Ethernet QSFP28 spine-facing ports.
N9K-C93108TC-FX3P	1-RU fixed-port switch with 48 100M/1/2.5/5/10GBASE-T ports and 6 40-/100-Gigabit QSFP28 ports
N9K-C9348GC-FXP	Nexus 9300 with 48p 100M/1 G, 4p 10/25 G SFP+ and 2p 100 G QSFP
N9K-C92348GC-X	The Cisco Nexus 92348GC-X switch (N9K-C92348GC-X) is a 1RU switch that supports 696 Gbps of bandwidth and over 250 mpps. The 1GBASE-T downlink ports on the 92348GC-X can be configured to work as 100-Mbps, 1-Gbps ports. The 4 ports of SFP28 can be configured as 1/10/25-Gbps and the 2 ports of QSFP28 can be configured as 40- and 100-Gbps ports. The Cisco Nexus 92348GC-X is ideal for big data customers that require a Gigabit Ethernet ToR switch with local switching.
N9K-C93180YC-EX	1-RU Top-of-Rack switch with 48 10-/25-Gigabit SFP28 fiber ports and 6 40-/100-Gigabit QSFP28 ports
N9K-C93180YC-EX-24	1-RU 24 1/10/25-Gigabit front panel ports and 6-port 40/100 Gigabit QSFP28 spine-facing ports
N9K-C93108TC-EX	1-RU Top-of-Rack switch with 48 10GBASE-T (copper) ports and 6 40-/100-Gigabit QSFP28 ports
N9K-C93108TC-EX-24	1-RU 24 1/10GBASE-T (copper) front panel ports and 6 40/100-Gigabit QSFP28 spine facing ports.

Table 12. Cisco Nexus 9200 and 9300 Fans and Fan Trays

Product ID	Description	Quantity	Cisco Nexus Switches
NXA-FAN-160CFM-PE	Fan module with port-side exhaust airflow (blue coloring)	3	9364C ^a 93360YC-FX2
NXA-FAN-160CFM-PI	Fan module with port-side intake airflow (burgundy coloring)	3	9364C ^a 93360YC-FX2
NXA-FAN-160CFM2-PE	Fan module with port-side exhaust airflow (blue coloring)	4	9364C-GX
NXA-FAN-160CFM2-PI	Fan module with port-side intake airflow (burgundy coloring)	4	9364C-GX
NXA-FAN-30CFM-B	Fan module with port-side intake airflow (burgundy coloring)	3	93108TC-EX 93108TC-FX ^a 93180YC-EX 93180YC-FX ^a 9348GC-FXP ^a
NXA-FAN-30CFM-F	Fan module with port-side exhaust airflow (blue coloring)	3	93108TC-EX 93108TC-FX ^a 93180YC-EX 93180YC-FX ^a 9348GC-FXP
NXA-FAN-35CFM-PE	Fan module with port-side exhaust airflow (blue coloring)	4	92300YC ^a 9332C ^a 93180YC-FX3S ^b

Product ID	Description	Quantity	Cisco Nexus Switches
		6	93180YC-FX3 93108TC-FX3P 9336C-FX2-E 9316D-GX 93600CD-GX
NXA-FAN-35CFM-PI	Fan module with port-side intake airflow (burgundy coloring)	4	92300YC ^a 9332C ^a 93180YC-FX3S ^b 93180YC-FX3 93108TC-FX3P
	Fan module with port-side exhaust airflow (blue coloring)	6	9316D-GX 93600CD-GX
		6	9336C-FX2-E
NXA-FAN-65CFM-PE	Fan module with port-side exhaust airflow (blue coloring)	3	93240YC-FX2 ^a 9336C-FX2 ^a
NXA-FAN-65CFM-PI	Fan module with port-side exhaust airflow (burgundy coloring)	3	93240YC-FX2 ^a 9336C-FX2 ^a

^a For specific fan speeds see the Overview section of the Hardware Installation Guide.

^b This switch runs with +1 redundancy mode so that if one fan fails, the switch can sustain operation. But if a second fan fails, this switch is not designed to sustain operation. Hence before waiting for the major threshold temperature to be hit, the switch will power down due to entering the **fan policy trigger** command.

Table 13. Cisco Nexus 9200 and 9300 Power Supplies

Product ID	Description	Quantity	Cisco Nexus Switches
NXA-PAC-500W-PE	500-W AC power supply with port-side exhaust airflow (blue coloring)	2	93108TC-EX 93180YC-EX 93180YC-FX
NXA-PAC-500W-PI	500-W AC power supply with port-side intake airflow (burgundy coloring)	2	93108TC-EX 93180YC-EX 93180YC-FX
NXA-PAC-650W-PE	650-W power supply with port-side exhaust (blue coloring)	2	92300YC 93180YC-FX3S 93108TC-EX 93180YC-EX 93180YC-FX3
NXA-PAC-650W-PI	650-W power supply with port-side intake (burgundy coloring)	2	92300YC 93180YC-FX3S 93108TC-EX 93180YC-EX 93180YC-FX3
NXA-PAC-750W-PE	750-W AC power supply with port-side exhaust airflow (blue coloring) 1	2	9336C-FX2 9336C-FX2-E 9332C 93240YC-FX2

Product ID	Description	Quantity	Cisco Nexus Switches
NXA-PAC-750W-PI	750-W AC power supply with port-side intake airflow (burgundy coloring) 1	2	9336C-FX2 9336C-FX2-E 9332C 93240YC-FX2
NXA-PAC-1100W-PE2	1100-W AC power supply with port-side exhaust airflow (blue coloring)	2	93240YC-FX2 9332C 9316D-GX 9336C-FX2 9336C-FX2-E 93600CD-GX
NXA-PAC-1100W-PI2	1100-W AC power supply with port-side intake airflow (burgundy coloring)	2	93240YC-FX2 9332C 9316D-GX 9336C-FX2 9336C-FX2-E 93600CD-GX
NXA-PAC-1100W-PI	Cisco Nexus 9000 PoE 1100W AC PS, port-side intake	2	93108TC-FX3P
NXA-PAC-1100W-PE	Cisco Nexus 9000 PoE 1100W AC PS, port-side exhaust	2	93108TC-FX3P
NXA-PAC-1900W-PI	Cisco Nexus 9000 PoE 1900W AC PS, port-side intake	2	93108TC-FX3P
NXA-PAC-1200W-PE	1200-W AC power supply with port-side exhaust airflow (blue coloring)	2	93360YC-FX2 9364C
NXA-PAC-1200W-PI	1200-W AC power supply with port-side intake airflow (burgundy coloring)	2	93360YC-FX2 9364C
N9K-PUV-1200W	1200-W Universal AC/DC power supply with bidirectional airflow (white coloring)	2	92300YC 93108TC-EX 93108TC-FX 93360YC-FX2 93180YC-FX3S 93180YC-EX 93180YC-FX 9364C
NXA-PDC-930W-PE	930-W DC power supply with port-side exhaust airflow (blue coloring)	2	93108TC-EX 93180YC-EX 93360YC-FX2 93180YC-FX3S 93180YC-FX 9364C
NXA-PDC-930W-PI	930-W DC power supply with port-side intake airflow (burgundy coloring)	2	93108TC-EX 93180YC-EX 93360YC-FX2 93180YC-FX3S 93180YC-FX 9364C
NXA-PDC-1100W-PE	1100-W DC power supply with port-side exhaust airflow (blue coloring)	2	93240YC-FX2 93600CD-GX 9316D-GX 9332C 9336C-FX2

Product ID	Description	Quantity	Cisco Nexus Switches
			9336C-FX2-E
NXA-PDC-1100W-PI	1100-W DC power supply with port-side intake airflow (burgundy coloring)	2	93240YC-FX2 93600CD-GX 9316D-GX 9332C 9336C-FX2 9336C-FX2-E
UCSC-PSU-930WDC	930-W DC power supply with port-side intake (green coloring)	2	93108TC-EX 93180YC-EX
UCS-PSU-6332-DC	930-W DC power supply with port-side exhaust (gray coloring)	2	93108TC-EX 93180YC-EX
NXA-PHV-1100W-PE	1100-W AC power supply with port-side exhaust airflow (blue coloring)	2	93240YC-FX2 9336C-FX2
NXA-PHV-1100W-PI	1100-W AC power supply with port-side intake airflow (burgundy coloring)	2	93240YC-FX2 9336C-FX2
NXA-PAC-2KW-PE	2000-W AC power supply with port-side exhaust airflow (blue coloring)	2	9364C-GX
NXA-PAC-2KW-PI	2000-W AC power supply with port-side intake airflow (burgundy coloring)	2	9364C-GX
NXA-PDC-2KW-PE	2000-W DC power supply with port-side exhaust airflow (blue coloring)	2	9364C-GX
NXA-PDC-2KW-PI	2000-W DC power supply with port-side intake airflow (burgundy coloring)	2	9364C-GX
N2200-PAC-400W	400-W AC power supply with port-side exhaust airflow (blue coloring)	2	92348GC-X
N2200-PAC-400W-B	400-W AC power supply with port-side intake airflow (burgundy coloring)	2	92348GC-X
N2200-PDC-350W-B	350-W DC power supply with port-side intake airflow	2	92348GC-X
N2200-PDC-400W	400-W DC power supply with port-side exhaust airflow (blue coloring)	2	92348GC-X

Compatibility Information

Fabric Module and Line Card compatibility details are listed below.

Table 14. Cisco Nexus 9500 Cloud Scale Line Cards

Product ID	N9K-C9504-FM-G	N9K-C9508-FM-G	N9K-C9504-FM-E	N9K-C9508-FM-E	N9K-C9508-FM-E2	N9K-C9516-FM-E2
N9K-X9716D-GX	4	4	No	No	No	No

Product ID	N9K-C9504-FM-G	N9K-C9508-FM-G	N9K-C9504-FM-E	N9K-C9508-FM-E	N9K-C9508-FM-E2	N9K-C9516-FM-E2
N9K-X9736C-FX	No	No	5	5	5	5
N9K-X97160YC-EX	No	No	4	4	4	4
N9K-X9788TC-FX	No	No	4	4	4	4
N9K-X9732C-EX	No	No	4	4	4	4
N9K-X9736C-EX	No	No	4	4	4	4
N9K-X9732C-FX	No	No	4 5 (n+1 redundancy)	4 5 (n+1 redundancy)	4 5 (n+1 redundancy)	4 5 (n+1 redundancy)

Table 15. Cisco Nexus 9500 R-Series Line Cards

Product ID	N9K-C9504-FM-R	N9K-C9508-FM-R
N9K-X9636C-RX	6	6
N9K-X9636Q-R	4 6 (n+2 redundancy)	4 6 (n+2 redundancy)
N9K-X9636C-R	5 6 (n+1 redundancy)	5 6 (n+1 redundancy)
N9K-X96136YC-R	6	6

Optics

To determine which transceivers and cables are supported by a switch, see the [Transceiver Module \(TMG\) Compatibility Matrix](#). To see the transceiver specifications and installation information, see the [Install and Upgrade Guides](#).

Cisco Network Insights

Cisco NX-OS Release 10.1(1) supports the Cisco Network Insights Advisor (NIA) and Cisco Network Insights for Resources (NIR) on Cisco Nexus 9200, 9300-EX, and 9300-FX platform switches and 9500 platform switches with -EX/FX line cards. For more information, see the [Cisco Network Insights documentation](#).

Upgrade and Downgrade

To perform a software upgrade or downgrade, follow the instructions in the *Cisco Nexus 9000 Series NX-OS Software Upgrade and Downgrade Guide, Release 10.1(x)*. For information about an In Service Software Upgrade (ISSU), see the [Cisco NX-OS ISSU Support Matrix](#).

Related Content

Document	Description
Cisco Nexus 9000 Series Switches	Cisco Nexus 9000 Series documentation
Cisco Nexus 9000 and 3000 Series NX-OS Switch License Navigator	Cisco Nexus 9000 and 3000 Series NX-OS Switch License Navigator
Cisco Nexus 9000 Series NX-OS Software Upgrade and Downgrade Guide, Release 10.1(x)	Cisco Nexus 9000 Series Software Upgrade and Downgrade Guide
Cisco Nexus 9000 Series FPGA/EPLD Upgrade Release Notes, Release 10.1(1)	Cisco Nexus 9000 Series FPGA/EPLD Upgrade Release Notes
Cisco Nexus NX-API Reference	Cisco Nexus 3000 and 9000 Series NX-API REST SDK User Guide and API Reference
ftp.cisco.com/pub/mibs/supportlists/nexus9000/Nexus9000MIBSupportList.html	Cisco NX-OS Supported MIBs
Cisco Nexus 9000 Series Switch FEX Support Matrix	Supported FEX modules
Cisco NX-OS Licensing Guide	Licensing Information

When you downgrade from Cisco NX-OS Release 10.1(1) to an earlier release, the features that use the ACI+NX-OS Essentials, Advantage, and add-on licenses or the Hardware Streaming Telemetry license continue to work in honor mode in the downgraded version. In addition, the output of the **show license usage** command continues to include entries for these unsupported licenses.

For more information, see the [Cisco NX-OS Licensing Guide](#).

Documentation Feedback

To provide technical feedback on this document, or to report an error or omission, please send your comments to nexus9k-docfeedback@cisco.com. We appreciate your feedback.

Legal Information

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2021–2023 Cisco Systems, Inc. All rights reserved.