

HMAN through **IRECAGENTSERVER**

- HMAN through HW_FLOWDB, on page 1
- HW IDPROM ENVMON through IFDAMP, on page 15
- IFMAP through INSTALL, on page 30
- INTERCHASSIS_REDUNDANCY through IOSXE_FMANRP, on page 56
- IOSXE_FMANRP_ADJ through IOSXE_INFRA, on page 74
- IOSXE MEMPOOL MIB through IOSXE RP IF FLOW IDS, on page 97
- IOSXE RP MGMTE through IOSXE UTD, on page 129
- IOSXE VMAN through IPC LOG, on page 159
- IPC TEST through IPV6 ACL, on page 175
- IPV6_ADDRESS through IRECAGENTSERVER, on page 202

HMAN through HW_FLOWDB

- HMAN
- HMAN CPU
- HPI
- HSRP
- HTSP
- HTTP
- HTTPC
- HUNTGRP
- HW API
- HW FLOWDB

HMAN

%HMAN-3-CONSOLE_SETUP_FAILED: Failed to setup console service. It should be enabled on [chars]

Explanation

Setup of a console service failed.

%HMAN-3-CONSOLE_SETUP_FAILED : Failed to setup console service. It should be enabled on [chars]

Recommended Action

Check the host manager launch parameters and correct as required.

%HMAN-3-HOSTNAME_SET_FAILED : Failed to set hostname: [chars]

Explanation

The host manager received notification that the system hostname has been set. The host manager failed to pass this value to the ASR kernel.

Recommended Action

Repeat the process to configure the hostname. If the problem persists, copy the message exactly as it appears on the console or in the system log. Research and attempt to resolve the issue using the tools and utilities provided at http://www.cisco.com/tac. With some messages, these tools and utilities will supply clarifying information. Search for resolved software issues using the Bug Toolkit at

https://bst.cloudapps.cisco.com/bugsearch/. If you still require assistance, open a case

with the Technical Assistance Center via the Internet

athttps://mycase.cloudapps.cisco.com/case, or contact your Cisco technical support representative and provide the representative with the gathered information.

%HMAN-2-INITIALIZATION_FAILED: Host Manager initialization failed.

Explanation

Initialization of the host manager failed.

Recommended Action

Review Host Manager logs taking note of the timestamp information to select specific information to review. Copy the message and other related information exactly as it appears on the console or in the system log. Research and attempt to resolve the issue using the tools and utilities provided at http://www.cisco.com/tac. With some messages, these tools and utilities will supply clarifying information. Search for resolved software issues using the Bug Toolkit at https://bst.cloudapps.cisco.com/bugsearch/. If you still require assistance, open a case with the Technical Assistance Center via the Internet athttps://mycase.cloudapps.cisco.com/case, or contact your Cisco technical support representative and provide the representative with the gathered information.

HMAN_CPU

%HMAN_CPU-3-PAGE_FAULT_HIGH: CPU Usage due to Memory Pressure exceeds threshold on [chars]. Below are the top 5 memory consuming processes: [chars] (PID=[dec] RSS=[dec] MB),

Explanation

When CPU usage due to Major Page Fault exceeds a pre-defined threshold for a CPU core, this error message is emitted.

Recommended Action

No action is needed if system continues to perform as expected. If system performance deteriorate (and eventually, system reloads due to unspecified reason) around the time when this message is observed, open a case with the Technical Assistance Center via the following Internet link, or contact your Cisco technical support

the following internet link, of contact your cisco technic

representative:https://mycase.cloudapps.cisco.com/case

HPI

%HPI-3-FAILED_START : channel:[chars] DSP ID:[hex], failed mode [dec] for service [dec]	
Explanation	Failed to start DSP services
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HPI-3-INVALID_PAYLOAD : wrong payload size, channel:[chars] DSP ID:[hex], failed mode [dec] for service [dec]	
Explanation	Failed to start DSP services
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HPI-3-CODEC_NOT_LOADED : channel:[chars] DSP ID:[hex], command failed as codec not loaded [dec]	
Explanation	Sending messages to DSP without a loaded codec can result with the DSP failing
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HPI-4-INVALID_CODEC_LOAD : channel:[chars] DSP ID:[hex], invalid hpi mode [dec] for loading codec [dec]	
Explanation	Attempt to load codec when the DSP is in an invalid mode which can result with DSP failure
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HPI-4-NO_CLOSE : channel:[chars] DSP ID:[hex]	
Explanation	Attempt to release DSP without sending close message

%HPI-4-NO_CLOSE : channel:[chars] DSP ID:[hex]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HPI-4-INVALID_ECAN_TYPE : [chars] ECAN is not available in voice-card [dec], [chars] ECAN will be used	
Explanation	All voice cards participated in DSPFarm must have the same echo canceller type
Recommended Action	Make sure all voice cards participated in DSPFarm have the same echo canceller type configured

%HPI-3-GSMAMRNB_LICENSE_NOT_ACTIVATED:

Explanation	Failed to start DSP services for GSM AMR-NB codec
Recommended	Copy the error message exactly as it appears on the console or in the system log.
Action	Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If
	you still require assistance, open a case with the Technical Assistance Center via the
	Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical
	support representative and provide the representative with the gathered information

%HPI-6-SRTP_EVAL_LIMIT : The SRTP bandwidth and tunnels usage exceed the license limits	
Explanation	The SRTP bandwidth and tunnels exceed the license limits
Recommended Action	No action is required.

%HPI-3-SRTP_EVAL_FREE_ERROR: Error encountered on release SRTP bandwidth and tunnels reservation	
Explanation	Error encountered on release SRTP bandwidth and tunnels
Recommended Action	No action is required.

%HPI-3-NACK_HIGH : DSP to IOS Nack message with severity [chars] [chars]	
Explanation	DSP to IOS Nack message with high severity

%HPI-3-NACK_HIGH : DSP to IOS Nack message with severity [chars] [chars]	ars]
--	------

Recommended Action

Check the NACKed message's parameters for configuration errors. These messages tend to affect call flow, thus they are labeled with high severity.

%HPI-4-NACK_MED : DSP to IOS Nack message with severity [chars] [chars]	
Explanation	DSP to IOS Nack message with medium severity

Recommended

Action

Check the NACKed message's parameters for minor configuration errors.

%HPI-6-NACK_LOW : DSP to IOS Nack message with severity [chars] [chars] [chars] Explanation DSP to IOS Nack message with low severity Recommended Action Information only, displaying NACKed messages that are for debugging purposes.

%HPI-6-NACK : DSP to IOS Nack message [chars] [chars]	
Explanation	DSP to IOS Nack message with no severity in order to work with dspware without Nack severity implementation
Recommended Action	Information only, displaying NACKed messages.

HSRP

%HSRP-3-NOSOCKET : Unable to open socket	
Explanation	The system was unable to initialize an IP connection for the Hot Standby protocol.
Recommended Action	Make sure that there is at least one interface configured to run IP.

%HSRP-4-BADAUTH : Bad authentication from [chars], group [dec], remote state [chars]	
Explanation	Two routers participating in HSRP disagree on the valid authentication string.
Recommended Action	Use the standby authentication command to repair the HSRP authentication discrepancy between the local system and the one whose IP address is reported.

%HSRP-4-BADAUTH2 : Bad authentication from [chars]	
Explanation	Two routers participating in HSRP disagree on the valid authentication string.
Recommended Action	Use the standby authentication command to repair the HSRP authentication discrepancy between the local system and the one whose IP address is reported.

%HSRP-3-MISCONFIG : Attempt to change [chars] MAC address to [enet] when DECNET already running	
Explanation	An HSRP group attempted to become active on an interface that can only support a single MAC address and which is running DECnet. If standby use-bia is not configured then HSRP would normally set the interface MAC address to the HSRP virtual MAC address, but this is not allowed if DECnet is running.
Recommended Action	Enable standby use-bia on the interface.

%HSRP-5-STATECHANGE : [chars] Grp [dec] state [chars] -> [chars]	
Explanation	The router has changed state
Recommended Action	No action is required.

%H3KP-4-DUPADL	%HSKP-4-DUPADDK: Duplicate address [cnars] on [cnars], sourced by [enet]	
Explanation	The IP address in an HSRP message received on the specified interface is the same as the IP address of the router. Another router might be configured with the same IP address. The most likely cause is a network loop or a misconfigured switch that is causing the router to see its own HSRP Hello messages.	
Recommended Action	Check the configurations on all the HSRP routers to ensure that the interface IP addresses are unique. Check that no network loops exist. If port channels are configured check that the switch is correctly configured for port-channels. Enable standby use-bia so that the error message displays the interface MAC address of the sending router. This can be used to determine if the error message is caused by a misconfigured router or a network loop.	

%HSRP-4-DUPVIP1 : [chars] Grp [dec] address [chars] is already assigned to [chars] group [dec]	
Explanation	The HSRP virtual IP address contained in the Hello message cannot be learnt as it is already assigned to a different HSRP group.
Recommended Action	Check the configuration on all HSRP routers and ensure that the virtual IP address of each HSRP group is unique.

%HSRP-4-DUPVIP2 : [chars] Grp [dec] address [chars] is already assigned on this interface	
Explanation	The HSRP virtual IP address contained in the Hello message cannot be learnt as it is already assigned to this interface.
Recommended Action	Check the configuration on all HSRP routers and ensure that the virtual IP address of each HSRP group is unique.

%HSRP-4-DUPVIP3 : [chars] Grp [dec] address [chars] is already assigned to, or overlaps with, an address on another interface or application	
Explanation	The HSRP virtual IP address contained in the Hello message cannot be learnt as it is already assigned to, or overlaps with, an address on another interface or application.
Recommended Action	Check the configuration on all HSRP routers and ensure that the virtual IP address of each HSRP group is unique.

%HSRP-4-BADVIP : [chars] Grp [dec] address [chars] is in the wrong subnet for this interface	
Explanation	The HSRP virtual IP address contained in the Hello message cannot be learnt as it is not within a subnet configured on the interface.
Recommended Action	Check the configuration on all HSRP routers and ensure that the virtual IP address is within a configured subnet.

%HSRP-4-DIFFVIP1 : [chars] Grp [dec] active routers virtual IP address [chars] is different to the locally configured address [chars]	
Explanation	The HSRP virtual IP address contained in the Hello message from the Active router is different from the virtual IP address configured locally.
Recommended Action	Check the configuration on all HSRP routers in the group and ensure they are all configured with the same virtual IP address.

HTSP

%HTSP-3-NOEVENT : no free event structure available from [chars] for DSP message	
Explanation	There were no event structures remaining in the system pools to alert the router of a voice or signaling event.
Recommended Action	Check that the voice port for which the event was reported is still operational. If not, clear the voice port.

%HTSP-3-CAPABILITYMISMATCH : voice port [chars]: call connection id [[hex] [hex] [hex] [hex]	
Explanation	There was a capabilities mismatch between the two call legs. capabilities are negotiated between call legs for CODEC, VAD and FAX rate.
Recommended Action	Check that the dial peer configuration is appropriate for the interface in question. Also check that and configuration on the interface is correct.

%HTSP-3-DSPALARM : voice port [chars]: status=[hex] message=[hex] text=[chars]	
Explanation	The DSP reported a fatal error. All calls on the DSP were dropped and a DSP reload was attempted.
Recommended Action	Verify that the DSP reloaded properly by attempting to place a call on the affected voice port. Contact your technical support representative, include the full text of the error message.

%HTSP-3-TRUNKNOTSUPPORTED : voice port [chars]: Ground Start trunking not supported	
Explanation	This voice port does not support the 'connection trunk' command when ground start signaling is configured. Trunking mode on this voice is supported when using loop start signaling.
Recommended Action	Shut down the voice port, remove the 'connection trunk' and/or 'signal groundStart' command from the voice port configuration, and unshut the voice port.

%HTSP-5-UPDOWN : Trunk port(channel) [[chars]] is [chars]	
Explanation	Trunk port:channel changed state.
Recommended Action	No action is required.

%HTSP-3-CADENCENOTSUPPORTED : voice port [chars]: ring cadence not suitable for caller id. on_time_first=[dec] off_time_first=[dec] on_time_second=[dec]	
Explanation	Ring off period is not sufficient for caller id transmission. If caller id transmission during ring is configured make sure that the ring off duration is long enough.
Recommended Action	If caller id transmission during ring is configured make sure that the ring off duration is long enough. Make sure that the cptone setting and caller-id alerting settings are correct.

%HTSP-5-VPM_BUSYOUT : voice port [chars]: [chars] busyout	
Explanation	voice port busyout status changed

%HTSP-5-VPM_BUSYOUT : voice port [chars]: [chars] busyout

Recommended

use SHOW VOICE BUSYOUT to find out the reason why voice port busyout

Action

monitoring is triggered

%HTSP-5-VPM_PCM_CAPTURE: User trigger PCM capture is [chars] on voice port [chars]

Explanation

User trigger PCM capture is enabled or disable on this voice port

Recommended

Action

This is just for information only

%HTSP-5-VPM CABLE STAT : voice port [chars]: cable [chars]

Explanation

Cable for analog voice port is reconnected or removed

Recommended

Action

Check the cable connection for this analog voice port

HTTP

%HTTP-3-PROC_NOCREAT: Unable to create HTTP process.

Explanation

An error occurred during initialization of the HTTP process. The HTTP process that

processes all HTTP requests and responses could not be created.

Recommended

Action

Reduce other system activity to ease memory demands. If conditions warrant, upgrade to a larger memory configuration.

%HTTP-4-SERVER CONN RATE EXCEED: Number of connections per minute has exceeded the maximum limit([dec]) as specified by the platform.

Explanation

The message indicates that the current number of connections requested per minute has exceeded the limit specified by the platform. HTTP server will resume accepting the connections 15 seconds from the time the message is issued. This restriction is done as per the HTTP throttling functionality.

Recommended

Reduce connection rate to the server.

Action

%HTTP-3-OUTOF_MEM: HTTP out of memory.

Explanation

An error occurred during initialization of the HTTP process. The HTTP process could not create crucial internal data structures that are required for operation of the HTTP subsystem. The most likely reason for this condition is an exhaustion of system memory.

%HTTP-3-OUTOF_MEM: HTTP out of memory.

Recommended Action Reduce other system activity to ease memory demands. if conditions warrant, upgrade

to a larger memory configuration.

%HTTP-3-INIT_FAIL: HTTP Process Init failed.

Explanation Initialization of the HTTP Subsystem has failed

Recommended Recommended to

Reduce other system activity to ease memory demands. If conditions warrant, upgrade

to a larger memory configuration.

%HTTP-6-SERVER_SETUP_FAILED : Server setup failed

Explanation Setup of the HTTP(S) server to listen on the specified port number has failed.

Recommended Action

Disable the server, verify that port number is correct and enable the server. Reduce other system activity to ease memory demands. If conditions warrant, upgrade to a

larger memory configuration.

HTTPC

%HTTPC-3-PROC_NOCREAT : Unable to create HTTP Client process.

Explanation

Recommended

Action

%HTTPC-3-OUTOF_MEM: HTTP Client out of memory.

Explanation

Recommended

Action

%HTTPC-3-CACHE_MEM: HTTP Client Cache Init out of memory.

Explanation

Recommended

Action

%HTTPC-3-INIT_F/	AIL : HTTP Client Process Init failed.
Explanation	
Recommended Action	
%HTTPC-3-OUTOF	SYNC : HTTP Client header tables out of sync.
Explanation	
Recommended Action	
%HTTPC-6-CONNE	ECT_FAILED : The connection to server [IP_address] failed
Explanation	
Recommended Action	
	/E_SOCK_READ_EVENT_WHILE_DISABLED : Received socket read event while read d callID([dec]) fd([dec]) - closing socket.
Explanation	The HTTP Client is receiving the socket READ event while the READ interest is being disabled. Something has gone wrong between the http client and the socket interfaced.
Recommended Action	Record the error and report it to the system administrator.
%HTTPC-3-CONNE	ECT_NULL : NULL connection structure for fd([dec]) - closing socket.
Explanation	The HTTP Client is receiving the socket READ event but it fails to locate the connection structure for this file descriptor(fd). If this is seen continuously in a loop, it is an indication that something has gone wrong in the socket code. Since the socket is immediately closed after this event, the HTTP client should stop seeing READ event.
Recommended Action	Record the error and traceback and report it to the system administrator.
%HTTPC-6-REQUE	ST_FAILED : request URI [chars] failed
Explanation	
Recommended Action	

%HTTPC-6-CLOSE_SRV_CONNECT : The connection to server [IP_address] appears to be hung and will be closed.	
Explanation	Messages are being backed up in the HTTP Client's write queue in the connection with the specified server. The connection is assumed to have gone bad and the HTTP Client is closing the connection.
Recommended Action	Check with the specified server for possible connection error.

%HTTPC-3-COOKIE_MEM : HTTP Client runs out of allowable memory to store cookies.	
Explanation	The total memory allocated for storing cookies has run out. All cookies received from the HTTP server will be dropped. Users may no longer be able to interact with a session-based origin server until memory is freed up.
Recommended Action	Users may want to try their requests at a later time or contact the system administrator to increase the maximum RAM allowed for saving HTTP cookies.

HUNTGRP

%HUNTGRP-3-INVALID_URL : Could not open the file provided in URL: <[chars]>	
Explanation	URL path provided can't be accessed. This usually indicates that path provided is invalid but may also be because the the path doesn't allow anonymous access to create files or open it in write mode
Recommended Action	Check that the url path provided is valid

%HUNTGRP-3-WRITE_FAIL : Could not write data to the URL: <[chars]>t %%bytes written=[dec] out of [dec]	
Explanation	Write attempt to the url path provided was unsuccessful. This usually indicates that the file was successfully opened with write and append permissions but writing all the content from buffer or may be some of it to the file failed.
Recommended Action	

HW_API

%HW_API-3-RESILIENCE_NO_HANDLER : No handlers in place for [chars] sw object creation failure.	
Explanation	COMMON_HW_API_INTERNAL_ERROR

%HW API-3-RESILIENCE_NO_HANDLER: No handlers in place for [chars] sw object creation failure.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW API-3-INVALID OBJ: Invalid object [hex]

Explanation

HW API INTERNAL ERROR

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW API-3-INVALID TYPE: Invalid type [dec]

Explanation

HW API INTERNAL ERROR

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW_API-3-INVALID_WALK_SPEC: Invalid walk spec [hex]

Explanation

HW API INTERNAL ERROR

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW_API-3-WALK_MODE_UNSUPPORTED : Walk mode '[chars]' unsupported

Explanation

HW API INTERNAL ERROR

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW_API-3-INVALID_CONTEXT : Invalid context [hex]

Explanation HW_API_INTERNAL_ERROR

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW_API-3-BACKWALK_REQUEST: Backwalk request failed, [chars]

Explanation A request to walk internal data structures has failed. Depending on criticality of the

data, accuracy of forwarding may impacted.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW_API-3-BACKWALK_REQUEST_VALUE: Backwalk request failed, [chars] ([hex])

Explanation A request to walk internal data structures has failed. Depending on criticality of the

data, accuracy of forwarding may impacted.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW API-3-VECTOR: Failed to set [chars] vector for [chars], [chars]

Explanation HW_API_INTERNAL_ERROR

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW API-3-NO OBJ TYPE LIST ENTRY: Invalid sw obj type ([dec]) used with obj type list

Explanation HW API INTERNAL ERROR

%HW_API-3-NO_OBJ_TYPE_LIST_ENTRY: Invalid sw_obj_type ([dec]) used with obj_type_list

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW_API-3-NO_OBJ_TYPE_LIST_ENTRY2: Invalid sw_obj_link_type ([dec]) used with obj_type_list

Explanation HW_API_INTERNAL_ERROR

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW_API-3-INIT_FAIL: HW-API init [chars] failed[chars]

Explanation HW_API_INTERNAL_ERROR

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

HW FLOWDB

Action

%HW_FLOWDB-3-HW_FLOWDB_00M : FlowDB memory usage exceeded 95[int]sage. 00M condition can occur.	
Explanation	FlowDB running low on memory. Out-of-memory condition can occur
Recommended	Check sw-distrib for actual utilization of FlowDB memory

HW_IDPROM_ENVMON through IFDAMP

- HW_IDPROM_ENVMON
- HW PFU
- ICC

- IDBMAN
- IDB_IDENTITY
- IDB_SGI
- IDMGR
- IEDGE
- IF
- IFDAMP

HW_IDPROM_ENVMON

%HW_IDPROM_ENVMON-3-HW_IDPROM_FIELD_INVALID: The idprom contains an invalid environmental monitoring field. Explanation If this error occurs then parsing of the environmental monitoring data is aborted. Environmental monitoring will be either incomplete or absent entirely. Recommended Action If this message recurs, copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW_IDPROM_ENVMON-3-HW_IDPROM_CHECKSUM_INVALID : The idprom contains an invalid checksum in a sensor entry. Expected: [hex], calculated: [hex]	
Explanation	If this error occurs then parsing of the environmental monitoring data is aborted. Environmental monitoring will be either incomplete or absent entirely.
Recommended Action	If this message recurs, copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW_IDPROM_ENVMON-2-ACT2_UDI_DATA_INVALID : The act2 udi secure area format mismatch with unsecure area

Explanation

This Router may not have been manufactured by Cisco or with Cisco's authorization. This product may contain software that was copied in violation of Cisco's license terms. If your use of this product is the cause of a support issue, Cisco may deny operation of the product, support under your warranty or under a Cisco technical support program such as Smartnet. Please contact Cisco's Technical Assistance Center for more information.

%HW_IDPROM_ENVMON-2-ACT2_UDI_DATA_INVALID : The act2 udi secure area format mismatch with unsecure area

Recommended Action

If this message recurs, copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW_IDPROM_ENVMON-3-PS_IDPROM_INVALID_PID : [chars] in slot PFU[dec] has INVALID PID [chars] and it needs to be replaced immediately

Explanation

The PID read from the PEM IDPROM is not supported in this hardware configuration. It will be allowed to continue but immediate replacement is required

Recommended Action

If this message recurs, copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

HW PFU

Explanation

The idprom contains information required in order to properly operate the environmental monitoring subsystems. The idprom could not be read, therefore no monitoring will take place.

Recommended Action

If this message recurs, copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit

 $(https://bst.cloudapps.cisco.com/bugsearch/).\ If\ you\ still\ require\ assistance,\ open\ a$

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW_PFU-3-PFU_IDPROM_CORRUPT: The PEM/FM idprom could be read, but is corrupt in slot P[dec] The system will run without environmental monitoring for this component

Explanation

The idprom contains information required in order to properly operate the environmental monitoring subsystems. The idprom could not be read, therefore no monitoring will take place.

%HW PFU-3-PFU_IDPROM_CORRUPT: The PEM/FM idprom could be read, but is corrupt in slot P[dec] The system will run without environmental monitoring for this component

Recommended Action

If this message recurs, copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%HW_PFU-3-PFU_IDPROM_INVALID_PID : The PEM/FM idprom has invalid PID in slot PFU[dec] The system will run without environmental monitoring for this component

Explanation

The idprom contains PID information required in order to properly operate the environmental monitoring subsystems. The idprom PID is invalid, therefore no monitoring will take place.

Recommended Action

If this message recurs, copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

ICC

%ICC-2-NOMEM : No memory available for [chars]

Explanation	The ICC subsystem could not o

Recommended Action

The ICC subsystem could not obtain the memory it needed.

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%ICC-4-CONSISTENCY : Internal consistency check: [chars]

Explanation

An internal inconsistency was found in some ICC data structures.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%ICC-4-COMM: Communication failure occurred while [chars]

Explanation

Recommended

Action

%ICC-4-BAD_ACCOUNTING : ICC received a bad class [dec]

Explanation

A communication failure has occurred between this card and another card in the system.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%ICC-4-HEARTBEAT : Card [dec] failed to respond to heartbeat

Explanation

A communication failure has occurred between the primary and the specified line card.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%ICC-5-WATERMARK : [dec] [chars] [chars] pkts for class [chars] are waiting to be processed

Explanation

Processor got packets for the class and are waiting to be procssed

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%ICC-2-OPEN: ICC Create Session Failed for card <[hex]> Queue <[chars]>

Explanation

ICC was not able to create a session for the destination seat

%ICC-2-OPEN: ICC Create Session Failed for card <[hex]> Queue <[chars]>

Recommended

collect output from 'show oir debug swover global mask' from SP

Action

%ICC-2-JOIN : ICC mcast joining failed member <[hex]> to group <[hex]> with ipc error <[chars]>

ICC was not able to join a member for the meast group Explanation

Recommended collect output 'show icc meast status' from RP

Action

%ICC-5-HUGE_BUFFER: Class [[chars]] with Request id [dec] requested a huge buffer of Size [dec].

Explanation Huge packet requests would deplete the memory at the linecards

Recommended ICC client is trying to request huge packet buffer Please use the command Show icc Action

internal to get get the traceback and file a DDTS against the component

%ICC-3-MAST_BAD_FREE : ICC multicast memory already freed

Explanation One of the ICC multicast request's memory was found to be free when response arrived

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IDBMAN

%IDBMAN-3-VLANINUSE: [chars]: Vlan [dec] is in use by [chars]

Explanation Each L3 interface has a Vlan associated with it. This message indicates that the Vlan

associated with the interface is being used by some other L3 Interface, which is not

anticipated to happen

Recommended

Action

No action is required.

%IDBMAN-3-INVALIDVLAN : [chars]: trying to use invalid Vlan [dec]

Explanation There is an internal error that caused an invalid Vlan to be used by the software.

%IDBMAN-3-INVALIDVLAN : [chars]: trying to use invalid Vlan [dec]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDBMAN-3-VLANNOTSET : [chars]: Vlan [dec] not set since it already has Vlan [dec]

Explanation

There is an internal error that caused an interface to not have its Vlan set to the requested value

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDBMAN-6-VLANMAPPED: Vlan [dec] is mapped to [chars]

Explanation

Informational message indicating that the given Vlan is mapped to the given interface

Recommended

Action

No action is required.

$\mbox{\%IDBMAN-3-AGGPORTMISMATCH}: [chars]([dec] / [dec]) does match internal slot/port state [chars]([dec] / [dec])$

Explanation

There is an internal error that caused an invalid aggregate port to be used by the software.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDBMAN-3-INVALIDAGGPORTBANDWIDTH : [chars]([dec] / [dec]) has an invalid bandwidth value of [dec]

Explanation

There is an internal error that caused an invalid bandwidth to be used for an aggregate port

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\% IDBMAN-3-DELETEDAGGPORT: [chars]([dec]/[dec])\ Group\ [dec]\ has\ been\ deleted,\ but\ is\ being\ reused.$	
Explanation	There is an internal error that caused an interface that has been deleted to be reused for a new aggregate port.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDBMAN-3-NOTANAGGPORT : [chars]([dec] / [dec]) is not an aggregate port	
Explanation	There is an internal error that caused an interface that is not an aggregate port to be used for aggregate port operations
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDBMAN-3-INVALIDPORT : [chars]: trying to use invalid port number [dec] (Max [dec])	
Explanation	There is an internal error that caused an invalid port numer to be used by the software.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDBMAN-4-ACTIVEPORTSINAGGPORT : [chars]([dec] / [dec]) has [dec] active ports, but is being removed	
Explanation	There is an internal error that caused an aggregate port with active ports to be removed
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

% IDBMAN-3-PORTNOTINAGGPORT: [chars]([dec] / [dec]) is not present in Aggport [chars]([dec] / [dec])

Explanation

There is an internal error that caused an invalid port to be referred to be part of an aggregate port.

%IDBMAN-3-PORTNOTINAGGPORT : [chars]([dec] / [dec]) is not present in Aggport [chars]([dec] / [dec])

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDBMAN-4-REMOVED_NONDEFAULT_CONFIG: Removed non default configuration for interfaces in slot [dec]

Explanation

In SSO mode, the non-default configuration for any removed linecard is not synced to the standby during the bulk sync, and it is removed from the configuration to avoid a config mismatch between active and standby supervisors.

Recommended Action

No action is required.

$\$IDBMAN-3-IIF_ID_REGISTRATION_FAILED: IIF_ID$ registration failed for Port [chars] due to memory allocation failure. Port has been shutdown

Explanation

The system is low on memory due to which IIF-ID registration failed. This results in failure to apply polices such as QoS and Security acls on this port.

Recommended Action

 $LOG_STD_REDUCE_ACTION\ Once\ memory\ is\ available,\ run\ 'no\ shutdown'\ on\ the$

port.

IDB_IDENTITY

%IDB_IDENTITY-3-MALLOC : Memory allocation failure for HWIDB type [dec]

Explanation

A memory allocation failure occured when trying to allocate the identity for this HWIDB. This HWIDB will not be allocated an IF Index which will prevent it from being used for forwarding data.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IDB_SGI

%IDB_SGI-2-XDRREG : [chars]

Explanation

An internal software error occurred.

%IDB_SGI-2-XDRREG: [chars]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDB SGI-2-MEMREQ: [chars]

Explanation

An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDB SGI-3-BADPTR: [chars] of interface with ifindex [int] is invalid

Explanation

An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDB SGI-3-MEMFAIL: [chars]

Explanation

An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDB_SGI-4-MEMBERREQ : member request failure for interface with ifindex [int] returned err - [chars]

Explanation

An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDB_SGI-3-XDRREQ: [chars]

Explanation An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDB SGI-4-INTERR: [chars] for interface with ifindex [int]

Explanation An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDB_SGI-4-UNEXPINP: [chars]

Explanation An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IDMGR

%IDMGR-3-MALLOC_FAILURE : [chars]

Explanation A malloc failure occured in ID Manager.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDMGR-3-INTERRUPT : [chars]

Explanation An id_get attempted at interrupt level.

%IDMGR-3-INTERRUPT: [chars]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDMGR-3-INVALID ID: bad id in [chars] (id: [hex])

Explanation An ID Manager error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDMGR-3-INVALID ID TABLE SIZE: bad new ID table size

Explanation A bad ne

A bad new table request to ID Manager occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IDMGR-3-ID_MANAGER_INTERNAL_ERROR: [chars]

Explanation Internal Error occured with ID Manager.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IEDGE

%IEDGE-4-PBHK_DEPLETED_INDICES: No more portbundles can be allocated

Explanation The source interfaces configured for Portbundle Hostkey feature are not sufficient and

the number of portbundles available are all used up. Add more source interfaces in the

configuration.

Recommended

Action

Check configuration on the ISG

%IEDGE-4-TC_UNDEFINED_ACL : Traffic class ACL [chars] is not defined, creating permit all ACL	
Explanation	The ACL specified for classification of traffic is not configured on the ISG. Creating a permit all ACL. ACL should be configured on the ISG.
Recommended Action	Configure the ACL on the ISG

%IEDGE-4-CLOCK_CHANGE_TIMER_INV : A Local clock change has caused a running timer to be invalid	
Explanation	A change in local clock has made a currently running timer to be invalid
Recommended Action	Check the clock configuration

%IEDGE-3-CH_INTERNAL_ERROR : Internal error in command processing - session handle=[hex]	
Explanation	There has been an internal error relating to CoA command processing.
Recommended Action	Copy the error message exactly as it appears, and report it to your technical support representative.

%IEDGE-3-CH_REGISTER_ERROR : CoA registration error in command processing - type '[chars]'	
Explanation	There has been an internal error relating to CoA command processing.
Recommended Action	Copy the error message exactly as it appears, and report it to your technical support representative.

IF

%IF-3-IDB_LIST_BAD_REF_COUNT : A bad reference count was encountered in an idb list element.	
Explanation	A software error occurred.
Recommended Action	Copy the error message exactly as it appears, and report it to your technical support representative.

%IF-2-IDB_TABLE_INIT : Malloc failed while initializing idb table
Explanation
Recommended Action

%IF-3-BAD_MTU : Internal error. MTU on [chars] too large or negative. Truncating from %Id to [int].	
Explanation	An internal software error occurred. The system attempted to set the MTU on an interface to an invalid value.
Recommended Action	Copy the error message exactly as it appears, and report it to your technical support representative.

%IF-3-BADHWUNLOCK : ([chars]) attempted to unlock [chars] ([dec]). Locked by [chars] ([dec]).	
Explanation	Attempt to release semaphore held by another process.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IF-3-SEMAHOG : ([chars]) could not get [chars] semaphore. Held by ([chars]).	
Explanation	Unable to obtain interface semaphore.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

**IF-4-BACKWARD_COUNTERS : Corrected for backward [chars] counters ([int] -> [int]) on [chars] Explanation The interface specified in the message has a packet counter that has decreased in number. This condition can occur if a packet is counted and then dropped. This event was detected and corrected.

%IF-4-BACKWARD_COUNTERS: Corrected for backward [chars] counters ([int] -> [int]) on [chars]

Recommended Action

Recommended

Action

If this condition persists, copy the error message exactly as it appears on the console or in the system log. Issue the **show tech-support** command to gather data that may help identify the nature of the error. If you cannot determine the nature of the error from the error message text or from the **show tech-support** command output, contact your Cisco technical support representative and provide the representative with the gathered information.

%IF-3-BADMACADDRTYPE : illegal mac address type, [dec]

Explanation This is an i

Copy

This is an interal error that was recovered gracefully.

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IF-4-NOBGPROCESS: Network background process not running. [chars]

Explanation

A process which manages network interface background processing is not yet running, but another system process has tried to send the process a message.

i

Recommended Action

An interface on the router may have missed a request to bring itself up. If that happens, it may be necessary to reset the interface using a **shutdown** operation and then a **no shutdown**.

IFDAMP

%IFDAMP-5-UPDOWN: interface [chars] update [chars] state to [chars], interface is [chars]suppressed

Explanation

dampening interface changed state.

Recommended

Action

No action is required.

%IFDAMP-5-ZERODELAY : dampening reuse timer is updated with 0 delay time

Explanation

Inconsistency of dampening reuse timer wheel

Recommended

No action is required.

Action

IFMAP through **INSTALL**

- IFMAP
- IFMGR
- IFS
- IKEV2
- ILPOWER
- IM
- IMGR
- INDXOBJ
- INFRA
- INSTALL

IFMAP

%IFMAP-3-CAUSE_CFG : hash table not initialized	
Explanation	PAL interface handle to uidb hash table not initialized
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IFMGR

%IFMGR-3-IFINDEX_PERSIST_ENTRY_CORRUPT : [chars] seems to be corrupted. Trying to read [dec] size	
Explanation	The ifIndex-table seems to be corrupted.
Recommended Action	Delete the ifindex-table.

%IFMGR-3-INVALID_PERSISTENT_DATA : Invalid persistent data	
Explanation	Trying to write invalid persistent data
Recommended Action	Copy the error message exactly as it appears, and report it to your technical support representative.

%IFMGR-3-NOVECTOR : Interface manager failed to allocate IF vector. size [dec]	
Explanation	The interface vector was not able to be allocated with the number of elements requiredinitially or resize (see size in the error message).
Recommended Action	TBD

%IFMGR-3-VECTOREXD : IF manager attempted to use interface [dec] outside vector range.	
Explanation	This message indicates that an interface with too large of an ifIndex value was attempted to be added to the IF-MGR DB.
Recommended Action	Additional IF-MGR warning and/or error messages should accompany indication of this error. These additional messages should provide more details on the effected interface.

%IFMGR-3-VECTORPOSUSED : IF manager attempted to add interface [dec] which was already added.	
Explanation	This message comes from the IF-MGR DB when it is trying to add an ifIndex value for this interface which already exists in the ifIndex DB.
Recommended Action	TBD

%IFMGR-4-VECTORIFSUSPECT : IF manager added interface [dec] which is unexpectedly large.	
Explanation	The ifIndex allocation scheme gives out sequential ifIndex values. This message comes from the IF-MGR DB when it is trying to add an ifIndex value much larger than the former greatest ifIndex value in the DB.
Recommended Action	TBD

%IFMGR-3-IFDB : IF manager interface database [chars] failure- [dec]		
Explanation		
Recommended Action	TBD	

%IFMGR-3-IFTDB : IF manager interface table database [chars] failure- [dec]		
Explanation		
Recommended Action	TBD	

Explanation

The interface type vector was not able to be allocated with the number of elements

required--initially or resize.

Recommended

Action

TBD

%IFMGR-3-NOIMACP: IF manager control process failed to start

Explanation

Recommended

TBD

Action

%IFMGR-4-NOIFINDEX: All SNMP if indices are exhausted

All SNMP MIB indices have been exhausted. Interfaces will not be able to obtain an Explanation

interface index that they can use to register with the interface MIB.

Recommended

Action

Attempt a system reload. If the problem persists after the system reload, copy the message exactly as it appears on the console or in the system log, contact your Cisco technical support representative, and provide the representative with the gathered information.

%IFMGR-3-BADIFINDEXTABLE: The file nvram:ifIndex-table is corrupt.

Explanation

The file is not in the expected format.

Recommended

Action

If possible, please delete the file.

%IFMGR-4-NOSYNC: ifIndex not being synced between active and standby

Explanation

When the standby comes up, then the tuple of ifIndex and ifDescr is synced so that when interfaces comes up they get the same ifIndex. This error happens when the

interface doesn't get the ifIndex for the given ifDescr

Recommended

Action

Inform the technical support to raise the ddts

%IFMGR-5-RESTART : [chars]

Explanation

The IF MGR process has restarted

%IFMGR-5-RESTART : [chars]		
Recommended	This is an informational message. The system should recover on its own.	
Action		

%IFMGR-4-STACK_RELATIONSHIP_ADD_ERROR : [chars]: Request for creating invalid stack relationship [dec], [dec]	
Explanation	The IF MGR received the call to add invalid stack relationship. The higher and lower ifIndex are shown in the message. The module of the IF MGR from where this message is generated is also shown in the message
Recommended Action	Inform the technical support to raise the ddts

%IFMGR-3-DUP_IFINDEX : Duplicate ifIndex ([dec]) found for ifDescr [chars]; exists in ifTable for ifDescr [chars].	
Explanation	Interfaces have same ifIndex in IF-MGR assigned list. The 2nd interface registered with IF-MGR will be assigned with new index
Recommended Action	1. No Action, if ifIndex persist is not required. 2. Reload the standby RP, if ERR msg only seen in standby RP 3. Reload the router with the proper ifindex-table and image

%IFMGR-7-NO_IFINDEX_FILE : Unable to open [chars] [chars]	
Explanation	This is a informational message. This means system found no saved ifIndex information, and ifIndex is not persisted across reboots. The ifIndices will be reassigned.
Recommended Action	1. No Action, if 'snmp-server ifIndex persist' is not configured. 2. If 'snmp-server ifindex persist' is configured then copy the error message exactly as it appears, and report it to your technical support representative.

IFS

%IFS-4-FILEMAX : Failed to open [chars], maximum open files [dec])	
Explanation	The router has reached the maximum number of files that may be open at one time.
Recommended Action	Close some files and try again. If this messages recurs, contact your technical support representative.

%IFS-3-FSMAX : Failed to add [chars], maximum filesystems [dec]	
Explanation	The router has reached the maximum number of file systems that can be supported at one time.

Recommended

Contact your technical support representative.

Action

%IFS-3-FSDUP : Failed to add [chars], filesystem prefix exists

Explanation A file system cound not be added because another file system exists with the same

name.

Recommended

Action

Contact your technical support representative.

%IFS-3-FS_CREATE_FAIL : Failed to create [chars] file system, [chars]

Explanation An internal software error occurred.

Recommended

Action

Call your technical support representative for assistance.

%IFS-3-FS_CREATE_FAIL2 : Failed to create [chars] simple file system, [chars]

Explanation An internal software error occurred.

Recommended

Action

Call your technical support representative for assistance.

%IFS-3-FS_MISSING_FUNCTIONS: '[chars]' file system missing required functions, not created

Explanation Some file systems require a certain set of function to be present in order to be usable.

This file sustem does not support all the mandatory functionality.

Recommended

Action

Call your technical support representative for assistance.

%IFS-3-FS_STRUCT_ERROR: Data does not match expected internal representation

Explanation A mismatch exists between the representation of data extracted from the filesystem

and the expectation of its formatting. This may occur when running in a dual-RP

environment, with different IOS versions running on the two RPs.

Recommended

Action

Ensure both RPs are running the IOS same version, if running in a dual-RP environment.

If not, call your technical support representative for assistance.

IKEV2	
%IKEV2-5-OSAL_INITIATE_TUNNEL: NULL	
Explanation	
Recommended Action	
%IKEV2-5-RECV_CONNECTION_REQUEST : NULL	
Explanation	
Recommended Action	
%IKEV2-3-NEG_ABORT : NULL	
Explanation	
Recommended Action	
%IKEV2-1-SEND_COOKIE_CHALLENGE: NULL	
Explanation	
Recommended Action	
%IKEV2-5-IPSEC_COLLISION: NULL	
Explanation	
Recommended Action	
%IKEV2-5-SA_UP: NULL	
Explanation	
Recommended Action	

%IKEV2-5-SA_DOWN: NULL

Explanation

Recommended

Action

%IKEV2-5-SA_REJECTED_RESOURCE_LOW: NULL

Explanation

Recommended

Action

%IKEV2-5-SA_REJECTED_LIMIT_REACHED: [chars]

Explanation

Recommended

Action

%IKEV2-5-INCREASE_PEER_WINDOW_SIZE : NULL

Explanation

Recommended

Action

ILPOWER

%ILPOWER-3-ILPOWER_INTERNAL_IF_ERROR: Inline Power internal error, interface [chars]: [chars]

Explanation A software check failed during Power over Ethernet (PoE) processing.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%ILPOWER-5-ILPOWER_POWER_DENY: Interface [chars]: inline power denied. Reason: [chars]

Explanation There is not enough power remaining in the switch to supply to the Power over Ethernet

(PoE) port.

%ILPOWER_5-ILPOWER_POWER_DENY : Interface [chars]: inline power denied. Reason: [chars]

Recommended

No action is required.

Action

%ILPOWER-5-ILPOWER_POWER_CDP_SHUT : Interface [chars]: inline power shut

Explanation

Inline power is shut because cdp consumption power on this Power over Ethernet (PoE) port is greater than 1. allocation power or 2. hardware interface limit or 3. user configured max power or 4. available power on this switch.

Recommended Action No action is required.

%ILPOWER-3-CONTROLLER_ERR: Controller error, Controller number [dec]: [chars]

Explanation

An error reported or caused by the Power over Ethernet (PoE) controller is detected.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%ILPOWER-3-CONTROLLER_POST_ERR: Inline Power Feature is disabled on this switch because Power On Self Test (POST) failed on this switch. Please consult TECH support for further assistance

Explanation

An error reported or caused by the Power over Ethernet (PoE) controller is detected during POST.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%ILPOWER-3-CONTROLLER_IF_ERR: Controller interface error, [chars]: [chars]

Explanation

An interface error is detected between the Power over Ethernet (PoE) controller and system.

%ILPOWER-3-CONTROLLER_IF_ERR: Controller interface error, [chars]: [chars]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%ILPOWER-3-CONTROLLER_PORT_ERR: Controller port error, Interface [chars]: [chars]

Explanation

A port error reported by the Power over Ethernet (PoE) controller is detected.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%ILPOWER-5-POWER_GRANTED : Interface [chars]: Power granted

Explanation

There is enough power available in the switch, and the switch is providing power on

the interface.

Recommended Action

No action is required.

%ILPOWER-5-LINKDOWN_DISCONNECT: Interface [chars]: Link down disconnect

Explanation

The powered device is no longer connected to the switch, or the connected powered device is being powered by an external AC power source. The switch is no longer

providing power on the interface.

Recommended Action

No action is required.

Action

%ILPOWER-5-IEEE DISCONNECT : Interface [chars]: PD removed

Explanation

The powered device is no longer connected to the switch, or the connected powered device is being powered by an external AC power source. The switch is no longer providing power on the interface.

Recommended

Action

No action is required.

%ILPOWER-7-DETECT : Interface [chars]: Power Device detected: [chars]	
Explanation	The switch has detected the attached power device.
Recommended Action	No action is required.
%ILPOWER-5-INV/denied	ALID_IEEE_CLASS : Interface [chars]: has detected invalid IEEE class: [dec] device. Power
Explanation	The power device has invalid IEEE class. switch won't powerup the device
Recommended Action	No action is required.
%ILPOWER-3-SHU configured power	T_OVERDRAWN : Interface [chars] is shutdown as it is consuming more than the maximum ([dec]) milliwatts.
Explanation	Interface is shutdown because it is consuming more than the maximum configured power
Recommended Action	Make sure correct power is budgeted for this interface based on the power device electrical specifications or ratings. It is recommended to change the police cutoff power to a higher value to keep the device powered on
	_OVERDRAWN : Interface [chars] is overdrawing power. it is consuming [dec] milliwatts m configured power is ([dec]) milliwatts.
Recommended Action	Make sure correct power is budgeted for this interface based on the power device electrical specifications or ratings. Otherwise you might risk overloading the switch. It is recommended to change the police cutoffpower appropriately if needed
	_OVERDRAWN : Interface [chars] is NOT overdrawing power. it is consuming [dec] as maximum configured value is ([dec]) milliwatts.
Explanation	
Recommended Action	No action is required.

%ILPOWER-5-POLICE_POWER_INVALID : Interface [chars]: invalid power police [dec] milliwatts current [dec] mA voltage [dec] mV

Explanation

power policing current or voltage value is invalid.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\label{lem:continuous} \begin{tabular}{ll} \tt MLPOWER-5-SENSE_POWER_INVALID: Interface~[chars]: invalid~power~sense~[dec]~milliwatts~current~[dec]~mA~voltage~[dec]~mV~\\ \end{tabular}$

Explanation

power sensing current or voltage value is invalid.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%ILPOWER-4-ILPOWER_POWER_SUPPLY : PoE Power Supply [chars]: [chars]

Explanation The power sup

The power supply for PoE is OIR

Recommended

Make sure power supply to PoE input is inserted after removal

Action

%ILPOWER-4-ILPOWER_PS_ABSENCE : PoE module Power Supply not present Inline Power Feature is disabled on [chars] because Power On Self Test (POST) failed : [chars]

Explanation The power supply for PoE expansion module is not present or not inserted properly

or faulty

Recommended Action Make sure power supply to expansion module is inserted properly and reload the switch

with PoE power supply present

%ILPOWER-5-PWRGOOD_SPARE_PAIR: Interface [chars]: spare pair power good

Explanation Spare pair power request was successful and power is available on spare pair

Recommended

No action is required.

Action

%ILPOWER-5-TSTART_SPARE_PAIR: Interface [chars]: spare pair power error: TSTART

Explanation spare pair tstart error has occurred, power on spare pair will not be supplied

Recommended Action

No action is required.

%ILPOWER-5-PGOOD_TIMEOUT_SPARE_PAIR: Interface [chars]: spare pair power good timeout error

Explanation spare pair power good timeout error has occurred, power on spare pair will not be

supplied

Recommended

Action

No action is required.

%ILPOWER-5-DET_SHORT_SPARE_PAIR: Interface [chars]: spare pair short detected

Explanation spare pair short detect error has occurred, power on spare pair will not be supplied

Recommended No action is required.

Action

%ILPOWER-5-DET_TIMEOUT_SPARE_PAIR: Interface [chars]: spare pair detect timeout

Explanation spare pair timeout detect error has occurred, power on spare pair will not be supplied

Recommended

Action

No action is required.

%ILPOWER-6-SET_ILPOWER: Set power allocated to POE to [dec] for slot [dec]

Explanation The power allocated to POE has changed

Recommended

Action

No action is required.

IM

 $\%IM\text{-}0\text{-}UIPEER_CREATE$: Failed to create user interface peer.

Explanation The system failed to create a user interface peer.

%IM-0-UIPEER_CREATE: Failed to create user interface peer.

Recommended Action

In most cases, the problem can be corrected by reloading the impacted hardware using the hw-module [slot | subslot] slot-number reload command. If the reload fails to correct the problem, collect the output of the error message, the logs, and the output of show tech-support and provide the gathered information to a Cisco technical support representative.

%IM-2-INITIALIZATION FAILED:

Explanation Initialization of IOx Manager process failed.

Recommended Action Review ioxman logs taking note of the timestamp information to select specific information to review. Copy the message and other related information exactly as it appears on the console or in the system log.

%IM-0-EVENT_LIBRARY:

Explanation An event facility initialization or maintenance function failed. This could be due to a

software defect or system resource exhaustion.

Recommended Action

In most cases, the problem can be corrected by reloading the impacted hardware using the hw-module [slot | subslot] slot-number reload command. If the reload fails to correct the problem, collect the output of the error message, the logs, and the output of show tech-support and provide the gathered information to a Cisco technical support representative.

%IM-2-INVALID ACT MSG: Virtualization Service[chars]

Explanation The virtualization service activate message was received, however, the data it contained

could not be interpreted

Recommended Action

Enable the IOx-manager trace logs and repeat the activation of the virtualization service. Collect the IOx-manager logs and scan them for the cause.

%IM-2-INVALID_DEACT_MSG: Failed to process virtualization service deactivate message

Explanation The virtualization service deactivate message was received, however, the data it

contained could not be interpreted

Recommended Action Enable the IOx-manager trace logs and repeat the activation of the virtualization service.

Collect the IOx-manager logs and scan them for the cause.

%IM-2-ALLOC_VIRT_INST_RCS : Virtualization Service[chars]	
Explanation	A memory allocation request failed to allocate a data structure required to activate the virtualization service.
Recommended Action	Enable the IOx-manager trace logs and repeat the activation of the virtualization service. Collect the IOx-manager logs and scan them for the cause.

%IM-2-START_FAILED : Virtualization Service[chars]	
Explanation	The named virtualization service failed to start.
Recommended Action	Enable the IOx-manager trace logs and repeat the activation of the virtualization service. Collect the IOx-manager logs and scan them for the cause.

%IM-2-VIRT_INST_MEMORY : Virtualization Service[chars]	
Explanation	The virtualization service requires physical memory in excess of the free memory available to virtualization services.
Recommended Action	Enable the IOx-manager trace logs and repeat the activation of the virtualization service. Collect the IOx-manager logs and scan them for the cause.

%IM-2-VIRT_INST_DISK : Virtualization Service[chars]	
Explanation	The virtualization service requires Disk Storage in excess of the Free Disk Storage available to virtualization services.
Recommended Action	Enable the IOx-manager trace logs and repeat the activation of the virtualization service. Collect the IOx-manager logs and scan them for the cause.

%IM-2-MEMORY_LIMIT : Virtualization Service[chars]	
Explanation	The virtualization service machine definition file is requesting more memory than the system has available for virtualization services.
Recommended Action	Enable the IOx-manager trace logs and repeat the activation of the virtualization service. Collect the IOx-manager logs and scan them for the cause.

%IM-2-VCPU_LIMIT : Virtualization Service[chars]	
Explanation	The virtualization service machine definition file is requesting more VCPUs than the system has reserved for virtualization services.
Recommended Action	Enable the IOx-manager trace logs and repeat the activation of the virtualization service. Collect the IOx-manager logs and scan them for the cause.

%IM-2-DISK_IMAGE_PATH : Virtualization Service[chars]	
Explanation	The virtualization service machine definition file contains an invalid disk image path for one of the disk devices. This may be a Harddisk, CDROM or USB storage device.
Recommended Action	Enable the IOx-manager trace logs and repeat the activation of the virtualization service. Collect the IOx-manager logs and scan them for the cause.

%IM-2-VIRT_INST_LOG_UNTHROTTLE : Failed to unthrottle the log for virtualization service [chars]	
Explanation	The named virtualization service had sent overwhelming sys log messages and its log had been throttled as a result, but system has failed to unthrottle it for some reason.
Recommended Action	For debugging collect the iox-manager logs and scan them for the cause.

%IM-2-VIRT_INST_STATE : Virtualization Service[chars]	
Explanation	The named virtualization service has failed. It is no longer running either because the guest OS has failed, the guest OS has shut down the machine or the emulator has failed.
Recommended Action	An attempt at restarting the virtualization service can be made from the IOS configuration by doing a no activate/activate. For debugging collect the IOx-manager logs and scan them for the cause.

%IM-2-FIND_VIRT_INST_ENTRY : Failed to find virtualization service with id [int] in the IOx-manager list	
Explanation	The virtualization service with the ID named could not be located in the IOx-manager list.
Recommended Action	Enable the IOx-manager trace logs and repeat the activation of the virtualization service. Collect the IOx-manager logs and scan them for the cause.

%IM-5-AUX : Virtualization Service[chars]	
Explanation	The AUX login to a virtualization service may allow the user access to system functions that may not have been tested or may interact with the system in unintended ways. Use with caution.
Recommended Action	No action is required

${\bf \%IM-2-INVALID_UNPROV_MSG: Failed\ to\ process\ virtualization\ service\ unprovision\ message}$		
Explanation The virtualization service unprovision message was received, however, the data contained could not be interpreted		
Recommended Action	Enable the IOx-manager trace logs and repeat the activation followed by deactivation and then unprovision of the virtualization service. Collect the IOx-manager logs and scan them for the cause.	

%IM-2-VCPU_INVALID : Virtualization Service[chars]		
Explanation The virtualization service machine definition file is requesting invalid VCPU value		
Recommended Action	Enable the IOx-manager trace logs and repeat the activation of the virtualization service. Collect the IOx-manager logs and scan them for the cause.	

%IM-2-CPUSHARES_LIMIT : Virtualization Service[chars]		
Explanation	The virtualization service machine definition file is requesting more CPU shares than the system has available for virtualization services.	
Recommended Action	Deactivate any other virtualization services to free up CPU share resources and activate this virtualization service. If that does not address the problem, then enable the IOx-manager trace logs and repeat the activation of the virtualization service. Collect the IOx-manager logs and scan them for the cause.	

%IM-2-INSTALL_FAILURE : Virtualization Service[chars]		
Explanation	Explanation The installation of the virtualization service failed.	
Recommended Action	Enable the IOx-manager trace logs and repeat the installation of the virtualization service. Collect the IOx-manager logs and scan them for the cause.	

%IM-2-INSTALL_MEDIA_RETRY : VM install media still unavailable.[chars]		
Explanation	The install media was not detected. Waiting for udev to complete install media(harddisk) detection.	
Recommended Action	After IOx-manager exceeds the maximum retry limit, verify if install media (harddisk) is accessible and retry the installation again.	

$\% IM-2-VIRT_INST_MGMT_INTERFACE$: Virtualization service [chars] has no management interface defined but it is configured in CLI.

Explanation	A management	interface	is o	configured	but none	is o	defined

%IM-2-VIRT_INST_MGMT_INTERFACE: Virtualization service [chars] has no management interface defined but it is configured in CLI.

Recommended

Action

Deactivate the virtualization service, remove the management interface configuration

CLI, and reactivate the virtual-service.

%IM-2-GENERAL FAILURE : Virtualization Service[chars]

Explanation The named virtualization service has triggered the log. Please interpret the log in the

context of the virtualization services.

Recommended Action

No action is required

%IM-3-SDWRAP_ERR : Description: [chars], errcode: [dec]

Explanation Debug infrastructure error

Recommended

Collect the IOx-manager logs and scan them for the cause.

Action

%IM-3-PSS_ERR : Purpose: [chars], URI: [chars], errcode: [dec]

Explanation Persistent Storage Service handling error

Recommended

Action

Collect the IOx-manager logs and scan them for the cause.

%IM-3-PSS_SNAPSHOT_ERR : Source URI: [chars], Destination URI: [chars], errcode: [dec]

Persistent Storage Service snapshot error Explanation

Recommended

Collect the IOx-manager logs and scan them for the cause.

Action

%IM-2-NETWORK_CONFIG_ERROR : Virtualization Service[chars]

Explanation A network configuration error has been detected for the named virtualization service.

Recommended

No action is required

Action

%IM-2-INSTALL_LOG : [chars] [chars] [chars]		
Explanation The installation log of the named virtualization service, is to provide more informat about long running operation, that could affect the control of CLI		
Recommended Action	No action is required	

%IM-2-UPGRADE_LOG : [chars] [chars] [chars]		
Explanation	The upgrade log of the named virtualization service, is to provide more information about long running operation, that could affect the control of CLI	
Recommended Action	No action is required	

%IM-2-INSTALL_STATE : [chars] '[chars] [chars]		
Explanation	The installation state of the named virtualization service has changed as notified by IOx-manager.	
Recommended Action	In the failed case, check IOx-manager's logs for the cause of the failure. In the successful case, this notification can be ignored.	

%IM-2-UNINSTALL_ALL_VMS : All Virtualization Services are being uninstalled [chars][chars]		
Explanation All virtualization services are being uninstalled by IOx-manager.		
Recommended Action	Examine the reason given as to why all virtualization services are being uninstalled for more information. If the reason indicated is due to some error condition, check IOx-manager's logs for the cause of the failure.	

%IM-2-ACTIVATION_STATE : [chars] '[chars] [chars]		
Explanation	The activation state of the named virtualization service has changed as notified by IOx-manager.	
Recommended Action	In the failed case, check IOx-manager's logs for the cause of the failure. In the successful case, this notification can be ignored.	

%IM-4-WATCHDOG_TIMER: [chars] '[chars] (chars]		
Explanation	The watchdog timer configured for the named virtual service has expired.	
Recommended Action	Check any logs produced by the virtualization service to determine the cause.	

%IM-2-HA_SYNC_ERR : [chars] '[chars]	
Explanation	The ha-sync persistent storage disk for the virtualization service cannot be watched for sync to standby RP.
Recommended Action	Collect the IOx-manager logs and scan them for the cause.

%IM-2-DEACT_FOR_ISSU : [chars] Max ([int]s)	
Explanation	An ISSU event is pending. Any active VMs will be automatically deactivated to allow ISSU preprocessing to validate the environment. Any ISSU-deactivated VMs will be automatically restarted if the ISSU is cancelled.
Recommended Action	None. Allow the ISSU to continue and the VMs will restart when the ISSU completes or cancel the ISSU and IOx-manager will automatically

%IM-2-RESET_FORCE : Virtualization Services non-recoverable reset command processed	
Explanation	A 'virtualization service reset force' command has been entered and processed. This action initiates a cleanup of last resort. Occasionally a VM will get into an unrecoverable state that prevents it from activating but also from uninstalling. This is a rare event but when it happens the only resort may be to remove the .conf control file and reboot, which forces a cleanup of all previously installed VM files and artifacts. Note that once this command is used, current VMs are considered to be in an unstable or unpredictable state, and all future install, uninstall, upgrade, and activation commands will be blocked.
Recommended Action	Once the command is entered and accepted, there is no recourse but to restart the system.

%IM-2-MOVE_STATE : [chars] '[chars] [chars]	
Explanation	The move of the core or log file of the named virtualization service has as been successful or failed as notified by IOx-manager.
Recommended Action	In the failed case, check IOx-manager's logs for the cause of the failure. In the successful case, this notification can be ignored.

%IM-2-RSYNC_STATE : [chars] [chars] [chars]	
Explanation	IOx-manager tries to remote sync the virtual-instance configuration file and the OVA repository to all online nodes. If rsync fails even after consecutive retries, this notification would be raised.
Recommended Action	In the failed case, check IOx-manager's logs for the cause of the failure. Check for the rsync error code and root cause the same.

%IM-2-HA_SYNC_THREAD_STATE : HA remote sychronize thread has failed and exited.	
Explanation	IOx-manager tries to remote sync the OVA repository to all online nodes using a separate thread. If that thread fails, this notification would be raised.
Recommended Action	In the failed case, check IOx-manager's logs for the cause of the failure. Check for the pthread error msg and root cause the same.

%IM-2-HA_STATE : [chars] [chars] [chars]	
Explanation	IOx-manager tries to detect the role/slot of various nodes on HA events from the platform. If any of those event callbacks fail, this notification would be raised.
Recommended Action	In the failed case, check IOx-manager's logs for the cause of the failure. Check for the HA event error msg and root cause the same.

%IM-2-HA_SWITCHOVER_STATE : [chars] [chars] [chars]	
Explanation	IOx-manager HA switchover state related messages for a virtual-service whilst it is being recovered on newly active RP after a HA switchover.
Recommended Action	In the failed case, check IOx-manager's logs for the cause of the failure. Check for the HA event error msg and root cause the same.

%IM-4-HA_SYNC_NEEDED: If using the guest shell, please use 'guestshell sync' if you want to preserve state on standby in case of supervisor switchover	
Explanation	Message notifying user that he needs to manually synchronize the Virtualization service contents to standby supervisor in order to preserve these contents in case of a supervisor switchover. Currently only applicable to the guest shell
Recommended Action	User can type the 'guestshell sync' command on active supervisor to synchronize it's contents to the standby supervisor if desired.

%IM-2-RESIZE_OPER_STATE : Virtualization service '[chars]' [chars][chars] to '[int]' [chars]	
Explanation	IOx-manager attempts to resize various VM parameters like rootfs size, CPU share, memory if requested by user. Success/failure status messages for these resize operations are communicated by this syslog.
Recommended Action	In the failed case, check IOx-manager's logs for the cause of the failure. Check for the HA event error msg and root cause the same.

Action

%IM-2-GUESTSHELL_ENABLED : The guest shell has been enabled. The command '[chars]' may be used to access it, '[chars] destroy' to remove it.	
Explanation	Informs the user that the guest shell virtualization service has been enabled (which is done by default).
Recommended	The user may use or remove the guest shell with the commands specified.

%IM-5-PERMISSION_DENIED : Virtualization Service '[chars]' is not owned by client IOSd	
Explanation	An attempt was made to modify a virtual-service that is not owned by by the client. The request was rejected.
Recommended Action	No action is required.

%IM-2-IOX_INST_CRIT : IOX SERVICE [chars] LOG: [chars]	
Explanation	The named virtual service has triggered the log. Please interpret the log in the context of the virtual services.
Recommended Action	No action is required

%IM-3-IOX_INST_ERR : IOX SERVICE [chars] LOG: [chars]	
Explanation	The named IOX service has triggered the log. Please interpret the log in the context of the IOX services.
Recommended Action	No action is required

%IM-4-IOX_INST_WARN : IOX SERVICE [chars] LOG: [chars]	
Explanation	The named IOX service has triggered the log. Please interpret the log in the context of the IOX services.
Recommended Action	No action is required

%IM-5-IOX_INST_NOTICE : IOX SERVICE [chars] LOG: [chars]	
Explanation	The named IOX service has triggered the log. Please interpret the log in the context of the IOX services.

%IM-5-IOX_INST_NOTICE : IOX SERVICE [chars] LOG: [chars]

Recommended

No action is required

Action

%IM-6-IOX_INST_INFO: IOX SERVICE [chars] LOG: [chars]

Explanation The named IOX service has triggered the log. Please interpret the log in the context

of the IOX services.

Recommended

Action

No action is required

%IM-7-IOX_INST_DEBUG : IOX SERVICE [chars] LOG: [chars]

Explanation The named IOX service has triggered the log. Please interpret the log in the context

of the IOX services.

Recommended

Action

No action is required

%IM-2-IOX_INST_LOG_UNTHROTTLE: Failed to unthrottle the log for IOX service [chars]

Explanation The named IOX service had sent overwhelming sys log messages and its log had been

throttled as a result, but system has failed to unthrottle it for some reason.

Recommended

Action

For debugging collect the ioxman logs and scan them for the cause.

%IM-6-IOX_RECONCILE_INFO: App-hosting application reconcile process [chars]

Explanation Indicates stage of reconcile (application recovery) process.

Recommended

Action

No action is required

IMGR

%IMGR-0-FIPS_FMFP_BYPASS_TEST: NIST bypass test failed for [chars].

Explanation Forwarding Manager IPsec component detected a discrepancy when adding or deleting

a security sensitive object. This could be due to a hardware or software resouce

limitation or a software defect.

Recommended Action Check the logs for information on the relevant object download states. Remove the object or a parent object in question. If the problem persists reboot the forwarding

processor (ESP).

%IMGR-6-FIPS_FMFP_CRNG_TEST : continuous [chars]approved RNG test failed.	
Explanation	Forwarding Manager IPsec component detected two identical random number sequences. This could be due to a hardware mulfunction or a software defect.
Recommended Action	If the problem persists reboot the forwarding processor (ESP).

%IMGR-6-FIPS_FMFP_OLAP_TEST : FIPS-approved RNG key seed and state overlap.	
Explanation	Forwarding Manager IPsec component detected an overlap in FIPS-approved RNG key seed and state. This could be due to a hardware mulfunction or a software defect.
Recommended Action	If the problem persists reboot the forwarding processor (ESP).

%IMGR-6-FIPS_FMFP_KAT_TEST : power up cryptographic self-test didnot run to completion: [chars].	
Explanation	Forwarding Manager power up known answer self-test (KAT) failed. This could be due to a hardware malfunction or a software defect.
Recommended Action	If using ipsec, reboot the forwarding processor (ESP).

%IMGR-0-FIPS_CPP_CLIENT_BYPASS_TEST : CPP Client FIPS bypass test failed for [chars].	
Explanation	Forwarding Manager CPP client IPSEC bypass test failed. This could be due to a hardware malfunction or a software defect.
Recommended Action	If the problem persists reboot the forwarding processor (ESP).

%IMGR-6-FIPS_FMFP_N2_ERR_FAIL : Cryptographic coprocessor non-critical failure: [chars].	
Explanation	Cryptographic coprocessor non-critical operation failed. If the problem persists reboot the forwarding processor(ESP)
Recommended Action	If the problem persists reboot the forwarding processor (ESP).

%IMGR-0-FIPS_FMFP_N2_SEVERE_ERR_FAIL : Cryptographic coprocessor severe failure: [chars].	
Explanation	Cryptographic coprocessor critical operation failed. Further data processing on ESP is halted

%IMGR-0-FIPS_FMFP_N2_SEVERE_ERR_FAIL: Cryptographic coprocessor severe failure: [chars].

Recommended

forwarding processor (ESP) is rebooted automatically. no action needed

Action

%IMGR-6-FMFP_KAT_TEST_RESULT : crypto self-test for algorithm: ([chars] ... passed).

Explanation

Forwarding Manager power up known answer self-test (KAT) success. This is not an

error message

Recommended

Action

No action needed.

%IMGR-6-FMFP_IPSEC_MIN_MTU_INFO: MTU smaller than minimum IPSec MTU, [chars].

Explanation

Minimum MTU supported by crypto processor is 256B, MTU lower than 256B is set

to 256B

Recommended

Action

No action needed

%IMGR-6-FMFP_IPSEC_UNSUPPORTED_CIPHER: Cipher [chars] is not supported on this ESP.

Explanation

This ESP does not support this IPSec cipher

Recommended

Action

No action needed

%IMGR-6-FMFP_IPSEC_CRYPTO_CTRL_THROTTLED: IPsec Control Plane Overload Crypto Device: [chars].

Explanation

This ESP crypto device is overloaded.

Recommended

Action

May need to config platform ipsec control-plane medium|heavy

INDXOBJ

%INDXOBJ-3-INTERRUPT: index object routine [chars] called from interrupt context

Explanation

inappropriate index object routine called from interrupt routine.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%INDXOBJ-3-ADD_ERROR : index add for [chars] failed: [chars]	
Explanation	index object routine error
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

INFRA

Action

%INFRA-3-INVALID_GPM_ACCESS: Invalid GPM [chars] at [hex] HAL start [hex] HAL end [hex] INFRA start [hex] INFRA [hex] NET [hex], MSGDEF_LIMIT_MEDIUM Explanation Processing packet went beyond valid packet data, packet was possibly invalid, ppe

info and encrypted pkt dump follow

Recommended LOG_STD_ACTION

 $\% INFRA-3-INVALID_GPM_ACCESS_INFO: [hex] [hex]$

Explanation Registers associated with previous exception error

Recommended LOG_STD_ACTION **Action**

 ${\bf \%INFRA-3-INVALID_GPM_ACCESS_DATA:}$

Explanation Packet associated with previous exception error The packet data has been encrypted

Recommended LOG_STD_ACTION **Action**

INSTALL

%INSTALL-5-OPERATION_START_INFO : Started [chars] package [chars]	
Explanation	This message is used to indicate the beginning of operations.
Recommended Action	No action required. This is not an error, it is an indication that the system is starting the operation.

%INSTALL-5-OPERATION_COMPLETED_INFO : Completed [chars] package [chars]	
Explanation	This message is used to indicate the completion of operations.
Recommended Action	No action required. This is not an error, it is an indication that the system completed the operation.

%INSTALL-3-OPERATION_ERROR_MESSAGE : Failed to [chars] package [chars], Error: [chars]	
Explanation	This message is used to inform the failure reason.
Recommended Action	Please refer to the error message to analyze the cause of failure.

%INSTALL-5-INSTALL_START_INFO : Started [chars] [chars]	
Explanation	This message is used to indicate the beginning of install operations.
Recommended Action	No action required. This is not an error, it is an indication that the system is starting this operation.

%INSTALL-5-INSTALL_COMPLETED_INFO : Completed [chars] [chars]	
Explanation	This message is used to indicate the completion of install operations.
Recommended Action	No action required. This is not an error, it is an indication that the system completed this operation.

%INSTALL-3-INSTANT_ERROR_MESSAGE : Error Message: [chars]	
Explanation	This message is used to send a instant erorr message.
Recommended Action	No action required.

%INSTALL-5-INSTALL_AUTO_ABORT : Install auto abort timer expired: initiating abort	
Explanation	An install operation has been aborted because the auto abort timer has expired.
Recommended Action	No user action is needed. If you want to commit the ISSU upgrade, redo the upgrade. Otherwise, this is an informational message only.

%INSTALL-5-INSTALL_AUTO_ABORT_TIMER_PROGRESS : Install auto abort timer will expire in [dec] seconds	
Explanation	An install operation will be aborted after specified seconds of time.

%INSTALL-5-INSTALL_AUTO_ABORT_TIMER_PROGRESS : Install auto abort timer will expire in [dec] seconds

Recommended

Action

No user action is needed. If you want to commit the ISSU upgrade, redo the upgrade.

Otherwise, this is an informational message only.

INTERCHASSIS_REDUNDANCY through IOSXE_FMANRP

- INTERCHASSIS_REDUNDANCY
- INTERFACE_API
- IOMD_INFRA
- IOSD
- IOSD INFRA
- IOSXE_APS
- IOSXE_CXSC
- IOSXE_ETHERCHAN
- IOSXE EZMENU
- IOSXE FMANRP

INTERCHASSIS_REDUNDANCY

*INTERCHASSIS_REDUNDANCY-4-STDBY_PRESENT : Removal of standby RP in location [chars]	is
recommended for inter-chassis redundancy configuration	

Explanation Removal of standby RP from the chassis is recommended for inter-chassis redundan	су
---	----

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

INTERFACE_API

%INTERFACE_API-4-BADSWIDB : [chars] may not be referencing the correct swidb

Explanation An internal software error occurred.

%INTERFACE_API-4-BADSWIDB: [chars] may not be referencing the correct swidb

Recommended Action

If this message recurs, copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%INTERFACE_API-4-BADPAKINPUT : pak->if_input is not initialized

Explanation

An internal software error occurred.

Recommended Action

If this message recurs, copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%INTERFACE_API-1-NAMESTRTOOLONG: Interface name [chars].[int] exceeded maximum allowed length [dec]

Explanation

An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%INTERFACE_API-3-NOADDSUBBLOCK: The [chars] subblock named [chars] was not added to [chars]

Explanation

A software error has occured, this message is displayed when IDB subblocks cannot be added.

Recommended

Action Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%INTERFACE_API-3-INVALIDSUBBLOCKPARAMETERS: Invalid subblock parameters for [chars] were supplied.

Explanation

An internal software error occurred.

%INTERFACE_API-3-INVALIDSUBBLOCKPARAMETERS : Invalid subblock parameters for [chars] were supplied.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show idb and show tech-support commands to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit BUG_TOOLKIT . If you still require assistance, open a case with the Technical Assistance Center via the Internet TAC_CASE_OPEN , or contact your Cisco technical support representative and provide the representative with the gathered information.

%INTERFACE_API-3-SUBNUMDBERR : subnum [hex] error in [chars]	
Explanation	A software error has occured, this message is displayed when a problem has occured with a sub_number db.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%INTERFACE_API-1-NOMORESWIDB : No more SWIDB can be allocated, maximum allowed [dec]	
Explanation	No more Interfaces can be created because the maximum number of SWIDB allowed for this platform has been reached
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%INTERFACE_API-1-NOMORE_HASWIDBS: No more IDBS can be created. The maximum allowed numbers, [int], has been reached on Standby Please force redundancy mode to RPR if full Active Capacity, [int], is needed

Explanation

No more Software IDB numbers can be Created. The maximum allowed numbers has been reached for this High Available System.

Recommended

%INTERFACE_API-1-NOMOREHWIDBNUMBERS: No more hardware IDB numbers can be issued. The maximum allowed numbers, [dec], has been reached for this platform.

Explanation

Action

No more hardware IDB numbers can be issued. The maximum allowed numbers has been reached for this platform.

%INTERFACE_API-1-NOMOREHWIDBNUMBERS: No more hardware IDB numbers can be issued. The maximum allowed numbers, [dec], has been reached for this platform.

Recommended In addition to the following, copy the information from **show idb**.

Action LOG_STD_ACTION

 ${\tt \%INTERFACE_API-1-NOMORESWIDBNUMBERS: No more software IDB numbers can be issued. The maximum allowed numbers, [dec], has been reached for this platform.}$

Explanation No more software IDB numbers can be issued. The maximum allowed numbers has

been reached for this platform.

Recommended In addition to the following, copy the information from **show idb**.

Action LOG_STD_ACTION

%INTERFACE_API-4-BADPAKOUTPUT: pak->if_output is not initialized on interface [chars]

Explanation An internal software error occurred.

Recommended Action

If this message recurs, copy the error message exactly as it appears on the console or

in the system log. Perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support

representative and provide the representative with the gathered information.

%INTERFACE_API-4-BADPOINTER: Function [chars] detected an invalid [chars] pointer of %08IX, ignoring

Explanation A software error has occurred, this message is displayed when an invalid pointer is

detected.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the

error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support

representative and provide the representative with the gathered information.

%INTERFACE_API-3-NODESTROYSUBBLOCK: The [chars] subblock named [chars] was not removed

Explanation A software error has occured, this message is displayed when IDB subblocks cannot

be removed.

%INTERFACE_API-3-NODESTROYSUBBLOCK: The [chars] subblock named [chars] was not removed

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%INTERFACE API-3-CANNOTGETMTU: Error [dec] received while getting MTU: [chars]. Using default [int]

Explanation

A software error has occurred while attempting to retrieve the MTU value from the

interface.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%INTERFACE_API-3-NOSUBBLOCK: [chars] subblock does not exist on interface [chars]

Explanation

An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%INTERFACE API-4-TBLERROR: A error occurred while using the Index Table utility for [chars].

Explanation

A software error has occurred; this message is displayed when an Index table feature

could not be used successfully.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%INTERFACE API-3-BADIDBSTATUSCHANGECALL: Invalid function call at interrupt level.

Explanation

An internal function was illegally called at interrupt level. This error might be caused by incorrectly coded creation or deletion of an interface, or during an OIR operation.

%INTERFACE_API-3-BADIDBSTATUSCHANGECALL: Invalid function call at interrupt level.

Recommended Action

Perform a search of the Bug Toolkit, BUG_TOOLKIT. If you still require assistance, copy the error message exactly as it appears on the console or in the system log. Issue the **show tech** command and copy the output. If you performed any actions before the error message appeared, make a note of this. Open a case with the Technical Assistance Center via the Internet TAC_CASE_OPEN, or contact your Cisco technical support representative and provide the representative with the gathered information.

%INTERFACE_API-3-IFNUMTOIDBERROR: Error occurred while using the ifnum to idb table for interface [chars], if number [dec], during [chars]

Explanation

A software error has occurred. This message is displayed when an operation on the if number to idb mapping table could not be performed successfully.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%INTERFACE_API-3-HWIDBQREENTRANT : [chars] in progress of being inserted/removed, ignoring new request to [chars]

Explanation

A software error has occurred while attempting to insert or remove the interface into the system as there's already another attempt in progress to insert or remove this interface. The first attempt must complete before a new attempt can be started. The user should retry this operation at a later time.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOMD_INFRA

%IOMD_INFRA-4-BADPOINTER: Function [chars] detected an invalid [chars] pointer of %08IX, ignoring

Explanation

A software error has occurred, this message is displayed when an invalid pointer is detected.

%IOMD_INFRA-4-BADPOINTER: Function [chars] detected an invalid [chars] pointer of %08IX, ignoring

Recommended Action

Examine the logs for IOMD. If the problem persists, copy the message exactly as it appears on the console or in the system log. Research and attempt to resolve the issue using the tools and utilities provided at http://www.cisco.com/tac. With some messages, these tools and utilities will supply clarifying information. Search for resolved software issues using the Bug Toolkit at https://bst.cloudapps.cisco.com/bugsearch/. If you still require assistance, open a case with the Technical Assistance Center via the Internet athttps://mycase.cloudapps.cisco.com/case, or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOMD_INFRA-3-IPCSENDFAIL: IOMD failed to send a message [chars] reason: [chars]

Explanation

IOMD failed to send message to the RP

Recommended Action

Examine the logs for IOMD. If the problem persists, copy the message exactly as it appears on the console or in the system log. Research and attempt to resolve the issue using the tools and utilities provided at http://www.cisco.com/tac. With some messages, these tools and utilities will supply clarifying information. Search for resolved software issues using the Bug Toolkit at https://bst.cloudapps.cisco.com/bugsearch/. If you still require assistance, open a case with the Technical Assistance Center via the Internet athttps://mycase.cloudapps.cisco.com/case, or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOMD_INFRA-3-IPCALLOCFAIL: Failed to allocate IPC buffer [chars]

Explanation

The IM failed to allocate a buffer for communication with RSP

Recommended Action

Examine the logs for IOMD. If the problem persists, copy the message exactly as it appears on the console or in the system log. Research and attempt to resolve the issue using the tools and utilities provided at http://www.cisco.com/tac. With some messages, these tools and utilities will supply clarifying information. Search for resolved software issues using the Bug Toolkit at https://bst.cloudapps.cisco.com/bugsearch/. If you still require assistance, open a case with the Technical Assistance Center via the Internet athttps://mycase.cloudapps.cisco.com/case, or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOMD_INFRA-6-TDLMSG_INCOMPATIBLE : Failed to copy message [chars] to buffer, not allowed for current domain.

Explanation

Failure to marshal a message indicates an incompatibility \ with the intended recipient.

%IOMD_INFRA-6-TDLMSG_INCOMPATIBLE : Failed to copy message [chars] to buffer, not allowed for current domain.

Recommended Action

Examine the logs for IOMD. If the problem persists, copy the message exactly as it appears on the console or in the system log. Research and attempt to resolve the issue using the tools and utilities provided at http://www.cisco.com/tac. With some messages, these tools and utilities will supply clarifying information. Search for resolved software issues using the Bug Toolkit at https://bst.cloudapps.cisco.com/bugsearch/. If you still require assistance, open a case with the Technical Assistance Center via the Internet athttps://mycase.cloudapps.cisco.com/case, or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOMD_INFRA-3-INVALID_SLOT_NUM: An invalid slot number is specified in one of the internal APIs. slot=[dec] max_slot=[dec]

Explanation

Invalid slot number to find the TDL domain

Recommended Action

Examine the logs for IOMD. If the problem persists, copy the message exactly as it appears on the console or in the system log. Research and attempt to resolve the issue using the tools and utilities provided at http://www.cisco.com/tac. With some messages, these tools and utilities will supply clarifying information. Search for resolved software issues using the Bug Toolkit at https://bst.cloudapps.cisco.com/bugsearch/. If you still require assistance, open a case with the Technical Assistance Center via the Internet athttps://mycase.cloudapps.cisco.com/case, or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOMD_INFRA-3-INVALID_BAY_NUM : An invalid bay number is specified in one of the internal APIs. bay=[dec] max_bay=[dec]

Explanation

Invalid bay number to find the TDL domain

Recommended Action

Examine the logs for IOMD. If the problem persists, copy the message exactly as it appears on the console or in the system log. Research and attempt to resolve the issue using the tools and utilities provided at http://www.cisco.com/tac. With some messages, these tools and utilities will supply clarifying information. Search for resolved software issues using the Bug Toolkit at https://bst.cloudapps.cisco.com/bugsearch/. If you still require assistance, open a case with the Technical Assistance Center via the Internet athttps://mycase.cloudapps.cisco.com/case, or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOMD_INFRA-4-INTR_OVER_LIMIT : IOMd main thread disabled interrupt for [int] msec.

Explanation

IOMd main thread process disabled interrupt too long

%IOMD_INFRA-4-INTR_OVER_LIMIT: IOMd main thread disabled interrupt for [int] msec.

Recommended Action

Examine the logs for IOMD. If the problem persists, copy the message exactly as it appears on the console or in the system log. Research and attempt to resolve the issue using the tools and utilities provided at http://www.cisco.com/tac. With some messages, these tools and utilities will supply clarifying information. Search for resolved software issues using the Bug Toolkit at https://bst.cloudapps.cisco.com/bugsearch/. If you still require assistance, open a case with the Technical Assistance Center via the Internet athttps://mycase.cloudapps.cisco.com/case, or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOMD_INFRA-3-INTR_EVENT : IOMd fast thread event ([dec]).

Explanation

IOMd fast thread event

Recommended Action

Examine the logs for IOMD. If the problem persists, copy the message exactly as it appears on the console or in the system log. Research and attempt to resolve the issue using the tools and utilities provided at http://www.cisco.com/tac. With some messages, these tools and utilities will supply clarifying information. Search for resolved software issues using the Bug Toolkit at https://bst.cloudapps.cisco.com/bugsearch/. If you still require assistance, open a case with the Technical Assistance Center via the Internet athttps://mycase.cloudapps.cisco.com/case, or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOMD_INFRA-3-I2C_WRITE: An I2C write has failed because [chars]

Explanation

An I2C write has failed. This could be due to a hardware or software defect.

Recommended Action

Note the time of the error message and examine the logs for I2C errors. If the logs provide information about a correctable problem, correct the problem. If the problem is not correctable or the logs are not helpful, collect the output of the error message, the logs, and the output of show tech-support and provide the gathered information to a Cisco technical support representative.

%IOMD_INFRA-3-I2C_READ : An I2C read has failed because [chars]

Explanation

An I2C read has failed. This could be due to a hardware or software defect.

Recommended Action

Note the time of the error message and examine the logs for I2C errors. If the logs provide information about a correctable problem, correct the problem. If the problem is not correctable or the logs are not helpful, collect the output of the error message, the logs, and the output of show tech-support and provide the gathered information to a Cisco technical support representative.

%IOMD_INFRA-3-LINECARDDIAGSFAILED : Module [chars] in Slot [dec] failed online diagnostics. Please use 'show post' for more details	
Explanation	Online Diag has failed. This could be due to a hardware or software defect.
Recommended Action	Note the time of the error message and examine the logs for errors. If the logs provide information about a correctable problem, correct the problem. If the problem is not correctable or the logs are not helpful, collect the output of the error message, the logs, and the output of show tech-support and provide the gathered information to a Cisco technical support representative.

IOSD

%IOSD-3-BIPC_REJECT : Could not accept ipc connection: [chars]		
Explanation	This error occurs if shell-manager has denied an ipc connection request from IOS.	
Recommended Action	Check the connection request parameters.	

%IOSD-3-TDL_PROPERTIES : Could not set message properties for connection: [chars]		
Explanation	This error occurs if shell-manager is unable to set message properties for the IOS-si connection	
Recommended Action	Check the connection request parameters.	

IOSD_INFRA

%IOSD_INFRA-6-IFS_DEVICE_OIR : Device [chars] [chars]		
Explanation	USB inserted/removed	
Recommended Action	No action is required.	

%IOSD_INFRA-3-IFS_DEVICE_DETECT_FAIL : Device [chars] [chars]		
Explanation	USB detection failed	
Recommended Action	USB Insertion could not be handled completely. Device needs to be removed and re-inserted	

IOSXE_APS

%IOSXE_APS-3-GROUP_CONFIG_FAIL : Group change for interface [chars] Group [dec] failed		
Explanation	Group change for interface has failed	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_APS-3-CONFIG_FAIL : config change for interface [chars] Group [dec] failed			
Explanation config for an interface to forwarding plane has failed			
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.		

%IOSXE_APS-3-FLOWIDDELETIONFAILED: Deletion of APS flow ID with manager failed for interface [chars] group [dec]		
Explanation	An unexpected condition has occurred that deletion of APS flow ID.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show interface command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_APS-3-FLOWIDALLOCFAILED : Allocation of APS flow ID with manager failed for interface [chars] group [dec]		
Explanation	An unexpected condition has occurred that allocation of APS flow ID. failed	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show interface command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_APS-3-PAIR_CONFIG_FAIL : Pair config for interface [chars] Group [dec] failed		
Explanation	Pair config for interface has failed	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

| Second | Pair config for interface | Chars | Group | Chars | Chars | Group | Chars |

%IOSXE_APS-3-FLOWCONFIGTOCCFAILED : Flow id to cc for interface [chars] Group [dec] failed				
Explanation Flow id to cc for an interface has failed				
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.			

%IOSXE_APS-3-DOWNLOADFAIL : Unable to download [chars] message to [chars]		
Explanation	An unexpected condition has occurred which resulted in a configuration not being sent to the reported process.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

IOSXE CXSC

%IOSXE_CXSC-3-ALLOC : Failed to allocate message	for pro	position
--	---------	----------

Explanation When attempting to program the dataplane with a CXSC proposition object, there was no enough memory to allocate the message.

%IOSXE_CXSC-3-ALLOC: Failed to allocate message for proposition

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE CXSC-3-MESSAGE: Failed to send message for proposition

Explanation

When the proposition was being prepared for sending to the data plane, there was an

error.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_CXSC-3-ACTION: Unknown proposition action ([dec])

Explanation

When the proposition was being sent to the data plane, the action was unknown error.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE CXSC-3-BAD PROPOSITION: Proposition obj corrupt

Explanation

When the proposition was being sent to the data plane, the object itself is corrupt.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_CXSC-3-BAD_SUMMARY : Summary obj corrupt

Explanation

When the proposition summary was being sent to the data plane, the object itself is corrupt.

%IOSXE_CXSC-3-BAD_SUMMARY: Summary obj corrupt

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_CXSC-4-DUAL_RP_UNSUPPORTED : Dual RPs are not supported in conjunction with CXSC

Explanation

CXSC is not supported in a dual RP environment. To resolve this warning, either unconfigure CXSC or remove the redundant Route Processor.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_CXSC-3-RF_INIT: Failed to initialize CXSC Redundancy Facility client

Explanation

An unexpected condition occurred where the CXSC Redundancy Facility failed to initialize.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE CXSC-3-STILE ACTIVATE : Failed to activate NBAR classification: ([dec])

Explanation

An unexpected condition occurred where the CXSC NBAR protocol classification failed to activate.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_CXSC-3-STATISTICS_ALLOCATION: Unable to allocate space for statistics

Explanation

During initialization, there was failure in the allocation of the memory to gather the statistics. It is non fatal, but after seeing this message, the CXSC subsystem will not be able to gather statistics.

%IOSXE_CXSC-3-STATISTICS_ALLOCATION: Unable to allocate space for statistics

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE CXSC-3-BAD PROTOCOLPACK: Invalid Protocol Pack object

Explanation When the Protocol Pack was being sent to the data plane, the object's contents were

invalid.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_CXSC-3-FILESYSTEM_ERR: FileSystem Error ([chars]): Unable to Copy File from [chars] to [chars]

Explanation

Unable to copy the NBAR Protocol Pack File to the file system for subsequent loading. The system will revert to the previously loaded Protocol Pack.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_CXSC-3-INSUFFICIENT_ALLOC_IOSXE_VER: Insufficent memory allocated for IOSXE version String

Explanation

The input IOSXE Version String has insufficient memory to hold the IOSXE Version.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_CXSC-3-INSUFFICIENT_ALLOC_NBAR_VER: Insufficent memory allocated for NBAR Engine Version String

Explanation

The input NBAR Engine Version string has insufficient memory to hold the NBAR Engine Version.

%IOSXE_CXSC-3-INSUFFICIENT_ALLOC_NBAR_VER: Insufficent memory allocated for NBAR Engine Version String

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_CXSC-3-PLATFORM_TYPE : Unrecognised platform type. CPU ID [dec]		
Explanation	The platform that the cxsc service is being installed on is not recognised. The most likely cause is that this platform is not supported.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

IOSXE_ETHERCHAN

%IOSXE_ETHERCHAN-6-LINK_MTU : Interface [chars] MTU set to port-channel [chars] MTU [dec]	
Explanation	The MTU for the interface mentioned in the message is changed to match the MTU configured on the port channel interface
Recommended Action	No action is required.

%IOSXE_ETHERCHAN-3-LINK_MTU_FAIL : Failure in changing MTU of interface [chars] to port-channel [chars] MTU	
Explanation	The MTU for the interface mentioned in the message cannot be changed to match the MTU configured on the port channel interface
Recommended Action	Remove the link mentioned in the message from the port-channel group

IOSXE_EZMENU

%IOSXE_EZMENU-3-VIRT_SRVC_REGISTER : Failed to register '[chars]' with virtual service manager		
Explanation	An unexpected error has occured while trying to register this virtual service with the virtual service manager. This has prevented the virtual service from being enabled/disabled.	

%IOSXE_EZMENU-3-VIRT_SRVC_REGISTER: Failed to register '[chars]' with virtual service manager

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_FMANRP

%IOSXE_FMANRP-4-MSGDISPATCHNULL: TDL messages NULL from IOS. Explanation An unexpected condition has occurred while IOS trying to dispatch the TDL message handler functions for received TDL messages from Forwarding Manager. Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP-4-MSGDISPATCH : Unable to dispatch received TDL message '[chars]' from Forwarding Manager. LUID: [chars]	
Explanation	An unexpected condition has occurred while IOS trying to dispatch the TDL message handler functions for received TDL messages from Forwarding Manager.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP-4-MSGIPCERR : Unable to process received IPC messages from Forwarding Manager, error: [chars].	
Explanation	An unexpected condition has occurred while IOS trying to process received IPC message from Forwarding Manager.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP-3-EPOCHTDLMSGMARSHAL : Failed to copy epoch TDL message to IPC buffer, epoch number [dec]	
Explanation	This operation to build a TDL messages for epoch message has failed.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP-3-MSGMARSHALERR : Unable to copy IPC messages into transport buffer. Message: [chars]	
Explanation	An unexpected condition has occurred while IOS trying to copy IPC message to transport buffer in order to send the message from IOSd to Forwarding Manager.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP-3-MSGENQERR : Unable to enqueue IPC messages to IOS IPC queue. Message: [chars].	
Explanation	An unexpected condition has occurred while IOS trying to enqueue IPC message to IOS IPC queue in order to send the message to Forwarding Manager.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP-4-MSGNONTDLSTATSERR : Unable to process received non-TDL stats message from Forwarding Manager, error: [chars] ([dec]).	
Explanation	An unexpected condition has occurred while IOS trying to process received non-TDL stats message from Forwarding Manager.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_FMANRP_ADJ through **IOSXE_INFRA**

- IOSXE_FMANRP_ADJ
- IOSXE_FMANRP_CCE
- IOSXE_FMANRP_CEF
- IOSXE_FMANRP_FPM
- IOSXE_FMANRP_OBJID
- IOSXE_FMANRP_OBJID2
- IOSXE_FMANRP_RTMAP
- IOSXE_FMANRP_URPF
- IOSXE_FMANRP_ZONES
- IOSXE_INFRA

IOSXE_FMANRP_ADJ

%IOSXE_FMANRP_ADJ-3-NOADJ : Adjacency entry is null	
Explanation	An unexpected condition has occurred which is due to the absence of an adjacency entry structure.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show adjacency command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_ADJ-3-NOFIBHWIDB : FIB Interface [chars] is null	
Explanation	An unexpected condition has occurred which is due to the absence of a FIB interface structure.
Recommended Action	LOG_STD_SH_CMD_ACTION(show adj)

%IOSXE_FMANRP_ADJ-3-ENQUEFAIL: Unable to send [chars] [chars] message to Forwarding Manage Process	
Explanation	An unexpected condition has occurred which resulted in a configuration not being sent

to the Forwarding Manager Processs.

%IOSXE_FMANRP_ADJ-3-ENQUEFAIL: Unable to send [chars] [chars] message to Forwarding Manage	er
Process	

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_ADJ-3-ENCSIZE : Invalid encap length [dec] which is larger than max allowed [dec] bytes	
Explanation	An unexpected condition has occurred which is due to invalid adjacency encapsulation size being larger than the maximum value allowed.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_FMANRP_CCE

%IOSXE_FMANRP_CCE-4-CCE_STACK_LIMIT : Failed to create class [dec] filter list	
Explanation	An operation to send a filter list to the forwarding processor for a particular class has failed due to a resource issue. This may imply that the notification was dropped.
Recommended Action	LOG_STD_SH_CMD_ACTION(show class-map [type <class type=""> <name>])</name></class>

%IOSXE_FMANRP_CCE-3-CCE_INVALID_FILTER_RELN : Invalid filter relation [int]	
Explanation	An internal error occured when trying to build class-map information for one of the classes in a policy-map.
Recommended Action	LOG_STD_SH_CMD_ACTION(show policy-map [type <policy type=""> <name>])</name></policy>

%IOSXE_FMANRP_CCE-3-CCE_FILTER_OVERFLOW : Filter list overflow at type [chars]	
Explanation	An internal error occured when trying to build class-map information for one of the classes in a policy-map.
Recommended Action	LOG_STD_SH_CMD_ACTION(show class-map [type <class type=""> <name>])</name></class>

%IOSXE_FMANRP_CCE-3-CCE_CLASS_CREATE : Unable to create class [int].[int]	
Explanation	An error occured when trying to create a class-map.
Recommended Action	LOG_STD_SH_CMD_ACTION(show policy-map [type <policy type=""> <name>])</name></policy>

%IOSXE_FMANRP_CCE-4-CCE_NESTED_CLASS_LIMIT : Nested class [dec] layers cannot exceed 4	
Explanation	When configure nested classes as match statements, the total levels of nested classes cannot exceed 4 layers
Recommended Action	LOG_STD_SH_CMD_ACTION(show class-map [type <class type=""> <name>])</name></class>

IOSXE_FMANRP_CEF

%IOSXE_FMANRP_CEF-3-NOFIB : FIB entry is null	
Explanation	An unexpected condition has occurred which is due to the absence of a FIB entry structure.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show ip cef command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_CEF-3-NOFIBSB : FIB SB entry is null	
Explanation	An unexpected condition has occurred which is due to the absence of a FIB SB entry structure.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show ip cef command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_CEF-3-NOFIBTABLE : FIB table is null	
Explanation	An unexpected condition has occurred which is due to the absence of a FIB table structure.

%IOSXE_FMANRP_CEF-3-NOFIBTABLE : FIB table is null

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show ip cef** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_CEF-3-NOFIBIDB: FIB interface is null

Explanation

An unexpected condition has occurred which is due to the absence of a FIB interface structure.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show ip cef** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_CEF-3-ENQUEFAIL: Unable to send [chars] [chars] message to Forwarding Manager Process

Explanation

An unexpected condition has occurred which resulted in a configuration not being sent to the Forwarding Manager Processs.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_CEF-4-UPDFRAGSTATSERR : Update IP Fragmentation statistics error

Explanation

An unexpected condition has occurred when updating fragmentation statistics

Recommended Action

%IOSXE_FMANRP_CEF-4-UPDREASSSTATSERR : Update IP Reassembly statistics error	
Explanation	An unexpected condition has occurred when updating reassembly statistics
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_CEF-4-UPDSTATSERR : Update CEF statistics error	
Explanation	An unexpected condition has occurred when updating cef statistics
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_CEF-3-ROUTEMSGMARSHAL : Failed to copy route essage to IPC buffer for prefix [chars]/[dec] - [chars]	
Explanation	This operation to build a TDL messages for route download has failed.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_CEF-3-NOFIBPUSHCNT : FIB push counter is null	
Explanation	An unexpected condition has occurred which is due to the absence of a FIB push counter structure.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show ip cef command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_CEF-3-NONATADDR : NAT address is null	
Evnlanation	An unexpected condition has occurred which is due to the absence of an NAT address

%IOSXE_FMANRP_CEF-3-NONATADDR: NAT address is null

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show ip alias** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE FMANRP FPM

%IOSXE_FMANRP_FPM-4-INVALIDLENTYPE: Field length type in PHDF file is invalid

Explanation

An unexpected condition has occurred which is due to the invalid field length type in PHDF file.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_FPM-4-INVALIDMATCHTYPE : FPM match type is invalid [dec]

Explanation

An unexpected condition has occurred which is due to the invalid FPM match type in one of FPM class-map filter match entry

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_FPM-4-INVALIDACTION : FPM feature action is invalid [dec]

Explanation

An unexpected condition has occurred which is due to the invalid action type when trying to bind FPM action with target class group.

Recommended Action

$\% IOSXE_FMANRP_FPM-3-NOSTATUPDATE: Failed to update class-map statistics during periodic update$	
Explanation	A statistics update for a class-map has failed.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_FMANRP_OBJID

%IOSXE_FMANRP_OBJID-5-DUPCREATE : Duplicate forwarding object creation obj_handle [hex], type [int], existing obj_id [hex], type [int]	
Explanation	An unexpected condition has occurred which results in duplicate forwarding object creation.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_FMANRP_OBJID2

%IOSXE_FMANRP_OBJID2-3-DUPCREATE : Duplicate forwarding object creation obj_handle [hex], type [int], existing obj_id [hex], type [int]	
Explanation	An unexpected condition has occurred which results in duplicate forwarding object creation with different object types.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_FMANRP_RTMAP

%IOSXE_FMANRP_RTMAP-3-RTMAPNULL : The route-map structure for [chars] is null	
Explanation	An unexpected condition has occurred which is due to the absence of a route-map data structure.
Recommended Action	show route-map

%IOSXE_FMANRP_RTMAP-4-UNKOWNCLIANT : Unknown client type [dec] received	
Explanation	An unexpected known client type is received for route-map download.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

MOSXE_FMANRP_RTMAP-3-INVALID_LIST: NULL **Explanation An internal list structure has been detected as invalid. **Copy the error message exactly as it appears on the console or in the system log. Issue the command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\% IOSXE_FMANRP_RTMAP-3-RTMAP_UNSUPPORTED: Routemap ([chars]) contain unsupported match/set clause, ignored$	
Explanation	A map contains unsupported match or set clause
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_FMANRP_URPF

%IOSXE_FMANRP_URPF-4-NOV4SWIDB : v4 sub-interface is null	
Explanation	An unexpected condition has occurred which is due to the absence of a v4 swidb structure.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show ip interface command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_URPF-4-NOV6SWIDB : v6 sub-interface is null	
Explanation	An unexpected condition has occurred which is due to the absence of a v6 swidb structure.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show ipv6 interface command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_URPF-3-INVALIDIFHDL: Invalid interface handle [int] for interface (number= [int], swidb= [hex], name= [chars])	
Explanation	An unexpected condition has occurred which is due to an invalid interface handle
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_URPF-4-UPDV4STATSERR : Update v4 URPF statistics error	
Explanation	An unexpected condition has occurred when updating v4 URPF statistics
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show ip interface <name></name> command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_FMANRP_URPF-4-UPDV6STATSERR : Update v6 URPF statistics error	
Explanation	An unexpected condition has occurred when updating v6 URPF statistics
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show ipv6 interface <name></name> command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE FMANRP ZONES

%IOSXE_FMANRP_ZONES-3-NOSTATUPDATE: Failed to update zone-pair statistics during periodic update
(zone [chars], class [int])

Explanation

A statistics update for a zone-pair has failed.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_INFRA

%IOSXE_INFRA-3-INVALID_ERRMSG: Error message type [dec] not defined

Explanation Error message type used is not defined in IOSXE infrastruction

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\$IOSXE_INFRA-3-SHIM_INIT_WQ_FAIL: IOSXE$ shim layer initialization failed: Can not create receiving queues

Explanation IOSXE IOS shim layer initialization of watched queue failed

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\$IOSXE_INFRA-3-SHIM_INIT_WQ_CHASFS_FAIL:IOSXE$ shim layer initialization failed: Can not create receiving chasfs watched queue

Explanation IOSXE IOS shim layer initialization of watched queue failed

Recommended Action

%IOSXE_INFRA-3-SHIM_INIT_PROC_FAIL: IOSXE shim layer initialization failed: Dispatch process creation failed	
Explanation	IOSXE IOS shim layer initialization creating dispatch process failed
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-SHIM_INIT_MEM_FAIL: IOSXE shim layer initialization failed: Memory initialization failed.	
Explanation	IOSXE IOS shim layer initialization of memory failed
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IUSXE_INFRA-3-SHIM_NO_IPC_DISPATCH_HDL: IUSXE shim layer [chars] process message without IPC dispatch handler.	
Explanation	IOSXE IOS shim layer has no ipc dispatch handler set
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\label{losxe_infra} \begin{subarray}{ll} s$	
Explanation	IOSXE IOS shim layer cannot find ipc handler
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-SHIM_INIT_TDL_FAIL : IOSXE shim layer initialization TDL Lib [chars] failed.	
Explanation	IOSXE IOS shim layer initialization of TDL library
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-SHIM_INIT_DISPATCH_INIT_FAIL: IOSXE shim layer initialization, dispatch path init failed. Explanation IOSXE IOS shim layer initialization of TDL disatch path

Recommended	
Action	

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-INVALID_RUNTIME_IDX : Thread runtime index [dec] is not valid Explanation Export the thread's running time failed. Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-6-THEAD_SELECT_ERR : Inbound message or packet select error, [chars].	
Explanation	Socket select operation error in threads
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-INJECT_HDR_LENGTH_ERR: Inject hdr size [int] exceeds limit

Explanation Inject header length exceeds pak header space

%IOSXE_INFRA-3-INJECT_HDR_LENGTH_ERR: Inject hdr size [int] exceeds limit

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-INJECT_EMBEDDED_HDR_LENGTH_ERR: Can't allot space needed for embedded inject hdr size [int] exceeds limit

Explanation

Can't allot space needed for embedded inject header, exceeds pak header space

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-INJECT_NO_IF_OUTPUT_ERR: Output intf is NULL, [chars]

Explanation

Output intf is requred to proceed, else skip the feautre

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-4-PUNT_KEEPALIVE_LOG_ERR_INV_PARAM: Invalid parameter: [chars]

Explanation

Invalid parameter was passed when generating punt err log

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-4-PUNT_KEEPALIVE_LOG_ERR_GET_FILE_NAME : Failed to get file name: [chars]

Explanation

Could not form a file name when generating punt err logPunt keepalive log error seen

Recommended Action

%IOSXE_INFRA-4-PUNT_KEEPALIVE_LOG_ERR_INV_FILE_ID : Invalid file descriptor: [dec]	
Explanation	Invalid file descriptor was found when generating punt err log
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-PUNT_KEEPALIVE_LOG_ERR_OPEN_FILE : Failed to open file: [chars]	
Explanation	Failed to open file when generating punt err log
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-4-PUNT_KEEPALIVE_LOG_ERR_CLOSE_FILE : Failed to close file with descriptor: [dec]	
Explanation	Closing of file failed when generating punt err log
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-PUNT_KEEPALIVE_LOG_ERR_WRITE_TO_FILE : Write to file Id [dec] failed [dec] bytes, expected [dec] bytes	
Explanation	Write to file failed when generating punt err log
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-PUNT_KEEPALIVE_LOG_ERR_ALLOC_TTY: Failed to allocate a tty	
Explanation	Can't allocate a TTY when generating punt err log

%IOSXE_INFRA-3-PUNT_KEEPALIVE_LOG_ERR_ALLOC_TTY: Failed to allocate a tty

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-PUNT_KEEPALIVE_LOG_ERR_ALLOC_CSB: Failed to allocate a csb

Explanation Can't allocate a csb when generating punt err log

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE INFRA-3-PUNT KEEPALIVE LOG ERR PARSE CMD: Failed to parse command: [chars]

Explanation

Failed to parse a command when generating punt err log

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-4-PUNT_KEEPALIVE_LOG_ERR_GET_PROCID: Failed to get process id

Explanation Can't get identifier of the process generating punt err log

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-4-PUNT_KEEPALIVE_LOG_ERR_INV_PROCID : Invalid proc id [dec], expected [dec]

Explanation Invalid process trying to generate punt err log

Recommended Action

%IOSXE_INFRA-4-NO_PUNT_KEEPALIVE : Keepalive not received for [int] seconds	
Explanation	Punt Inject keepalive message was not received
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-2-FATAL_NO_PUNT_KEEPALIVE : Keepalive not received for [int] seconds resetting	
Explanation	Punt Inject keepalive message was not received
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-INJECT_GSB_CTL_INIT_FAIL : Inject adjacency subblock init failed	
Explanation	Adj subblock control or register failed
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-PUNT_ADDR_RES_ENCAP_ERR : Punted address resolution packet with unknown encap [chars]	
Explanation	Punted packet for ARP/ND with encap not supported
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-PUNT_SVC_PROC_ERR : Punt service [chars] create failed	
Explanation	Punt service process can not be created

%IOSXE_INFRA-3-PUNT_SVC_PROC_ERR: Punt service [chars] create failed

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-VM_PAGE_TABLE_ERR: VM guarded page operation failed, address [hex], [chars]

Explanation VM guarded page avl tree operation error

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-PUNT_SVC_TYPE_UNKNOWN : Punted packet with unknown service type [int]

Explanation

Punted pak with an unsupported service type

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-5-PUNT_SVC_CANT_ENQUEUE: Punted pak can't be enqueued for service

Explanation Punted pak enqueue failed

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-5-PUNT_SVC_INVALID_OPT_PKT : Invalid IPv4 options packet punted to RP

Explanation Invalid IPv4 options packet dropped in RP

Recommended Action

%IOSXE_INFRA-4-INJECT_TUN_NONIP_WARN : pak with linktype [chars] gets into non-ip tunnel	
Explanation	IP/IPv6/MPLS packet should to go through GRE tunnel for non-IP payload
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-INJECT_FEATURE_ESS_ERR : ESS segment not found, type [dec] hdl [hex]	
Explanation	Packets to be injected to an unsupported ESS segment
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). It you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-6-PROCPATH_CLIENT_HOG : IOS shim client '[chars]' has taken %Id msec (runtime: %Id msec) to process a '[chars]' message	
Explanation	The specified IOSXE IOS shim client has taken too long to process a received IPC or chasfs message
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-6-AUXTHD_REQUEST : Too many outstanding requests for file system access	
Explanation	Resource temporarily unavailable
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-APP_SESS_OPEN_FAILED : An attempt to open [chars] with handle number [dec] has failed ([dec])	
Explanation	Application session between processes failed to estabish.

%IOSXE_INFRA-3-APP_SESS_OPEN_FAILED : An attempt to open [chars] with handle number [dec] has failed ([dec])

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

**MIOSXE_INFRA-3-CONSOLE_DBUG_DROP: System dropped [dec] bytes of console debug messages. Explanation Debugging messages are being generated faster than they can be displayed on the console. The messages can not be guaranteed to be seen so this message replaces the lost messages. Recommended Consider using conditional debugging or turning off console logging.

%IOSXE_INFRA-3-PUNT_INCOMP_WRONG_ADJID : Punted address resolution packet linktype [chars], adj-id [dec] is with linktype [chars]

Explanation

CPP needs to punt incomplete adjacency for resolution by specifying the adjacency-id, but the included adjacency-id does not match the incomplete adjacency this packet triggered.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

MIOSXE_INFRA-3-IFS_EXTLINK_ADD_FAIL: Could not add filesystem [chars] to IFS links **Explanation Attempt to add filesystem root to allow for links failed **Copy the error message exactly as it appears on the console or in the system log. **Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE INFRA-3-IFS UDEV REMOVE FAIL: Could not remove udev device [chars]

Explanation Attempt to remove udev device failed

%IOSXE_INFRA-3-IFS_UDEV_REMOVE_FAIL: Could not remove udev device [chars]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE INFRA-3-IFS DFLT FS REG FAIL: Unable to set [chars] as a default file system.

Explanation IOSXE's platform dependent code failed to register the default file system.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\$IOSXE_INFRA-3-IFS_INIT_HIDDEN_FAIL: IOSXE$ shim layer initialization failed: Can not create receiving queues

Explanation

IOSXE IOS shim layer initialization of hidden path watch failed

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-BSO_MSG_HDR_LENGTH_ERR: BSO message header length [int] is incorrect

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-BSO_MSG_HDR_MSGTYPE_ERR : BSO message header msgtype [int] is incorrect

Explanation	BSO message header msgtype is incorrect
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-BSO_MSG_UNMARSHAL_ERR : BSO message unmarshalling has failed	
Explanation	BSO message unmarshalling has failed
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-BSO_MSG_CACHE_ERR : BSO message query cache update error - [chars]	
Explanation	BSO message query cache update error
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-4-BSO_MSG_RIB_WATCH_WARN : BSO message RIB watch start error	
Explanation	BSO message RIB watch start error
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-RELOAD_INFO_SAVE_FAIL : Unable to save reload information: [dec]: [chars].	
Explanation	IOSXE's platform dependent code failed to save the reload information.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-	3-SN_IPFRR_PROC_ERR : Static Nexthop IPFRR [chars] create failed
Explanation	SN IPFRR process can not be created

%IOSXE_INFRA-3-SN_IPFRR_PROC_ERR: Static Nexthop IPFRR [chars] create failed

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE INFRA-6-CONSOLE ACTIVE: [chars]

Explanation

Indicates that the current instance of IOS is assuming active control of the console.

This is informational.

Recommended Action

No action is required.

%IOSXE_INFRA-6-PLATFORM_RELOAD : [chars]

Explanation

Indicates that the current instance of IOS is being reset by the platform code. This is

part of a normal reset sequence and the message is informational.

Recommended

Action

No action is required.

%IOSXE_INFRA-6-CHASFS_CLOCK_SET_FAIL: Failed to set Chasfs property on system time change

Explanation

Unable to set chasfs property on system time change

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-CYAN_API_ERROR : Failed to retrieve platform dependent value of [chars] (err=[dec])

Explanation CYAN API function failed

Recommended Action

%IOSXE_INFRA-6-SHIM_RXMSG_IPC_INFO: IOS shim layer process IPC msg for fd [dec], seq_num [dec], ipc_status [dec]

Explanation

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-SHIM_IPC_NOT_PROCESSED : msg handler returned FALSE for IPC msg for fd [dec], seq_num [dec], service [chars]

Explanation

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-SWIFT_ORCH_PROC_FAIL: IOSXE SWIFT Orchestrator process creation failed

Explanation

The SWIFT Orchestrator process could not be created

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-BAD_GLIBC_BUF_FREE : An IOS buffer is freed into GLIBC buffer pool, buffer blockmagic [hex], flags [hex]

Explanation

An IOS buffer is freed into GLIBC buffer pool.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_INFRA-3-BIPC_MGS_ALLOC_FAIL : Allocating [dec] byte for IPC [chars] msg failed: out of memory

Explanation

system is out of memory

%IOSXE_INFRA-3-BIPC_MGS_ALLOC_FAIL: Allocating [dec] byte for IPC [chars] msg failed: out of memory

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_MEMPOOL_MIB through **IOSXE_RP_IF_FLOW_IDS**

- IOSXE MEMPOOL MIB
- IOSXE MGMTVRF
- IOSXE MLP
- IOSXE OIR
- IOSXE PEM
- IOSXE_QFP
- IOSXE RP ALARM
- IOSXE RP CFG NOT
- IOSXE RP DPIDB
- IOSXE RP IF FLOW IDS

IOSXE_MEMPOOL_MIB

%IOSXE_MEMPOOL_MIB-3-BUFFPOOL_	_REG_ERROR : Bufferpool register data exceeds allocated memory;
Retrieved only [dec] entries.	

Recommended Action

Explanation

Memory allocated is not enough

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_MGMTVRF

%IOSXE_MGMTVRF-3-PROCESS_CREATE_FAIL: Management VRF process creation failed, [chars]

Explanation

Can not create IOS process for mgmt port init

%IOSXE_MGMTVRF-3-PROCESS_CREATE_FAIL: Management VRF process creation failed, [chars]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_MGMTVRF-3-VRF_CREATE_FAIL: Management VRF creation failed [chars]

Explanation Can not create mgmt vrf during system init

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_MGMTVRF-3-AFI_ATTACH_FAIL: Management VRF AFI [chars] attach failed

Explanation Can not create aff subblock for mgmt vrf

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_MGMTVRF-3-INTF_ATTACH_FAIL: Management VRF attach to mgmt [chars] failed

Explanation Can not associate mgmt port to mgmt vrf

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_MGMTVRF-3-SET_TABLEID_FAIL : Installing [chars] Management interface tableid [hex] failed

Explanation Fail to set mgmt port tableid into Linux kernel

Recommended Action

%IOSXE_MGMTVRF-6-CREATE_SUCCESS_INFO: Management vrf [chars] created with ID [dec], ipv4 table-id [hex], ipv6 table-id [hex]	
Explanation	mgmt vrf and ipv4, ipv6 tables created for mgmt port
Recommended Action	

IOSXE_MLP

%IOSXE_MLP-3-ENQUEFAIL : Unable to send [chars] [chars] message to Forwarding Manager Process	
Explanation	An unexpected condition has occurred which resulted in a configuration not being sent to the Forwarding Manager Processs.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_MLP-4-UPDSTATSERR : Update MLP statistics error	
Explanation	An unexpected condition has occurred when updating mlp statistics
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_MLP-2-DB_ENTRY_ALLOC_FAIL : MLP link db entry allocation for link [chars] failed	
Explanation	MLP link database error. Memory chunk allocation for MLP link database entry has failed.
Recommended Action	Check for accurate memory management. Perform memory leak checks and look for memory corruption causes. Execute 'show proc memory' command.

%IOSXE_MLP-2-DB_INSERT_FAIL : MLP link db entry add for interface [chars] failed	
Explanation	MLP link database error. Insertion of a new entry into MLP link database has failed.
Recommended Action	Check for accurate memory management. Perform memory leak checks, look for memory corruption causes, verify correct database management. Execute 'show proc memory' command.

%IOSXE_MLP-2-DB_DELETE_FAIL : MLP link db entry delete for link [chars] failed	
Explanation	MLP link database error. Removal of entry from MLP link database has failed.
Recommended Action	Check for accurate memory management. Perform memory leak checks, look for mamory corruption causes and check for correct database management. Execute 'show proc memory' command.

%IOSXE_MLP-2-DB_ENTRY_FREE_FAIL : MLP link entry free failed	
Explanation	MLP link database error. Memory chunk free of MLP link database entry has failed.
Recommended Action	Check for accurate memory management. Perform memory leak checks and look for memory corruption causes. Execute 'show proc memory' command.

%IOSXE_MLP-2-DB_ALLOC_FAIL : MLP link db allocation failed	
Explanation	MLP link database error. Memory chunk creation for MLP link database has failed.
Recommended Action	Check for accurate memory management. Perform memory leak checks and look for memory corruption causes. Execute 'show proc memory' command.

%IOSXE_MLP-2-DB_DESTROY_FAIL : MLP link database destroy failed	
Explanation	MLP link database error. Memory chunk destroy has failed for MLP link database.
Recommended Action	Check for accurate memory management. Perform memory leak checks and look for memory corruption causes. Execute show proc memory command.

IOSXE_OIR

%IOSXE_OIR-6-INSCARD : Card ([chars]) inserted in [chars]slot [chars]	
Explanation	The OIR facility detected the insertion of a card in the slot number specified in the message.
Recommended Action	No action is required.

%IOSXE_OIR-6-REMCARD : Card ([chars]) removed from [chars]slot [chars]	
Explanation	The OIR facility detected the removal of a card from the slot number specified in the message.
Recommended Action	No action is required.

%IOSXE_OIR-6-ONLINECARD : Card ([chars]) online in [chars]slot [chars]	
Explanation	The OIR facility detected the state change to online for the card in the slot number specified in the message.
Recommended Action	No action is required.

%IOSXE_OIR-6-OFFLINECARD : Card ([chars]) offline in [chars]slot [chars]	
Explanation	The OIR facility detected the state change to offline for the card in the slot number specified in the message.
Recommended Action	No action is required.

%IOSXE_OIR-3-CARDERR : Could not read state property for [chars] slot [dec]	
Explanation	The OIR facility detected a failure for exceeding the number of retries to find state chasfs property.
Recommended Action	No action is required.

%IOSXE_OIR-6-SOFT_STARTSPA : SPA([chars]) restarted in [chars]	
Explanation	The SPA in the specified subslot is restarted by the command hw-module subslot slot#/subslot# start
Recommended Action	No action is required.

%IOSXE_OIR-3-SPA_INTF_ID_ALLOC_FAILED : Failed to allocate interface identifiers for SPA([chars]) in slot/bay: [int]/[int]	
Explanation	Failed to get CC buffer and flow control identifiers for the SPA in the specified subslot Traffic cannot flow through the SPA under this failure condition. This can happen if the system runs out of available identifiers.
Recommended Action	Try to reduce the number of interfaces configured in the system either by physically removing the SPAs or by changing the system configuration

%IOSXE_OIR-6-SOFT_STOPSPA : SPA([chars]) stopped in [chars], interfaces disabled	
Explanation	The SPA in the specified subslot is stopped by the command hw-module subslot slot#/subslot# stop The interfaces on that processor will be administratively shut down and marked as removed. The routing table will be flushed of any routes through the removed interfaces.
Recommended Action	No action is required.

%IOSXE_OIR-6-SOFT_RELOADSPA : SPA([chars]) reloaded on [chars]	
Explanation	The SPA in the specified subslot is reloaded by the command hw-module subslot slot#/subslot# reload
Recommended Action	No action is required.

%IOSXE_OIR-6-SYNCSPA : SPA ([chars]) reloading to come up in [chars] mode	
Explanation	The SPA in the specified subslot is reloaded by the command hw-module subslot slot#/subslot# reload
Recommended Action	No action is required.

%IOSXE_OIR-6-INSSPA : SPA inserted in [chars]/[int]	
Explanation	The OIR facility detected the insertion of a SPA in the subslot number specified in the message.
Recommended Action	No action is required.

%IOSXE_OIR-6-REMSPA : SPA removed from [chars]/[int], interfaces disabled	
Explanation	The OIR facility detected the removal of a SPA from the subslot number specified in the message. The interfaces on that processor will be administratively shut down and marked as removed. The routing table will be flushed of any routes through the removed interfaces.
Recommended Action	No action is required.

%IOSXE_OIR-6-INSSSFP : Smart SFP inserted in port [chars]	
Explanation	The OIR facility detected the insertion of TSoP/VCoP SSFP in the port number

specified in the message.

Recommended

Action

No action is required.

%IOSXE_OIR-6-REMSSFP: Smart SFP removed from port [chars]

Explanation The OIR facility detected the removal of TSoP/VCoP SSFP in the port number specified

in the message.

Recommended

Action

No action is required.

%IOSXE_OIR-6-SPARELOAD : SPA reloaded on subslot [int]/[int]

Explanation The SPA in the specified subslot is reloaded.

Recommended

Action

No action is required.

%IOSXE OIR-6-CARDRECONCILE: SPA type changed on subslot [int]/[int] from [int] to [int]

Explanation The SPA in the specified subslot has been initialized, and it has been detected that it

is of a different type to the SPA that was previously in this subslot.

Recommended

Action

No action is required.

%IOSXE_OIR-3-OIRTWICE: Subslot [int]/[int] OIR insertion/removal not paired up: [chars]

Explanation An internal OIR-related error occurred for the specified SPA.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE OIR-3-QUIESCE FAIL: Quiesce failed for subslot [int]/[int] (error = [dec])

Explanation The RP failed to contact the SPA during failover. The SPA will be reset.

Recommended

Action

No action is required.

%IOSXE_OIR-3-UNQUIESCE_FAIL : Unquiesce failed for subslot [int]/[int] (error = [dec])	
Explanation	The RP failed to unquiesce the SPA in the specified subslot. The SPA will be reset.
Recommended Action	No action is required.

%IOSXE_OIR-3-POWER_CYCLE_IMMINENT : The SPA in subslot [int]/[int] will be power cycled in [dec] seconds.	
Explanation	The SPA in the specified subslot will be power cycled in the amount of time specified in the error message.
Recommended Action	No action is required.

%IOSXE_OIR-3-PROCMSG : Process msg send failed for process[dec]	
Explanation	Process message send failed.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_OIR-3-MODULE : Missing [chars] for [chars]	
Explanation	A hardware or software error occurred.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_OIR-3-SPA_MDR_FAIL : Minimal Disruptive Restart process failed for SPA in subslot [int]/[int], reason [chars].	
Explanation	The SPA in the subslot failed Minimal Disruptive Restart. Minimal Disruptive Restart process is aborted and an attempt will be made to recover the SPA by resetting the SPA hardware.
Recommended Action	No action is required.

IOSXE_PEM

%IOSXE_PEM-6-INSPEM_FM : PEM/FM [chars] inserted	
Explanation	The platform detected the insertion of a power/fan module in the slot number specified in the message.
Recommended Action	No action is required.

%IOSXE_PEM-6-REMPEM_FM : PEM/FM [chars] removed	
Explanation	The platform detected the removal of a power/fan module in the slot number specified in the message.
Recommended Action	No action is required.

%IOSXE_PEM-6-PEMOK : The PEM in [chars] is functioning properly	
Explanation	The PEM hardware may have been either switched off, or reporting a failure condition. This message indicates that the PEM is no longer either switched off, or reporting a failure
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_PEM-3-PEMFAIL : The PEM in [chars] is switched off or encountering a failure condition.	
Explanation	The PEM hardware has been either switched off, or is reporting a failure condition.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\mbox{\ensuremath{\mbox{\textsc{NIOSXE_PEM-6-FANOK}}}}$: The fan in [chars]/[dec] is functioning properly

Explanation	The fan was reporting a failure condition. This message indicates that the fan is no
	longer reporting a failure

%IOSXE_PEM-6-FANOK: The fan in [chars]/[dec] is functioning properly

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE PEM-3-FANFAIL: The fan in [chars]/[dec] is encountering a failure condition

Explanation

The fan's hardware is reporting that the fan is failing. This is most likely because the hardware detects the fan as spinning below the minimum speed.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_PEM-3-PEMCHASFSERR: The PEM in [chars] has encountered a system software error.

Explanation

The PEM's underlying software for storing PEM state is not working properly.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\$IOSXE_PEM-3-TEMPERATURE_RAISE:$ Sensor [chars] has reached maximum temeprature value, Leads to shutdown the system

Explanation

The Temperature sensor reaching maximum threshold value working properly.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE PEM-3-FAN FAIL SHUTDOWN: More thatn one [chars] has failed, Leads to shutdown the system

Explanation

The Temperature sensor reaching maximum threshold value working properly.

%IOSXE PEM-3-FAN FAIL_SHUTDOWN: More that none [chars] has failed, Leads to shutdown the system

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_PEM-3-SSFP_TEMPERATURE_RAISE : [chars] transceiver temeprature reached threshold value, Leads to shutdown the system

Recommended Action

Explanation

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

The Temperature sensor reaching maximum threshold value working properly.

%IOSXE_PEM-3-PEMREDLOWSTANDBY: Cannot activate [chars] configuration. Total power budget of standby power supplies is [dec]W. Standby power must be greater than or equal to the largest power supply capacity ([dec]W).

Explanation

Operating in unprotected mode Should insert at least one ps in standby slots with a capacity greater than or equal to the largest capacity power supply in the system. The configuration will be applied automatically once requirements are met.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\% IOSXE_PEM-3-PEMREDNOPWR: Cannot enable power redundancy mode [chars] because config would create mode with insufficient [chars] power$

Explanation

Configuration set by user is not valid as power supplies in the active slots do not contain enough power to meet the power requirements

Recommended Action

Insert additional power supplies and configure them to be active or configure current standby power supplies to active such that power requirements are met

IOSXE_QFP

%IOSXE_QFP-2-LOAD_EXCEED: Slot: [int], QFP:[int], Load [int]%[hex]ceeds the setting threshold.

Explanation

QFP Load exceeds setting threshold.

%IOSXE_QFP-2-LOAD_EXCEED: Slot: [int], QFP:[int], Load [int]%[hex]ceeds the setting threshold.

Recommended

Monitor the traffic load.

Action

%IOSXE_QFP-2-LOAD_RECOVER: Slot: [int], QFP:[int], Load [int]%% recovered.

Explanation

QFP Load recovered.

Recommended

No action required (normal operation).

Action

IOSXE_RP_ALARM

%IOSXE_RP_ALARM-6-INFO: [chars] [chars] [chars]: [chars]

Explanation

Recommended

Action

%IOSXE_RP_ALARM-6-INFO: [chars] [chars] [chars] [chars]

Explanation

Alarm assertion or deassertion information.

Recommended

Action

No action is required.

%IOSXE_RP_ALARM-2-PEM: [chars] [chars] [chars]: [chars]

Explanation

Recommended

Action

%IOSXE_RP_ALARM-2-PEM: [chars] [chars] [chars] [chars]

Explanation

Power Entity Module missing information

Recommended

No action is required.

Action

%IOSXE_RP_ALARM-2-ESP: [chars] [chars] [chars]: [chars]

Explanation

%IOSXE_RP_ALARM-2-ESP: [chars] [chars] [chars]: [chars]

Recommended

Action

%IOSXE_RP_ALARM-2-ESP: [chars] [chars] [chars] [chars]

Explanation

No ESP running alarm information

Recommended

Action

No action is required.

IOSXE_RP_CFG_NOT

%IOSXE_RP_CFG_NOT-3-MSGNOCAND: Can not construct a candidate entry for configuration export

Explanation

This error usually indicates either an out of memory condition or a TDL error. If ample memory is available, then the the TDL error may indicate a version conflict with respect to configuration.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_CFG_NOT-3-MSGNOPWARR: Can not construct an array for configuration export

Explanation

This error usually indicates either an out of memory condition or a TDL error. If ample memory is available, then the the TDL error may indicate a version conflict with respect to configuration.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_CFG_NOT-3-MSGNOUPDATEMSG : Can not construct an update message for configuration export

Explanation

This error usually indicates either an out of memory condition or a TDL error. If ample memory is available, then the the TDL error may indicate a version conflict with respect to configuration.

${\tt \%IOSXE_RP_CFG_NOT-3-MSGNOUPDATEMSG: Can\ not\ construct\ an\ update\ message\ for\ configuration\ export}$

Recommended Action

%IOSXE_RP_CFG_NOT-3-MSGNOREPLMSG : Can not construct a replace message for configuration export	
Explanation	This error usually indicates either an out of memory condition or a TDL error. If ample memory is available, then the the TDL error may indicate a version conflict with respect to configuration.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_CFG_NOT-2-MSGNOEXP : Can not construct a '[chars]' message for configuration export: [chars]	
Explanation	This error usually indicates either an out of memory condition or a TDL error. If ample memory is available, then the the TDL error may indicate a version conflict with respect to configuration.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_CFG_NOT-2-MSGTDLINITERROR : Configuration Notification messaging module initialization failed: Unable to initialize messaging: [chars]	
Explanation	The Configuration Notification subsystem has failed to initialize the infrastructure for messaging with the Pluggable Services Daemon. Notification of configuration to critical modules cannot proceed.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_CFG_NOT-2-MSGTDLERROR : Error processing TDL message. [dec]	
Explanation	An unexpected condition in which IOS has received a TDL message which it can not process.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_CFG_NOT-2-MSGIPCINITERROR : Error initializing IPC queue	
Explanation	An unexpected condition in which IOS could not initialize a message queue to the PSD.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IUSXE_RP_CFG_NU1-3-MSGIPCTXERRUR : IPC transmit error. [dec]	
Explanation	An unexpected condition in which IOS encountered an error trying to send a message to another process. %d
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\% IOSXE_RP_CFG_NOT-3-MSGOBJNULL: An unexpected condition in which IOS has received a null pointer that it expects to be non-null.$	
Explanation	An unexpected condition has occurred while IOS is trying to process a username command.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\% IOSXE_RP_CFG_NOT-3-MSGENCRYPTINVALID: The mcprp_cfg_notify subsystem has seen an encryption type it does not recognize. [dec]$

Explanation An unexpected condition has occurred while IOS is trying to process a username

command.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE RP CFG NOT-3-NVWRITE EXPORT: Failed to export [chars] notification: [dec]

Explanation When a 'write memory' or 'write erase' operation occurs, the Configuration Notification

subsystem exports this event into the chassis file system. This message indicates that

the export failed.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE RP CFG NOT-3-MCP DBPERSIST STAT: Failed to read [chars] property: [dec]

Explanation When a 'reload' operation occurs, this chasfs property is read to determine the status

of the DB persist/restore/delete operation. This message indicates that the read failed.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_CFG_NOT-3-MCP_DBPERSIST_ERROR: System configuration update could not complete

Explanation When a 'reload' operation occurs, this chasfs property is read to determine the status of the DR partial/restard/delete operation. This message indicates that the operation

of the DB persist/restore/delete operation. This message indicates that the operation

failed.

Recommended Action

%IOSXE_RP_CFG_NOT-3-MCP_FRU_LOCATION : Failed to get local FRU location: [dec]	
Explanation	Unable to get local FRU location
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_CFG_NOT-3-MCP_FRU_INVALID : Unknow FRU location: [chars]	
Explanation	Unknown FRU location
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_CFG_NOT-3-BOOT_VAR_NOT_SET : Boot variable either does not exist or buffer is too small. Keeping it blank.	
Explanation	Boot variable either does not exist or buffer is too small. Not able to set boot variable. Ignoring it.Aborting reload.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_CFG_NOT-3-BOOT_IMAGE_NOT_FOUND : Primary image is not found, the system is going to reload as per user request.	
Explanation	Primary image which is set in boot statement either does not exist or not found. Primary image is not found, it should prompt the user to see if they wish to proceed. Aborting reload.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_CFG_NOT-6-IOX_SERVICE_NOTSUPPORTED : IOx service not supported.	
Explanation	IOx service is not supported in this platform currently. This may be either due to the feature unavailability or due the current inadequate license level of the system.
Recommended Action	

IOSXE_RP_DPIDB

%IOSXE_RP_DPIDB-3-IDXBADRANGE : Datapath IDB index [dec] is not in a valid range		
Explanation	An unexpected condition has occurred as the index of a datapath IDB is not valid.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show interface command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_RP_DPIDB-3-IDXALLOCFAILED : Datapath IDB index allocation failed: [chars]		
Explanation	An unexpected condition has occurred as all the available of datapath IDB indices are used.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show interface command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_RP_DPIDB-3-IDXINSERTFAILED : Insertion of datapath IDB index [dec] into database failed	
Explanation	An unexpected condition has occurred that insertion of datapath IDB indices failed.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show interface command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-IDXLOOKUPFAILED : Lookup of datapath IDB index from the database failed ([chars])

Explanation

An unexpected condition has occurred that lookup of datapath IDB indices failed.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show interface** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-IDXDELETIONFAILED : Deletion of datapath IDB index from the database failed ([chars] [hex]) rc [dec]

Explanation

An unexpected condition has occurred that deletion of datapath IDB indices failed.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show interface** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-NOHWSUBBLOCK : HWIDB [chars] does not have a hardware subblock

Explanation

An unexpected condition has occurred that no hardware subblock was previously

allocated for a HWIDB.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show interface** command to gather data that may help identify the nature

of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-NOSWSUBBLOCK : SWIDB [chars] does not have a software subblock

Explanation

An unexpected condition has occurred that no software subblock was previously allocated for a SWIDB.

%IOSXE_RP_DPIDB-3-NOSWSUBBLOCK : SWIDB [chars] does not have a software subblock

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show interface** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-IDBBADTYPE : Datapath IDB type [dec] is not valid

Explanation

An unexpected condition has occurred as the type of a datapath IDB is not valid.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show interface** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-IDBEXIST : Datapath IDB already exists in this mapping entry: [chars]-[dec]

Explanation

An unexpected condition has occurred that an attempt is made to save datapath IDB in a mapping entry filled by another.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show interface** command to gather data that may help identify the nature

of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-IDBNONEXIST : Datapath IDB does not exist in this mapping entry: [chars]-[dec]

Explanation

Datapath IDB lookup points to empty mapping entry.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show interface** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-RF : Datapath IDB RF operation failed - [chars]

Explanation

Failure in some datapath ID RF activity.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show interface** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-CF: Datapath IDB CF operation failed - [chars]

Explanation

Failure in some datapath ID CF activity.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show interface** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support

representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-RPC : Datapath IDB RPC operation failed - [chars]

Explanation

Failure in some datapath ID RPC activity.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show interface** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE RP DPIDB-3-REGISTRATION: ISSU [chars] failed for [chars]; [chars]

Explanation

An ISSU registration for the set of initial capabilities and sessions failed due to the reason specified. This will have the effect of the DPIDX ISSU support being unavailable between peers.

Recommended Action

%IOSXE_RP_DPIDB-3-ISSU : [chars] [chars] failed; [chars]		
Explanation	An operation pertaining to the ISSU support for DPIDX failed to complete using either the CF or IPC transport context with the reason specified	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_RP_DPIDB-3-TRANSFORM : [chars] of [chars] via [chars] failed for dpidx [int]		
Explanation	An attempt to either encode or decode a versioned synchronization message has failed due to an internal error encountered by the ISSU component.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_RP_DPIDB-3-RECEIVE : Message via [chars] is [chars]		
Explanation	An attempt to receive and process a versioned negotiation or synchronization message has failed due to an internal error being detected by the information received from the IPC or CF components.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_RP_DPIDB-3-TRANSMIT : Unable to send via [chars] [chars] [chars]; [chars]		
Explanation	An attempt to send a versioned negotiation or synchronization message has failed due to an internal error encountered by the IPC or CF components.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_RP_DPIDB-3-NEGOTIATION : Failed to start ISSU [chars] session negotiation; [chars]		
Explanation	The ISSU negotiation with the peer failed to start for either the CF or IPC transport with the reason specified.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_RP_DPIDB-6-READY : [chars] peer not ready, discarding [chars]

Explanation

The synchronization attempt for the message has determined that the transport has lost communication with its peer. This is a normal situation which indicates that the standby route-processor is currently out of service implying a simplex redundancy mode.

Recommended Action

%IOSXE RP DPIDB-6-RELOAD: [chars], reloading [chars]

Explanation

A synchronization attempt between the active and standby RP peers has failed with the reason indicated. The standby peer is reloaded in an attempt to resynchronize when operating in a stateful redundant mode.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-DECODE: Decode via [chars] of [chars] failed

Explanation

A message of the transport and type described failed in its attempt to be decoded on the standby. The resultant action taken by the standby route processor is an attempt to resynchronize.

Recommended Action

%IOSXE_RP_DPIDB-3-PROGRESSION : Unable to inform RF of bulk sync completion; [chars]		
Explanation	The active route processor has sent a notification to the standby to inform of the completion of the bulk synchronization of the DPIDX configuration. The standby has failed to respond to the active informing that it received the notification noting the reason for the failure. The resultant action taken by the standby route processor is an attempt to resynchronize.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical	

support representative and provide the representative with the gathered information.

**MIOSXE_RP_DPIDB-3-BULK_SYNC: Failed to send [chars] information to peer Explanation The bulk synchronization of the DPIDX configuration to the standby RP has failed to complete successfully; DPIDX has therefore taken the action which will result in a reload of the peer in order to once more attempt to successfully synchronize the configuration state which may have failed initially to a transient condition. Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-DYN_SYNC : Failed to process [chars] dynamic state		
Explanation	The incremental synchronization of the DPIDX configuration to the standby RP has failed to complete successfully. This implies that the configuration state between the active and standby RP is inconsistent.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show interfaces command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_RP_DPIDB-6-TIMEOUT : Bulk sync is flow controlled by [chars]

Explanation

The bulk synchronization of the DPIDX configuration to the standby RP has encountered a flow control condition which has effected a timeout awaiting the condition to clear. This will result in a reload of the standby RP to allow the bulk synchronization to restart.

%IOSXE_RP_DPIDB-6-TIMEOUT: Bulk sync is flow controlled by [chars]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-IDBNOTVAI : Invalid API call for [chars]

Explanation Failure in an internal API

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show interface** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE RP DPIDB-3-NULLTIMER: NULL timer

Explanation A timer is NULL

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show interface** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-LIST : List [chars] failed for [chars]

Explanation List enqueue or removal failed

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show interface** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE RP DPIDB-3-FASTNOTIFY: Fast notify failed for [chars]

Explanation A fast notify message failed

%IOSXE_RP_DPIDB-3-FASTNOTIFY: Fast notify failed for [chars]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show interface** command to gather data that may help identify the nature

of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-DOWNLOADFAIL: Unable to download [chars] message to [chars]

Explanation

An unexpected condition has occurred which resulted in a configuration not being sent

to the reported process.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-FRRLDFLOWIDDELETIONFAILED: Deletion of fast-reroute flow ID with manager failed

Explanation

An unexpected condition has occurred that deletion of fast-reroute flow ID.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show interface** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE RP DPIDB-3-EFPSTATSFAILED: EFP stats message data get error: ([dec]) for EFP [int] on [chars]

Explanation

An unexpected error occurred extracting fields from an EFP stats message.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_DPIDB-3-MTU_ALLOC_FAIL: No hardware resources for [int] byte MTU on [chars]

Explanation

We reached to the threshold of maximum supported unique MTU on this platform.

%IOSXE RP DPIDB-3-MTU	ALLOC FAIL: No hardware resources f	or [int	t] byte MTU on I	chars
-----------------------	--	---------	------------------	-------

Recommended

No action is required.

Action

%IOSXE_RP_DPIDB-3-IP_MTU_ALLOC_FAIL: No hardware resources for [int] byte IP MTU on [chars] Explanation We reached to the threshold of maximum supported unique IP MTU on this platform.

Recommended Action

No action is required.

IOSXE_RP_IF_FLOW_IDS

%IOSXE_RP_IF_FLOW_IDS-3-NO_BUFF_FOR_SYNC: The Checkpoint Facility reported the error [chars] during a request for a buffer length of [dec]. This [chars] CF client has failed to synchronize a transaction to the Standby RP.

Explanation This error indicates that the buffer management within the Checkpoint Facility has either run out of buffers, or has some other problem. If this occurs during Bulk Sync

then Bulk Sync will terminate without completing. Otherwise the incremental Sync will fail.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-3-BUFF_OFFSET_NULL: Unable to utilize the memory buffer provided by the Checkpoint Facility. This [chars] CF client has failed to Bulk Sync.

ExplanationThis error indicates the Checkpoint Facility is having problems recognizing its own buffer levent. If this accurs during Bulk Syne then Bulk Syne will terminete without

buffer layout. If this occurs during Bulk Sync then Bulk Sync will terminate without

completing. Otherwise the incremental Sync will fail.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-3-CF_SEND_BULK_NONBLOCKED : The Checkpoint Facility reported the error [chars] while attempting to send a message. Bulk Sync of this [chars] CF client is terminating.

Explanation

This error indicates the Checkpoint Facility has internal problems related to IPC, and cannot perform a non-blocked send operation.

%IOSXE_RP_IF_FLOW_IDS-3-CF_SEND_BULK_NONBLOCKED: The Checkpoint Facility reported the error [chars] while attempting to send a message. Bulk Sync of this [chars] CF client is terminating.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-3-DEFERRED_DURING_BULK_SYNC : Encountered error [chars] while trying to place an [chars] transaction on the Deferred list during Bulk Sync for the [chars] CF client.

Explanation Unable to cache a deferred transaction while Bulk Sync is underway. This can adversely impact SSO state on the Standby RP.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-3-CF_SEND_INCR_NONBLOCKED: The Checkpoint Facility reported the error [chars] while attempting to send a non-blocked message. The Incremental Sync transaction for this [chars] CF client cannot be sent to the Standby RP.

Explanation This error indicates the Checkpoint Facility has internal problems related to IPC. Recommended Copy the error message exactly as it appears on the copsole or in the system log.

Recommended Action

Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-6-CFPEER_CANNOT_RECV : The Checkpoint Peer is not ready to receive messages. The Incremental Sync transaction for this [chars] CF client will not occur.

Explanation	This error indicates the Checkpoint Facility has signalled the peer has gone away.
Recommended	Copy the error message exactly as it appears on the console or in the system log.

%IOSXE_RP_IF_FLOW_IDS-3-SEND_FAIL_RELOAD : Checkpoint Facility Failed to send a [chars] transaction for this [chars] CF client. Reloading the Standby RP.

Explanation

This indicates the underlying Checkpoint Facility could not deliver a message sent from the active RP to the standby RP. The process will automatically reload the standby RP.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-4-DEF_LIST_REMOVE: Failed to remove one entry from the Deferred Sync list, for the [chars] CF client.

Explanation

An unexpected condition occured during list maintenance.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-3-CF_CANNOT_REGISTER: The call to add this [chars] CF client to the Checkpoint Facility failed with the error [chars]. This client is unable to proceed and will not be registered.

Explanation

For some reason the Checkpoint Facility will not register this client. As a result the Standby will never receive synchronized state from this CF client on the Active RP, The system is not capable of SSO and HA switchover.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-3-RF_PEER_EVENT_BUFFER: This [chars] RF client is unable to acquire an event buffer to send an RF peer message, the error [chars] was returned.

Explanation

This indicates the RF facility is unable to provide a message buffer needed to communicate with the RF peer. As a consequence the RF progression may be compromised.

Recommended Action

%IOSXE_RP_IF_FLOW_IDS-3-RF_SEND_PEER : This [chars] RF client encountered error [chars], when attempting to send a peer message.	
Explanation	This indicates the RF facility could not send a message to the RF peer. As a consequence the RF progression may be compromised.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-3-RF_PROCESS_FAILED : This [chars] RF client Failed to create the Bulk Sync Process.	
Explanation	The background process which performs the RF Bulk Sync failed to be created. As a consequence the Standby will never obtain the relevent SSO state to enable HA switchover.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-3-RF_POOL_REGEN_PROCESS_FAILED : The [chars] RF client Failed to create the Id Pool Regeneration process.	
Explanation	The background process which performs Flow Control Id Pool regeneration failed to start. As a consequence the Standby will never obtain the relevent SSO state to enable HA switchover.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\% IOSXE_RP_IF_FLOW_IDS-3-RF_POOL_REGEN_ERROR: Id\ Pool\ Regeneration\ encountered\ error\ code\ [dec],\ cannot\ switchover.$

Explanation

The background process which performs Flow Control Id Pool regeneration encountered an error. As a consequence the Standby does not have valid Flow Id pools and cannot progress to Active state.

%IOSXE_RP_IF_FLOW_IDS-3-RF_POOL_REGEN_ERROR : Id Pool Regeneration encountered error code [dec], cannot switchover.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\$IOSXE_RP_IF_FLOW_IDS-3-RF_SPA_ID_REGEN_ERROR$: Error code [dec] encountered trying to regenerate spa [chars] identifier in slot/subslot ([int]/[int])

Explanation

The background process which performs Flow Control Id Pool regeneration encountered an error. As a consequence the Standby does not have valid Id pools and cannot progress to Active state.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-3-RF_IF_ID_REGEN_ERROR: Error code [dec] encountered trying to regenerate interface flow-control identifer. If id [int] resides in slot/subslot/port ([int]/[int]/[int]).

Explanation

The background process which performs Flow Control Id Pool regeneration encountered an error. As a consequence the Standby does not have valid Id pools and cannot progress to Active state.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-3-RF_ADD_CLIENT_FAILED: The RF facility failed to add this [chars] client, reason given is [chars].

Explanation Recommended

Action

This indicates the RF facility could not add the client.

%IOSXE_RP_IF_FLOW_IDS-3-REGISTRATION : ISSU [chars] failed for [chars]; [chars]	
Explanation	An ISSU registration for the set of initial capabilities and sessions failed due to the reason specified. This will have the effect of the SPA MARMOT ID ISSU support being unavailable between peers.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-3-ISSU_OP : [chars] [chars] failed; [chars]	
Explanation	An operation pertaining to the ISSU support for SPA MARMOT IDs failed to complete using the CF transport context with the reason specified
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-3-TRANSFORM : [chars] of [chars] via CF failed	
Explanation	An attempt to either encode or decode a versioned synchronization message has failed due to an internal error encountered by the ISSU component.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-3-TRANSMIT : Unable to send via [chars] [chars] [chars] [chars]; [chars]	
Explanation	An attempt to send a versioned negotiation or synchronization message has failed due to an internal error encountered by the CF component.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-3-NEGOTIATION : Failed to start ISSU [chars] session negotiation; [chars]	
Explanation	The ISSU negotiation with the peer failed to start for either the CF or IPC transport with the reason specified.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-6-READY : [chars] peer not ready, discarding [chars]	
Explanation	The synchronization attempt for the message has determined that the transport has lost communication with its peer. This is a normal situation which indicates that the standby route-processor is currently out of service implying a simplex redundancy mode.
Recommended Action	

MIUSKE_KP_IF_FLUW_IDS-3-DECODE: Decode via GF of [Chars] tailed	
Explanation	A message sent via the CF transport failed in its attempt to be decoded on the standby. The resultant action taken by the standby route processor is an attempt to resynchronize.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_IF_FLOW_IDS-3-RECEIVE : Client reports message CF is [chars]	
Explanation	An attempt to receive and process a versioned negotiation or synchronization message has failed due to an internal error being detected by the information received from the CF component.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_RP_MGMTE through **IOSXE_UTD**

• IOSXE_RP_MGMTE

- IOSXE_RP_NV
- IOSXE_RP_SPA
- IOSXE_RP_VTYMGT
- IOSXE_SERVICE_ENGINE
- IOSXE_SPA
- IOSXE_TIMESTAMP_ENGINE
- IOSXE_UPGRADE_ROMMON
- IOSXE_USB
- IOSXE_UTD

IOSXE_RP_MGMTE

%IOSXE_RP_MGMTE-3-MSGCREATENULL : Cannot allocate [chars] TDL message	
Explanation	An unexpected condition in which IOS cannot allocate TDL message for Management ethernet.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_MGMTE-3-MSGTDLINITERROR: Management ethernet interface messaging module initialization failed: Unable to initialize messaging: [chars]	
Explanation	The Management ethernet interface subsystem has failed to initialize the infrastructure for messaging with the Pluggable Services Daemon. Configuration of management ethernet modules cannot proceed.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_MGMTE-3-PROCESS_CREATE_FAIL : Management ethernet statistics process creation failed	
Explanation	Can not create IOS process for RP management ethernet port statistics collection
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_RP_NV

%IOSXE_RP_NV-3-NV_ACCESS_FAIL : Initial read of NVRAM contents failed	
Explanation	This error happens when the contents of the NVRAM cannot be read during system initialization. The failure may be due to data corruption of the NVRAM contents. The initial configuration dialog will be entered and the configuration must be restored.
Recommended Action	LOG_STD_ACTION

%IOSXE_RP_NV-3-BACKUP_NV_ACCESS_FAIL : Initial read of backup NVRAM contents failed	
Explanation	This error happens when the contents of the backup NVRAM cannot be read during system initialization. The failure may be due to data corruption of the backup NVRAM contents. The primary nvram contents will be backed up here again.
Recommended Action	LOG_STD_ACTION

IOSXE_RP_SPA

$\% IOSXE_RP_SPA-3-SEND_NGIO_MSG_FAIL: NGIO\ Module\ message\ send\ failed\ for\ slot\ [dec]\ subslot\ [dec]$	
Explanation	Failed to send ngio msg to iomd.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-3-MAC_FILTER_ADD_FAIL : All the available [dec] mac filters for [chars] have been consumed. Failed to add [enet] for interface [chars]	
Explanation	The hardware cannot support any more filters.
Recommended Action	The interface configuration should be reworked to not cross the limit set by the hardware. If the error is still seen please LOG_STD_SH_TECH_ACTION

%IOSXE_RP_SPA-3-SEND_L2_HDR_MSG_FAIL : slot [dec] subslot [dec]		
Explanation	Failed to send ngio L2 header to iomd.	_

%IOSXE_RP_SPA-3-SEND_L2_HDR_MSG_FAIL : slot [dec] subslot [dec]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-3-NO_HOST_INFO: slot [dec] subSlot [dec], spaType [hex]

Explanation

Failed to get information about the host linecard.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\$IOSXE_RP_SPA-3-MAX_SPA$: Power to IPSEC-SPA-2G in [chars] is denied because it has exceeded the number allowed([dec])

Explanation

The number of IPSEC-SPA-2G in a chassis is limited. This message is displayed when the number of IPSEC-SPA-2G in the chassis has exceeded this limit.

Recommended

Use only the number of supported IPSEC-SPA-2G

Action

%IOSXE_RP_SPA-3-SPA_NO_HOST_INFO: slot [dec] subSlot [dec], PID [chars]

Explanation

Failed to get information about the host linecard.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE RP SPA-3-HWIDB FAILURE: Creation: slot [dec] subSlot [dec] port [dec] vc [dec]

Explanation

Failed to create an interface hwidb.

%IOSXE_RP_SPA-3-HWIDB_FAILURE: Creation: slot [dec] subSlot [dec] port [dec] vc [dec]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the

error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\$IOSXE_RP_SPA-3-INVALID_PORT_NUM: slot=[dec], hwidbType=[hex], max_port_num=[dec], LCtype=[hex]$

Explanation

The port number is out of range.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the

error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-4-SPA_RESP_CMD_MISMATCH: [chars]: Expecting response to interface configuration command [int] but received response to command [int].

Explanation

An internal synchronization error occurred while configuring the interface. The

configuration may not have succeeded.

Recommended Action

Check that the running configuration for the interface is correct. If this message occurred on the standby, try reloading the standby to ensure that its configuration is in sync. If this message is repeatable, please LOG STD SH TECH ACTION

%IOSXE_RP_SPA-6-CARDRELOAD : Module [int] reload due to SPA insert in [int]/[int].

Explanation

When inserting a SPA on this carrier card, the card is reset.

Recommended Action

No action is required.

$\$IOSXE_RP_SPA-6-CTRLRSWITCH: switching controller type from [chars]([dec]) to [chars]([dec]) for subslot [int]/[int].$

Explanation

When IOSXE-SIP40 is inserted in the slot previously occupied by IOSXE-SIP10 or vice-versa the controller type of the card is overwritten to reflect the current SIP.

Recommended Action

No action is required.

$\$IOSXE_RP_SPA-4-SPA_CMD_NO_RESP: [chars]: No \ response \ for \ interface \ configuration \ command \ [int]$	
Explanation	A timeout occurred while RP was waiting for a response from line card. This may happen due to line card CPU being too busy to respond to the command.
Recommended Action	No action is required.

%IOSXE_RP_SPA-3-IPCALLOCFAIL : Failed to allocate IPC buffer [chars]	
Explanation	The RP failed to allocate a buffer for communication with a SPA
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-3-DPIDX_LKUP_FAIL : Failed to retrieve datapath identifier for interface [chars]	
Explanation	The SPA driver is not able to retrieve the datapath identifier for the interface specified in the message. This indicates a software error.
Recommended Action	No action is required.

%IOSXE_RP_SPA-3-FLOWID_ALLOC_FAIL: Failed to allocate a flow control identifier for interface [chars]	
Explanation	The SPA driver is not able to allocate the datapath flow control identifier for the interface specified in the message. This indicates a software error.
Recommended Action	No action is required.

%IOSXE_RP_SPA-3-FLOWID_RELEASE_FAIL : Failed to release a flow control identifier for interface [chars] (status = [dec])	
Explanation	The SPA driver is not able to release the datapath flow control identifier for the interface specified in the message. This indicates a software error.
Recommended Action	No action is required.

%IOSXE_RP_S	SPA-3-VC_PRO	V_{FAIL} : Failed to	o provision interfac	ce [chars]
			•	

Explanation The SPA driver is not able to provision the interface specified in the message. Verify

that the SPA hardware is not provisioned above the supported limit. Otherwise, this

indicates a hardware error.

Recommended

Action

No action is required.

%IOSXE_RP_SPA-3-CI_UPDATE_FAIL: Failed to update connection identifier for interface [chars]

Explanation The SPA driver is not able to update the datapath connection identifier for the interface

specified in the message. This indicates a software error.

Recommended

Action

No action is required.

%IOSXE_RP_SPA-3-NULL_DATA_STRUCTURE: common_str_empty_str

Explanation A SPA driver is not able to retrieve the data structure mentioned in the message. This

indicates a software error.

Recommended

Action

No action is required.

%IOSXE RP SPA-3-HWIDB INIT FAIL: Failed to initialize data structure for SPA port [dec]/[dec]/[dec]

Explanation A SPA driver was not able to properly initialize a data structure mentioned in the

message. This indicates a software error.

Recommended

Action

No action is required.

%IOSXE_RP_SPA-3-ERROR: common_str_empty_str

Explanation This message can take many forms. It provides information about a software error.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log.

Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If
you still require assistance open a case with the Technical Assistance Center via the

you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-4-LCLOG_TOOLONG : Message too long from slot [int]/[int]: [int] bytes

Explanation The SPA module passed down a logger message that is too long for the RP to handle.

%IOSXE_RP_SPA-4-LCLOG_TOOLONG : Message too long from slot [int]/[int]: [int] bytes

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-4-LCLOG_PARSE_ERR: Error parsing logger message: [chars] from subslot [int]/[int]

Explanation

The SPA module passed down a logger message that could not be parsed.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-3-BAD_IFCOMTYPE : Bad ifcom message type=[int]

Explanation

A SPA module passed down a message that the RP software was not prepared to handle.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-4-IPCFAILED: IPC failed to send RPC message to SPA module

Explanation

The RP failed to send an RPC message via IPC to a SPA module.

Recommended Action

No action is required.

%IOSXE_RP_SPA-3-FOREVER: cmd [int] to [chars] (slot [int]/[int]) took [int]secs, done [hex]

Explanation

A CCB command from the RP to a SPA module took longer than expected.

Recommended Action

%IOSXE_RP_SPA-4-SEMAHOG : Process [dec] ([chars]) hogging [chars]! calling proc [dec] ([chars])	
Explanation	The RP waited too long for a reply to a command sent to a SPA module.
Recommended Action	No action is required.

%IOSXE_RP_SPA-3-IPCPORTFAIL : Failed to open IPC port '[chars]' with error [chars]	
Explanation	The RP failed to open a port for communication with a SPA module.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-4-CCB_PLAYBACK_ERROR : CCB playback failed for slot [dec].	
Explanation	The High Availability component for SPA modules failed to synchronize some new state information for the specified slot.
Recommended Action	Reload the standby supervisor module to force a fresh bulk synchronization. If this error recurs, LOG_STD_ACTION

%IOSXE_RP_SPA-4-CCB_RECORD_ERROR : CCB record failed for slot [dec].	
Explanation	The High Availability component for SPA modules failed to record some new state information for the specified slot.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-3-IPCSENDFAIL : Failed to send IPC message [chars]		
Explanation	The RP failed to send a message to a SPA module.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_RP_SPA-3 command [int].	3-IFCFG_NO_UNIQUE_KEY : No unique-key generator registered for interface configuration
Explanation	The High Availability component for SPA modules is unable to properly synchronize state information for the current configuration.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-3-IFCFG_FOREVER : to [chars] (slot [int]/[int]) took [int]secs, ret_val [int]		
Explanation	A interface config command from the RP to a SPA module took longer than expected.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_RP_SPA- out	4-IFCFG_CMD_TIMEOUT : Interface configuration command ([hex]) to slot [int]/[int] timed
Explanation	The RP sent an configuration command to the slot specified in the error message and received no confirmation for the command.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-3-IFCFG_CMD_NOT_OWNER : Process '[chars]' waiting for interface configuration command ([hex]) to slot [int]/[int] without acquiring lock owned by process '[chars]'	
Explanation	A process on the RP sent an configuration command to the slot specified in the error message and a different process waited for the result. This could cause incorrect line card configuration states.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-4-IFCFG_DFLT_LIST_ERROR : For Interface Configuration command [int], default retval list search resulted [hex] for slot [int]/[int]	
Explanation	The High Availability component for SPA modules failed to synchronize some new state information for the specified slot.
Recommended Action	LOG_STD_SH_CMD_ACTION(show platform redundancy if-config default-retvals)

%IOSXE_RP_SPA-4-IFCFG_PLAYBACK_ERROR : Interface Configuration command [int] playback failed for slot [int]/[int].	
Explanation	The High Availability component for SPA modules failed to synchronize some new state information for the specified slot.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-4-IFCFG_RECORD_ERROR : Interface Configuration command [int] record failed for slot [int]/[int].	
Explanation	The High Availability component for SPA modules failed to record some new state information for the specified slot.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-4-INCR_CFG_SYNC_FAIL: [chars] incremental running-config sync for [[dec]/[dec]] failed - [chars]([dec]) , Reload Standby	
Explanation	The specified IOSXE incremental running-config sync failed
Recommended Action	Power cycle the redundant supervisor

%IOSXE_RP_SPA-3-IPCPORT : Failed to [chars] IPC port '[chars]', error [chars]	
Explanation	The Linecard failed to create a port for communication with the Route Processor (IOSXE-RP).
Recommended Action	Copy the error message exactly as it appears, and report it to your technical support representative.

%IOSXE_RP_SPA-3-PROGRESSION : Unable to inform RF of bulk sync completion; [chars]	
Explanation	The standby has failed to notify the active that its bulks synchronization of the SPA TSM has completed. The resultant action taken by the standby route processor is an attempt to resynchronize.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-3-VC_FLOWID_ALLOC_FAIL: Failed to allocate a flow control identifier for VC [dec] under interface [chars]	
Explanation	The SPA driver is not able to allocate the datapath flow control identifier for the VC/interface specified in the message. This indicates a software error.
Recommended Action	No action is required.

%IOSXE_RP_SPA-3-VC_INGID_ALLOC_FAIL : Failed to allocate a ingress identifier for VC [dec] interface [chars]	
Explanation	The SPA driver is not able to allocate the datapath ingress identifier for the VC/interface specified in the message. This indicates a software error.
Recommended Action	No action is required.

%IOSXE_RP_SPA-4-SPA_RESP_CMD_ERR: [chars]: Received response to interface configuration command [chars] with wrong return value [int].	
Explanation	An internal error occurred while configuring the interface. The configuration may not have succeeded.
Recommended Action	Check that the running configuration for the interface is correct. If this message is repeatable, please LOG_STD_SH_TECH_ACTION

%IOSXE_RP_SPA-3-FRR_CFG_REC_FAIL : Failed to record fast reroute conifguration on [chars]: [chars]	
Explanation	This message is displayed when a fast reroute configuration is not properly recorded.

%IOSXE_RP_SPA-3-FRR_CFG_REC_FAIL: Failed to record fast reroute conifguration on [chars]: [chars]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-3-MISSING_SPA_PKG_ERR: sipspa[chars] package is not installed for slot = [dec] and subslot = [dec], SPA bootup failed.

Explanation This message is displayed when attempting to bootup a SPA without installing a subpackage required for the same.

Recommended Action

Download the sub-package required for the affected SPA from the Cisco CCO software download site and install the same. This SPA can be booted in sub-package mode only. Please refer to the Cisco ASR platform documentation for obtaining and installing sub-packages.

$\$IOSXE_RP_SPA-3-UNSUPPORTED_SRVCS_SPA: Service SPA ([hex]) in [dec]/[dec] is not supported. SPA bootup failed.$

Explanation This message is displayed when attempting to bootup any service SPA in router running

non K9 image, i.e., non-crypto image.

Recommended Action

Download the K9 IOS XE sub-packages and the required sub-package for the given service SPA from the Cisco CCO software download site and install the same. This SPA can be booted in sub-package mode only. Please refer to the Cisco ASR platform documentation for obtaining and installing sub-packages.

%IOSXE_RP_SPA-3-MISSING_SPA_PKG_WARN: sipspa[chars] package is not installed in standby for slot = [dec] and subslot = [dec].

Explanation

This message is displayed in standby console when attempting to bootup or restart or reload a WMA SPA without installing a subpackage in the standby RP, although the SPA is or will be operational due to prior wma spa package installation in active RP. If switchover takes place the WMA SPA will still be operational. But any subsequent soft or hard oir of the SPA will fail due to missing sub package required to boot up the SPA. Hence it is recommended to complete the wma spa package installation in standby also before switchover or immidiately after switchover.

Recommended Action

Download the sub-package required for the affected SPA from the Cisco CCO software download site and install the same for the standby RP as is done on active RP. Please refer to the Cisco ASR platform documentation for obtaining and installing sub-packages.

%IOSXE_RP_SPA-3-SPA_WRONGTYPE : Mismatched SPA type ([dec]) in slot [dec]/[dec]. Expected type [dec]. Use 'no card [dec]/[dec]' command to override preprovisioning and update card type.	
Explanation	The SPA inserted does not match the currently provisioned SPA type.
Recommended Action	Replace wrong SPA with currently provisioned SPA type, or type 'no card' to allow new card type to be discovered.

%IOSXE_RP_SPA-6-MEDIA_AUTOFAILOVER : Media Fail over from ([chars]) to ([chars])	
Explanation	Gige Media Failover.
Recommended Action	This is inforamtional message, Not an error message. Use 'show interface gig' to see the current active media type.

%IOSXE_RP_SPA-3-SONET_ALARM_PROC_ERR: [chars] Error has occurred while processing in the sonet alarm-proc	
Explanation	Either free/create of the memory failed in SONET alarm proc
Recommended Action	

$\label{losxe_rp_spa} $$ \noindent $$ IOSXE_RP_SPA-3-LIC_REQ_FAILED: [int]/[int]/[int]: Interface enable not allowed - license request failed , err=[hex]$	
Explanation	A 10 Gig License is required to enable this port. License request has been denied by license manager
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-3-LIC_REL_FAILED : [int]/[int]/[int]: Failed to release license feature [chars], handle=[hex], err=[hex]	
Explanation	License release has been denied by license manager
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_SPA-3-LIC_REG_FAILED : [int]/[int]/[int]: Failed to register license feature [chars], err=[hex]		
Explanation	License registration has been denied by license manager	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

$IOSXE_RP_VTYMGT$

%IOSXE_RP_VTYMGT-3-MSGDISPATCHNULL : Received NULL TDL message		
Explanation	An unexpected condition in which IOS has received a NULL TDL message for Vty Management.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_RP_VTYMGT-3-MSGDISPATCH : Unable to dispatch received TDL messages for Vty Management		
Explanation	An unexpected condition has occurred while IOS is trying to dispatch to the TDL message handler functions for received TDL messages for Vty Management.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_RP_VTYMGT-3-MSGMISSINGFIELD : Missing field '[chars]' in TDL Vty Management message '[chars]' received		
Explanation	A message missing a required field was received for Vty Management	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_RP_VTYMGT-3-MSGINVALIDFIELDINT : Invalid field '[chars]' in TDL message '[chars]' received: value '[int]' for Vty Management

Explanation

A message with an invalid field value was received for Vty Management

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_VTYMGT-3-MSGINVALIDFIELDSTR : Invalid field '[chars]' value '[chars]' in TDL message '[chars]' received for Vty Management

Explanation

A message with an invalid field value was received for Vty Management

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_VTYMGT-3-MSGERROR : Error '[dec]' handling a received TDL message '[chars]' for Vty Management: [chars]

Explanation

An unexpected condition has occurred while IOS is processing a received Vty

Management TDL message

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_VTYMGT-3-MSGBUILDERROR : Error '[dec]' building TDL Vty Management message '[chars]': [chars]

Explanation

An unexpected condition has occurred while IOS is building a TDL response message

for Vty Management

Recommended Action

$\% IOSXE_RP_VTYMGT-3-MSGMARSHALERROR: Error '[dec]' \ marshaling \ TDL \ Vty \ Management \ message \ '[chars]': [chars]$	
Explanation	An unexpected condition has occurred while IOS is marshaling TDL response message for Vty Management
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_VTYMGT-3-MSGENQUEUEERROR : Error queueing TDL Vty Management message '[chars]'	
Explanation	An unexpected condition has occurred when IOS attempted to queue a TDL response message for Vty Management
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_VTYMGT-3-MSGBIPCERR : Unable to process received BIPC messages for Vty Management, error: [chars]	
Explanation	An unexpected condition has occurred while IOS was trying to process a received BIPC message for Vty Management.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_VTYMGT-3-MSGBIPCBUFFER : Unable to acquire a BIPC buffer of length [dec] for sending messages.	
Explanation	A message was to be sent by IOS, but no BIPC buffer was available. The message to be sent has been discarded and the associated operation failed.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_VTYMGT-3-MSGEXTAPPUPDATE : Unable to update external application data for line '[dec]'	
Explanation	An attempt to update the external application for a line failed unexpectedly. The line update failed and if the line number specified is valid, the line was released.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_VTYMGT-3-MSGVTYSVCINIT : Unable to initialize the Vty Management service listen port	
Explanation	The platform IPC services failed to register the Vty Management service's need for a listen port. The Vty Management service will be unable to process requests. IOS services will be unavailable to external access methods.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_VTYMGT-3-MSGVTYCOUNT : Invalid vty count [dec] detected on initialization	
Explanation	Upon initialization, the Vty Management subsystem checks that the number of available vtys for the platform is valid.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_RP_VTYMGT-3-SET_ACCESS_FAIL : Installing LIIN interface access control failed	
Explanation	This error happens when the Vty Management subsystem failed to set the access control function for the LIIN, possibly due to IOS out of memory or corruption. Persistent access features into IOS will not work.
Recommended Action	LOG_STD_ACTION

IOSXE_SERVICE_ENGINE

%IOSXE_SERVICE_ENGINE-3-MSGOPENFAIL : Cannot open interface [chars] ([dec])	
Explanation	During the creation of a Service-Engine interface, it is necessary to program the system parameters in the driver. The driver cannot be opened.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SERVICE_ENGINE-3-MSGSETFAIL : Set id on interface [chars] ([dec])	
Explanation	During the creation of a Service-Engine interface, it is necessary to program the system parameters in the driver. The failed to accept the programming.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SERVICE_ENGINE-3-MSGINITFAIL : Initialization of interface [chars] failed	
Explanation	The initialization of the interface mentioned in the error message has failed.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_SPA

%IOSXE_SPA-3-CREATION_FAILURE : slot=[dec] subslot=[dec], spa_type=[hex], lc_type=[hex].	
Explanation	Failed to create a SPA object.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-3-SPA_CREATION_FAILURE: slot=[dec] subslot=[dec], PID=[chars] lc_type=[hex].

Explanation Failed to create a SPA object.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the

error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE SPA-3-NULL VFT: [chars] virtual function table is not initialized. spaType=[hex]

Explanation A required function table is not initialized

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE SPA-3-NULL VFUNC: [chars] vector is not initialized. spaType=[hex]

Explanation A required function vector is not initialized

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-3-MEM_ALLOC_ERROR: [chars]

Explanation Memory allocation error.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support

representative and provide the representative with the gathered information.

%IOSXE_SPA-3-NULL_SPA_PTR:

Explanation

Pointer to a SPA object is NULL.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE SPA-3-NULL BAY PTR:

Explanation

Pointer to SPA bay is NULL.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE SPA-3-INVALID SLOT NUM: slot= [dec], max slot = [dec]

Explanation

An invalid slot number is specified in one of the internal APIs.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-3-INVALID_SUBSLOT_NUM: subslot=[dec], max subslot = [dec]

Explanation

An invalid subslot number is specified in one of the internal APIs.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

%IOSXE_SPA-3-INVALID_DB_NUM : db = [dec], max db = [dec], db intf = [dec], max db intf = [dec]

Explanation

An invalid daughter board number is specified in one of the internal APIs.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE SPA-3-INVALID RP SLOT NUM: slot=[dec], max slot = [dec]

Explanation

An invalid RP slot number is specified in one of the internal APIs.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE SPA-3-INVALID CPU NUM : cpu= [dec], max cpu = [dec]

Explanation

An invalid CPU number is specified in one of the internal APIs.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-3-INVALID_SLOTUNIT_NUM : cardwide-port = [dec], max cardwide-port = [dec]

Explanation

An invalid cardwide-port number is specified in one of the internal APIs.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

%IOSXE_SPA-3-INVALID_INDX_RANGE : index1= [dec], index2= [dec], maxIndex= [dec]

Explanation

An invalid index range is specified in one of the internal APIs.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-3-INVALID_IF_INDEX : index= [dec], spaType=[hex], slot [dec] subSlot [dec] slotunit [dec] vc [dec]

Explanation

Index for the interface is not valid.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-3-INVALID_DATA_INSTANCE: interface type [chars], slot [dec] port [dec] vc [dec]: [chars]

Explanation

Data required to support the interface is not available.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-3-POWER_CYCLE: [chars] occurred on Shared Port Adapter [int]/[int]

Explanation

An error has occurred which will cause the Shared Port Adapter to be power cycled

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support

representative and provide the representative with the gathered information.

%IOSXE SPA-3-DIAG CONFIG: [chars] did not complete [dec]/[dec]

Explanation

An error has occured during diagnostic test.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the

error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-3-UNSUPPORTED_DATA : Data conversion error ([chars], [hex])

Explanation

An internal software error has occured when converting the data specified in the

message from one representation to another.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-3-IPC_FAILURE : IPC failure while [chars]

Explanation

An error has occurred while prepareing or sending an IPC message.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-3-SENDCFGFAIL : Failed to send configuration for [chars] to carrier-card for subslot=[dec]/[dec]

Explanation

Sending configuration failed.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the

error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

%IOSXE_SPA-3-CREATE_TDLH_FAILURE : Failed to create SPA [dec]/[dec] handle

Explanation

Failed to create message handle for SPA communication.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-3-DOMAIN_TDLH_FAILURE : [chars], rc = [dec]

Explanation

Failed to bind message handle for SPA communication.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-3-SETUP_TDLH_FAILURE : Failed to set the alloc/free handler for SPA [dec]/[dec] handle

Explanation

Failed to set the alloc/free handler for SPA communication.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-3-DISPATCH_INIT_TDLH_FAILURE : Failed to initialize dispatch path for SPA [dec]/[dec] handle

Explanation

Failed to initialize dispatch path handle for SPA communication.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

%IOSXE_SPA-3-INVALID_SPA_TDL_CCAPI_USAGE:

Explanation Incorrect usage of an internal API that should only be used on CC.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-6-TDLMSG_INCOMPATIBLE: Failed to copy message [chars] to buffer, not allowed for current domain.

Explanation Failure to marshal a message indicates an incompatibility with the intended recipient.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-3-CREATE_TDLMSG_FAILURE : Failed to create [chars] message for [chars].

Explanation Failed to create/allocate necessary TDL message for SPA communication.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_SPA-3-INVALID_HANDLE : Failed to get a valid IPC handle for type [int], slot [dec], subslot [dec].

Explanation The client handle was found to be NULL for the given type/slot/subslot.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

Explanation	Ethernet link is down due to remote/local fault.	
Recommended Action	Replace the faulty cable.	

%IOSXE_SPA-6-DUAL_RATE_CHANGE : [chars]: [chars]	
Explanation	Change in rate of the link.
Recommended Action	No action is required.

%IOSXE_SPA-3-SPA_SETUP_FAILURE : Failed to properly setup for SPA communication on slot [dec], subslot [dec].	
Explanation	Discovery of the linux interface used to communicate with a SPA failed
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\% IOSXE_SPA-3-ABANDON_SPA_CONFIGURATION: Abandon configuration for subslot [dec]/[dec], the SPA type([dec]) is NOT match with SUP card.$	
Explanation	Abandon SPA configuration.
Recommended Action	Please check the startup configuration, use no card command to override wrong card configuration and update card type.

IOSXE_TIMESTAMP_ENGINE

%IOSXE_TIMESTAMP_ENGINE-4-ERROR: NULL	
Explanation	An unexpected condition has occurred.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_TIMESTAMP_ENGINE-3-TSU_ERR : An unexpected condition has occurred at module ([chars])	
Explanation	An unexpected condition has occurred at the Interface Module TSU.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_UPGRADE_ROMMON

%IOSXE_UPGRADE_ROMMON-0-ROMMON_UPGRADE_FAIL : ROMMON upgrade failed: partition [chars]	
Explanation	An attempt to upgrade the ROMmon failed.
Recommended Action	Check the system messages to see if any messages appeared that might indicate the source of the ROMmon problem. If you do not find any additional information indicating a correctable problem, collect all output on the screen, in particular the console port output after the upgrade rom-monitor command was entered and the output of show rom-monitor, and provide the collected information to a Cisco technical support representative.

%IOSXE_UPGRADE_ROMMON-0-ROMMON_LOADTEST_FAIL : ROMMON FIPS_140-3 Load test *FAILED*: file [chars]	
Explanation	FIPS 140-3 Related Load test failed for the ROMmon.
Recommended Action	Check the system messages to see if any messages appeared that might indicate the source of the ROMmon Load test problem. If you do not find any additional information indicating a correctable problem, collect all output on the screen, in particular the console port output after the upgrade rom-monitor command was entered and the output of show rom-monitor, and provide the collected information to a Cisco technical support representative.

$IOSXE_USB$

%IOSXE_USB-3-ESHOW_USB : Internal Error locating database for USB Devices.	
Explanation	The mcp_usb_devices is incorrect and needs to be changed
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_UTD

When attempting to program the dataplane there was not enough memory to allocate the message. ### Recommended Action | Copy the error message exactly as it appears on the console or in the system log. | Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_UTD-3-MESSAGE : Failed to send message	
Explanation	When the message was being prepared for sending to the data plane, there was an error.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_UTD-4-VERSION_INCOMPATIBILITY : UTD OVA version ([chars]) does not match supported UTD version ([chars])	
Explanation	The UTD OVA version does not match the required UTD version embedded in this IOS-XE version. This is an unsupported configuration and may behave unexpectedly.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\$IOSXE_UTD-4-SIG_UPDATE_CFG:UTD$ signature updates have been configured - A brief service interruption at the time of update is expected

Explanation

The UTD service will be restarted if a new signature package is found. During this time, if fail-close has been configured (recommended), traffic that would be inspected by UTD will be dropped. Otherwise (default), traffic that would be inspected by UTD will be allowed to pass uninspected. To minimize this service interruption, it is recommended to schedule this operation outside of normal business hours.

%IOSXE_UTD-4-SIG_UPDATE_CFG: UTD signature updates have been configured - A brief service interruption at the time of update is expected

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_UTD-4-SIG_UPDATE_EXEC: UTD signature update has been executed - A brief service interruption is expected

Explanation

The UTD service will be restarted if a new signature package is found. During this time, if fail-close has been configured (recommended), traffic that would be inspected by UTD will be dropped. Otherwise (default), traffic that would be inspected by UTD will be allowed to pass uninspected. To minimize this service interruption, it is recommended to execute this operation outside of normal business hours.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_UTD-4-MT_CONFIG_DOWNLOAD: UTD MT configuration download has [chars]

Explanation

In UTD multitenancy mode, the configuration download to the container can take a while. Please be patient.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_UTD-4-MT_CONTAINER_MESSAGE_TIMEOUT: UTD message sent to the container has timed out

Explanation

The UTD message sent to the container has timed out.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_UTD-4-MT_CONTAINER_MESSAGE_NAK : Container responded to UTD message with an error: [dec]	
Explanation	The container rejected the UTD message
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_UTD-4-MT_CONTAINER_SESSION_TIMEOUT : UTD container download has timed out		
Explanation	The container did not respond with an up/down status before the session timed out.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_UTD-4-MT_CONTAINER_STATUS_DOWN : UTD poll: container status is DOWN		
Explanation	The container sent a down status to the poll message	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

IOSXE_VMAN through IPC_LOG

- IOSXE_VMAN
- IOSXE_WCCP
- IOSXE_WD
- IOS_LICENSE_IMAGE_APPLICATION
- IOXN_APP
- **IP**
- IPA
- IPACCESS
- IPC

• IPC_LOG

IOSXE_VMAN

%IOSXE_VMAN-3-MSGINITFAIL : Failed to initialize required Virt-manager resource: [chars]	
Explanation	During the initialization of the resources required by Virt-manager, a failure occurred. This has prevented virtual services from being activated.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_VMAN-3-MSGDISPATCH : Unable to dispatch received TDL message from Virt-manager		
Explanation	An unexpected condition has occurred while IOS was trying to dispatch a TDL message received from Virt-manager.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IOSXE_VMAN-3-RSPMSGHDLR : Failed to deliver response message: [chars]	
Explanation	An unexpected condition has occurred while IOS was trying to deliver a response message to a virtual service received from Virt-manager.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE_WCCP

O/ IOOVE	MACON A	NOUNDLIT			
%IUSXE	WCCP-4	-NOINPUT	: NULL	inbut.	Icharsi

Explanation An unexpected condition has occurred which is due to the NULL value of the input

parameter.

%IOSXE_WCCP-4-NOINPUT : NULL input, [chars]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show ip wccp** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_WCCP-4-NOSVCGRP: [chars] Service Group ([dec], [dec], [int]) NOT exist

Explanation

An unexpected condition has occurred which is due to the absence of the service group structure.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show ip wccp** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE WCCP-4-NOACL: Access list is null

Explanation

An unexpected condition has occurred which is due to the absence of an access list structure.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show ip access-lists** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_WCCP-4-ACELIMIT: Too many ACEs in MASK ACL, please switch to Hash mode

Explanation

Mask merged ACL generate too many ACEs.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show ip access-lists** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

%IOSXE_WCCP-4-BADACE : Access list contains invalid ace

Explanation An unexpected condition has occurred which is due to an invalid statement in the

access list structure.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show ip access-lists** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE WCCP-4-NOINTF: No [chars] interface info for Service Group ([dec], [dec], [int])

Explanation An unexpected condition has occurred which is due to the absence of MCP WCCP

interface info for the specific service group.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show platform software wccp** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_WCCP-4-UNKNOWNDIR: Unknown [chars] interface direction [hex] for Service Group ([dec], [dec], [int])

Explanation An unexpected condition has occurred which is due to the unknown direction has been

applied to the interface for the service group.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show platform software wccp** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_WCCP-4-NOSTATS: WCCP [chars] message error

Explanation

An unexpected condition has occurred which is due to the error in receiving WCCP stats update message.

%IOSXE_WCCP-4-NOSTATS: WCCP [chars] message error

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show platform software wccp <id> counters** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE_WCCP-4-NOSTATSSVC: Service Group ([dec], [dec], [int]) not exist for the stats message

Explanation

An unexpected condition has occurred which can't find the service group for the service

Recommended Action

group stats message.

Copy the error message exactly as it appears on the console or in the system log. Issue the **show platform software wccp** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOSXE WCCP-4-NOSTATSINTF: Interface handle [int] not exsit for the stats message

Explanation

An unexpected condition has occurred which can't find the interface handle for the interface stats message.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show platform software wccp <id> int counters** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IOSXE WD

%IOSXE_WD-2-HEARTBEAT_FAIL : Heartbeat is not emitted. Heartbeat count:[dec] Explanation Failure in IOS to generate a heartbeat is an abnormal condition Recommended Action This message may be related to an abnormal configuration and system load, or transient high processing demand. When reporting this message, copy the message text exactly as it appears, include the stack trace and report to your technical support representative

%IOSXE_WD-2-HOG_DETECT_FAIL : CPUHOG detection failed to start.	
Explanation	Failure in setting up CPUHOG detection mechanism is an abnormal condition
Recommended Action	This message may be related to an abnormal configuration and system load, or transient high processing demand. When reporting this message, copy the message text exactly as it appears, include the stack trace and report to your technical support representative

IOS_LICENSE_IMAGE_APPLICATION

%IOS_LICENSE_IMAGE_APPLICATION-3-FAILED : [chars]	
Explanation	The ios licensing subsystem failed to create a process/watched boolean etc to watch request from the remote show subsys license commands
Recommended Action	please capture the error msg and forward it to the appropriate licensing component

%IOS_LICENSE_IMAGE_APPLICATION-3-UNKNOWN_EVENT : [chars]	
Explanation	The ios image licensing subsystem received an event which it does not understand or recognizes
Recommended Action	please capture the error msg and forward it to the appropriate licensing component

%IOS_LICENSE_IMAGE_APPLICATION-3-UNKNOWN_VERSION : [chars]
Explanation
Recommended Action

%IOS_LICENSE_IMAGE_APPLICATION-6-NO_LICENSE: No valid license available: [chars] = [chars]; [chars] = [dec]; [chars] = [chars]:[chars]	
Explanation	The ios image licensing subsystem received an event for an unknown version of a feature There is no valid license available on the box and we are running on a default feature
Recommended Action	please capture the error msg and forward it to the appropriate licensing component please purchase a license to activate required features

%IOS_LICENSE_IMAGE_APPLICATION-6-LICENSE_LEVEL : Module name = [chars] Next reboot level = [chars] and License = [chars]	
Explanation	This is an informational message to display the change in the next reboot license level

%IOS_LICENSE_IMAGE_APPLICATION-6-LICENSE_LEVEL : Module name = [chars] Next reboot level =
[chars] and License = [chars]

Recommended

This is an informational message, no action is required

Action

%IOS_LICENSE_IMAGE_APPLICATION-6-LICENSE_LEVEL_CONFIG: Please issue 'license boot' config command to make extension license ([chars]) available for use.

Explanation This is an informational message to info user that to make extension license available

to support image level, licensing image level needs to be configured

Recommended Action This is an informational message, no action is required

%IOS_LICENSE_IMAGE_APPLICATION-6-LICENSE_CONFIG : EULA must be accepted for license level = [chars]

Explanation

This is an informational message to inform user that the user needs to reissue the

command from an interactive terminal

Recommended Action This is an informational message, no action is required

IOXN_APP

$\%IOXN_APP-3-INITFAIL:$ Failed to create chasfs property ioxman (rc =[chars]) or caf (rc = [chars]) is not up

Explanation

An unexpected condition resulted into failure to start an application.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOXN_APP-3-CLEANUPFAIL: Failed to create chasfs property to indicate cleanup of previous app installation (rc = [chars])

Explanation

An unexpected condition resulted in failure to setup the start of an application.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOXN APP-3-GSFAIL: [chars] [int]

Explanation An unexpected condition resulted into failure to start an application.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOXN_APP-3-CFGFAIL: [chars] [chars]

Explanation An unexpected condition resulted into failure to apply auto config

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\$IOXN_APP-3-PREVOPFAIL: Overriding previous operation ([chars] iox) that is taking longer than [int] secs to complete$

Explanation

An unexpected condition resulted in failure to apply iox config

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IOXN_APP-3-MSGFAIL : Message dispatch failure ([chars]).

Explanation Message could not be dispatched to an application.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IP

%IP-4-CLASS : Bad IP address and mask [IP_address]%m in class_resolve()

Explanation An internal software error occurred.

%IP-4-CLASS: Bad IP address and mask [IP_address]%m in class_resolve()

Recommended Action

If this message recurs, copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IP-4-DUPADDR: Duplicate address [IP_address] on [chars], sourced by [enet]

Explanation

Another system is using your IP address.

Recommended Action

Change the IP address of one of the two systems.

%IP-4-ZERO_ADDR: Zero MAC address for [IP_address] in ARP cache

Explanation

An entry in the ARP cache have a NULL MAC address

Recommended

Action

If this message recurs, call your technical support representative for assistance.

%IP-3-DESTHOST: src=[IP address], dst=[IP address], NULL desthost

Explanation

An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IP-3-BADIPALIGN: Invalid alignment in packet for IP. [chars]=[hex]

Explanation

The packet data structure is misaligned. This condition may result in a small amount of overhead in processing IP traffic.

Recommended Action

Enter a show hardware command and report the output, along with this error message, to your technical support representative.

%IP-3-BADSROUTE: Improper source route. Length [dec] Ptr [dec]

Explanation

A hardware or software error occurred.

%IP-3-BADSROUTE: Improper source route. Length [dec] Ptr [dec]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IP-6-PHYBCASTDROP : Physical broadcast packet detected and dropped, src=[IP_address], dst=[IP_address]

Explanation

Physical broadcast packet was dropped.

Recommended

No action is required.

Action

%IP-6-L2MCASTDROP: Layer 2 Multicast packet detected and dropped, src=[IP_address], dst=[IP_address]

Explanation

Layer 2 Multicast packet with Layer3 Unicast Destination was dropped.

Recommended Action

No action is required.

%IP-3-L00PPAK: Looping packet detected and dropped - src=[IP_address], dst=[IP_address], hl=[int], tl=[int], prot=[int], sport=[int], dport=[int] in=[chars], nexthop=[IP_address], out=[chars]options=[chars]

Explanation

A software error occurred.

Recommended

Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IP-5-WEBINST_START : Attempting web install from host [IP_address]

Explanation

A hardware or software error occurred.

Recommended

Action

Copy the error message exactly as it appears, and report it to your technical support representative.

%IP-5-WEBINST_KILL : Terminating DNS process

Explanation

A hardware or software error occurred.

%IP-5-WEBINST_KILL: Terminating DNS process

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IP-5-WEBINST COMP: Selected IP address [IP address]

Explanation

A hardware or software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IP-5-WEBINST_RESP: Sending DNS response to [IP_address] (request was for [IP_address])

Explanation

A hardware or software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IP-3-CNTRFULL: IP counter block is full (setting protocol [dec])

Explanation

An internal software error occured.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IP-5-TURBOACL: [chars]

Explanation

Error occured in intialisation of TURBOACL.

%IP-5-TURBOACL : [chars]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show process** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IP-5-ACL:[chars]

Explanation

Error occured in IP access checks.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IP-4-UNICASTRPF: IP unicast reverse-path check disabled on [chars]

Explanation

The IP verify unicast reverse-path feature was disabled because CEF was disabled (either through configuration or due to an internal error.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IP-3-LOOPOUTIF: Output interface for packet has been changed for [dec] times and dropped - src=[IP_address], dst=[IP_address], hl=[int], tl=[int], prot=[int], in=[chars], nexthop=[IP_address], out=[chars]

Explanation

A software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

Action

%IP-3-MAXIRDP : Attempt to send IRDP to proxies exceeding configurable limit: [dec], interface: [chars], secondary = [dec], proxy = [dec]	
Explanation	The sum of configured secondary addresses and configured proxy addresses exceeds the number of total addresses that the IRDP can support in its implementation.
Recommended Action	Reduce the number of either the secondary IP addresses or proxy addresses configured for the interface.

%IP-4-IPPOOLS : Detected a local pool and a DHCP pool with the same name: [chars]	
Explanation	A local pool and a DHCP pool have been configured with the same name. This may cause conflict during address allocations.
Recommended Action	Change the name of one of the two pools

%IP-3-ICMPRATELIMIT: [int]nreachables rate-limited within [int] milliseconds on [chars]. [int] log messages suppressed since last log message displayed on [chars]	
Explanation	An excessive number of packets are triggering log messages on this interface
Recommended Action	change the log threshold with the icmp rate-limit command or find the source of the packets and block the packets from this router

%IP-3-ICMPRATELIMITDF: [int] DF unreachables rate-limited within [int] milliseconds on [chars]. [int] DF log messages suppressed since last log message displayed on [chars]	
Explanation	An excessive number of packets are triggering log messages on this interface
Recommended Action	change the log threshold with the icmp rate-limit command or find the source of the packets and block the packets from this router

%IP-3-NOOUTINTF: Output interface not available. source address: [IP_address], destination address: [IP_address], routing type: [int]	
Explanation	The output interface for this packet is not set
Recommended	Copy the error message exactly as it appears on the console or in the system log.

Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IP-3-NONALIAS : non-alias address [IP_address] in table [chars] found in IP alias list	
Explanation	The IP alias list holds IP aliases only but non-alias entries are found.

%IP-3-NONALIAS: non-alias address [IP_address] in table [chars] found in IP alias list

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IP-3-IPTOPOID : Topology ID [hex] is invalid, can't get the base topology ID.

Explanation

An internal software error occurred

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IP-3-SBINIT : Error initializing [chars] subblock data structure. [chars]

Explanation

Initialization of the specified subblock data structure could not be accomplished.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IPA

%IPA-3-PORTCONN: bay [[int]] failed to establish [chars] connection ([hex])

Explanation

An attempt to establish the console or debugger connection with the channel port

adapter failed.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPA-3-PORTIOKILL: Port IO [chars] process terminating.

Explanation

Unexpected termination of a port io process.

%IPA-3-PORTIOKILL: Port IO [chars] process terminating.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPA-3-NEVER: bay [[chars]] mailbox response timed out after ([int] + [int]) usecs, mbx=[hex]

Explanation

A mailbox command sent from driver to the channel port adapter never completed within the expected time limit. As a result of this error, the channel port adapter driver will reset the port adapter and reload microcode to it.

Recommended Action

The reset and reload rectified the problem. If that did not occur, then try the **microcode reload** operation again. <Body><par>If the error still occurs, record the output from the following commands: <Bullet><par>show tech
<Bullet><par>dir slot0: <Bullet><par>dir slot1: <Bullet><par>par>dir slot0 to your technical support representative.

%IPA-3-UKNMBXCMD: [chars]: unknown mailbox command: [hex] [hex] [hex]

Explanation

The channel port adapter sent a mailbox command that the driver did not expect. This may occur if there is a version mismatch between the system image and the microcode.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPA-3-INVMBXCMD : [chars]: invalid mailbox command: [hex]

Explanation

A subsytem attempted to register a mailbox command that is out of range.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

IPACCESS

%IPACCESS-2-NOMEMORY : Alloc fail for acl-config buffer. Disabling distributed mode on Ic	
Explanation	Unable to malloc a buffer to send access-list configuration down to linecards.
Recommended Action	Enter a show chunks command and report the output, along with this error message, to your technical support representative.

%IPACCESS-2-WRONGREQUEST : Invalid request to allocate chunk of size [dec]	
Explanation	We only allow acl chunks of max size IPACCESS_LARGE_CHUNK_SZ
Recommended Action	

%IPACCESS-2-WRONGSIZE : Incorrect length acl ipc xdr of type=[chars] len=[dec] received	
Explanation	Received an acl message of the wrong size for that type
Recommended Action	Report this error message, to your tech support representative.

%IPACCESS-4-INVALIDACL : Invalid ACL field: [chars] is [dec]	
Explanation	An internal software error occurred.
Recommended Action	Copy the message exactly as it appears, and report it to your technical support representative.

%IPACCESS-3-SANITY_ERROR : [chars]	
Explanation	A sanity error occurred while the ACL was being configured on the RP, or while the ACL configuration was being downloaded to the line card.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPACCESS-3-XDRREGISTRATION : Failed to register [chars] XDR client due to [chars]	
Explanation	Failure to register the said XDR client.
Recommended Action	Copy the message exactly as it appears, and report it to your technical support representative.

IPC

%IPC-3-LOG_ERR : [chars] CPP QoS Client Proxy failure	
Explanation	QoS proxy failed because of receiving invalid sub-type or failed to allocate ipc response buffer.
Recommended Action	LOG_STD_ACTION

IPC_LOG

%IPC_LOG-3-IPC_LOGWRITE_FAILED : ipc log write [int] bytes failed because [chars]	
Explanation	An internal logging mechanism failed to write a message.
Recommended Action	No action is required. However, if router performance is noticeably degraded, contact Cisco Technical Assistance. Copy the message exactly as it appears on the console or in the system log. Research and attempt to resolve the issue using the tools and utilities provided at http://www.cisco.com/tac . With some messages, these tools and utilities will supply clarifying information. Search for resolved software issues using the Bug Toolkit at https://bst.cloudapps.cisco.com/bugsearch/ . If you still require assistance, open a case with the Technical Assistance Center via the Internet athttps://mycase.cloudapps.cisco.com/case, or contact your Cisco technical support representative and provide the representative with the gathered information.

IPC_TEST through IPV6_ACL

- IPC_TEST
- IPFAST
- IPFLOW
- IPMOBILE
- IPNAT
- IPNAT_HA
- IPSEC
- IPV4_FORWARDING
- IPV4_REASS_PROXY
- IPV6_ACL

IPC_TEST

%IPC_TEST-3-INVALID_SUBTYPE : CPP IPC TEST Proxy subtype [int]	
Explanation	IPC test proxy failed because of receiving invalid sub-type.
Recommended Action	LOG_STD_ACTION

%IPC_TEST-3-REPLY_FAILED : CPP IPC TEST Proxy send reply	
Explanation	IPC test proxy failed because the reply failed to send.
Recommended Action	

%IPC_TEST-3-MEM_ALLOC_FAILED : CPP IPC TEST Proxy mem alloc	
Explanation	IPC test proxy failed because the GPM allocation failed.
Recommended Action	

IPFAST

%IPFAST-2-RADIXINIT : Error initializing IP fast cache structures	
Explanation	A programming error occurred.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPFAST-2-IPCACHEINIT : Error initializing IP fast cache structures	
Explanation	A programming error occurred.
Recommended Action	Copy the error message exactly as it appears, and report it to your technical support representative.

%IPFAST-2-MSGDROP : IPC queue limit is reached and message is dropped. queue limit = [dec] cumulative drops = [dec]	
Explanation	IPC raw queue limit for IP fast path is reached.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPFAST-6-PAKSHORT : Packet too short from [IP_address], datagram size [dec], tl [dec]	
Explanation	An IP packet which is too short was received
Recommended Action	No action is required.

$\% IPFAST-2-INVALSIZE: The\ IP\ fast\ path\ received\ an\ IPC\ message\ with\ an\ invalid\ size (size/type-[dec]/[dec])$	
Explanation	The IP fast path switching module has received an IPC message with an invalid size.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPFAST-2-FAILOPENIPCPORT : Could not open the IPC ports. [chars]	
Explanation	ipfast could not open the ipc port to communicate to the LC/RRP/SP.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IPFLOW

%IPFLOW-2-QUEUEINIT : Error initializing Flow feature queue		
Explanation	Initialization of the Flow feature queue could not be accomplished because of a low memory condition.	

ALIBEL OLLL A	ALIEUEIAUT	E 1 1/2 11 1	
%IPFI (1W-7.	.() - -	· Frror initiali7i	ng Flow feature gueue

Recommended Action

Reduce other system activitiy to ease memory demands. If conditions warrant, upgrade

to a larger memory configuration.

%IPFLOW-3-DISABLEFLOWEXPORT: NULL

Explanation Flow export is disabled because export destination address matches with one of the

interface's IP addresses

Recommended Action IP addresses of all the interfaces must be checked to make sure none of them matches

with flow export destination IP address.

%IPFLOW-2-PROCESSINIT: Error initializing Flow background process

Explanation Initialization of the Flow background process could not be accomplished because of

a low memory condition.

Recommended Action Reduce other system activitiy to ease memory demands. If conditions warrant, upgrade

to a larger memory configuration.

%IPFLOW-2-CACHEINIT: Error initializing IP flow cache

Explanation Initialization of the Flow cache could not be accomplished because of a low memory

condition.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Issue the show tech-support command to gather data that may help identify the nature of the

error. Also perform a search of the Bug Toolkit

(https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a

case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPFLOW-2-EXPORTINIT: Error initializing Flow Export queue

Explanation Initialization of the Flow export queue could not be accomplished because of a low

memory condition.

Recommended Action

Reduce other system activitiy to ease memory demands. If conditions warrant, upgrade

to a larger memory configuration.

%IPFLOW-2-TEMPLATETBL_INIT : Error initializing Flow Export Template Table

Explanation Initialization of the Flow export template table could not be accomplished because of

a low memory condition.

%IPFLOW-2-TEMPLATETBL	INIT : Error	initializing	Flow Exp	port Tem	plate Table

Recommended

Reduce other system activity to ease memory demands. If conditions warrant, upgrade

Action to a larger memory configuration.

%IPFLOW-4-V9_TEMPLATE_EXPORT : Error creating [chars]

Explanation Version 9 export template length is zero

Recommended

Action

This is a debug message only. No action is required.

%IPFLOW-3-SBINIT: Error initializing [chars] subblock data structure. [chars]

Explanation

Initialization of the specified subblock data structure could not be accomplished.

Recommended

Action

IPMOBILE

%IPMOBILE-6-REDUPDATEFAIL: Too many redundancy update failures ([dec]) in the last minute.

Explanation

The standby HA attempts to update its binding table by contacting the active HA several times each minute. Some or all of these attempts failed and the number of

failures exceeded a threshhold number.

Recommended Action

Ensure connectivity between the active HA and the standby HA. Also make sure the clocks are in sync between the two and that the security associations are properly set between the two. If the preemption delay is set, try setting it to a shorter time period.

%IPMOBILE-6-DUPMOBNET: Unable to [chars] dynamic mobile network [IP_address] [IP_address] for MR [chars]; already [chars] MR [chars]

Explanation

A mobile router's attempt to dynamically add or delete a mobile network failed because that mobile network was already statically configured for or dynamically registered by another mobile router. A mobile network may be configured or registered for only one mobile router.

Recommended

Action

To avoid duplication errors, check the static mobile network configuration on the HA or the dynamic mobile network configuration on the mobile router(s).

%IPMOBILE-6-DUPVIRTNET : Unable to [chars] dynamic mobile network [IP_address] [IP_address] for MR [chars]; already configured as a virtual network		
Explanation	A mobile router's attempt to dynamically add or delete a mobile network failed because that mobile network was already configured as a virtual network in the home agent.	
Recommended Action	To avoid duplication errors, make sure that the virtual networks configuration on the home agent and the dynamic mobile network configuration on the mobile router do not have any overlapping network prefixes.	

%IPMOBILE-3-NOSOCKET : Unable to open socket		
Explanation	The requested operation could not be accomplished because of a low memory condition.	
Recommended Action	Reduce other system activity to ease memory demands. If conditions warrant, upgrade to a larger memory configuration.	

%IPMOBILE-6-SECURE : Security violation on [chars] from [chars] [chars] - errcode [chars] ([dec]), reason [chars] ([dec])		
Explanation	A security violation occurred during registration attempt.	
Recommended Action This is for informational purpose only.		

%IPMOBILE-2-ASSERTFAILED : IPMOBILE assertion failed: [chars]		
Explanation	The software detected an inconsistency. This is considered a serious error. The router attempts to continue, but IP Mobility processing may be impaired.	
Recommended Action	Copy the error message exactly as it appears, noting any IP Mobility problems that you are experiencing, and report it to your technical support representative.	

%IPMOBILE-3-CONFIGERROR : Standby FA configuration is not in sync with the active		
Explanation	The software detected an inconsistency in configuration between the standby and the active. Standby FA may not proceed with the sync for this visitor.	
Recommended Action	Re-configure standby FA and make sure the configuration between the standby and the active is in sync.	

%IPMOBILE-3-NOTUNNEL : Maximum number of tunnels [dec] reached		
Explanation	The number of Mobile IP tunnels allowed on the box is reached.	
Recommended Action	This occures if the HA/FA is overloaded. If you suspect this condition contact technical support representative with the output of show tech	

%IPMOBILE-5-MIP_TUNNELDELETE : Mobile IP tunnel [chars] deleting	
Explanation	The Mobile IP tunnel is going to be deleted.
Recommended Action	This occurs if the active mobile ip binding is deleted. If you suspect this condition contact technical support representative with the output of show tech

%IPMOBILE-0-NOPROCESS : [chars]	
Explanation	A Process could not be started
Recommended Action	Please contact your technical support representative with the error message you got and with the output of 'show process'.

%IPMOBILE-0-IPMOBILE_DHCP : [chars]	
Explanation	Two reasons for this error message, 1. DHCP Client failed to get started, this could be because of malloc failures. 2. IPMOBILE DHCP Process failed to start
Recommended Action	If this error message is seen it is recommended not to use this HA for binding creation with DHCP Address Allocation. Check the available memory in the box and for the first reason try to get 'debug dhcp detail' before the failure. Contact your technical support representative with the error message you got.

%IPMOBILE-3-SA_PARSE_FAILED : Error in parsing the security association for [chars]	
Explanation	The Mobile IP Home Agent encountered an error while processing the Security Association in the RADIUS Access-Accept message.
Recommended Action	Check the Radius profile config for the Mobile Node for which the processing of the Security Association failed.

IPNAT

%IPNAT-4-ADDR_ALLOC_FAILURE : Address allocation failed for [IP_address], pool [chars] might be exhausted	
Explanation	An address could not be allocated from the IP NAT pool. This condition can cause a translation failure and might result in packets being dropped. The counter for misses will be incremented for these packets.
Recommended Action	Check to see if the NAT pool has been exhausted. To reuse any existing addresses in the NAT pool for new packet flows, clear the current NAT entries using clear ip nat translation *

%IPNAT-3-SYSSTATSNULL: NAT global/system statistics structure from platform is nul	
Explanation	The structure for passing global/systems statistics from platform is nul which is invalid. This condition can cause the NAT global statistic counters in inaccurate on the RP
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-3-POOLSTATSNULL: NAT pool statistics structure from platform is nul	
Explanation	The structure for passing global/systems stats from platform is nul which is invalid. This condition can cause the statistic counters for NAT pool to be inaccurate on the RP
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-3-BADMAPPINGTYPE : NAT mapping type [dec] for mapping statistics from platform is invalid	
Explanation	The mapping type for passing mapping statistics from platform is not for static nor dynamic mapping type which is invalid. This condition can cause the statistic counters for NAT mapping to be inaccurate on the RP
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-3-MAPPINGSTATSNULL : NAT mapping statistics structure from platform is nul	
Explanation	The structure for passing mapping statistics from platform is nul which is invalid. This condition can cause the statistic counters for NAT mapping to be inaccurate on the RP
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAI-3-LIMITS	TATSNULL : NAT mexentry statistics structure from platform is nul
Explanation	The structure for passing maxentry limit statistics from platform is nul which is invalid. This condition can cause the statistic counters for NAT maxentry limit to be inaccurate on the RP
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-3-PORTNULL : Start port or end port for port block allocation request is nul	
Explanation	Start port or end port for port block allocation request is nul, This condition can cause the new translations to fail in the data path
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-3-PORTLISTNULL : Portlist for address [IP_address] proto [dec] is nul	
Explanation	The portlist for the address which requests more port blocks is nul which is invalid. This condition can cause the new translations to fail in the data path
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-3-WLANSESSNULL : NAT WLAN session structure for session [chars] from platform is nul	
Explanation	The structure for passing WLAN session from platform is nul which is invalid. This condition can cause the NAT WLAN session to fail in the data path
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-6-ID : [chars] identifier has wrapped	
Explanation	The identifier which is assigned to that which is resultant from the configuration in question has cycled through the available number space and is now allocating from its initial value again.
Recommended Action	No action is required.

%IPNAT-3-RTMAPNULL : route-map for configuration download is nul	
Explanation	The route-map structure is nul which is invalid. This condition can cause the new translations to fail in the data path
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-3-CSBNULL : Parser structure for route-map [chars] configuration is nul	
Explanation	The parser structure for route-map configuraion is nul which is invalid. This condition can cause the new translations to fail in the data path
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-3-RTMAPNAMENULL : Route-map name for [chars] configuration is nul	
Explanation	The route-map name is nul which is invalid. This condition can cause the new translations to fail in the data path
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-6-ENTRIES : Static translation count reset, inside/outside source/destination [int]/[int] [int]/[int]	
Explanation	Upon the removal of the last remaining static translation from the configuration it has been determined that there is a discrepancy with the internal accounting as regards the previous provisioning of inside source/destination versus outside source entries. The internal accounting has been reset to indicate that there are no translations of any type currently.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-3-CONFIG : Unable to [chars] the configuration of dynamic mappings	
Explanation	An internal operation relating to the configuration of the dynamic mappings has failed. This may imply that the mapping has not been installed.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-6-PORT_ALLOC : Port allocation via [chars] for [int] [chars] [chars] ports, min [int] max [int]	
Explanation	A port allocation request for the specified range of ports has been attempted from the named party on the standby RP. This is an informational message which tracks the request source.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-3-SBINIT : Error initializing [chars] subblock data structure. [chars]	
Explanation	Initialization of the specified subblock data structure could not be accomplished.
Recommended Action	

%IPNAT-3-IF_UP : Error in sending interface UP event for [chars] to the ager process	
Explanation	An internal operation relating to the interface UP event has failed which is unexpected.

%IPNAT-3-IF_UP: Error in sending interface UP event for [chars] to the ager process

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-3-UNEXPECTED_MAPPING_FLAG: Unexpected mapping flag %#04x received

Explanation

An internal operation relating to notifying the platform about a mapping has provided

an unexpected input.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-3-MAPPING_NULL: Unexpected NULL pointer received as input.

Explanation

An internal operation relating to notifying the platform about a mapping has provided

an unexpected input.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT-3-UNEXPECTED ADDRESS: NULL

Explanation

An address contained an unexpected value.

Recommended Action

IPNAT HA

**MPNAT_HA-3-MISMATCH: [chars] [chars] mismatch with id [int] Explanation The specified synchronization operation has failed to complete on the standby route processor due to an inconsistency in the internal id which would have resulted in an inconsistent configuration between active and standby. The resultant action taken by the standby route processor is an attempt to resynchronize.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT_HA-6-MAPPING_EXISTS : [chars] [chars] [mapping id [int]

Explanation The specified synchronization operation on the standby route processor has detected the presence of an existing matching mapping. This may be associated with any observed PRC failures on the standby.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT_HA-6-MAPPING_COMPARE : [chars] [chars] [chars] mapping id [int] comparing [chars] [chars] mapping id [int]

Explanation The specified synchronization operation on the standby route processor has detected an internal condition with respect to the properities of dynamic mappings. This is informational.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT_HA-3-TRANSFORM : [chars] of [chars] via [chars] failed [chars]

Explanation	An attempt to either encode or decode a versioned synchronization message has failed
	due to an internal error encountered by the ISSU component.

Recommended Action

%IPNAT_HA-3-RECEIVE : Message via [chars] is [chars]

Explanation An attempt to receive and process a versioned negotiation or synchronization message

has failed due to an internal error being detected by the information received from the

IPC or CF components.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT_HA-3-TRANSMIT : Unable to send via [chars] [chars] [chars] [chars]; [chars]

Explanation An attempt to send a versioned negotiation or synchronization message has failed due

to an internal error encountered by the IPC or CF components.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT_HA-3-PROGRESSION: Unable to inform RF of bulk sync completion; [chars]

Explanation The active route processor has sent a notification to the star

The active route processor has sent a notification to the standby to inform of the completion of the bulk synchronization of the NAT configuration. The standby has failed to respond to the active informing that it received the notification noting the reason for the failure. The resultant action taken by the standby route processor is an attempt to resynchronize.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT_HA-3-ISSU : [chars] [chars] failed; [chars]

Explanation An operation pertaining to the ISSU support for NAT failed to complete using either

the CF or IPC transport context with the reason specified

Recommended Action

%IPNAT_HA-3-NEGOTIATION : Failed to start ISSU [chars] session negotiation; [chars]	
Explanation	The ISSU negotiation with the peer failed to start for either the CF or IPC transport with the reason specified.
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT_HA-3-REGISTRATION: ISSU [chars] failed for [chars]; [chars] Explanation An ISSU registration for the set of initial capabilities and sessions failed due to the reason specified. This will have the effect of the NAT ISSU support being unavailable between peers. Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

Explanation	A message of the transport and type described failed in its attempt to be decoded on
	the standby. The resultant action taken by the standby route processor is an attempt to resynchronize.
Recommended Copy the error message exactly as it appears on the console or in the	
Action	Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If
	you still require assistance, open a case with the Technical Assistance Center via the
	Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT_HA-3-BULK_SYNC : Failed to send [chars] information to peer		
Explanation	The bulk synchronization of the NAT configuration to the standby RP has failed to complete successfully; NAT has therefore taken the action which will result in a reload of the peer in order to once more attempt to successfully synchronize the configuration state which may have failed initially to a transient condition.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IPNAT_HA-3-DYN_SYNC : Failed to process [chars] dynamic state

Explanation

The incremental synchronization of the NAT configuration to the standby RP has failed to complete successfully. This implies that the configuration state between the active and standby RP is inconsistent.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show ip nat ha** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet

(https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT HA-3-DYN DEFERQ: [chars] failed to defer[chars]

Explanation

The incremental synchronization of the NAT dynamic state to the standby RP has failed to add the information to the deferral queue for later processing during the time where the standby RP is progressing to it's hot standby redundant state. This implies that the runtime state between the active and standby RP would be inconsistent once the standby has been fully initialized.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Issue the **show ip nat ha** command to gather data that may help identify the nature of the error. Also perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support

representative and provide the representative with the gathered information.

%IPNAT HA-6-TIMEOUT: Bulk sync is flow controlled by [chars]

Explanation

The bulk synchronization of the NAT configuration to the standby RP has encountered a flow control condition which has effected a timeout awaiting the condition to clear. This will result in a reload of the standby RP to allow the bulk synchronization to restart.

Recommended Action

%IPNAT_HA-3-CLIENT : Failed to register with [chars], [chars]

Explanation

The NAT High Availability has failed to register with the specified component during initialization. This is an internal error which indicates that the NAT HA services will be unavailable.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT HA-6-READY: [chars] peer not ready, discarding [chars]

Explanation

The synchronization attempt for the message has determined that the transport has lost communication with its peer. This is a normal situation which indicates that the standby route-processor is currently out of service implying a simplex redundancy mode.

Recommended Action

%IPNAT_HA-6-RELOAD : [chars], reloading [chars]

Explanation

A synchronization attempt between the active and standby RP peers has failed with the reason indicated. The standby peer is reloaded in an attempt to resynchronize when operating in a stateful redundant mode.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT_HA-6-RELOAD_DISABLED : Standby reload has been disabled, NAT RP state is out of sync and the standby should be reloaded manually

Explanation

The active and standby RPs are out of sync and the standby RP would have been reloaded, but this reload was suppressed based on the configured environment.

Recommended Action

%IPNAT_HA-3-ATTRIBUTE: Bulk sync of [chars] via [chars], [chars] is invalid for [chars] Explanation An attempt to bulk sync an address pool or a dynamic/static translation has detected that the entity which is to be sent to the standby RP when acting in a stateful redundant.

that the entity which is to be sent to the standby RP when acting in a stateful redundant mode contains an invalid owner property and hence cannot be synchronized. The detection of this case will result in a failure of the bulk sync.

detection of this case will result in a failure of the bulk sync

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT_HA-3-PURGE: Failed to purge [chars] information

Explanation The synchronization of the NAT configuration state to the standby RP has failed to

purge an entry which has been deemed to be stale; NAT has therefore taken the action which will result in a reload of the peer in order to once more attempt to successfully synchronize the configuration state which may have failed initially to a transient

condition.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT_HA-6-INTERFACE : [chars] type/slot [hex] uint [int] num [int] channel [int]

Explanation An attempt to sync a dynamic translation or address change has detected that the

interface which was encoded on the active RP is not present on the standby RP. The

detection of this case may result in a failure of the bulk or LBL sync.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT_HA-3-INTERFACE_TYPE : [chars] type/slot [hex] unit [int] num [int] channel [int] value [int]

Explanation

An attempt to sync a dynamic translation or address change has detected that the interface which was encoded on the active RP has a different type the standby RP. The detection of this case will result in a failure of the bulk or LBL sync.

%IPNAT_HA-3-INTERFACE_TYPE: [chars] type/slot [hex] unit [int] num [int] channel [int] value [int]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPNAT_HA-6-ADDR_CHANGE : [chars] unable to encode data descriptor for interface [chars]

Explanation

An attempt to sync an address change to the standby RP has detected that the interface which was to be encoded on the active RP is no longer present or does not support encoding. The interface may have been removed from the configuration or may not support encoding.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IPSEC

%IPSEC-3-SA_SOFT_BYTE: SA ([hex],[hex])

Explanation SA Softbyte Lifetime expiry event.

Recommended

Action

LOG STD ACTION

%IPSEC-3-SA_HARD_BYTE: SA ([hex],[hex])

Explanation SA Hardbyte Lifetime expiry event.

Recommended

Action

LOG STD ACTION

%IPSEC-3-IPC_ERR_SA: rc [hex]

Explanation An error has occurred sending SA Byte Lifetime expiry event.

Recommended

Action

LOG_STD_ACTION

%IPSEC-3-ANTI_REPLAY : SA ([hex],[hex])

Explanation Anti Replay check failed for the SA.

Recommended

Action

LOG_STD_ACTION

%IPSEC-3-SEQNO_OVERFLOW: SA ([hex],[hex])

Explanation Sequence Number overflow for the SA.

Recommended

Action

LOG_STD_ACTION

%IPSEC-3-UNEXPECTED_ERROR: orh.w0 [hex], error_op [hex], SA ([hex],[hex])

Explanation Unexpected error for the SA.

Recommended

Action

LOG_STD_ACTION

%IPSEC-3-INVALID_SPI: spi [hex]

Explanation Got an invalid SPI value.

Recommended

Action

LOG_STD_ACTION

%IPSEC-3-IN_POLICY_MISS : sa [hex], cp sa [hex]

Explanation TCAM miss.

Recommended

LOG_STD_ACTION

Action

%IPSEC-3-IN_POLICY_FAIL: out sa ([hex],[hex]), out sp ([hex],[hex]), in sa ([hex],[hex]), in sp ([hex],[hex])

Explanation In-Out SP mis-match.

Recommended

Action

LOG_STD_ACTION

%IPSEC-3-IPC_PAK_ALLOC_SA_EVENT : event [hex], sa [hex]

Explanation IPC pak allocation failed.

%IPSEC-3-IPC_PAK_ALLOC_SA_EVENT : event [hex], sa [hex]

Recommended

LOG_STD_ACTION

Action

%IPSEC-3-IPC_PAK_SEND_SA_EVENT : rc [hex], event [hex], sa [hex]

Explanation

IPC send failed.

Recommended

LOG_STD_ACTION

Action

%IPSEC-3-IKE_TED_MSG_LIMIT : cnt [dec], sp [hex], cp sp [hex]

Explanation

IKE TED Message Limit exceeded.

Recommended

LOG_STD_ACTION

Action

%IPSEC-3-IKE_TED_MSG_RATE: cnt [dec], sp [hex], cp sp [hex]

Explanation

IKE TED Message Rate exceeded.

Recommended

Action

LOG STD ACTION

%IPSEC-3-IPC_PAK_ALLOC : sp [hex], cp sp [hex]

Explanation

IPC pak allocation failed.

Recommended

LOG_STD_ACTION

Action

%IPSEC-3-IPC_PAK_SEND : rc [hex], sp [hex], cp sp [hex]

Explanation

IPC send failed.

Recommended

LOG_STD_ACTION

Action

%IPSEC-3-INVALID_VAL : val [hex]

Explanation

Invalid value seen.

Recommended

LOG STD ACTION

Action

%IPSEC-3-IPC_HANDLER_ERR : rc [hex]

Explanation Error setting IPC Handler.

Recommended

Action

LOG_STD_ACTION

%IPSEC-3-DROP: result type [hex]

Explanation Classification results in Drop.

Recommended

Action

LOG_STD_ACTION

%IPSEC-3-INVALID_SA: sa [hex], cp sa [hex]

Explanation SA is invalid.

Recommended Action

ed LO

LOG_STD_ACTION

%IPSEC-3-SA_NOT_FOUND:

Explanation SA not found.

Recommended

Action

LOG_STD_ACTION

%IPSEC-3-FOR_US_CLEARTEXT_POLICY_FAIL:

Explanation Policy fail for For-Us cleartext packet.

Recommended

Action

LOG_STD_ACTION

%IPSEC-3-TRANSIT_POLICY_FAIL:

Explanation Policy fail for transit ipsec packet.

Recommended LOG_STD_ACTION

Action

%IPSEC-3-INTF_NOT_CFG:

Explanation

Got an encrypted packet on an interface on which ipsec is not configured.

Recommended Action

LOG_STD_ACTION

%IPSEC-3-FRAG_MPASS:

Explanation

Multipass Error

Recommended

LOG_STD_ACTION

Action

%IPSEC-3-INVALID_PROT: invalid ipsec prot [hex]

Explanation

Got an invalid IPSEC protocol value.

Recommended

LOG_STD_ACTION

Action

%IPSEC-3-NO_MEMORY : No memory [hex]

Explanation

No memory to send response back.

Recommended

Action

LOG_STD_ACTION

%IPSEC-3-MEM_REQ_FAILED: IPC type [hex]

Explanation

Requesting more memory failed.

Recommended

LOG_STD_ACTION

Action

%IPSEC-3-CHUNK_CREATE_FAIL:

Explanation

Chunk creation failed

Recommended

LOG_STD_ACTION

Action

%IPSEC-3-CHUNK_DESTROY_FAIL:

Explanation

Chunk destroy failed

%IPSEC-3-CHUNK_DESTROY_FAIL:

Recommended

LOG_STD_ACTION

Action

%IPSEC-3-CHUNK_DESTROY_ERROR:

Explanation Chunk destroy error, force cleanup

Recommended LOG_STD_ACTION

Action

%IPSEC-3-MEM_EXTEND_FAILED : IPC type [hex]

Explanation Extending memory failed

Recommended LOG_STD_ACTION

Action

%IPSEC-3-IPC_INVALID_MSG_LEN: [dec]:[dec] len [dec] flags [hex] source [dec]

Explanation Invalid IPC message length

Recommended LOG STD ACTION

Action

%IPSEC-3-MEM_ALLOC_REACHED_LIMIT: IPC type [hex]

Explanation Cannot allocate more memory to store state for IPSec Traffic, reached upper limit.

Recommended LOG STD ACTION

Action

%IPSEC-3-PKT_T00_BIG: IPSec Packet size [dec] larger than maximum supported size [dec] hence dropping it, MSGDEF_LIMIT_GLACIAL

Explanation Maximum size for packet with IPSEC encapsulation is 9K, This packet exceeded the

size limit hence dropping it.

Recommended

Action

LOG STD ACTION

%IPSEC-3-REPLAY_ERROR: IPSec SA receives anti-replay error, DP Handle [dec], src_addr %Ci, dest_addr %Ci, SPI [hex], MSGDEF_LIMIT_GLACIAL

Explanation

Anti-replay error is encountered for this IPSec session.

Recommended

LOG_STD_ACTION

Action

 $\%IPSEC-3-REPLAY_ERROR_IPV6: IPSec\ SA\ receives\ anti-replay\ error,\ DP\ Handle\ [dec],\ ipv6\ src_addr\ \%Cl,\ ipv6\ dest_addr\ \%Cl,\ SPI\ [hex],\ MSGDEF_LIMIT_GLACIAL$

Explanation

Anti-replay error is encountered for this IPSec session.

Recommended

LOG_STD_ACTION

Action

%IPSEC-3-RECVD_PKT_NOT_IPSEC : Rec'd packet not an IPSEC packet, dest_addr= %Ci, src_addr= %Ci, prot= [dec], MSGDEF_LIMIT_GLACIAL

Explanation

Rec'd packet matched crypto map ACL, but is not IPSEC-encapsulated.

Recommended

LOG_STD_ACTION

Action

%IPSEC-3-RECVD_PKT_NOT_IPSECV6: Rec'd packet not an IPSEC packet, dest_addr= %CI, src_addr= %CI, prot= [dec], MSGDEF_LIMIT_GLACIAL

Explanation

Rec'd packet matched crypto map ACL, but is not IPSEC-encapsulated.

Recommended

LOG_STD_ACTION

Action

 $\% IPSEC-3-HMAC_ERROR: IPSec\ SA\ receives\ HMAC\ error,\ DP\ Handle\ [dec],\ src_addr\ \% Ci,\ dest_addr\ \% Ci,\ SPI\ [hex],\ MSGDEF_LIMIT_GLACIAL$

Explanation

HMAC calculation error is encountered for this IPSec session.

Recommended

LOG_STD_ACTION

Action

 $\label{lem:continuous} $$ \ ^{PSEC-3-HMAC_ERROR_V6: IPSec\ SA\ receives\ HMAC\ error,\ DP\ Handle\ [dec],\ ipv6\ src_addr\ \%CI,\ ipv6\ dest_addr\ \%CI,\ SPI\ [hex],\ MSGDEF_LIMIT_GLACIAL $$$

Explanation

HMAC calculation error is encountered for this IPSec session.

Recommended

LOG_STD_ACTION

Action

%IPSEC-3-FRAG_ERROR: IPSec SA received fragmented ESP packet, DP Handle [dec], src_addr %Ci, dest_addr %Ci, SPI ([hex]), MSGDEF_LIMIT_GLACIAL

Explanation

Fragmented ESP packet is received for this IPSec session.

Recommended

Action

LOG STD ACTION

%IPSEC-3-FRAG_ERROR_IPV6: IPSec SA received fragmented ESP packet, DP Handle [dec], ipv6 src_addr %CI, ipv6 dest_addr %CI, SPI ([hex]), MSGDEF_LIMIT_GLACIAL

Explanation

Fragmented ESP packet is received for this IPSec session.

Recommended

Action

LOG_STD_ACTION

IPV4 FORWARDING

%IPV4_FORWARDING-2-CAUSE_THROTTLE_ERR : Allocation of ipv4 throttle [chars] memory failed

Explanation

Allocation of memory resource use by ipv4 throttle fail

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV4_FORWARDING-3-CAUSE_LINKTYPE_ERR: Unsupported link type - linktype = [dec], dropping packet

Explanation

Link type is unsupported at the current time.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

$\% IPV4_FORWARDING-4-CHECKSUM_ERR$: Checksum buffer walk failed

Explanation

Internal problem occured during calculating segmented packet checksum.

Recommended Action

70IF V4_FUNVVAND	ind-3-TABLE_ID_32_Enn . Table ID 512e configured incorrectly. [dec]
Explanation	Table ID size must be less than or equal to 16 or 32 bits.

% IDV// FORWARDING_2-TARLE ID S7 FRR: Table ID size configured incorrectly: [doc]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV4 FORWARDING-3-TRAFFIC IDX ERR: Traffic index invalid value: [dec] Buckets allocated: [dec]

Explanation Traffic index is greater than or equal to the buckets allocated

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IPV4_REASS_PROXY

%IPV4_REASS_PROXY-3-PROXY_IPC_FRAG_INFO_MEM_INIT_FAILED:

Explanation Initialization of fragment information pool failed.

Recommended LOG STD ACTION

Action

%IPV4 REASS PROXY-3-PROXY IPC FRAG INFO MEM EXTEND FAILED:

Explanation Increasing of fragment information pool failed.

Recommended LOG STD ACTION

Action

%IPV4_REASS_PROXY-3-PROXY_IPC_INIT_FAILED: [dec]

Explanation IPC handler initialization failed.

Recommended LOG STD ACTION

Action

%IPV4_REASS_PROXY-4-PROXY_IPC_INVALID_MSG: [hex]		
Explanation	Received an invalid IPC messages subtype.	
Recommended Action	LOG_STD_ACTION	

IPV6_ACL

$\% IPV6_ACL-6-ACCESSLOGNP: list [chars]/[dec] [chars] [dec] [IPV6 address] [chars]-> [IPV6 address], [dec] packet[chars]$		
Explanation	A packet matching the log criteria for the given access list was detected.	
Recommended Action	No action is required.	

%IPV6_ACL-6-ACCESSLOGDP : list [chars]/[dec] [chars] [chars] [IPV6 address] [chars]-> [IPV6 address] ([dec]/[dec]), [dec] packet[chars]		
Explanation	A packet matching the log criteria for the given access list was detected.	
Recommended Action	No action is required.	

%IPV6_ACL-6-ACCESSLOGSP : list [chars]/[dec] [chars] [chars] [IPV6 address] [chars]-> [IPV6 address], [dec] packet[chars]		
Explanation	A packet matching the log criteria for the given access list was detected.	
Recommended Action	No action is required.	

%IPV6_ACL-6-ACCESSLOGP : list [chars]/[dec] [chars] [lPV6 address]([dec]) [chars]-> [IPV6 address]([dec]), [dec] packet[chars]		
Explanation	A packet matching the log criteria for the given access list was detected.	
Recommended Action	No action is required.	

IPV6_ADDRESS through IRECAGENTSERVER

• IPV6_ADDRESS

- IPV6_ADDRMGR
- IPV6_FORWARDING
- IPV6_POLICY_API
- IPV6_REASS_PROXY
- IPV6_RIP
- IP_SNMP
- IP_TUNNEL
- IP_VFR
- IRECAGENTSERVER

IPV6_ADDRESS

%IPV6_ADDRESS-3-INTERNAL : Internal error, [chars]		
Explanation	An internal software error occurred.	
Recommended Action	Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.	

%IPV6_ADDRESS-3-NO_UNIQUE_IDENTIFIER : Cannot determine an unique IPv6 identifier for the system. IPv6 will not be started.		
Explanation	An unique IPv6 Identifier could not be determined for the system. Therefore the IPv6 process will not be started. This machine will not be able to process any IPv6 packets.	
Recommended Action	Verify that there is at least one interface in this machine that supports IEEE-style addresses.	

%IPV6_ADDRESS-3-NO_PROCESS : Cannot start an IPv6 process; router will not process IPv6 packets.		
Explanation	An IPv6 process could not be started. This machine will not be able to process any IPv6 packets.	
Recommended Action	Reduce other system activity to ease memory demands. If conditions warrant, upgrade to a larger memory configuration.	

%IPV6_ADDRESS-3-ADDRESS	_CFG : [IPV6 address]/[dec] can not be	configured on [chars], [chars]
-------------------------	--	--------------------------------

Explanation An error was encountered while configuring an IPv6 address

%IPV6 ADDRESS_3-ADDRESS_CFG: [IPV6 address]/[dec] can not be configured on [chars], [chars]

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV6_ADDRESS-3-NULLIDB : Uninitialized interface pointer - [chars]

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV6_ADDRESS-3-OPINPROGRESS: Operation in progress - [chars]

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IPV6 ADDRMGR

%IPV6_ADDRMGR-3-INTERNAL: Internal error, [chars]

Explanation An internal software error occurred.

Recommended Action Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IPV6 FORWARDING

%IPV6_FORWARDING-2-CAUSE_THROTTLE_ERR: Allocation of ipv6 throttle [chars] memory failed

Explanation Allocation of memory resource use by ipv6 throttle fail

%IPV6_FORWARDING-2-CAUSE_THROTTLE_ERR: Allocation of ipv6 throttle [chars] memory failed

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV6_FORWARDING-3-CAUSE_LINKTYPE_ERR: Unsupported link type [chars], dropping packet

Explanation

Link type is unsupported at the current time.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV6 FORWARDING-4-CHECKSUM ERR: Checksum buffer walk failed

Explanation

Internal problem occured during calculating segmented packet checksum.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV6_FORWARDING-3-TABLE_ID_SZ_ERR: Table ID size configured incorrectly: [dec]

Explanation

Table ID size must be less than or equal to 16 or 32 bits.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IPV6_POLICY_API

%IPV6_POLICY_API-4-IPV6_POLICYOVERIDE: Dynamic policy overriding static on intf:[chars]

Explanation

Static policy and dynamic policy are configured on the interface. The dynamic policy

will override the static policy.

Recommended Action Remove the static policy config if desired.

%IPV6_POLICY_API-4-IPV6_LOCALPOLICYOVERIDE: Local dynamic policy overriding static local policy

Explanation Static policy and dynamic local policy are configured. The dynamic local policy will

override the static local policy.

Recommended

Action

Remove the static local policy config if desired.

IPV6_REASS_PROXY

%IPV6_REASS_PROXY-3-PROXY_IPC_FRAG_INFO_MEM_INIT_FAILED:

Explanation

Initialization of fragment information pool failed.

Recommended

LOG_STD_ACTION

Action

%IPV6_REASS_PROXY-3-PROXY_IPC_FRAG_INFO_MEM_EXTEND_FAILED:

Explanation

Increasing of fragment information pool failed.

Recommended

Action

LOG_STD_ACTION

%IPV6_REASS_PROXY-3-PROXY_IPC_INIT_FAILED: [dec]

Explanation

IPC handler initialization failed.

Recommended

LOG_STD_ACTION

Action

%IPV6_REASS_PROXY-4-PROXY_IPC_INVALID_MSG: [hex]

Explanation

Received an invalid IPC messages subtype.

Recommended

Action

LOG_STD_ACTION

IPV6_RIP

%IPV6_RIP-3-NULLIDB: Uninitialized interface pointer - RIPv6

Explanation A

An internal software error occurred.

%IPV6 RIP-3-NULLIDB: Uninitialized interface pointer - RIPv6

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV6_RIP-3-NULLPAK: Uninitialized packet pointer - RIPv6

Explanation

An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV6 RIP-3-NULLPDB: Uninitialized PDB pointer - RIPv6

Explanation

An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV6_RIP-3-NULLIPDB: Uninitialized iPDB pointer - RIPv6

Explanation

An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV6_RIP-3-NULLPROTO: Uninitialized protocol pointer - RIPv6

Explanation

An internal software error occurred.

Recommended Action

%IPV6_RIP-3-NULLSOC : Uninitialized socket pointer - RIPv6

Explanation An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV6_RIP-3-ALLOC_PDB: Can't alloc PDB structure - RIPv6

Explanation An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV6 RIP-3-ALLOC IPDB: Can't alloc iPDB structure - RIPv6

Explanation An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV6_RIP-3-PROCESS_CREATE : Can't create process - RIPv6

Explanation An internal software error occurred.

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV6_RIP-3-ALLOC_ERR : Memory allocation problem - RIPv6

Explanation An internal software error occurred.

%IPV6 RIP-3-ALLOC_ERR: Memory allocation problem - RIPv6

Recommended Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

%IPV6_RIP-3-PROCESS_MSG_SEND : Can't send message to process - RIPv6

Explanation

An internal software error occurred.

Recommended

Action

Copy the error message exactly as it appears on the console or in the system log. Perform a search of the Bug Toolkit (https://bst.cloudapps.cisco.com/bugsearch/). If you still require assistance, open a case with the Technical Assistance Center via the Internet (https://mycase.cloudapps.cisco.com/case), or contact your Cisco technical support representative and provide the representative with the gathered information.

IP_SNMP

%IP_SNMP-3-SOCKET: can't open UDP socket

Explanation

The SNMP server was unable to open a port for receiving or transmitting SNMP requests. This usually happens when the SNMP server is started using the snmp-server community configuration command on a router or communication server with an interface that has no IP address configured. Another possible cause is low memory.

Recommended Action

Configure at least one interface with an IP address or specify the no snmp-server command to remove the SNMP server process. Call your technical support representative if problems persist or if it becomes necessary to add memory.

%IP_SNMP-4-NOTRAPIP: SNMP trap source [chars] has no ip address

Explanation

The user entered an snmp-server trap-source command. The interface requested for use as the source address has no ipv4 address associated with it. The SNMP trap is being sent anyway, but without the source address that the user intended.

Recommended Action

There are two possible solutions. Either enter a no snmp-server trap-source command to disable the request for a specific source IP address, or add an IP address to the interface referenced in the snmp-server trap-source configuration command.

%IP SNMP-4-NOTRAPIPV6 : SNMP trap source [chars] has no ipv6 address

Explanation

The user entered an snmp-server trap-source command. The interface requested for use as the source address has no ipv6 address associated with it. The SNMP trap is being sent anyway, but without the source address that the user intended.

%IP_SNMP-4-NOTRAPIPV6 : SNMP trap source [chars] has no ipv6 address

Recommended Action

There are two possible solutions. Either enter a no snmp-server trap-source command to disable the request for a specific source IP address, or add an IPV6 address to the interface referenced in the snmp-server trap-source configuration command.

%IP_SNMP-4-T00BIG : Oversize message from [IP_address], datagram size [int], udp length [int]

Explanation

An incoming SNMP packet had a length field so large that the system had to assume it was in error. This system made a correct reaction to bad external data. Since SNMP packets should originate from systems under the same administration, this may indicate that the network host used to originate the SNMP request had a problem in its networking layer. Alternatively, if the SNMP packet originated from outside the local administrative domain, it could indicate an failed attempt at security penetration and that site should be watched more closely.

Recommended Action

If the origin is local, no action is required. If the origin is determined to be malicious, either contact the administrator of the originating site or install filters to prevent access by that site, as circumstances warrant.

IP TUNNEL

%IP_TUNNEL-3-IPC_OPEN_REPLY: IPC Open Reply failed, request [int]

Explanation

For a request from upper TUNNEL software stack layers it was not possible to open the reply buffer. The consequence of this could be a stuck monitor that cannot be established etc. In rare cases this could also affect other operations such as feature activation.

Recommended Action

This is normally a software issue. LOG STD RECUR ACTION

%IP_TUNNEL-3-IPC_NORES: No space for the IPC reply, size [int]

Explanation

For a request from upper TUNNEL software stack layers it was not possible to allocate space for a reply for the specified size. The consequence of this could be a stuck monitor that cannot be established etc. In rare cases this could also affect other operations such as feature activation.

Recommended Action

This is normally a software issue. LOG_STD_RECUR_ACTION

%IP_TUNNEL-2-IPC_INIT: IPC message handler registration failure, rc [int]

Explanation

Registering an IPC message handler for the Tunnel feature failed. This may cause the feature to not function.

%IP_TUNNEL-2-IPC_INIT : IPC message handler registration failure, rc [int]	
Recommended	This is normally a software issue. The consequences are that the tunnel feature may
Action	not function. LOG_STD_ACTION

IP_VFR

%IP_VFR-4-TINY_FRAGMENTS : [chars]: from the host [IP_address] destined to [IP_address]	
Explanation	This message indicates that the router is receiving tiny fragments - meaning the initial fragment does not have complete layer 4 header
Recommended Action	This is an informational message

%IP_VFR-3-OVERLAP_FRAGMENTS : [chars]: from the host [IP_address] destined to [IP_address]	
Explanation	This message is logged whenever the router encounters overlap fragments. Overlap fragment means, offset of one fragment overlaps the offset of another fragment. For example, if first fragment's offset is 0 and length is 800, then the second fragments offset must be 800. If second fragment's offset is less than 800, that means the second fragment overlaps the first fragment.
Recommended Action	This could possibly be an attack, configure a static ACL to prevent further overlap fragments from the sender

$\% IP_VFR-4-FRAG_TABLE_OVERFLOW: [chars]: the fragment table has reached its maximum threshold [dec]$	
Explanation	This means the number of datagrams reassembled at a time reached its maximum limit, increase the value of max-reassemblies using ip virtual-reassembly max-reassemblies <number></number>
Recommended Action	

%IP_VFR-4-TOO_MANY_FRAGMENTS : [chars]: Too many fragments per datagram (more than [dec]) - sent by [IP_address], destined to [IP_address]	
Explanation	This message indicates the datagram being reassembled has received more fragments than its threshold value
Recommended Action	Check if the fragments received are from a genuine source, if so increase the value of max-fragments using the CLI ip virtual-reassembly max-fragments <number></number>

%IP_VFR-3-INVALID_FRAG_LENGTH : [chars]: fragment length invalid - received from [IP_address], destined to [IP_address]	
Explanation	This message indicates that the router has encountered a ping-of-death sort of an attack
Recommended Action	To prevent further attacks, its highly recommendated that an ACL be configured to drop any traffic from the sender

%IP_VFR-3-SYSTEM_ERROR : [chars]: IP VFR System failure - [chars]	
Explanation	This message indicates the misc errors in the VFR subsystem
Recommended Action	

IRECAGENTSERVER

%IRECAGENTSERVER-3-NOINIT : Can't initialize iREC agent server	
Explanation	Internal problems with initializing ports for the iREC agentserver
Recommended Action	Make sure the iREC agent server port is available on the localmachine.

%IRECAGENTSERVER-3-NOMEM : Can't initialize memory for iREC agent server	
Explanation	Insufficient Memory for iREC agent server
Recommended Action	Increase amount of available memory

%IRECAGENTSERVER-3-NOSOCKETS: Max Number of iREC agent Server sockets exceeded	
Explanation	There are too many iREC agent clients requesting service
Recommended Action	Reduce number of iREC agent requesting service

%IRECAGENTSERVER-3-NOPROC : Could not start iREC agent Server	
Explanation	Internal Problem in process creation
Recommended Action	None