



Firmware Release 1.6.9 - Release Notes for the Cisco 500 Series WPAN Industrial Routers

The following release notes support Firmware Release 1.6.9 on the Cisco 500 Series WPAN Industrial Routers. These release notes are updated to describe new features, limitations, troubleshooting, recommended configurations, caveats, and how to obtain support and documentation.

Contents

This publication consists of the following sections:

- [Related Documentation, page 1](#)
- [Caveats, page 2](#)
- [Obtaining Documentation and Submitting a Service Request, page 3](#)

Related Documentation

The following documentation is available:

- All of the Cisco 500 Series WPAN Industrial Routers documentation can be found here:
<http://www.cisco.com/c/en/us/support/routers/500-series-wpan-industrial-routers/tsd-products-support-series-home.html>



Americas Headquarters:
Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

© 2016 Cisco Systems, Inc. All rights reserved.

Caveats

Caveats describe unexpected behavior in Cisco IOS releases. Caveats listed as open in a prior release are carried forward to the next release as either open or closed (resolved).



Note

You must have a Cisco.com account to log in and access the Cisco Bug Search Tool. If you do not have one, you can [register for an account](#).

For more information about the Cisco Bug Search Tool, see the [Bug Search Tool Help & FAQ](#).

Open Caveats

- **CSCva89386**
txPower is always 30 regardless of cfg bin on IR509 and IR529.
- **CSCva67733**
Changing the DODAGID will not trigger store pan information.
- **CSCva04700**
The tlv 25 IPRouterRPLMetrics rank value is not correct.
- **CSCva56953**
There are no statistics for interface out packets in TLV24.
Symptoms:
Get TLV 24 and there are no statistics for interface out packets. It always display 0 on lowpan interface.
- **CSCuy0720**
TLV19 interface settings for loopback and PPP can not be set to down.
- **CSCva17573**
No TLV on CGE can display the ieee154 phy mode info.
- **CSCva19891**
IR509 hangs when executing get tlv.
- **CSCuy54264**
If a DAGW loses its parent, it can take around 2hrs for the DAGW to change its parent to another available within acceptable range.
- **CSCuz87922**
Upgrading IR529 via FND fails, but upgrading IR509 works as expected.

Closed Caveats

- Fixed a hang issue caused by big packets from ethernet.

Obtaining Documentation and Submitting a Service Request

For information on obtaining documentation, using the Cisco Bug Search Tool (BST), submitting a service request, and gathering additional information, see What's New in Cisco Product Documentation at: <http://www.cisco.com/en/US/docs/general/whatsnew/whatsnew.html>.

Subscribe to What's New in Cisco Product Documentation, which lists all new and revised Cisco technical documentation, as an RSS feed and deliver content directly to your desktop using a reader application. The RSS feeds are a free service.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2016 Cisco Systems, Inc. All rights reserved.

Printed in the USA on recycled paper containing 10% postconsumer waste.