



Caveats

This chapter describes open and resolved severity 1 and 2 caveats and select severity 3 caveats:

- The “Open Caveats” sections list open caveats that apply to the current release and may apply to previous releases. A caveat that is open for a prior release and is still unresolved applies to all future releases until it is resolved.
- The “Resolved Caveats” sections list caveats resolved in a specific release, but open in previous releases.

The bug IDs are sorted alphanumerically.



Note The Caveats section includes the bug ID and a short description of the bug. For details on the symptoms, conditions, and workaround for a specific caveat you must use the Bug Search Tool.

- [Resolved Caveats – Cisco IOS XE 17.15.3b, on page 1](#)
- [Open Caveats – Cisco IOS XE 17.15.3b, on page 2](#)
- [Resolved Caveats – Cisco IOS XE 17.15.2, on page 2](#)
- [Open Caveats – Cisco IOS XE 17.15.2, on page 2](#)
- [Resolved Caveats - Cisco IOS XE 17.15.1b, on page 3](#)
- [Open Caveats - Cisco IOS XE 17.15.1b, on page 3](#)
- [Resolved Caveats - Cisco IOS XE 17.15.1, on page 3](#)
- [Open Caveats - Cisco IOS XE 17.15.1, on page 4](#)
- [Cisco Bug Search Tool, on page 4](#)

Resolved Caveats – Cisco IOS XE 17.15.3b

| Identifier | Headline |
|----------------------------|---|
| CSCwm82342 | Post reload HSRP is stuck in Init state and shows interface down |
| CSCwm04031 | 17.9.2a/Both active and standby RSP's OAM/CFM configs automatically changed after a reload. |
| CSCwn12822 | Discrepancy with counters on SONET controller during BERT test. |
| CSCwn94246 | XCVR incompatible alarm missing without Sonet controller configurations. |

| Identifier | Headline |
|----------------------------|---|
| CSCwn41240 | Observed unframed T1 as none and not shown in running-config under T3 controller. |
| CSCwn38105 | SSH process goes down with a segmentation fault. |
| CSCwo10841 | XCVR incompatible alarm not asserted in Bay0 sonet controller cards |
| CSCwn88535 | ISSU : Missing alarms for Software distribution |
| CSCwm99575 | Trap interval support for Ethernet OAM |
| CSCwn57972 | XCVR incompatible alarms are not generated with Telcordia profile |
| CSCwn53341 | Fan failure alarm does not display correct module name or description with hard OIR |
| CSCwn42612 | With the T3 CTRL shut operation, if the mode T3 is not configured, then the line side connected device receives LOS |
| CSCwn22679 | When standby RSP management interface goes down, there is no alarm generated on active node |

Open Caveats – Cisco IOS XE 17.15.3b

There are no open caveats in this release.

Resolved Caveats – Cisco IOS XE 17.15.2

| Identifier | Headline |
|----------------------------|--|
| CSCwj72178 | (RSP3) - OSPF not coming on G8032 VLAN after a reload. |
| CSCwk78043 | Double description under CPG STS1E mode. |
| CSCwk87121 | Ports on router remain down after ISSU operation with RSP3. |
| CSCwm91197 | Silent reload of 3GMS IM due to PCI transaction failure. |
| CSCwm86214 | LDP session flap causes memory leak for EMPLS3LD which leads to RSP crash. |

Open Caveats – Cisco IOS XE 17.15.2

| Identifier | Headline |
|----------------------------|---|
| CSCwk02087 | 17.6.3-BFD stuck in INIT state for interface Te0/0/0 & Te0/4/3 |
| CSCwm04031 | 17.9.2a-Both active and standby RSP's OAM or CFM configurations automatically changed after a reload. |

Resolved Caveats - Cisco IOS XE 17.15.1b

The list of resolved caveats for the RSP3 module.

| Identifier | Headline |
|----------------------------|--|
| CSCwi33111 | Eomer T1: Sev changes back from major to minor after IM OIR. |
| CSCwj06370 | Serial cease traffic when configuring module other port |
| CSCwj05647 | 3GMS Serial interface protocol down with specific Modem |
| CSCwj12451 | Update 2^20-O151 QRSS bert help string with QRSS Keyword in NCS42xx platform |
| CSCwj44502 | DCR clocking fails to get acquired on the with sts1-E mode |
| CSCwj99522 | Need to support dtr not-used CLI in RS232 transparent mode |
| CSCwi92203 | Channelized DS3: RAI is propagating to all DS1's when DS3 RAI is asserted |
| CSCwk58917 | L-bit propogation not enabled for LOF alarm after framing change with framed SAToP |

Open Caveats - Cisco IOS XE 17.15.1b

The list of open caveats for the RSP3 module.

| Identifier | Headline |
|----------------------------|--|
| CSCwk02087 | 17.6.3-BFD stuck in INIT state for interface Te0/0/0 & Te0/4/3 |
| CSCwj60760 | Confd process not in Started State in 5 mins after netconf-yang config is done |
| CSCwk27810 | After reconfiguring second synce source the QL-failed for that source interface and ranking also 254 |

Resolved Caveats - Cisco IOS XE 17.15.1

The list of resolved caveats for the RSP2 module.

| Identifier | Headline |
|----------------------------|--|
| CSCwi76112 | Message to be displayed for M13 framing when configured with clear-channel |
| CSCwi60730 | Speed LED status is not correct when sonet/sdh mode is configured |

Open Caveats - Cisco IOS XE 17.15.1

The list of open caveats for the RSP2 module.

| Identifier | Headline |
|----------------------------|--|
| CSCwh75614 | Increased CPU after upgrading router to 17.6.3 from 16.9.4 when 1000 SLM/DMM sessions are configured |
| CSCwj38216 | BDI ARP is not learning but peer side BDI MAC is learning through VC |

Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST), the online successor to Bug Toolkit, is designed to improve effectiveness in network risk management and device troubleshooting. You can search for bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. For more details on the tool, see the help page located at <http://www.cisco.com/web/applicat/cbsshelp/help.html>