

Cisco Catalyst 1300x Release Note 4_10_0_82

First Published: 2025-10-20

Introduction

This release note is for Version 4.10.0.82. This software supports the Catalyst 1300x Stackable Managed Switch Series.



Note The full list of the supported SKUs and the minimal supported version per SKU can be found in below.

Supported Platform

The following tables list the SKUs that are supported in the Catalyst 1300x series. Each table lists one of the Catalyst 1300x Series and provides information on each SKU description, OID and minimum supported version. Boards not listed in the following table are not supported by Catalyst C1300x release.

sysOID branch: iso (1) . org (3) . dod (6) . internet (1) . private (4) . enterprises (1) . cisco (9) . ciscoProducts (1) (OID field below begins from cisco (9) . ciscoProducts (1))

Table 1: Catalyst 1300x Stackable Managed Switches

Device PID	Description	OID	Minimum Supported Version
C1300X-24P-4X	Catalyst 1300X Series Managed Switch, 24GE+4SFP28,PoE (C1300X-24P-4X)	9.1.3413	4.10.0.82
C1300X-24T-4X	Catalyst 1300X Series Managed Switch, 24GE+4SFP28 (C1300X-24T-4X)	9.1.3414	4.10.0.82
C1300X-48P-4X	Catalyst 1300X Series Managed Switch, 48GE+4SFP28, PoE (C1300X-48P-4X)	9.1.3416	4.10.0.82
C1300X-48T-4X	Catalyst 1300X Series Managed Switch, 48GE+4SFP28 (C1300X-48T-4X)	9.1.3417	4.10.0.82

What's New

This section details the new features found on firmware version 4.10.0.82



Note This release does not support the 802.1x command “dot1x control-direction”. This command will be added in future releases.

SAN (Subject Alternative Name) HTTPS Certificate Field

In the Cisco Catalyst 1300x series release 4.10.0, the user can configure the Subject Alternative Name (SAN) field when creating HTTPS certificates. SAN allows a certificate to secure multiple domain names or IP addresses, offering more flexibility and broader coverage than the traditional Common Name (CN) field, which supports only a single domain.

The SAN field is optional and can be configured when generating a self-signed certificate or a certificate request



Note In this release the feature is supported only via CLI commands. GUI support will be added in later features

OSPFv2 and OSPFv3 Support

The C1300X Series release 4.10.0 supports OSPFv2 and OSPFv3. the details of the settings and functionality that are supported can be found in the C1300x CLI Guide.



Note The GUI supports only a subset of the OSPF commands.

Stacking Enhancements

On the Catalyst 1300x Series line the uplink interfaces support a maximum speed of 25G, so the user can select to set the stacking interface speed to 25G (the default) or 10G.



Note 25G is supported only if the uplink interfaces are configured as stacking interfaces. When configured as (regular) network ports the maximum speed is 10G.

PoE 802.3BT

In Catalyst C1300x, some PoE interfaces also support 4-pair 802.3BT PoE which can provide up to 60W PoE. Please check specific PoE SKU details to determine which ports support 2-pair 802.3BT and which support 4-pair 802.3BT.

The 802.3BT auto-class feature is supported on both types of PoE ports. The autotclass supports Auto/LLDP and Manual activations.

FIPS Enabled - GUI Control

In the Catalyst 1300x Series release 4.10.0, GUI support was added, allowing users to control the feature through the GUI interface.

Caveats

Caveats Acknowledged in Release 4.10.0.82.

Bug ID	Description
CSCwr76525	Symptom The console may lose response in rare scenarios. Workaround Use SSH or telnet to access the CLI.
CSCwr76554	Symptom C1300x - UDLD exchange fails with the Cisco Nexus switch. Workaround None.
CSCwr76557	Symptom CDP Negotiated power is 0 when an AIR-CAP3702I/CAP36021 AP is connected to the port. Workaround None.
CSCwr71240	Symptom The device crashes if the "show ip ospf database router" command is executed with more than 3000 route entries. Crash notice: %SNMP-F-FTLERR: SNMP Package: SnmpCen Routine: 24 Location: 10 Error: Bad value returned by application: Range error: variable = 3353, field = rIOspfRouterLsaType, value =8". Workaround None.
CSCwr76537	Symptom The port PoE status shows 'Fault' because of a short condition when a NIC is connected to the device. Workaround None.
CSCwr71246	Symptom OSPFv2 ASBR advertisement does not turn on bit E (ASBR). Workaround None.

Bug ID	Description
CSCwr76565	Symptom The “no redistribute ospf [process-id] command cannot be executed without optional parameters. Workaround Provide an optional parameter with the required settings.
CSCwr76567	Symptom OSPFv3 displays a learned /128 route in the totally stub/nssa area. Workaround None. It's a display issue and it does not effect the functionality.
CSCwr76572	Symptom Occasionally, the output of the “show ipv6 route” command may display OIA route types as an O route type. Workaround None. It's a display issue and it does not effect the functionality.
CSCwr76574	Symptom In certain cases a ping may fail when MSTP topology changes. Workaround None. ICMP packet forwarding is delayed and this causes the ping to timeout. IP connectivity is not broken.
CSCwr69885	Symptom The SFP-10G-T-X module installed in the C1300X uplink port does not establish a link when connected to the mGig ports on certain C9200 models, such as the C9200L-24PXG-4X. Workaround If possible connect to a non Mgid port on the 9200 or use a different SFP.
CSCwr76652	Symptom In some cases, after disabling and then re-enabling CDP negotiation, the device supplies 39W of power even though the access point requested only 30W. This issue occurs only with certain access points that support class 6. Workaround Disconnect and reconnect the AP for proper delivery of power.
CSCwr76655	Symptom The device’s online help indicates that Auto Detection is a supported console speed setting. However, only static speeds are actually supported. Workaround None.

Bug ID	Description
CSCwr76658	Symptom OSPF stops sending updates and does not resume until the 'clear ipv6 ospf process' command is issued. Workaround None.
CSCwr76659	Symptom The area area-id virtual-link command accepts the message-digestparameter even if the md5 parameter appears before the message-digest-key parameter. Workaround None. The command is accepted and functions properly in both formats.
CSCwr76660	Symptom In some cases, OSPFv2 routes are not redistributed into RIP. Workaround Apply the no redistribute ospf x command and then apply the redistribute ospf x command.
CSCwr76662	Symptom Philips device with CSR8510 Bluetooth 4.0 is not recognized in some of the C1300X devices. Workaround None.
CSCwr76663	Symptom The syslog date time on the remote log server is incorrect when the timezone is configured with a negative offset. Workaround None.
CSCwr76665	Symptom In some cases the OSPFv3 DR may advertise the wrong prefix in the Intra-Area Prefix-LSA (for example 2008:1::2/64 instead of sement address 2008:1::/64. Workaround None.
CSCwr76675	Symptom The DUT always displays the "Invalid signature detected" log if it is connected to the PoE port of another switch. Workaround None.

Bug ID	Description
CSCwr76694	Symptom If the OSPFv3 virtual link hello time is changed multiple times, the virtual link will remain down. Workaround Apply the clear ipv6 ospf process command.
CSCwr76698	Symptom The OSPFv3 “nssa translator-role always” command does not function properly, and routes are still learned from a different router. Workaround None.
CSCwr76699	Symptom The Cisco SFP-10/25Gbase-LR cannot work as stacking ports. Workaround None.
CSCwr76701	Symptom SNTP web GUI should support four types of authentication-key like the CLI. Workaround Use the CLI to configure.
CSCwr76704	Symptom When the clock is updated using an SNTP broadcast packet, the "last synchronized" field always shows 00:00:00 instead of the actual synchronization time. This is only a display issue—the clock is synchronized correctly. Workaround None.
CSCwr76706	Symptom The OSPFv3 route table show the /128 route even though the parent route /64 is also present. Workaround None.
CSCwr76707	Symptom It is not possible to change the OSPFv2 area ID of an Area Network. A “Success” indication is presented even though the operation failed. Workaround Use CLI to modify the Area ID of network.

Bug ID	Description
CSCwr76708	Symptom In some cases, a “Bad Packet” message may be displayed when connecting devices after configuring OSPFv2. This is only a display issue, the OSPF neighbor process completes successfully. Workaround None.
CSCwr76709	Symptom Generating a self-signed certificate with SAN (Subject Alternative Name) information may result in security warnings or connection failures in some browsers. Workaround Use Firefox.
CSCwr76711	Symptom The maximum hardware resources for QoS and ACL cannot be fully utilized. Workaround None.
CSCwr76713	Symptom Cisco CWDM SFP VID cannot be read via the show inventory command. Workaround None.
CSCwr76715	Symptom The sFlow flow-sample does not work when a port added to a port channel. Workaround None.
CSCwr76716	Symptom CPU input rate can't automatically be refreshed. Workaround None.
CSCwr76722	Symptom The privacy methods AES256 and AES192 in SNMPv3 cannot be configured in web GUI. Workaround Use the CLI to configure.

Bug ID	Description
CSCwr76723	Symptom In the POE port limit mode, LLDP power negotiation may cause abnormal behavior. Workaround None.
CSCwr28463	Symptom The Cisco DBS-210 base station cannot be powered on via the PoE. Workaround None.

