



# Cisco Application Policy Infrastructure Controller Release Notes, Release 3.2(3)

The Cisco Application Centric Infrastructure (ACI) is an architecture that allows the application to define the networking requirements in a programmatic way. This architecture simplifies, optimizes, and accelerates the entire application deployment lifecycle. Cisco Application Policy Infrastructure Controller (APIC) is the software, or operating system, that acts as the controller.

The *Cisco Application Centric Infrastructure Fundamentals* guide provides complete details about the Cisco ACI, including a glossary of terms that are used in the Cisco ACI.

This document describes the features, bugs, and limitations for the Cisco APIC.

**Note:** Use this document with the *Cisco Nexus 9000 ACI-Mode Switches Release Notes, Release 13.2(3)*, which you can view at the following location:

<https://www.cisco.com/c/en/us/support/switches/nexus-9000-series-switches/products-release-notes-list.html>

Release notes are sometimes updated with new information about restrictions and bugs. See the following website for the most recent version of this document:

<https://www.cisco.com/c/en/us/support/cloud-systems-management/application-policy-infrastructure-controller-apic/tsd-products-support-series-home.html>

You can watch videos that demonstrate how to perform specific tasks in the Cisco APIC on the Cisco ACI YouTube channel:

<https://www.youtube.com/c/CiscoACIchannel>

For the verified scalability limits (except the CLI limits), see the *Verified Scalability Guide* for this release.

For the CLI verified scalability limits, see the *Cisco NX-OS Style Command-Line Interface Configuration Guide* for this release.

You can access these documents from the following website:

<https://www.cisco.com/c/en/us/support/cloud-systems-management/application-policy-infrastructure-controller-apic/tsd-products-support-series-home.html>

**Note:** The documentation set for this product strives to use bias-free language. For the purposes of this documentation set, bias-free is defined as language that does not imply discrimination based on age, disability, gender, racial identity, ethnic identity, sexual orientation, socioeconomic status, and intersectionality. Exceptions may be present in the documentation due to language that is hardcoded in the user interfaces of the product software, language used based on RFP documentation, or language that is used by a referenced third-party product.

**Table 1** shows the online change history for this document.

Table 1 Online History Change

Date	Description
------	-------------

Date	Description
December 9, 2022	In the Open Bugs section, added bug CSCvw33061.
August 1, 2022	In the Miscellaneous Compatibility Information section, added: <ul style="list-style-type: none"> <li>■ 4.1(2k) CIMC HUU ISO (recommended) for UCS C220/C240 M4 (APIC-L2/M2)</li> </ul>
February 23, 2022	In the Miscellaneous Compatibility Information section, added: <ul style="list-style-type: none"> <li>■ 4.1(2g) CIMC HUU ISO (recommended) for UCS C220/C240 M4 (APIC-L2/M2)</li> </ul>
February 9, 2021	In the Open Bugs section, added bug CSCvt07565.
February 3, 2021	In the Miscellaneous Compatibility Information section, for CIMC HUU ISO, added: <ul style="list-style-type: none"> <li>■ 4.1(2b) CIMC HUU ISO (recommended) for UCS C220/C240 M4 (APIC-L2/M2)</li> </ul>
December 16, 2020	In the Miscellaneous Compatibility Information section, CIMC release 4.1(1g) is now recommended for UCS C220/C240 M4 (APIC-L2/M2).
October 8, 2019	In the Miscellaneous Compatibility Information section, updated the latest supported CIMC releases to: <ul style="list-style-type: none"> <li>— 4.0(2g) CIMC HUU ISO (recommended) for UCS C220/C240 M4 (APIC-L2/M2)</li> <li>— 3.0(4l) CIMC HUU ISO (recommended) for UCS C220/C240 M3 (APIC-L1/M1)</li> </ul>
October 4, 2019	In the Miscellaneous Guidelines section, added the following bullet: <ul style="list-style-type: none"> <li>■ When you create an access port selector in a leaf interface rofile, the feXid property is configured with a default value of 101 even though a FEX is not connected and the interface is not a FEX interface. The feXid property is only used when the port selector is associated with an infraFexBndlGrp managed object.</li> </ul>
October 3, 2019	In the Miscellaneous Guidelines section, added the bullet that begins as follows: <ul style="list-style-type: none"> <li>■ Fabric connectivity ports can operate at 10G or 25G speeds (depending on the model of the APIC server) when connected to leaf switch host interfaces.</li> </ul>
September 17, 2019	3.2(3i): In the Open Bugs section, added bug CSCuu17314, CSCve84297, and CSCvg70246.
September 10, 2019	In the Known Behaviors section, added the following bullet: <ul style="list-style-type: none"> <li>■ When there are silent hosts across sites, ARP glean messages might not be forwarded to remote sites if a 1st generation ToR switch (switch models without -EX or -FX in the name) happens to be in the transit path and the VRF is deployed on that ToR switch, the switch does not forward the ARP glean packet back into the fabric to reach the remote site. This issue is specific to 1st generation transit ToR switches and does not affect 2nd generation ToR switches (switch models with -EX or -FX in the name). This issue breaks the capability of discovering silent hosts.</li> </ul>
July 17, 2019	3.2(3i): In the Open Bugs section, added bug CSCvq39922.

## Contents

Date	Description
March 25, 2019	In the Miscellaneous Compatibility Information section, added: <ul style="list-style-type: none"> <li>— 4.0(2f) CIMC HUU ISO (recommended) for UCS C220/C240 M4</li> <li>— 3.0(4j) CIMC HUU ISO (recommended) for UCS C220/C240 M3</li> </ul>
February 25, 2019	3.2(3s): Release 3.2(3s) became available. Added the resolved bugs for this release.
January 23, 2019	In Miscellaneous Guidelines section, added the following text:  If you upgraded from a release prior to the 3.2(1) release and you had any apps installed prior to the upgrade, the apps will no longer work. To use the apps again, you must uninstall and reinstall them.
December 7, 2018	3.2(3r): Release 3.2(3r) became available. Added the resolved bugs for this release.
November 21, 2018	3.2(3i): In the Open Bugs section, added bug CSCvn15374.
November 2, 2018	In the New Software Features section, added the following feature:  VMware vSphere proactive HA support for Cisco ACI Virtual Edge
October 24, 2018	3.2(3o): Release 3.2(3o) became available; there are no changes to this document for this release.
September 13, 2018	3.2(3i): In the Resolved Bugs section, added bug CSCvk73182.  3.2(3n): Release 3.2(3n) became available. Added the resolved bugs for this release.
September 5, 2018	3.2(3i): In the Miscellaneous Compatibility Information section, added mention of support for the 3.0(4d) CIMC HUU ISO.
August 18, 2018	3.2(3i): Release 3.2(3i) became available.

## Contents

This document includes the following sections:

- [New and Changed Information](#)
- [Upgrade and Downgrade Information](#)
- [Bugs](#)
- [Compatibility Information](#)
- [Usage Guidelines](#)
- [Related Documentation](#)

## New and Changed Information

This section lists the new and changed features in this release and includes the following topics:

- [New Software Features](#)
- [New Hardware](#)

## New Software Features

The following table lists the new software features in this release:

Table 2 New Software Features, Guidelines, and Restrictions

Feature	Description	Guidelines and Restrictions
VMware vSphere proactive HA support for Cisco ACI Virtual Edge	<p>You can improve Cisco ACI Virtual Edge availability by using VMware vSphere Proactive HA in vCenter 6.5. Cisco APIC and VMware vCenter work together to detect a nonworking Cisco ACI Virtual Edge, isolate its host, and move its VMs to a functioning host, preserving network connectivity.</p> <p>For more information, see the <i>Cisco ACI Virtual Edge Installation Guide</i>.</p>	vSphere Proactive HA is not available for Cisco ACI Virtual Edge when it is part of Cisco ACI Virtual Pod.

## New Hardware Features

For new hardware features, see the *Cisco Nexus 9000 ACI-Mode Switches Release Notes, Release 13.2(3)* at the following location:

<https://www.cisco.com/c/en/us/support/switches/nexus-9000-series-switches/products-release-notes-list.html>

## Changes in Behavior

For the changes in behavior, see the [Cisco ACI Releases Changes in Behavior](#) document.

## Upgrade and Downgrade Information

For upgrade and downgrade considerations for the Cisco APIC, see the Cisco APIC documentation site at the following URL:

<https://www.cisco.com/c/en/us/support/cloud-systems-management/application-policy-infrastructure-controller-apic/tsd-products-support-series-home.html>

See the "Upgrading and Downgrading the Cisco APIC and Switch Software" section of the *Cisco APIC Installation, Upgrade, and Downgrade Guide*.

## Bugs

This section contains lists of open and resolved bugs and known behaviors.

- [Open Bugs](#)
- [Resolved Bugs](#)
- [Known Behaviors](#)

## Open Bugs

This section lists the open bugs. Click the bug ID to access the Bug Search tool and see additional information about the bug. The "Exists In" column of the table specifies the 3.2(3) releases in which the bug exists. A bug might also exist in releases other than the 3.2(3) releases.

Table 3 Open Bugs in This Release

Bug ID	Description	Exists in
<a href="#">CSCvm63668</a>	A single user can send queries to overload the API gateway.	3.2(3n) and later
<a href="#">CSCyp94085</a>	The APIC Licensemgr generates a core file while parsing an XML response.	3.2(3n) and later
<a href="#">CSCvg57942</a>	In a RedHat OpenStack platform deployment running the Cisco ACI Unified Neutron ML2 Plugin and with the CompHosts running OVS in VLAN mode, when toggling the resolution immediacy on the EPG<->VMM domain association (fvRsDomAtt.reslmedcy) from Pre-Provision to On-Demand, the encaps VLANs (vlanCktEp mo's) are NOT programmed on the leaf switches.  This problem surfaces sporadically, meaning that it might take several reslmedcy toggles between PreProv and OnDemand to reproduce the issue.	3.2(3n) and later

## Bugs

Bug ID	Description	Exists in
<a href="#">CSCvr85515</a>	When trying to track an AVE endpoint IP address, running the "show endpoint ip x.x.x.x" command in the Cisco APIC CLI to see the IP address and checking the IP address on the EP endpoint in the GUI shows incorrect or multiple VPC names.	3.2(3n) and later
<a href="#">CSCvs29366</a>	For a DVS with a controller, if another controller is created in that DVS using the same host name, the following fault gets generated: "hostname or IP address conflicts same controller creating controller with same name DVS".	3.2(3n) and later
<a href="#">CSCvs66244</a>	The CLI command "show interface x/x switchport" shows VLANs configured and allowed through a port. However, when going to the GUI under Fabric > Inventory > node_name > Interfaces > Physical Interfaces > Interface x/x > VLANs, the VLANs do not show.	3.2(3n) and later
<a href="#">CSCuu17314</a>	CDP is not enabled on the management interfaces for the leaf switches and spine switches.	3.2(3i) and later
<a href="#">CSCvd43548</a>	The stats for a given leaf switch rule cannot be viewed if a rule is double-clicked.	3.2(3i) and later
<a href="#">CSCvd66359</a>	The Port ID LLDP Neighbors panel displays the port ID when the interface does not have a description. Example: Ethernet 1/5, but if the interface has description, the Port ID property shows the Interface description instead of the port ID.	3.2(3i) and later
<a href="#">CSCve84297</a>	A service cannot be reached by using the APIC out-of-band management that exists within the 172.17.0.0/16 subnet.	3.2(3i) and later
<a href="#">CSCvf70362</a>	This enhancement is to change the name of "Limit IP Learning To Subnet" under the bridge domains to be more self-explanatory.  Original :  Limit IP Learning To Subnet: [check box]  Suggestion :  Limit Local IP Learning To BD/EPG Subnet(s): [check box]	3.2(3i) and later
<a href="#">CSCvf70411</a>	A route will be advertised, but will not contain the tag value that is set from the VRF route tag policy.	3.2(3i) and later
<a href="#">CSCvg00627</a>	A tenant's flows/packets information cannot be exported.	3.2(3i) and later
<a href="#">CSCvg35344</a>	Requesting an enhancement to allow exporting a contract by right clicking the contract itself and choosing "Export Contract" from the right click context menu. The current implementation of needing to right click the Contract folder hierarchy to export a contract is not intuitive.	3.2(3i) and later

## Bugs

Bug ID	Description	Exists in
<a href="#">CSCvg70246</a>	When configuring an L3Out under a user tenant that is associated with a VRF instance that is under the common tenant, a customized BGP timer policy that is attached to the VRF instance is not applied to the L3Out (BGP peer) in the user tenant.	3.2(3i) and later
<a href="#">CSCvg81020</a>	For strict security requirements, customers require custom certificates that have RSA key lengths of 3072 and 4096.	3.2(3i) and later
<a href="#">CSCvh52046</a>	This is an enhancement to allow for text-based banners for the Cisco APIC GUI login screen.	3.2(3i) and later
<a href="#">CSCvh54578</a>	For a client (browser or ssh client) that is using IPv6, the Cisco APIC aaaSessionLR audit log shows "0.0.0.0" or some bogus value.	3.2(3i) and later
<a href="#">CSCvh59843</a>	Enabling Multicast under the VRF on one or more bridge domains is difficult due to how the drop-down menu is designed. This is an enhancement request to make the drop-down menu searchable.	3.2(3i) and later
<a href="#">CSCvi20535</a>	When a VRF table is configured to receive leaked external routes from multiple VRF tables, the Shared Route Control scope to specify the external routes to leak will be applied to all VRF tables. This results in an unintended external route leaking. This is an enhancement to ensure the Shared Route Control scope in each VRF table should be used to leak external routes only from the given VRF table.	3.2(3i) and later
<a href="#">CSCvi41092</a>	The APIC log files are extremely large, which takes a considerable amount of time to upload, especially for users with slow internet connectivity.	3.2(3i) and later
<a href="#">CSCvi80543</a>	This is an enhancement that allows failover ordering, categorizing uplinks as active or standby, and categorizing unused uplinks for each EPG in VMware domains from the APIC.	3.2(3i) and later
<a href="#">CSCvi82903</a>	When authenticating with the Cisco APIC using ISE (TACACS), all logins over 31 characters fail.	3.2(3i) and later
<a href="#">CSCvi95657</a>	On modifying a service parameter, the Cisco APIC sends 2 posts to the backend. The first post deletes all of the folders and parameters. The second post adds all of the remaining modified folders and parameters to the backend. These 2 posts will disrupt the running traffic.	3.2(3i) and later
<a href="#">CSCvj04166</a>	The remote leaf TEP pool cannot be deleted after decommissioning the remote leaf and deleting the remote leaf vPC configuration.	3.2(3i) and later
<a href="#">CSCvj09453</a>	The actrIRule is has the wrong destination.	3.2(3i) and later

## Bugs

Bug ID	Description	Exists in
<a href="#">CSCvj56726</a>	The connectivity filter configuration of an access policy group is deprecated and should be removed from GUI.	3.2(3i) and later
<a href="#">CSCvk04072</a>	There is no record of who acknowledged a fault in the Cisco APIC, nor when the acknowledgement occurred.	3.2(3i) and later
<a href="#">CSCvk12786</a>	Apps fail to install/uninstall/run when the cluster is not healthy and nodes are powered down/unreachable without being decommissioned.	3.2(3i) and later
<a href="#">CSCvk18014</a>	The action named 'Launch SSH' is disabled when a user with read-only access logs into the Cisco APIC.	3.2(3i) and later
<a href="#">CSCvk38296</a>	When deploying a single node PBR with a one-arm load balancer and without SNAT, the PBR datapath does not work as expected.	3.2(3i) and later
<a href="#">CSCvm56946</a>	Support for local user (admin) maximum tries and login delay configuration.	3.2(3i) and later
<a href="#">CSCvm89559</a>	The svc_ifc_policye process consumes 100% of the CPU cycles. The following messages are observed in svc_ifc_policymgr.bin.log:  8816  18-10-12 11:04:19.101  route_control  ERROR  co=doer:255:127:0xff0000000c42ad2:11  Route entry order exceeded max for st10960-2424833-any-2293761-33141-shared-svc-int Order:18846Max:17801    ../dme/svc/policyelem/src/gen/ifc/beh/imp/./rtctrl/RouteMapUtils.cc  239:q	3.2(3i) and later
<a href="#">CSCvn00576</a>	An SHA2 CSR for the ACI HTTPS certificate cannot be configured in the APIC GUI.	3.2(3i) and later
<a href="#">CSCvn15374</a>	When upgrading Cisco APICs, constant heartbeat loss is seen, which causes the Cisco APICs to lose connectivity between one another. In the Cisco APIC appliance_director logs, the following message is seen several hundred times during the upgrade:  appliance_director  DBG4  ...  Lost heartbeat from appliance id= ...  appliance_director  DBG4  ...  Appliance has become unavailable id= ...  On the switches, each process (such as policy-element) see rapidly changing leader elections and minority states:  adrs_rv  DBG4    Updated leader election on replica=(6,26,1)	3.2(3i) and later

## Bugs

Bug ID	Description	Exists in
<a href="#">CSCvp62048</a>	New port groups in VMware vCenter may be delayed when pushed from the Cisco APIC.	3.2(3i) and later
<a href="#">CSCvp64280</a>	<p>A vulnerability in the fabric infrastructure VLAN connection establishment of the Cisco Nexus 9000 Series Application Centric Infrastructure (ACI) Mode Switch Software could allow an unauthenticated, adjacent attacker to bypass security validations and connect an unauthorized server to the infrastructure VLAN.</p> <p>The vulnerability is due to insufficient security requirements during the Link Layer Discovery Protocol (LLDP) setup phase of the infrastructure VLAN. An attacker could exploit this vulnerability by sending a malicious LLDP packet on the adjacent subnet to the Cisco Nexus 9000 Series Switch in ACI mode. A successful exploit could allow the attacker to connect an unauthorized server to the infrastructure VLAN, which is highly privileged. With a connection to the infrastructure VLAN, the attacker can make unauthorized connections to Cisco Application Policy Infrastructure Controller (APIC) services or join other host endpoints.</p> <p>Cisco has released software updates that address this vulnerability. There are workarounds that address this vulnerability.</p> <p>This advisory is available at the following link:  <a href="https://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20190703-n9kaci-bypass">https://tools.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-20190703-n9kaci-bypass</a></p>	3.2(3i) and later
<a href="#">CSCvp72283</a>	<p>An APIC running the 3.0(1k) release sometimes enters the "Data Layer Partially Diverged" state. The aci diag rvc read command shows the following output for the service 10 (observer):</p> <p>Non optimal leader for shards  :10:1,10:3,10:4,10:6,10:7,10:9,10:10,10:12,10:13,10:15,10:16,10:18,10:19,10:21,10:22,10:24,10:25,  10:27,10:28,10:30,10:31</p>	3.2(3i) and later
<a href="#">CSCvp79454</a>	Syslog is not sent upon any changes in the fabric. Events are properly generated, but no Syslog is sent out of the oobmgmt ports of any of the APICs.	3.2(3i) and later
<a href="#">CSCvp99430</a>	The troubleshooting wizard is unresponsive on the APIC.	3.2(3i) and later
<a href="#">CSCvq31358</a>	"show external-l3 interfaces node <id> detail" will display "missing" for both "Oper Interface" and "Oper IP", even though the L3Out is functioning as expected.	3.2(3i) and later
<a href="#">CSCvq39922</a>	<p>Specific operating system and browser version combinations cannot be used to log in to the APIC GUI.</p> <p>Some browsers that are known to have this issue include (but might not be limited to) Google Chrome version 75.0.3770.90 and Apple Safari version 12.0.3 (13606.4.5.3.1).</p>	3.2(3i) and later

## Bugs

Bug ID	Description	Exists in
<a href="#">CSCvq43101</a>	When opening an external subnet, a user cannot see Aggregate Export/Import check boxes set in GUI even though they were already configured.	3.2(3i) and later
<a href="#">CSCvq86573</a>	Under a corner case, the Cisco APIC cluster DB may become partially diverged after upgrading to a release that introduces new services. A new release that introduces a new DME service (such as the domainmgr in the 2.3 release) could fail to receive the full size shard vector update in first two-minute window, which causes the new service flag file to be removed before all local leader shards are able to boot into the green field mode. This results in the Cisco APIC cluster DB becoming partially diverged.	3.2(3i) and later
<a href="#">CSCvr30815</a>	vmmPLInf objects are created with epqKey's and DN's that have truncated EPG names ( truncated at ".").	3.2(3i) and later
<a href="#">CSCvr65035</a>	The last APIC in the cluster gets rebooted when APIC-1 is decommissioned due to some issue seen on APIC-1 while upgrading. In addition, after decommissioning APIC-1, the other APICs still wait for APIC-1 to get upgraded.	3.2(3i) and later
<a href="#">CSCvr94614</a>	There is a minor memory leak in svc_ifc_policydist when performing various tenant configuration removals and additions.	3.2(3i) and later
<a href="#">CSCvs47757</a>	The plnghandler process crashes on the Cisco APIC, which causes the cluster to enter a data layer partially diverged state.	3.2(3i) and later
<a href="#">CSCvs78996</a>	The policy manager (PM) may crash when use testapi to delete MO from policymgr db.	3.2(3i) and later
<a href="#">CSCvt07565</a>	The eventmgr database size may grow to be very large (up to 7GB). With that size, the Cisco APIC upgrade will take 1 hour for the Cisco APIC node that contains the eventmgr database.  In rare cases, this could lead to a failed upgrade process, as it times out while working on the large database file of the specified controller.	3.2(3i) and later
<a href="#">CSCvu01452</a>	The MD5 checksum for the downloaded Cisco APIC images is not verified before adding it to the image repository.	3.2(3i) and later
<a href="#">CSCvu21530</a>	Protocol information is not shown in the GUI when a VRF table from the common tenant is being used in any user tenant.	3.2(3i) and later

## Bugs

Bug ID	Description	Exists in
<a href="#">CSCvu39569</a>	<p>The following error is encountered when accessing the Infrastructure page in the ACI vCenter plugin after inputting vCenter credentials.</p> <p>" The Automation SDK is not authenticated"</p> <p>VMware vCenter plug-in is installed using powerCLI. The following log entry is also seen in vsphere_client_virgo.log on the VMware vCenter:</p> <p>/var/log/vmware/vsphere-client/log/vsphere_client_virgo.log</p> <p>[ERROR] http-bio-9090-exec-3314 com.cisco.aciPluginServices.core.Operation sun.security.validator.ValidatorException: PKIX path validation failed: java.security.cert.CertPathValidatorException: signature check failed</p>	3.2(3i) and later
<a href="#">CSCvu62465</a>	<p>For an EPG containing a static leaf node configuration, the Cisco APIC GUI returns the following error when clicking the health of Fabric Location:</p> <p>Invalid DN topology/pod-X/node-Y/local/svc-policyelem-id-0/ObservedEthlf, wrong rn prefix ObservedEthlf at position 63</p>	3.2(3i) and later
<a href="#">CSCwv62861</a>	A leaf switch reloads due to an out-of-memory condition after changing the contract scope to global.	3.2(3i) and later
<a href="#">CSCwv33061</a>	Traffic loss is observed from multiple endpoints deployed on two different vPC leaf switches.	3.2(3i) and later

## Resolved Bugs

This section lists the resolved bugs. Click the bug ID to access the Bug Search tool and see additional information about the bug. The "Fixed In" column of the table specifies whether the bug was resolved in the base release or a patch release.

Table 4 Resolved Bugs in This Release

Bug ID	Description	Fixed in
<a href="#">CSCvn09842</a>	<p>When upgrading the Cisco APICs, constant heartbeat loss is seen, causing the Cisco APICs to lose connectivity between one another. On the Cisco APIC appliance_director logs, the following messages are seen several hundred times during the upgrade:</p> <p>appliance_director  DBG4  ...  Lost heartbeat from appliance id= ...</p> <p>appliance_director  DBG4  ...  Appliance has become unavailable id= ...</p> <p>On the switches, each process (such as policy-element) sees rapidly-changing leader elections and minority states:</p> <p>adrs_rv  DBG4  ...  Updated leader election on replica=(6,26,1)</p>	3.2(3s)

## Bugs

Bug ID	Description	Fixed in
<a href="#">CSCvm35382</a>	A user cannot log in and the following message is received:  REST Endpoint user authorization datastore is not initialized - Check Fabric Membership Status of this fabric node	3.2(3r)
<a href="#">CSCvn09842</a>	When upgrading the Cisco APICs, constant heartbeat loss is seen, causing the Cisco APICs to lose connectivity between one another. On the Cisco APIC appliance_director logs, the following messages are seen several hundred times during the upgrade:  appliance_director  DBG4  ...  Lost heartbeat from appliance id= ...  appliance_director  DBG4  ...  Appliance has become unavailable id= ...  On the switches, each process (such as policy-element) sees rapidly-changing leader elections and minority states:  adrs_rv  DBG4  ...  Updated leader election on replica=(6,26,1)	3.2(3r)
<a href="#">CSCvn15374</a>	When upgrading the Cisco APICs, constant heartbeat loss is seen, causing the Cisco APICs to lose connectivity between one another. On the Cisco APIC appliance_director logs, the following messages are seen several hundred times during the upgrade:  appliance_director  DBG4  ...  Lost heartbeat from appliance id= ...  appliance_director  DBG4  ...  Appliance has become unavailable id= ...  On the switches, each process (such as policy-element) sees rapidly-changing leader elections and minority states:  adrs_rv  DBG4  ...  Updated leader election on replica=(6,26,1)	3.2(3r)
<a href="#">CSCvn15376</a>	When upgrading the Cisco APICs, constant heartbeat loss is seen, causing the Cisco APICs to lose connectivity between one another. On the Cisco APIC appliance_director logs, the following messages are seen several hundred times during the upgrade:  appliance_director  DBG4  ...  Lost heartbeat from appliance id= ...  appliance_director  DBG4  ...  Appliance has become unavailable id= ...  On the switches, each process (such as policy-element) sees rapidly-changing leader elections and minority states:  adrs_rv  DBG4  ...  Updated leader election on replica=(6,26,1)	3.2(3r)
<a href="#">CSCvn17432</a>	A Cisco ACI Virtual Edge VM is not being powered on after the host exits maintenance mode.	3.2(3r)
<a href="#">CSCvn30618</a>	On all 3 Cisco APICs in the cluster, the data layer is partially diverged and policydist dumps cores after the Cisco APICs are upgraded.	3.2(3r)
<a href="#">CSCvm09583</a>	CPU utilization on the leaf switch that is attached to the OpenStack compute/controller has high CPU utilization when the number of endpoints increases.	3.2(3n)
<a href="#">CSCvj58499</a>	Bootstrap logs are presently being overwritten when a Cisco APIC reloads, and might lead to loss of important debug information.	3.2(3i)

## Bugs

Bug ID	Description	Fixed in
<a href="#">CSCvj64016</a>	When trying to register a new spine switch, in the fabric membership, there is a serial number printed in hex. Example: 0x4647453230303530124354.	3.2(3i)
<a href="#">CSCvk01823</a>	Decoy service (uwsqi processes) is holding memory after each time a CLI command is run. Memory utilization keeps increasing for each process until it reaches the max threshold of 8G.	3.2(3i)
<a href="#">CSCvk20510</a>	When using the QoS for L3outs with contracts feature, under the contract, if "Qos Priority" is left as the default (Unspecified), the DSCP marking does not occur on the egress packet.	3.2(3i)
<a href="#">CSCvk50417</a>	On a vMotion, there is a 9-second outage while the VM is migrated.	3.2(3i)
<a href="#">CSCvk53536</a>	This bug will be hit if you have a management IP pool (vnsUcastAddrBlk) configured with the wrong range, such as 23.0.0.1 to 230.0.0.1 and the gateway (vnsAddrInst) belonging to the 23.0.0.0 subnet.  The tenant/fabric is locked for any configuration changes. Changes made will not appear in GUI. Even if you delete a tenant, the GUI would still show the tenant.  The Cisco APICs are fully fit and converged, configuration changes to a tenant are accepted, but not deployed. However, changes made to other tenants or policies can still be applied and deployed.	3.2(3i)
<a href="#">CSCvk57005</a>	The spine switch reloads due to a opflex_proxy hap reset.	3.2(3i)
<a href="#">CSCvk73182</a>	An endpoint is unreachable from the leaf node because the static pervasive route (toward the remote bridge domain subnet) is missing.	3.2(3i)

## Known Behaviors

This section lists bugs that describe known behaviors. Click the Bug ID to access the Bug Search Tool and see additional information about the bug. The "Exists In" column of the table specifies the 3.2(3) releases in which the known behavior exists. A bug might also exist in releases other than the 3.2(3) releases.

Table 5 Known Behaviors in This Release

Bug ID	Description	Exists in
<a href="#">CSCuo52668</a>	The Cisco APIC does not validate duplicate IP addresses that are assigned to two device clusters. The communication to devices or the configuration of service devices might be affected.	3.2(3i) and later
<a href="#">CSCuo79243</a>	In some of the 5-minute statistics data, the count of ten-second samples is 29 instead of 30.	3.2(3i) and later
<a href="#">CSCuo79250</a>	The node ID policy can be replicated from an old appliance that is decommissioned when it joins a cluster.	3.2(3i) and later

## Bugs

Bug ID	Description	Exists in
<a href="#">CSCup47703</a>	The DSCP value specified on an external endpoint group does not take effect on the filter rules on the leaf switch.	3.2(3i) and later
<a href="#">CSCup79002</a>	The hostname resolution of the syslog server fails on leaf and spine switches over in-band connectivity.	3.2(3i) and later
<a href="#">CSCuq21360</a>	Following a FEX or switch reload, configured interface tags are no longer configured correctly.	3.2(3i) and later
<a href="#">CSCur39124</a>	Switches can be downgraded to a 1.0(1) version if the imported configuration consists of a firmware policy with a desired version set to 1.0(1).	3.2(3i) and later
<a href="#">CSCur71082</a>	If the Cisco APIC is rebooted using the CIMC power reboot, the system enters into fsck due to a corrupted disk.	3.2(3i) and later
<a href="#">CSCus15627</a>	The Cisco APIC Service (ApicVMMSservice) shows as stopped in the Microsoft Service Manager (services.msc in control panel > admin tools > services). This happens when a domain account does not have the correct privilege in the domain to restart the service automatically.	3.2(3i) and later
<a href="#">CSCut51929</a>	The traffic destined to a shared service provider endpoint group picks an incorrect class ID (PcTag) and gets dropped.	3.2(3i) and later
<a href="#">CSCuu09236</a>	Traffic from an external Layer 3 network is allowed when configured as part of a vzAny (a collection of endpoint groups within a context) consumer.	3.2(3i) and later
<a href="#">CSCuu61998</a>	Newly added microsegment EPG configurations must be removed before downgrading to a software release that does not support it.	3.2(3i) and later
<a href="#">CSCuu64219</a>	Downgrading the fabric starting with the leaf switch will cause faults such as policy-deployment-failed with fault code F1371.	3.2(3i) and later
<a href="#">CSCuw81638</a>	The OpenStack metadata feature cannot be used with Cisco ACI integration with the Juno release <b>(or earlier) of OpenStack due to limitations with both OpenStack and Cisco's ML2 driver.</b>	3.2(3i) and later
<a href="#">CSCva32534</a>	Creating or deleting a fabricSetupP policy results in an inconsistent state.	3.2(3i) and later
<a href="#">CSCva60439</a>	After a pod is created and nodes are added in the pod, deleting the pod results in stale entries from the pod that are active in the fabric. This occurs because the Cisco APIC uses open source DHCP, which creates some resources that the Cisco APIC cannot delete when a pod is deleted.	3.2(3i) and later

## Bugs

Bug ID	Description	Exists in
<a href="#">CSCva86794</a>	When a Cisco APIC cluster is upgrading, the Cisco APIC cluster might enter the minority status if there are any connectivity issues. In this case, user logins can fail until the majority of the Cisco APICs finish the upgrade and the cluster comes out of minority.	3.2(3i) and later
<a href="#">CSCva97082</a>	When downgrading to a 2.0(1) release, the spines and its interfaces must be moved from infra L3out2 to infra L3out1. After infra L3out1 comes up, delete L3out2 and its related configuration, and then downgrade to a 2.0(1) release.	3.2(3i) and later
<a href="#">CSCvb39702</a>	No fault gets raised upon using the same encapsulation VLAN in a copy device in tenant common, even though a fault should get raised.	3.2(3i) and later
<a href="#">CSCvg41711</a>	In the leaf mode, the command "template route group <group-name> tenant <tenant-name>" fails, declaring that the tenant passed is invalid.	3.2(3i) and later
<a href="#">CSCvg79127</a>	When First hop security is enabled on a bridge domain, traffic is disrupted.	3.2(3i) and later
<a href="#">CSCvg81856</a>	Cisco ACI Multi-Site Orchestrator BGP peers are down and a fault is raised for a conflicting rtrId on the fvRtdEpP managed object during L3extOut configuration.	3.2(3i) and later
<a href="#">CSCvh76076</a>	The PSU SPROM details might not be shown in the CLI upon removal and insertion from the switch.	3.2(3i) and later
<a href="#">CSCvh93612</a>	If two intra-EPG deny rules are programmed—one with the class-eq-deny priority and one with the class-eq-filter priority—changing the action of the second rule to "deny" causes the second rule to be redundant and have no effect. The traffic still gets denied, as expected.	3.2(3i) and later
<a href="#">CSCvj90385</a>	With a uniform distribution of EPs and traffic flows, a fabric module in slot 25 sometimes reports far less than 50% of the traffic compared to the traffic on fabric modules in non-FM25 slots.	3.2(3i) and later

- In a multipod configuration, before you make any changes to a spine switch, ensure that there is at least one operationally "up" external link that is participating in the multipod topology. Failure to do so could bring down the multipod connectivity. For more information about multipod, see the *Cisco Application Centric Infrastructure Fundamentals* document and the *Cisco APIC Getting Started Guide*.
- With a non-english SCVMM 2012 R2 or SCVMM 2016 setup and where the virtual machine names are specified in non-english characters, if the host is removed and re-added to the host group, the GUID for all the virtual machines under that host changes. Therefore, if a user has created a micro segmentation endpoint group using "VM name" attribute specifying the GUID of respective virtual machine, then that micro segmentation endpoint group will not work if the host (hosting the virtual machines) is removed and re-added to the host group, as the GUID for all the virtual machines would have changed. This does not happen if the virtual name has name specified in all english characters.
- A query of a configurable policy that does not have a subscription goes to the policy distributor. However, a query of a configurable policy that has a subscription goes to the policy manager. As a result, if the policy propagation from the policy distributor to the policy manager takes a prolonged amount of time, then in such

cases the query with the subscription might not return the policy simply because it has not reached policy manager yet.

- When there are silent hosts across sites, ARP glean messages might not be forwarded to remote sites if a 1st generation ToR switch (switch models without -EX or -FX in the name) happens to be in the transit path and the VRF is deployed on that ToR switch, the switch does not forward the ARP glean packet back into the fabric to reach the remote site. This issue is specific to 1st generation transit ToR switches and does not affect 2nd generation ToR switches (switch models with -EX or -FX in the name). This issue breaks the capability of discovering silent hosts.

## Compatibility Information

The following sections list compatibility information for the Cisco APIC software.

### Virtualization Compatibility Information

This section lists virtualization compatibility information for the Cisco APIC software.

- For a table that shows the supported virtualization products, see the ACI Virtualization Compatibility Matrix at the following URL:

<https://www.cisco.com/c/dam/en/us/td/docs/Website/datacenter/aci/virtualization/matrix/virtmatrix.html>

- This release supports VMM Integration and VMware Distributed Virtual Switch (DVS) 6.5 and 6.7. For more information about guidelines for upgrading VMware DVS from 5.x to 6.x and VMM integration, see the *Cisco ACI Virtualization Guide, Release 3.2(3)* at the following URL:

<https://www.cisco.com/c/en/us/support/cloud-systems-management/application-policy-infrastructure-controller-apic/tsd-products-support-series-home.html>

- For information about Cisco APIC compatibility with Cisco UCS Director, see the appropriate *Cisco UCS Director Compatibility Matrix* document at the following URL:

<https://www.cisco.com/c/en/us/support/servers-unified-computing/ucs-director/products-device-support-tables-list.html>

- If you use Microsoft vSwitch and want to downgrade to Cisco APIC Release 2.3(1) from a later release, you first must delete any microsegment EPGs configured with the Match All filter.

### Hardware Compatibility Information

This release supports the following Cisco APIC servers:

Product ID	Description
APIC-L1	Cisco APIC with large CPU, hard drive, and memory configurations (more than 1000 edge ports)
APIC-L2	Cisco APIC with large CPU, hard drive, and memory configurations (more than 1000 edge ports)
APIC-M1	Cisco APIC with medium-size CPU, hard drive, and memory configurations (up to 1000 edge ports)

## Compatibility Information

Product ID	Description
APIC-M2	Cisco APIC with medium-size CPU, hard drive, and memory configurations (up to 1000 edge ports)

The following list includes general hardware compatibility information:

- For the supported hardware, see the *Cisco NX-OS Release Notes for Cisco Nexus 9000 Series ACI-Mode Switches, Release 13.2(3)* at the following location:  
<https://www.cisco.com/c/en/us/support/switches/nexus-9000-series-switches/products-release-notes-list.html>
- To connect the N2348UPO to Cisco ACI leaf switches, the following options are available:
  - Directly connect the 40G FEX ports on the N2348UPO to the 40G switch ports on the Cisco ACI leaf switches
  - Break out the 40G FEX ports on the N2348UPO to 4x10G ports and connect to the 10G ports on all other Cisco ACI leaf switches.

Note: A fabric uplink port cannot be used as a FEX fabric port.
- Connecting the Cisco APIC (the controller cluster) to the Cisco ACI fabric requires a 10G interface on the Cisco ACI leaf switch. You cannot connect the Cisco APIC directly to the Cisco N9332PQ ACI leaf switch, unless you use a 40G to 10G converter (part number CVR-QSFP-SFP10G), in which case the port on the Cisco N9332PQ switch auto-negotiate to 10G without requiring any manual configuration.
- The Cisco N9K-X9736C-FX (ports 29 to 36) and Cisco N9K-C9364C-FX (ports 49-64) switches do not support 1G SFPs with QSA.
- Cisco N9K-C9508-FM-E2 fabric modules must be physically removed before downgrading to releases earlier than Cisco APIC 3.0(1).
- The Cisco N9K-C9508-FM-E2 and N9K-X9736C-FX locator LED enable/disable feature is supported in the GUI and not supported in the Cisco ACI NX-OS Switch CLI.
- Contracts using matchDscp filters are only supported on switches with "EX" on the end of the switch name. For example, N9K-93108TC-EX.
- N9K-C9508-FM-E2 and N9K-C9508-FM-E fabric modules in the mixed mode configuration are not supported on the same spine switch.
- The N9K-C9348GC-FXP switch does not read SPROM information if the PSU is in a shut state. You might see an empty string in the Cisco APIC output.
- When the fabric node switch (spine or leaf) is out-of-fabric, the environmental sensor values, such as Current Temperature, Power Draw, and Power Consumption, might be reported as "N/A." A status might be reported as "Normal" even when the Current Temperature is "N/A."

## Adaptive Security Appliance (ASA) Compatibility Information

This section lists ASA compatibility information for the Cisco APIC software.

- This release supports Adaptive Security Appliance (ASA) device package version 1.2.5.5 or later.

- If you are running a Cisco Adaptive Security Virtual Appliance (ASA) version that is prior to version 9.3(2), you must configure SSL encryption as follows:

```
(config)# ssl encryption aes128-sha1
```

## Miscellaneous Compatibility Information

This section lists miscellaneous compatibility information for the Cisco APIC software.

- This release supports the following software:

- Cisco NX-OS Release 13.2(3)
- Cisco AVS, Release 5.2(1)SV3(3.11)

For more information about the supported AVS releases, see the AVS software compatibility information in the *Cisco Application Virtual Switch Release Notes* at the following URL:

<https://www.cisco.com/c/en/us/support/switches/application-virtual-switch/products-release-notes-list.html>

- Cisco UCS Manager software release 2.2(1c) or later is required for the Cisco UCS Fabric Interconnect and other components, including the BIOS, CIMC, and the adapter.
- This release supports the following firmware:
  - 4.1(2k) CIMC HUU ISO (recommended) for UCS C220/C240 M4 (APIC-L2/M2)
  - 4.1(2g) CIMC HUU ISO for UCS C220/C240 M4 (APIC-L2/M2)
  - 4.1(2b) CIMC HUU ISO for UCS C220/C240 M4 (APIC-L2/M2)
  - 4.1(1g) CIMC HUU ISO for UCS C220/C240 M4 (APIC-L2/M2)
  - 3.0(4l) CIMC HUU ISO (recommended) for UCS C220/C240 M3 (APIC-L1/M1)
  - 3.0(4d) CIMC HUU ISO
  - 3.0(3f) CIMC HUU ISO for UCS C220/C240 M4 (APIC-L2/M2)
  - 3.0(3e) CIMC HUU ISO for UCS C220/C240 M3 (APIC-L1/M1)
  - 2.0(13i) CIMC HUU ISO
  - 2.0(9c) CIMC HUU ISO
  - 2.0(3i) CIMC HUU ISO
- This release supports the partner packages specified in the *L4-L7 Compatibility List Solution Overview* document at the following URL:  
<https://www.cisco.com/c/en/us/solutions/data-center-virtualization/application-centric-infrastructure/solution-overview-listing.html>
- A known issue exists with the Safari browser and unsigned certificates, which applies when connecting to the Cisco APIC GUI. For more information, see the *Cisco APIC Getting Started Guide*.

## Usage Guidelines

- For compatibility with OpenStack and Kubernetes distributions, see the *Cisco Application Policy Infrastructure Controller OpenStack and Container Plugins, Release 3.2(3), Release Notes*.

## Usage Guidelines

The following sections list usage guidelines for the Cisco APIC software.

### Virtualization Compatibility Guidelines

This section lists virtualization-related usage guidelines for the Cisco APIC software.

- Do not separate virtual port channel (vPC) member nodes into different configuration zones. If the nodes are in different configuration zones, then the vPCs' **modes become mismatched** if the interface policies are modified and deployed to only one of the vPC member nodes.
- If you are upgrading VMware vCenter 6.0 to vCenter 6.7, you should first delete the following folder on the VMware vCenter: C:\ProgramData\cisco\_aci\_plugin.

If you do not delete the folder and you try to register a fabric again after the upgrade, you will see the following error message:

```
Error while saving setting in C:\ProgramData\cisco_aci_plugin\
```

The *user* is the user that is currently logged in to the vSphere Web Client, and *domain* is the domain to which the user belongs. Although you can still register a fabric, you do not have permissions to override settings that were created in the old VMware vCenter. Enter any changes in the Cisco APIC configuration again after restarting VMware vCenter.

- If the communication between the Cisco APIC and VMware vCenter is impaired, some functionality is adversely affected. The Cisco APIC relies on the pulling of inventory information, updating VDS configuration, and receiving event notifications from the VMware vCenter for performing certain operations.
- After you migrate VMs using a cross-data center VMware vMotion in the same VMware vCenter, you might find a stale VM entry under the source DVS. This stale entry can cause problems, such as host removal failure. The workaround for this problem is to enable "Start monitoring port state" on the vNetwork DVS. See the KB topic "Refreshing port state information for a vNetwork Distributed Virtual Switch" on the VMware Web site for instructions.
- When creating a vPC domain between two leaf switches, both switches must be in the same switch generation. Switches not in the same generation are not compatible vPC peers. The generations are as follows:
  - Generation 1—Cisco Nexus 9200 and 9300 platform switches without "EX" on the end of the switch name; for example, Cisco Nexus 93120TX.
  - Generation 2—Cisco Nexus 9300-EX and FX platform switches; for example, Cisco Nexus 93108TC-EX.
- The following Red Hat Virtualization (RHV) guidelines apply:
  - We recommend that you use release 4.1.6 or later.
  - Only one controller (compCtrlr) can be associated with a Red Hat Virtualization Manager (RHVM) data center.
  - Deployment immediacy is supported only as pre-provision.

## Usage Guidelines

- IntraEPG isolation, micro EPGs, and IntraEPG contracts are not supported.
- Using service nodes inside a RHV domain have not been validated.

## GUI Guidelines

This section lists GUI-related usage guidelines for the Cisco APIC software.

- The Cisco APIC GUI includes an online version of the Quick Start Guide that includes video demonstrations.
- To reach the Cisco APIC CLI from the GUI: choose System > Controllers, highlight a controller, right-click, and choose "launch SSH". To get the list of commands, press the escape key twice.
- The Basic GUI mode is deprecated. We do not recommend using Cisco APIC Basic mode for configuration. However, if you want to use Cisco APIC Basic mode, use the following URL:

`APIC_URL/indexSimple.html`

## CLI Guidelines

This section lists CLI-related usage guidelines for the Cisco APIC software.

- The output from show commands issued in the NX-OS-style CLI are subject to change in future software releases. We do not recommend using the output from the show commands for automation.
- The CLI is supported only for users with administrative login privileges.
- If FIPS is enabled in the Cisco ACI setups, then SHA256 support is mandatory on the SSH Client. Additionally, to have the SHA256 support, the openssh-client must be running version 6.6.1 or higher.

## Layer 2 and Layer 3 Configuration Guidelines

This section lists Layer 2 and Layer 3-related usage guidelines for the Cisco APIC software.

- For Layer 3 external networks created through the API or GUI and updated through the CLI, protocols need to be enabled globally on the external network through the API or GUI, and the node profile for all the participating nodes needs to be added through the API or GUI before doing any further updates through the CLI.
- When configuring two Layer 3 external networks on the same node, the loopbacks need to be configured separately for both Layer 3 networks.
- All endpoint groups (EPGs), including application EPGs and Layer 3 external EPGs, require a domain. Interface policy groups must also be associated with an Attach Entity Profile (AEP), and the AEP must be associated with domains. Based on the association of EPGs to domains and of the interface policy groups to domains, the ports VLANs that the EPG uses are validated. This applies to all EPGs including bridged Layer 2 outside and routed Layer 3 outside EPGs. For more information, see the *Cisco APIC Layer 2 Networking Configuration Guide*.

**Note:** When creating static paths for application EPGs or Layer 2/Layer 3 outside EPGs, the physical domain is not required. Upgrading without the physical domain raises a fault on the EPG stating "invalid path configuration."

- In a multipod fabric, if a spine switch in POD1 uses the infra tenant L3extOut-1, the TORs of the other pods (POD2, POD3) cannot use the same infra L3extOut (L3extOut-1) for Layer 3 EVPN control plane connectivity. Each POD must use its own spine switch and infra L3extOut.

## Usage Guidelines

- You do not need to create a customized monitoring policy for each tenant. By default, a tenant shares the common policy under tenant common. The Cisco APIC automatically creates a default monitoring policy and enables common observable. You can modify the default policy under tenant common based on the requirements of your fabric.
- The Cisco APIC does not provide IPAM services for tenant workloads.
- Do not mis-configure Control Plane Policing (CoPP) pre-filter entries. CoPP pre-filter entries might impact connectivity to multi-pod configurations, remote leaf switches, and Cisco ACI Multi-Site deployments.
- You cannot use remote leaf switches with Cisco ACI Multi-Site.

## IP Address Guidelines

This section lists IP address-related usage guidelines for the Cisco APIC software.

- For the following services, use a DNS-based hostname with out-of-band management connectivity. IP addresses can be used with both in-band and out-of-band management connectivity.
  - Syslog server
  - Call Home SMTP server
  - Tech support export server
  - Configuration export server
  - Statistics export server
- The infrastructure IP address range must not overlap with other IP addresses used in the fabric for in-band and Out-of-band networks.
- If an IP address is learned on one of two endpoints for which you are configuring an atomic counter policy, you should use an IP-based policy and not a client endpoint-based policy.
- A multipod deployment requires the 239.255.255.240 system Global IP Outside (GIPO) to be configured on the inter-pod network (IPN) as a PIM BIDIR range. This 239.255.255.240 PIM BIDIR range configuration on the IPN devices can be avoided by using the Infra GIPO as System GIPO feature. The Infra GIPO as System GIPO feature must be enabled only after upgrading all of the switches in the Cisco ACI fabric, including the leaf switches and spine switches, to the latest Cisco APIC release.
- Cisco ACI does not support a class E address as a VTEP address.

## Miscellaneous Guidelines

This section lists miscellaneous usage guidelines for the Cisco APIC software.

- User passwords must meet the following criteria:
  - Minimum length is 8 characters
  - Maximum length is 64 characters
  - Fewer than three consecutive repeated characters
  - At least three of the following character types: lowercase, uppercase, digit, symbol

## Usage Guidelines

- Cannot be easily guessed
  - Cannot be the username or the reverse of the username
  - Cannot be any variation of "cisco", "isco", or any permutation of these characters or variants obtained by changing the capitalization of letters therein
- In some of the 5-minute statistics data, the count of ten-second samples is 29 instead of 30.
  - The power consumption statistics are not shown on leaf node slot 1.
  - If you defined multiple login domains, you can choose the login domain that you want to use when logging in to a Cisco APIC. By default, the domain drop-down list is empty, and if you do not choose a domain, the DefaultAuth domain is used for authentication. This can result in login failure if the username is not in the DefaultAuth login domain. As such, you must enter the credentials based on the chosen login domain.
  - A firmware maintenance group should contain a maximum of 80 nodes.
  - When contracts are not associated with an endpoint group, DSCP marking is not supported for a VRF with a vzAny contract. DSCP is sent to a leaf switch along with the actrl rule, but a vzAny contract does not have an actrl rule. Therefore, the DSCP value cannot be sent.
  - The Cisco APICs must have 1 SSD and 2 HDDs, and both RAID volumes must be healthy before upgrading to this release. The Cisco APIC will not boot if the SSD is not installed.
  - In a multipod fabric setup, if a new spine switch is added to a pod, it must first be connected to at least one leaf switch in the pod. Then the spine switch is able to discover and join the fabric.

Caution: If you install 1-Gigabit Ethernet (GE) or 10GE links between the leaf and spine switches in the fabric, there is risk of packets being dropped instead of forwarded, because of inadequate bandwidth. To avoid the risk, use 40GE or 100GE links between the leaf and spine switches.

- For a Cisco APIC REST API query of event records, the Cisco APIC system limits the response to a maximum of 500,000 event records. If the response is more than 500,000 events, it returns an error. Use filters to refine your queries. For more information, see *Cisco APIC REST API Configuration Guide*.
- Subject Alternative Names (SANs) contain one or more alternate names and uses any variety of name forms for the entity that is bound by the Certificate Authority (CA) to the certified public key. These alternate names are called "Subject Alternative Names" (SANs). Possible names include:
  - DNS name
  - IP address
- If a node has port profiles deployed on it, some port configurations are not removed if you decommission the node. You must manually delete the configurations after decommissioning the node to cause the ports to return to the default state. To do this, log into the switch, run the `setup-clean-config.sh` script, wait for the script to complete, then enter the `reload` command.
- When using the SNMP trap aggregation feature, if you decommission Cisco APICs, the trap forward server will receive redundant traps.
- If you upgraded from a release prior to the 3.2(1) release and you had any apps installed prior to the upgrade, the apps will no longer work. To use the apps again, you must uninstall and reinstall them.

## Related Documentation

- Fabric connectivity ports can operate at 10G or 25G speeds (depending on the model of the APIC server) when connected to leaf switch host interfaces. We recommend connecting two fabric uplinks, each to a separate leaf switch or vPC leaf switch pair.

For APIC-M3/L3, virtual interface card (VIC) 1445 has four ports (port-1, port-2, port-3, and port-4 from left to right). Port-1 and port-2 make a single pair corresponding to eth2-1 on the APIC server; port-3 and port-4 make another pair corresponding to eth2-2 on the APIC server. Only a single connection is allowed for each pair. For example, you can connect one cable to either port-1 or port-2 and another cable to either port-3 or port-4, but not 2 cables to both ports on the same pair. Connecting 2 cables to both ports on the same pair creates instability in the APIC server. All ports must be configured for the same speed: either 10G or 25G.

- When you create an access port selector in a leaf interface rofile, the fexId property is configured with a default value of 101 even though a FEX is not connected and the interface is not a FEX interface. The fexId property is only used when the port selector is associated with an infraFexBndIgrp managed object.

## Related Documentation

The Cisco Application Policy Infrastructure Controller (APIC) documentation can be accessed from the following website:

<https://www.cisco.com/c/en/us/support/cloud-systems-management/application-policy-infrastructure-controller-apic/tsd-products-support-series-home.html>

The documentation includes installation, upgrade, configuration, programming, and troubleshooting guides, technical references, release notes, and knowledge base (KB) articles, as well as other documentation. KB articles provide information about a specific use case or a specific topic.

By using the "Choose a topic" and "Choose a document type" fields of the APIC documentation website, you can narrow down the displayed documentation list to make it easier to find the desired document.

The following list provides links to the release notes and verified scalability documentation:

- [Verified Scalability](#)
- [Cisco ACI Simulator Release Notes](#)
- [Cisco NX-OS Release Notes for Cisco Nexus 9000 Series ACI-Mode Switches](#)
- [Cisco Application Policy Infrastructure Controller OpenStack and Container Plugins Release Notes](#)
- [Cisco Application Virtual Switch Release Notes](#)

## New Documentation

This section lists the new Cisco ACI product documents for this release.

- *Cisco ACI Virtual Edge Configuration Guide, Release 1.2(2)*
- *Cisco ACI Virtual Edge Installation Guide, Release 1.2(2)*
- *Cisco ACI Virtual Edge Release Notes, Release 1.2(2)*
- *Cisco ACI Virtualization Guide, Release 3.2(3)*
- *Cisco APIC NX-OS Style CLI Command Reference, Release 3.2(3)*

Related Documentation

- *Cisco Application Virtual Switch Configuration Guide, Release 5.2(1)SV3(3.25)*
- *Cisco Application Virtual Switch Installation Guide, Release 5.2(1)SV3(3.25)*
- *Cisco Application Virtual Switch Release Notes, 5.2(1)SV3(3.25)*

## Related Documentation

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company.  
(1110R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2018-2022 Cisco Systems, Inc. All rights reserved.