



Cisco TelePresence IX System Software Compatibility

First Published: 2018-08-22

Last Modified: 2019-06-13

Cisco TelePresence IX System Software Compatibility

This document shows you the software that has been tested with systems running IX software.

For CUCM device pack compatibility, see the [Cisco Unified Communications Manager Device Package Compatibility Matrix](#).

Cisco TelePresence IX System Software Compatibility for Release 9.x

The following table summarizes the IX software Release 9.x compatibility. The deployment of software shown in this matrix are tested and are supported by Cisco. Other combinations of products may work but are not supported and have not been tested.

Software version	IX 9.0.0	IX 9.0.1	IX 9.1.0
Cisco Unified Communications Manager	10.5.2 (see note 3) 11.0.1 (see note 4) 11.5.1 (see note 5) 12.0.1 (see note 6)	10.5.2 (see note 3) 11.0.1 (see note 4) 11.5.1 (see note 5) 12.0.1 (see note 6) 12.5.1	10.5.2 (see note 3) 11.0.1 (see note 4) 11.5.1 (see note 5) 12.0.1 (see note 6) 12.5.1
Cisco TelePresence System (CTS) TX software (see note 1)	6.1.13	6.1.13	6.1.13
Cisco TelePresence System (CTS) software (see note 2)	1.9.12 1.10.16	1.9.12 1.10.16	1.9.12 1.10.16
Cisco TelePresence Collaboration Endpoint (CE8) Software	CE 9.4.0	CE 9.6.1	CE 9.7.1
Cisco TelePresence Codec (TC7) Software	TC 7.3.12	TC 7.3.15	TC 7.3.17
DX650/DX70/DX80	10.2.5(215)	10.2.5(215)	10.2.5(215)

Software version	IX 9.0.0	IX 9.0.1	IX 9.1.0
TelePresence Management Suite (TMS)	15.6	15.6 15.7 15.8 (see note 7)	15.6 15.7 15.8 (see note 7) 15.9
TelePresence Manager Suite (TMS) with Phone Book support	15.6	15.6 15.7 15.8 (see note 7)	15.6 15.7 15.8 (see note 7) 15.9
Cisco Meeting Server	2.3.2	2.3.2 2.5	2.6.1
Cisco TelePresence Conductor	XC 4.3.2 XC 4.3.3	XC 4.3.2 XC 4.3.3	XC 4.3.5
Cisco TelePresence MCU	4.5(1.89)	4.5(1.98)	4.5(1.98)
Cisco TelePresence Server (TS)	4.4(1.24)	4.4(1.28)	4.4(1.28)
Cisco TelePresence Video Communications Server (VCS)	8.11	8.11 12.5	12.5
Cisco TelePresence Manager (CTS-Manager)	Not supported	Not supported	Not supported
Cisco TelePresence Multipoint Switch (CTMS)	Not supported	Not supported	Not supported



- Note**
1. Supported on CTS500-32, TX1310-47, TX1310-65, TX9000, and TX9200.
 2. Supported on CTS500-37, CTS1000, CTS1100, CTS1300-65, CTS3000, CTS3010, CTS3200, and CTS3210.
 3. Minimum device package version to support disable “Proximity Content Share To Clients” for 10.5 is 10.5.(2.18155).
 4. Minimum device package version to support disable “Proximity Content Share To Clients” for 11.0 is 11.0.(1.25097).
 5. Minimum device package version to support disable “Proximity Content Share To Clients” for 11.5.1 is 11.5(1.16083).
 6. Minimum device package version to support disable “Proximity Content Share To Clients” for 12.0.1 is 12.0(1.22022).
 7. TMS 15.8 requires LSC to be installed on IX5000 (see [CSCvo06229](#)). To install LSC, see the *Administration Guide for Cisco TelePresence Software Release IX 8 and Later*, located here: <https://www.cisco.com/c/en/us/support/collaboration-endpoints/ix5000-series/products-maintenance-guides-list.html>.

Cisco TelePresence IX System Software Compatibility for Release 8.x

The following table summarizes the IX software Release 8.x compatibility. The deployment of software shown in this matrix are tested and are supported by Cisco. Other combinations of products may work but are not supported and have not been tested.

Software version	IX 8.0.x	IX 8.1.0	IX 8.1.1 (see note 1) IX 8.1.2	IX 8.2.0 IX 8.2.1 IX 8.2.2	IX 8.2.3	IX 8.3.1.1
Cisco Unified Communications Manager	9.1.2 (see notes 2 and 3) 10.5 (see note 4)	9.1.2 (see note 3) 10.5 (see note 4) 11.0 (see note 5)	10.5 (see note 4) 11.0 (see note 5) 11.5	10.5 11.0.1 11.5.1	10.5 11.0.1 11.5.1	10.5.2 (see note 13) 11.0.1 (see note 14) 11.5.1 (see note 15) 12.0.1 (see note 16)
Cisco TelePresence System (CTS) TX software (see note 6)	6.1.x	6.1.x	6.1.x (see note 7)	6.1.12 6.1.13	6.1.13	6.1.13

Software version	IX 8.0.x	IX 8.1.0	IX 8.1.1 (see note 1) IX 8.1.2	IX 8.2.0 IX 8.2.1 IX 8.2.2	IX 8.2.3	IX 8.3.1.1
Cisco TelePresence System (CTS) software (see note 8)	1.9.x 1.10.x	1.9.x 1.10.x	1.9.x (see note 9) 1.10.x (see note 10)	1.9.x 1.10x	1.9.12 1.10.16	1.9.12 1.10.16
Cisco TelePresence Collaboration Endpoint (CE8) Software	Not supported	CE 8.0	CE 8.1	CE 8.1.1 CE 8.3.1 CE 9.0.1	CE 9.1.4	CE 9.2.4
Cisco TelePresence Codec (TC7) Software	TC 7.2	TC 7.3	TC 7.3	TC 7.3.6 TC 7.3.8 TC 7.3.0	TC 7.3.8 TC 7.3.9	TC 7.3.12
DX650/DX70/DX80	10.2.2	10.2.4	10.2.5	10.2.5	10.2.5(60)	10.2.5(215)
TelePresence Management Suite (TMS)	14.6	15.0.1	15.2.1	15.1 15.2.1 15.3	15.6	15.6
TelePresence Manager Suite (TMS) with Phone Book support	Not supported	Not supported	Not supported	15.3 15.5	15.6	15.6
Cisco Meeting Server	Not supported	Not supported	Not supported	2.1.4 2.2.2	2.2.6	2.3.2
Cisco TelePresence Conductor	XC 3.0	XC 4.0	XC 4.1	XC 4.2 XC 4.3	XC 4.3	XC 4.3
Cisco TelePresence MCU	4.5(1.19)	4.5(1.55)	4.5(1.55)	4.5(1.85) 4.5(1.89)	4.5(1.89)	4.5(1.89)
Cisco TelePresence Server (TS)	4.1	4.1 4.2	4.2 4.3	4.3 4.4	4.4(1.20)	4.4(1.20)
Cisco TelePresence Video Communications Server (VCS)	8.2	8.5	8.7	8.7.3 (see note 11) 8.9.1	8.9.1	8.10
Cisco TelePresence Manager (CTS-Manager)	1.9.3	1.9.4	1.9.4	1.9.4(56)	1.9.4(56)	1.9.4(56)

Software version	IX 8.0.x	IX 8.1.0	IX 8.1.1 (see note 1) IX 8.1.2	IX 8.2.0 IX 8.2.1 IX 8.2.2	IX 8.2.3	IX 8.3.1.1
Cisco TelePresence Multipoint Switch (CTMS)	1.9.6 (see note 12)	Not supported	Not supported	Not supported	Not supported	Not supported



- Note**
1. H.265 is not supported in IX 8.1.1.
 2. H.265 is not supported on Unified CM version 9.1.2 (H.264 only). H.264 and H.265 is supported for systems running Unified CM version 10.5 and higher.
 3. Minimum device package version for 9.1.2 is 9.1(2.13063). Older versions do not have the Cisco TelePresence IX5000 device type.
 4. Minimum device package version for 10.5 is 10.5(1.12016). Older versions do not have the Cisco TelePresence IX5000 device type.
 5. Minimum device package version for 11.0 is 11.0(1.22023).
 6. Supported on CTS500-32, TX1310-47, TX1310-65, TX9000, and TX9200.
 7. IX 8.1.2 and higher requires TX 6.1.12 and higher.
 8. Supported on CTS500-37, CTS1000, CTS1100, CTS1300-65, CTS3000, CTS3010, CTS3200, and CTS3210.
 9. IX 8.1.2 and higher requires CTS 1.9.11.
 10. IX 8.1.2 and higher requires CTS 1.10.15.
 11. See the TechZone article [Cisco Expressway B2BUA Drops RTCP Multistreaming Refresh Packets During Decryption in Cisco WebEx Calls](#).
 12. Do not use IX release 8.0.5 if you are using CTMS between IX5000 or IX5200 systems and SX80, MX700, or MX800 systems running TC release 7.x software. In these situations, use release 8.0.4.
 13. Minimum device package version to support enable “Proximity Content Share From Clients” for 10.5.2 is 10.5(2.17139).
 14. Minimum device package version to support enable “Proximity Content Share From Clients” for 11.0.1 is 11.0(1.24087).
 15. Minimum device package version to support enable “Proximity Content Share From Clients” for 11.5.1 is 11.5(1.14064).
 16. Minimum device package version to support enable “Proximity Content Share From Clients” for 12.0.1 is 12.0(1.22006).

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The following information is for FCC compliance of Class A devices: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio-frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case users will be required to correct the interference at their own expense.

The following information is for FCC compliance of Class B devices: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If the equipment causes interference to radio or television reception, which can be determined by turning the equipment off and on, users are encouraged to try to correct the interference by using one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Modifications to this product not authorized by Cisco could void the FCC approval and negate your authority to operate the product.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2018–2019 Cisco Systems, Inc. All rights reserved.