



# Cisco Unified Communications Manager Device Package 14.0(1.12014-1) Release Notes

**First Published:** 2022-01-19

## Introduction

Cisco Unified Communications Manager Device Package Release 14.0(1.12014-1) provides database and firmware updates for Cisco Unified Communications Manager 14.0(1).

For information about all released Cisco Unified Communications Manager device packages, see the [Cisco Unified Communications Manager Device Package Compatibility Matrix](#).

For information about how to install Cisco Unified Communications Manager device packages, see the [Cisco Unified Communications Manager Device Package Installation Guide](#).

## Device Package 14.0(1.12014-1)

The Cisco Unified Communications Manager Device Package 14.0(1.12014-1) filename and MD5 are in the following table.

**Table 1: Cisco Options Package Filename and MD5**

File	MD5
cmterm-devicepack14.0.1.12014-1.cop.sha512	20ee5b6d624b6f73bf8003db642dd915

Use the information in the following table to determine if you must install this device package.

**Table 2: Cisco Unified Communications Manager Device Package Release 14.0(1.12014-1)**

Device	Bug ID	Headline	Database Update	Firmware Upgrade	Notes
Webex Desk and Webex Desk Mini	CSCvy38655	QED files for the Webex Desk product	Yes	No	For more information, see the release notes for <a href="#">Cisco Webex RoomOS 10</a> .
Cisco IP Phone 8800 Series (excluding 8832)	CSCvy67284	QED for ELM calling number and line label display (88xx not including 8832)	Yes	No	For more information, see the <a href="#">Cisco IP Phone 8800 Release Notes for Firmware Release 14.1(1)</a> .

Device	Bug ID	Headline	Database Update	Firmware Upgrade	Notes
Webex Wireless Phone 840	CSCvy91825	1.4(0) QED files for Webex Wireless Phone 840	Yes	No	For more information, see the <a href="#">Webex Wireless Phone 840 and 860 Release Notes for Software Release 1.4(0)</a> .
Webex Wireless Phone 860	CSCvy91827	1.4(0) QED files for Webex Wireless Phone 860	Yes	No	For more information, see the <a href="#">Webex Wireless Phone 840 and 860 Release Notes for Software Release 1.4(0)</a> .
Cisco IP Phone 7800 Series and Cisco IP Phone 8800 Series	CSCvz34992	Add the QED to officially support Delayed PLAR CSCvp92871 (78xx, 88xx)	Yes	No	For more information, see the <a href="#">Cisco IP Phone 7800 Release Notes for Firmware Release 14.1(1)</a> and <a href="#">Cisco IP Phone 8800 Release Notes for Firmware Release 14.1(1)</a> .
Webex Board Pro 55 and 75	CSCvz41380	QED files for "Cisco Webex Board Pro 55" and "Cisco Webex Board Pro 75"	Yes	No	For more information, see the release notes for <a href="#">Cisco Webex RoomOS 10</a> .
Cisco IP Phone 7800 Series and Cisco IP Phone 8800 Series	CSCwa20601	checkin 14.1.1 firmware files for 7800 and 8800 IP Phones	No	Yes	For more information, see the <a href="#">Cisco IP Phone 7800 Release Notes for Firmware Release 14.1(1)</a> and <a href="#">Cisco IP Phone 8800 Release Notes for Firmware Release 14.1(1)</a> .
Cisco Headset 730	CSCwa32590	1.7 Release Load for 730 Headset (+ adapter)	No	Yes	For more information, see the <a href="#">Cisco Headset 730 Release Notes</a> .
Cisco Wireless IP Phone 8821	CSCwa47639	11.0(6)SR2 SIP loads for 8821 WLAN IP Phones	No	Yes	For more information, see the <a href="#">Cisco Wireless IP Phone 8821 and 8821-EX Release Notes for Firmware Release 11.0(6)SR2</a> .

## Firmware Table

The Cisco Unified Communications Manager Device Package Release 14.0(1.12014-1) contains loads for the following device releases.



**Note** The device package also contains configuration files for Cisco Webex DX, and Cisco TelePresence IX, MX, SX, and other TelePresence models. If there are any new configuration files for these models, they are listed in the previous table: [Device Package 14.0\(1.12014-1\)](#), on page 1. You can get the latest firmware for these models from the [Download Software](#) page.

**Table 3: Device Package Contents**

Device Type	Load Name	Version
3905	3905.9-4-1SR3	9.4(1SR3.0)
3911_3951-sip	3911_3951-sip.8-1-4a	8.1(4.0)
6608	6608-4.0.0.32-mgcp	4.0(0.32)
6608cfb	6608cfb-4.0.0.03-sccp	4.0(0.3)
6608mtp	6608mtp-4.0.0.06-sccp	4.0(0.6)
6624	6624-4.0.0.13-mgcp	4.0(0.13)
6901-sccp	6901-sccp.9-3-1-SR2-2	9.3(1.0)SR2.2
6901-sip	6901-sip.9-3-1-SR2-3	9.3(1.0)SR2.3
6911-sccp	6911-sccp.9-3-1-SR2-3	9.3(1.0)SR2.3
6911-sip	6911-sip.9-3-1-SR2-4	9.3(1.0)SR2.4
6945-SCCP	6945-SCCP-9-4-1-3SR3	9.4(1.3)SR3
6945-SIP	6945-SIP-9-4-1-3SR3	9.4(1.3)SR3
69xx-SCCP	69xx-SCCP-9-4-1-3SR3	9.4(1.3)SR3
69xx-SIP	69xx-SIP-9-4-1-3SR3	9.4(1.3)SR3
7832-sip.14	7832-sip.14-1-1-0001-125.k4	14.1.1(0001.125)
78xx.14	78xx.14-1-1-0001-136.k4	14.1.1(0001.136)
7911_7906-sccp	7911_7906-sccp.9-4-2SR3-1	9.4(2)SR3.1
7911_7906-sip	7911_7906-sip.9-4-2SR3-1	9.4(2)SR3.1
7914-sccp	7914-sccp.5-0-4	5.0(4.0)
7915	7915.1-0-4-2	1.0(4.2)
7916	7916.1-0-4-2	1.0(4.2)
7925-sccp	7925-sccp.1-4-8SR1-5.k3	1.4(8)SR1.5

Device Type	Load Name	Version
7926-sccp	7926-sccp.1-4-8SR1-5.k3	1.4(8)SR1.5
7931-sccp	7931-sccp.9-4-2SR2-2	9.4(2)SR2.2
7931-sip	7931-sip.9-4-2SR2-2	9.4(2)SR2.2
7936-sccp	7936-sccp.3-3-21	3.3(21.0)
7937	7937-1-4-5-7-SCCP	1.4(5.7)
7940-7960	7940-7960-8.12.00-sip	8.12(00.0)
7940-7960-sccp	7940-7960-sccp.8-1-2SR2	8.1(2)SR2.0
7941_7961-sccp	7941_7961-sccp.9-4-2SR3-1	9.4(2)SR3.1
7941_7961-sip	7941_7961-sip.9-4-2SR3-1	9.4(2)SR3.1
7942_7962-sccp	7942_7962-sccp.9-4-2SR3-1	9.4(2)SR3.1
7942_7962-sip	7942_7962-sip.9-4-2SR3-1	9.4(2)SR3.1
7945_7965-sccp	7945_7965-sccp.9-4-2SR3-1	9.4(2)SR3.1
7945_7965-sccp	7945_7965-sccp.9-4-2SR4	9.4(2)SR4.0
7945_7965-sip	7945_7965-sip.9-4-2SR4-3	9.4(2)SR4.3
7975-sccp	7975-sccp.9-4-2SR3-1	9.4(2)SR3.1
7975-sccp	7975-sccp.9-4-2SR4	9.4(2)SR4.0
7975-sip	7975-sip.9-4-2SR4	9.4(2)SR4.0
7985	7985-4-1-7-0-sccp	4.1(7.0)
8821-sip	8821-sip.11-0-6SR2-4.k4	11.0(6)SR2.4
8831-sip	8831-sip.10-3-1SR7-2	10.3(1)SR7.2
8832-sip.14	8832-sip.14-1-1-0001-125.k4	14.1.1(0001.125)
8845_65-sip.14	8845_65-sip.14-1-1-0001-125.k4	14.1.1(0001.125)
88xx-sip.14	88xx-sip.14-1-1-0001-125.k4	14.1.1(0001.125)
894x-sccp	894x-sccp.9-4-2SR3-1	9.4(2)SR3.1
894x-sip	894x-sip.9-4-2SR3-1	9.4(2)SR3.1
8961	8961.9-4-2SR4-1.k3	9.4(2)SR4.1
9951	9951.9-4-2SR4-1.k3	9.4(2)SR4.1
9971	9971.9-4-2SR4-1.k3	9.4(2)SR4.1

<b>Device Type</b>	<b>Load Name</b>	<b>Version</b>
ATA	ata-3.2.4-sccp	3.2(4.0)
ATA 187	ata187.9-2-3-1	9.2(3.1)
ATA 190	ata190.1-2-2-003_SR2-1	1.2(2.3)SR2.1
ATA 191.12	ata191.12-0-1-0405-005	12.0.1(0405.5)
Headset-builtin	headset-builtin.2-3-0001-13	2.3(0001.13)

---

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The following information is for FCC compliance of Class A devices: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio-frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case users will be required to correct the interference at their own expense.

The following information is for FCC compliance of Class B devices: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If the equipment causes interference to radio or television reception, which can be determined by turning the equipment off and on, users are encouraged to try to correct the interference by using one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Modifications to this product not authorized by Cisco could void the FCC approval and negate your authority to operate the product.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2022 Cisco Systems, Inc. All rights reserved.