

Cisco IP DECT 6800 Series Release Notes for Firmware Release 4.7

First Published: 2020-03-12

Cisco IP DECT 6800 Series Release Notes for Firmware Release 4.7

These release notes support the Cisco IP DECT 6800 Series running Firmware Release 4.7.

We recommend that existing customers update their firmware to this firmware release.

This release supports the following devices:

- Cisco IP DECT 210 Multi-Cell Base Station
- Cisco IP DECT Phone 6825 Handset
- Cisco IP DECT Phone 6825 Ruggedized Handset

The Cisco IP DECT 6800 Series is compatible with the following systems:

- BroadSoft BroadWorks 21.0 and later
- Asterisk 13.1 and later

The firmware release versions are:

- Base station version: 4.7; (displayed on the device as firmware version V0470 B0006)
- Handset version: 4.7; (displayed on the device as firmware version V0470 B0003)

Related Documentation

Use the following sections to obtain related information.

Cisco IP DECT 6800 Series Documentation

See the publications that are specific to your language and firmware release. Navigate from the following Uniform Resource Locator (URL):

<https://www.cisco.com/c/en/us/support/collaboration-endpoints/ip-dect-6800-series-multiplatform-firmware/tsd-products-support-series-home.html>

New and Changed Features

The following sections describe the features that are new or have changed in this release.

Base Station User Interface Enhancements

The base station web pages have these enhancements:

- The **Extensions**, **Terminal**, and **Edit extension** pages have changed to streamline handset deployment.

The following new fields are added to the **Extensions** page:

- Extension information with status
- Terminal position indicates RPN number and name of the base station.
- Battery charge level
- Received Signal Strength Indicator (RSSI) of the base station
- Time in minutes and seconds since the data was last received from the handset

The following fields are moved from the **Extensions** page to the **Terminal** page:

- Extension
- Display Name
- Server
- Server Alias
- State

The following fields no longer display on the **Edit Extension** web page:

- Forwarding Unconditional Number
- Forwarding No Answer Number
- Forwarding on Busy Number

- The **Edit Extension** page increases the maximum length of the following fields to 128 characters:
 - Authentication User Name
 - Authentication Password
 - XSI Username
 - XSI Password
- The **Network Settings** web page has the **Failover Reconnect Time** field added.
- The **Statistics** web page has **Emergency calls**, **Call drops due to emergency call**, and **Emergency calls rejected** fields added in the **Calls** view.
- The **Generic Statistics** web page does not support **Total Codec usage (G.711A, G.711U, G.726, G.729)** field in this release.
- The handsets send messages to the base station every 15 minutes. If the base station doesn't receive 4 messages from a handset, it changes the state of that handset to **Removed**. On the **Extensions** page, the handset displays **Removed** in the **Terminal Status** field and displays a red dot beside the handset extension.

Where to Find More Information*Cisco IP DECT 6800 Series Administration Guide***Domain Name Server – Naming Authority Pointer (DNS NAPTR) Support**

You use the Name Authority Pointer (NAPTR) to allow the handset to automatically determine and select the appropriate transport protocol for the phone line.

You specify the transport protocol of your choice (UDP, TCP, or TLS) on the base station web page. You set the **SIP Transport** field on the **Servers** page to **Auto** to enable the phone to automatically select the protocol.

When you configure the setting to **Auto**, the handset determines the transport protocol based on the NAPTR records on the DNS server. The handset uses the protocol specified in the record that has the lowest order and preference. When there are multiple records with the same order and preference, the handset looks for a protocol within the records, in the following order of preference: UDP, TCP, and TLS. The phone uses the highest priority protocol that it finds in a record.

Where to Find More Information*Cisco IP DECT 6800 Series Administration Guide***Handset User Interface Enhancements**

Users see the following enhancements:

- The handset displays the Cisco logo at startup.
- The handset warns the user when it's too far away from the base station.
 - When the handset is in use, the user hears a beep. The **Coverage warning** field in the **Audio Settings** menu must be set to **On**.
 - When the handset is idle, the user sees  instead of the coverage bars in the top left corner of the screen.
- When the user has a recurrent alarm, the handset identifies that the alarm is recurrent after it sounds for that particular day. The **Alarms** screen displays the time and weekdays for the recurrent alarm.

Where to Find More Information*Cisco IP DECT 6800 Series User Guide***OPUS Codec Support**

The handsets and base station now support the OPUS codec.

You enable the codec on the **Server** page of the base station administration page. By default, OPUS doesn't display in the **Codec Priority** field, so you need to click **Reset Codecs** to add OPUS to the list.

Where to Find More Information*Cisco IP DECT 6800 Series Administration Guide*

Cisco IP DECT Phone 6825 Ruggedized Handset

If you need to use the handset in a volatile, dusty, or damp environment, you can use the Cisco IP DECT Phone 6825 Ruggedized Handset. This handset is IP65-rated, which means that the handset is sealed to protect it from dust and water.

The standard handset and ruggedized handset have the same call features. The ruggedized handset has the orange band to differentiate it from the standard handset.

Figure 1: Cisco IP DECT Phone 6825 Ruggedized Handset



Where to Find More Information

- *Cisco IP DECT 6800 Series Administration Guide*
- *Cisco IP DECT 6800 Series User Guide*

Documentation Changes

Starting with Firmware Release 4.7, updates directly related to the release features are clearly marked in the documents. This change allows users of previous releases to identify content applicable to their release.

For example, the new field, **Failover Reconnect Timer**, is identified in the *Cisco IP DECT 6800 Series Administration Guide* as a new field for Firmware Release 4.7.

Firmware Release 4.7 also caused a major revision to two administration web pages. The new version and old version of the sections to describe the pages are contained in the *Cisco IP DECT 6800 Series Administration Guide*. The new sections and the old sections identify the firmware release and contain cross-references between the sections to assist the user.

Upgrade the Firmware

You can upgrade the base station and handset firmware with TFTP, HTTP, or HTTPS. You upgrade the base station first. After the upgrade, the base station automatically reboots. Then you upgrade the handsets, which automatically reboot.

You access the Cisco Software Download page to get the firmware in zip files. The zip files contain these firmware files:

- For the base station, the zip filename starts with IPDECT-DBS210.
- For the standard and ruggedized handsets, the zip filename start with IPDECT-PH6825.

The Firmware Release 4.7 zip files contain files:

- For the base station: `IPDeCt-DBS210.0470MPP-6_REL.zip`
- For standard and ruggedized handsets: `IPDeCt-PH6825.0470MPP-3_REL.zip`



Note

- If you upgrade the base station from Firmware Release V460B1 or earlier, the administration user ID and password reset to the default values.
- After you install this load and then need to downgrade the release to Firmware Release V460B1 or earlier, you must perform a factory reset on the base station. This reset will set the administration user ID and password to the default values.

For detailed information about the upgrade procedure, refer to the “Maintenance” chapter in the *Cisco IP DECT 6800 Series Administration Guide*.

Before you begin

You need the TFTP, HTTP, or HTTPS server information.

Procedure

-
- Step 1** From your browser, go to <https://software.cisco.com/download/home/286323307>.
 - Step 2** If required, sign in with your user ID and password.
 - Step 3** Click **IP DECT 210 Multi-Cell Base-Station**.
 - Step 4** Select **All Release > MPP DECT v4 > 4.7.1**.
 - Step 5** Download the zip file for the required version.
 - Step 6** Return to <https://software.cisco.com/download/home/286323307>.
 - Step 7** Click **IP DECT 6825 with Multiplatform Firmware**.
 - Step 8** Select **All Release > MPP DECT v4 > 4.7.1**.
 - Step 9** Download the zip file for the required version.
 - Step 10** On your PC, unzip the files.
 - Step 11** Access the TFTP server file system.
 - Step 12** If not available, create a `Cisco` directory.
 - Step 13** Open the `Cisco` directory.
 - Step 14** Copy the new base station firmware file to the `Cisco` folder.
 - Step 15** Copy the new handset firmware file to the `Cisco` folder.
 - Step 16** Complete the upgrade as described in the *Cisco IP DECT 6800 Series Administration Guide*.
-

Limitations and Restrictions

System Behavior During Times of Network Congestion

Anything that degrades network performance can affect phone system voice quality, and in some cases, can cause a call to drop. Sources of network degradation can include, but are not limited to, the following activities:

- Administrative tasks, such as an internal port scan or security scan
- Attacks that occur on your network, such as a Denial of Service attack

Caller Identification and Other Phone Functions

Caller identification or other phone functions have not been verified with third-party applications for the visually or hearing impaired.

Base Station Firmware Downgrade Limitation

After the upgrade for V460 B4, a downgrade of the base to a firmware version earlier than V460 B2 requires you to factory reset the base. This factory reset will reset the login credentials to the defaults. If you don't perform the factory reset, you can't log into the administration web pages.

Base Station Alert Due to a Clock Synchronization Error

The base station self-check process fails if there's a clock synchronization error. When this error occurs, the LED on the base station flashes red, amber, and green. In this case, we recommend the standard RMA process.

Open Caveats

The following caveats are open at the time of the release.

- 243937 Holding tone not played
- 249172 Add second extension also added the line as the Alarm Line
- 279421 Unattended Transfer fails
- 290676 DBS210 Dialing '#' Does Not Send Call Immediately
- 293361 All handsets entered "Search" mode during failover/fallback testing, and could not be back to normal mode without rebooting the base.
- 305835 DBS210 moves one hour back at 2:00 AM instead 3:00 AM when DST ends in NEW Zealand on April 5, 2020.
- 2 days of no 2 way audio / DBS-210
- PRT Upload issue
- Security web page - Web password constraints section
- UDP/TCP Option in SIP message on 210 base station
- DECT 6825 base unit, suddenly stopped getting an IP from the DHCP server
- Handset turns on when placed in charger (previously turned off)
- SIP log showing blank entries

- When You receive a call there is white noise on some of the calls

Resolved Caveats

The following caveats were resolved for the release.

- 206584 Display backlight flashes each time LED indicates missed call
- 207753 Emergency call: Not able to create emergency call at RTP busy RFP
- 248054 Web parameter length issue
- 248277 Generic Statistics Admin Page display requests
- 248462 Horizontal scroll bar missing: Horizontal scroll bar has been added to "Dial Plans" webpage of the base station
- 249523 G729 Both parties put call on hold
- 251148 Duplicate codec usage statistics
- 252367 Guards missing on webpage field
- 252428 Unable to hold the call for more than 10 minutes
- 252833 Option 150 makes Configuration-field disappear
- 252836 <Profile_Rule> Does not set "Configuration File Download" in correct state
- 253061 Dialplan "*xx|#xx|x." makes handset call out after one digit
- 253064 Dialplan "*xx|#xx|x." makes handset call out after one digit
- 253221 After "append to contact" other number types disappear
- 253629 "Can't locate a base station" OOB error text not in red
- 254611 Contact - HS is reset suddenly while appending
- 258255 'Unexpected reboot' seen in syslog after configuration loaded
- 260042 After all digits erased and then press clear again cannot return to main central dir
- 260629 Base station can not change the AC code
- 263152 SIP User Name and password disappears/becomes corrupted at BS FWU
- 263188 When attempting to dial an international number, I get "Invalid number"
- 266423 OPUS: Target crashes, when trying to establish phone conference
- 267018 G729: 10 calls is not working
- 268392 Connection Failed when accessing LDAP server through TLS
- 268897 OPUS audio disappear after multiple "hold-resume" cycles
- 269382 Wrong format in SDP telephone-event
- 269820 Clock configuration fix in device driver

- 276414 DBS-210 customer deployment 1 base w/ 5 handsets. Handsets become stale and unresponsive to making or receiving calls
- 279405 Unattended Transfer failed
- 279408 Pause screen shown when call ends
- 279414 LLDP-med messages are not send if CDP is enabled
- 280516 TCP Failover is not handled correctly when TCP connection fails on REGISTER
- 286959 Missing Last Digits in XSI Search
- 288549 After registered, handset could not seize line
- 288551 SCA After registered, red small square stayed on
- 289743 SCA - Stops sending call-info and line-seize subscriptions
- 290544 SIP error 5xx will trigger failover on base station
- 304046 HW self-check for missing CLK

Cisco IP Phone Firmware Support Policy

For information on the support policy for phones, see <https://cisco.com/go/phonefirmwaresupport>.

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The following information is for FCC compliance of Class A devices: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio-frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case users will be required to correct the interference at their own expense.

The following information is for FCC compliance of Class B devices: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If the equipment causes interference to radio or television reception, which can be determined by turning the equipment off and on, users are encouraged to try to correct the interference by using one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Modifications to this product not authorized by Cisco could void the FCC approval and negate your authority to operate the product.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2020 Cisco Systems, Inc. All rights reserved.