



# Cisco IP Phone 7800 Series Multiplatform Phones Release Notes for Firmware Release 11.1(1)

---

**First Published:** 2017-10-17

## Cisco IP Phone 7800 Series Multiplatform Phones Release Notes for Firmware Release 11.1(1)

Use these release notes with the following Cisco IP Phone 7800 Series Multiplatform Phones running SIP Firmware Release 11.1(1).

- Cisco IP Phone 7811 Multiplatform Phones
- Cisco IP Phone 7821 Multiplatform Phones
- Cisco IP Phone 7841 Multiplatform Phones
- Cisco IP Phone 7861 Multiplatform Phones

The following table describes the individual phone requirements.

Phone	Support Requirements
Cisco IP Phone 7800 Series Multiplatform Phones	BroadSoft BroadWorks 21.0 Asterisk 13.1

## Related Documentation

Use the following sections to obtain related information.

### Cisco IP Phone 7800 Series Documentation

See the publications that are specific to your language, phone model, and multiplatform firmware release. Navigate from the following Uniform Resource Locator (URL):

<https://www.cisco.com/c/en/us/products/collaboration-endpoints/unified-ip-phone-7800-series/index.html>

## New and Changed Features

The following sections describe the features that are new or have changed in this release.

## Asian Language Support

The phones now support these languages:

- Japanese
- Korean
- Chinese Simplified
- Chinese Hong Kong

### Where to Find More Information

- *Cisco IP Phone 7800 Series Multiplatform Phones Administration Guide*

## Configuration Report to Provisioning Server

You can configure the phone to report its current configuration to the server. After you configure, the server issues a SIP NOTIFY message to the phone to report the configuration. You can configure this feature from the phone web page.

### Where to Find More Information

- *Cisco IP Phone 7800 Series Multiplatform Phones Administration Guide*

## Distinctive Ringtone

You can set a distinctive ringtone for an extension. Distinctive ringtone allows the phone to avoid playing default ringtone always and enables the receiver to identify the type of the incoming call on the extension. Distinctive ringtone depends on the SIP Alert-Info message that the server sends to the phone. When the phone receives a correct SIP Alert-INFO message, it plays the specified ringtone. Otherwise, the phone plays the default ringtone.

### Where to Find More Information

- *Cisco IP Phone 7800 Series Multiplatform Phones Administration Guide*

## Download Status with Phone Web Page

You can view different download status in the phone web page from **Info > Download Status**:

- Firmware Upgrade Status: Displays the upgrade status (failed or succeeded) with reason for the same.
- Provisioning Status: Displays the upgrade status (resync) of the phone.
- Custom CA Status: Indicates whether provisioning using a custom CA succeeded or failed.

### Where to Find More Information

- *Cisco IP Phone 7800 Series Multiplatform Phones Administration Guide*

## Factory Reset Button on the Phone Web Page

You can press a button on the phone web page to perform a factory reset on an inactive phone. If the phone is not idle, you can't reset the phone.

### Where to Find More Information

*Cisco IP Phone 7800 Series Multiplatform Phones Administration Guide*

## IPv6 Support

The Cisco IP Phones support IPv6 addressing. A valid IPv6 address is 128 bits in length that includes the subnet prefix. The subnet prefix length is a decimal value from 1-128. IPv6 has support for NTP and SIP. IPv6 addresses must be in one of the following formats:

- Eight sets of four hexadecimal digits separated by colons, where the left-most digits represent the highest-order bits. Any leading or trailing zeros in each group may be omitted. An example of an IPv6 address is 2009:10:74:10:6969:ad71:93c5:2fca.
- Compressed format to collapse a single run of consecutive zero groups into a single group represented by a double colon. Note that this can only be done once in an address. An example of compressed format IPv6 address is fe80::21b:54ff:feb0:4f91.

Phone features that do not support IPv6 are:


- Group Paging
- TR069
- LDAP
- STUN

### Where to Find More Information

- *Cisco IP Phone 7800 Series Multiplatform Phones Administration Guide*

## Presence

You can set up your phones so that users can view the presence status of their contacts. You need to set up the XMPP service on the Broadsoft server, and enable access to the XMPP server in the Phone tab of the phone web page.


Users need to access Broadsoft's UC-One Communicator to set up their instant message and presence (IM&P) contact lists. After they have a list of contacts, they press **Contacts**  and access the IM&P entry.

### Where to Find More Information

- *Cisco IP Phone 7800 Series Multiplatform Phones Administration Guide*
- *Cisco IP Phone 7800 Series Multiplatform Phones User Guide*

## Phone Screen Contrast

You can adjust the phone screen brightness and contrast on the screen.

To change the brightness, press **Applications**  and select **User preferences > Screen preferences > Display contrast**. You press the Navigation cluster up or down to increase or decrease the brightness.

### Where to Find More Information

- *Cisco IP Phone 7800 Series Multiplatform Phones User Guide*

## Secure Calls on Extensions

You can configure phones to only allow secure calls. Use the phone web page to configure the extension as secure.

When a user wants to place a call on a secure extension, they can only place calls to secure extensions. Calls to nonsecure extensions are blocked. When a call is secure, the lock icon is displayed on the phone screen.

### Where to Find More Information

- *Cisco IP Phone 7800 Series Multiplatform Phones Administration Guide*
- *Cisco IP Phone 7800 Series Multiplatform Phones User Guide*

## Installation

### Upgrade Firmware

The Cisco IP Phone 7800 Series Multiplatform Phones support a single image upgrade by TFTP, HTTP, or HTTPS.

After the firmware upgrade completes, the phone reboots automatically.

---

#### Step 1

Click the following URL:

<http://software.cisco.com/download/navigator.html?mdfid=284883944&i=rm>

- Step 2** Select the **IP Phones with Multiplatform Firmware** in the middle pane.
- Step 3** Select the **IP Phones 7800 Series With Multiplatform Firmware** in the right pane.
- Step 4** Select your phone model in the right pane.
- Step 5** Select **Multiplatform Firmware**.
- Step 6** In the **All Releases > MPPv11** folder, select **11.1.1**.
- Step 7** (Optional) Place your mouse pointer on the filename to display the file details and checksum values.
- Step 8** Download the file `cmterm-78xx.11-1-1MPP-897_REL.zip`.
- Step 9** Click **Accept License Agreement** when you accept the software license.
- Step 10** Unzip the files.
- Step 11** Put the files in the TFTP, HTTP, or HTTPS download directory.
- Step 12** Configure the Upgrade Rule on the **Provisioning** tab in the web page with the valid URL.  
Use the URL format—`<protocol>://<serv_ip[:port]>/<filepath>/sipxxx.loads`
- The third-party call control can also upgrade via a URL in the web browser:  
`<protocol>://<serv_ip[:port]>/<filepath>/sipxxx.loads`
- Here is an example,  
`http://10.73.10.223/firmware/sip78xx.11-1-1MPP-897.loads`
- Note** Use the `*.loads` file in the URL. The `*.zip` file contains other files.
- 

## Limitations and Restrictions

### Phone Behavior During Times of Network Congestion

Anything that degrades network performance can affect phone voice and video quality, and in some cases, can cause a call to drop. Sources of network degradation can include, but are not limited to, the following activities:

- Administrative tasks, such as an internal port scan or security scan
- Attacks that occur on your network, such as a Denial of Service attack

### Caller Identification and Other Phone Functions

Caller identification or other phone functions have not been verified with third-party applications for the visually or hearing impaired.

### No Beep Sound Heard when the Mute Key is Pressed

When you press the **Mute** button during a call, you may not hear a beep sound. For anyone who is visually impaired, press the **Mute** button once to mute the phone and press the button twice to unmute the phone.

## Phone Has a Firmware Build Earlier than 11.0.0

Sometimes, a phone taken out of the box has a firmware build earlier than 11.0.0. When this happens, you must upgrade the firmware on your phone before you provision it.

## Caveats

### Access Cisco Bug Search

Known problems (bugs) are graded according to severity level. These release notes contain descriptions of the following:

- All severity level 1 or 2 bugs
- Significant severity level 3 bugs

You can search for problems by using Cisco Bug Search.

#### Before You Begin

To access Cisco Bug Search, you need the following items:

- Internet connection
- Web browser
- Cisco.com user ID and password

---

**Step 1** To access Cisco Bug Search, go to:  
<https://tools.cisco.com/bugsearch>

**Step 2** Log in with your Cisco.com user ID and password.

**Step 3** To look for information about a specific problem, enter the bug ID number in the Search for field, then press **Enter**.

---

## Open Caveats

The following list contains the severity 1, 2, and 3 defects that are open for the Cisco IP Phone 7800 Series Multiplatform Phones that use Firmware Release 11.1(1).

For more information about an individual defect, you can access the online history for the defect by accessing the Bug Search tool and entering the Identifier. You must be a registered Cisco.com user to access this defect information.

Because the defect status continually changes, the list reflects a snapshot of the defects that were open at the time this report was compiled. For an updated view of the open defects or to view specific bugs, access the Bug Search Toolkit as described in the [Access Cisco Bug Search, on page 6](#).

- CSCvb50513 MPP phone having an issue upgrading to Enterprise firmware.

- CSCvc85704 MPP: CFWD all De-act star code does not work.
- CSCvc94798 7800-MPP: BS BLF List disappearing when receiving call.
- CSCvd27675 MPP: Play ringtone failed and phone cannot answer or place a call.
- CSCvd46241 MPP: Secondary DNS on a phone's web page has a nonexistent IP address.
- CSCvg09851 Sometimes duplicated IPv6 address warning messages are not able to be shown on LCD GUI.
- CSCvg69428 Customer is reporting random reboots.
- CSCvh13270 78xx: Display is showing two calls during conference.
- CSCvh19503 PC port mirror does not work on 78xx 11-1-1MPP897. Loads with switch voice VLAN configured.

## Resolved Caveats

The following list contains the severity 1, 2, and 3 defects that are resolved for the Cisco IP Phone 7800 Series Multiplatform Phones that use Firmware Release 11.1(1).

For more information about an individual defect, you can access the online history for the defect by accessing the Bug Search tool and entering the Identifier. You must be a registered Cisco.com user to access this defect information.

Because the defect status continually changes, the list reflects a snapshot of the defects that were resolved at the time this report was compiled. For an updated view of the resolved defects or to view the specific bugs, access the Bug Search Toolkit as described in the [Access Cisco Bug Search, on page 6](#).

- CSCvg50696 Phone can get into a state that requires hard factory reset.
- CSCva83207 EM Sign-in soft key not displayed after factory reset and EM enabled.
- CSCvb55751 7861 sometimes needs reboot for pushed config to take effect.
- CSCvb61321 Phones appear to ignore the 120 seconds timer in the 200 OK.
- CSCvb69587 MPP-Generic-78xx: Spelling is wrong for directory in LCD Idle screen.
- CSCvb71520 7811 sends SIP ACK incorrectly containing "user=phone".
- CSCvb83904 MPP-78XX - phone's switch does not change CoS value after extended CoS changes.
- CSCvb85886 MPP-78xx: Press BLF SD PLK three times, phone still play tone while idle.
- CSCvc24856 MPP-78xx: Cisco IP Phone Menu display error: displays part of the item number.
- CSCvc27600 Auth-resync not working.
- CSCvc78710 MPP: Phone reboots periodically due to provision even phone config file not changed
- CSCvc80575 MPP: agent not sign out from BroadSoft server after disable ACD
- CSCvc97003 MPP-78xx: Changes in NTP time during a call could cause abnormal values in rtcp reports.
- CSCvd09730 MPP: User can factory reset phone without password.
- CSCvd15759 MPP: phone sends wrong DNS query to TFTP server.
- CSCvd27898 MPP: DN not register after upgrade.

- CSCvd42430 MPP: backtrace at spr\_voip.
- CSCvd70401 Intermittent re-invite errors on hold/resume.
- CSCvd70446 Phone does not re-register upon DNS change of outbound proxy.
- CSCvd90401 Opus Payload incorrectly has a clock rate at 16000 (RFC 7587)
- CSCve06933 Provisioning Fails: If cname is used for provisioning server and used on the cert
- CSCve89301 Phone rebooted when call came in from webex
- CSCve89514 After adjusting call volume mid call, dial pad keys become unusable
- CSCvf82885 Lack of Connectivity: REGISTER with a Call-ID incomplete.
- CSCvf96511 ISSUE WITH "DO NOT DISTURB" AND "CALL FORWARD ALL" FEATURES.
- CSCvf99303 78xx-MPP: XML Corp Directory doesn't allow you to dial out.
- CSCvg22226 Evaluation of MPP-sp-dspg for Dnsmasq October 2017 vulnerabilities
- CSCvg30255 Under CPE with QMON: After any incoming/outgoing call
- CSCvg30274 BLF led randomly not aligned (blinking orange) because device didn't
- CSCvg61103 MPP phones are now using up the bandwidth on their network

## Cisco IP Phone Firmware Support Policy

For information on the support policy for phones, see <http://www.cisco.com/c/en/us/support/docs/collaboration-endpoints/unified-ip-phone-7900-series/116684-technote-ipphone-00.html>.

## Documentation, Service Requests, and Additional Information

For information on obtaining documentation, submitting a service request, and gathering additional information, see the monthly *What's New in Cisco Product Documentation*, which also lists all new and revised Cisco technical documentation, at:

<http://www.cisco.com/c/en/us/td/docs/general/whatsnew/whatsnew.html>

Subscribe to the *What's New in Cisco Product Documentation* as a Really Simple Syndication (RSS) feed and set content to be delivered directly to your desktop using a reader application. The RSS feeds are a free service and Cisco currently supports RSS Version 2.0.



---

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The following information is for FCC compliance of Class A devices: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio-frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case users will be required to correct the interference at their own expense.

The following information is for FCC compliance of Class B devices: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If the equipment causes interference to radio or television reception, which can be determined by turning the equipment off and on, users are encouraged to try to correct the interference by using one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Modifications to this product not authorized by Cisco could void the FCC approval and negate your authority to operate the product

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NONINFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2018 Cisco Systems, Inc. All rights reserved.