

Cisco IP Phone 7800 Series Multiplatform Phones Release Notes for Firmware Release 12.0(3)

First Published: 2023-08-17

Last Modified: 2023-08-17

Release Notes

Use these release notes with the Cisco IP Phone 7800 Series Multiplatform Phones running SIP Firmware Release 12.0(3).

The following table describes the individual phone requirements.

Phone	Support Requirements
Cisco IP Phone 7800 Series Multiplatform Phones	BroadSoft BroadWorks 24.0 MetaSphere CFS version 9.5 Asterisk 16.0

Related Documentation

Use the following sections to obtain related information.

Cisco IP Phone 7800 Series Documentation

See the publications that are specific to your language, phone model, and multiplatform firmware release. Navigate from the following Uniform Resource Locator (URL):

<https://www.cisco.com/c/en/us/products/collaboration-endpoints/ip-phone-7800-series-multiplatform-firmware/index.html>

New and Changed Features

Automatic Renewal of MIC Certificate

From 12.0.3 release onwards, all phones can automatically renew its Manufacture Installed Certificate (MIC) by reaching out to cloud service at sudirenewal.cisco.com. To allow traffic to the cloud service, make sure to update your firewall settings. If you are a service provider and your servers challenge phones for their certificate, make sure to update the server trust store to include new root CA. For more information, see the field notice FN - 72302 - <https://www.cisco.com/c/en/us/support/docs/field-notices/723/fn72302.html>.



Note From 12.0.3 release, SUDI feature is enabled by default.

Where to Find More Information

- *Cisco IP Desk Phone with Multiplatform Firmware (MPP) - Administration Guide*

Factory Reset with SIP-Notify

You can initiate a factory reset of a phone when the phone is deleted from server. Once deleted by the administrator, phone will receive SIP-NOTIFY message with event:factory-reset and performs factory-reset accordingly.

Where to Find More Information

- *Cisco IP Phone 7800 Series Multiplatform Phones User Guide*
- *Cisco IP Desk Phone with Multiplatform Firmware (MPP) - Administration Guide*

Invoking of XML Service with Multicast Paging

This feature allows phones to receive pages from a server to optionally display an image or other UI elements. With this feature, you can invoke the XML service from multicast paging. When configured, user will not be able to see the **XML application** in the **Information and settings** menu on the phone.

To enable this feature from the phone administration web page, use the **XML Application Service URL** parameter under **XML Service** from **Voice > Phone**.

Where to Find More Information

- *Cisco IP Phone 7800 Series Multiplatform Phones User Guide*
- *Cisco IP Desk Phone with Multiplatform Firmware (MPP) - Administration Guide*

HTTPS Enablement by Default

With this release you must enable **Https** by default to access the phone administration web page. To enable this feature from the phone administration web page, use the **Enable Protocol** and **Web Server Port** under **System Configuration** section from **Voice > System**. A phone with Firmware version 12.0(3) and later always gets redirected to **https://<ip address>:443**. When you enable protocol to **Https** and web server port to **443**, after the factory reset, if you do not change the values and your user wants to access the phone administration web page with **http://<ip address>** or **http://<ip address>:80**, the URL gets redirected to **https://<ip address>:443**.

Where to Find More Information

- *Cisco IP Desk Phone with Multiplatform Firmware (MPP) - Administration Guide*

Password Alert after Factory Reset

After a factory reset, when the phone boots up for the first time, it displays a prompt to set up a password as a security measure. If the user chooses to skip the password setup, phone shows a warning message. You can set the user password in the phone administration web page. If the password is not created, the user can use the **Create** softkey on the **Issues** screen to create a new password. Once the user creates the password the phone displays an unlock icon on the phone screen.

To enable this feature from the phone administration web page, use the **Display Password Warnings** parameter under **System Configuration** section from **Voice > System**.

Where to Find More Information

- *Cisco IP Desk Phone with Multiplatform Firmware (MPP) - Administration Guide*

Upgrade Firmware

You can upgrade the phone firmware with TFTP, HTTP, or HTTPS. After the upgrade completes, the phone reboots automatically.

Procedure

-
- Step 1** Click this link:
<https://software.cisco.com/download/home/286318380>
 On the **Software Download** web page that is displayed, ensure that **IP Phone 7800 Series with Multiplatform Firmware** is selected in the middle pane.
- Step 2** Select your phone model in the right pane.
- Step 3** On the next page that is displayed, select **Multiplatform Firmware**.
- Step 4** On the next page that is displayed, select **12.0.3** in the **All Releases > MPPv12** folder.
- Step 5** (Optional) Place your mouse pointer on the file name to see the file details and checksum values.
- Step 6** Download the corresponding file.
 cmterm-78xx.12-0-3MPP0001-87.zip
- Step 7** Click **Accept License Agreement**.
- Step 8** Unzip the file and place the files in the appropriate location on your upgrade server.
 The appropriate location is the TFTP, HTTP, or HTTPS download folder, depending on the protocol that you want to use for the upgrade.
- Step 9** Upgrade the phone firmware with one of these methods.
- Upgrade the phone firmware from the phone administration web page:
 - a. On the phone administration web page, go to **Admin Login > Advanced, Voice > Provisioning > Firmware Upgrade**.
 - b. In the **Upgrade Rule** field, enter the load file URL as described below.
 Load file URL format:

```
<upgrade protocol>://<upgrade server ip address>[:<port>]/<path>/<file name>.loads
```

 Examples:

```
http://10.73.10.223/firmware/sip78xx.12-0-3MPP0001-87.loads
```

```
https://server.domain.com/firmware/sip78xx.12-0-3MPP0001-87.loads
```
 - c. Click **Submit All Changes**.

- Upgrade the phone firmware directly from your web browser:

In the address bar of your web browser, enter the phone upgrade URL as described below.

Phone upgrade URL format:

```
<phone protocol>://<phone ip address[:port]>/admin/upgrade?<load file URL>
```

Load file URL format:

```
<upgrade protocol>://<upgrade server ip address>[:<port>]/<path>/<file name>.loads
```

Examples:

```
https://10.74.10.225/admin/upgrade?http://10.73.10.223/firmware/sip78xx.12-0-3MPP0001-87.loads
```

```
https://10.74.10.225/admin/upgrade?https://server.domain.com/firmware/sip78xx.12-0-3MPP0001-87.loads
```

Note Specify the <file name>.loads file in the URL. The <file name>.zip file contains other files.

Limitations and Restrictions

Phone Behavior During Times of Network Congestion

Anything that degrades network performance can affect phone audio and, in some cases, can cause a call to drop. Sources of network degradation can include, but are not limited to, the following activities:

- Administrative tasks, such as an internal port scan or security scan.
- Attacks that occur on your network, such as a Denial of Service attack.

Caveats

-

View Caveats

You can search for caveats (bugs) with the Cisco Bug Search tool.

Known caveats are graded according to severity level, and are either open or resolved.

Before you begin

You have your Cisco.com user ID and password.

Procedure

Step 1 Click one of the following links:

- To view all caveats that affect this release:

https://bst.cloudapps.cisco.com/bugsearch/search?productId=&productId=Cisco%20IP%20Phone%207800%20Series%20with%20Multiplatform%20Firmware&kw=*&dt=usV&ts=1203

- To view open caveats that affect this release:

https://bst.cloudapps.cisco.com/bugsearch/search?productId=&productId=Cisco%20IP%20Phone%207800%20Series%20with%20Multiplatform%20Firmware&kw=*&dt=usV&ts=1203

- To view resolved caveats that affect this release:

https://bst.cloudapps.cisco.com/bugsearch/search?productId=&productId=Cisco%20IP%20Phone%207800%20Series%20with%20Multiplatform%20Firmware&kw=*&dt=usV&ts=1203

Step 2 When prompted, log in with your Cisco.com user ID and password.

Step 3 (Optional) For information about a specific caveat, enter the bug ID number (*CSCxxxxxxx*) in the **Search for** field, and press **Enter**.

Open Caveats

The following list contains the severity 1, 2, and 3 defects that are open for the Cisco IP Phone 7800 Series Multiplatform Phones that use Firmware Release 12.0(3).

For more information about an individual defect, you can access the online history for the defect by accessing the Bug Search tool and entering the Identifier (*CSCxxxxxxx*). You must be a registered Cisco.com user to access this defect information.

Because the defect status continually changes, the list reflects a snapshot of the defects that were resolved at the time this report was compiled. For an updated view of the resolved defects or to view specific bugs, access the Bug Search Toolkit as described in the [View Caveats, on page 4](#).

- CSCwf10956—Macro \$SERVIP is not expanded in Log Request Msg in syslog.
- CSCwf70230—78xx is stripping leading "+" when dialling from the monitored line button without extension.

Resolved Caveats

The following list contains the severity 1, 2, and 3 defects that are resolved for the Cisco IP Phone 7800 Series Multiplatform Phones that use Firmware Release 12.0(3).

For more information about an individual defect, you can access the online history for the defect by accessing the Bug Search tool and entering the Identifier (*CSCxxxxxxx*). You must be a registered Cisco.com user to access this defect information.

Because the defect status continually changes, the list reflects a snapshot of the defects that were resolved at the time this report was compiled. For an updated view of the resolved defects or to view specific bugs, access the Bug Search Toolkit as described in the [View Caveats, on page 4](#).

- CSCvb85886—MPP-78xx:Press BLF SD PLK three times, phone still play tone while idle.
- CSCwd81572—Specific tones are not heard on speaker phone, but can be heard on the handset.
- CSCwd51776—Virtual extension number is not provided on MPP with "Webex Directory" contact search.
- CSCwd61181—Cisco MPP Phones reboots upon receiving "GetSoftKeys" API calls.
- CSCwd41757—Cisco MPP phones: Call is disconnected during a call.

- CSCvb83904—MPP-78XX phone's switch not change Cos value after extended Cos changes.
- CSCwf29727—Hard transfer button does not transfer 78XX MPP.
- CSCwf82386—Expiring SUDI/MIC in MPP phones.
- CSCwf29727—Hard transfer button does not transfer.
- CSCwh14446—MPP is losing registration randomly.
- CSCwf35777—Inbound caller ID issue.
- CSCwh20086—MPP restarts randomly while idle.

Cisco IP Phone Firmware Support Policy

For information on the support policy for phones, see the [Cisco IP Phone Firmware Support Policy](#).

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

THE SOFTWARE LICENSE AND LIMITED WARRANTY FOR THE ACCOMPANYING PRODUCT ARE SET FORTH IN THE INFORMATION PACKET THAT SHIPPED WITH THE PRODUCT AND ARE INCORPORATED HEREIN BY THIS REFERENCE. IF YOU ARE UNABLE TO LOCATE THE SOFTWARE LICENSE OR LIMITED WARRANTY, CONTACT YOUR CISCO REPRESENTATIVE FOR A COPY.

The following information is for FCC compliance of Class A devices: This equipment has been tested and found to comply with the limits for a Class A digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference when the equipment is operated in a commercial environment. This equipment generates, uses, and can radiate radio-frequency energy and, if not installed and used in accordance with the instruction manual, may cause harmful interference to radio communications. Operation of this equipment in a residential area is likely to cause harmful interference, in which case users will be required to correct the interference at their own expense.

The following information is for FCC compliance of Class B devices: This equipment has been tested and found to comply with the limits for a Class B digital device, pursuant to part 15 of the FCC rules. These limits are designed to provide reasonable protection against harmful interference in a residential installation. This equipment generates, uses and can radiate radio frequency energy and, if not installed and used in accordance with the instructions, may cause harmful interference to radio communications. However, there is no guarantee that interference will not occur in a particular installation. If the equipment causes interference to radio or television reception, which can be determined by turning the equipment off and on, users are encouraged to try to correct the interference by using one or more of the following measures:

- Reorient or relocate the receiving antenna.
- Increase the separation between the equipment and receiver.
- Connect the equipment into an outlet on a circuit different from that to which the receiver is connected.
- Consult the dealer or an experienced radio/TV technician for help.

Modifications to this product not authorized by Cisco could void the FCC approval and negate your authority to operate the product.

The Cisco implementation of TCP header compression is an adaptation of a program developed by the University of California, Berkeley (UCB) as part of UCB's public domain version of the UNIX operating system. All rights reserved. Copyright © 1981, Regents of the University of California.

NOTWITHSTANDING ANY OTHER WARRANTY HEREIN, ALL DOCUMENT FILES AND SOFTWARE OF THESE SUPPLIERS ARE PROVIDED "AS IS" WITH ALL FAULTS. CISCO AND THE ABOVE-NAMED SUPPLIERS DISCLAIM ALL WARRANTIES, EXPRESSED OR IMPLIED, INCLUDING, WITHOUT LIMITATION, THOSE OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE AND NON-INFRINGEMENT OR ARISING FROM A COURSE OF DEALING, USAGE, OR TRADE PRACTICE.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

All printed copies and duplicate soft copies of this document are considered uncontrolled. See the current online version for the latest version.

Cisco has more than 200 offices worldwide. Addresses and phone numbers are listed on the Cisco website at www.cisco.com/go/offices.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2023 Cisco Systems, Inc. All rights reserved.