



October 2021

- [What's New in This Release, on page 1](#)
- [What's Changed in this Release, on page 1](#)
- [Caveats, on page 1](#)

What's New in This Release

There are no new features in this release of Cisco Spaces.

What's Changed in this Release

Location Analytics

The following enhancements are made in the Cisco Spaces Dashboard:

- Visits having a duration of less than five minutes are excluded. This helps to exclude transient and transitory visitors, who contribute to inflating the visitor and visits count.
- Visits having a duration of more than 1440 minutes are excluded. This helps to exclude devices that are always on, and contribute to inflating the average duration metric.

Caveats

Caveats describe unexpected behavior in the Cisco Spaces application. The Resolved Caveats and Open Caveats sections list the caveats in this release.

The following information is provided for each caveat:

- Identifier: Each caveat is assigned a unique identifier (ID) with a pattern of CSCxxNNNNN, where *x* is any letter (a-z) and *N* is any number (0-9). These IDs are frequently referenced in Cisco documentation, such as Security Advisories, Field Notices, and other Cisco support documents. Cisco Technical Assistance Center (TAC) engineers or other Cisco staff can also provide you with the ID for a specific caveat.
- Description: A description of what is observed when the caveat occurs.

This section contains the following topics:

Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST) is a gateway to the Cisco bug-tracking system, which maintains a comprehensive list of defects and vulnerabilities in Cisco products and software. The BST provides you with detailed defect information about your products and software.

Open Caveats

There are no open caveats in this release of Cisco Spaces.

Resolved Caveats

This section lists the bugs that have been resolved in this release of Cisco Spaces.

Table 1: Cisco Spaces Resolved Caveats

Caveat Identifier	Caveat Description
CSCvu98859	Telemetry such as Button Click and Movement data gets reset to 18+ hours when applying new configuration
CSCvv16880	During gateway deployment workflow, the AP is sometimes erroneously categorized as <code>needs config mode</code> due to timing issues
CSCvz89535	Mapservice-Map import/sync is failed on re-importing the same file with location changes
CSCvz89525	Mapservice-Floor map image appeared as blank when the re-sync happened for the same DNAC map file