

Release Notes for Cisco Catalyst 9800 Series Wireless Controller, Cisco IOS XE Dublin 17.12.x

First Published: 2023-07-31

Last Modified: 2025-09-04

Release Notes for Cisco Catalyst 9800 Series Wireless Controller, Cisco IOS XE Dublin 17.12.x

Introduction to Cisco Catalyst 9800 Series Wireless Controllers

The Cisco Catalyst 9800 Series Wireless Controllers comprise next-generation wireless controllers (referred to as *controller* in this document) built for intent-based networking. The controllers use Cisco IOS XE software and integrate the radio frequency (RF) capabilities from Cisco Aironet with the intent-based networking capabilities of Cisco IOS XE to create a best-in-class wireless experience for your organization.

The controllers are enterprise ready to power your business-critical operations and transform end-customer experiences:

- The controllers come with high availability and seamless software updates that are enabled by hot and cold patching. This keeps your clients and services up and running always, both during planned and unplanned events.
- The controllers come with built-in security, including secure boot, run-time defenses, image signing, integrity verification, and hardware authenticity.
- The controllers can be deployed anywhere to enable wireless connectivity, for example, on an on-premise device, on cloud (public or private), or embedded on a Cisco Catalyst switch (for SDA deployments) or a Cisco Catalyst access point (AP).
- The controllers can be managed using Cisco Catalyst Center, programmability interfaces, for example, NETCONF and YANG, or web-based GUI or CLI.
- The controllers are built on a modular operating system. Open and programmable APIs enable the automation of your day zero to day *n* network operations. Model-driven streaming telemetry provides deep insights into your network and client health.

The controllers are available in multiple form factors to cater to your deployment options:

- Catalyst 9800 Series Wireless Controller Appliance
- Catalyst 9800 Series Wireless Controller for Cloud
- Catalyst 9800 Embedded Wireless Controller for a Cisco Switch



Note All the Cisco IOS XE programmability-related topics on the controllers are supported by DevNet, either through community-based support or through DevNet developer support. For more information, go to <https://developer.cisco.com>.



Note For information about the recommended Cisco IOS XE releases for Cisco Catalyst 9800 Series Wireless Controllers, see the documentation at:
<https://www.cisco.com/c/en/us/support/docs/wireless/catalyst-9800-series-wireless-controllers/214749-tac-recommended-ios-xe-builds-for-wirele.html>

What's New in Cisco IOS XE Dublin 17.12.6

There are no new features in this release.

What's New in Cisco IOS XE Dublin 17.12.5

There are no new features in this release.

What's New in Cisco IOS XE Dublin 17.12.4

There are no new features in this release.



Note Cisco recommends that you run the Cisco IOS XE 17.12.4ESW software (ESW13 or later) till the Cisco IOS XE 17.12.5 release is available. For information, see the [Download Cisco IOS® XE 17.12.4 ESW Images for 9800](#). Alternatively, the Cisco Catalyst Advantage users may run the Cisco IOS XE 17.12.4 FCS software, install ASP54 (or later), and all applicable SMUs to apply fixes for the following issues:

- [CSCwj93876](#)
 - [CSCwm33207](#)
 - [CSCwi78109](#)
-



Note From Cisco IOS XE 17.12.4 release onwards until the end of this release train, while the Cisco Wave 1 APs (Cisco Aironet 1700, 2700, and 3700 Series APs) can join the controller, note that Cisco TAC support is not available for these APs.

What's New in Cisco IOS XE Dublin 17.12.3

Table 1: New and Modified Software Features

Feature Name	Description and Documentation Link
Support for Cisco Catalyst 9163E Access Point and CW-ANT-D1-NS-00 Antenna on Cisco Catalyst 9163E Access Point	From this release, support for Cisco Catalyst 9163 Access Point and CW-ANT-D1-NS-00 Antenna on this access point is introduced. For more information, see Cisco Catalyst 9163E Access Point .
Automated Frequency Coordination (AFC) Support	<p>This release supports the Automated Frequency Coordination (AFC) feature, a coordination system in cloud, that allocates the channels and power levels to APs to operate in standard power mode in the 6-GHz frequency spectrum. To begin with, the feature will be available only in the U.S., subject to final approval from the FCC.</p> <p>Note The AFC support will be enabled in Cisco Catalyst 9800 Wireless Controllers running IOS-XE 17.12.3, through Cisco cloud-based software service, after a final approval is obtained from the FCC.</p> <p>The feature is supported in the following APs:</p> <ul style="list-style-type: none"> • Cisco Catalyst Wireless 9166D1 Access Point • Cisco Catalyst Wireless 9162I Series Access Point • Cisco Catalyst Wireless 9164I Series Access Point • Cisco Catalyst 9136 Series Access Point • Cisco Catalyst Wireless 9163E Access Point • Cisco Catalyst Wireless 9166I Access Point <p>For more information, see the chapter Automated Frequency Coordination.</p>
Cloud Monitoring for Catalyst Controllers	<p>The Cloud Monitoring for Catalyst Controllers feature helps to monitor controllers using the Meraki dashboard. Currently, this feature is in a limited customer beta and is not supported by Cisco TAC.</p> <p>For more information about this feature, see Cloud Monitoring for Catalyst.</p> <p>For further help, write to: c9800-dashboard-monitoring@external.cisco.com</p>
Electronic Shelf Label (ESL) Support Through Internal IoT Radio	This release supports Application Hosting (IOx App) on APs to access its internal IoT radio. The IOx App supports the capability to load custom or proprietary firmware onto the internal IoT radio. For example, running third-party proprietary firmware on the AP's IoT radio for ESL.

Feature Name	Description and Documentation Link
Support for Automatic Log Deletion for Wireless	<p>The Automatic Log Deletion feature allows you to delete entries from the logging buffer automatically after a configurable time. You must configure the local syslog retention period after which the entries are purged from the device. This feature also allows one buffer clean up per day, which cleans the buffer log based on the configured duration every 24 hours.</p> <p>The following command is introduced as part of this feature:</p> <ul style="list-style-type: none"> • logging purge-log buffer days <p>For more information about the command, see https://www.cisco.com/c/en/us/td/docs/wireless/controller/9800/17-12/cmd-ref/b_wl_17_12_cr/configuration-commands-g-to-z.html#wp1458580136.</p>
Cisco Catalyst 9800 Wireless Controller for Cloud - Ultra-Low Profile	<p>The Cisco Catalyst 9800 Wireless Controller for Private Cloud - Ultra-Low Profile is introduced to cater to the Cisco FlexConnect deployment mode, targeting a maximum of 100 APs and 1000 clients; and compute resource requirements of two virtual Central Processing Units (vCPUs), 6-GB RAM, and 16-GB hard disk.</p> <p>The supported private cloud providers are VMware ESXi, KVM, Hyper-V, and Cisco NFVIS (on ENCS).</p> <p>For more information, see <i>Cisco Catalyst 9800-CL Cloud Wireless Controller Installation Guide</i>.</p>
AP Power Distribution Support for Cisco Catalyst 9162 Series Access Points	<p>From this release, AP power distribution is supported in Cisco Catalyst 9162 Series APs. This allows the network administrator to determine how the AP radios operate when it is powered with less than 30W.</p>

What's New in Cisco IOS XE Dublin 17.12.2

From this release, Layer 2 VRF is also supported with WGB, RADSEC, and TRUSTSEC capabilities. However, RLAN is not supported with VRF. For more information, see [Remote LANs](#).

What's New in Cisco IOS XE Dublin 17.12.1

Table 2: New and Modified Software Features

Feature Name	Description and Documentation Link
Access Point Auto Location Support	<p>This feature enables support for Access Point Auto Location, which helps to effectively self-locate APs on a map by combining various ranging technologies and algorithms. This feature requires the use of Cisco Spaces to interpret the AP location information and place the APs on maps.</p> <p>The following commands are introduced:</p> <ul style="list-style-type: none">• ap geolocation derivation ranging• geolocation ftm initiator burst-size• geolocation ftm initiator burst-duration• ap name ap-name floor• ap geolocation ranging all accurate• ap geolocation ranging site ap-site-tag accurate• show ap geolocation ranging <p>Note Fine Timing Measurement (FTM) ranging is a disruptive process and may cause disturbances in radio. We recommend that you run FTM ranging during offpeak or quiet hours.</p> <p>FTM ranging is not supported with FRA (dual 5G) operation.</p> <p>For more information, see AP Management.</p>

Feature Name	Description and Documentation Link
Modified Trustpoints for Secure Unique Device Identity (SUDI) Certificates	

Feature Name	Description and Documentation Link
	<p>From Cisco IOS XE Dublin 17.12.1 onwards, the following changes have been introduced for trustpoints:</p> <ul style="list-style-type: none"> Trustpoint names for existing SUDI certificates <p>If your device supports Cisco Manufacturing CA III certificate and is not disabled, the trustpoint names are as follows:</p> <ul style="list-style-type: none"> For <i>Cisco Manufacturing CA III</i> certificate, the trustpoint name has changed from CISCO_IDEVID_SUDI to CISCO_IDEVID_CMCA3_SUDI For <i>Cisco Manufacturing CA SHA2</i> certificate, the trustpoint name has changed from CISCO_IDEVID_SUDI_LEGACY to CISCO_IDEVID_CMCA2_SUDI <p>If your device does not support Cisco Manufacturing CA III certificate or if the certificate is disabled using no platform sudi cmca3 command, the trustpoint names are as follows:</p> <ul style="list-style-type: none"> For <i>Cisco Manufacturing CA SHA2</i> certificate, the trustpoint name has changed from CISCO_IDEVID_SUDI to CISCO_IDEVID_CMCA2_SUDI For <i>Cisco Manufacturing CA</i> certificate, the trustpoint name has changed from CISCO_IDEVID_SUDI_LEGACY to CISCO_IDEVID_CMCA_SUDI <ul style="list-style-type: none"> Hardware SUDI certificates <ul style="list-style-type: none"> If your device supports <i>High Assurance SUDI CA</i> certificate, this certificate is loaded under CISCO_IDEVID_SUDI trustpoint. If your device does not support <i>High Assurance SUDI CA</i> certificate, <i>ACT2 SUDI CA</i> certificate is loaded under CISCO_IDEVID_SUDI trustpoint. show wireless management trustpoint command output <p>If Cisco Catalyst 9300 Series Switch is used with a Cisco Catalyst 9800 Series Wireless Controller for wireless deployments, the trustpoint name in the output of show wireless management trustpoint command is updated to the modified trustpoint name as mentioned previously.</p> <p>The following example shows a sample output of show wireless management trustpoint command. Note that if your device does not support Cisco Manufacturing CA III certificate or if the certificate is disabled, the Trustpoint Name in the following output displays CISCO_IDEVID_CMCA2_SUDI.</p> <pre>Device# show wireless management trustpoint Trustpoint Name : CISCO_IDEVID_CMCA3_SUDI Certificate Info : Available</pre>

Feature Name	Description and Documentation Link
	<p>Certificate Type : MIC Certificate Hash : <SHA1 - hash> Private key Info : Available FIPS suitability : Not Applicable</p> <ul style="list-style-type: none"> • show ip http server status command output <p>If you configure the trustpoint for the HTTP server as CISCO_IDEVID_SUDI, the output of show ip http server status command displays the operating trustpoint along with the configured trustpoint.</p> <p>The following example shows a sample output of show ip http server status command with both the configured and the operating trustpoint names. Note that if your device does not support Cisco Manufacturing CA III certificate or if the certificate is disabled, the operating trustpoint in the following output displays CISCO_IDEVID_CMCA2_SUDI.</p> <pre>Device# show ip http server status ... HTTP secure server trustpoint: CISCO_IDEVID_SUDI HTTP secure server operating trustpoint: CISCO_IDEVID_CMCA3_SUDI</pre>
Archive less than 1 day	The request platform software trace archive last command has been enhanced to archive all the trace logs relevant to all the processes running on a system.
Cisco Catalyst 9166D Series Wi-Fi 6E Access Point	<p>The Cisco Catalyst 9166D Series Wi-Fi 6E Access Point is an enterprise-class tri-band (2.4 GHz, 5 GHz, 6 GHz) indoor access point with integrated directional antennas. The AP supports full interoperability with leading 802.11ax and 802.11ac clients and a hybrid deployment with other APs and controllers.</p> <p>For a full listing of the AP's features and specifications, see the Cisco Catalyst 9166D Series Wi-Fi 6E Access Point Data Sheet.</p>
Cisco Catalyst 9800 Wireless Controller for Cloud - Ultra-Low Profile (Beta, No TAC Support)	<p>The ultra-low profile memory variant of the Catalyst 9800 Wireless Controller for Cloud comes with 4GB RAM and 2vCPUs and is deployed in a private cloud (supports ESXi, KVM, and NFVIS on ENCS hypervisors) as Infrastructure as a Service (IaaS). This controller can support up to 50 APs and 1000 clients.</p> <p>For more information and technical support, see the Cisco Catalyst 9800-CL Cloud Wireless Controller Installation Guide.</p>
Cisco Catalyst IW9167I Heavy Duty Access Point	<p>The Cisco Catalyst IW9167I Wi-Fi 6 Access Point is a heavy-duty tri-band (2.4 GHz, 5 GHz, 6 GHz ready) outdoor access point with integrated antennas.</p> <p>For a full listing of the AP's features and specifications, see the Cisco Catalyst IW9167 Heavy Duty Series Data Sheet.</p>

Feature Name	Description and Documentation Link
Ease of Debugging	<p>The following commands are introduced on the AP console to enable or disable the client debug bundle and to verify the client debug status:</p> <ul style="list-style-type: none"> • debug client-bundle start • show client-bundle status • debug client-bundle stop
Embedded Packet Capture Enhancement	<p>In this release, the Embedded Packet Capture (EPC) feature is enhanced to support increased buffer size, continuous capture, and filtering of multiple MAC addresses in one EPC session.</p> <p>The following commands are introduced:</p> <ul style="list-style-type: none"> • monitor capture epc-session-name buffer circular file • monitor capture epc-session-name continuous-capture • monitor capture epc-session-name inner mac <p>For more information, see Embedded Packet Capture.</p>
FIPS 140-3 compliance	<p>This release enables all Wave 2 APs to achieve FIPS 140-3 compliance, ensuring adherence to security standards. The Cisco Catalyst 9800 controllers, however, are FIPS 140-2 compliant.</p> <p>Caution Downgrading to versions below 17.12.1 can have a negative impact on Wave 2 APs in the following scenarios:</p> <ul style="list-style-type: none"> • When FIPS or WLANCC security modes are enabled. • When the ECDHE-RSA-AES128-GCM-SHA256 cipher suite is not selected for AP DTLS (by default it is selected). <p>Note There is no impact on the Cisco IOS AP models.</p> <p>The show wireless certification config command has been introduced to verify whether downgrade is impacted or not.</p> <p>For more information, see FIPS.</p>
Improve crash datacollection, kernel panics, out of memory	<p>A new command is introduced to limit the number of kernel core dumps collected on the AP:</p> <ul style="list-style-type: none"> • core-dump kernel limit

Feature Name	Description and Documentation Link
Indoor deployment support for UK -ROW domain on IW9167I and IW9167E	Indoor deployment for UK -ROW domain is supported on Cisco Catalyst IW9167I and IW9167E Heavy Duty Access Point from this release. For more information, see the Cisco Catalyst IW9167 Heavy Duty Series Software Configuration Guide . .
Intelligent Capture (iCAP) Hardening	This feature aims at making troubleshooting for wireless clients and APs easier. In this release, the following enhancements are made to the iCAP feature: <ul style="list-style-type: none"> • Anomaly Detection • RF Statistics The following commands are introduced: <ul style="list-style-type: none"> • icap subscription client anomaly-detection report-individual enable • icap subscription client anomaly-detection report-individual per-client throttle • icap subscription client anomaly-detection report-individual per-type throttle • ap name icap subscription client anomaly-detection report-individual enable • ap name icap subscription client anomaly-detection report-individual per-client throttle • ap name icap subscription client anomaly-detection report-individual per-type throttle For more information, see Intelligent Capture Hardening .
MacBook Analytics	This feature is supported on the controller when the MacBook device sends 11k action frames along with the model information. For more information, see Device Analytics .
Mesh Support in Cisco Catalyst 9130AX Series Access Points	From this release, mesh support is included in the Cisco Catalyst 9130AX Series Access Points. All traditional capabilities of mesh are included in the Cisco Catalyst 9130AX Series APs operating in Cisco IOS XE Dublin 17.12.1. For more information, see Mesh Access Points .
New Countries Supporting 6-GHz Radio Band	From this release, Australia, Brazil, Costa Rica, Honduras, Hong Kong, Japan, Jordan, Kenya, Malaysia, Morocco, New Zealand, Peru, Qatar, Saudi Arabia, and United Arab Emirates are added to the list of countries that supports 6-GHz radio band. For more information, see Regulatory Compliance Domain .

Feature Name	Description and Documentation Link
RF based Automatic Load Balancing	<p>The RF based Automatic AP Load Balancing feature uses Radio Resource Management (RRM) neighbor report-based AP grouping and load-balancing across WNCd instances.</p> <p>The following commands are introduced:</p> <ul style="list-style-type: none"> • ap neighborhood load-balance • ap neighborhood calendar-profile • wireless load-balance ap method rf • show ap neighborhood summary • show ap neighborhood details • show ap neighborhood • show ap neighborhood mac details • show ap neighborhood wncd <p>For more information, see RF based Automatic AP Load Balancing.</p>
Rogue Channel Width	<p>From this release, you can specify the channel width and the band for rogue detection.</p> <p>The following command is introduced:</p> <ul style="list-style-type: none"> • condition chan-width <p>For more information, see Radio Resource Management.</p>
Rogue PMF	<p>From this release, the controller will contain rogue APs with 802.11w Protected Management Frame (PMF) on centrally switched WLANs.</p> <p>The following commands are introduced:</p> <ul style="list-style-type: none"> • rogue detection containment pmf-denial • pmf-deauth <p>For more information, see Radio Resource Management.</p>
Software entropy enhancement for FIPS 140-3	<p>From Cisco IOS XE Dublin 17.12.1 onwards, Federal Information Processing Standard (FIPS) 140-3 is supported as a security standard to validate cryptographic modules.</p>

Feature Name	Description and Documentation Link
Support for Cisco Wave 1 Access Points	<p>Support for the following Cisco Wave 1 APs are introduced in this release:</p> <ul style="list-style-type: none"> • Cisco Aironet 1570 Series Access Point • Cisco Aironet 1700 Series Access Point • Cisco Aironet 2700 Series Access Point • Cisco Aironet 3700 Series Access Point <p>Note Feature support is the same as in Release 17.3.x. Features introduced in 17.4.1 or later are not supported on these APs in Release 17.12.1.</p>
VRF Support	<p>From this release, Virtual Routing and Forwarding (VRF) is supported.</p> <p>For more information, see VRF Support.</p>
Wakeup Threshold for AP Power Save Mode	<p>This feature enables you to define the client threshold in the AP power profile configuration to determine when an AP wakes up from the power save mode or enters the power save mode.</p> <p>The following command is introduced:</p> <ul style="list-style-type: none"> • power-save-client-threshold <p>For more information, see AP Management.</p>
Wireless Mesh Support for Cisco Software-Defined Access	<p>From this release, wireless mesh is supported on Cisco Software-Defined Access.</p> <p>The following commands are introduced:</p> <ul style="list-style-type: none"> • show ap name mesh roam history • show wireless mesh ap fabric summary

Table 3: New and Modified GUI Features

Feature Name	GUI Path
AP Location	<ul style="list-style-type: none"> • Configuration > Wireless > Wireless Global • Configuration > Tags & Profiles > AP Join
Configuring Transition Mode and Pure WPA3 (6-GHz) on the Same WLAN Profile	<ul style="list-style-type: none"> • Configuration > Tags & Profiles > WLANs
Rogue Channel Width	<ul style="list-style-type: none"> • Configuration > Security > Wireless Protection Policies > Rogue AP Rules

MIBs

The following MIBs are newly added or modified:

- AIRESpace-WIRELESS-CAPABILITY.my
- AIRESpace-WIRELESS-MIB.my
- CISCO-LWAPP-AP-CAPABILITY.my
- CISCO-LWAPP-CDP-CAPABILITY.my
- CISCO-LWAPP-DOT11-CAPABILITY.my
- CISCO-LWAPP-DOT11-CLIENT-CALIB-CAPABILITY.my
- CISCO-LWAPP-DOT11-CLIENT-CAPABILITY.my
- CISCO-LWAPP-DOWNLOAD-CAPABILITY.my
- CISCO-LWAPP-GUEST-LAN-CAPABILITY.my
- CISCO-LWAPP-IPV6-CAPABILITY.my
- CISCO-LWAPP-MESH-CAPABILITY.my
- CISCO-LWAPP-MESH-LINKTEST-CAPABILITY.my
- CISCO-LWAPP-MFP-CAPABILITY.my
- CISCO-LWAPP-MOBILITY-CAPABILITY.my
- CISCO-LWAPP-MOBILITY-EXT-CAPABILITY.my
- CISCO-LWAPP-QOS-CAPABILITY.my
- CISCO-LWAPP-QOS-MIB.my
- CISCO-LWAPP-REAP-CAPABILITY.my
- CISCO-LWAPP-RF-CAPABILITY.my
- CISCO-LWAPP-ROGUE-CAPABILITY.my
- CISCO-LWAPP-ROGUE-MIB.my
- CISCO-LWAPP-RRM-CAPABILITY.my
- CISCO-LWAPP-SI-CAPABILITY.my
- CISCO-LWAPP-TUNNEL-CAPABILITY.my
- CISCO-LWAPP-WLAN-CAPABILITY.my
- CISCO-LWAPP-WLAN-POLICY-CAPABILITY.my
- CISCO-LWAPP-WLAN-POLICY-MIB.my
- CISCO-LWAPP-WLAN-SECURITY-CAPABILITY.my
- CISCO-WIRELESS-HOTSPOT-CAPABILITY.my

Product Analytics

This feature allows for the collection of non-personal usage device systems information for Cisco products, which helps in continuous product improvements. This feature is supported on the Cisco Catalyst 9800 Series Wireless Controllers (9800-80, 9800-40, 9800-L, 9800-CL, CW9800M, and CW9800H1/H2). You can use the **pa** command to enable or disable this feature.

The following commands are introduced as part of this feature:

- **pa**
- **show product-analytics kpi**
- **show product-analytics report**
- **show product-analytics stats**



Note Turning off Smart Licensing Device Systems Information does not impact other Systems Information collection including from Cisco Catalyst Center or vManage.

Important: We are constantly striving to advance our products and services. Knowing how you use our products is key to accomplishing this goal. To that end, Cisco will collect device and licensing [Systems Information](#) through Cisco Smart Software Manager (CSSM) and other channels for product and customer experience improvement, analytics, and adoption. Cisco processes your data in accordance with the [General Terms and Conditions](#), the [Cisco Privacy Statement](#) and any other applicable agreement with Cisco. To modify your organization's preferences for device and licensing systems information, use the **pa** command. For more information, see [Cisco Catalyst 9800 Series Wireless Controller Command Reference](#).

For additional information on this feature, see [Wireless Product Analytics FAQ](#).

Behavior Changes

Behavior Change for Cisco IOS XE 17.12.6

- Controller displayed out-of-order packet issue with fragmented packets when Auto QoS was enabled. When a client tries to connect to an EAP-TLS-based SSID, during the certificate exchange, the client sends its device certificate. If the certificate is fragmented because it exceeds the MTU (1500), the fragments are observed to be sent out-of-order from the controller when Auto QoS is enabled.

With the change in behavior, the fragments are classified and applied with default action. For workarounds, refer to [CSCwo97886](#).

- The **ip proxy-arp** configuration is disabled by default under VLAN interfaces for the controller.
- For Cisco Aironet 1815T Series AP, from Cisco IOS XE 17.12.x, `.../storage/config.oep` was created beforehand as long as the AP is in OEAP mode.

With the change in behavior, once the AP boots in FlexConnect OEAP mode, it switches on the default OEAP DHCP server (dhcp0) as day 1 configuration.

- In the Mobility Data DTLS tunnel, DTLS encryption was enabled on Peer1 and disabled on Peer2, causing the mobility tunnel to be up. However, with the change in behavior, DTLS encryption is enabled on Peer1 and disabled on Peer2, causing the mobility tunnel to go down.
- The maximum supported RFIDs per WNCD for any platform has been increased to greater than 9601 RFIDs. The new value of the maximum RFID is platform dependent.
- When source-interface was configured under mDNS globally, this source-interface was chosen to send out mDNS packets. When the source-interface was not configured, then, the controller used wireless management interface (WMI) to send out the mDNS packets.

With the change in behavior, when source-interface is configured, the controller uses this configured source-interface to send out mDNS packets. When the source-interface is not configured,

- Option 1: Use SVI as the source-interface (if SVI of the intended VLAN is configured).
 - Option 2: If option 1 fails, use the default Wireless Management Interface (WMI).
- Authentication for AP with EAP fails if the password is more than 31 characters. With the change in behavior, password with more than 31 characters works successfully.
 - When you apply an AP tag configuration, ensure that the number of APs associated with a non-default site tag does not exceed the platform limit. The system allows these configurations, but APs exceeding the limit cannot join the network.

The configuration validator now checks for this condition and when more APs than the platform limit are associated with the same site tag, the configuration is not rejected.

- Cisco Catalyst 9105 AP bridges the RLAN traffic to a wrong VLAN.

To prevent this issue:

- Delete any unused VLAN from the FlexConnect profile.
- Run the **capwap ap erase all** command to clear the AP cache.

Behavior Change for Cisco IOS XE 17.12.1 to 17.12.5

- From Cisco IOS XE Dublin 17.12.2 onwards, 6-GHz radio band is not supported for Honduras country code (HN) in Cisco Catalyst 9136, 9162, 9164, and 9166 Series APs.
- From Cisco IOS XE Dublin 17.12.x, the Express Wi-Fi by Facebook feature is not supported.
- From Cisco IOS XE Dublin 17.12.2, the **show running-config wlan** command is modified. The *wlan_name* variable is removed.
- The following command output is modified for the KPIs for AP Health Via the Controller and AP feature:
 - **show ap name config general**
- The following command outputs are modified for the Configuring Transition Mode and Pure WPA3 (6 GHz) on the Same WLAN Profile feature:
 - **show wlan all**
 - **show wlan id**
 - **show wlan name**

- **show wlan summary**

- WPA2 should be disabled while WPA3, PMF and dot11ax are enabled to broadcast WLAN exclusively on 6-GHz band. WPA2 can be enabled when broadcasting on other bands, such as 2.4 and 5-GHz.
- The inner MAC filtering feature of Embedded Packet Capture (EPC), captures CAPWAP data fragments and CAPWAP control not filtered by MAC.
- When wireless interface is not available, the RMI +RP configuration on the Web UI is disabled.
- From this release, the **bssid-neighbor-stats interval** value has been changed from 1 to 180 seconds to 30 to 600 seconds. The default value is 180 seconds.
- From this release, the default console baud rate of the 802.11AX APs is changed from 9600 bps to 115200 bps.
- Both internal and external APs in NAT deployments must use different AP join profiles when CAPWAP Discovery Private and Public are enabled separately. This is applicable to APs upgraded to Cisco IOS XE Dublin 17.12.x and later.
- If you have configured CISCO_IDEVID_SUDI trustpoint in your configuration, you will need to replace it with CISCO_IDEVID_CMCA3_SUDI to avoid client connection and AP join issues. The reason for this change being the CISCO_IDEVID_SUDI changed from SW-SUDI certificate in previous releases to HW-SUDI certificate. The processing of HW-SUDI certificate is much slower than the SW-SUDI. Here, CISCO_IDEVID_CMCA3_SUDI is the new SW-SUDI certificate.
- From Cisco IOS XE Dublin 17.12.x onwards, in dual 5-GHz scenarios for 6-GHz capable APs in India country code (IN), the slot2 BSSID count transition is corrected from 7 to 0. Previously, it transitioned incorrectly from 7 to F. Check [CSCwo59295](#) for more details.

Interactive help

Interactive help is a user interface feature that

- provides step-by-step guidance within the application
- adapts instructions and walk-throughs to the user's context, and
- assists users in completing complex configurations or navigating the system.

Modes of starting the interactive Help

You can start the interactive help in the these ways.

- Hover over the blue flap at the right-hand corner of a window in the GUI and clicking **Interactive Help**.
- Click **Walk-me Thru** in the left pane of a window in the GUI.
- Click **Show me How** whenever displayed in the GUI. Clicking **Show me How** triggers a specific interactive help that is relevant to the context you are in.

For example, **Show me How** in **Configure > AAA** walks you through the various steps for configuring a RADIUS server. Choose **Configuration > Wireless Setup > Advanced** and click **Show me How** to trigger the interactive help that walks you through the steps relating to various kinds of authentication.

Additional troubleshooting information

If the WalkMe launcher is unavailable on Safari, modify the browser settings.

1. Choose **Preferences > Privacy**.
2. In the **Website tracking** section, uncheck the **Prevent cross-site tracking** check box to disable this action.
3. In the **Cookies and website data** section, uncheck the **Block all cookies** check box to disable this action.

Supported Hardware

The following table lists the supported virtual and hardware platforms. (See [Supported PIDs and Ports](#) for the list of supported modules.)

Table 4: Supported Virtual and Hardware Platforms

Platform	Description
Cisco Catalyst 9800-80 Wireless Controller	A modular wireless controller with up to 100-GE modular uplinks and seamless software updates. The controller occupies a 2-rack unit space and supports multiple module uplinks.
Cisco Catalyst 9800-40 Wireless Controller	A fixed wireless controller with seamless software updates for mid-size to large enterprises. The controller occupies a 1-rack unit space and provides four 1-GE or 10-GE uplink ports.
Cisco Catalyst 9800-L Wireless Controller	The Cisco Catalyst 9800-L Wireless Controller is the first low-end controller that provides a significant boost in performance and features.
Cisco Catalyst 9800 Wireless Controller for Cloud	A virtual form factor of the Catalyst 9800 Wireless Controller that can be deployed in a private cloud (supports VMware ESXi, Kernel-based Virtual Machine [KVM], Microsoft Hyper-V, and Cisco Enterprise NFV Infrastructure Software [NFVIS] on Enterprise Network Compute System [ENCS] hypervisors), or in the public cloud as Infrastructure as a Service (IaaS) in Amazon Web Services (AWS), Google Cloud Platform (GCP) marketplace, and Microsoft Azure.
Cisco Catalyst 9800 Embedded Wireless Controller for Switch	The Catalyst 9800 Wireless Controller software for the Cisco Catalyst 9000 switches brings the wired and wireless infrastructure together with consistent policy and management. This deployment model supports only Software Defined-Access (SDA), which is a highly secure solution for small campuses and distributed branches.

The following table lists the host environments supported for private and public cloud.

Table 5: Supported Host Environments for Public and Private Cloud

Host Environment	Software Version
VMware ESXi	<ul style="list-style-type: none"> • VMware ESXi vSphere 6.0, 6.5, 6.7, and 7.0 • VMware ESXi vCenter 6.0, 6.5, 6.7, and 7.0 • VMware ESXi vSphere 6.0, 6.5, 6.7, 7.0, and 8.0 • VMware ESXi vCenter 6.0, 6.5, 6.7, 7.0, and 8.0
KVM	<ul style="list-style-type: none"> • Linux KVM-based on Red Hat Enterprise Linux 7.6, 7.8, and 8.2 • Ubuntu 16.04.5 LTS, Ubuntu 18.04.5 LTS, Ubuntu 20.04.5 LTS
AWS	AWS EC2 platform
NFVIS	ENCS 3.8.1 and 3.9.1
GCP	GCP marketplace
Microsoft Hyper-V	Windows Server 2019, and Windows Server 2016 (Version 1607) with Hyper-V Manager (Version 10.0.14393)
Microsoft Azure	Microsoft Azure

The following table lists the supported Cisco Catalyst 9800 Series Wireless Controller hardware models.

The base PIDs are the model numbers of the controller.

The bundled PIDs indicate the orderable part numbers for the base PIDs that are bundled with a particular network module. Running the **show version**, **show module**, or **show inventory** command on such a controller (bundled PID) displays its base PID.

Note that unsupported SFPs will bring down a port. Only Cisco-supported SFPs (GLC-LH-SMD and GLC-SX-MMD) should be used on the route processor (RP) ports of C9800-80-K9 and C9800-40-K9.

Table 6: Supported PIDs and Ports

Controller Model	Description
C9800-CL-K9	Cisco Catalyst Wireless Controller as an infrastructure for cloud.
C9800-80-K9	Eight 1/10-Gigabit Ethernet SFP or SFP+ ports and two power supply slots.
C9800-40-K9	Four 1/10-Gigabit Ethernet SFP or SFP+ ports and two power supply slots.
C9800-L-C-K9	<ul style="list-style-type: none"> • 4x2.5/1-Gigabit ports • 2x10/5/2.5/1-Gigabit ports

Controller Model	Description
C9800-L-F-K9	<ul style="list-style-type: none"> • 4x2.5/1-Gigabit ports • 2x10/1-Gigabit ports

The following table lists the supported SFP models.

Table 7: Supported SFPs

SFP Name	C9800-80-K9	C9800-40-K9	C9800-L-C-K9	C9800-L-F-K9
COLORCHIP-C040-Q020-CWDM4-03B	Supported	—	—	—
DWDM-SFP10G-30.33	Supported	Supported	—	—
DWDM-SFP10G-61.41	Supported	Supported	—	—
FINISAR-LR – FTLX1471D3BCL 1	Supported	Supported	—	Supported
FINISAR-SR – FTLX8574D3BCL	Supported	Supported	—	Supported
FINISAR-FTL4C1QL2L	Supported	—	—	—
FINISAR-FTL4C1QE1C	Supported	—	—	—
GLC-BX-D	Supported	Supported	Supported	Supported
GLC-BX-U	Supported	Supported	Supported	Supported
GLC-EX-SMD	Supported	Supported	—	—
GLC-LH-SMD	Supported	Supported	Supported	—
GLC-SX-MMD	Supported	Supported	Supported	Supported
GLC-T	Supported	—	Supported	—
GLC-TE	Supported	Supported	Supported	Supported
GLC-ZX-SMD	Supported	Supported	Supported	Supported
QSFP-100G-LR4-S	Supported	—	—	—
QSFP-100G-SR4-S	Supported	—	—	—
QSFP-40G-BD-RX	Supported	—	—	—
QSFP-40G-CSR-S	Supported	—	—	—

SFP Name	C9800-80-K9	C9800-40-K9	C9800-L-C-K9	C9800-L-F-K9
QSFP-40G-ER4	Supported	—	—	—
QSFP-40G-LR4	Supported	—	—	—
QSFP-40G-LR4-S	Supported	—	—	—
QSFP-40G-SR-BD	Supported	—	—	—
QSFP-40G-SR4	Supported	—	—	—
QSFP-40G-SR4-S	Supported	—	—	—
QSFP-40GE-LR4	Supported	—	—	—
QSFP-H40G-ACU7M	Supported	—	—	—
SFP-10G-AOC10M	Supported	Supported	—	—
SFP-10G-AOC1M	Supported	Supported	—	—
SFP-10G-AOC2M	Supported	Supported	—	—
SFP-10G-AOC3M	Supported	Supported	—	—
SFP-10G-AOC5M	Supported	Supported	—	—
SFP-10G-AOC7M	Supported	Supported	—	—
SFP-10G-ER	Supported	Supported	—	—
SFP-10G-LR	Supported	Supported	—	Supported
SFP-10G-LR-S	Supported	Supported	—	Supported
SFP-10G-LR-X	Supported	Supported	—	Supported
SFP-10G-LRM	Supported	Supported	—	Supported
SFP-10G-SR	Supported	Supported	—	Supported
SFP-10G-SR-S	Supported	Supported	—	Supported
SFP-10G-SR-X	Supported	Supported	—	Supported
SFP-10G-ZR	Supported	Supported	—	—
SFP-H10GB-ACU10M	Supported	Supported	—	Supported
SFP-H10GB-ACU7M	Supported	Supported	—	Supported
SFP-H10GB-CU1.5M	Supported	Supported	—	Supported

SFP Name	C9800-80-K9	C9800-40-K9	C9800-L-C-K9	C9800-L-F-K9
SFP-H10GB-CU1M	Supported	Supported	—	Supported
SFP-H10GB-CU2.5M	Supported	Supported	—	Supported
SFP-H10GB-CU2M	Supported	Supported	—	Supported
SFP-H10GB-CU3M	Supported	Supported	—	Supported
SFP-H10GB-CU5M	Supported	Supported	—	Supported

¹ The FINISAR SFPs are not Cisco specific and some of the features, such as DOM, may not work properly.

Optics Modules

The Cisco Catalyst 9800 Series Wireless Controller supports a wide range of optics. The list of supported optics is updated on a regular basis. See the tables at the following location for the latest transceiver module compatibility information:

<https://www.cisco.com/c/en/us/support/interfaces-modules/transceiver-modules/products-device-support-tables-list.html>

Network Protocols and Port Matrix

Table 8: Cisco Catalyst 9800 Series Wireless Controller - Network Protocols and Port Matrix

Source	Destination	Protocol	Destination Port	Source Port	Description
Any	Cisco Catalyst 9800 Series Wireless Controller	TCP	22	Any	SSH
Any	Cisco Catalyst 9800 Series Wireless Controller	TCP	23	Any	Telnet
Any	Cisco Catalyst 9800 Series Wireless Controller	TCP	80	Any	HTTP
Any	Cisco Catalyst 9800 Series Wireless Controller	TCP	443	Any	HTTPS

Source	Destination	Protocol	Destination Port	Source Port	Description
Any	Cisco Catalyst 9800 Series Wireless Controller	UDP	161	Any	SNMP Agent
Any	Any	UDP	5353	5353	mDNS
Any	Cisco Catalyst 9800 Series Wireless Controller	UDP	69	69	TFTP
Any	DNS Server	UDP	53	Any	DNS
Any	Cisco Catalyst 9800 Series Wireless Controller	TCP	830	Any	NetConf
Any	Cisco Catalyst 9800 Series Wireless Controller	TCP	443	Any	REST API
Any	WLC Protocol	UDP	1700	Any	Receive CoA packets.
AP	Cisco Catalyst 9800 Series Wireless Controller	UDP	5246	Any	CAPWAP Control
AP	Cisco Catalyst 9800 Series Wireless Controller	UDP	5247	Any	CAPWAP Data
AP	Cisco Catalyst 9800 Series Wireless Controller	UDP	5248	Any	CAPWAP MCAST
AP	Cisco Catalyst Center	TCP	32626	Any	Intelligent capture and RF telemetry
AP	AP	UDP	16670	Any	Client Policies (AP-AP)

Source	Destination	Protocol	Destination Port	Source Port	Description
Cisco Catalyst 9800 Series Wireless Controller	Cisco Catalyst 9800 Series Wireless Controller	UDP	16666	16666	Mobility Control
Cisco Catalyst 9800 Series Wireless Controller	SNMP	UDP	162	Any	SNMP Trap
Cisco Catalyst 9800 Series Wireless Controller	RADIUS	UDP	1812/1645	Any	RADIUS Auth
Cisco Catalyst 9800 Series Wireless Controller	RADIUS	UDP	1813/1646	Any	RADIUS ACCT
Cisco Catalyst 9800 Series Wireless Controller	TACACS+	TCP	49	Any	TACACS+
Cisco Catalyst 9800 Series Wireless Controller	Cisco Catalyst 9800 Series Wireless Controller	UDP	16667	16667	Mobility
Cisco Catalyst 9800 Series Wireless Controller	NTP Server	UDP	123	Any	NTP
Cisco Catalyst 9800 Series Wireless Controller	Syslog Server	UDP	514	Any	SYSLOG
AP	Cisco Catalyst 9800 Series Wireless Controller	HTTPS	8443	Any	Out of Band AP Image Download Cisco CleanAir Spectral Capture
Cisco Catalyst 9800 Series Wireless Controller	NetFlow Server	UDP	9996	Any	NetFlow

Source	Destination	Protocol	Destination Port	Source Port	Description
Cisco Catalyst 9800 Series Wireless Controller	Cisco Connected Mobile Experiences (CMX)	UDP	16113	Any	NMSP
Cisco Catalyst Center	Cisco Catalyst 9800 Series Wireless Controller	TCP	32222	Any	Device Discovery
Cisco Catalyst Center	Cisco Catalyst 9800 Series Wireless Controller	TCP	25103	Any	Telemetry Subscriptions

Supported APs

The following Cisco APs are supported in this release.

Indoor Access Points

- Cisco Catalyst 9105AX (I/W) Access Points
- Cisco Catalyst 9115AX (I/E) Access Points
- Cisco Catalyst 9117AX (I) Access Points
- Cisco Catalyst 9120AX (I/E/P) Access Points
- Cisco Catalyst 9130AX (I/E) Access Points
- Cisco Catalyst 9136AX Access Points
- Cisco Catalyst 9162 (I) Series Access Points
- Cisco Catalyst 9164 (I) Series Access Points
- Cisco Catalyst 9166 (I/D1) Series Access Points
- Cisco Aironet 1815 (I/W/M/T), 1830 (I), 1840 (I), and 1852 (I/E) Access Points
- Cisco Aironet 1700 (I) Series Access Point
- Cisco Aironet 1800i Access Point
- Cisco Aironet 2700 (I/E) Series Access Point
- Cisco Aironet 2800 (I/E) Series Access Points
- Cisco Aironet 3700 (I/E/P) Series Access Point
- Cisco Aironet 3800 (I/E/P) Series Access Points
- Cisco Aironet 4800 (I) Series Access Points

Outdoor Access Points

- Cisco Aironet 1540 (I/D) Series Access Points
- Cisco Aironet 1560 (I/D/E) Series Access Points
- Cisco Aironet 1570 (I/D/E) Series Access Points
- Cisco Catalyst Industrial Wireless 6300 Heavy Duty Series Access Point
- Cisco 6300 Series Embedded Services Access Point
- Cisco Catalyst 9124AX (I/D/E) Access Points
- Cisco Catalyst 9163 (E) Series Access Points
- Cisco Catalyst Industrial Wireless 9167 (I/E) Heavy Duty Access Points
- Cisco Catalyst Industrial Wireless 9165E Rugged Access Point

Integrated Access Points

- Integrated Access Point on Cisco 1100 ISR (ISR-AP1100AC-x, ISR-AP1101AC-x, and ISR-AP1101AX-x)

Network Sensor

- Cisco Aironet 1800s Active Sensor

Pluggable Modules

- Cisco Wi-Fi Interface Module (WIM)

Supported Access Point Channels and Maximum Power Settings

Supported access point channels and maximum power settings on Cisco APs are compliant with the regulatory specifications of channels, maximum power levels, and antenna gains of every country in which the access points are sold. For more information about the supported access point transmission values in Cisco IOS XE software releases, see the *Detailed Channels and Maximum Power Settings* document at <https://www.cisco.com/c/en/us/support/ios-nx-os-software/ios-xe-17/products-technical-reference-list.html>.

For information about Cisco Wireless software releases that support specific Cisco AP modules, see the "Software Release Support for Specific Access Point Modules" section in the *Cisco Wireless Solutions Software Compatibility Matrix* document.

Compatibility Matrix

The following table provides software compatibility information. For more information, see [Cisco Wireless Solutions Software Compatibility Matrix](#)

Table 9: Compatibility Information

Cisco Catalyst 9800 Series Wireless Controller Software	Cisco Identity Services Engine	Cisco Prime Infrastructure	Cisco AireOS-IRCM Interoperability	Cisco Catalyst Center	Cisco CMX
Dublin 17.12.6	3.4 3.3 3.2 3.1 3.0 2.7 * all with latest patches	3.10.5 3.10.4 Update 03 3.10.4 Update 02	8.10.196.0 8.10.190.0 8.10.185.0 8.10.183.0 8.10.182.0 8.10.181.0 8.10.171.0 8.10.162.0 8.10.151.0 8.10.142.0 8.10.130.0 8.8.130.0 8.5.176.2 8.5.182.104	See Cisco Catalyst Center Compatibility Information	11.0.0, 11.0.1, 11.1.0 10.6.3
Dublin 17.12.5	3.4 3.3 3.2 3.1 3.0 2.7 * all with latest patches	3.10.5 3.10.4 Update 03 3.10.4 Update 02	8.10.196.0 8.10.190.0 8.10.185.0 8.10.183.0 8.10.182.0 8.10.181.0 8.10.171.0 8.10.162.0 8.10.151.0 8.10.142.0 8.10.130.0 8.8.130.0 8.5.176.2 8.5.182.104	See Cisco Catalyst Center Compatibility Information	11.0.0, 11.0.1, 11.1.0 10.6.3

Cisco Catalyst 9800 Series Wireless Controller Software	Cisco Identity Services Engine	Cisco Prime Infrastructure	Cisco AireOS-IRCM Interoperability	Cisco Catalyst Center	Cisco CMX
Dublin 17.12.4	3.4 3.3 3.2 3.1 3.0 2.7 * all with latest patches	3.10.5 3.10.4 Update 03 3.10.4 Update 02	8.10.196.0 8.10.190.0 8.10.185.0 8.10.183.0 8.10.182.0 8.10.181.0 8.10.171.0 8.10.162.0 8.10.151.0 8.10.142.0 8.10.130.0 8.8.130.0 8.5.176.2 8.5.182.104	See Cisco Catalyst Center Compatibility Information	11.0.0, 11.0.1, 11.1.0 10.6.3
Dublin 17.12.3	3.2 3.1 3.0 2.7 * all with latest patches	3.10.5 3.10.4 Update 03 3.10.4 Update 02	8.10.196.0 8.10.190.0 8.10.185.0 8.10.183.0 8.10.182.0 8.10.181.0 8.10.171.0 8.10.162.0 8.10.151.0 8.10.142.0 8.10.130.0 8.8.130.0 8.5.176.2 8.5.182.104	See Cisco Catalyst Center Compatibility Information	11.0.0, 11.0.1, 11.1.0 10.6.3

Cisco Catalyst 9800 Series Wireless Controller Software	Cisco Identity Services Engine	Cisco Prime Infrastructure	Cisco AireOS-IRCM Interoperability	Cisco Catalyst Center	Cisco CMX
Dublin 17.12.2	3.2 3.1 3.0 2.7 * all with latest patches	3.10.5 3.10.4 Update 03 3.10.4 Update 02	8.10.196.0 8.10.190.0 8.10.185.0 8.10.183.0 8.10.182.0 8.10.181.0 8.10.171.0 8.10.162.0 8.10.151.0 8.10.142.0 8.10.130.0 8.8.130.0 8.5.176.2 8.5.182.104	See Cisco Catalyst Center Compatibility Information	11.0.0 10.6.3

Cisco Catalyst 9800 Series Wireless Controller Software	Cisco Identity Services Engine	Cisco Prime Infrastructure	Cisco AireOS-IRCM Interoperability	Cisco Catalyst Center	Cisco CMX
Dublin 17.12.1	3.2 3.1 3.0 2.7 * all with latest patches	3.10.6 3.10.5 3.10.4 Update 03 3.10.4 Update 02 (base version) Note Base release of Cisco Prime Infrastructure that supports corresponding Cisco Catalyst 9800 Series Wireless Controller platform release and its features.	8.10.196.0 8.10.190.0 8.10.185.0 8.10.183.0 8.10.182.0 8.10.181.0 8.10.171.0 8.10.162.0 8.10.151.0 8.10.142.0 8.10.130.0 8.8.130.0 8.5.176.2 8.5.182.104	See Cisco Catalyst Center Compatibility Information	11.0.0 10.6.3

GUI System Requirements

The following subsections list the hardware and software required to access the Cisco Catalyst 9800 Controller GUI.

Table 10: Hardware Requirements

Processor Speed	DRAM	Number of Colors	Resolution	Font Size
233 MHz minimum ²	512 MB ³	256	1280 x 800 or higher	Small

² We recommend 1 GHz.

³ We recommend 1-GB DRAM.

Software Requirements

Operating Systems:

- Windows 7 or later
- Mac OS X 10.11 or later

Browsers:

- Google Chrome: Version 59 or later (on Windows and Mac)
- Microsoft Edge: Version 40 or later (on Windows)
- Safari: Version 10 or later (on Mac)
- Mozilla Firefox: Version 60 or later (on Windows and Mac)



Note Firefox Version 63.x is not supported.

The controller GUI uses Virtual Terminal (VTY) lines for processing HTTP requests. At times, when multiple connections are open, the default number of VTY lines of 15 set by the device might get exhausted. Therefore, we recommend that you increase the number of VTY lines to 50.

To increase the VTY lines in a device, run the following commands in the following order:

1. **device#** configure terminal
2. **device(config)#** line vty 50
A best practice is to configure the service tcp-keepalives to monitor the TCP connection to the device.
3. **device(config)#** service tcp-keepalives-in
4. **device(config)#** service tcp-keepalives-out

Before You Upgrade

Ensure that you familiarize yourself with the following points before proceeding with the upgrade:

- When you upgrade from Cisco IOS XE 17.9.5 or 17.12.2 to Cisco IOS XE 17.15.x, the controller WebUI does not support images greater than 1.5 GB.

Workaround:

- Upgrade using the CLI commands, or,
- Upgrade to a fixed release first, and then upgrade to 17.15.x.
- When you upgrade from Cisco IOS XE Dublin 17.12.3 to 17.12.4 or Cisco IOS XE 17.15.1, the Cisco Catalyst Wi-Fi 6 APs fail to upgrade the AP image.

Workaround:

- Reboot the impacted APs through the power cycle.

For more information, see [CSCwm08044](#)

**Caution**

During controller upgrade or reboot, if route processor ports are connected to any Cisco switch, ensure that the route processor ports are not flapped (shut/no shut process). Otherwise, it may lead to a kernel crash.

- ISSU feature is supported only within and between major releases, for example, 17.3.x (within a release) and 17.3.x to 17.6.x (among major releases).
- Controller upgrade from Cisco IOS XE Bengaluru 17.3.x to Cisco IOS XE Bengaluru 17.6.x or Cisco IOS XE Cupertino 17.9.x or later using ISSU may fail if the **domain** command is configured. Ensure that you run the **no domain** command before starting an ISSU upgrade because the **domain** command has been removed from Cisco IOS XE Bengaluru 17.6.x.
- Controller upgrade from Cisco IOS XE Bengaluru 17.3.x to any release using ISSU may fail if the **snmp-server enable traps hsrp** command is configured. Ensure that you remove the **snmp-server enable traps hsrp** command from the configuration before starting an ISSU upgrade because the **snmp-server enable traps hsrp** command has been removed from Cisco IOS XE Bengaluru 17.4.x.
- Controller upgrade to Cisco IOS XE Dublin 17.12.x from any prior release using ISSU may fail if the **snmp-server enable traps license** command is configured. Ensure that you remove the **snmp-server enable traps license** command from the configuration before starting an ISSU upgrade because the **snmp-server enable traps license** command has been removed from Cisco IOS XE Dublin 17.12.x.
- Rolling AP upgrade, which is a part of the ISSU feature, is not supported for mesh APs.
- Ensure that you add Authentication and Key Management (AKM) setting when you configure WPA3. In older releases, this scenario was not mandatory which resulted in an invalid configuration. However, from 17.9 and higher releases, this invalid scenario is detected and prevented.

Cisco Wave 2 APs may get into a boot loop when upgrading software over a WAN link. For more information, see: <https://www.cisco.com/c/en/us/support/docs/wireless/catalyst-9800-series-wireless-controllers/220443-how-to-avoid-boot-loop-due-to-corrupted.html>.

The following Wave 1 APs are not supported from 17.4 to 17.9.2, 17.10.x, 17.11.x, 17.13.x, 17.14.x, and 17.15.x:

- Cisco Aironet 1570 Series Access Point
- Cisco Aironet 1700 Series Access Point
- Cisco Aironet 2700 Series Access Point
- Cisco Aironet 3700 Series Access Point

**Note**

- Support for the above APs was reintroduced from Cisco IOS XE Cupertino 17.9.3.
- Support for these APs does not extend beyond the normal product lifecycle support. Refer to the individual End-of-Support bulletins on Cisco.com.
- Feature support is on parity with the 17.3.x release. Features introduced in 17.4.1 or later are not supported on these APs in the 17.9.3 release.
- You can migrate directly to 17.9.3 from 17.3.x, where x=4c or later.

- From Cisco IOS XE Dublin 17.10.x, Key Exchange and MAC algorithms like diffie-hellman-group14-sha1, hmac-sha1, hmac-sha2-256, and hmac-sha2-512 are not supported by default and it may impact some SSH clients that only support these algorithms. If required, you can add them manually. For information on manually adding these algorithms, see the **SSH Algorithms for Common Criteria Certification** document available at: https://www.cisco.com/c/en/us/td/docs/routers/ios/config/17-x/sec-vpn/b-security-vpn/m_sec-secure-shell-algorithm-ccc.html
- If APs fail to detect the backup image after running the **archive download-sw** command, perform the following steps:
 1. Upload the image using the **no-reload** option of the **archive download-sw** command:

```
Device# archive download-sw /no-reload tftp://<tftp_server_ip>/<image_name>
```
 2. Restart the CAPWAP process using **capwap ap restart** command. This allows the AP to use the correct backup image after the restart (reload is not required.)

```
Device# capwap ap restart
```

**Caution**

The AP will lose connection to the controller during the join process. When the AP joins the new controller, it will see a new image in the backup partition. So, the AP will not download a new image from the controller.

- Fragmentation lower than 1500 is not supported for the RADIUS packets generated by wireless clients in the Gi0 (OOB) interface.
- Cisco IOS XE allows you to encrypt all the passwords used on the device. This includes user passwords and SSID passwords (PSK). For more information, see the "Password Encryption" section of the [Cisco Catalyst 9800 Series Configuration Best Practices](#) document.
- While upgrading to Cisco IOS XE 17.3.x and later releases, if the **ip http active-session-modules none** command is enabled, you will not be able to access the controller GUI using HTTPS. To access the GUI using HTTPS, run the following commands in the order specified below:
 1. **ip http session-module-list pkilist OPENRESTY_PKI**
 2. **ip http active-session-modules pkilist**
- Cisco Aironet 1815T OfficeExtend Access Point will be in local mode when connected to the controller. However, when it functions as a standalone AP, it gets converted to FlexConnect mode.

- The Cisco Catalyst 9800-L Wireless Controller may fail to respond to the BREAK signals received on its console port during boot time, preventing users from getting to the ROMMON. This problem is observed on the controllers manufactured until November 2019, with the default config-register setting of 0x2102. This problem can be avoided if you set config-register to 0x2002. This problem is fixed in the 16.12(3r) ROMMON for Cisco Catalyst 9800-L Wireless Controller. For information about how to upgrade the ROMMON, see the Upgrading ROMMON for Cisco Catalyst 9800-L Wireless Controllers section of the [Upgrading Field Programmable Hardware Devices for Cisco Catalyst 9800 Series Wireless Controllers](#) document.
- By default, the controller uses a TFTP block size value of 512, which is the lowest possible value. This default setting is used to ensure interoperability with legacy TFTP servers. If required, you can change the block size value to 8192 to speed up the transfer process, using the **ip tftp blocksize** command in global configuration mode.
- We recommend that you configure the **password encryption aes** and the **key config-key password-encrypt key** commands to encrypt your password.
- If the following error message is displayed after a reboot or system crash, we recommend that you regenerate the trustpoint certificate:

```
ERR_SSL_VERSION_OR_CIPHER_MISMATCH
```

Use the following commands in the order specified below to generate a new self-signed trustpoint certificate:

1. device# **configure terminal**
 2. device(config)# **no crypto pki trustpoint** *trustpoint_name*
 3. device(config)# **no ip http server**
 4. device(config)# **no ip http secure-server**
 5. device(config)# **ip http server**
 6. device(config)# **ip http secure-server**
 7. device(config)# **ip http authentication** *local/aaa*
- Do not deploy OVA files directly to VMware ESXi 6.5. We recommend that you use an OVF tool to deploy the OVA files.
 - Ensure that you remove the controller from Cisco Prime Infrastructure before disabling or enabling Netconf-YANG. Otherwise, the system may reload unexpectedly.
 - Unidirectional Link Detection (UDLD) protocol is not supported.
 - SIP media session snooping is not supported on FlexConnect local switching deployments.
 - The Cisco Catalyst 9800 Series Wireless Controllers (C9800-CL, C9800-L, C9800-40, and C9800-80) support a maximum of 14,000 leases with internal DHCP scope.
 - Configuring the mobility MAC address using the **wireless mobility mac-address** command is mandatory for both HA and 802.11r.
 - If you have Cisco Catalyst 9120 (E/I/P) and Cisco Catalyst 9130 (E) APs in your network and you want to downgrade, use only Cisco IOS XE Gibraltar 16.12.1t. Do not downgrade to Cisco IOS XE Gibraltar 16.12.1s.

- The following SNMP variables are not supported:
 - CISCO-LWAPP-WLAN-MIB: cLWlanMdnsMode
 - CISCO-LWAPP-AP-MIB.my: cLApDot11IfRptncPresent, cLApDot11IfDartPresent
- If you are upgrading from Cisco IOS XE Gibraltar 16.11.x or an earlier release, ensure that you unconfigure the *advipservices* boot-level licenses on both the active and standby controllers using the **no license boot level advipservices** command before the upgrade. Note that the **license boot level advipservices** command is not available in Cisco IOS XE Gibraltar 16.12.1s and 16.12.2s.
- The Cisco Catalyst 9800 Series Wireless Controller has a service port that is referred to as *GigabitEthernet 0* port.

The following protocols and features are supported through this port:

- Cisco Catalyst Center
 - Cisco Smart Software Manager
 - Cisco Prime Infrastructure
 - Telnet
 - Controller GUI
 - DNS
 - File transfer
 - GNMI
 - HTTP
 - HTTPS
 - LDAP
 - Licensing for Smart Licensing feature to communicate with CSSM
 - Netconf
 - NetFlow
 - NTP
 - RADIUS (including CoA)
 - Restconf
 - SNMP
 - SSH
 - SYSLOG
 - TACACS+
- During device upgrade using GUI, if a switchover occurs, the session expires and the upgrade process gets terminated. As a result, the GUI cannot display the upgrade state or status.

- From Cisco IOS XE Bengaluru 17.4.1 onwards, the telemetry solution provides a name for the receiver address instead of the IP address for telemetry data. This is an additional option. During the controller downgrade and subsequent upgrade, there is likely to be an issue—the upgrade version uses the newly named receivers, and these are not recognized in the downgrade. The new configuration gets rejected and fails in the subsequent upgrade. Configuration loss can be avoided when the upgrade or downgrade is performed from Cisco Catalyst Center.
- From Cisco IOS XE Bengaluru 17.4.1 onwards, session timeout under the policy profile is supported.
- Communication between Cisco Catalyst 9800 Series Wireless Controller and Cisco Prime Infrastructure uses different ports:
 - All the configurations and templates available in Cisco Prime Infrastructure are pushed through SNMP and CLI, using UDP port 161.
 - Operational data for controller is obtained over SNMP, using UDP port 162.
 - AP and client operational data leverage streaming telemetry:
 - Cisco Prime Infrastructure to controller: TCP port 830 is used by Cisco Prime Infrastructure to push the telemetry configuration to the controller (using NETCONF).
 - Controller to Cisco Prime Infrastructure: TCP port 20828 is used for Cisco IOS XE 16.10.x and 16.11.x, and TCP port 20830 is used for Cisco IOS XE 16.12.x, 17.1.x and later releases.
- The Cisco Centralized Key Management (CCKM) feature was deprecated in Cisco IOS XE 17.10.x, but currently remains supported. However, support for CCKM will be removed in a future release. Therefore, we recommend that you migrate to Fast Transition (FT) with 802.1X authentication and validate the configuration with supported key caching mechanisms.
- To migrate public IP address from 16.12.x to 17.x, ensure that you configure the **service internal** command. If you do not configure the **service internal** command, the IP address does not get carried forward.
- RLAN support with Virtual Routing and Forwarding (VRF) is not available.
- When you encounter the SNMP error *SNMP_ERRORSTATUS_NOACCESS 6*, it means that the specified SNMP variable is not accessible.
- We recommend that you perform a controller reload whenever there is a change in the controller's clock time to reflect an earlier time.



Note The DTLS version (DTLSv1.0) is deprecated for Cisco Aironet 1800 based on latest security policies. Therefore, any new out-of-box deployments of Cisco Aironet 1800 APs will fail to join the controller and you will get the following error message:

```
%APMGR_TRACE_MESSAGE-3-WLC_GEN_ERR: Chassis 1 R0/2: wncd: Error in AP Join, AP <AP-name>,
mac:<MAC-address>Model AIR-AP1815W-D-K9, AP negotiated unexpected DTLS version v1.0
```

To onboard new Cisco Aironet 1800 APs and to establish a CAPWAP connection, explicitly set the DTLS version to 1.0 in the controller using the following configuration:

```
config terminal
ap dtls-version dtls_1_0
end
```

Note that setting the DTLS version to 1.0 affects all the existing AP CAPWAP connections. We recommend that you apply the configuration only during a maintenance window. After the APs download the new image and join the controller, ensure that you remove the configuration.

To upgrade the field programmable hardware devices for Cisco Catalyst 9800 Series Wireless Controllers, see [Upgrading Field Programmable Hardware Devices for Cisco Catalyst 9800 Series Wireless Controllers](#).



Important Before you begin a downgrade process, you must manually remove the configurations which are applicable in the current version but not in older version. Otherwise, you might encounter an unexpected behavior.

- When you downgrade an AP from a higher version to Cisco IOS XE Amsterdam 17.3.x, the AP will not be accessible through SSH or the console due to the denial of the **enable** password, when the AP has not yet joined a controller. If the AP joins a controller, then the AP becomes accessible without any password denial.

Upgrade Path to Cisco IOS XE Dublin 17.12.x

Table 11: Upgrade Path to Cisco IOS XE Dublin 17.12.x

Current Software	Upgrade Path for Deployments with 9130 or 9124	Upgrade Path for Deployments Without 9130 or 9124
16.10.x	4	Upgrade first to 16.12.5 or 17.3.x and then to 17.12.x.
16.11.x	—	Upgrade first to 16.12.5 or 17.3.x and then to 17.12.x.
16.12.x	Upgrade first to 17.3.5 or later or 17.6.x or later, and then to 17.12.x.	Upgrade first to 17.3.5 or later or 17.6.x or later, and then to 17.12.x.
17.1.x	Upgrade first to 17.3.5 or later and then to 17.12.x.	Upgrade first to 17.3.5 or later and then to 17.12.x.

Current Software	Upgrade Path for Deployments with 9130 or 9124	Upgrade Path for Deployments Without 9130 or 9124
17.2.x	Upgrade first to 17.3.5 or later and then to 17.12.x.	Upgrade first to 17.3.5 or later and then to 17.12.x.
17.3.1 to 17.3.4	Upgrade first to 17.3.5 or later or 17.6.x or later, and then to 17.12.x.	Upgrade directly to 17.12.x.
17.3.4c or later	Upgrade directly to 17.12.x.	Upgrade directly to 17.12.x.
17.4.x	Upgrade first to 17.6.x and then to 17.12.x.	Upgrade directly to 17.12.x.
17.5.x	Upgrade first to 17.6.x and then to 17.12.x.	Upgrade directly to 17.12.x.
17.6.x	Upgrade directly to 17.12.x.	Upgrade directly to 17.12.x.
17.7.x	Upgrade directly to 17.12.x.	Upgrade directly to 17.12.x.
17.8.x	Upgrade directly to 17.12.x.	Upgrade directly to 17.12.x.
17.9.x	Upgrade directly to 17.12.x.	Upgrade directly to 17.12.x.
17.10.x	Upgrade directly to 17.12.x.	Upgrade directly to 17.12.x.
17.11.x	Upgrade directly to 17.12.x.	Upgrade directly to 17.12.x.
8.9.x or any 8.10.x version prior to 8.10.171.0	Upgrade first to 8.10.171.0 or later, 17.3.5 or later, or 17.6.x or later, and then to 17.12.x.	Upgrade directly to 17.12.x.
8.10.171.0 and above	Upgrade directly to 17.12.x.	Upgrade directly to 17.12.x.

⁴ The Cisco Catalyst 9130 and 9124 APs are not supported in 16.10.x and 16.11.x releases.

Upgrading the Controller Software

This section describes the various aspects of upgrading the controller software.

Finding the Software Version

The package files for the Cisco IOS XE software are stored in the system board flash device (flash:).

Use the **show version** privileged EXEC command to see the software version that is running on your controller.



Note Although the **show version** output always shows the software image running on the controller, the model name shown at the end of the output is the factory configuration, and does not change if you upgrade the software license.

Use the **show install summary** privileged EXEC command to see the information about the active package.

Use the **dir filesystem:** privileged EXEC command to see the directory names of other software images that you have stored in flash memory.

Software Images

- **Release:** Cisco IOS XE Dublin 17.12.x
- **Image Names (9800-80, 9800-40, and 9800-L):**
 - C9800-80-universalk9_wlc.17.12.x.SPA.bin
 - C9800-40-universalk9_wlc.17.12.x.SPA.bin
 - C9800-L-universalk9_wlc.17.12.x.SPA.bin
- **Image Names (9800-CL):**
 - **Cloud:** C9800-CL-universalk9.17.12.x.SPA.bin
 - **Hyper-V/ESXi/KVM:** C9800-CL-universalk9.17.12.x.iso, C9800-CL-universalk9.17.12.x.ova
 - **KVM:** C9800-CL-universalk9.17.12.x.qcow2
 - **NFVIS:** C9800-CL-universalk9.17.12.x.tar.gz

Software Installation Commands

Cisco IOS XE Dublin 17.12.x	
To install and activate a specified file, and to commit changes to be persistent across reloads, run the following command:	
device# install add file <i>filename</i> [activate [commit]	
To separately install, activate, commit, end, or remove the installation file, run the following command:	
device# install ?	
Note We recommend that you use the GUI for installation.	
add file tftp: <i>filename</i>	Copies the install file package from a remote location to a device, and performs a compatibility check for the platform and image versions.
activateauto-abort-timer]	Activates the file and reloads the device. The auto-abort-timer keyword automatically rolls back image activation.
commit	Makes changes that are persistent over reloads.
rollback to committed	Rolls back the update to the last committed version.
abort	Cancels file activation, and rolls back to the version that was running before the current installation procedure started.
remove	Deletes all unused and inactive software installation files.

Licensing

The Smart Licensing Using Policy feature is automatically enabled on the controller. This is also the case when you upgrade to this release. By default, your Smart Account and Virtual Account in Cisco Smart Software Manager (CSSM) are enabled for Smart Licensing Using Policy. For more information, see [Smart Licensing Using Policy](#).

For a more detailed overview on Cisco Licensing, see cisco.com/go/licensingguide.

Interoperability with Clients

This section describes the interoperability of the controller software with client devices.

The following table lists the configurations used for testing client devices.

Table 12: Test Configuration for Interoperability

Hardware or Software Parameter	Hardware or Software Type
Release	Cisco IOS XE Dublin 17.12.x
Cisco Wireless Controller	See Supported Hardware , on page 17.
Access Points	See Supported APs , on page 24.
Radio	<ul style="list-style-type: none"> • 802.11ax • 802.11ac • 802.11a • 802.11g • 802.11n • 802.11ax in 6GHz (Wi-Fi 6E)
Security	Open, PSK (WPA2-AES), 802.1X (WPA2-AES) (EAP-FAST, EAP-TLS) WPA3 AKM 802.11ax
RADIUS	See Compatibility Matrix , on page 25.
Types of tests	Connectivity, traffic (ICMP), and roaming between two APs

The following table lists the client types on which the tests were conducted. Client types included laptops, hand-held devices, phones, and printers.

Table 13: Client Types

Client Type and Name	Driver or Software Version
Laptops	
Acer Aspire E 15 E5-573-3870 (Qualcomm Atheros QCA9377)	Windows 10 Pro (12.0.0.832)
Apple Macbook Air 11 inch	macOS Sierra 10.12.6
Apple Macbook Air 13 inch	macOS High Sierra 10.13.4
Macbook Pro Retina	macOS Catalina
Macbook Pro Retina 13 inch early 2015	macOS Mojave 10.14.3
Macbook Pro OS X	macOS X 10.8.5
Macbook Air	macOS Sierra v10.12.2
Macbook Air 11 inch	macOS Yosemite 10.10.5
MacBook M1 Chip	macOS Catalina
MacBook M1 Chip	macOS Ventura 13.2.1
MacBook Pro M2 Chip	macOS Ventura 13.3 beta
MacBook Pro M2 Chip	macOS Ventura 13.1
MacBook Pro M2 Chip (6Ghz Supported client)	macOS Sonoma 14.0
Dell Inspiron 2020 Chromebook	Chrome OS 75.0.3770.129
Google Pixelbook Go	Chrome OS 97.0.4692.27
HP chromebook 11a	Chrome OS 76.0.3809.136
Samsung Chromebook 4+	Chrome OS 77.0.3865.105
Dell Latitude (Intel AX210)	Windows 11 (22.110.x.x)
Dell Latitude 3480 (Qualcomm DELL wireless 1820)	Win 10 Pro (12.0.0.242)
Dell Inspiron 15-7569 (Intel Dual Band Wireless-AC 3165)	Windows 10 Home (21.40.0)
Dell Latitude E5540 (Intel Dual Band Wireless AC7260)	Windows 7 Professional (21.10.1)
Dell Latitude E5430 (Intel Centrino Advanced-N 6205)	Windows 7 Professional (15.18.0.1)
Dell Latitude E6840 (Broadcom Dell Wireless 1540 802.11 a/g/n)	Windows 7 Professional (6.30.223.215)
Dell XPS 12 v9250 (Intel Dual Band Wireless AC 8260)	Windows 10 Home (21.40.0)
Dell Latitude 5491 (Intel AX200)	Windows 10 Pro (21.20.1.1)

Client Type and Name	Driver or Software Version
Dell XPS Latitude 12 9250 (Intel Dual Band Wireless AC 8260)	Windows 10 Home
Dell Inspiron 13-5368 Signature Edition	Windows 10 Home (18.40.0.12)
FUJITSU Lifebook E556 Intel 8260 (Intel Dual Band Wireless-AC 8260 (802.11n))	Windows 8 (19.50.1.6)
Lenovo Yoga C630 Snapdragon 850 (Qualcomm AC 2x2 Svc)	Windows 10 Home
Lenovo Thinkpad Yoga 460 (Intel Dual Band Wireless-AC 9260)	Windows 10 Pro (21.40.0)
Webex Room Bar Pro	RoomOS 11.5.2.4
Note For clients using Intel wireless cards, we recommend that you to update to the latest Intel wireless drivers if the advertised SSIDs are not visible.	
Tablets	
Apple iPad Pro (12 inch) 6th Gen	iOS 17 (beta)
Apple iPad Pro (12.9 inch) 6th Gen	iOS 16.4
Apple iPad Pro (11 inch) 4th Gen	iOS 16.4
Apple iPad 2021	iOS 15.0
Apple iPad 7th Gen 2019	iOS 14.0
Apple iPad MD328LL/A	iOS 9.3.5
Apple iPad 2 MC979LL/A	iOS 11.4.1
Apple iPad Air MD785LL/A	iOS 11.4.1
Apple iPad Air 11 4th Gen	iOS 16.4
Apple iPad Air2 MGLW2LL/A	iOS 10.2.1
Apple iPad Mini 4 9.0.1 MK872LL/A	iOS 11.4.1
Apple iPad Mini 2 ME279LL/A	iOS 11.4.1
Apple iPad Mini 4 9.0.1 MK872LL/A	iOS 11.4.1
Microsoft Surface Pro 3 13 inch (Intel AX201)	Windows 10 (21.40.1.3)
Microsoft Surface Pro 3 15 inch (Qualcomm Atheros QCA61x4A)	Windows 10
Microsoft Surface Pro 7 (Intel AX201)	Windows 10
Microsoft Surface Pro 6 (Marvell Wi-Fi chipset 11ac)	Windows 10
Microsoft Surface Pro X (WCN3998 Wi-Fi Chip)	Windows

Client Type and Name	Driver or Software Version
Mobile Phones	
Apple iPhone 5	iOS 12.4.1
Apple iPhone 6s	iOS 13.5
Apple iPhone 7 MN8J2LL/A	iOS 11.2.5
Apple iPhone 8	iOS 13.5
Apple iPhone 8 Plus	iOS 14.1
Apple iPhone 8 Plus MQ8D2LL/A	iOS 12.4.1
Apple iPhone X MQA52LL/A	iOS 13.1
Apple iPhone 11	iOS 15.1
Apple iPhone 12	iOS 16.0
Apple iPhone 12 Pro	iOS 15.1
Apple iPhone 13	iOS 15.1
Apple iPhone 13 Mini	iOS 15.1
Apple iPhone 13 Pro	iOS 15.1
Apple iPhone 14 Pro	iOS 17 (beta)
Apple iPhone 14	iOS 16.6
Apple iPhone SE MLY12LL/A	iOS 11.3
Apple iPhone SE	iOS 15.1
ASCOM i63	Build v 3.0.0
ASCOM Myco 3	Android 9
Cisco IP Phone 8821	11.0.6 SR4
Cisco CP-840S	Android 10 (Version 16.0.34190)
Cisco CP-860S	Android 10 (Version 16.0.34190)
Drager Delta	VG9.0.2
Drager M300.3	VG3.0
Drager M300.4	VG3.0
Drager M540	VG4.2
Google Pixel 3a	Android 11
Google Pixel 4	Android 11
Google Pixel 5	Android 11
Google Pixel 6	Android 12

Client Type and Name	Driver or Software Version
Google Pixel 7	Android 13
Huawei Mate 20 pro	Android 9.0
Huawei P20 Pro	Android 10
Huawei P40	Android 10
LG v40 ThinQ	Android 9.0
One Plus 8	Android 11
Oppo Find X2	Android 10
Redmi K20 Pro	Android 10
Samsung Galaxy S9+ - G965U1	Android 10.0
Samsung Galaxy S10 Plus	Android 11.0
Samsung S10 (SM-G973U1)	Android 11.0
Samsung S10e (SM-G970U1)	Android 11.0
Samsung Galaxy S20 Ultra	Android 10.0
Samsung Galaxy S21 Ultra 5G	Android 13.0
Samsung Galaxy S22 Ultra	Android 13.0
Samsung Fold 2	Android 10.0
Samsung Galaxy Z Fold 3	Android 13.0
Samsung Note20	Android 12.0
Samsung G Note 10 Plus	Android 11.0
Samsung Galaxy A01	Android 11.0
Samsung Galaxy A21	Android 10.0
Sony Xperia 1 ii	Android 11
Sony Xperia	Android 11
Xiaomi Mi 9T	Android 9
Xiaomi Mi 10	Android 11
Spectralink 84 Series	7.5.0.x257
Spectralink 87 Series	Android 5.1.1
Spectralink Versity Phones 92/95/96 Series	Android 10.0

Client Type and Name	Driver or Software Version
Spectralink Versity Phones 9540 Series	Android 8.1.0
Vocera Badges B3000n	4.3.3.18
Vocera Smart Badges V5000	5.0.6.35
Zebra MC40	Android 4.4.4
Zebra MC40N0	Android 4.1.1
Zebra MC92N0	Android 4.4.4
Zebra MC9090	Windows Mobile 6.1
Zebra MC55A	Windows 6.5
Zebra MC75A	OEM ver 02.37.0001
Zebra TC51	Android 6.0.1
Zebra TC52	Android 10.0
Zebra TC53	Android 11.0
Zebra TC55	Android 8.1.0
Zebra TC57	Android 10.0
Zebra TC58	Android 11.0
Zebra TC70	Android 6.1
Zebra TC75	Android 10.0
Zebra TC520K	Android 10.0
Zebra TC8000	Android 4.4.3
Printers	
Zebra QLn320 Mobile Printer	LINK OS 5.2
Zebra ZT230 IndustrialPrinter	LINK OS 6.4
Zebra ZQ310 Mobile Printer	LINK OS 6.4
Zebra ZD410 Industrial Printer	LINK OS 6.4
Zebra ZT410 Desktop Printer	LINK OS 6.2
Zebra ZQ610 Industrial Printer	LINK OS 6.4
Zebra ZQ620 Mobile Printer	LINK OS 6.4
Wireless Module	
Intel AX 411	Driver v22.230.0.8
Intel AX 211	Driver v22.230.0.8, v22.190.0.4
Intel AX 210	Driver v22.230.0.8, v22.190.0.4, v22.170.2.1

Client Type and Name	Driver or Software Version
Intel AX 200	Driver v22.130.0.5
Intel 11AC	Driver v22.30.0.11
Intel AC 9260	Driver v21.40.0
Intel Dual Band Wireless AC 8260	Driver v19.50.1.6
Samsung S21 Ultra	Driver v20.80.80
QCA WCN6855	Driver v1.0.0.901
PhoenixContact FL WLAN 2010	Firmware version: 2.71

Issues

Issues describe unexpected behavior in Cisco IOS releases in a product. Issues that are listed as Open in a prior release are carried forward to the next release as either Open or Resolved.



Note All incremental releases contain fixes from the current release.

Cisco Bug Search Tool

The Cisco [Bug Search Tool](#) (BST) allows partners and customers to search for software bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. The BST is designed to improve the effectiveness in network risk management and device troubleshooting. The tool has a provision to filter bugs based on credentials to provide external and internal bug views for the search input.

To view the details of an issue, click the corresponding identifier.

Open Caveats for Cisco IOS XE Dublin 17.12.6

Identifier	Headline
CSCwk79990	C9800-L encounters kernel unresponsiveness due to IntelResetRequest
CSCwp20385	Cisco Catalyst 9136 AP wired 0 interface gets stranded, and RX packets are not processed
CSCwp31397	Controller DFS Radar Detection results in most of the APs allocated to the same channel
CSCwq27429	17.9.3- Neighbors APs not seen on 9800-40 even though AP populates neighbor AP details
CSCwq89790	AP deletes client webauth pending at 300th sec when LWA init timer is more than 300 sec

Identifier	Headline
CSCwo09824	Cisco Wireless 9176 AP unable to join controller after GUAP
CSCwo89933	C9800 WLC zombie process \"date\" is not killed and exhausts available process ID, which leads to failures of other processes
CSCwp95190	9800 unable to handle new client connections due to memory failure
CSCwq60945	Access point data tunnel going to NULL state an unable to recover it as it incorrectly detects an existing session already in place
CSCwq73700	COS APs is not keeping manual Geolocation coordinates accross reboots
CSCwq79928	Daily Tracebacks Generated on 9800-80
CSCwq80342	AP with log "wlan_cfg80211_chan_tuple_set: ERROR!! Invalid combination of mode 28 11AHE40"

Open Caveats for Cisco IOS XE Dublin 17.12.5

Identifier	Headline
CSCwj80614	Clients are unable to connect due to assignment of IP address that is in use by stale client entry in device-tracking database in FlexConnect local switching
CSCwm73020	Controller relays unicast DHCP requests
CSCwn18885	Cisco Catalyst 9136 APs encounter kernel unresponsiveness silently with the last reload reason 'unknown' [SF 07624324]
CSCwn36778	Cisco Catalyst 9800-80 controller displays low memory leak potentially in the 'ipv4_addr' field
CSCwn81268	IOX-APP using USB in RUN state ends up in activated state after switch reload
CSCwn83970	Cisco Catalyst 9162 AP does not respond to probe and open auth request on 5GHz(#SF 07658283)
CSCwn89252	Cisco Catalyst 9120 AP running 17.15.2 does not install Solum IOX APP
CSCwj53257	Catalyst APs report 3600 seconds NOP timer on the last radar detected channel from DCA list
CSCwn31021	Controller fails to represent the correct format of AP Name and VLAN ID in option 82
CSCwn33501	Controller does not relay any output for all the APs connected for the #show ap summary sort name command
CSCwn40321	Cisco Catalyst 9120 AP intermittently handles dynamic BW from iOS devices with 11ax enabled
CSCwn46128	SNMP trap filters do not work

Identifier	Headline
CSCwn54374	Cisco Catalyst 9136 AP encounters kernel unresponsiveness
CSCwn55495	Cisco Catalyst 9800-40 controller displays random CPU spikes on EZMAN
CSCwn55534	IP theft is observed on the controller when the client receives a second DHCP offer following DORA

Open Caveats for Cisco IOS XE Dublin 17.12.4

Identifier	Headline
CSCwk14917	Controller unexpectedly reloads due to unresponsiveness
CSCwj39057	Cisco Catalyst 9130 AP observes traffic loss and delay due to channel utilization and interference
CSCwk03445	AP experiences slowness on 6-GHz band
CSCwj42305	Client is unable to connect due to delete reason NACK_IFID_EXISTS
CSCwk05809	CPUHOG traceback messages observed in Cisco IOS XE Dublin 17.12.2
CSCwj80614	Clients are unable to connect due to assignment of IP address that is in use by stale client entry in device-tracking database in FlexConnect local switching
CSCwj89538	Cisco Aironet 2802 Series AP unable to send reassociation and association requests
CSCwj99712	Controller unable to load broadcast counters under interface
CSCwk21570	Clients on FlexConnect are unable to pass traffic if rate-limiting AVP is missing
CSCwk07132	FlexConnect local switching client rate-limit pushed by AAA is applied per stream and not per client in Cisco IOS XE Dublin 17.12.3
CSCwi04855	AP repeatedly joins and disjoins controller with traceback
CSCwj83526	AP becomes non-operational when connected to Cisco Catalyst 9300 Switch via mGig port
CSCwh63050	Controller sends IGMP queries without IP address and MAC address on Cisco IOS XE Cupertino 17.9.3
CSCwj30587	CAPWAP messaging causes memory leak in WNCd
CSCwj93876	Controller reloads with reason "Critical process wncmgrd fault on rp_0_0 (rc=134)\\"
CSCwk32111	Controller generates -1 days messages even when registered using Air Gapped licensing
CSCwk17102	Missing M1 packet causes unexpected client disconnect and inability to reconnect with the controller
CSCwi42059	AP unable to join controller due to stale entries in Cisco IOS XE Cupertino 17.9.4

Identifier	Headline
CSCwj77042	Kernel panic is observed at "pc : splitmac_api_add_client+0x68/0x498 [umac]"
CSCwk58876	802.11AX APs end abnormally or fail to respond to AUTH frames
CSCwk79990	C9800-L-C ends abnormally due to IntelResetRequest

Open Caveats for Cisco IOS XE Dublin 17.12.3

Identifier	Headline
CSCwi99296	Cisco Catalyst 9120 AP encounters multiple kernel unresponsiveness accompanied by AP disconnection from the controller.
CSCwi40659	Clients in the same Remote LAN (RLAN) of different OEAPs cannot communicate with each other.
CSCwj03495	Cisco Aironet 1562 as Mesh AP (MAP) recognizes Cisco Catalyst 9124 Root AP (RAP) as a parent and completes authentication, but fails in the CAPWAP join because Mesh Adjacent messages are undetected by the RAP.
CSCwj05365	Cisco Catalyst 9115 AP encounters a kernel unresponsiveness.
CSCwh63050	Controller sends Internet Group Management Protocol (IGMP) queries without the controller's Internet Protocol (IP) address and Media Access Control (MAC) address.
CSCwi16509	Cisco Aironet 3802 AP disjoins with the error "Invalid radio slot id" and does not reconnect to the controller.
CSCwh52553	Cisco Catalyst 9105 AP encounters high utilization and performance issues due to high Multicast Domain Name System (mDNS) traffic.
CSCwj01916	Cisco Catalyst 9162 APs in FlexConnect mode frequently disconnect from the controller.
CSCvy50798	Cisco Catalyst 9124 AP is not visible in the controller's WebUI even after it is registered.
CSCwj08379	Controller becomes nonoperational when rogue Network-Assurance is enabled.
CSCwi04855	Cisco Catalyst 9115 APs join and disjoin the controller repeatedly with traceback.
CSCwi96176	Cisco Catalyst 9130 and 9166 APs connected to the controller show high channel utilization with one single client connected.
CSCwi91590	Cisco Catalyst 9130 and 9136 APs encounter kernel unresponsiveness due to a free Socket Buffer (skb).
CSCwi95945	Cisco Catalyst 9130 APs stop forwarding router advertisements after 4-6 hours of operation.
CSCwi99437	Clients fail to connect when BSSID is broadcast by Cisco Aironet 1850 APs, but succeed in connecting in the same scenario if it is Cisco Aironet 3800 AP.

Identifier	Headline
CSCwi54064	APs connected to the same controller classify each other as rogue and generate an "AP Impersonation" threat warning.
CSCwj00434	A Cisco Catalyst 2800 AP in Workgroup Bridge (WGB) mode gets stuck after a Dynamic Frequency Channel (DFS) channel change occurs on the controller with CleanAir enabled.
CSCwi56780	Mac Authentication Bypass (MAB) is not initiated unless the client device is deauthenticated.
CSCwi69696	Cisco Aironet 1815 AP encounters random drops in traffic towards wireless clients during normal AP operation.
CSCwj04146	Cisco Aironet 4800 AP does not send traffic over the air when using the 802.1X WLAN.
CSCwi96508	Cisco Wave 2 APs allowing SKC roam cause client deletion with the reason as INVALID_PMKID.
CSCwj32623	Standard power AP is operating on low power in a high density Wi-Fi network.

Open Caveats for Cisco IOS XE Dublin 17.12.2

Caveat ID	Description
CSCwf29762	Controller system not responsive due to null check in mDNS.
CSCwf93063	Intel Wi-Fi 6E AX210 client connection unresponsive after a few minutes of traffic with 1815 AP.
CSCwh18613	The encrypted pre-shared key of a wireless mesh network changes when the password encryption aes command is run.
CSCwh20239	Cisco Catalyst 9105 AP experiences WCPd restart when generating core.
CSCwh56147	SNMP OID for AP location tag is missing on the controller.
CSCwh58099	The controller allows the clients to reconnect only after client deletion and CoA termination.
CSCwh59543	Radio FW_1 and CAPWAPd unresponsive during scale longevitiy.
CSCwh63050	The controller is sending Internet Group Management Protocol (IGMP) queries with a non-IP address using MAC address in range of controller MAC addresses.
CSCwh67349	Cisco Aironet 3800 Series AP continuously unresponsive in CAPWAPd.
CSCwh68219	Clients are failing to authenticate via 802.1X using Extensible Authentication Protocol-Transport Layer Security Authentication (EAP-TLS).
CSCwh80060	Cisco 802.11ax APs connected to the controller are losing the Flex WLAN-VLAN mapping.

Caveat ID	Description
CSCwh92459	Controller unresponsive due to process WNCd fault on rp_0_0
CSCwh88100	Cisco Aironet 3800 Series AP : Kernel panic with PC at skb_unlink+0x40/0x54
CSCwh92425	Cisco Catalyst 9136 Series AP does not process power save mode in the 2.4-GHz band.
CSCwe93421	Cisco Catalyst 9115 Series Wi-Fi 6 APs intermittently stops transmitting multicast traffic downstream.
CSCwh29442	Cisco Catalyst 9800-40 Wireless Controller unresponsive after In-Service Software Upgrade (ISSU) upgrade.
CSCwh46368	Cisco Catalyst 9800-40 Wireless Controller device tracking binds BSSID MAC to wired IP address causing reachability issues.
CSCwh49467	AP is leaking multicast traffic to wrong Basic service set identifiers (BSSID).
CSCwh49810	Client loses network access after inter-WNCd roaming.
CSCwh62342	AP does not respond to the query even when the service provider is on its Multicast Domain Name System (mDNS) cache table.
CSCwh67342	Cisco Catalyst 9130AX Series AP is not able to join when Controller-Based Application Recognition (CBAR) is enabled on the controller.
CSCwh68948	Client is not able to get an IP address over fiber link in Cisco Aironet 1562 AP in FlexConnect local switching mode + local DHCP.
CSCwh74415	APs are not working in per client rate limit with FlexConnect local switching.
CSCwh75431	Cisco Aironet 1800 Series APs reporting false high channel utilization causing performance issues across the 5-GHz band.
CSCwh82580	Cisco Catalyst 9120AX Series unresponsive when Cisco Prime Infrastructure turns off 1 SSID via the Schedule SSID availability feature.
CSCwh89539	CAPWAP messages are queued for longer than x seconds with client throttling being turned on.
CSCwh60483	Cisco Catalyst 9136 Series AP shows abnormal temperature readings.
CSCwh49406	Cisco Catalyst 9130AX Series AP are spamming the syslog controllers with thousands of logs per second.
CSCwh95315	Cisco Catalyst IW9167 Heavy Duty Series AP is changing its backhaul upon reload.
CSCwh67285	Controller reboots and causes a switchover in High Availability environments.
CSCwh68360	Cisco Catalyst 9120AX Series: Kernel panic due to wlc_key_set_data.
CSCwh63270	Cisco Catalyst 9130AX Series APs unresponsive due to radio failure.
CSCwh87903	Cisco Catalyst 9120AX Series AP sending authentication response failure for specific client MAC addresses due to suppressed by MAC filter.

Caveat ID	Description
CSCwh81332	When the controller upgrades to 17.6.6, most of the connected APs gets unresponsive.
CSCwm95849	Cisco Catalyst 9136 AP does not receive the 6e SSID

Open Caveats for Cisco IOS XE Dublin 17.12.1

From this release, the list of caveats is displayed using BST tool. When you click the BST link, it opens a separate window and lists the bugs sorted by severity. You can filter it further using the options in the tool.

Click on the following link to view the Open Caveats: [BST Link](#)

Resolved Caveats for Cisco IOS XE Dublin 17.12.6

Identifier	Headline
CSCwj28408	BGL18 Alpha: EWLC HA is getting crashed during Image Activation
CSCwj80614	Clients are unable to connect due to assignment of IP address that is in use by stale client entry in device-tracking database in FlexConnect local switching
CSCwk82116	Sonic: Unable to add/delete VLAN under VLAN page
CSCwm57815	RF group name is empty after assigning AI RF profile to sites
CSCwm67254	Accounting start and stop messages are missing CUI attributes
CSCwm73020	Controller relays unicast DHCP requests
CSCwn36778	Cisco Catalyst 9800-80 controller displays low memory leak potentially in the 'ipv4_addr' field
CSCwn45380	Controller uses registry to initialize the trap queue length in SNMP
CSCwn83626	Client is stuck in association while changing WLAN from central switching profile to local profile
CSCwn90360	Controller is unable to start EAP process due to the delay of packet transmission from AP
CSCwn90874	Guest anchor controller shows error message when creating anchor-export-ACK
CSCwn92477	Controller unexpectedly reboots during WNCd process due to assertion failure with invalid BSSID
CSCwn92827	Secondary controller fails with rsync error
CSCwn98574	observing vrf name corrupt, causing client stuck at mobility while roaming and frequent disconnects
CSCwo02178	FT-SAE clients fails to roam between controller in same mobility group due to PMKID mismatch

Identifier	Headline
CSCwo35645	NETCONF over SSH fails to return all the records for wireless-client-oper and shows 'invalid XML' before everything is returned
CSCwo37680	Controller initiates client deletion with code: CO_CLIENT_DELETE_REASON_DOT11_MAX_STA
CSCwo60822	SJC Alpha eWLC always prints AP Image Predownload Successful even when it fails on some APs
CSCwo61286	Audit session ID changes after inter-WNCd roam on Central Web Authentication (CWA) with PSK
CSCwo62157	Controller with CAPWAP enabled display memory leak in tdl_mac_addr object
CSCwo62333	Cisco Catalyst 9800-L controller in FlexConnect/Software Defined Access (SDA) fails to start MAB on association request
CSCwo68664	Cisco Catalyst 9800-L controller in Software-Defined Access (SDA) Wireless does not enforce the Extensible Authentication Protocol (EAP) timeout
CSCwo70030	Rogue processing is performed by WNCd even though the "\"ssid-neighbor-stats\" configuration is disabled
CSCwo97161	Unable to push a large RPC config via Netconf over SSH
CSCwo97886	Controller display out of order packet issue with fragmented packet when AutoQOS is enabled
CSCwp07189	9800 WLC sending capwap control payload with DHCP_GW_NM payload to local mode APs
CSCwp13687	Cisco Catalyst 9800-CL controller modifies the script generating SSC to avoid issues with RSA key generation impacting AP join
CSCwp20530	Controller does not forward downstream packets to the wireless client after switchover
CSCwp26707	Controller fails to start L2 authentication for 11r clients with vlan-persistent configured in 17.12.5
CSCwp32113	Controller reloads due to kernel unresponsiveness with segmentation fault (11) in process IGMPSN
CSCwp65184	WLC crash after predownload initiated
CSCwp86129	Client connected to local mac-auth PSK or MPSK SSIDs get disconnected and do not remain connected to the controller
CSCwq30202	Frequent channel changes seen on 6GHz
CSCvy53719	Cisco Catalyst 9800-80 controller displays stale, non-impacting "\"mce: [Hardware Error]\" messages during IOS-XE 17.x boot-up

Identifier	Headline
CSCwf36148	Optimising the SISF code wrt to calling CO API to fetch the wireless client config info
CSCwh99327	APSP custom site filter config doesn't reflect in UI
CSCwi66855	Catalyst 9000 - Allow file uploads for files > 1GB
CSCwm09484	WNCD Crash in CiscoSSL Code
CSCwn31021	Controller fails to represent the correct format of AP Name and VLAN ID in option 82
CSCwn33501	Controller connected to the AP does not give any output while executing the #show ap summary sort name command
CSCwn45670	Controller GUI FlexConnect configuration page fails after upgrade to Cisco IOS XE 17.15.1
CSCwn56767	C9200 : Troubleshooting page does not load correctly on 17.12
CSCwn94159	Controller with 6 GHz support AP's radio channel bandwidth changes due to DCA happening frequently
CSCwo07767	Controller's active chassis get stuck in active recovery state on 17.12.4
CSCwo19011	Controller observes unexpected SISF reboot with WNCD core
CSCwo20395	Controller's rogue classification rules do not apply configured classifications
CSCwo21938	AFC is using manual geolocation co-ordinates
CSCwo29017	wncmgrd kernel unresponsiveness after issue command \u2018show ap config slots\u2019
CSCwo30925	Cisco Wi-Fi 6 and above APs do not support disabling WMM on radios that support 802.11n/11ac/11ax operation
CSCwo33572	Failed to collect RA tracing logs on Cisco IOS XE Release 17.9.5
CSCwo41248	Controller display wrong message when configuring 2 radios on the same UNII band (100 - 144)
CSCwo52310	Wireless cloud service consumes 100% CPU due to geolocation derivation
CSCwo64967	Mobility tunnel with data-link encryption intermittently disconnects when the fourth octet of the WMI address is 255
CSCwo66748	'cLApAssociatedClientCount' Object isn't working with 17.12.X
CSCwo67294	Controller unexpectedly reloads due to a corrupted value in IGMP Layer 2 Snooping process
CSCwo67413	Controller pushes aWIPS profiles from FQDN-only setup for intrusion detection

Identifier	Headline
CSCwo73753	C9800 not enforcing SGT policies for static/sxp tags on the same L2 network
CSCwo89539	Controller reload unexpectedly when adding "\"location civic-location-id\" to multiple interfaces
CSCwo98644	RRM does not update the default channel when using IPv6 only on the controller
CSCwp03988	Controller reloads unexpectedly due to unsuccessful copy of the MAC address
CSCwp06711	Controller overwrites the static AP location based on the Location Tag settings
CSCwp12959	Wireless clients may be excluded after one authentication failure or not excluded as expected
CSCwp16968	Client disconnection issue during fast roaming on WGB 1562 due to MAC address record mismatch
CSCwp20167	Access points- >Country code for "\" Philippines "\" misspelled as Philipines
CSCwp25552	BSSID-mac dispatched as 00:00:00:00:00:00 for slot 1 WLAN 1
CSCwp25836	Request for rpc support for dual band radio use-cases
CSCwp59171	Users unable to add allowed user on Lobby admin page
CSCwp64707	C9400 switch fails to provide "\"show running-config format netconf-xml\""
CSCwp93598	Memory leak found in the controller process related to handling a specific database string
CSCwp99623	C9800-CL Public Cloud VLAN Page In GUI Fails To Load
CSCwq19937	[17.18.1-SST] 9800 Webui Filter Does Not Contain filters does not work
CSCwi53615	The operation state of the 6Ghz radio goes down after enabling dual-band
CSCwj32611	AP kernel panic: "\"vmap allocation for size 2093056 failed: use vmalloc=< size > to increase size.\""
CSCwk09142	9136 AP radio crash on process Fatal error received from wcss software
CSCwn18885	Wi-Fi 6E and Wi-Fi 7 APs reboot with Access Violation without crash files, reload reason is unknown
CSCwn66225	Non-ROW AP transmits invalid TX power IE in beacons, breaking client connectivity
CSCwn81268	Due to switch reload when AP boots up, IOX-APP is starting before USB is detected
CSCwn88092	Unable to view the events for wireless clients in the Client 360 section of the Event Viewer
CSCwn89252	AP running 17.15.2 not possible to install Solum IOX APP
CSCwn92652	Radio ucode crashes seen in 9105 APs in monitor mode

Identifier	Headline
CSCwn96529	Cisco Catalyst 9136I-ROW AP in Site-Survey mode cannot add country code \"IN\"
CSCwo04380	Beacons stuck on Radio 1 on 9162 APs after upgrade to 17.12.4.158
CSCwo08220	CW9162I-E disjoining from WLC when ECDHE-RSA DTLS ciphersuite is activated
CSCwo58100	9130, and 916x APs on 17.12.x drop the EAP response coming from the AAA server
CSCwo61838	Cisco Catalyst 9120 / 17.12.4 ESW13 encounters kernel unresponsiveness due to OOM process gRPC
CSCwo68312	Cisco Catalyst 9124AXE-E APs identifies antennas wrongly
CSCwo69382	Need to remove Airdrop from the awips signature file on COS APs
CSCwp07242	Cisco Catalyst 9105 AP stops acking frames due to rxstuck
CSCwp38822	9166 will not allow 802.1x QoS WLAN markers/VAP but will Open and PSK
CSCwp59643	COS AP Crash due to Soft lockup and Null pointer dereference in 17.12.4
CSCwp61910	C9130AX - RHL driver bootup failure causes sh crash, which triggers kernel panic
CSCwp62799	C9130AX - RHL bootup failure due to Wbpll handshake failure
CSCwp99685	C9800 WLAN clients stuck in S_AUTHIF_ADD_MOBILE_ACK_WAIT_KM
CSCwq51138	SDA: AP Flooding SSDP Packets on L2-only VLAN with Wireless Pool Enabled
CSCwh80118	Couldnt convert the AP to WGB mode after factory reset to default
CSCwj40021	WLC 9800 AP hostname not displayed completely in out bound syslogs
CSCwj72174	AP2800 connected to same controller is detected as Rogue by other connected AP2800s
CSCwn61711	AP912X: wlc_dpc:506: PSM microcode watchdog fired;
CSCwn66085	Increased radar detection DFS events on 9166I-ROW APs after upgrading to 17.15.1
CSCwn91637	9800-80 running 17.12 9136 is working in quad-radio mode and not able to disable it
CSCwn92047	Cisco Catalyst 9105 Access Point controller fails to start after reboot when internal AP is configured as 802.1X supplicant
CSCwn99070	Radio core fails to generate properly causing operational issues
CSCwo05017	Cisco Catalyst 9162 Access Point experiences out-of-memory reset due to unbounded /tmp usage causing system instability
CSCwo08563	SFTP copy not working with IPv6 on COS APs
CSCwo14129	Wave 2 APs experience unresponsiveness due to soft lockup in version 17.12.4 causing system instability

Identifier	Headline
CSCwo16038	Cisco Catalyst 9124 AP workgroup Bridge becomes unreachable connecting to Cisco 2800 Root Access Point when Wi-Fi Multimedia (WMM) is disabled
CSCwo19025	High Channel Utilization On AP 9166D 6GHZ Radio
CSCwo34769	Access Point in FlexConnect mode does not advertise RSNxE in probe response frames
CSCwo37756	Cisco Aironet 1815t AP does not receive an internal DHCP IP address when connected to LAN3
CSCwo43801	AP duplicates DHCP request packets when using FlexConnect mode with Central Switching WLAN
CSCwo46493	Cisco Catalyst 9136 AP dual ethernet failover reboots
CSCwo53891	Cisco 91xx AP reboots with incorrect reason 'Controller Last Sent: Channel0 Detected'
CSCwo72236	AP prints logs every 30 seconds : \\\"RTNETLINK answers: No such file or directory\\\"
CSCwo75325	SST:17.12.6: Crash due to radio failures (Beacon Stuck) seen on 1832 or 1852 APs
CSCwo75806	Reassociation Response from AP is delayed for over 200ms on AP WCP component intermittently
CSCwo82821	Cisco Catalyst 9120 Series APs experience kernel panic at txq_hw_fill+0x394
CSCwo89749	Cisco Catalyst 9105 Series APs reboot due to kernel panic
CSCwo94810	Cisco Wireless 916x Series, 9130 Series, and 917x Series APs reject association from IoT client TI module
CSCwp39841	AP9120 crashed as Kernel panic due to NMI watchdog timeout
CSCwp93242	AP serial number in IOX application
CSCwq17491	Observing randomly ICMP packet drops with 3802 AP and proprietary high roaming device
CSCwq19861	IOX app not able to communicate with IOt chip

Resolved Caveats for Cisco IOS XE Dublin 17.12.5

Identifier	Headline
CSCwm89597	SAEvLogShowLogIn is causing high CPU utilization, impacting system efficiency.
CSCwm12544	Controller unexpectedly reloads with cpp-ucode exception due to a rbuf out-of-handle
CSCwn27877	Cisco Catalyst 9105 AP does not respond to clients on 5GHz CS00012380774
CSCwm42613	Wireless clients are unable to join due to high memory usage - AAA_CHUNK_ATTR_SUBLIST

Identifier	Headline
CSCwj30587	Memory leak observed in wncd_x caused by CAPWAP messaging
CSCwi04855	APs repeatedly join and disjoin controller with traceback
CSCwi78109	Controller GUI displays error messages: %CLI_AGENT-1-NVGEN_ERR while processing NVGEN command
CSCwj13190	Inventory app shows "Internal Error" for controller that was in Catalyst Center for several releases
CSCwj73849	Controller sends 2 M5 to AP when 'EAPOL-Key Max Retries' is 2 while the expected number is 3
CSCwj85091	Controller unexpectedly reloads while running the show wireless client mac-address detail command
CSCwj88071	Controller sends an invalid XML character (Unicode: 0x4) found in RPC response for ap-model
CSCwj93876	Controller unexpectedly reloads with reason "Critical process wncmgrd fault on rp_0_0 (rc=134)"
CSCwk05809	%EVENTLIB-3-CPUHOG message observed on Cisco IOS XE 17.12
CSCwk17102	Client experiences unexpected disconnect due to missing M1 packet
CSCwk24352	Wireless clients are unable to receive the splash page and gets stuck due to webauth requirement
CSCwk37983	Client VLAN is retained after changing SSIDs if "\vlan-persistent\" is enabled
CSCwk39866	Client page is stuck in loading state
CSCwk54291	Controller voice CAC BW is not cleared
CSCwk58326	Controller sends multicast packets with previous WMI
CSCwk61854	Configuration update failure when AP is in delete pending state
CSCwk64840	Controller unexpectedly reboots due to memory depletion due to mobilityd process
CSCwk66790	gRPC tunnel for IoT in Software Defined Access (SDA) with "9300 Fabric In A Box (FIAB) & ECA" does not appear for the APs
CSCwk70277	FRA sets slot 2 to 6 GHz in Cisco Catalyst 9166 AP even when 6-GHz network is disabled
CSCwk71592	Intermittent multicast and unicast traffic encounter failure post roaming on an IRCM testbed with mobility enabled
CSCwk76746	Controller stops responding constantly when running specific UDN related commands
CSCwk84121	Local switching clients are assigned to Zone ID 0 when IP overlap is configured and FlexConnect VLAN central switching

Identifier	Headline
CSCWk97948	Controller ends abnormally during an ISSU upgrade from Cisco IOS XE 17.3 to 17.12
CSCWm03016	Controller experiences kernel unresponsiveness abnormally pointing to client_orch
CSCWm29051	Controller experiences kernel unresponsiveness two times due to Critical process WNCd fault on rp_0_0 (rc=139)
CSCWm29437	Controller reboots handling AP radio payloads due to Critical process wncd fault on rp_0_0 (rc=139)
CSCWm36607	Controller displays fman_rp memory leak in FMAN_RP_DB at /tmp/rp/tlddb
CSCWm40646	Clients stuck in IP learning state as DHCP option 82 field is left empty with EoGRE tunnel enabled
CSCWm67710	Cisco Catalyst 9800-80 controller encounters critical process WNCd failure (rc 0)
CSCWm74071	Controller encounters kernel unresponsiveness due to client being stuck in 802.11r preauth and BSSID/AP going down at the same time
CSCWm86679	Cisco Catalyst 9800-40 controllers encounter kernel unresponsiveness and reboot unexpectedly at rogue_start_containers
CSCWm89346	Controller encounters kernel unresponsiveness post telemetry update from Cisco Catalyst Center
CSCWn06627	Controller encounters kernel unresponsiveness with geolocation config pointing towards geo_cloudm_graph_shortest_path
CSCWn10992	DTLS timeout because of improper client load balancing
CSCWn13406	Controller RA trace fails to stop, displaying can't read "str": no such variable
CSCWn15048	Replace Expansion Module's SN field with empty value before sending invalid characters
CSCWn26561	Sequence number missed on NMSPD for RFID measurement during RFID stats collection window
CSCWn35094	Cisco Catalyst 9500 Switch encounters kernel unresponsiveness while profile download
CSCWn36115	iPhone 16 device listed as unclassified in the iOS 18.0.1
CSCWn51207	Cisco Catalyst 9800-40 controller encounters kernel unresponsiveness after upgrade from 17.3.6 to 17.12.3ESW05
CSCWn61980	Rogue AP fails to connect with UI/Rest AP when detected by a dual band radio AP
CSCWi48178	Cisco Catalyst 9800-40 controller displays WNCd error in SafeC Validation for memcmp_s: dmax
CSCWj00465	Active controller becomes ActiveRecovery when the redundancy port link is down

Identifier	Headline
CSCwj38602	Cisco Catalyst 9124-E AP operates the same channel on slot1 and slot 2 at the same time
CSCwj82407	Controller's Web UI enhancement shows login banner while using TACACS/RADIUS
CSCwj85339	Controller displays no effect on disabling DCA Aggressive on startup
CSCwj97107	Standby controller does not take active role after reloading the active controller with "reload slot" command
CSCwk11417	ewlc_cert_mgr, SafeC Validation: strncpy_s: does not have enough space after assigning new WebAdmin cert
CSCwk46067	Ranging response counter is not updated post SSO
CSCwk52366	Controller encounters fix flow control display issue
CSCwk59342	Controller using channels 1, 5, 6, 9, 11, and 13 on 2.4GHz RF profiles causes discrepancies
CSCwk74269	SNMP query with bsnAPIfTable OID fails for Cisco Catalyst 9166D APs
CSCwk74699	Controller GUI does not change AP tags displaying "System Busy! Please retry after sometime"
CSCwk77766	Cisco Catalyst 9800-80 encounters kernel unresponsiveness due to incorrect delete reason code in the AP delete mobile payload
CSCwk77862	AP does not disjoin automatically when the AP-name is changed in the Regex filter
CSCwk94110	NMSP config related timers are not initialised post process restart
CSCwk98607	Controller removes GUI restriction for IP addresses with 0.0.0.0 to behave the same as CLI
CSCwm08261	Controller RADSEC fix using a Samsung device displays wrong Acct-Terminate-Code when manually disabling Wi-Fi
CSCwm14401	Controller experiences an unexpected reset of WNCd
CSCwm28542	OKC roam fails after a brief WAN drop
CSCwm36501	Controller encounters kernel unresponsiveness due to TLB miss
CSCwm80472	Controller's UI and CLI fail to delete a mobility peer due to 'invalid transversal ctx for walker next rec'
CSCwm93080	IP address of the TACACS server disappears when the GUI timeout is changed
CSCwm96234	WebUI fails when special character combinations are used in the login banner on the device's general page
CSCwm98000	Cisco Catalyst 9105 AP displays Short Preamble "Allowed" but then rejects association with SP "Not Allowed"

Identifier	Headline
CSCwn00375	Controller does not generate AP disjoin event message syslog after the AP is disconnected
CSCwn05795	Cisco Catalyst 9120AXI-I AP's 2.4-GHz band does not activate due to a 'Regulatory domain check failed' error
CSCwn10016	Controller's default DHCP lease time doesn't match the CLI
CSCwn14199	Controller reloads unexpectedly when deleting an object from the client database
CSCwn16547	Cisco Catalyst 9800-40 controller's CSR pop does not appear on the GUI
CSCwn20875	Guest users must re-authenticate before sleeping client timeout
CSCwn47727	Rogue Containment does not work for UNII-3 channels
CSCwn17412	The FlexConnect local switching traffic is centralized randomly during a web-auth SSID
CSCwi01131	Controller disconnects clients on the 6GHz radio when 200 or more are connected during GTK rotation
CSCwj39057	Cisco Catalyst 9130 AP experiences traffic loss and delays due to perceived channel utilization and interference
CSCwj60401	Cisco Catalyst 9124 and 9166 APs do not request more than 30 watts while connected to the IE3300 switch
CSCwj75335	Cisco Aironet 1852 AP encounters kernel unresponsiveness
CSCwj77042	AP undergoes unexpected reload at "pc : splitmac_api_add_client+0x68/0x498 [umac]"SF#07186679
CSCwj84554	IOx app installation fails due to incorrect mounting
CSCwj91255	Cisco Catalyst 9120AXI-E AP does not acknowledge frames sent from iOS devices
CSCwk12169	Cisco Catalyst 9105/9115/9120 AP fails for clients connected in 5G slot
CSCwk33521	Cisco Catalyst 9124, 913x and 916x AP in Local mode encounters kernel unresponsiveness
CSCwk39263	Cisco Catalyst 9115 and 9120 APs loses its port 802.1X configuration on upgrade
CSCwk43012	Cisco Catalyst 9120AXI-B, 9166I-B and 9178I APs encounters kernel unresponsiveness
CSCwk43888	Cisco Catalyst 9300 switches Fabric in a Box (FIAB) experiences CAPWAPd core issues on multiple APs running 17.12.4
CSCwk44208	Cisco Catalyst 9164 AP displays Radio4 core in Local mode on ap-17.15.0.71
CSCwk52996	Cisco Catalyst 9120 AP unexpectedly reloads along with radio abnormalities on wlc_bmac_suspend_mac

Identifier	Headline
CSCwk58876	802.11AX APs end abnormally or fail to respond to AUTH frames
CSCwk79057	AP does not failover to the RADIUS server in Flexconnect Local Switching Local Authentication
CSCwk82371	Cisco Catalyst 9120AXI-S AP does not detect the RFIDs in Monitor mode
CSCwk98117	Cisco Catalyst 9166D APs are unable to transmit NDP packets over the air
CSCwm07499	Cisco Catalyst 91xx AP does not rotate awipsd.log causing an upgrade issue "tar: write error: No space left on device"
CSCwm08044	APs do not upgrade without a power cycle displaying error: unlzma: write: No space left on device
CSCwm09148	EWC rogue syslogs are missing
CSCwm30964	EWC does not start on RAP after factory reset
CSCwm31864	Cisco Wave APs experience kernel unresponsiveness due to memory leak reason OOM
CSCwm49467	FlexConnect APs disable u-APSD in the assoc request if clients don't have it enabled
CSCwm58430	Cisco Catalyst 9115 AP experiences kernel unresponsiveness due to: Beacon Stuck Reset Radio
CSCwm66129	Cisco Wave 2 APs 2800, 3800, and 4800 display duplicate entries for stale clients in the Wi-Fi driver
CSCwm79348	IOX-APP fails to detect USB and is stuck in the activate state
CSCwn03468	Clients encounter slow speeds while connecting to slot 2 operating in the 5-GHz band on CM66
CSCwn09549	Cisco Catalyst 9124 MAP fails to join and intermittently disconnects with Cisco Catalyst 9124 RAP
CSCwn10606	Cisco Catalyst 9120 AP fails to report RFID packets to the controller intermittently
CSCwn44287	Multiple Cisco Wave 2 and Cisco Catalyst APs detect CAPWAPd cores
CSCwn52205	AP remains stuck in the activate state without progressing to RUN when IOX-APP starts before USB detection
CSCwn82037	Cisco Catalyst 9120 AP fails to report RFID packets to the controller intermittently
CSCwf96093	Cisco Catalyst 9136 AP's Slot2 5G Rx-SOP threshold functionality doesn't take effect as expected
CSCwh11335	AP joins with secondary controllers at N+1 configs on CAPWAP restart
CSCwi83037	Cisco Aironet 4800 AP: Radio Core data files generated Radio 1 during longevity testing

Identifier	Headline
CSCwi84945	GH100 devices do not associate with Cisco Catalyst 9130 AP but 9120 AP stays connected
CSCwj03060	Cisco Aironet 1815w AP encounters kernel unresponsiveness on image version 17.9.4.205
CSCwj66264	Cisco Catalyst 9300 and 9400 switches' mGig port displays half-duplex mismatch messages
CSCwj69642	Cisco Catalyst 9166 APs stop forwarding traffic for some seconds
CSCwj72985	Cisco Wave 2 APs experiences unresponsiveness due to WCPD
CSCwj98859	APs continue to use IP addresses after sending the DHCP release
CSCwk33513	WGB takes time to roam for Cisco Catalyst 9120, 9105 AP
CSCwk52242	Clients using Cisco IW3702 AP in FlexConnect mode cannot obtain IP addresses while behind third-party WGB
CSCwk62326	RNR Tag is missing in 2.4-GHz and 5-GHz beacons when the 6-GHz SSID is hidden in 17.12
CSCwk62869	Cisco Wave 1 APs only send out 3-addr IGMP packets, which slows WGB-wired clients to recover traffic quickly when roaming between AireOS and the 9800 controller with Mobility Tunnel up
CSCwk62951	Cisco Catalyst 9130 AP undergoes upgrade failure when moving from 17.12 to 17.15
CSCwk66698	vAP undergoes DTLS teardown after CAPWAP configure
CSCwk66729	FlexConnect AP with Client QoS policy changes WLAN-VLAN mapping without manual configuration change
CSCwk68079	Cisco Catalyst 9105 AP generates "protocol 0000 is buggy, dev archer" message per minute
CSCwk70785	AP does not update the MTU value for PMTU probe causing disconnection
CSCwk77222	Cisco Aironet 2802 AP encounters kernel unresponsiveness after upgrading to 17.9.5.47
CSCwk80486	APs mark own BSSID as rogue in 2.4 GHz and in 5 GHz
CSCwk85707	SSH access remains unrestricted for EWC-capable APs connecting to the Cisco Embedded Wireless Controller
CSCwk93880	Cisco IW-6300H-AC-E-K9 APs encounter kernel unresponsiveness due to FIQ/NMI reset
CSCwm04379	Cisco Catalyst 9115AX displays BcmRadioStats error : Failed to add multicast MAC address for RRM as dot11_client entry
CSCwm34600	AAA override VLAN does not apply upon roaming in FlexConnect local authentication

Identifier	Headline
CSCwm37410	Cisco Catalyst 9120 AP does not forward large packets when MTU=1500
CSCwm38017	Cisco Catalyst 9166 APs Slot 1 ROW domain with country Ukraine sets default channel to 36 while it doesn't support UNII1 channels
CSCwm38427	WGB receives an unexpected de-authentication message when roaming from one AP to another in FlexConnect Mode
CSCwm49168	Cisco Catalyst 9164I-ROW AP VAP driver drops EAP identity requests packet intermittently
CSCwm50811	AP displays BSSID as rogue intermittently, causing the control packet to be considered for impersonation detection
CSCwm56315	Cisco Aironet 2800, 3800, 4800 AP: STA-ID list mismatch with radio driver client summary after veriwave roaming test
CSCwm61128	AAA override VLAN is not used for FT 11R roam-in local authentication
CSCwm65107	Cisco Catalyst 9130 AP encounters kernel unresponsiveness due to OOM
CSCwm72142	Cisco Catalyst 9136 AP's tmp directory is exhausted
CSCwm73271	Cisco Wave 2 AP does not send syslog messages if the receiver is using an IPv6 address
CSCwn04950	Cisco Embedded Wireless Controller in the Site Survey mode does not connect with the internal AP
CSCwn08479	Cisco Catalyst 9120 Wi-Fi 6 AP experiences kernel unresponsiveness due to wlc_bsscfg_find_by_target_bssid+0xb8/0xe0
CSCwn14495	Cisco Catalyst 91XX AP detects its own BSSID as rogue
CSCwn15002	Cisco Catalyst 9120 AP encounters kernel unresponsiveness at wlc_low_txq_enq
CSCwn16777	Intermittent onboarding failure for PN-D following IW WGB cold reboot
CSCwn19804	Cisco Aironet 1562D AP doesn't deploy in indoor mode
CSCwn36047	Cisco Catalyst 1852AP's console gets flooded with FIPS Tracelogs while radio bringup
CSCwn48978	AP incorrectly send ARP requests for the DHCP IP address even after a DHCP release packet
CSCwn66225	iPhone clients get disconnected following Tx power invalid on beacon frame
CSCwk63163	Controller does not respond to CoA

Resolved Caveats for Cisco IOS XE Dublin 17.12.4

Identifier	Headline
CSCWj93153	Controller becomes unresponsive during WNCd process
CSCWk05030	Controller observes unresponsiveness due to critical software exception
CSCWk07124	802.1X timeout value is set to 0 by default when configuring RLAN through GUI
CSCWj98534	Cisco Catalyst 9115 APs intermittently stop transmitting multicast traffic downstream
CSCWh95938	Cisco Catalyst 9105 AP encounters a radio crash during longevity test because of Single Client Bridge (SCB) mismatch
CSCWj08367	Cisco Catalyst 9800 Wireless Controller generates system report with crash information, segmentation fault - Process = IGMPSN
CSCWj48018	Cisco Catalyst 9105 AP encounters kernel unresponsiveness when PC is at wlc_ampdu_dotxstatus+0x5c/0x5cc
CSCWj79545	Controller unexpectedly reboots during WNCd process due to assertion failure with invalid BSSID
CSCWj67158	Controller does not send mobile address to AP if the CoA is received when the user is in the ip_learn state.
CSCWj86938	Memory leak in scale network with telemetry shared user events with Cisco Catalyst Center
CSCWi72191	VLAN change on the AP port results in unsuccessful update of IPv6 routes on Wave 2 AP
CSCWj42408	Controller posture flow does not work when PMF is optional
CSCWj25110	Controller reports incorrect values during SNMP polling
CSCWi92913	Cisco Catalyst 9105 and 9115 APs show false radar detection
CSCWj34753	Mesh AP (MAP) reports client unicast traffic when the destination is on the same wired port
CSCWi88967	Cisco Catalyst 9120 APs disconnect due to Port Status Monitor (PSM) microcode watchdog CS00012333933
CSCWj01916	Cisco Catalyst 9162 APs in FlexConnect mode frequently disconnect from the controller
CSCWj49502	Cisco Catalyst 9115 AP becomes unresponsive due to Capwapd process crash
CSCWi01382	5-GHz and 2.4-GHz radios remain non-operational down in an AP
CSCWj60910	Controller and PI report observe RRM message mismatch
CSCWe93421	Cisco Catalyst 9115 Series Wi-Fi 6 APs intermittently stop transmitting multicast traffic downstream

Identifier	Headline
CSCwi76476	Cisco Wave 1 APs WGB sends Address Resolution Protocol (ARP) broadcast request as IPv4 multicast to passive clients
CSCwi96176	Cisco Catalyst 9130 and 9166 APs connected to the controller show high channel utilization with one single client connected
CSCwj10697	Cisco Catalyst 9124AX AP experiences image upgrade failure
CSCwj38728	Cisco Catalyst 9130 AP syslog timestamps do not match the AP's internal clock
CSCwi99566	Cisco Catalyst 9124AXI-E AP becomes unresponsive due to channel 36 not being supported in the Jordan regulatory domain
CSCwj72370	Controller uses incorrect username for "show platform" command when logging in GUI
CSCwj96666	Syntax errors observed in LWAPP client
CSCwj42847	Cisco Catalyst 9120 AP encounters kernel unresponsiveness on Power Supply Module (PSM) watchdog CS00012342194
CSCwi99296	Cisco Catalyst 9120 AP encounters kernel unresponsiveness with the PC due to wlc_bmac_suspend_mac_and_wait
CSCwj55168	Multiple Cisco Catalyst 9130 APs encounter kernel unresponsiveness
CSCwi95945	Cisco Catalyst 9130 APs stop forwarding router advertisements after 4-6 hours of operation
CSCwi64010	Controller accepts configuration of a reserved IPv6 multicast address as a mobility IPv6 address
CSCwj34916	Cisco Wave 2 APs in FlexConnect mode are unable to execute Secure Agile Exchange (SAE) Hash-to-element (H2E) IE authentication, stopping beacon/probe responses that cause M3 mismatch
CSCwi56780	Mac Authentication Bypass (MAB) is not initiated unless the client device is deauthenticated
CSCwe11889	Authenticated APs only support Extensible Authentication Protocol-Transport Layer Security (EAP-TLS) certificate renewal once the certificate's validity has expired
CSCwj19805	Cisco Catalyst 9130AX AP BLE 2.7.22 reports chip sync issue during firmware upgrade and 0dBm TxPower
CSCwj96620	Syntax errors observed in LWAPP
CSCwh82872	Cisco Catalyst 9115AXI-S AP association request dropped on the Cisco Catalyst 9800-80 Wireless Controller
CSCwi92439	Cisco Aironet 1815 APs report high channel utilization in the 5-Ghz band
CSCwj06987	APs dissociate from the controller and stop functioning

Identifier	Headline
CSCWj20953	Cisco Catalyst 9130AX APs in FlexConnect mode encounter kernel unresponsiveness
CSCWj66429	Cisco Catalyst 9115 AP encounters kernel unresponsiveness
CSCWj94201	Controller experiences unresponsiveness CPUHOG
CSCWk02633	RSA key pair is configured in the TrustPoint configuration when EC keypair is selected while creating a trustpoint on the controller
CSCWj82898	Controller is unable to onboard on Cisco Spaces
CSCWj69755	Controller WebUI is not updating configuration port parameters
CSCWi54064	APs connected to the same controller classify each other as rogue and generate an "AP Impersonation" threat warning
CSCWj26848	Cisco Wave 2 APs do not check DELETE_VAP_PAYLOAD CAPWAP payload sanity before deleting blindly
CSCWj76892	Controller configures aggregation scheduler parameter incorrectly, causing low downlink speed
CSCWj82679	Power Policy status shows "Not Applied" since the client has not been disconnected after the calendar period ends on the 6G radio
CSCWi27380	Media stream feature does not work
CSCWj15376	Cisco NMSP runs into security protocol issues
CSCWi96508	Cisco Wave 2 APs allowing SKC roam cause client deletion with the reason as INVALID_PMKID
CSCWj40202	Controller does not send RADIUS accounting messages WLAN with PSK/MAB authentication
CSCWj33376	Incorrect selection of APs in load balancing
CSCWi81972	Cisco Wave 2 APs do not check DELETE_VAP_PAYLOAD CAPWAP payload sanity before deleting blindly
CSCWj04904	Cisco Catalyst 9300LM switch is not compatible with Cisco Aironet 1815 AP when the switch is connected to a port with Cisco Unified IP Phone 7945G
CSCWj26196	Controller running the IOS XE software encounters an unexpected reset while trying to validate the MAC address with the EWLC_APP_INFRA_ID_MAGIC
CSCWi96089	Cisco Wave 2 APs do not plumb keys after session timeout reauthentication
CSCWj36962	Controller reboots unexpectedly due to invalid QoS parameters
CSCWj97748	Cisco Catalyst 9130 AP encounters kernel unresponsiveness with PC at _raw_spin_lock/LR wlan_objmgr_peer_try_get_ref

Identifier	Headline
CSCwj85005	Locally Significant Certificates (LSC) provisioning fails depending on Subject Name Parameters values in the controller
CSCwj31356	Cisco Catalyst 9800 Wireless Controller reboots due to Radio Resource Management (RRM) process fault on rp_0_0 (rc=139)
CSCwj34379	Controller encounters unresponsiveness when accessing crimson database
CSCwj34460	Cisco Catalyst 9120 AP encounters kernel unresponsiveness when PC is at wlc_txhinfo2bandunit
CSCwj93906	Cisco Catalyst 9120 AXI AP sends Msg:2 in mode:2 alerting beacon parameter failure
CSCwj77128	URL filter allows only letters as the first character
CSCwj09698	Cisco Catalyst 9800 Wireless Controller encounters an unexpected reset in wncmgrd with a scaled setup while being managed by the Meraki Dashboard
CSCwj93744	Cisco Catalyst 9136 AP encounters Slot 1 radio unresponsiveness with error - Radio recovered from internal failure
CSCwk62269	Click-AP assessment for OpenSSH regreSSHion vulnerability.
CSCwi93213	Controller is marked as AAA Server Down after switchover when using key 6 password encryption.
CSCwi39486	During controller switchover, a client using a static IP is assigned to the wrong VLAN.
CSCwj73634	Controller encounters configuration loss after High Availability SSO failover
CSCwk33139	Cisco IOS XE controller software encounters an arbitrary file upload vulnerability

Resolved Caveats for Cisco IOS XE Dublin 17.12.3

Identifier	Headline
CSCwf49289	The controller does not have its Secure Unique Device Identifier (SUDI) certificates initialized upon new APP registration.
CSCwh59543	Cisco Catalyst 9120 AP encounters a Radio FW_1 unresponsiveness and Capwapd unresponsiveness during scale longevity.
CSCwh88320	Controller reports false jammer alerts.
CSCwf79175	Pairwise Master Key Identification (PMKID) mismatch between FlexConnect central authentication Wave 2 AP and controller for 802.11X-SHA256 on roaming clients.
CSCwi35946	Cisco Catalyst 9120 AP encounters a kernel unresponsiveness.
CSCwi67013	Cisco Aironet 2800 APs running on the Taiwan domain are unable to send Wi-Fi signals on channels 52, 120, 124 and 128.

Identifier	Headline
CSCwh09642	IP theft was observed due to the zone ID being 0x00000000 after the In Service Software Upgrade (ISSU) process.
CSCwh61007	Controller frequently becomes nonoperational when provisioning multiple APs.
CSCwh14232	Controllers do not send Logical Link Control (LLC) / XID spoofed frames following a mobility event.
CSCwi08442	APs are unable to join when Controller-Based Application Recognition (CBAR) is enabled on the controller.
CSCwi22270	Cisco Catalyst 9120 AP encounters a radio unresponsiveness during longevity run.
CSCwi69042	Cisco Aironet 1562 Mesh AP (MAP) is unable to join the network through the Root AP (RAP) using the Extensible Authentication Protocol (EAP) and the Flex+Bridge site tag.
CSCwf78066	Catalyst Center heat map displays the message "No radios in the selected band" for APs managed by the controller.
CSCwh68768	Controller in the public cloud fails to create a FlexConnect WLAN using Basic Wireless Setup.
CSCwh63270	Cisco Catalyst 9130AXI APs joined to controller frequently become nonoperational due to radio failure.
CSCwf84639	Cisco Catalyst 9120 AP Dual Band (XOR) radio mode is not updated in the radio_oper_data database.
CSCwi07094	Apple Client cannot connect to the FlexConnect WPA2+WPA3 SSID when Secure Agile Exchange (SAE) is enabled and Opportunistic Key Caching (OKC) is disabled.
CSCwh91254	PHY High Txpower issue on Broadcom (BCM) APs causes increased coverage and clients are unable to authenticate.
CSCwh20334	Controller's Change of Authorization (CoA) server key appears blank in the GUI.
CSCwh49406	Cisco Catalyst 9130 series AP spams syslog controllers with thousands of CleanAir logs per second.
CSCwh95315	Cisco Catalyst IW9167E Heavy Duty AP changes its backhaul upon reload.
CSCwh60483	Cisco Catalyst 9136I AP shows incorrect temperature readings.
CSCwf96138	Roaming issues observed in iPhone SE 3rd generation.
CSCwi34051	The Cisco Aironet 2800 AP randomly encountered FIQ/NMI resets; PC at wl_get_staid_info.
CSCwh81332	Cisco Catalyst 9130 APs encountered kernel unresponsiveness after upgrade to Cisco IOS XE Bengaluru 17.6.6.

Identifier	Headline
CSCwf92100	Embedded Wireless Controller: Preferred active configuration is lost after CAPWAP AP configuration update in WebUI.
CSCwi28174	Layer 3 multicast packets are sent on native VLAN when VLAN ID 1 is selected on policy profile with AAA override.
CSCwh12481	Cisco Catalyst 9130AXI and 9130AXE AP unable to join the controller when only TZ (Tanzania) country code is configured.
CSCwi03442	Cisco Catalyst 9130 APs does not honor unscheduled automatic power save delivery (U-APSD) trigger frame, which causes RTP stream disruption.
CSCwh30078	Cisco Wave 2 AP becomes nonoperational in throughput testing.
CSCwh33056	Policy tag description is blank after deleting WLAN location entries.
CSCwi19481	Cisco Catalyst 9130 AP in FlexConnect mode stops forwarding router advertisements after 4-6 hours of uptime.
CSCwh88100	Cisco Aironet 3800 AP becomes nonoperational due to kernel panic with PC at skb_unlink+0x40/0x54.
CSCwh37783	Controller Lobby Admin page is unable to load.
CSCwf88890	GUI is stuck on loading in Monitoring > Wireless > AP Statistics > General for Cisco Aironet 3800 AP.
CSCwf87281	NULL Timer causes segmentation fault in the controller.
CSCwh74415	Per client rate limit is not working for FlexConnect local switching APs.
CSCwf54827	Uptime in Acct-Session-Time is high after idle timeout.
CSCwh87903	Cisco Catalyst 9120 AP sends authorization response failures for specific MAC addresses due to "suppressed by MAC filter".
CSCwf93747	Controller WebUI does not load policy profile page when large number of WLANs are configured.
CSCwf60519	Client is unable to connect due to invalid PMKID after an 802.11r reauthentication failure.
CSCwi42112	MAC address of wired clients are being learned from the Cisco Catalyst 9124 MAP port.
CSCwi19804	Cisco Catalyst 9105, 9115, 9120 AP radio are misconfigured after AP reload when admin state is down.
CSCwh76420	Controller becomes nonoperational while performing ISSU upgrade.
CSCwh75431	Cisco Aironet 1830, 1850 APs report false utilization affecting performance on 5 GHz.
CSCwi64652	802.11ax APs do not reset Bluetooth Low Energy (BLE) interface after 100 attempts.

Identifier	Headline
CSCwi52692	Cisco Catalyst 9130 AP signals Universal PoE spare pair to turn off Type-Length-Value (TLV) fields in Cisco Discovery Protocol.
CSCwi49666	Cisco Catalyst 9136 AP environmental sensors are reporting incorrect ambient temperature.
CSCwh62342	FlexConnect AP as an mDNS gateway responds incorrectly when Location Specific Services (LSS) filter is enabled in 5GHz-band.
CSCwh31966	Controller becomes nonoperational on WNCd process during database termination.
CSCwh44793	Cisco Catalyst 9130 AP on Cisco IOS XE Amsterdam 17.3.6 fails to join with error to set FT data in BSSID after site-tag is changed on the controller.
CSCwi11038	Cisco Catalyst 9115 OEAP experiences kernel unresponsiveness.
CSCwi35699	Cisco Catalyst 9120 AP detects its own BSSID as malicious after channel resets.
CSCwi06055	Cisco Industrial Wireless 3702 AP radios reset and stay down when board temperature is less than -20° C.
CSCwi05672	Wireless Driver is unable to decrypt ICAP packets in Cisco Catalyst 9130 AP.
CSCwf86242	Controller experiences unexpected reload with CAPWAP window size set to 0.
CSCwi04705	Controller is not sending gARP broadcast announcements on behalf of the client on inter-controller roaming events.
CSCwf75646	Controller MIB update is required to include all coded integer values for cRFStatusLastSwactReasonCode.
CSCwh42002	Controller becomes nonoperational while processing CAPWAP data and generates WNCd core file.
CSCwf90646	Controller sends CAPWAP payload for DOT11R_WLC_MAC_IP_PAYLOAD as two packets with the same sequence number of 2 but there is no information about fragmentation or offset.
CSCwi38791	Cisco Catalyst 1850 AP becomes nonoperational due to kernel panic in Cisco IOS XE Dublin 17.11.

Resolved Caveats for Cisco IOS XE Dublin 17.12.2

This release provides a critical fix for a security vulnerability. See the following table for information.

Caveat ID	Description
CSCwh87343	Cisco IOS XE Software Web UI Privilege Escalation Vulnerability For more information, see Security Advisory: cisco-sa-iosxe-webui-privesc-j22SaA4z .
CSCwfl4400	Cisco Catalyst 9166 AP: CAPWAP down/up during Dual Band operation changes between 5 GHz and 6 GHz.

Caveat ID	Description
CSCwf60151	Memory leak at kernel level with PUBd process triggering unexpected reloads on the controllers.
CSCwe11213	Cisco Catalyst 9130AX Series AP unresponsive due to radio failure.
CSCwf79458	802.11ax workgroup bridge (WGB) 2.4-GHz radio does not roam with 802.11r enabled.
CSCwh20306	Cisco Catalyst AP hyperlocation breaks when Adaptive Wireless Intrusion Prevention System (wIPS) is enabled.
CSCwf83278	Client traffic unresponsive with N+1 when AP sends CLIENT_DEL_STOP_REASSOC.
CSCwh08532	Differentiated Services Code Point (DSCP) marking on Cisco Catalyst AP for QoS metal policies not happening in slow path and fast path.
CSCwh20301	No telemetry data transfer from controller to Cisco Catalyst Center.
CSCwf53520	Kernel panic unresponsive when Cisco Aironet 1815 Series AP is running version 17.9.2.
CSCwh22038	Functional The Cisco Catalyst 9162 Series AP Radio1 unresponsive on 17.12.1.5
CSCwh42002	Controller unresponsive with WNCd core while processing CAPWAP data.
CSCwh61011	AP stops processing downstream frames after CAPWAP restart.
CSCwf59348	Beacon set Max Transmit Power Level to 128 dBm in Country IE, which happens in some 5G channels.
CSCwf63818	Cisco Aironet 1830 Series AP running version 17.9.2 is unresponsive due to kernel panic.
CSCwf93992	Cisco Aironet 2800 APs in FlexConnect mode are not processing Extensible Authentication Protocol-Transport Layer Security Authentication (EAP-TLS) fragmented packets if delay is more than 50 ms.
CSCwf99932	Functional Cisco Catalyst 9120 AP Radio1 unresponsive on ap-17.12.0.116.
CSCwh09879	Clients are not able to connect to FlexConnect APs after country code change.
CSCwh20934	Systemd critical process not working when joining the Cisco Catalyst 9800-CL running 17.9.3
CSCwh54279	Cisco Aironet 1815 Series OEAP running 17.9.4 is unresponsive due to kernel panic.
CSCwh74663	Clients are stuck in authenticating or in IP learn for open SSIDs.
CSCwh81040	Cisco Catalyst 9120 AP in local mode is unresponsive when WGB associates with the SSID profile.
CSCwf87904	The Cisco Catalyst 9164 Series AP unresponsive on [<fffffbffd6524e0>] cisco_wlan_crypto_decap+0x2a8/0x518 [umac](SF06713784)
CSCwh26854	Cisco Catalyst 9166 and 9162 APs adaptive 802.11r roam fails in Apple clients.

Caveat ID	Description
CSCwh54762	AP kernel panic due to not syncing.
CSCwf53331	Cisco Catalyst 9124 AP: Kernel panic observed after changing channel on the 5-GHz in Bridge mode.
CSCwf85025	The transmission power in Cisco Catalyst 9166-ROW GB decreases when there is a channel change.
CSCwh06834	Using special characters in the password while generating TP generates an invalid TP.
CSCwh08625	AP is unresponsive due to kernel panic with low PC and LR values.
CSCwh18759	Cisco Aironet 1815 Series AP unresponsive due to system memory running low and kernel panic; not syncing.
CSCwf13804	netlink_socket_receive multicast_group 1 return failure: No buffer space available errors are seen.
CSCwf52815	Cisco AP should improve Path Maximum Transmission Unit (PMTU) to be able to honor the ICMP unreachable MTU value.
CSCwf62051	Cisco Aironet 1815w AP unresponsive due to kernel panic.
CSCwf90014	Issues with Cisco Intelligent Capture (iCAP) on IPv6 cluster.
CSCwf44321	Interferers on Connected Mobile Experiences won't be displayed, although they are shown on the controller for 2.4 and 5 GHz.
CSCwf61881	AP is randomly moving from US -> UX domain and unable to set it to standard power.
CSCwf86242	Cisco 9800 Wireless Controller unexpectedly reloads with CAPWAP window size set to 0.
CSCwh61007	Controller constantly being unresponsive whenever it provisions multiple APs.
CSCwf29742	Cisco Catalyst 9120 AP: Firmware unresponsive while running multicast & longevity with 80+ clients
CSCwh33190	Cisco Catalyst 9115 Series Wi-Fi 6 AP unresponsive due to kernel panic.
CSCwf07384	Wired client behind Cisco Catalyst 9105 Series RLAN is not able to pass traffic.
CSCwf68131	The Cisco Catalyst Series 9105AXW AP faces bad block monitoring after upgrading the software.
CSCwf95868	Single Band BCM WGB Radio 0 Tx power decreases by nearly 20 dBm while configuring antenna number.
CSCwh13494	Cisco Catalyst 9136 Series APs in -F regulatory domain are beaconing at a lower power.
CSCwf83292	Cisco Catalyst 9130 Series AP receives DHCP offer and ACK at the wired Ethernet port, but does not send it over the radio interface to the client.

Caveat ID	Description
CSCwf90114	Stale entries remain for APs no longer connected to system.
CSCwh59420	Cisco Catalyst 9136 Series APs unresponsive on Cisco IOS XE Cupertino 17.9.x
CSCwh76420	A controller may get unresponsive within WNCd service when performing an ISSU upgrade from Cisco IOS XE Bengaluru 17.6.x releases to Cisco IOS XE Cupertino 17.9.x releases.
CSCwf81866	Radio 0 WGB configuration is not backed up correctly when doing a TFTP backup of the configuration.
CSCwf65794	Cisco 1852 AP reloads unexpectedly due to radio failure.
CSCwf78066	Cisco Catalyst Center users might see a "No radios in the selected band" message on the floor maps and the AP icons might start showing up as white circles instead of the normal AP icons.
CSCwh29924	Cisco Catalyst 9105 APs, Cisco Catalyst 9115 APs, or Cisco Catalyst 9120 APs WGB: Antenna-a couldn't function properly if configuration is ab-antenna.
CSCwf12301	The retries number is always 0 for [QCA 12.0] WCPD TX.
CSCwf10839	A large amount of Virtual Router Redundancy Protocol (VRRP) traffic causes the switch port to be down due to storm-control action configuration.
CSCwe24263	Cisco Catalyst 9130 Series AP: Inconsistent Tx power levels advertised in beacons.
CSCwh30996	The Bluetooth Low Energy Power Distribution Unit used in dual mode for iBeacon with PDU type is adv_discover_ind vs the one used in tx only mode for vibeacon is adv_non_connectable_ind.
CSCwf91445	Controller pushes accounting information for pre-shared key (PSK) Local Auth WLANs.
CSCwf94863	Cisco Catalyst 9115 Series Wi-Fi 6 AP unexpectedly reboots due to kernel panic.
CSCwf64009	Cisco Aironet 1815 Series AP leaking RLAN VLAN traffic with looped port.
CSCwf98534	Geolocation reported by Global Navigation Satellite System(GNSS) module does not take into account external GPS antenna cable length in the computation of the ellipse uncertainty region.
CSCwh09676	Wireless Control Protocol (WCP) Dynamic Memory Allocation unfree logs missing and dmalloc files not updated periodically.
CSCwh27366	AP radio firmware failure reset code 2 with failure signature GDP.
CSCwh27425	Cisco Catalyst 9115AX Series AP does not forward a part of CAPWAP data packets to the uplink direction.
CSCwf13107	Radio being unresponsive during longevity test with Cisco Catalyst 9105 Series AP.
CSCwh35072	Cisco Aironet 3800 Series AP reloads unexpectedly due to FIQ/NMI reset.

Caveat ID	Description
CSCwh45418	Cisco Catalyst 9124 Series AP is sending incorrect duplex information via Cisco Discovery Protocol (CDP).
CSCwh50681	New SSID arp0v0 being broadcast after Cisco IOS XE Cupertino 17.9.3 wireless upgrade.
CSCwf68612	Controller may reload unexpectedly, generating a system-report containing a core file for the WNCd process.
CSCwf99906	Network Time Protocol (NTP) authentication removed after reload using more than 16 bytes.
CSCwh11858	When removing an Fully qualified domain name (FQDN) ACL from the switch, the device unexpectedly reloads, the ACL is not deleted after the reload.
CSCwf21390	Duplicate Access-Request messages with Cisco Trusted Security (CTS) client username when more than one RADIUS server is configured.
CSCwf36752	Using template from Cisco Catalyst Center or using copy-paste with a specific configuration for first time, the TACACS+ encryption fails.
CSCwf66661	Web UI page renders the page slowly while accessing device_type contents.

Resolved Caveats for Cisco IOS XE Dublin 17.12.1

From this release, the list of caveats is displayed using BST tool. When you click the BST link, it opens a separate window and lists the bugs sorted by severity. You can filter it further using the options in the tool.

Click on the following link to view the Resolved Caveats: [BST Link](#)

Troubleshooting

For the most up-to-date, detailed troubleshooting information, see [Troubleshooting TechNotes](#).

Related Documentation

- [Information about Cisco IOS XE](#)
- [Cisco Validated Design documents](#)
- [MIB Locator](#) to locate and download MIBs for selected platforms, Cisco IOS releases, and feature sets

Cisco Wireless Controller

For more information about the Cisco wireless controller, lightweight APs, and mesh APs, see these documents:

- [Cisco Wireless Solutions Software Compatibility Matrix](#)
- [Cisco Catalyst 9800 Series Wireless Controller Software Configuration Guide](#)

- [Cisco Catalyst 9800 Series Wireless Controller Command Reference](#)
- [Cisco Catalyst 9800 Series Configuration Best Practices](#)
- [In-Service Software Upgrade Matrix](#)
- [Upgrading Field Programmable Hardware Devices for Cisco Catalyst 9800 Series Wireless Controllers](#)

The installation guide for your controller is available at:

- [Hardware Installation Guides](#)

[All Cisco Wireless Controller software-related documentation](#)

Cisco Catalyst 9800 Series Wireless Controller Data Sheets

- [Cisco Catalyst 9800-CL Wireless Controller for Cloud Data Sheet](#)
- [Cisco Catalyst 9800-80 Wireless Controller Data Sheet](#)
- [Cisco Catalyst 9800-40 Wireless Controller Data Sheet](#)
- [Cisco Catalyst 9800-L Wireless Controller Data Sheet](#)

Cisco Embedded Wireless Controller on Catalyst Access Points

For more information about the Cisco Embedded Wireless Controller on Catalyst Access Points, see:

<https://www.cisco.com/c/en/us/support/wireless/embedded-wireless-controller-catalyst-access-points/tsd-products-support-series-home.html>

Wireless Product Comparison

- [Compare specifications of Cisco wireless APs and controllers](#)
- [Wireless LAN Compliance Lookup](#)
- [Cisco AireOS to Cisco Catalyst 9800 Wireless Controller Feature Comparison Matrix](#)

Cisco Access Points—Statement of Volatility

The STATEMENT OF VOLATILITY is an engineering document that provides information about the device, the location of its memory components, and the methods for clearing device memory. Refer to the data security policies and practices of your organization and take the necessary steps required to protect your devices or network environment.

The Cisco Aironet and Catalyst AP Statement of Volatility (SoV) documents are available on the [Cisco Trust Portal](#).

You can search by the AP model to view the SoV document.

Cisco Prime Infrastructure

[Cisco Prime Infrastructure Documentation](#)

Cisco Connected Mobile Experiences

[Cisco Connected Mobile Experiences Documentation](#)

Cisco Catalyst Center

[Cisco Catalyst Center Documentation](#)

Communications, services, and additional information

- To receive timely, relevant information from Cisco, sign up at [Cisco Profile Manager](#).
- To get the business impact you're looking for with the technologies that matter, visit [Cisco Services](#).
- To submit a service request, visit [Cisco Support](#).
- To discover and browse secure, validated enterprise-class apps, products, solutions, and services, visit [Cisco DevNet](#).
- To obtain general networking, training, and certification titles, visit [Cisco Press](#).
- To find warranty information for a specific product or product family, access [Cisco Warranty Finder](#).

Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST) is a gateway to the Cisco bug-tracking system, which maintains a comprehensive list of defects and vulnerabilities in Cisco products and software. The BST provides you with detailed defect information about your products and software.

Documentation feedback

To provide feedback about Cisco technical documentation, use the feedback form available in the right pane of every online document.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2025 Cisco Systems, Inc. All rights reserved.