



# Release Notes for Cisco Catalyst 9800 Series Wireless Controller, Cisco IOS XE 26.2.x



Cisco Catalyst 9800 Series Wireless Controller, Cisco IOS XE 26.2.x ..... 3

New software features..... 3

New hardware features..... 8

Changes in behavior ..... 9

Resolved issues..... 11

Open issues ..... 19

Known issues ..... 20

Compatibility ..... 20

Supported hardware..... 33

Related content ..... 43

Communications, services, and additional information:..... 44

Legal information..... 44

## Cisco Catalyst 9800 Series Wireless Controller, Cisco IOS XE 26.2.x

The controllers are available in multiple forms to cater to your deployment options:

- Catalyst 9800 Series Wireless Controller Appliance
  - Cisco Catalyst 9800 Series Wireless Controllers (C9800-L, C9800-40, C9800-80)
  - Cisco CW9800 Series Wireless Controllers (CW9800L, CW9800M, CW9800H1, CW9800H2)
- Catalyst 9800 Series Wireless Controller for Cloud
- Embedded Wireless Controller (EWC) on Catalyst 9000 Series Switches.

This document describes the new software features that were introduced or enhanced, change in behavior, issues, supported hardware, and so on, for Cisco IOS XE 26.2.x.

### New software features

This section provides a brief description of the new software features introduced in this release.

**Table 1.** New software features for Cisco Catalyst 9800 Series Wireless Controllers, Release 26.2.1

| Product impact       | Feature                                          | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
|----------------------|--------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Software Reliability | Cisco Live Protect Vulnerability Shields         | <p>Live Protect validates vulnerability shields that protect Cisco products without requiring device reloads or service interruptions. You can deploy security shields in two modes:</p> <ul style="list-style-type: none"><li>• Monitoring mode: Provides visibility into potential exploit attempts without enforcement, allowing you to assess threats before taking action.</li><li>• Enforce (Protecting) mode: Actively applies mitigation policies to reduce exposure to known vulnerabilities.</li></ul> <p>Live Protect allows you to monitor, enforce, disable, and retire the vulnerability shields enabling a smooth transition to remediation. This capability helps businesses maintain continuous operations while managing risks until the software upgrades or patches are deployed.</p> |
|                      | Sensor Connect Backup and Restore                | <p>This release introduces Backup and Restore for the Sensor Connect application database, preserving configuration and operational data not included in the controller configuration backup. The capability enables Sensor Connect to be restored to its saved Day-N state after controller replacement or application redeployment.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
|                      | AP and Sensor Connect Support for Full Filtering | <p>This release enables Cisco Wireless APs to filter BLE advertisements before forwarding them to Sensor Connect and Cisco Spaces, reducing unnecessary traffic in dense Bluetooth environments. Advertisements can be filtered by Bluetooth MAC address type, RSSI threshold, and MAC address prefix using deny, static allow, dynamic allow, and limit lists.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                       |
|                      | IPv6 Layer 3 Access                              | <p>This release introduces controller-based IPv6 Layer 3 access, enabling the controller to terminate wireless client IPv6 subnets on switched virtual interfaces and advertise client routes through OSPFv3. It also provides VRF-aware services, including DHCPv6 relay, IPv6 multicast routing, NAT64, and flow-based ECMP forwarding.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                             |

|                                                                                           |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
|-------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Enhanced BLE performance on Cisco Wireless APs                                            | Cisco Spaces Connector IoT Service: Controllers running Cisco IOS XE Wireless release 26.2.1 and later support the Cisco Spaces Connector IoT Service solution only with Cisco Spaces Connector 3.3 or later and IOx App 2.1.x or later. Before upgrading the controller to release 26.2.1 or later, upgrade the Cisco Spaces Connector to release 3.3 or later and the IOx App to the latest 2.1.x release in Cisco Spaces.                                                              |
| NDcPPv4.0 updates for Common Criteria Certification                                       | To support NDcPP v4.0 Common Criteria certification, the HTTPS Web GUI now defaults ECDHE key establishment to the stronger <b>secp384r1</b> curve. The update aligns secure HTTP behavior with modern TLS requirements and applies consistently across CLI and YANG configuration interfaces.                                                                                                                                                                                            |
| Post-Quantum Cryptography Support for the Web Server                                      | <p>Many applications and services still rely on TLS 1.2 or earlier, which lack the extensibility needed to negotiate post-quantum cryptography (PQC) cipher suites. Retrofitting these legacy versions is impractical, leaving applications that depend on them exposed to “harvest now, decrypt later” attacks.</p> <p>The migration to TLS 1.3 enables support for PQC algorithms such as ML-KEM.</p>                                                                                   |
| RMI Support for Syslog Source Interfaces                                                  | <p>Syslog now supports the Redundancy Management Interface (RMI) as a logging source on wireless controllers. When RMI is selected, syslog uses the RMI IP address and automatically resets existing connections when the RMI configuration changes or is removed.</p> <p>Existing management-IP and source-interface behavior remains unchanged. The enhancement supports IPv4 and IPv6 on both active and standby controllers.</p>                                                      |
| High Availability support for CTS IP-SGT Bindings                                         | <p>Cisco TrustSec now synchronizes IP-SGT bindings from the active device to the standby device, including bindings learned through SXP, VLAN, LISP, OMP, and Layer 3 interfaces. Incremental and bulk synchronization preserve binding information during a Stateful Switchover, reducing relearning delays and maintaining consistent SGACL enforcement.</p> <p>The enhancement supports SXP version 5, IPv4 and IPv6 connections, VRFs, and stacked, SVL, and chassis deployments.</p> |
| AP Certificate Renewal Without an AP Reload                                               | From Cisco IOS XE 26.2.1 onwards, supported Cisco Catalyst access points can apply renewed Locally Significant Certificates without a complete AP reload. This enhancement reduces service disruption during certificate renewal through Cisco Catalyst 9800 Series Wireless Controllers or Cisco Catalyst Center. This release also includes the ability to enable or disable LSC provisioning.                                                                                          |
| Cryptographic Enhancements for Cisco aWIPS                                                | From Cisco IOS XE 26.2.1 onwards, Cisco Advanced Wireless Intrusion Prevention System (aWIPS) includes updated cryptographic processing for secure profile exchange between Cisco Catalyst Center and Cisco Catalyst 9800 Series Wireless Controllers.                                                                                                                                                                                                                                    |
| 6 GHz LPI Support for Korea                                                               | From this release, supported IW9165E APs can operate as URWB mobility clients in Korea’s 6-GHz Low Power Indoor domain, providing indoor connectivity across the U-NII-5 through U-NII-8 bands.                                                                                                                                                                                                                                                                                           |
| Support for 802.1x Authentication on Ethernet Port for Controller Managed URWB Vehicle AP | This feature enables 802.1X authentication of wired clients connected to Vehicle APs operating as mobility clients. It validates RADIUS-based access control and EAP message forwarding through the URWB network. Supported methods include EAP-PEAP, EAP-TLS, and EAP-FAST. MAB is not supported, and the release supports one wired client per LAN port with up to two RADIUS servers per Vehicle AP.                                                                                   |

|               |                                                      |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
|---------------|------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|               | 802.1X Authentication for Wired Clients              | This feature enables 802.1X authentication for wired clients connected through a Workgroup Bridge (WGB), enforcing controlled network access through a configured RADIUS server. It ensures proper forwarding of EAP packets through the WGB wired0 and wired1 ports and supports multiple clients through a compatible switch or hub.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
|               | WPA3-Enterprise and SCEP Certificate Renewal Support | This feature enables WPA3-Enterprise security on Industrial Wireless devices operating in Workgroup Bridge (WGB) mode, providing robust encryption and enterprise authentication for wireless connections. It supports EAP-TLS, PEAP, and EAP-FAST authentication and meets WPA3 requirements for the 6 GHz radio band, including mandatory Protected Management Frames (PMF). Simple Certificate Enrollment Protocol (SCEP) support automates digital certificate renewal for EAP-TLS deployments, simplifying certificate lifecycle management and reducing manual effort.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                         |
|               | 802.11v Support for 6 GHz WGB                        | Enables 802.11v support on the WGB to optimize roaming performance by restricting channel scanning to those learned from the neighbor list.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                          |
|               | Software Model Version in the gRPC Header            | The gRPC dialout message header dynamically determines the Cisco IOS XE software version running on the device, and based on this software version, the telemetry receiver selects the YANG model version.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
|               | Resilient Infrastructure Changes                     | <p>As part of Cisco's Resilient Infrastructure program and Cisco's commitment to secure infrastructure, this release includes additional changes aimed towards continuing to make Cisco IOS XE more secure by default. Note that some of these changes may require operational changes if you are not following secure best practices. This release includes these changes:</p> <ul style="list-style-type: none"> <li>• The RADIUS client appends the Message-Authenticator attribute (Attribute 80 HMAC-MD5) to all outgoing Access-Request packets to mitigate cryptographic forgery and Blast-RADIUS vulnerabilities (CVE-2024-3596).</li> <li>• The RADIUS client drops incoming Access-Accept, Access-Reject, and Access-Challenge packets if the Message-Authenticator packet is absent or invalid. Ensure AAA servers (example, Cisco ISE) are configured to return Attribute 80.</li> <li>• Outbound SSH connections enforce Trust-On-First-Use (TOFU). The device prompts to verify and store remote server host keys in the known-hosts database on first connection and validates against them on subsequent sessions.</li> <li>• The embedded web server daemon is disabled by default on factory configurations to restrict unauthenticated management access. Web UI and RESTCONF require explicit enablement of the ip http secure-server command.</li> <li>• The IOS XE device rejects unauthenticated NTP Mode 6 and Mode 7 control queries (monlist) to prevent NTP reflection and amplification DDoS attacks. Standard time synchronization (Modes 3 and 4) is unaffected.</li> <li>• System logging timestamps automatically include the four-digit calendar year (service timestamps log datetime msec year) to standardize multi-year audit logs and SIEM compliance.</li> <li>• Warning messages are emitted on the console and logged to syslog whenever legacy insecure protocols (Telnet, FTP, TFTP, HTTP) are enabled in the configuration.</li> <li>• Real-time tracking of active insecure services is published to the operational database (operDB) and YANG data models, allowing management controllers (such as Cisco Catalyst Center) to monitor security compliance.</li> </ul> |
| Ease of Setup | Wireless Active Testing SCEP Support                 | This release adds SCEP-based certificate provisioning for Wireless Active Testing EAP-TLS SSIDs. Integration with customer SCEP servers enables automatic enrollment and renewal of client certificates, eliminating the need for manual certificate provisioning.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |

|                                                                                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
|---------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Expanded SFP Module Support for Cisco Catalyst 9800 Series Wireless Controllers | <p>This release expands SFP support across CW9800M, CW9800H1, and CW9800H2 controllers. The update adds support for the SFP-10G-T-X that delivers 10 Gigabit Ethernet connectivity over standard copper network cables, providing customers with greater deployment flexibility and broader hardware compatibility.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                    |
| Auto MACsec for Wireless Access Points                                          | <p>This release introduces Auto MACsec, which automatically discovers compatible access switches through LLDP, authenticates access points using a hardware-backed identity, and establishes MACsec encryption before the AP joins the wireless controller.</p> <p>The feature reduces per-port configuration while protecting wired uplink traffic from interception and man-in-the-middle attacks. Auto MACsec is enabled by default and can be managed through the AP join profile using the GUI or CLI.</p> <p>Auto MACsec peer detection is supported on Wi-Fi 7 APs equipped with MACsec-capable physical layer (PHY) interfaces.</p>                                                                                                                |
| 6 GHz Country Support                                                           | <p>From Cisco IOS XE 26.2.1 onwards, 6 GHz radio support on supported Wi-Fi 6E and Wi-Fi 7 APs is added for Bosnia and Herzegovina (BA), North Macedonia (MK), Montenegro (ME), Ukraine (UA), Andorra (AD), Gibraltar (GI), Georgia (GE), El Salvador (SV), Isle of Man (IM), Moldova (MD), Namibia (NA), Paraguay (PY), and Togo (TG).</p> <p>This release also updates 5 GHz channel availability on supported Wi-Fi 7 access points. Support is added for Andorra, channels 149–165 are added for Bahrain, channels 36–165 are added for Togo, and channels 36–132 are added for Ukraine.</p> <p>For more information, refer to <a href="#">Cisco CW917x Wi-Fi 7 Access Point Country Codes and Phases</a>.</p>                                         |
| Regulatory Updates for Kuwait, Bahrain, and Ukraine                             | <p>From Cisco IOS XE 26.2.1 onwards, regulatory settings for supported Wi-Fi 6E and Wi-Fi 7 access points are updated for Kuwait, Bahrain, and Ukraine.</p> <p>In Kuwait, the maximum transmit power for the UNII-2C band is reduced from 30 dBm to 27 dBm. In Bahrain, the maximum transmit power for the UNII-3 band is limited to 23 dBm. In Ukraine, support is added for the UNII-1 and UNII-2 bands.</p> <p>These updates align access-point operation with the applicable regulatory requirements in each country.</p> <p>For more information, refer to <a href="#">Cisco CW917x Wi-Fi 7 Access Point Country Codes and Phases</a>.</p>                                                                                                            |
| UNII-2C Channel Support for Outdoor Access Points in Mexico                     | <p>From Cisco IOS XE 26.2.1 onwards, UNII-2C channels in the 5 GHz band are supported for outdoor deployments in Mexico on Cisco Catalyst 9124AXI, 9124AXD, and 9124AXE access points, Cisco Catalyst Wireless 9163E access points, and Cisco Wireless CW9179F access points operating with the outdoor configuration.</p> <p>This enhancement expands the 5 GHz channel availability for supported outdoor access points while maintaining compliance with Mexico's regulatory requirements.</p> <p>For detailed channel and maximum-power information, refer to the applicable Detailed Channels and Maximum Power Settings document. For CW9179F availability, refer to <a href="#">Cisco CW917x Wi-Fi 7 Access Point Country Codes and Phases</a>.</p> |

|                        |                                                           |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                    |
|------------------------|-----------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|                        | Support for Ethernet Encapsulation in CAPWAP Data Tunnels | <p>From Cisco IOS XE 26.2.1 onwards, supported Cisco Wi-Fi 6, Wi-Fi 6E, and Wi-Fi 7 access points use Ethernet encapsulation for client traffic transported through CAPWAP data tunnels. Instead of carrying client data using an 802.11 frame header, the access point and controller transport the traffic using an 802.3 Ethernet frame with 802.1Q encapsulation.</p> <p>The access point advertises its capability when it joins the controller, allowing the controller to select the appropriate encapsulation automatically. No additional configuration is required. Existing wireless-specific information, including RSSI and SNR data, continues to be carried in the CAPWAP header.</p> <p>During an ISSU, the controller supports a combination of access points using the existing and new encapsulation formats, enabling continued client traffic while access points are upgraded in stages.</p> |
|                        | Certificate Renewal Support for Secure AP Onboarding      | From Cisco IOS XE 26.2.1 onwards, supported Cisco Wireless APs can receive and apply renewed certificates through the Cisco Catalyst Center secure AP onboarding workflow. This enhancement helps maintain certificate-based AP authentication by allowing certificates to be renewed before expiration.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
|                        | Controller-directed URWB Traffic Support                  | This feature centralizes forwarding and traffic egress at the controller, enabling vehicle APs and their wired clients to maintain seamless connectivity while roaming across infrastructure subnets.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                              |
|                        | Network Address Translation on URWB                       | This feature enables multiple services on URWB mobile-unit networks to be accessed through a single external IP address using distinct TCP or UDP port mappings configured in the URWB network profile.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
| Ease of Use            | Extended GUI Session Idle Timeout Configuration           | This enhancement extends the configurable GUI idle-timeout beyond the current 20-minute maximum while keeping the default timeout unchanged. Customers can set longer timeouts—at least two hours—through CLI or YANG, preventing disruptive logouts during troubleshooting and other long-running activities while retaining control over their security posture.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
|                        | Secondary Ethernet Port Support (URWB)                    | This feature enables two wired interfaces in URWB deployments, allowing the primary and secondary Ethernet ports to be managed independently. It supports wired client connectivity, daisy-chaining, and mesh ring deployments without requiring external switches, improving deployment flexibility and cost efficiency. On supported Cisco Catalyst 9124AX Series access points, the secondary Ethernet port can also provide optional PoE-out to power downstream devices.                                                                                                                                                                                                                                                                                                                                                                                                                                      |
|                        | Multi-Controller Topology Awareness                       | This feature provides all controllers in a mobility group with visibility into URWB telemetry across the entire group. It synchronizes topology information between peer controllers, ensuring a consistent network state and a unified view of URWB nodes and links. This capability simplifies network monitoring and troubleshooting when a URWB network spans multiple controllers.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
| API Experience         | IOx Enablement                                            | IOx adds secure, Docker-based application hosting to the IW9165E, enabling custom applications, analytics, and third-party software to run locally at the network edge.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
| Operational Efficiency | Power Saving Modes                                        | Mapped digital I/O interfaces and IOx applications enable external control systems to place the IW9165E in light-sleep mode and restore it to active operation, reducing power consumption while retaining URWB backhaul connectivity.                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |

|                                  |                             |                                                                                                                                                                                       |
|----------------------------------|-----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Industrial Wireless Connectivity | URWB Support on CW9177I/D/E | URWB is now supported on all the CW9177 variants, such as CW9177I, CW9177D, and CW9177E.                                                                                              |
|                                  | Enable GPIO on IW9165E APs  | This feature exposes GPIO pins as /dev/dio-x character devices to IOx, allowing applications to monitor digital inputs, control external hardware signals, and manage LED indicators. |

## New hardware features

This section provides a brief description of the new hardware features introduced in this release.

**Table 2.** New hardware features for Cisco Catalyst 9800 Series Wireless Controllers, Release 26.2.1

| Feature                                                                  | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |
|--------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Support for Cisco Wireless 9177I, 9177D, and 9177E Wi-Fi 7 Access Points | <p>From Cisco IOS XE 26.2.1 onwards, the following Cisco Wireless 9177 Series Wi-Fi 7 access points are supported:</p> <ul style="list-style-type: none"> <li>• Cisco Wireless 9177I Series Wi-Fi 7 Access Point (CW9177I)</li> <li>• Cisco Wireless 9177D Series Wi-Fi 7 Access Point (CW9177D)</li> <li>• Cisco Wireless 9177E Series Wi-Fi 7 Access Point (CW9177E)</li> </ul> <p>The CW9177I, CW9177D, and CW9177E are tri-band access points that operate in the 2.4-GHz, 5-GHz, and 6-GHz bands. These access points interoperate with 802.11be, 802.11ax, and legacy clients and can be deployed alongside other access points and controllers in hybrid deployments.</p> <p>For a complete list of features and specifications, see the <a href="#">Cisco Wireless 9177 Series Wi-Fi 7 Access Point Data Sheet</a>.</p> <p><i>Note: For information about the countries in which these access points are supported, see the <a href="#">Cisco Wireless Compliance Tool</a>.</i></p> |
| Support for CW-ANT-T-D4-N, CW-ANT-T-O3-N, and CW-ANT-T-D3-N Antennas     | <p>From Cisco IOS XE 26.2.1 onwards, the CW-ANT-T-D4-N, CW-ANT-T-O3-N, and CW-ANT-T-D3-N antennas are supported on the Cisco Wireless 9177E Wi-Fi 7 Access Point.</p> <p>For antenna features and specifications, see the <a href="#">Cisco Wireless 9177 Series Wi-Fi 7 Access Point Data Sheet</a>.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                   |

## MIBs

The following MIBs have been modified:

- AIRESpace-WIRELESS-MIB.my
- CISCO-LWAPP-DOT11-CLIENT-MIB.my
- CISCO-LWAPP-DOT11-MIB.my
- CISCO-LWAPP-QOS-MIB.my
- CISCO-LWAPP-RF-MIB.my
- CISCO-LWAPP-RRM-MIB.my
- CISCO-WIRELESS-HOTSPOT-MIB.my

## Changes in behavior

This section provides a brief description of the behavior changes introduced in this release.

**Table 3.** Behavior changes for Cisco Catalyst 9800 Series Wireless Controllers, Release 26.2.1

| Description                                                                                                                   | Behavior changes                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
|-------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Updated Mesh PSK downgrade procedure                                                                                          | <p>MAP is unable to connect if authentication method is PSK, during the downgrade process from Cisco IOS XE 26.2 to an older release such as 17.18.x or 17.15.x.</p> <p>If you are using PSK for Mesh authentication and need to downgrade to a version that does not include this fix, follow these steps:</p> <ol style="list-style-type: none"><li>1. Before downgrade: Enable the default PSK.</li><li>2. After downgrade: MAPs should typically join the controller successfully if the provisioned PSK remains unchanged. If MAPs fail to join using PSK, perform these recovery steps:<ul style="list-style-type: none"><li>• Change the Mesh authentication method to EAP.</li><li>• Once the MAPs have joined the controller through EAP, run this command on the controller for each of the affected APs:<br/><b>ap name ap-name mesh security psk provisioning delete</b></li><li>• Change the Mesh authentication method back to PSK. The MAPs will join using the default PSK and then automatically update to the provisioned PSK.</li></ul></li><li>3. Once all APs have successfully joined the controller, disable the default PSK.</li></ol> |
| Accelerometer support – Integration of tilt information (accelerometer) into the <b>show ap config general</b> command output | <p>To improve the efficiency of physical installation monitoring, accelerometer data—specifically tilt angle and last update timestamp—were directly integrated into the <b>show ap config general</b> command and the <b>show tech wireless</b> output.</p> <p>This information was isolated within a specific, granular command, which hindered the ability to perform automated, large-scale detection of mounting or installation issues.</p> <p>Including this data in the general configuration summary will allow for streamlined, automated verification of AP physical orientation across the network.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
| YANG channel-width configuration fails with <b>band-default</b>                                                               | <p>YANG-based configuration fails when the channel-width range of a 5 GHz or 6 GHz RF profile uses <b>band-default</b> for either the minimum or maximum value while the other limit is explicitly configured. Examples include:</p> <ul style="list-style-type: none"><li>• 5 GHz: minimum <b>band-default</b>, maximum 80 MHz</li><li>• 6 GHz: minimum <b>band-default</b>, maximum 160 MHz</li></ul> <p>With the change in behavior, the YANG configuration now accepts <b>band-default</b> as either the minimum or maximum channel-width value when the other limit is explicitly configured with a valid value. This behavior is supported by both default and custom RF profiles in the 5-GHz and 6-GHz bands.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                      |

|                                                                 |                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
|-----------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Add GCMP-256 support for WPA3-Enterprise non-192-bit mode       | <p>WPA3 specification version 3.4 requires GCMP-256 support with 802.1X-SHA256 (AKM 5) and FT-802.1X (AKM 3) to enable MLO and EHT for Wi-Fi 7 WLANs. Currently, these AKMs support only CCMP-128 because configuration validation blocks GCMP-256, preventing compatible Wi-Fi 7 clients from associating.</p> <p>With the change of behavior, GCMP-256 can now be configured with AKM 3 and AKM 5 in WPA3-Enterprise non-192-bit mode, either as the only cipher or together with CCMP-128. This enables MLO/EHT-capable Wi-Fi 7 clients to associate in accordance with WPA3 specification.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |
| Update client details after an AP radio channel change          | <p>When an AP radio's channel is changed while a wireless client remains associated, the <b>show wireless client mac &lt;MAC&gt; detail</b> command on the controller continues to display the previous channel. The AP correctly operates on the new channel, but the client details are updated only after the AP state is toggled.</p> <p>The controller now updates the client's channel information when the associated AP radio changes channels. The show wireless client mac &lt;MAC&gt; detail command displays the current channel without requiring an AP state toggle.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
| NETCONF/YANG support for Regulatory Activation File (RAF)       | <p>In the earlier releases, you could activate regulatory domain on APs through CLI commands and through the GUI process ensuring compliance with regional regulations.</p> <p>With the change in behavior, NETCONF/YANG now supports Regulatory Activation File (RAF).</p> <p>The YANG paths are:</p> <ul style="list-style-type: none"> <li>• Cisco-IOS-XE-wireless-raf-cfg-rpc/apply-raf-config</li> <li>• Cisco-IOS-XE-wireless-raf-cfg-rpc/clear-country-ap-map</li> <li>• Cisco-IOS-XE-wireless-raf-cfg-rpc/clear-country-map-all-ap</li> </ul> <p>RPC-YANG support is added for the following RAF EXEC CLIs and <b>show</b> commands:</p> <ul style="list-style-type: none"> <li>• <b>ap regulatory activation file</b> <i>file-name</i></li> <li>• <b>ap regulatory activation apply</b></li> <li>• <b>ap regulatory activation clear all</b></li> <li>• <b>ap regulatory activation clear</b> <i>mac-address</i></li> <li>• <b>clear ap name</b> <i>ap-name</i> <b>country</b></li> <li>• <b>show ap regulatory activation all</b></li> <li>• <b>show ap regulatory activation mac</b> <i>mac-address</i></li> </ul> |
| Validate channel availability before enabling dual 5 GHz radios | <p>The controller previously allowed XOR 5/6 GHz radio to be changed to the 5 GHz band without verifying that the configured country supports enough channels for dual 5 GHz operation. This could result in an invalid configuration on band-locked radios and APs requiring 100-MHz separation between radio channels.</p> <p>The controller now checks the country-specific 5 GHz channel availability before changing an XOR 5/6 GHz radio to 5 GHz. If the required lower and upper-band channels are unavailable, the command is rejected, preventing unsupported dual 5 GHz operation.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                             |
| Display consistent URWB and power data in AP statistics         | <p>In the WebUI, the <b>General</b> tab under <b>Monitoring &gt; Wireless &gt; AP Statistics</b> does not consistently display data in the URWB and Power sections, resulting in incomplete or unreliable AP statistics.</p> <p>The <b>General</b> tab now consistently retrieves and displays URWB and Power information for the selected AP.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                            |

## Resolved issues

This table lists the resolved issues in this specific software release.

**Note:** This software release may contain bug fixes first introduced in other releases. To see additional information, click the bug ID to access the [Cisco Bug Search Tool](#).

**Table 4.** Resolved issues for Cisco Catalyst 9800 Series Wireless Controllers, Release 26.2.1

| Bug ID                     | Description                                                                                                                |
|----------------------------|----------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCww11377</a> | Refresh of Topology not happening post removal of any mesh-point from CURWB topology                                       |
| <a href="#">CSCwt36615</a> | Non-English Characters in CLI breaks the spacing                                                                           |
| <a href="#">CSCwt09514</a> | MAP is unable to connect if authentication method is PSK - AP                                                              |
| <a href="#">CSCwv47563</a> | Flex mode APs loses auth token and fails to come up on controller when moving across 9800-CL running on different versions |
| <a href="#">CSCwr07706</a> | C9120 txerr noticed followed by Dot11BaseDriver Recover for cause : 48 - Toggling radio                                    |
| <a href="#">CSCwr81031</a> | Memory leak on 9176 APs on kmallocl slabs                                                                                  |
| <a href="#">CSCws27309</a> | CW9162I-ROW APs are disjoining from 9800-CL running 17.12.04 - SMU-PATCHED                                                 |
| <a href="#">CSCws32577</a> | 9130 RAP, systemd[1]: capwapd.service watchdog timeout (limit 1min 30s)! , continuously reloading and not joining to wlc   |
| <a href="#">CSCws66689</a> | When RLAN port 1 is connected 9172H sends DHCP discover out of wired1 instead of wired0                                    |
| <a href="#">CSCws67290</a> | Radio crash corrupted coredump is seen on AP CW9174I                                                                       |
| <a href="#">CSCws68479</a> | Missing support for certain bands and channels in wifi6/6e regdb                                                           |
| <a href="#">CSCws68505</a> | AP crash due to kernel panic                                                                                               |
| <a href="#">CSCws68847</a> | OOM crash observed after overnight run                                                                                     |
| <a href="#">CSCws77227</a> | AP CW9176I kernel panic crash                                                                                              |
| <a href="#">CSCws77337</a> | 9166 SDA APs having image download issues due to /tmp not having enough space caused by sdavc App pack                     |
| <a href="#">CSCws80385</a> | AP CW9176I kernel panic random crash                                                                                       |
| <a href="#">CSCws83579</a> | Radio Firmware crash seen while performing uplink                                                                          |
| <a href="#">CSCws87617</a> | 9130 not able to upgrade to 17.18.2 CCO image due to another upgrade is still in progress                                  |
| <a href="#">CSCws93044</a> | AP does not transmit beacons for over one second right after the client connects                                           |
| <a href="#">CSCwt01278</a> | 9115/9120 APs facing kernel panic crashes in 17.18.2                                                                       |

|                            |                                                                                                         |
|----------------------------|---------------------------------------------------------------------------------------------------------|
| <a href="#">CSCwt02580</a> | 9172H/9179: Kernel panic seen at reg_get_sp_eirp                                                        |
| <a href="#">CSCwt05272</a> | AP 9120 crashed due to Kernal Panic                                                                     |
| <a href="#">CSCwt08175</a> | AP Kernel Panic due to Use-After-Free Race Condition in SPSCPriorityQueue::push()                       |
| <a href="#">CSCwt18007</a> | Pre-commit CDT failure   9120 AP crash<br>_ZN15IsCapwapEnabled4pushEiP6Packet+0x3c/0x130                |
| <a href="#">CSCwt19011</a> | 9166 17.15.4b AP in SDA mode not forwarding IPv4 ARP upstream or other IPv4 packets after DHCP          |
| <a href="#">CSCwt19117</a> | Dot11u config is removed from AP so AP stops beaconing with dot11u impacting OpenRoaming                |
| <a href="#">CSCwt19490</a> | 9800 WLC: Stale client IP used in RADIUS accounting causes ISE IP\u2013SGT/SXP overwrite                |
| <a href="#">CSCwt20299</a> | Application traffic is using wired0 as egress interface instead of auxiliary client interface           |
| <a href="#">CSCwt24610</a> | gaps in panic log - /dev/kmsg tail is not reflecting correctly in panic log                             |
| <a href="#">CSCwt26500</a> | Need changes for CSCwq11842 to work in all AP models                                                    |
| <a href="#">CSCwt33908</a> | PHY OFF error assert causing AP crash during longevity tests                                            |
| <a href="#">CSCwt50389</a> | Ascom Myco2 phones are not able to connect to 9176 APs due to EAP_ID_REQ or M2 not acked by AP          |
| <a href="#">CSCwt64349</a> | observing kfence calltrace on multiple AP models                                                        |
| <a href="#">CSCwt65349</a> | CW9172I AP crashes with ar_wal_mlo_ipc.c assert and watchdog panic                                      |
| <a href="#">CSCwt72800</a> | CW9176I AP crash due to kernel panic with pc do_undefinstr+0x30/0x50                                    |
| <a href="#">CSCwt74576</a> | Cisco Catalyst 9136 AP wcpd process memory increasing gradually                                         |
| <a href="#">CSCwt78829</a> | Memory Leak in python Process on Wireless Active Testing (WAT) AP with TEAgent IOx Application          |
| <a href="#">CSCwt80663</a> | Tier E countries + RAF not working                                                                      |
| <a href="#">CSCwt83641</a> | CW9172 AP radio forwarding failure in upstream path                                                     |
| <a href="#">CSCwt88263</a> | Pre-commit CDT failure-12   AP crash kmem_cache_free+0x150/0x2c8                                        |
| <a href="#">CSCwt92054</a> | 9176 not processing CTS packets when configured with datarate 36M and channel width 40M or higher       |
| <a href="#">CSCwu04935</a> | 9178: AP continuously reloading with \"NSS CAPWAP tunnel creation failed\" log when vlan-tag is enabled |
| <a href="#">CSCwu08256</a> | AP unable to join back to the controller after dropping from the controller                             |
| <a href="#">CSCwu13170</a> | 9176 AP has Kernel panic, pc: find_busiest_group                                                        |
| <a href="#">CSCwu14554</a> | 9105/9172H RLAN AP not passing multicast traffic for central switching                                  |

|                            |                                                                                                                                |
|----------------------------|--------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCWu18918</a> | AP not completing DHCPv6 after dropping from the controller                                                                    |
| <a href="#">CSCWu20280</a> | 9176 AP crashing due to kernel panic at wlan_sm_dispatch+0xb8/0x208 [umac]                                                     |
| <a href="#">CSCWu27163</a> | 9120 and 9130 APs see WhereCall V RFID it's configured for 5.5M rate but they don't transmit packet to WLC, while 2800 does    |
| <a href="#">CSCWu42085</a> | 9120 kernel panic crash at wlc_twt_scb_get_schedid+0x34/0x170 [wl] & txq_hw_fill+0x8c8/0xff8 [wl]                              |
| <a href="#">CSCWu52744</a> | C9120 COS AP crash PC is at phy_ac_noise_lte_avg LR is at phy_noise_lte_avg                                                    |
| <a href="#">CSCWu52745</a> | C9120 COS AP crash PC is at sysfs_remove_bin_file LR is at lp55xx_unregister_sysfs                                             |
| <a href="#">CSCWu66197</a> | C9130AXI AP crashed due to Kernel panic after upgrading to 17.15.5.201(APSP 1)                                                 |
| <a href="#">CSCWu66664</a> | AP 9136 crashes generating capwapd core                                                                                        |
| <a href="#">CSCWu84328</a> | Client connectivity issues on 9176 AP due to scheduler stuck                                                                   |
| <a href="#">CSCWu96123</a> | 9120 AP reload due to Radio firmware beacon TX stuck                                                                           |
| <a href="#">CSCWv08841</a> | Client connectivity issues on AP due to scheduler stuck                                                                        |
| <a href="#">CSCWv11776</a> | COS AP as WGB wired client unable to pass traffic randomly                                                                     |
| <a href="#">CSCWv17189</a> | Possible kernel slab leak in 17.15.4bESW1 EWC RAP                                                                              |
| <a href="#">CSCWv30224</a> | CW9172I running 17.18.3.18 crashes in RRMReceive::process_rx_frame_from_driver                                                 |
| <a href="#">CSCWv36063</a> | Wifi6E and Wifi7 APs disconnecting all clients in 6ghz when bss-color change occur even if globally disable                    |
| <a href="#">CSCWv44721</a> | Image upgrade failure: opkg_verify cost long time causing capwapd watchdog timeout.                                            |
| <a href="#">CSCWv45612</a> | 9120 crashing due to kernel panic with PC at __delay in 17.18.2                                                                |
| <a href="#">CSCWv52872</a> | AP may get stuck on boot when console is connected to unterminated cable (minimal fix)                                         |
| <a href="#">CSCWv52931</a> | When EWC AP in mesh mode (with PSK provisioning) is factory reset, the RAP must be reloaded in order for existing MAPs to join |
| <a href="#">CSCWr00948</a> | Access points connected to 9xxx PoE ports cannot negotiate full power after switch power outage                                |
| <a href="#">CSCWr97166</a> | Regdb update to fix all issues caught using new scripts                                                                        |
| <a href="#">CSCWs35315</a> | Auxiliary-client interface taking over the CAPWAP connection from the AP                                                       |
| <a href="#">CSCWs47852</a> | AP intermittently joins WLC but WLC fails to get AP type resulting AP being rejected                                           |
| <a href="#">CSCWs70285</a> | Clean up for /storage/cnssdaemon.log                                                                                           |
| <a href="#">CSCWs72425</a> | 9136I IOX application activation failure                                                                                       |

|                            |                                                                                                                                              |
|----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCws79118</a> | Unexpectedly reduced transmit power for 9124-AXE on 2.4 GHz in -Z regulatory domain                                                          |
| <a href="#">CSCws93536</a> | Panic log missed from AP crashfile when minidump is enabled                                                                                  |
| <a href="#">CSCwt13894</a> | CW9172H WAT Agent fails to connect to SSIDs with leading or trailing spaces                                                                  |
| <a href="#">CSCwt43633</a> | C9166/C9176 AP Bad Intf: Dropped Corrupted Interferer Stream message continuously noticed on AP console                                      |
| <a href="#">CSCwt47537</a> | Kernel: BUG: KFENCE: memory corruption in   use-after-free write in   use-after-free read in. In ap version 17.12.6.28                       |
| <a href="#">CSCwt49364</a> | ThousandEyes Endpoint Agent upgrade leads to duplicated agent in Active Testing AP                                                           |
| <a href="#">CSCwt51709</a> | COS APs initiate DHCP process even when static IP is configured, causing intermittent DHCP Fallback issues                                   |
| <a href="#">CSCwt68617</a> | FT-SAE in Flex Standalone mode does not allow client association                                                                             |
| <a href="#">CSCwt71378</a> | Multiple APs hit bootloader failure after repeated reset testing                                                                             |
| <a href="#">CSCwt77092</a> | AP - KFENCE memory corruption events lead to RCU stalls and HW watchdog reset                                                                |
| <a href="#">CSCwt77136</a> | continuous KFENCE IPv6 MLD memory corruption leads to RCU stalls and HW watchdog reset                                                       |
| <a href="#">CSCwt88383</a> | 9172I AP is crashing with pc : dp_rx_mon_process_2_0+0x26c0/0x28c0 [monitor]                                                                 |
| <a href="#">CSCwt99080</a> | CleanAir Spectrum AP Type Invalid                                                                                                            |
| <a href="#">CSCwu17010</a> | 9120 AP forwards HE PHY Capability bitset with 40 / 80 MHz supported when configured 20 MHz only channel width                               |
| <a href="#">CSCwu17364</a> | DHCP for Personal SSID on OEAP enabled after AP reboot.                                                                                      |
| <a href="#">CSCwu35228</a> | 9136 APs sending Accounting packet to AAA server when local-accounting is disabled                                                           |
| <a href="#">CSCwu52776</a> | C9120 COS AP crash due to: RHL Probe failure, reboot to recover                                                                              |
| <a href="#">CSCwu54425</a> | C9120 COS AP crash PC is at _ZN7Element19read_cycles_handlerEPS_Pv                                                                           |
| <a href="#">CSCwu65418</a> | 17.15.5 Catalyst 9176 5Ghz high retry rate                                                                                                   |
| <a href="#">CSCwu70466</a> | 9136 APs sends interim accounting packet in Central auth/accounting configs                                                                  |
| <a href="#">CSCwu88097</a> | FIPS mode: AP is still offering SHA1 algorithms                                                                                              |
| <a href="#">CSCwu94430</a> | C9800: bytes_rx/bytes_tx in client traffic statistics is incrementing by ~2^32 periodically                                                  |
| <a href="#">CSCwu98499</a> | 9105AW WGB mode, ports 1/2/3 do not go up in 17.15/17.18                                                                                     |
| <a href="#">CSCwv20470</a> | Clients obtain an IP address from the VLAN mapped under the Policy Profile instead of the VLAN assigned by AAA Override.Flex local-auth roam |
| <a href="#">CSCwv40607</a> | WAT reports wrong DNS IPs from previous connections in ThousandEyes                                                                          |

|                             |                                                                                                                                                       |
|-----------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCCwy58521</a> | APs advertise invalid Maximum Transmit Power (-99 dBm) in 5 GHz Country Information IE when configured with Bolivia (BO) country code                 |
| <a href="#">CSCCww06803</a> | AP kernel crash in ieee80211_session_timeout_iter_cb() due to stale node reference                                                                    |
| <a href="#">CSCCww07021</a> | AwipsRadioEncap can access released packet memory during header expansion                                                                             |
|                             |                                                                                                                                                       |
| <a href="#">CSCCwt39252</a> | 17155 - Client loses connectivity during ISSU upgrade form 17.12.4ESW15 to 17.15.5                                                                    |
| <a href="#">CSCCwq66623</a> | SJC Alpha - 17.18.2 alpha APs not joining controller- stuck in DTLS                                                                                   |
| <a href="#">CSCCwr20303</a> | Controller unexpected reload after modifying ap location name config due to stale oid for AP                                                          |
| <a href="#">CSCCwr65627</a> | Large number of APs (2K+) take several minutes to join N+1 WLC when Primary goes down                                                                 |
| <a href="#">CSCCwr67652</a> | wlc mem is noticed due to wsa_db                                                                                                                      |
| <a href="#">CSCCwr90981</a> | AP count varying in 5GHz radio                                                                                                                        |
| <a href="#">CSCCws16148</a> | WLC Crash after issuing the command \" ap geolocation ranging accurate method uwbl\"                                                                  |
| <a href="#">CSCCws18528</a> | [APCI] MLO Rogue Containment for all bands is not working                                                                                             |
| <a href="#">CSCCws23072</a> | RRM Crashes and tracebacks observed on CW9800 Platform                                                                                                |
| <a href="#">CSCCws38733</a> | ap ranging CLI triggers a WLC switchover and core file is created                                                                                     |
| <a href="#">CSCCws39889</a> | RF Based AP Load Balancing: WLC Crash due to observed during load balancing algo run                                                                  |
| <a href="#">CSCCws42581</a> | Memory corruption in L2 multicast while handling dynamic multicast router ports and group                                                             |
| <a href="#">CSCCws47700</a> | WGB roaming may trigger a wncd process unexpected reload and wireless controller reload due to mac_theft                                              |
| <a href="#">CSCCws58494</a> | WebAuth Clients moved to RUN State on the WLC but it is stuck in WebAuth on the AP                                                                    |
| <a href="#">CSCCws58703</a> | SST: ndbmand cores are seen after ISSU upgrade from 17.15.x to 17.18.2 with CatC, NETCONF not working                                                 |
| <a href="#">CSCCws65956</a> | Controller crash with wncmgrd has been helddown (rc 139)                                                                                              |
| <a href="#">CSCCws68160</a> | WLC Unexpected reload with Critical process wncd fault on rp_0_0 (rc=139) after client deletion due to continuous IP Theft                            |
| <a href="#">CSCCws68876</a> | Unexpected reload due to ISSU client ISSU Virtual-Template Client                                                                                     |
| <a href="#">CSCCws76688</a> | Client stuck in AUTHENTICATING state on Catalyst 9800 when OKC is enabled in Flex mode AP \u2013 EAP Identity Request sent after 4\u2013Way Handshake |
| <a href="#">CSCCws91899</a> | C9800 Crash while processing Flex Connect Client                                                                                                      |

|                            |                                                                                                                  |
|----------------------------|------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCws93542</a> | Post failover DHCP Offer is not forwarded by the WLC to the client                                               |
| <a href="#">CSCwt07093</a> | APs not being able to connect due capwap messages being queued due to fragments drop                             |
| <a href="#">CSCwt09034</a> | DTLS Alert Message processing and Open SSL Decryption on C9800-CL leads to watchdog crash in WNCD                |
| <a href="#">CSCwt13732</a> | WNCD process terminated causing WLC to crash. Critical process wncd has failed (rc 0)) triggerd wired WGB client |
| <a href="#">CSCwt22893</a> | WLC unexpected SISF reboot with WNCD core on 17.18.2                                                             |
| <a href="#">CSCwt26121</a> | APMGR - Code Scan fixes for APMGR                                                                                |
| <a href="#">CSCwt31565</a> | Wireless Clients Stuck in RUN State on Cisco 9800-40-K9 Running 17.12.6a                                         |
| <a href="#">CSCwt31826</a> | Constant switchover and/or reload due to SIGSEGV on rogued process                                               |
| <a href="#">CSCwt37351</a> | The wncd process unexpected finish due to an invalid handler-id for a a radio wlan id and wlc may reload         |
| <a href="#">CSCwt38788</a> | The mobility process ends unexpectedly due to an uninitialized variable; wlc may be reloaded.                    |
| <a href="#">CSCwt52617</a> | Post SSO - Few wireless clients experiences loss of connectivity to devices outside the Fabric                   |
| <a href="#">CSCwt52815</a> | WLC fails to update associated Channel width for client after it is changed on AP radio.                         |
| <a href="#">CSCwt87508</a> | During Capture Enable Device Experienced an Unexpected Reload                                                    |
| <a href="#">CSCwt91818</a> | C9800 WLC crash during APSP installation due to stale old APSP entry not correctly removed                       |
| <a href="#">CSCwt98619</a> | CW9800L PID is missing in ISSU comp_matrix file                                                                  |
| <a href="#">CSCwu00043</a> | 17.18.3: LSC certificate failure \" CRYPTO_PKI: Failed to add ca req pool entry 538\" in scale environment       |
| <a href="#">CSCwu08974</a> | C9800 wncd crashes on ARP probe debug log                                                                        |
| <a href="#">CSCwu52200</a> | C9800 Unexpected Reload After a wired guest client joins that previously joined as wireless                      |
| <a href="#">CSCwu77375</a> | RRM DCA is not happening with AP9167EH slot1 configured as backhaul and slot2 as client serving                  |
| <a href="#">CSCwu92389</a> | RMI link flaps logs on WLC but no switchover happens                                                             |
| <a href="#">CSCwv33315</a> | wncd crash (SIGABRT) - heap buffer overflow in CAPWAP TX completion path                                         |
| <a href="#">CSCwv33856</a> | WLC experiences a WNCD process leak due to country code resolution failure                                       |
| <a href="#">CSCwv40125</a> | 26.2.1eft11 AP recovery failure and WNCD Crash during HA switchover                                              |
| <a href="#">CSCwv41569</a> | SSID Broadcast Failure with Overnight Calendar Profile Schedule                                                  |

|                            |                                                                                                                                                    |
|----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCwv77065</a> | WLC9800 ACR full-replace fails for AP filter priority mapping changes due to intermediate-state validation                                         |
| <a href="#">CSCwq81507</a> | Extend the timeout for IoT_Orchestrator delete operation                                                                                           |
| <a href="#">CSCwr30777</a> | 9800 standby chassis shows Cisco Unknown Power Supply and same SN on output from \" show inventory\" 17.12.4                                       |
| <a href="#">CSCwr74373</a> | C9800 WLC Accounting-Request packets are not sent when an ungraceful disassociation takes place                                                    |
| <a href="#">CSCwr79853</a> | In file manager, when selecting one file in the location box, download fails                                                                       |
| <a href="#">CSCwr80088</a> | Site tag and policy tag are not mapped correctly to 9130AP on controller                                                                           |
| <a href="#">CSCwr96860</a> | Antenna Gain configuration via RESTCONF RPC fails for AP models 3800E and 9120AXE \u2014 \u2014slot: 0 does not have a dedicated radio\u201d error |
| <a href="#">CSCws10863</a> | 9800 - APs with an unresolved regulatory domain stop RRM from running for other APs                                                                |
| <a href="#">CSCws17199</a> | Add GCMP256 support in WPA3 enterprise(non-192-bit)                                                                                                |
| <a href="#">CSCws17518</a> | Unexpected reload after running a command on a WLC                                                                                                 |
| <a href="#">CSCws17702</a> | PAED process crashes every 24 after record pruning and DB query errors.                                                                            |
| <a href="#">CSCws19686</a> | Configuring duplicate AP names results in \" Internal Error, Check Logs\" instead of duplicate name warning                                        |
| <a href="#">CSCws22542</a> | 17.15.3 6GHz band support missing for Turkey in RW domain                                                                                          |
| <a href="#">CSCws26758</a> | WLC client entries causing AP to reach max number of clients per radio                                                                             |
| <a href="#">CSCws30144</a> | Cloud services OTP token for Virtual Wireless Controller disappears in some edge cases                                                             |
| <a href="#">CSCws31123</a> | Client deleted after CoA reauth with URL redirect                                                                                                  |
| <a href="#">CSCws31873</a> | Media-Stream and Multicast traffic fails after SSO when GTK key-rotation is enabled                                                                |
| <a href="#">CSCws46519</a> | When running \" show ap lldp neighbor\" on the WLC, outdated information continues to persist.                                                     |
| <a href="#">CSCws49525</a> | SIT: CleanAir Pro - Spectral Capture; fails to provide: spectral_recording directory/file on eWLC despite: Upload-Response (Success)               |
| <a href="#">CSCws62182</a> | the GUI displays the channel Bandwidth (Negotiated/capable) wrong                                                                                  |
| <a href="#">CSCws66137</a> | Client association time shown as \" 01/01/1970 00:00:00\" while local authentication (no central authentication) is in place                       |
| <a href="#">CSCws80754</a> | Local DHCP on Anchor WLC intermittently stops forwarding DHCP OFFER or ACK                                                                         |
| <a href="#">CSCws82703</a> | selinux: qwlc: subject polaris_iosd_t denials 2026-01-16 11:14:35 - while trying to access installation file from webui                            |

|                            |                                                                                                                                                                           |
|----------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCws83128</a> | AP rename fails with false \u201cAP name already exists\u201d conflict for a specific hostname string (not present in AP database), controller reverts AP to default name |
| <a href="#">CSCws93326</a> | SJC Alpha 26.1.1 ERR Logs: (ERR): MAC: 0000.0000.0000 \u00a0Set RA trace entry for multi link client. Unable to fetch dot11 operational data                              |
| <a href="#">CSCwt08276</a> | RF Based AP Load Balancing: Algorithm issues could cluster scattered APs                                                                                                  |
| <a href="#">CSCwt20158</a> | bsnMobileStation showing only a few clients - root cause is Wifi7                                                                                                         |
| <a href="#">CSCwt21195</a> | Default 6 GHz RF profile cannot be selected when creating a new location.                                                                                                 |
| <a href="#">CSCwt25978</a> | Wireless bundle client does not work with site tag space in name                                                                                                          |
| <a href="#">CSCwt40423</a> | Cloudm Tracebacks running out of ID                                                                                                                                       |
| <a href="#">CSCwt41808</a> | wncmgrd Process Crash Due to Invalid String Pointer during AP Join AVL Tree                                                                                               |
| <a href="#">CSCwt41939</a> | TMPFS Memory leak in IOS_PRIV_OPER_DB tbl_ewlc_critical_events table after selinux denials                                                                                |
| <a href="#">CSCwt43333</a> | XPath configuration failure for APs(9120/9166) in sniffer mode and for 9120 when radio role is sniffer                                                                    |
| <a href="#">CSCwt58885</a> | 'debug wireless bundle client start ap-archive site-tag \"my site\" level critical monitor-time 60' does not work when the site tag name contains spaces                  |
| <a href="#">CSCwt61816</a> | Monitoring > Wireless Clients shows an incorrectly large client count                                                                                                     |
| <a href="#">CSCwt72694</a> | Catalyst Center Sending Invalid/Legacy License Activation Command Syntax - C9500-40X                                                                                      |
| <a href="#">CSCwt84933</a> | Channels 100-140 are available for Nigeria, but they are licensed spectrum                                                                                                |
| <a href="#">CSCwt87345</a> | 9800 clear wireless device-tracking counters vlan < vlanid > not working                                                                                                  |
| <a href="#">CSCwt95088</a> | No Duty Cycle present in Persistent device output                                                                                                                         |
| <a href="#">CSCwt98260</a> | NameServer Configuration mandatory for AWIPS even if URL points to an IP address instead of FQDN                                                                          |
| <a href="#">CSCwu20316</a> | 9800 showing dot1x pmf client deauth as CLIENT_DELETE_REASON_CLIENT_EAP_TIMEOUT_FAILURE                                                                                   |
| <a href="#">CSCwu32896</a> | LWA Controller not sending redirection HTTP 200 for FlexConnect APs due to client ip address not learned for webauth                                                      |
| <a href="#">CSCwu42825</a> | Wifi7 syslogs are generating in WLC in large numbers                                                                                                                      |
| <a href="#">CSCwu71312</a> | 17.18 : Support -A, -B domain support for Honduras indoor                                                                                                                 |
| <a href="#">CSCwu76364</a> | CLUS26 - Client Telemetry status is Fair                                                                                                                                  |
| <a href="#">CSCwu86004</a> | 9800 deauthenticates client when receiving DHCP RELEASE from client.                                                                                                      |
| <a href="#">CSCwv31549</a> | Incorrect Client Exclusion reasons on bsnStationBlacklistingReasonCode traps                                                                                              |
| <a href="#">CSCwv38974</a> | 9800 crash due to unexpected values in 6ghz channel power payload                                                                                                         |

## Open issues

This table lists the open issues in this specific software release.

**Note:** This software release may contain open bugs first identified in other releases. To see additional information, click the bug ID to access the [Cisco Bug Search Tool](#).

**Table 5.** Open issues for Cisco Catalyst 9800 Series Wireless Controllers, Release 26.2.1

| Bug ID                     | Description                                                                                                                                                    |
|----------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|
| <a href="#">CSCWv09937</a> | URWB: issue with Wi-Fi-client connectivity when mobile primary unit is restored after failover                                                                 |
| <a href="#">CSCww25465</a> | Topology Awareness: Coordinator dropdown fails to list coordinators with network names after Coordinator/Node AP moves between WLCs in the same mobility group |
| <a href="#">CSCWu65611</a> | DHCP Offer Received by C9800 but Not Forwarded to AP/Client on VLAN 155 Resulting in Intermittent DHCP Failures                                                |
| <a href="#">CSCWu92593</a> | AP 9176I IPV6 RA packet drop using SLAAC                                                                                                                       |
| <a href="#">CSCWv27458</a> | AP crashed due to kernel panic with different PC and LR                                                                                                        |
| <a href="#">CSCWv40579</a> | CW9176I AP crash due to kernel panic                                                                                                                           |
| <a href="#">CSCWv47361</a> | AP CW9166 in fabric deployment does not send upstream mDNS queries/responses after upgrade to 17.15.5                                                          |
| <a href="#">CSCWv53150</a> | 9166 dropping upstream dot11ax QoS data packets after bss-color change causing client disassoc                                                                 |
| <a href="#">CSCWv53177</a> | 9120 running 17.18.3 crashing due to _ZNK6String5derefEv                                                                                                       |
| <a href="#">CSCWv71535</a> | 9176 in flex mode doesn't forward ipv6 RA for stateful DHCPv6 downstream client                                                                                |
| <a href="#">CSCWv84099</a> | OOB predownload fails with Unknown Error From Server                                                                                                           |
| <a href="#">CSCWv85898</a> | Controller mobility tunnel drops randomly on 17.12.6a.                                                                                                         |
| <a href="#">CSCWv90808</a> | 9120 channel mismatch between wcpd and driver causing AP to detect own BSSIDs as rogue for 24ghz                                                               |
| <a href="#">CSCWv97545</a> | 9800 EHSA fsm: EHSA standby down, HA/SSO reloads both units                                                                                                    |
| <a href="#">CSCww11976</a> | 9136 radio reset due to beacon stuck in slot 3 6ghz after switch upgrade                                                                                       |
| <a href="#">CSCws76413</a> | CW9800M Raised Authentication failure as Sub-block is missing                                                                                                  |
| <a href="#">CSCWu62311</a> | AP crash - Kernel panic nss_core_handle_cause_queue                                                                                                            |
| <a href="#">CSCWv22511</a> | Client detail for some Associated Client doesn't show info element when using Cisco Spaces Connector                                                           |
| <a href="#">CSCWv54843</a> | WLC \"show ap wlan summary\" command shows inflated client count                                                                                               |
| <a href="#">CSCWv61312</a> | Client deletion on WLC due to IP Learn timeout after roam                                                                                                      |

|                            |                                                                                        |
|----------------------------|----------------------------------------------------------------------------------------|
| <a href="#">CSCww71860</a> | 9115 & 9120 AP crashed due to kernel panic with reason \"console_unlock+0x288/0x284 \" |
| <a href="#">CSCww82245</a> | CW9179 APs absent from bsnAP SNMP tables while older APs populate correctly            |
| <a href="#">CSCww84920</a> | Unable to delete the RAF file from WLC running 17.18.3                                 |
| <a href="#">CSCww10073</a> | UTF tracelogs exceed maximum allowed size in 9800-CL                                   |
| <a href="#">CSCww17212</a> | C9115AP Radio reset happened due to radio firmware crash                               |
| <a href="#">CSCww21004</a> | Swapping primary and secondary controller name on Bulk AP Provisioning gives an error  |

## Known issues

The known issues for Cisco IOS XE 26.2.1 include:

### Wireless clients cannot join or roam after an ISSU abort from Cisco IOS XE 26.2.1

If an ISSU from Cisco IOS XE 26.2.1 is aborted and the wireless controller reverts to an earlier release, such as Cisco IOS XE 17.18 or 26.1.1, the APs might remain on release 26.2.1 and continue using the updated local MAC behavior.

Since the reverted controller does not contain the code required to process the new anchor requests from these APs, new wireless clients cannot join the network, and existing clients cannot roam successfully. As a result, affected clients are denied network access.

## Compatibility

### Compatibility matrix

The following table provides software compatibility information. For more information, refer to [Cisco Wireless Solutions Software Compatibility Matrix](#).

**Table 6.** Compatibility Matrix for Cisco Catalyst 9800 Series Wireless Controllers, Release 26.2.1

| Cisco Catalyst 9800 Series Wireless Controller Software | Cisco Identity Services Engine                                   | Cisco Catalyst Center                                                      | Cisco CMX |
|---------------------------------------------------------|------------------------------------------------------------------|----------------------------------------------------------------------------|-----------|
| IOS XE 26.2.1                                           | 3.4<br>3.3<br>3.2<br>3.1<br>3.0<br><br>* all with latest patches | Refer to <a href="#">Cisco Catalyst Center Compatibility Information</a> . | 11.1.1    |

## Software requirements

Operating Systems:

- Windows 10 or later
- macOS X 10.11 or later

Browsers:

- Google Chrome: Version 59 or later (on Windows and Mac)
- Microsoft Edge: Version 40 or later (on Windows)
- Safari: Version 10 or later (on Mac)
- Mozilla Firefox: Version 60 or later (on Windows and Mac)

Note that Firefox version 63.x is not supported.

The controller GUI uses Virtual Terminal (VTY) lines for processing HTTP requests. At times, when multiple connections are open, the default number of VTY lines of 15 set by the device might get exhausted. Therefore, we recommend that you increase the number of VTY lines to 50.

To increase the VTY lines in a device, run the following commands in the following order:

```
Device# configure terminal
```

```
Device(config)# line vty 50
```

The best practice is to configure the service tcp-keepalives to monitor the TCP connection to the device.

```
Device(config)# service tcp-keepalives-in
```

```
Device(config)# service tcp-keepalives-out
```

## Before you upgrade

Ensure that you familiarize yourself with the following points before proceeding with the upgrade:

- If you have APs in remote sites, behind a WAN link, read the following document to accelerate the image download and make it more reliable:  
<https://www.cisco.com/c/en/us/support/docs/wireless/catalyst-9800-series-wireless-controllers/223125-understand-access-point-image-upgrades.html>.
- When you upgrade from Cisco IOS XE 17.9.5 or lower, or 17.12.2 or lower, to Cisco IOS XE 17.18.2, the controller WebUI does not support images greater than 1.5 GB.

Workaround:

- Upgrade using the CLI commands, or,
- Upgrade to 17.9.6, 17.12.3, or higher, then upgrade to 17.18.2 or later.
- For images: If upgrading from 17.9.6 or lower, 17.12.4 or lower, or 17.15.1 or lower, to 17.18.2, Cisco Catalyst Wi-Fi 6 APs may fail to upgrade their image due to lack of space on the temporary partition.

Workaround:

- Reboot the impacted APs using a power cycle, then proceed to upgrade normally.

For more information, refer to [CSCwm08044](#) and [CSCwm07499](#).

- APs running older release code (before 8.10.190.0, 17.3.8, 17.6.5, 17.9.3 or older), may get into a boot loop when upgrading software over a WAN link. For more information, refer to :

<https://www.cisco.com/c/en/us/support/docs/wireless/catalyst-9800-series-wireless-controllers/220443-how-to-avoid-boot-loop-due-to-corrupted.html>.

- The following Wave 1 APs are not supported in 17.18.2 and higher, and they will not join the controller. We recommend that you validate the current models before upgrading:
  - Cisco Aironet 1570 Series Access Point
  - Cisco Aironet 1700 Series Access Point
  - Cisco Aironet 2700 Series Access Point
  - Cisco Aironet 3700 Series Access Point
- From Cisco IOS XE Dublin 17.10.x, Key Exchange and MAC algorithms like diffie-hellman-group14-sha1, hmac-sha1, hmac-sha2-256, and hmac-sha2-512 are not supported by default and it may impact some SSH clients that only support these algorithms. If required, you can add them manually. For information on manually adding these algorithms, refer to the SSH Algorithms for Common Criteria Certification document available at:  
[https://www.cisco.com/c/en/us/td/docs/routers/ios/config/17-x/sec-vpn/b-security-vpn/m\\_sec-secure-shell-algorithm-ccc.html](https://www.cisco.com/c/en/us/td/docs/routers/ios/config/17-x/sec-vpn/b-security-vpn/m_sec-secure-shell-algorithm-ccc.html).
- If APs fail to detect the backup image after running the archive download-sw command, perform the following steps:
  - Upload the image using the no-reload option of the archive download-sw command:  

```
Device# archive download-sw /no-reload tftp://<tftp_server_ip>/<image_name>
```
  - Restart the CAPWAP process using **capwap ap restart** command. This allows the AP to use the correct backup image after the restart (reload is not required.)  

```
Device# capwap ap restart
```

The AP will lose connection to the controller during the join process. When the AP joins the new controller, it will see a new image in the backup partition. So, the AP will not download a new image from the controller.
- The use of MTU lower than 1500 on G0 (OOB) interface that may cause fragmentation for RADIUS packets for client authentication, is not supported.
- While upgrading to Cisco IOS XE 17.3.x and later releases, if the **ip http active-session-modules none** command is enabled, you will not be able to access the controller GUI using HTTPS. To access the GUI using HTTPS, run the following commands in the order specified below:  

```
ip http session-module-list pkilist OPENRESTY_PKI  
ip http active-session-modules pkilist
```
- Cisco Aironet 1815T OfficeExtend Access Point will be in local mode when connected to the controller. However, when it functions as a standalone AP, it gets converted to FlexConnect mode.
- The Cisco Catalyst 9800-L Wireless Controller may fail to respond to the BREAK signals received on its console port during boot time, preventing users from getting to the ROMMON. This problem is observed on the controllers manufactured until November 2019, with the default config-register setting of 0x2102. This problem can be avoided if you set config-register to 0x2002.

This problem is fixed in the 16.12(3r) ROMMON for Cisco Catalyst 9800-L Wireless Controller.

---

For information about how to upgrade the ROMMON, refer to the Upgrading ROMMON for Cisco Catalyst 9800-L Wireless Controllers section of the [Upgrading Field Programmable Hardware Devices for Cisco Catalyst 9800 Series Wireless Controllers](#) document.

- By default, the controller uses a TFTP block size value of 512, which is the lowest possible value. This default setting is used to ensure interoperability with legacy TFTP servers. If required, you can change the block size value to 8192 to speed up the transfer process, using the **ip tftp blocksize** command in global configuration mode.
- If the following error message is displayed after a reboot or system crash, we recommend that you regenerate the trustpoint certificate: ERR\_SSL\_VERSION\_OR\_CIPHER\_MISMATCH.

Use the following commands in the order specified below to generate a new self-signed trustpoint certificate:

```
device# configure terminal
device(config)# no crypto pki trustpoint trustpoint_name
device(config)# no ip http server
device(config)# no ip http secure-server
device(config)# ip http server
device(config)# ip http secure-server
device(config)# ip http authentication local/aaa
```

- Do not deploy OVA files directly to VMware ESXi 6.5. We recommend that you use an OVF tool to deploy the OVA files.
- Ensure that you remove the controller from Cisco Prime Infrastructure before disabling or enabling Netconf-YANG. Otherwise, the system may reload unexpectedly.
- From Cisco IOS XE Bengaluru 17.4.1 onwards, the telemetry solution provides a name for the receiver address instead of the IP address for telemetry data. This is an additional option. During the controller downgrade and subsequent upgrade, there is likely to be an issue—the upgrade version uses the newly named receivers, and these are not recognized in the downgrade. The new configuration gets rejected and fails in the subsequent upgrade. Configuration loss can be avoided when the upgrade or downgrade is performed from Cisco Catalyst Center.
- The Cisco Centralized Key Management (CCKM) feature was deprecated in Cisco IOS XE 17.10.x but currently remains supported. However, support for CCKM will be removed in a future release. Therefore, we recommend that you migrate to Fast Transition (FT) with 802.1X authentication and validate the configuration with supported key caching mechanisms.
- To migrate public IP address from 16.12.x to 17.x. ensure that you configure the service internal command. If you do not configure the service internal command, the IP address does not get carried forward.
- RLAN support with Virtual Routing and Forwarding (VRF) is not available.
- Unidirectional Link Detection (UDLD) protocol is not supported.
- When you encounter the SNMP error SNMP\_ERRORSTATUS\_NOACCESS 6, it means that the specified SNMP variable is not accessible.
- We recommend that you perform a controller reload whenever there is a change in the controller's clock to reflect an earlier time.

- The DTLS version (DTLSv1.0) is deprecated for Cisco Aironet 1800 based on latest security policies. Therefore, any new out-of-box deployments of Cisco Aironet 1800 APs will fail to join the controller, and you will get the following error message:

```
%APMGR_TRACE_MESSAGE-3-WLC_GEN_ERR: Chassis 1 R0/2: wncd: Error in AP Join,
AP <AP-name>,

mac:<MAC-address>Model AIR-AP1815W-D-K9, AP negotiated unexpected DTLS version v1.0
```

To onboard new Cisco Aironet 1800 APs and to establish a CAPWAP connection, explicitly set the DTLS version to 1.0 in the controller using the following configuration:

```
config terminal
ap dtls-version dtls_1_0
end
```

**Note:** Setting the DTLS version to 1.0 affects all the existing AP CAPWAP connections. We recommend that you apply the configuration only during a maintenance window. After the APs download the new image and join the controller, ensure that you remove the configuration.

- Before you begin a downgrade process, you must manually remove the configurations which are applicable in the current version but not in the older version. Otherwise, you might encounter unexpected behavior.
- To upgrade the field programmable hardware devices for Cisco Catalyst 9800 Series Wireless Controllers, refer to [Upgrading Field Programmable Hardware Devices for Cisco Catalyst 9800 Series Wireless Controllers](#).

## Upgrade path to Cisco IOS XE 26.2.1

**Table 7.** Upgrade Path to Cisco IOS XE Dublin 26.2.1

| Current software | Upgrade path for deployments with 9130, 9124, or 916x                                                                 | Upgrade path for deployments without 9130 and 9124                       |
|------------------|-----------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------|
| 16.10.x          | —<br><br><b>Note:</b> The Cisco Catalyst 9130 and 9124 APs are not supported in 16.10.x and 16.11.x releases.         | Upgrade first to 16.12.5 or 17.3.x and then to 26.2.1.                   |
| 16.11.x          | —                                                                                                                     | Upgrade first to 16.12.5 or 17.3.x and then to 26.2.1.                   |
| 16.12.x          | Upgrade first to 17.3.5 or later or 17.6.x or later, then to 17.9.6 or later or 17.12.x or later, and then to 26.2.1. | Upgrade first to 17.3.5 or later or 17.6.x or later, and then to 26.2.1. |
| 17.1.x           | Upgrade first to 17.3.5 or later or 17.6.x or later, then to 17.9.6 or later or 17.12.x or later, and then to 26.2.1. | Upgrade first to 17.3.5 or later and then to 26.2.1.                     |
| 17.2.x           | Upgrade first to 17.3.5 or later or 17.6.x or later, then to 17.9.6 or later or 17.12.x or later, and then to 26.2.1. | Upgrade first to 17.3.5 or later and then to 26.2.1.                     |

| Current software                                | Upgrade path for deployments with 9130, 9124, or 916x                                                                                       | Upgrade path for deployments without 9130 and 9124 |
|-------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------|
| 17.3.1 to 17.3.4                                | Upgrade first to 17.3.5 or later or 17.6.x or later, then to 17.9.6 or later or 17.12.x or later, and then to 26.2.1.                       | Upgrade directly to 26.2.1.                        |
| 17.3.4c or later                                | Upgrade to 17.9.6 or later or 17.12.x or later, and then to 26.2.1.                                                                         | Upgrade directly to 26.2.1.                        |
| 17.4.x                                          | Upgrade first to 17.6.x and then to 26.2.1.                                                                                                 | Upgrade directly to 26.2.1.                        |
| 17.5.x                                          | Upgrade first to 17.6.x and then to 26.2.1.                                                                                                 | Upgrade directly to 26.2.1.                        |
| 17.6.x                                          | Upgrade to 17.9.6 or later or 17.12.x or later, and then to 26.2.1.                                                                         | Upgrade directly to 26.2.1.                        |
| 17.7.x                                          | Upgrade to 17.9.6 or later or 17.12.x or later, and then to 26.2.1.                                                                         | Upgrade directly to 26.2.1.                        |
| 17.8.x                                          | Upgrade to 17.9.6 or later or 17.12.x or later, and then to 26.2.1.                                                                         | Upgrade directly to 26.2.1.                        |
| 17.9.1 to 17.9.5                                | Upgrade to 17.9.6 or later or 17.12.x or later, and then to 26.2.1.                                                                         | Upgrade directly to 26.2.1.                        |
| 17.9.6 or later                                 | Upgrade directly to 26.2.1.                                                                                                                 | Upgrade directly to 26.2.1.                        |
| 17.10.x                                         | Upgrade to 17.12.x or later, and then to 26.2.1.                                                                                            | Upgrade directly to 26.2.1.                        |
| 17.11.x                                         | Upgrade to 17.12.x or later, and then to 26.2.1.                                                                                            | Upgrade directly to 26.2.1.                        |
| 17.12.x                                         | Upgrade directly to 26.2.1.                                                                                                                 | Upgrade directly to 26.2.1.                        |
| 17.13.x                                         | Upgrade directly to 26.2.1.                                                                                                                 | Upgrade directly to 26.2.1.                        |
| 17.14.x                                         | Upgrade directly to 26.2.1.                                                                                                                 | Upgrade directly to 26.2.1.                        |
| 17.15.x                                         | Upgrade directly to 26.2.1.                                                                                                                 | Upgrade directly to 26.2.1.                        |
| 17.16.x                                         | Upgrade directly to 26.2.1.                                                                                                                 | Upgrade directly to 26.2.1.                        |
| 17.17.x                                         | Upgrade directly to 26.2.1.                                                                                                                 | Upgrade directly to 26.2.1.                        |
| 8.9.x or any 8.10.x version prior to 8.10.171.0 | Upgrade first to 8.10.171.0 or later, 17.3.5 or later, or 17.6.x or later, then to 17.9.6 or later or 17.12.x or later, and then to 26.2.1. | Upgrade directly to 26.2.1.                        |

## Upgrading the controller software

This section describes the various aspects of upgrading the controller software.

### Finding the software version

The package files for the Cisco IOS XE software are stored in the system board flash device (flash:).

Use the **show version** privileged EXEC command to see the software version that is running on your controller.

**Note:** Although the **show version** output always shows the software image running on the controller, the model name shown at the end of the output is the factory configuration and does not change if you upgrade the software license.

Use the **show install summary** privileged EXEC command to see the information about the active package.

Use the **dir** filesystem: privileged EXEC command to see the directory names of other software images that you have stored in flash memory.

## Software images

- **Release:** Cisco IOS XE 26.2.1

Image names (9800-80, 9800-40, and 9800-L):

- C9800-80-universalk9\_wlc.26.02.01.SPA.bin
- C9800-40-universalk9\_wlc.26.02.01.SPA.bin
- C9800-L-universalk9\_wlc.26.02.01.SPA.bin

Image names (CW9800M, CW9800H1/CW9800H2, CW9800L)

- CW9800H-wlc-universalk9.26.02.01.SPA.bin
- CW9800M-wlc-universalk9.26.02.01.SPA.bin
- CW9800L-wlc-universalk9.26.02.01.SPA.bin

Image names (9800-CL):

- **Cloud:** C9800-CL-universalk9.26.02.01.SPA.bin
- **Hyper-V/ESXi/KVM:** C9800-CL-universalk9.26.02.01.iso, C9800-CL-universalk9.26.02.01.ova
- **KVM:** C9800-CL-universalk9.26.02.01.qcow2
- **NFVIS:** C9800-CL-universalk9.26.02.01.tar.gz

## Software installation commands

To install and activate a specified file, and to commit changes to be persistent across reloads, run the following command:

```
device# install add file filename [activate |commit]
```

To separately install, activate, commit, end, or remove the installation file, run the following command:

```
device# install ?
```

**Note:** We recommend that you use the GUI for installation.

| Commands                                | Description                                                                                                                               |
|-----------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------|
| <b>add file tftp:</b> <i>filename</i>   | Copies the install file package from a remote location to a device and performs a compatibility check for the platform and image versions |
| <b>activate</b> <b>auto-abort-timer</b> | Activates the file and reloads the device; the auto-abort-timer keyword automatically rolls back image activation                         |
| <b>Commit</b>                           | Makes changes that are persistent over reloads                                                                                            |

| Commands                     | Description                                                                                                              |
|------------------------------|--------------------------------------------------------------------------------------------------------------------------|
| <b>rollback to committed</b> | Rolls back the update to the last committed version                                                                      |
| <b>Abort</b>                 | Cancels file activation and rolls back to the version that was running before the current installation procedure started |
| <b>Remove</b>                | Deletes all unused and inactive software installation files                                                              |

## Licensing

### Cisco Wireless Licenses

Cisco Wireless Licenses, a part of the Cisco Networking Subscription licensing model, is a software license that helps you to deploy your Wi-Fi 7 Access Points in an on-premise, hybrid, or a cloud managed network. From Cisco IOS XE 17.15.2, Cisco Wireless licenses are supported on Wi-Fi 7 Access Points (APs) and later models.

The Cisco Wireless Licenses consist of the following tiers:

- Cisco Wireless Essentials: The tier that provides fundamental features and functionalities that are essential to manage a network.
- Cisco Wireless Advantage: The tier that supports additional features and capabilities and includes all the essential capabilities in addition to the advanced capabilities to manage a network.

For more information, refer to [Cisco Wireless Licensing](#).

## Interoperability with clients

This section describes the interoperability of the controller software with client devices.

The following table lists the configurations used for testing client devices.

**Table 8.** Test configuration for interoperability

| Hardware or software parameter | Hardware or software type                                                                                                                                               |
|--------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Release                        | Cisco IOS XE 26.2.1                                                                                                                                                     |
| Cisco Wireless Controller      | Refer to <a href="#">Supported hardware</a>                                                                                                                             |
| Access Points                  | Refer to <a href="#">Supported APs</a>                                                                                                                                  |
| Radio                          | <ul style="list-style-type: none"> <li>• 802.11ac</li> <li>• 802.11ax</li> <li>• 802.11a</li> <li>• 802.11g</li> <li>• 802.11n</li> <li>• 802.11be (Wi-Fi 7)</li> </ul> |
| Security                       | Open, PSK (WPA2-AES), 802.1X (WPA2-AES) (EAP-FAST, EAP-TLS), WPA3 AKM                                                                                                   |
| RADIUS                         | Refer to <a href="#">Compatibility Matrix</a>                                                                                                                           |
| Types of tests                 | Connectivity, traffic (ICMP), and roaming between two APs                                                                                                               |

The following table lists the client types on which the tests were conducted. Client types included laptops, hand-held devices, phones, and printers.

**Table 9.** Client types

| Client type and name                                           | Driver or software version            |
|----------------------------------------------------------------|---------------------------------------|
| <b>Laptops</b>                                                 |                                       |
| Acer Aspire E 15 E5-573-3870 (Qualcomm Atheros QCA9377)        | Windows 10 Pro (12.0.0.832)           |
| Apple MacBook Air 11 inch                                      | macOS Sierra 10.12.6                  |
| Apple MacBook Air 13 inch                                      | macOS High Sierra 10.13.4             |
| MacBook Pro Retina                                             | macOS Catalina                        |
| MacBook Pro Retina 13 inch early 2015                          | macOS Mojave 10.14.3                  |
| MacBook Pro OS X                                               | macOS X 10.8.5                        |
| MacBook Air                                                    | macOS Sierra v10.12.2                 |
| MacBook Air 11 inch                                            | macOS Yosemite 10.10.5                |
| MacBook M1 Chip                                                | macOS Catalina                        |
| MacBook M1 Chip                                                | macOS Ventura 13.2.1                  |
| MacBook Pro M2 Chip                                            | macOS Ventura 13.3 beta               |
| MacBook Pro M2 Chip                                            | macOS Ventura 13.1                    |
| Dell Inspiron 2020 Chromebook                                  | Chrome OS 75.0.3770.129               |
| Google Pixelbook Go                                            | Chrome OS 97.0.4692.27                |
| HP Chromebook 11a                                              | Chrome OS 76.0.3809.136               |
| Samsung Chromebook 4+                                          | Chrome OS 77.0.3865.105               |
| Dell Latitude (Intel AX210)                                    | Windows 11 (22.110.x.x)               |
| Dell Latitude 3480 (Qualcomm DELL wireless 1820)               | Win 10 Pro (12.0.0.242)               |
| Dell Inspiron 15-7569 (Intel Dual Band Wireless-AC 3165)       | Windows 10 Home (21.40.0)             |
| Dell Latitude E5540 (Intel Dual Band Wireless AC7260)          | Windows 7 Professional (21.10.1)      |
| Dell Latitude E5430 (Intel Centrino Advanced-N 6205)           | Windows 7 Professional (15.18.0.1)    |
| Dell Latitude E6840 (Broadcom Dell Wireless 1540 802.11 a/g/n) | Windows 7 Professional (6.30.223.215) |
| Dell XPS 12 v9250 (Intel Dual Band Wireless AC 8260)           | Windows 10 Home (21.40.0)             |

| Client type and name                                                                                                                                            | Driver or software version   |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------|
| Dell Latitude 5491 (Intel AX200)                                                                                                                                | Windows 10 Pro (21.20.1.1)   |
| Dell XPS Latitude12 9250 (Intel Dual Band Wireless AC 8260)                                                                                                     | Windows 10 Home              |
| Dell Inspiron 13-5368 Signature Edition                                                                                                                         | Windows 10 Home (18.40.0.12) |
| FUJITSU Lifebook E556 Intel 8260 (Intel Dual Band Wireless-AC 8260 (802.11n))                                                                                   | Windows 8 (19.50.1.6)        |
| Lenovo Yoga C630 Snapdragon 850 (Qualcomm AC 2x2 Svc)                                                                                                           | Windows 10 Home              |
| Lenovo ThinkPad Yoga 460 (Intel Dual Band Wireless-AC 9260)                                                                                                     | Windows 10 Pro (21.40.0)     |
| <b>Note:</b> For clients using Intel wireless cards, we recommend that you update to the latest Intel wireless drivers if the advertised SSIDs are not visible. |                              |
| <b>Tablets</b>                                                                                                                                                  |                              |
| Apple iPad Pro (12.9 inch) 6th Gen                                                                                                                              | iOS 16.4                     |
| Apple iPad Pro (11 inch) 4th Gen                                                                                                                                | iOS 16.4                     |
| Apple iPad 2021                                                                                                                                                 | iOS 15.0                     |
| Apple iPad 7th Gen 2019                                                                                                                                         | iOS 14.0                     |
| Apple iPad MD328LL/A                                                                                                                                            | iOS 9.3.5                    |
| Apple iPad 2 MC979LL/A                                                                                                                                          | iOS 11.4.1                   |
| Apple iPad Air MD785LL/A                                                                                                                                        | iOS 11.4.1                   |
| Apple iPad Air2 MGLW2LL/A                                                                                                                                       | iOS 10.2.1                   |
| Apple iPad Mini 4 9.0.1 MK872LL/A                                                                                                                               | iOS 11.4.1                   |
| Apple iPad Mini 2 ME279LL/A                                                                                                                                     | iOS 11.4.1                   |
| Apple iPad Mini 4 9.0.1 MK872LL/A                                                                                                                               | iOS 11.4.1                   |
| Microsoft Surface Pro 3 13 inch (Intel AX201)                                                                                                                   | Windows 10 (21.40.1.3)       |
| Microsoft Surface Pro 3 15 inch (Qualcomm Atheros QCA61x4A)                                                                                                     | Windows 10                   |
| Microsoft Surface Pro 7 (Intel AX201)                                                                                                                           | Windows 10                   |
| Microsoft Surface Pro 6 (Marvell Wi-Fi chipset 11ac)                                                                                                            | Windows 10                   |
| Microsoft Surface Pro X (WCN3998 Wi-Fi Chip)                                                                                                                    | Windows                      |
| <b>Mobile phones</b>                                                                                                                                            |                              |

| Client type and name          | Driver or software version |
|-------------------------------|----------------------------|
| Apple iPhone 5                | iOS 12.4.1                 |
| Apple iPhone 6s               | iOS 13.5                   |
| Apple iPhone 7 MN8J2LL/A      | iOS 11.2.5                 |
| Apple iPhone 8                | iOS 13.5                   |
| Apple iPhone 8 Plus           | iOS 14.1                   |
| Apple iPhone 8 Plus MQ8D2LL/A | iOS 12.4.1                 |
| Apple iPhone X MQA52LL/A      | iOS 13.1                   |
| Apple iPhone 11               | iOS 15.1                   |
| Apple iPhone 12               | iOS 16.0                   |
| Apple iPhone 12 Pro           | iOS 15.1                   |
| Apple iPhone 13               | iOS 15.1                   |
| Apple iPhone 13 Mini          | iOS 15.1                   |
| Apple iPhone 13 Mini Pro      | iOS 15.1                   |
| Apple iPhone SE MLY12LL/A     | iOS 11.3                   |
| Apple iPhone SE               | iOS 15.1                   |
| ASCOM i63                     | Build v 3.0.0              |
| ASCOM Myco 3                  | Android 9                  |
| Cisco IP Phone 8821           | 11.0.6 SR4                 |
| Drager Delta                  | VG9.0.2                    |
| Drager M300.3                 | VG3.0                      |
| Drager M300.4                 | VG3.0                      |
| Drager M540                   | VG4.2                      |
| Google Pixel 3a               | Android 11                 |
| Google Pixel 4                | Android 11                 |
| Google Pixel 5                | Android 11                 |
| Google Pixel 6                | Android 12                 |
| Google Pixel 7                | Android 13                 |

| Client type and name                       | Driver or software version |
|--------------------------------------------|----------------------------|
| Huawei Mate 20 pro                         | Android 9.0                |
| Huawei P20 Pro                             | Android 10                 |
| Huawei P40                                 | Android 10                 |
| LG v40 ThinQ                               | Android 9.0                |
| One Plus 8                                 | Android 11                 |
| Oppo Find X2                               | Android 10                 |
| Redmi K20 Pro                              | Android 10                 |
| Samsung Galaxy S9+ - G965U1                | Android 10.0               |
| Samsung Galaxy S10 Plus                    | Android 11.0               |
| Samsung S10 (SM-G973U1)                    | Android 11.0               |
| Samsung S10e (SM-G970U1)                   | Android 11.0               |
| Samsung Galaxy S20 Ultra                   | Android 10.0               |
| Samsung Galaxy S21 Ultra 5G                | Android 13.0               |
| Samsung Galaxy S22 Ultra                   | Android 13.0               |
| Samsung Fold 2                             | Android 10.0               |
| Samsung Galaxy Z Fold 3                    | Android 13.0               |
| Samsung Note20                             | Android 12.0               |
| Samsung G Note 10 Plus                     | Android 11.0               |
| Samsung Galaxy A01                         | Android 11.0               |
| Samsung Galaxy A21                         | Android 10.0               |
| Sony Xperia 1 ii                           | Android 11                 |
| Sony Xperia                                | Android 11                 |
| Xiaomi Mi 9T                               | Android 9                  |
| Xiaomi Mi 10                               | Android 11                 |
| Spectralink 84 Series                      | 7.5.0.x257                 |
| Spectralink 87 Series                      | Android 5.1.1              |
| Spectralink Versity Phones 92/95/96 Series | Android 10.0               |

| Client type and name                   | Driver or software version |
|----------------------------------------|----------------------------|
| Spectralink Versity Phones 9540 Series | Android 8.1.0              |
| Vocera Badges B3000n                   | 4.3.3.18                   |
| Vocera Smart Badges V5000              | 5.0.6.35                   |
| Zebra MC40                             | Android 4.4.4              |
| Zebra MC40N0                           | Android 4.1.1              |
| Zebra MC92N0                           | Android 4.4.4              |
| Zebra MC9090                           | Windows Mobile 6.1         |
| Zebra MC55A                            | Windows 6.5                |
| Zebra MC75A                            | OEM ver 02.37.0001         |
| Zebra TC51                             | Android 6.0.1              |
| Zebra TC52                             | Android 10.0               |
| Zebra TC55                             | Android 8.1.0              |
| Zebra TC57                             | Android 10.0               |
| Zebra TC58                             | Android 11.0               |
| Zebra TC70                             | Android 6.1                |
| Zebra TC75                             | Android 10.0               |
| Zebra TC520K                           | Android 10.0               |
| Zebra TC8000                           | Android 4.4.3              |
| <b>Printers</b>                        |                            |
| Zebra QLn320 Mobile Printer            | LINK OS 5.2                |
| Zebra ZT230 IndustrialPrinter          | LINK OS 6.4                |
| Zebra ZQ310 Mobile Printer             | LINK OS 6.4                |
| Zebra ZD410 Industrial Printer         | LINK OS 6.4                |
| Zebra ZT410 Desktop Printer            | LINK OS 6.2                |
| Zebra ZQ610 Industrial Printer         | LINK OS 6.4                |
| Zebra ZQ620 Mobile Printer             | LINK OS 6.4                |
| Wireless module                        |                            |

| Client type and name             | Driver or software version                   |
|----------------------------------|----------------------------------------------|
| Intel AX 411                     | Driver v22.230.0.8                           |
| Intel AX 211                     | Driver v22.230.0.8, v22.190.0.4              |
| Intel AX 210                     | Driver v22.230.0.8, v22.190.0.4, v22.170.2.1 |
| Intel AX 200                     | Driver v22.130.0.5                           |
| Intel 11AC                       | Driver v22.30.0.11                           |
| Intel AC 9260                    | Driver v21.40.0                              |
| Intel Dual Band Wireless AC 8260 | Driver v19.50.1.6                            |
| Samsung S21 Ultra                | Driver v20.80.80                             |
| QCA WCN6855                      | Driver v1.0.0.901                            |
| PhoenixContact FL WLAN 2010      | Firmware version: 2.71                       |

## Supported hardware

### Supported virtual and hardware platforms

The following table lists the supported virtual and hardware platforms. (Refer to [Supported PIDs and ports](#) for the list of supported modules.)

**Table 10.** Supported virtual and hardware platforms

| Platform                                        | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                      |
|-------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Cisco Catalyst 9800-80 Wireless Controller      | A modular wireless controller with up to 100-GE modular uplinks and seamless software updates.<br><br>The controller occupies a 2-rack unit space and supports multiple module uplinks.                                                                                                                                                                                                                                                                          |
| Cisco Catalyst 9800-40 Wireless Controller      | A fixed wireless controller with seamless software updates for mid-size to large enterprises.<br><br>The controller occupies a 1-rack unit space and provides four 1-GE or 10-GE uplink ports.                                                                                                                                                                                                                                                                   |
| Cisco Catalyst 9800-L Wireless Controller       | The Cisco Catalyst 9800-L Wireless Controller is the first low-end controller that provides a significant boost in performance and features.                                                                                                                                                                                                                                                                                                                     |
| Cisco 9800 Series Wireless Controller for Cloud | A virtual form factor of the Catalyst 9800 Wireless Controller that can be deployed in a private cloud (supports VMware ESXi, Kernel-based Virtual Machine [KVM], Microsoft Hyper-V, and Cisco Enterprise NFV Infrastructure Software [NFVIS] on Enterprise Network Compute System [ENCS] hypervisors), or in the public cloud as Infrastructure as a Service (IaaS) in Amazon Web Services (AWS), Google Cloud Platform (GCP) marketplace, and Microsoft Azure. |

| Platform                                                                           | Description                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                |
|------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Embedded Wireless Controller on Catalyst 9000 Series Switches                      | <p>The Catalyst 9800 Wireless Controller software for the Cisco Catalyst 9000 switches brings the wired and wireless infrastructure together with consistent policy and management.</p> <p>This deployment model supports only Software Defined-Access (SDA), which is a highly secure solution for small campuses and distributed branches.</p>                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                           |
| Cisco CW9800 Series Wireless Controller (CW9800M, CW9800H1, CW9800H2, and CW9800L) | <p>The CW9800M controller is the next generation Cisco CW9800 series wireless LAN controller built to deliver a 53% performance improvement while consuming 18% less power when compared to the previous generation models.</p> <p>Additionally, the CW9800M controller supports 3000 APs and 32000 clients to ensure better performance and scale for business-critical networks and provides up to 40 Gbps of forwarding throughput for both normal packet and encrypted packets while remaining a single RU designed to save you space and provide greater flexibility in your datacenters.</p> <p>The CW9800H1 and CW9800H2 controllers are the next-generation Cisco CW9800 wireless LAN controllers that boast up to a 36% increase in performance and consume up to 40% less power compared to their predecessors.</p> <p>Additionally, the CW9800H1 and CW9800H2 models are built with a space-saving single RU design and support up to 6000 APs and 64,000 clients with 100 Gbps of maximum throughput. They also offer a choice of uplinks with either 4 x 25 Gbps (CW9800H1) or 2 x 40 Gbps (CW9800H2) configurations to meet high throughput demands of next-generation wireless requirements.</p> <p>The CW9800L controller is the next-generation, low-end controller that provides a significant boost in performance and features. Supporting up to 10 Gbps throughput, 500 APs, and 10,000 clients, the CW9800L delivers double the capacity and increased performance compared to the base C9800-L.</p> |

## Supported host environments - public and private cloud

The following table lists the host environments supported for private and public cloud.

**Table 11.** Supported host environments for public and private cloud

| Host environment  | Software version                                                                                                                                                                         |
|-------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| VMware ESXi       | <ul style="list-style-type: none"> <li>VMware ESXi vSphere 6.5, 6.7, 7.0, and 8.0</li> <li>VMware ESXi vCenter 6.5, 6.7, 7.0, and 8.0</li> </ul>                                         |
| KVM               | <ul style="list-style-type: none"> <li>Linux KVM-based on Red Hat Enterprise Linux 9.2, or latest version</li> <li>Ubuntu 16.04.5 LTS, Ubuntu 18.04.5 LTS, Ubuntu 20.04.5 LTS</li> </ul> |
| AWS               | AWS EC2 platform                                                                                                                                                                         |
| NFVIS             | ENCS 3.8.1 and 3.9.1                                                                                                                                                                     |
| GCP               | GCP marketplace                                                                                                                                                                          |
| Microsoft Hyper-V | Windows Server 2019, Windows Server 2025, with Hyper-V Manager (Version 10.0.x)                                                                                                          |
| Microsoft Azure   | Microsoft Azure                                                                                                                                                                          |

## Supported PIDs and ports

The following table lists the supported Cisco Catalyst 9800 Series Wireless Controller hardware models.

The base PIDs are the model numbers of the controller.

The bundled PIDs indicate the orderable part numbers for the base PIDs that are bundled with a particular network module. Running the **show version**, **show module**, or **show inventory** command on such a controller (bundled PID) displays its base PID.

**Note:** Unsupported SFPs will bring down a port. Only Cisco-supported SFPs (GLC-LH-SMD and GLC-SX-MMD) should be used on the route processor (RP) ports of C9800-80-K9 and C9800-40-K9.

**Table 12.** Supported PIDS and ports

| Controller model | Description                                                                                                                  |
|------------------|------------------------------------------------------------------------------------------------------------------------------|
| C9800-CL-K9      | Cisco Catalyst Wireless Controller as an infrastructure for cloud.                                                           |
| C9800-80-K9      | Eight 1/10-Gigabit Ethernet SFP or SFP+ ports and two power supply slots.                                                    |
| C9800-40-K9      | Four 1/10-Gigabit Ethernet SFP or SFP+ ports and two power supply slots.                                                     |
| C9800-L-C-K9     | <ul style="list-style-type: none"><li>• 4x2.5/1-Gigabit ports</li><li>• 2x10/5/2.5/1-Gigabit ports</li></ul>                 |
| C9800-L-F-K9     | <ul style="list-style-type: none"><li>• 4x2.5/1-Gigabit ports</li><li>• 2x10/1-Gigabit ports</li></ul>                       |
| CW9800H1         | <ul style="list-style-type: none"><li>• 8x1 GE/10 GE SFP ports</li><li>• 4x25 GE SFP interfaces</li></ul>                    |
| CW9800H2         | <ul style="list-style-type: none"><li>• 8x1 GE/10 GE SFP Ports</li><li>• 2X 40 GE QSFP interfaces</li></ul>                  |
| CW9800M          | <ul style="list-style-type: none"><li>• Four built-in 1 GE /10 GE SFP ports</li><li>• Two built-in 25 GE SFP ports</li></ul> |
| CW9800L          | <ul style="list-style-type: none"><li>• 2x 10G/1G SFP Ports (Data Ports)</li><li>• 2x1G Copper (RP and SP ports)</li></ul>   |

## Supported SFPs

The following table lists the supported SFP models.

**Table 13.** Supported SFP models

| SFP name                      | C9800-80-K9 | C9800-40-K9 | C9800-L-F-K9 | CW9800H1 | CW9800H2 | CW9800M | CW9800L |
|-------------------------------|-------------|-------------|--------------|----------|----------|---------|---------|
| COLORCHIP-C040-Q020-CWDM4-03B | Supported   | —           | —            | —        | —        | —       | —       |
| DWDM-SFP10G-30.33             | Supported   | Supported   | —            | —        | —        | —       | —       |
| DWDM-SFP10G-61.41             | Supported   | Supported   | —            | —        | —        | —       | —       |

| SFP name                                                                                                                              | C9800-80-K9 | C9800-40-K9 | C9800-L-F-K9 | CW9800H1  | CW9800H2  | CW9800M   | CW9800L   |
|---------------------------------------------------------------------------------------------------------------------------------------|-------------|-------------|--------------|-----------|-----------|-----------|-----------|
| FINISAR-LR – FTLX1471D3BCL<br>(The FINISAR SFPs are not Cisco specific and some of the features, such as DOM, may not work properly.) | Supported   | Supported   | Supported    | –         | –         | –         | –         |
| FINISAR-SR – FTLX8574D3BCL                                                                                                            | Supported   | Supported   | Supported    | –         | –         | –         | –         |
| GLC-BX-D                                                                                                                              | Supported   | Supported   | Supported    | Supported | Supported | Supported | –         |
| GLC-BX-U                                                                                                                              | Supported   | Supported   | Supported    | Supported | Supported | Supported | –         |
| GLC-EX-SMD                                                                                                                            | Supported   | Supported   | –            | Supported | Supported | Supported | –         |
| GLC-LH-SMD                                                                                                                            | Supported   | Supported   | –            | Supported | Supported | Supported | Supported |
| GLC-SX-MMD                                                                                                                            | Supported   | Supported   | Supported    | Supported | Supported | Supported | Supported |
| GLC-T                                                                                                                                 | Supported   | –           | –            | –         | –         | –         | –         |
| GLC-TE                                                                                                                                | Supported   | Supported   | Supported    | Supported | Supported | Supported | Supported |
| GLC-ZX-SMD                                                                                                                            | Supported   | Supported   | Supported    | Supported | Supported | Supported | –         |
| QSFP-100G-LR4-S                                                                                                                       | Supported   | –           | –            | –         | –         | –         | –         |
| QSFP-100G-SR4-S                                                                                                                       | Supported   | –           | –            | –         | –         | –         | –         |
| QSFP-40G-BD-RX                                                                                                                        | Supported   | –           | –            | Supported | Supported | Supported | –         |
| QSFP-40G-ER4                                                                                                                          | Supported   | –           | –            | –         | Supported | –         | –         |
| QSFP-40G-LR4                                                                                                                          | Supported   | –           | –            | –         | Supported | –         | –         |
| QSFP-40G-LR4-S                                                                                                                        | Supported   | –           | –            | –         | Supported | –         | –         |
| QSFP-40G-LR4-S-RF                                                                                                                     |             |             | –            | Supported | Supported | Supported | –         |
| QSFP-40G-CSR4                                                                                                                         | –           | –           | –            | –         | Supported | –         | –         |
| QSFP-40G-SR4                                                                                                                          | Supported   | –           | –            | –         | Supported | –         | –         |
| QSFP-40G-SR4-S                                                                                                                        | Supported   | –           | –            | –         | Supported | –         | –         |
| QSFP-40G-SR-BD                                                                                                                        | –           | –           | –            | Supported | Supported | Supported | –         |
| QSFP-40GE-LR4                                                                                                                         | Supported   | –           | –            | –         | –         | –         | –         |

| SFP name         | C9800-80-K9 | C9800-40-K9 | C9800-L-F-K9 | CW9800H1  | CW9800H2  | CW9800M   | CW9800L   |
|------------------|-------------|-------------|--------------|-----------|-----------|-----------|-----------|
| QSFP-H40G-ACU7M  | —           | —           | —            | Supported | Supported | Supported | —         |
| QSFP-H40G-ACU10M | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-CU1M   | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-CU2M   | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-CU3M   | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-CU4M   | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-CU5M   | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-CU0-5M | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-AOC1M  | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-AOC2M  | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-AOC3M  | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-AOC5M  | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-AOC7M  | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-AOC10M | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-AOC15M | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-AOC20M | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-AOC25M | —           | —           | —            | —         | Supported | —         | —         |
| QSFP-H40G-AOC30M | —           | —           | —            | —         | Supported | —         | —         |
| SFP-10G-AOC10M   | Supported   | Supported   | —            | —         | —         | —         | Supported |
| SFP-10G-AOC1M    | Supported   | Supported   | —            | Supported | Supported | Supported | Supported |
| SFP-10G-AOC2M    | Supported   | Supported   | —            | Supported | Supported | Supported | Supported |

| SFP name         | C9800-80-K9 | C9800-40-K9 | C9800-L-F-K9 | CW9800H1  | CW9800H2  | CW9800M   | CW9800L   |
|------------------|-------------|-------------|--------------|-----------|-----------|-----------|-----------|
| SFP-10G-AOC3M    | Supported   | Supported   | —            | Supported | Supported | Supported | Supported |
| SFP-10G-AOC5M    | Supported   | Supported   | —            | Supported | Supported | Supported | Supported |
| SFP-10G-AOC7M    | Supported   | Supported   | —            | Supported | Supported | Supported | Supported |
| SFP-10G-BXD-I    |             |             |              | Supported | Supported | Supported | Supported |
| SFP-10G-BXU-I    |             |             |              | Supported | Supported | Supported | Supported |
| SFP-10G-CSR-S    |             |             |              | Supported | Supported | Supported | —         |
| SFP-10G-ER       | Supported   | Supported   | —            | Supported | Supported | Supported | —         |
| SFP-10G-LR       | Supported   | Supported   | Supported    | Supported | Supported | Supported | Supported |
| SFP-10G-LR-I     |             |             | —            | Supported | Supported | Supported | —         |
| SFP-10G-LR-S     | Supported   | Supported   | Supported    | Supported | Supported | Supported | Supported |
| SFP-10G-LR-X     | Supported   | Supported   | Supported    | Supported | Supported | Supported | Supported |
| SFP-10G-LRM      | Supported   | Supported   | Supported    | —         | —         | —         | Supported |
| SFP-10G-SR       | Supported   | Supported   | Supported    | Supported | Supported | Supported | Supported |
| SFP-10G-SR-S     | Supported   | Supported   | Supported    | Supported | Supported | Supported | Supported |
| SFP-10G-SR-I     | —           | —           | —            | Supported | Supported | Supported | Supported |
| SFP-10G-SR-X     | Supported   | Supported   | Supported    | —         | —         | —         | Supported |
| SFP-10G-ZR       |             |             | —            | Supported | Supported | Supported | —         |
| SFP-10G-ZR-I     | —           | —           | —            | Supported | Supported | Supported | Supported |
| SFP-10G-T-X      | —           | —           | —            | Supported | Supported | Supported | —         |
| SFP-25G-CSR-S    | —           | —           | —            | Supported | Supported | Supported | —         |
| SFP-25G-SR-S     | —           | —           | —            | Supported | —         | Supported | —         |
| SFP-25G-ER-I     | —           | —           | —            | Supported | —         | Supported | —         |
| SFP-10/25G-LR-I  | —           | —           | —            | Supported | —         | Supported | —         |
| SFP-10/25G-LR-S  | —           | —           | —            | Supported | —         | Supported | —         |
| SFP-10/25G-CSR-S | —           | —           | —            | Supported | —         | Supported | —         |
| SFP-10/25G-BXD-I | —           | —           | —            | Supported | —         | Supported | Supported |
| SFP-10/25G-BXU-I | —           | —           | —            | Supported | —         | Supported | Supported |

| SFP name                   | C9800-80-K9 | C9800-40-K9 | C9800-L-F-K9 | CW9800H1  | CW9800H2  | CW9800M   | CW9800L   |
|----------------------------|-------------|-------------|--------------|-----------|-----------|-----------|-----------|
| SFP-H25G-CU1M              | —           | —           | —            | Supported | —         | Supported | —         |
| SFP-H25G-CU3M              | —           | —           | —            | Supported | —         | Supported | —         |
| SFP-H25G-CU5M              | —           | —           | —            | Supported | —         | Supported | —         |
| SFP-25G-AOC1M              | —           | —           | —            | Supported | —         | Supported | —         |
| SFP-25G-AOC2M              | —           | —           | —            | Supported | —         | Supported | —         |
| SFP-25G-AOC3M              | —           | —           | —            | Supported | —         | Supported | —         |
| SFP-25G-AOC5M              | —           | —           | —            | Supported | —         | Supported | —         |
| SFP-25G-AOC7M              | —           | —           | —            | Supported | —         | Supported | —         |
| SFP-25G-AOC10M             | —           | —           | —            | Supported | —         | Supported | —         |
| SFP-H10GB-ACU10M           | Supported   | Supported   | Supported    | Supported | Supported | Supported | Supported |
| SFP-H10GB-ACU7M            | Supported   | Supported   | Supported    | Supported | Supported | Supported | Supported |
| SFP-H10GB-CU1.5M           | Supported   | Supported   | Supported    | Supported | Supported | Supported | Supported |
| SFP-H10GB-CU1M             | Supported   | Supported   | Supported    | Supported | Supported | Supported | Supported |
| SFP-H10GB-CU2.5M           | Supported   | Supported   | Supported    | —         | —         | —         | Supported |
| SFP-H10GB-CU2M             | Supported   | Supported   | Supported    | Supported | Supported | Supported | Supported |
| SFP-H10GB-CU3M             | Supported   | Supported   | Supported    | Supported | Supported | Supported | Supported |
| SFP-H10GB-CU5M             | Supported   | Supported   | Supported    | Supported | Supported | Supported | Supported |
| SFP-H10GB-CU1-5M           | Supported   | Supported   | —            | Supported | Supported | Supported | —         |
| SFP-H10GB-CU2-5M           |             |             |              | Supported | Supported | Supported |           |
| Finisar-LR (FTLX1471D3BCL) | —           | —           | Supported    | Supported | Supported | Supported | Supported |
| Finisar-SR (FTLX8574D3BC)  | —           | —           | —            | Supported | Supported | Supported | Supported |

## Optic modules

The Cisco Catalyst 9800 Series Wireless Controller supports a wide range of optics. The list of supported optics is updated on a regular basis. Refer to the tables at the following location for the latest transceiver module compatibility information:

<https://www.cisco.com/c/en/us/support/interfaces-modules/transceiver-modules/products-device-support-tables-list.html>.

## Network protocols and port matrix

**Table 14.** Cisco Catalyst 9800 series wireless controller - network protocols and port matrix

| Source | Destination                                    | Protocol | Destination port | Source port | Description                          |
|--------|------------------------------------------------|----------|------------------|-------------|--------------------------------------|
| Any    | Cisco Catalyst 9800 Series Wireless Controller | TCP      | 22               | Any         | SSH                                  |
| Any    | Cisco Catalyst 9800 Series Wireless Controller | TCP      | 23               | Any         | Telnet                               |
| Any    | Cisco Catalyst 9800 Series Wireless Controller | TCP      | 80               | Any         | HTTP                                 |
| Any    | Cisco Catalyst 9800 Series Wireless Controller | TCP      | 443              | Any         | HTTPS                                |
| Any    | Cisco Catalyst 9800 Series Wireless Controller | UDP      | 161              | Any         | SNMP agent                           |
| Any    | Any                                            | UDP      | 5353             | 5353        | mDNS                                 |
| Any    | Cisco Catalyst 9800 Series Wireless Controller | UDP      | 69               | 69          | TFTP                                 |
| Any    | DNS Server                                     | UDP      | 53               | Any         | DNS                                  |
| Any    | Cisco Catalyst 9800 Series Wireless Controller | TCP      | 830              | Any         | NetConf                              |
| Any    | Cisco Catalyst 9800 Series Wireless Controller | TCP      | 443              | Any         | REST API                             |
| Any    | WLC Protocol                                   | UDP      | 1700             | Any         | Receive CoA packets                  |
| AP     | Cisco Catalyst 9800 Series Wireless Controller | UDP      | 5246             | Any         | CAPWAP Control                       |
| AP     | Cisco Catalyst 9800 Series Wireless Controller | UDP      | 5247             | Any         | CAPWAP Data                          |
| AP     | Cisco Catalyst 9800 Series Wireless Controller | UDP      | 5248             | Any         | CAPWAP MCAST                         |
| AP     | Cisco Catalyst Center                          | TCP      | 32626            | Any         | Intelligent capture and RF telemetry |
| AP     | AP                                             | UDP      | 16670            | Any         | Client Policies (AP-AP)              |

| Source                                         | Destination                                    | Protocol | Destination port | Source port | Description                                                      |
|------------------------------------------------|------------------------------------------------|----------|------------------|-------------|------------------------------------------------------------------|
| Cisco Catalyst 9800 Series Wireless Controller | Cisco Catalyst 9800 Series Wireless Controller | UDP      | 16666            | 16666       | Mobility Control                                                 |
| Cisco Catalyst 9800 Series Wireless Controller | SNMP                                           | UDP      | 162              | Any         | SNAMP Trap                                                       |
| Cisco Catalyst 9800 Series Wireless Controller | RADIUS                                         | UDP      | 1812/1645        | Any         | RADIUS Auth                                                      |
| Cisco Catalyst 9800 Series Wireless Controller | RADIUS                                         | UDP      | 1813/1646        | Any         | RADIUS ACCT                                                      |
| Cisco Catalyst 9800 Series Wireless Controller | TACACS+                                        | TCP      | 49               | Any         | TACACS+                                                          |
| Cisco Catalyst 9800 Series Wireless Controller | Cisco Catalyst 9800 Series Wireless Controller | UDP      | 16667            | 16667       | Mobility                                                         |
| Cisco Catalyst 9800 Series Wireless Controller | NTP Server                                     | UDP      | 123              | Any         | NTP                                                              |
| Cisco Catalyst 9800 Series Wireless Controller | Syslog Server                                  | UDP      | 514              | Any         | SYSLOG                                                           |
| AP                                             | Cisco Catalyst 9800 Series Wireless Controller | HTTPS    | 8443             | Any         | Out of Band AP Image Download<br>Cisco CleanAir Spectral Capture |
| Cisco Catalyst 9800 Series Wireless Controller | NetFlow Server                                 | UDP      | 9996             | Any         | NetFlow                                                          |
| Cisco Catalyst 9800 Series Wireless Controller | Cisco Connected Mobile Experiences (CMX)       | UDP      | 16113            | Any         | NMSP                                                             |

| Source                | Destination                                    | Protocol | Destination port | Source port | Description             |
|-----------------------|------------------------------------------------|----------|------------------|-------------|-------------------------|
| Cisco Catalyst Center | Cisco Catalyst 9800 Series Wireless Controller | TCP      | 32222            | Any         | Device Discovery        |
| Cisco Catalyst Center | Cisco Catalyst 9800 Series Wireless Controller | TCP      | 25103            | Any         | Telemetry Subscriptions |

## Supported APs

The following Cisco APs are supported in this release:

**Table 15.** Supported APs

| AP type                  | AP names                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                        |
|--------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Indoor Access Points     | <ul style="list-style-type: none"> <li>• Cisco Catalyst 9105AX (I/W) Access Points</li> <li>• Cisco Catalyst 9115AX (I/E) Access Points</li> <li>• Cisco Catalyst 9120AX (I/E/P) Access Points</li> <li>• Cisco Catalyst 9130AX (I/E) Access Points</li> <li>• Cisco Catalyst 9136AX Access Points</li> <li>• Cisco Catalyst 9162 (I) Series Access Points</li> <li>• Cisco Catalyst 9164 (I) Series Access Points</li> <li>• Cisco Catalyst 9166 (I/D1) Series Access Points</li> <li>• Cisco Wireless 9171 (I) Series Wi-Fi 7 Access Points</li> <li>• Cisco Wireless 9172 (I/H) Series Wi-Fi 7 Access Points</li> <li>• Cisco Wireless 9174 (I/E) Series Wi-Fi 7 Access Points</li> <li>• Cisco Wireless 9176 (I/D1) Series Wi-Fi 7 Access Points</li> <li>• Cisco Wireless 9178 (I) Series Wi-Fi 7 Access Points</li> </ul> |
| Outdoor Access Points    | <ul style="list-style-type: none"> <li>• Cisco Catalyst 9124AX (I/D/E) Access Points</li> <li>• Cisco Catalyst 9163 (E) Series Access Points</li> <li>• Cisco Wireless 9177 (I/E/D) Series Wi-Fi 7 Access Points</li> <li>• Cisco Wireless 9179 (F) Series Wi-Fi 7 Access Points</li> <li>• Cisco Catalyst Industrial Wireless 9167 (I/E) Heavy Duty Access Points</li> <li>• Cisco Catalyst Industrial Wireless 9165E Rugged Access Point</li> <li>• Cisco Catalyst Industrial Wireless 9165D Heavy Duty Access Point</li> </ul>                                                                                                                                                                                                                                                                                               |
| Integrated Access Points | Integrated Access Point on Cisco 1100 ISR (ISR-AP1100AC-x, ISR-AP1101AC-x, and ISR-AP1101AX-x)                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                  |
| Network Sensor           | Cisco Aironet 1800s Active Sensor                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                               |
| Pluggable Modules        | Cisco Wi-Fi Interface Module (WIM) - WP-WIFI6-x                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                                 |

## Supported AP channels and maximum power settings

Supported access point channels and maximum power settings on Cisco APs are compliant with the regulatory specifications of channels, maximum power levels, and antenna gains of every country in which the access points are sold. For more information about the supported access point transmission values in Cisco IOS XE software releases, refer to the Detailed Channels and Maximum Power Settings document at

---

<https://www.cisco.com/c/en/us/support/wireless/catalyst-9100ax-access-points/products-technical-reference-list.html>.

For information about Cisco Wireless software releases that support specific Cisco AP modules, refer to [Cisco Access Points Supported in Cisco Wireless Controller Platform Software Releases](#).

## Related content

### Cisco Wireless Controller:

For more information about the Cisco wireless controller, lightweight APs, and mesh APs, refer to these documents:

[Cisco Wireless Solutions Software Compatibility Matrix](#)

[Cisco Catalyst 9800 Series Wireless Controller Software Configuration Guide](#)

[Cisco Catalyst 9800 Series Wireless Controller Command Reference](#)

[Cisco Catalyst 9800 Series Configuration Best Practices](#)

[In-Service Software Upgrade Matrix](#)

[Upgrading Field Programmable Hardware Devices for Cisco Catalyst 9800 Series Wireless Controllers](#)

The installation guide for your controller is available at:

[Hardware Installation Guides](#)

[All Cisco Wireless Controller software-related documentation](#)

### Cisco Catalyst 9800 Series Wireless Controller Data Sheets:

[Data Sheet Listing](#)

### Wireless Product Comparison:

[Compare specifications of Cisco wireless APs and controllers](#)

[Wireless LAN Compliance Lookup](#)

[Cisco AireOS to Cisco Catalyst 9800 Wireless Controller Feature Comparison Matrix](#)

### Cisco Access Points-Statement of Volatility:

The STATEMENT OF VOLATILITY is an engineering document that provides information about the device, the location of its memory components, and the methods for clearing device memory. Refer to the data security policies and practices of your organization and take the necessary steps required to protect your devices or network environment.

The Cisco Aironet and Catalyst AP Statement of Volatility (SoV) documents are available on the [Cisco Trust Portal](#).

You can search by the AP model to view the SoV document.

### Cisco Prime Infrastructure:

[Cisco Prime Infrastructure Documentation](#)

### Cisco Spaces:

[Cisco Spaces Documentation](#)

---

## Cisco Catalyst Center:

[Cisco Catalyst Center Documentation](#)

## Product Analytics

[Cisco Enterprise Networking Product Analytics Frequently Asked Questions](#)

## Communications, services, and additional information:

- To receive timely, relevant information from Cisco, sign up at [Cisco Profile Manager](#).
- To get the business impact you're looking for with the technologies that matter, visit [Cisco Services](#).
- To submit a service request, visit [Cisco Support](#).
- To discover and browse secure, validated enterprise-class apps, products, solutions, and services, visit [Cisco DevNet](#).
- To obtain general networking, training, and certification titles, visit [Cisco Press](#).
- To find warranty information for a specific product or product family, access [Cisco Warranty Finder](#).

## Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST) is a gateway to the Cisco bug-tracking system, which maintains a comprehensive list of defects and vulnerabilities in Cisco products and software. The BST provides you with detailed defect information about your products and software.

## Documentation feedback

To provide feedback about Cisco technical documentation, use the feedback form available on the right pane of every online document.

## Legal information

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: [www.cisco.com/go/trademarks](http://www.cisco.com/go/trademarks). Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

Any Internet Protocol (IP) addresses and phone numbers used in this document are not intended to be actual addresses and phone numbers. Any examples, command display output, network topology diagrams, and other figures included in the document are shown for illustrative purposes only. Any use of actual IP addresses or phone numbers in illustrative content is unintentional and coincidental.

© 2026 Cisco Systems, Inc. All rights reserved.