

# Release Notes for Cisco Embedded Wireless Controller on Catalyst Access Points, Cisco IOS XE 17.15.x

---

**First Published:** 2024-08-14

**Last Modified:** 2025-08-06

## Release Notes for Cisco Embedded Wireless Controller on Catalyst Access Points, Cisco IOS XE 17.15.x

### Introduction to Cisco Embedded Wireless Controller on Catalyst Access Points

The Cisco Embedded Wireless Controller on Catalyst Access Points is a version of the Cisco IOS XE-based controller software on Catalyst access points (AP). In this solution, a Catalyst AP that is running the Cisco Embedded Wireless Controller on Catalyst Access Points software, is designated as the primary AP. Other APs, referred to as subordinate APs, associate to this primary AP.

The Cisco Embedded Wireless Controller on Catalyst Access Points provides enterprise-level WLAN features while maintaining operational simplicity and affordability. This solution is targeted at small and medium-sized business (SMB) customers or distributed enterprises, and can be run at single site deployments.

- The controllers come with high availability (HA) and seamless software updates. This keeps your services on always, both during planned and unplanned events.
- The deployment can be managed using a mobile application, Cisco Catalyst Center, Netconf/Restconf, web-based GUI, or CLI.

### What's New in Cisco IOS XE 17.15.4

There are no new features in this release.

### What's New in Cisco IOS XE 17.15.3

There are no new features in this release.

### What's New in Cisco IOS XE 17.15.2b

There are no new features in this release.

## What's New in Cisco IOS XE 17.15.2

**Table 1: New and Modified Software Features**

Feature Name	Description and Documentation Link
Support for Cisco Catalyst 9124AX Series Outdoor Access Point in Morocco	<p>Morocco allows indoor channels and power for units attached outside buildings. In this release, the Cisco Catalyst 9124AX Series Outdoor Access Point is supported in Morocco. The outdoor designation is 2.4 GHz only for licensed users.</p> <p>For more information, see the Detailed Channels and Maximum Power Settings document at <a href="https://www.cisco.com/c/en/us/support/cisco-embedded-wireless-controller/cisco-ios-xe-17/products-technical-reference-list.html">https://www.cisco.com/c/en/us/support/cisco-embedded-wireless-controller/cisco-ios-xe-17/products-technical-reference-list.html</a>.</p>

## What's New in Cisco IOS XE 17.15.1

**Table 2: New and Modified Software Features**

Feature Name	Description and Documentation Link
Software-Defined Access (SDA) Restriction Update	<p>Fabric in a Box (FIAB) is now supported from the 17.15.1 release.</p> <p>For more information, see the chapter <a href="#">Software-Defined Access Wireless</a>.</p>
SuiteB-1X and SuiteB-192-1X Support in FlexConnect Mode for WPA2 and WPA3	<p>From Cisco IOS XE 17.15.1 onwards, Cisco WLAN FlexConnect mode supports enterprise authentication key management (AKM) — SuiteB-192-1X (AKM 12) and SuiteB-1X (AKM 11).</p> <p>This feature supports the configuration of SuiteB-192-1X and SuiteB-1X in FlexConnect mode, and also supports Galois Counter Mode Protocol 128 (GCMP-128), GCMP-256, and Counter Cipher Mode with Block Chaining Message Authentication Code Protocol 256 (CCMP-256) ciphers for pairwise transport keys (PTK) and group temporal key (GTK) derivation in FlexConnect Local Authentication mode and FlexConnect Central Authentication mode.</p> <p>For more information, see the chapter <a href="#">SuiteB-1X and SuiteB-192-1X Support in FlexConnect Mode for WPA2 and WPA3</a>.</p>

Feature Name	Description and Documentation Link
Wi-Fi Protected Access (WPA3) Security Enhancements for Access Points	<p>The following are the security enhancements developed in Cisco IOS XE 17.15.1, for APs:</p> <ul style="list-style-type: none"> <li>• GCMP-256 Cipher and SuiteB-192-1X AKM</li> <li>• SAE-EXT-KEY Support</li> <li>• AP Beacon Protection</li> <li>• Multiple Cipher Support per WLAN</li> <li>• Opportunistic Wireless Encryption (OWE) Support with GCMP-256 Cipher</li> </ul> <p>The following commands are introduced:</p> <ul style="list-style-type: none"> <li>• <b>security wpa akm sae ext-key</b></li> <li>• <b>security wpa akm ft sae ext-key</b></li> <li>• <b>security wpa akm suiteb-192</b></li> <li>• <b>security wpa akm suiteb</b></li> <li>• <b>security wpa wpa2 ciphers</b></li> <li>• <b>security wpa wpa3 beacon-protection</b></li> </ul> <p>For more information, see the chapter <a href="#">Wi-Fi Protected Access (WPA3) Security Enhancements for Access Points</a>.</p>
Tier B/C/D Country Support for Cisco Catalyst 9124 Outdoor Access Points	<p>From this release, Cisco Catalyst 9124 Outdoor APs are supported in the following countries: Bosnia, Hong Kong, India, Indonesia, Israel, Jordan, Kuwait, Puerto Rico, Qatar, Saudi Arabia, Singapore, South Africa, Taiwan, Turkey, and United Arab Emirates.</p> <p>For more information, see the chapter <a href="#">Country Codes</a>.</p>

Table 3: New and Modified GUI Features

Feature Name	GUI Path
SuiteB-1X and SuiteB-192-1X Support in FlexConnect Mode for WPA2 and WPA3	<b>Configuration &gt; Tags &amp; Profiles &gt; WLANs</b>
Wi-Fi Protected Access (WPA3) Security Enhancements for Access Points	<b>Configuration &gt; Tags &amp; Profiles &gt; WLANs</b>

## Behavior Change

### Behavior Change for Cisco IOS XE 17.15.4

- The Cisco Catalyst 9124 mesh APs (MAP) powered with 30W, when joined to a Cisco Catalyst 9124 EWC root AP, tri-radio was not supported with 30W. It was only possible to enable it if MAP was powered with 60W. With the change in behavior, you can enable tri-radio with 30W.

### Behavior Change for Cisco IOS XE 17.15.3

The EWC APs were losing the Static IP assignment and reverting to DHCP once it was converted to CAPWAP mode. From this release onwards, the Static IP address is retained upon conversion to the CAPWAP mode from the EWC mode.

## Interactive Help

The Cisco Catalyst 9800 Series Wireless Controller GUI features an interactive help that walks you through the GUI and guides you through complex configurations.

You can start the interactive help in the following ways:

- By hovering your cursor over the blue flap at the right-hand corner of a window in the GUI and clicking **Interactive Help**.
- By clicking **Walk-me Thru** in the left pane of a window in the GUI.
- By clicking **Show me How** displayed in the GUI. Clicking **Show me How** triggers a specific interactive help that is relevant to the context you are in.

For instance, **Show me How** in **Configure > AAA** walks you through the various steps for configuring a RADIUS server. Choose **Configuration > Wireless Setup > Advanced** and click **Show me How** to trigger the interactive help that walks you through the steps relating to various kinds of authentication.

The following features have an associated interactive help:

- Configuring AAA
- Configuring FlexConnect Authentication
- Configuring 802.1X Authentication
- Configuring Local Web Authentication
- Configuring OpenRoaming
- Configuring Mesh APs



**Note** If the WalkMe launcher is unavailable on Safari, modify the settings as follows:

1. Choose **Preferences > Privacy**.
2. In the **Website tracking** section, uncheck the **Prevent cross-site tracking** check box to disable this action.
3. In the **Cookies and website data** section, uncheck the **Block all cookies** check box to disable this action.

## Supported Cisco Access Point Platforms

The following Cisco access points are supported in the Cisco Embedded Wireless Controller on Catalyst Access Points network. Note that the APs listed as primary APs can also function as subordinate APs.

**Table 4: Cisco APs Supported in Cisco Embedded Wireless Controller on Catalyst Access Points**

Primary AP	Subordinate AP
Cisco Catalyst 9115 Series	Cisco Aironet 1540 Series
Cisco Catalyst 9117 Series	Cisco Aironet 1560 Series
Cisco Catalyst 9120 Series	Cisco Aironet 1815i
Cisco Catalyst 9124AXE/I/D	Cisco Aironet 1815w
Cisco Catalyst 9130	Cisco Aironet 1830 Series
Cisco Catalyst 9105AXI	Cisco Aironet 1840 Series
	Cisco Aironet 1850 Series
	Cisco Aironet 2800 Series
	Cisco Aironet 3800 Series
	Cisco Aironet 4800 Series
	Cisco Catalyst 9115 Series
	Cisco Catalyst 9117 Series
	Cisco Catalyst 9120 Series
	Cisco Catalyst 9124AXE/I/D
	Cisco Catalyst 9130
	Cisco Catalyst 9105AXW
	Cisco Catalyst 9105AXI
	Cisco Catalyst Industrial Wireless 6300 Heavy Duty Series Access Points
	Cisco 6300 Series Embedded Services Access Points

**Table 5: Image Types and Supported APs in Cisco Embedded Wireless Controller on Catalyst Access Points**

Image Type	Supported APs
ap1g4	Cisco Aironet 1810 Series Cisco Aironet 1830 Series Cisco Aironet 1850 Series
ap1g5	Cisco Aironet 1815i Cisco Aironet 1815w Cisco Aironet 1540 Series Cisco Aironet 1850 Series
ap1g6	Cisco Catalyst 9117 Series
ap1g6a	Cisco Catalyst 9130 Cisco Catalyst 9124AXE/I/D
ap1g7	Cisco Catalyst 9115 Series Cisco Catalyst 9120 Series
ap1g8	Cisco Catalyst 9105 Series
ap3g3	Cisco Aironet 2800 Series Cisco Aironet 3800 Series Cisco Aironet 4800 Series Cisco Aironet 1560 Series Cisco Catalyst Industrial Wireless 6300 Heavy Duty Series Access Points Cisco 6300 Series Embedded Services Access Points

## Maximum APs and Clients Supported

**Table 6: Scale Supported in Cisco EWC Network**

Primary AP Model	Maximum APs Supported	Maximum Clients Supported
Cisco Catalyst 9105 AWI	50	1000
Cisco Catalyst 9115 Series	50	1000
Cisco Catalyst 9117 Series	50	1000
Cisco Catalyst 9120 Series	50	1000

Primary AP Model	Maximum APs Supported	Maximum Clients Supported
Cisco Catalyst 9124AXE/I/D	50	1000
Cisco Catalyst 9130	50	1000

**Note**

- If 25 to 50 APs have joined the EWC network, the maximum clients on the EWC internal AP is limited to 20.
- From Cisco IOS XE Dublin 17.12.1 onwards, the maximum supported scale in Cisco Catalyst 9120AX Series APs, Cisco Catalyst 9124AX Series APs, and Cisco Catalyst 9130AX Series APs, is reduced to 50 APs from 100 APs and 1000 clients from 2000 clients.

## Compatibility Matrix

The following table provides software compatibility information:

**Table 7: Compatibility Information**

Cisco Embedded Wireless Controller on Catalyst Access Points	Cisco ISE	Cisco CMX	Cisco Catalyst Center
Cisco IOS XE 17.15.x	3.2	10.6.3	<a href="#">See Cisco Catalyst Center Compatibility Information</a>
	3.1	10.6.2	
	3.0	10.6	
	2.7	10.5.1	

## Supported Browsers and Operating Systems for Web UI

**Note**

The following list of Supported Browsers and Operating Systems is not comprehensive at the time of writing this document and the behavior of various browser for accessing the GUI of the EWC is as listed below.

**Table 8: Supported Browsers and Operating Systems**

Browser	Version	Operating System	Status	Workaround
Google Chrome	77.0.3865.120	macOS Mojave Version 10.14.6	Works	Proceed through the browser warning.

Browser	Version	Operating System	Status	Workaround
Safari	13.0.2 (14608.2.40.1.3)	macOS Mojave Version 10.14.6	Works	Proceed through the browser warning.
Mozilla Firefox	69.0.1	macOS Mojave Version 10.14.6	Works only if exception is added.	Set the exception.
Mozilla Firefox	69.0.3	macOS Mojave Version 10.14.6	Works only if exception is added.	Set the exception.
Google Chrome	77.0.3865.90	Windows 10 Version 1903 (OS Build 18362.267)	Works	Proceed through the browser warning.
Microsoft Edge	44.18362.267.0	Windows 10 Version 1903 (OS Build 18362.267)	Works	Proceed through the browser warning.
Mozilla Firefox	68.0.2	Windows 10 Version 1903 (OS Build 18362.267)	Works	Proceed through the browser warning.
Mozilla Firefox	69.0.3	Windows 10 Version 1903 (OS Build 18362.267)	Works only if exception is added.	Set the exception.
Google Chrome	78.0.3904.108	macOS Catalina 10.15.1	Does not work	NA

## Before You Upgrade

- (#CSCwn29592) EWC running the Cisco IOS XE 17.12.x image on Cisco Catalyst 9124AX APs or 9130AX APs is sometimes unable to load Cisco IOS XE 17.15.2 image due to space constraints.

### Workaround:

- Downgrade first to Cisco IOS XE Cupertino 17.9.6 and then upgrade to Cisco IOS XE 17.15.2.
- The following Remote Procedure Call (RPCs) should be used for Cisco Catalyst 9800 Series Wireless Controller and Cisco Embedded Wireless Controller:
  - Cisco Catalyst 9800 Series Wireless Controller: Use **ewlc-wncd-stats** within *Cisco-IOS-XE-wireless-ap-global-oper*.
  - Cisco Embedded Wireless Controller: Use **ewlc-wncd-stats** within *Cisco-IOS-XE-wireless-access-point-oper*.

## Upgrading the Controller Software

This section covers the various aspects of upgrading the controller software.





**Note** Before converting from CAPWAP to embedded wireless controller (EWC), ensure that you upgrade the corresponding AP with the CAPWAP image in Cisco AireOS Release 8.10.105.0. If this upgrade is not performed, the conversion will fail.

## Finding the Software Version

The following table lists the Cisco IOS XE 17.15.x software for Cisco Embedded Wireless Controller on Catalyst Access Points.

Choose the appropriate AP software based on the following:

- Cisco Embedded Wireless Controller on Catalyst Access Points software to be used for converting the AP from a unified wireless network CAPWAP lightweight AP to a Cisco Embedded Wireless Controller on Catalyst Access Points-capable AP (primary AP)
- AP software image bundle to be used either for upgrading the Cisco Embedded Wireless Controller on Catalyst Access Points software on the primary AP or for updating the software on the subordinate APs or both

Prior to ordering Cisco APs, see the corresponding ordering guide for your Catalyst or Aironet access point.

**Table 9: Cisco Embedded Wireless Controller on Catalyst Access Points Software**

Primary AP	AP Software for Conversion from CAPWAP to Cisco EWC	AP Software Image Bundle for Upgrade	AP Software in the Bundle
Cisco Catalyst 9115 Series	C9800-AP-universalk9.17.15.04.zip C9800-AP-universalk9.17.15.03.zip C9800-AP-universalk9.17.15.2b.zip C9800-AP-universalk9.17.15.02.zip C9800-AP-universalk9.17.15.01.zip	C9800-AP-universalk9.17.15.04.zip C9800-AP-universalk9.17.15.03.zip C9800-AP-universalk9.17.15.2b.zip C9800-AP-universalk9.17.15.02.zip C9800-AP-universalk9.17.15.01.zip	ap1g7
Cisco Catalyst 9117 Series	C9800-AP-universalk9.17.15.04.zip C9800-AP-universalk9.17.15.03.zip C9800-AP-universalk9.17.15.2b.zip C9800-AP-universalk9.17.15.02.zip C9800-AP-universalk9.17.15.01.zip	C9800-AP-universalk9.17.15.04.zip C9800-AP-universalk9.17.15.03.zip C9800-AP-universalk9.17.15.2b.zip C9800-AP-universalk9.17.15.02.zip C9800-AP-universalk9.17.15.01.zip	ap1g6
Cisco Catalyst 9120 Series	C9800-AP-universalk9.17.15.04.zip C9800-AP-universalk9.17.15.03.zip C9800-AP-universalk9.17.15.2b.zip C9800-AP-universalk9.17.15.02.zip C9800-AP-universalk9.17.15.01.zip	C9800-AP-universalk9.17.15.04.zip C9800-AP-universalk9.17.15.03.zip C9800-AP-universalk9.17.15.2b.zip C9800-AP-universalk9.17.15.02.zip C9800-AP-universalk9.17.15.01.zip	ap1g7

Primary AP	AP Software for Conversion from CAPWAP to Cisco EWC	AP Software Image Bundle for Upgrade	AP Software in the Bundle
Cisco Catalyst 9124AXE/I/D	C9800-AP-universalk9.17.15.04.zip C9800-AP-universalk9.17.15.03.zip C9800-AP-universalk9.17.15.2b.zip C9800-AP-universalk9.17.15.02.zip C9800-AP-universalk9.17.15.01.zip	C9800-AP-universalk9.17.15.04.zip C9800-AP-universalk9.17.15.03.zip C9800-AP-universalk9.17.15.2b.zip C9800-AP-universalk9.17.15.02.zip C9800-AP-universalk9.17.15.01.zip	ap1g6a
Cisco Catalyst 9130	C9800-AP-universalk9.17.15.04.zip C9800-AP-universalk9.17.15.03.zip C9800-AP-universalk9.17.15.2b.zip C9800-AP-universalk9.17.15.02.zip C9800-AP-universalk9.17.15.01.zip	C9800-AP-universalk9.17.15.04.zip C9800-AP-universalk9.17.15.03.zip C9800-AP-universalk9.17.15.2b.zip C9800-AP-universalk9.17.15.02.zip C9800-AP-universalk9.17.15.01.zip	ap1g6a

### Supported Access Point Channels and Maximum Power Settings

Supported access point channels and maximum power settings on Cisco APs are compliant with the regulatory specifications of channels, maximum power levels, and antenna gains of every country in which the access points are sold. For more information about the supported access point transmission values in Cisco IOS XE software releases, see the *Detailed Channels and Maximum Power Settings* document at <https://www.cisco.com/c/en/us/support/ios-nx-os-software/ios-xe-17/products-technical-reference-list.html>.

For information about Cisco Wireless software releases that support specific Cisco AP modules, see the "Software Release Support for Specific Access Point Modules" section in the *Cisco Wireless Solutions Software Compatibility Matrix* document.

## Guidelines and Restrictions

Internet Group Management Protocol (IGMP)v3 is not supported on Cisco Aironet Wave 2 APs.

Embedded Wireless Controller SNMP configuration is supported in Cisco Catalyst Center.

High memory usage on AP running Embedded Wireless Controller. Enabling **crash kernel** on the AP consumes additional memory on the AP. Hence, if **crash kernel** is enabled, the overall memory usage of the device will increase and will impact the scale numbers. On Cisco Catalyst 9130 Access Points, the memory consumption is a high of 128 MB.

During the EWC HA pair selection, after a power outage, the standby AP fails to come up in the new EWC HA pair. Another EWC capable AP becomes the standby AP and fails to come up as well. To avoid this situation, ensure that the same IP address is enforced on the active or standby APs during HA pair selection.

## Interoperability with Clients

This section describes the interoperability of the controller software with client devices.

The following table describes the configurations used for testing client devices.

**Table 10: Test Configuration for Interoperability**

Hardware or Software Parameter	Hardware or Software Type
Release	Cisco IOS XE Dublin 17.15.x
Access Points	<ul style="list-style-type: none"> <li>• Cisco Aironet Series Access Points <ul style="list-style-type: none"> <li>• 1540</li> <li>• 1560</li> <li>• 1815i</li> <li>• 1815w</li> <li>• 1830</li> <li>• 1840</li> <li>• 1850</li> <li>• 2800</li> <li>• 3800</li> <li>• 4800</li> </ul> </li> <li>• Cisco Catalyst 9105AX Access Points</li> <li>• Cisco Catalyst 9115AX Access Points</li> <li>• Cisco Catalyst 9117AX Access Points</li> <li>• Cisco Catalyst 9120AX Access Points</li> <li>• Cisco Catalyst 9124AXE/I/D Access Points</li> <li>• Cisco Catalyst 9130AX Access Points</li> </ul>
Radio	<ul style="list-style-type: none"> <li>• 802.11ax</li> <li>• 802.11ac</li> <li>• 802.11a</li> <li>• 802.11g</li> <li>• 802.11n (2.4 GHz or 5 GHz)</li> </ul>
Security	Open, PSK (WPA2-AES), 802.1X (WPA2-AES) (EAP-FAST, EAP-TLS), WPA3.
Cisco ISE	See <a href="#">Compatibility Matrix</a> , on page 7.
Types of tests	Connectivity, traffic (ICMP), and roaming between two APs

The following table lists the client types on which the tests were conducted. Client types included laptops, hand-held devices, phones, and printers.

**Table 11: Client Types**

Client Type and Name	Driver / Software Version
<b>Wi-Fi 6 Devices (Mobile Phone and Laptop)</b>	
Apple iPhone 11	iOS 14.1
Apple iPhone SE 2020	iOS 14.1
Dell Intel AX1650w	Windows 10 ( 21.90.2.1)
DELL LATITUDE 5491 (Intel AX200)	Windows 10 Pro (21.40.2)
Samsung S20	Android 10
Samsung S10 (SM-G973U1)	Android 9.0 (One UI 1.1)
Samsung S10e (SM-G970U1)	Android 9.0 (One UI 1.1)
Samsung Galaxy S10+	Android 9.0
Samsung Galaxy Fold 2	Android 10
Samsung Galaxy Flip Z	Android 10
Samsung Note 20	Android 10
<b>Laptops</b>	
Acer Aspire E 15 E5-573-3870 (Qualcomm Atheros QCA9377)	Windows 10 Pro (12.0.0.832)
Apple Macbook Air 11 inch	OS Sierra 10.12.6
Apple Macbook Air 13 inch	OS Catalina 10.15.4
Apple Macbook Air 13 inch	OS High Sierra 10.13.4
Macbook Pro Retina	OS Mojave 10.14.3
Macbook Pro Retina 13 inch early 2015	OS Mojave 10.14.3
Dell Inspiron 2020 Chromebook	Chrome OS 75.0.3770.129
Google Pixelbook Go	Chrome OS 84.0.4147.136
HP chromebook 11a	Chrome OS 76.0.3809.136
Samsung Chromebook 4+	Chrome OS 77.0.3865.105
DELL Latitude 3480 (Qualcomm DELL wireless 1820)	Win 10 Pro (12.0.0.242)
DELL Inspiron 15-7569 (Intel Dual Band Wireless-AC 3165)	Windows 10 Home (18.32.0.5)

Client Type and Name	Driver / Software Version
DELL Latitude E5540 (Intel Dual Band Wireless AC7260)	Windows 7 Professional (21.10.1)
DELL XPS 12 v9250 (Intel Dual Band Wireless AC 8260 )	Windows 10 (19.50.1.6)
DELL Latitude 5491 (Intel AX200)	Windows 10 Pro (21.40.2)
DELL XPS Latitude12 9250 (Intel Dual Band Wireless AC 8260)	Windows 10 Home (21.40.0)
Lenovo Yoga C630 Snapdragon 850 (Qualcomm AC 2x2 Svc)	Windows 10(1.0.10440.0)
Lenovo Thinkpad Yoga 460 (Intel Dual Band Wireless-AC 9260)	Windows 10 Pro ( 21.40.0)
<b>Note</b> For clients using Intel wireless cards, we recommend you to update to the latest Intel wireless drivers if advertised SSIDs are not visible.	
<b>Tablets</b>	
Apple iPad Pro	iOS 13.5
Apple iPad Air2 MGLW2LL/A	iOS 12.4.1
Apple iPad Mini 4 9.0.1 MK872LL/A	iOS 11.4.1
Apple iPad Mini 2 ME279LL/A	iOS 12.0
Microsoft Surface Pro 3 – 11ac	Qualcomm Atheros QCA61x4A
Microsoft Surface Pro 3 – 11ax	Intel AX201 chipset. Driver v21.40.1.3
Microsoft Surface Pro 7 – 11ax	Intel Wi-Fi chip (HarrisonPeak AX201) (11ax, WPA3)
Microsoft Surface Pro X – 11ac & WPA3	WCN3998 Wi-Fi Chip (11ac, WPA3)
<b>Mobile Phones</b>	
Apple iPhone 5	iOS 12.4.1
Apple iPhone 6s	iOS 13.5
Apple iPhone 8	iOS 13.5
Apple iPhone X MQA52LL/A	iOS 13.5
Apple iPhone 11	iOS 14.1
Apple iPhone SE MLY12LL/A	iOS 11.3
ASCOM SH1 Myco2	Build 2.1
ASCOM SH1 Myco2	Build 4.5
ASCOM Myco 3 v1.2.3	Android 8.1

Client Type and Name	Driver / Software Version
Drager Delta	VG9.0.2
Drager M300.3	VG2.4
Drager M300.4	VG2.4
Drager M540	DG6.0.2 (1.2.6)
Google Pixel 2	Android 10
Google Pixel 3	Android 11
Google Pixel 3a	Android 11
Google Pixel 4	Android 11
Huawei Mate 20 pro	Android 9.0
Huawei P20 Pro	Android 9.0
Huawei P40	Android 10
LG v40 ThinQ	Android 9.0
One Plus 8	Android 10
Oppo Find X2	Android 10
Redmi K20 Pro	Android 10
Samsung Galaxy S7	Android 6.0.1
Samsung Galaxy S7 SM - G930F	Android 8.0
Samsung Galaxy S8	Android 8.0
Samsung Galaxy S9+ - G965U1	Android 9.0
Samsung Galaxy SM - G950U	Android 7.0
Sony Xperia 1 ii	Android 10
Sony Xperia xz3	Android 9.0
Xiaomi Mi10	Android 10
Spectralink 8744	Android 5.1.1
Spectralink Versity Phones 9540	Android 8.1
Vocera Badges B3000n	4.3.2.5
Vocera Smart Badges V5000	5.0.4.30
Zebra MC40	Android 5.0
Zebra MC40N0	Android Ver: 4.1.1
Zebra MC92N0	Android Ver: 4.4.4
Zebra TC51	Android 7.1.2

Client Type and Name	Driver / Software Version
Zebra TC52	Android 8.1.0
Zebra TC55	Android 8.1.0
Zebra TC57	Android 8.1.0
Zebra TC70	Android 6.1
Zebra TC75	Android 6.1.1
<b>Printers</b>	
Zebra QLn320 Printer	LINK OS 6.3
Zebra ZT230 Printer	LINK OS 6.3
Zebra ZQ310 Printer	LINK OS 6.3
Zebra ZD410 Printer	LINK OS 6.3
Zebra ZT410 Printer	LINK OS 6.3
Zebra ZQ610 Printer	LINK OS 6.3
Zebra ZQ620 Printer	LINK OS 6.3
<b>Wireless Module</b>	
Intel 11ax 200	Driver v22.20.0
Intel AC 9260	Driver v21.40.0
Intel Dual Band Wireless AC 8260	Driver v19.50.1.6

## Issues

Issues describe unexpected behavior in Cisco IOS releases. Issues that are listed as Open in a prior release are carried forward to the next release as either Open or Resolved.



**Note** All incremental releases will cover fixes from the current release.

## Cisco Bug Search Tool

The Cisco [Bug Search Tool](#) (BST) allows partners and customers to search for software bugs based on product, release, and keyword, and aggregates key data such as bug details, product, and version. The BST is designed to improve the effectiveness in network risk management and device troubleshooting. The tool has a provision to filter bugs based on credentials to provide external and internal bug views for the search input.

To view the details of a caveat, click the corresponding identifier.

## Open Issues for Cisco IOS XE 17.15.4

Identifier	Headline
<a href="#">CSCwk79990</a>	Controller encounters kernel unresponsiveness due to IntelResetRequest
<a href="#">CSCwp14628</a>	Cisco Aironet 3800 APs display client authentication issue after AP Migration to a controller running 17.15.3
<a href="#">CSCwp20530</a>	Controller does not forward downstream packets to the wireless client after switchover
<a href="#">CSCwp27215</a>	Cisco Catalyst 9124 AP in Mesh mode encounters poor iperf traffic performance
<a href="#">CSCwp32113</a>	Controller reloads due to kernel unresponsiveness with segmentation fault (11) in process IGMP SN
<a href="#">CSCwp61179</a>	Cisco Catalyst 9130 AP fails in port authentication with ClearPass Server
<a href="#">CSCwp65769</a>	Wave 2 APs performing with fast transition with 802.1X authentication send incorrect M2 message during re-key on session timeout
<a href="#">CSCwo86312</a>	Controller shows a mismatch between client counts from "show client" commands and SNMP walk totals
<a href="#">CSCwo92511</a>	Controller has inconsistent default MTU settings for mobility tunnels
<a href="#">CSCwp07279</a>	Controller unexpectedly reloads due to local software fatal error
<a href="#">CSCwp39409</a>	Controller reboots unexpectedly due to an assertion failure in WNCd process
<a href="#">CSCwp93598</a>	Memory leak found in the controller process related to handling a specific database string

## Open Issues for Cisco IOS XE 17.15.3

Identifier	Headline
<a href="#">CSCwn36778</a>	Cisco Catalyst 9800-80 controller displays low memory leak potentially in the 'ipv4_addr' field
<a href="#">CSCwn90360</a>	Controller does not start EAP process due to the packet transmission delay from AP
<a href="#">CSCwn90855</a>	Controller overrides client's IP address in the device tracking database causing packet loss
<a href="#">CSCwn94597</a>	Cisco Catalyst 9136 AP displays client stale entry due to delete reason NACK_IFID_EXISTS
<a href="#">CSCwo03840</a>	Multiple AP modes encounter CAPWAPd crash while changing from dualstack to IPv6
<a href="#">CSCwo08534</a>	Cisco Catalyst 9120 AP encounters kernel unresponsiveness due to: Radio firmware beacon TX stuck



Identifier	Headline
<a href="#">CSCwk53741</a>	Anchor controller drops mobility tunnel even when keepalive timers aren't hit
<a href="#">CSCwn31021</a>	Controller fails to represent the correct format of AP Name and VLAN ID in option 82
<a href="#">CSCwn73024</a>	Cisco Catalyst 9130AX AP fails PKCS certificate enrollment to support special characters on WGB
<a href="#">CSCwn76129</a>	Controller fails to handle loadbalance discovery message resulting in stale AP entries
<a href="#">CSCwn79857</a>	URL with multiple IPs do not work in FlexConnect Local Switching
<a href="#">CSCwn83397</a>	Wired Mesh AP client flaps between VLAN 0 and numbered native VLAN on Root AP
<a href="#">CSCwo04476</a>	Cisco Catalyst 9130AX AP encounters kernel unresponsiveness
<a href="#">CSCwo15057</a>	Cisco Catalyst 9120 AP encounters kernel unresponsiveness
<a href="#">CSCwo16038</a>	Cisco Catalyst 9124 AP's WGB becomes unreachable after connecting to a Cisco Aironet 2800 Root AP when WMM is disabled
<a href="#">CSCwo20395</a>	Controller's rogue classification rules do not apply configured classifications
<a href="#">CSCwo29017</a>	Controller encounters kernel unresponsiveness after issuing command 'show ap config slots'
<a href="#">CSCwo30925</a>	Cisco Wi-Fi 6 and above APs do not support disabling WMM on radios that support 802.11n/11ac/11ax operation
<a href="#">CSCwo31854</a>	RA Trace / Always-on traces do not generate past logs when collected over several hours
<a href="#">CSCwo32255</a>	Anchor controller's AVC statistics show in the controller's CLI but not in the Web UI
<a href="#">CSCwo37680</a>	Controller initiates client deletion with code: CO_CLIENT_DELETE_REASON_DOT11_MAX_STA
<a href="#">CSCwo37756</a>	Cisco Aironet 1815t AP does not receive an internal DHCP IP address when connected to LAN3

## Open Issues for Cisco IOS XE 17.15.2b

There are no open issues in the Cisco IOS XE 17.15.2b release.

## Open Issues for Cisco IOS XE 17.15.2

Identifier	Headline
<a href="#">CSCwn29592</a>	EWC running the Cisco IOS XE 17.12.x image on Cisco Catalyst 9124AX APs or 9130AX APs is sometimes unable to load Cisco IOS XE 17.15.2 image

Identifier	Headline
<a href="#">CSCwk64840</a>	Controller unexpectedly reboots due to memory depletion due to mobilityd process
<a href="#">CSCwm97615</a>	Cisco Aironet 1562 MAP does not form mesh with Cisco Catalyst 9124 RAP running 17.9
<a href="#">CSCwm37410</a>	Cisco Catalyst 9120 AP does not forward large packets when MTU=1500
<a href="#">CSCwn08479</a>	Cisco Catalyst 9120 AP experiences kernel unresponsiveness due to wlc_bsscfcg_find_by_target_bssid+0xb8/0xe0

## Open Issues for Cisco IOS XE 17.15.1

Identifier	Headline
<a href="#">CSCwh63050</a>	Controller sends IGMP queries without IP address and MAC address on Cisco IOS XE Cupertino 17.9.3
<a href="#">CSCwi04855</a>	APs repeatedly join and disjoin controller with traceback
<a href="#">CSCwj39057</a>	Cisco Catalyst 9130 AP experiences traffic loss and delays due to perceived channel utilization and interference
<a href="#">CSCwj42305</a>	Client is unable to connect due to delete reason NACK_IFID_EXISTS
<a href="#">CSCwj80614</a>	Clients are unable to connect due to assignment of IP address that is in use by stale client entry in device-tracking database in FlexConnect local switching
<a href="#">CSCwj83526</a>	APs become non-operational when connected to Cisco Catalyst 9300 Switch via mGig port
<a href="#">CSCwj85091</a>	Controller unexpectedly reloads while running the <b>show wireless client mac-address detail</b> command
<a href="#">CSCwj89538</a>	Cisco Aironet 2802 AP fails to send reassociation response or association request
<a href="#">CSCwk05809</a>	%EVENTLIB-3-CPUHOG message observed on Cisco IOS XE 17.12
<a href="#">CSCwk17102</a>	Client experiences unexpected disconnect due to missing M1 packet
<a href="#">CSCwk17667</a>	Controller reboots due to high ODM memory consumption
<a href="#">CSCwk37983</a>	Client VLAN is retained after changing SSIDs if "\"vlan-persistent\" is enabled
<a href="#">CSCwk39866</a>	Client page is stuck in loading state
<a href="#">CSCwk46105</a>	Controller experiences unexpected reloads with high WNCd memory
<a href="#">CSCwk48338</a>	Cisco Catalyst 9130 does not accept clients on the 5 GHz band
<a href="#">CSCwk48634</a>	FlexConnect local switching dropping upstream broadcast ARP from Android devices in data path in Cisco Catalyst 9130 AP

Identifier	Headline
<a href="#">CSCwk52996</a>	Cisco Catalyst 9120 AP unexpectedly reloads along with radio abnormalities on wlc_bmac_suspend_mac
<a href="#">CSCwk54291</a>	Controller voice CAC BW is not cleared
<a href="#">CSCwk58326</a>	Controller sends multicast packets with previous WMI
<a href="#">CSCwk61068</a>	Controller unexpectedly reloads on 17.9.4 with reason "critical process WNCd fault"
<a href="#">CSCwk61854</a>	Configuration update failure when AP is in delete pending state
<a href="#">CSCwk62836</a>	Cisco Catalyst 9120 AP running on Cisco IOS XE Cupertino 17.9.5
<a href="#">CSCwk64235</a>	URL filter inconsistency observed post modification
<a href="#">CSCwk66988</a>	Cisco Catalyst 9130 experiences radio failure

## Resolved Issues for Cisco IOS XE 17.15.4

Identifier	Headline
<a href="#">CSCwo98644</a>	RRM does not update the default channel when using IPv6 only on the controller
<a href="#">CSCwp59171</a>	Users unable to add allowed user on Lobby admin page
<a href="#">CSCwo89539</a>	Controller reload unexpectedly when adding "location civic-location-id" to multiple interfaces
<a href="#">CSCwn99763</a>	Noise floor value is always displayed as 0 for a few x-paths
<a href="#">CSCwo00821</a>	IoT Orchestrator is unable to start after an upgrade or a reload
<a href="#">CSCwp31397</a>	Controller DFS Radar Detection results in most of the APs allocated to the same channel
<a href="#">CSCwo62157</a>	Controller with CAPWAP enabled display memory leak in tdl_mac_addr object
<a href="#">CSCwn39428</a>	Error message "Flow Monitor is Required" is shown even when flow monitor name is available
<a href="#">CSCwp21187</a>	Controller unexpectedly reboots due to due to mDNS packet
<a href="#">CSCwo29017</a>	wncmgrd kernel unresponsiveness after issue command \u2018show ap config slots\u2019
<a href="#">CSCwn92827</a>	Secondary controller fails with rsync error
<a href="#">CSCwo15982</a>	Controller unexpectedly reboots with 17.15.3.14 image
<a href="#">CSCwo54553</a>	Controller displays traceback messages when default-policy-tag APs block initiates a configuration change for other APs due to Ref-count not zero
<a href="#">CSCwp16968</a>	1562 WGB FT Roaming client disconnection issue due to MAC record Mismatch

Identifier	Headline
<a href="#">CSCwo07767</a>	Controller's active chassis get stuck in active recovery state on 17.12.4
<a href="#">CSCwn92477</a>	Controller unexpectedly reboots during WNCd process due to assertion failure with invalid BSSID
<a href="#">CSCwn90855</a>	Controller overrides client's IP address in the device tracking database causing packet loss
<a href="#">CSCwn94511</a>	The factory-reset all command is unsecure but functions as if it has a secure option
<a href="#">CSCwo97886</a>	Controller display out of order packet issue with fragmented packet when AutoQOS is enabled
<a href="#">CSCwo35645</a>	NETCONF over SSH fails to return all the records for wireless-client-oper and shows 'invalid XML' before everything is returned
<a href="#">CSCwp12959</a>	Wireless client gets excluded with one authentication failure or never gets excluded
<a href="#">CSCwn11160</a>	Controller running in HA in guest anchor sends traffic to the wrong tunnel after switchover for already connected clients
<a href="#">CSCwo37680</a>	Controller initiates client deletion with code: CO_CLIENT_DELETE_REASON_DOT11_MAX_STA
<a href="#">CSCwn96363</a>	Remove redundant counters from "show wireless stats ap name <ap-name> dot11 5GHz" output
<a href="#">CSCwo70030</a>	WNCd process rogues even when bssid-neighbor-stats config is disabled
<a href="#">CSCwn31021</a>	Controller fails to represent the correct format of AP Name and VLAN ID in option 82
<a href="#">CSCwo19011</a>	Controller observes unexpected SISF reboot with WNCd core
<a href="#">CSCwp25552</a>	BSSID-mac dispatched as 00:00:00:00:00:00 for slot 1 WLAN 1
<a href="#">CSCwn33501</a>	Controller connected to the AP does not give any output while executing the #show ap summary sort name command
<a href="#">CSCwp03988</a>	Unexpected Reload Due to Unsuccessful copy of the MAC address
<a href="#">CSCwo20395</a>	Controller's rogue classification rules do not apply configured classifications
<a href="#">CSCwo53638</a>	Client error: High-availability data path setup failed on standby device in RA trace
<a href="#">CSCwo61286</a>	Audit session ID changes after inter-WNCd roam on Central Web Authentication (CWA) with PSK
<a href="#">CSCwp26707</a>	Controller fails to start L2 authentication for 11r clients with vlan-persistent configured in 17.12.5
<a href="#">CSCwp86129</a>	Client connected to local mac-auth PSK or MPSK SSIDs get disconnected and do not remain connected to the controller

Identifier	Headline
<a href="#">CSCwo98083</a>	Access points are unreachable in inventory on Cisco Connected Cloud version 2.3.7.9
<a href="#">CSCwo64967</a>	Mobility tunnel with data-link encryption intermittently disconnects when the fourth octet of the WMI address is 255
<a href="#">CSCwo41248</a>	Controller display wrong message when configuring 2 radios on the same UNII band (100 - 144)
<a href="#">CSCwo33572</a>	Failed to collect RA tracing logs on Cisco IOS XE Release 17.9.5

## Resolved Issues for Cisco IOS XE 17.15.3

Caveat ID	Description
<a href="#">CSCwn17412</a>	FlexConnect local switching traffic gets randomly centralized on a WebAuth SSID
<a href="#">CSCwj84377</a>	Client detail for 'Associated' Client does not display some info element when using Cisco Spaces with Connector
<a href="#">CSCwk26966</a>	Cisco Aironet 3802 AP displays false radar detection only on UNI-II after upgrading the software
<a href="#">CSCwk58326</a>	Controller sends multicast packets with previous WMI
<a href="#">CSCwk64840</a>	Controller unexpectedly reboots due to memory depletion due to mobilityd process
<a href="#">CSCwk81946</a>	Controller experiences kernel unresponsiveness due to tdl memory corruption
<a href="#">CSCwm48283</a>	Controller is stuck in internal-error state after upgrade to HP5
<a href="#">CSCwm58430</a>	Cisco Catalyst 9115 AP experiences kernel unresponsiveness due to: Beacon Stuck Reset Radio
<a href="#">CSCwm67254</a>	RadSec messages are missing CUI attributes
<a href="#">CSCwm73020</a>	Controller relays unicast DHCP requests
<a href="#">CSCwm79348</a>	AP remains stuck in the activate state without progressing to RUN when IOX-APP starts before USB detection
<a href="#">CSCwm86679</a>	Cisco Catalyst 9800-40 controllers encounter kernel unresponsiveness and reboot unexpectedly at rogue_start_container
<a href="#">CSCwn09549</a>	Cisco Catalyst 9124 AP unable to join and intermittently disconnects with Cisco Catalyst 9124 AP
<a href="#">CSCwn10606</a>	Cisco Catalyst 9120 Wi-Fi 6 AP fails to report RFID packets to the controller
<a href="#">CSCwn10992</a>	DTLS timeout because of improper client load balancing
<a href="#">CSCwn15048</a>	Controller does not filter out the expansion module SN field before sending it to DNAC, causing the collection to fail

Caveat ID	Description
<a href="#">CSCwn26561</a>	RFID measurement is missing during RFID statistics collection window
<a href="#">CSCwn27951</a>	Cisco Catalyst 9105W AP: RLAN fast switching breaks DHCP for non-native VLAN wireless
<a href="#">CSCwn36115</a>	iPhone 16 device is listed as unclassified in iOS 18.0.1
<a href="#">CSCwn44287</a>	APs running on Cisco Catalyst 9300 Series switches FiaB generate CAPWAP crash files
<a href="#">CSCwn50926</a>	Acct-Session-ID attribute is missing from access request after client deletion
<a href="#">CSCwn52205</a>	AP IOX wait for time it takes for AP to detect and add USB device entry before starting IOX APP
<a href="#">CSCwn61980</a>	Rogues detected on inactive bands by dual-band radio APs fail to display properly on the UI
<a href="#">CSCwn66225</a>	Invalid Tx power on beacon frame causes iPhone clients to disconnect
<a href="#">CSCwn81268</a>	IOX AP in RUN state ends up in activate state after switch reload
<a href="#">CSCwn82037</a>	Cisco Catalyst 9120 AP does not report RFID packets to controller intermittently
<a href="#">CSCwn83869</a>	AP sleep count timer value stuck in 80 while configuring speed after the radar event in MFG
<a href="#">CSCwn89252</a>	APs running IOS XE 17.15.2 unable to install Solum IOX APP
<a href="#">CSCwn90874</a>	Guest anchor controller shows error message when creating anchor-export-ACK
<a href="#">CSCwn98574</a>	Corrupt VRF name causes client to frequent disconnects and get stuck at mobility while roaming
<a href="#">CSCwo02178</a>	FT-SAE clients fails to roam between controller in same mobility group due to PMKID mismatch
<a href="#">CSCwo26102</a>	Cisco Aironet 1800i AP shows wrong compile time after joining latest controller version
<a href="#">CSCwi48178</a>	WNCd error in SafeC Validation for memcmp_s: dmax is 0
<a href="#">CSCwj53257</a>	APs detected for the first time set timer to 3600 seconds instead of 1800 seconds
<a href="#">CSCwj72174</a>	Cisco Aironet 2800 Series AP connected to same controller is detected as rogue by other connected APs
<a href="#">CSCwk33513</a>	WGB takes time to roam for Cisco Catalyst 9120, 9105 AP
<a href="#">CSCwk76786</a>	AP radio service is down after DFS is set to CH100 and automatically changes to sniffer mode on CH100 and then back to client serving
<a href="#">CSCwm37410</a>	Cisco Catalyst 9120 AP does not forward large packets when MTU=1500

Caveat ID	Description
<a href="#">CSCwm56315</a>	Cisco Aironet 2800, 3800, 4800 AP: STA-ID list mismatch with radio river client summary after veriwave roaming test
<a href="#">CSCwm66425</a>	BLE operations with RadioActive trace enabled encounters kernel unresponsiveness
<a href="#">CSCwm78841</a>	Over the Air (OTA) packet does not display increment in AP after setting truncate value to 25bytes and enabling OTA
<a href="#">CSCwm91684</a>	DNAC SSID monitor does not work for ICAP RF-Stats
<a href="#">CSCwm92779</a>	DNAC Wireless Client Assurance Dashboard displays no data for "Avg Latency"
<a href="#">CSCwm92836</a>	Request ID mismatch observed at max connections for AP Tx profile configuration
<a href="#">CSCwn00375</a>	Controller does not generate AP disjoin event message syslog after the AP is disconnected
<a href="#">CSCwn08479</a>	Cisco Catalyst 9120 Wave 2 APs encounter kernel unresponsiveness at wlc_bsscfig_find_by_target_bssid+0xb8/0xe0 CS00012376904
<a href="#">CSCwn14495</a>	Cisco Catalyst 91XX AP detects its own BSSID as rogue
<a href="#">CSCwn15002</a>	Cisco Catalyst 9120 AP encounters kernel unresponsiveness at wlc_low_txq_enq
<a href="#">CSCwn19804</a>	Cisco Aironet 1562D AP doesn't deploy in indoor mode
<a href="#">CSCwn43094</a>	RLAN clients do not show up in the controller's client table after a CAPWAP drop/join
<a href="#">CSCwn48978</a>	AP incorrectly send ARP requests for the DHCP IP address even after a DHCP release packet
<a href="#">CSCwn77377</a>	IP addresses cannot be retrieved from the status file when the DHCP options on lease are available
<a href="#">CSCwn84552</a>	Cisco Catalyst 9105 APs get stuck in a code download loop while upgrading or downgrading
<a href="#">CSCwn85374</a>	Controller displays memory usage increasing in the cloudm process

## Resolved Issues for Cisco IOS XE 17.15.2b

Identifier	Headline
<a href="#">CSCwm97615</a>	Cisco Aironet 1562 MAP does not form mesh with Cisco Catalyst 9124 RAP running 17.9

## Resolved Issues for Cisco IOS XE 17.15.2

Identifier	Headline
<a href="#">CSCwm12544</a>	Controller unexpectedly reloads with cpp-ucode exception due to a rbuf out-of-handle

## Resolved Issues for Cisco IOS XE 17.15.1

Identifier	Headline
<a href="#">CSCwj39057</a>	Cisco Catalyst 9130 AP experiences traffic loss and delays due to perceived channel utilization and interference
<a href="#">CSCwj85091</a>	Controller unexpectedly stops working while running the show wireless client mac-address detail command
<a href="#">CSCwk12169</a>	Cisco Catalyst 9105/9115/9120 AP fails for clients connected in 5G slot
<a href="#">CSCwm07499</a>	Cisco Catalyst 91xx AP does not rotate awipsd.log causing an upgrade issue "tar: write error: No space left on device"
<a href="#">CSCwm09148</a>	EWC rogue syslogs are missing
<a href="#">CSCwm30964</a>	EWC does not start on RAP after factory reset

## Resolved Issues for Cisco IOS XE 17.15.1

Identifier	Headline
<a href="#">CSCwh56566</a>	Controller experiences flow monitor failure due to manual flow record parameters
<a href="#">CSCwh80060</a>	Cisco Wave 2 APs connected to the controller are losing the FlexConnect WLAN-VLAN mapping
<a href="#">CSCwh81071</a>	Slot 2 is down for GB country after performing factory reset
<a href="#">CSCwi16509</a>	APs do not join the controller with invalid radio slot ID error
<a href="#">CSCwi22895</a>	Controller becomes unresponsive within Radio Resource Management (RRM) service due to ReloadReason=Critical process rrm fault
<a href="#">CSCwi27380</a>	Media stream feature does not work
<a href="#">CSCwi28382</a>	Controller reloads unexpectedly due to Keymgmt: Failed to eapol key m1 retransmit failure
<a href="#">CSCwi55714</a>	Controller unexpectedly reboots when handling NMSP TLS connection
<a href="#">CSCwi56780</a>	MAC Authentication Bypass (MAB) is not initiated unless the client device is deauthenticated
<a href="#">CSCwi69251</a>	Cisco Catalyst 9800-40 Wireless Controller becomes unresponsive on Critical process Radio Resource Management (RRM) fault on rp_0_0
<a href="#">CSCwi75759</a>	Cisco Catalyst 9800-40 Wireless Controller reloads due to critical process WNCd fault
<a href="#">CSCwi99276</a>	Controller does not have Network Access Control (NAC) in the policy profile configuration enabled on Prime Infrastructure
<a href="#">CSCwj08367</a>	Cisco Catalyst 9800 Wireless Controller encounters unresponsiveness generating system report, segmentation fault - Process = IGMPSPN



Identifier	Headline
<a href="#">CSCwj09698</a>	Cisco Catalyst 9800 Wireless Controller encounters an unexpected reset in wncmgrd with a scaled setup while being managed by the Meraki Dashboard
<a href="#">CSCwj25187</a>	Controller does not display the redundancy details on the Web-UI, only on the CLI
<a href="#">CSCwj26196</a>	Controller encounters an unexpected reset while trying to validate the MAC address with the EWLC_APP_INFRA_ID_MAGIC
<a href="#">CSCwj31356</a>	Controller reboots due to Radio Resource Management (RRM) process fault on rp_0_0 (rc=139)
<a href="#">CSCwj36962</a>	Controller reboots unexpectedly due to invalid QoS parameters
<a href="#">CSCwj42408</a>	Controller posture flow does not work when PMF is optional
<a href="#">CSCwj34379</a>	Cisco Catalyst 9800-80 Wireless Controller encounters WNCd issues when accessing Crimson Database
<a href="#">CSCwj79545</a>	Controller unexpectedly reboots during WNCd process due to assertion failure with invalid BSSID
<a href="#">CSCwj86938</a>	Memory leak in scale network with telemetry shared user events with Cisco Catalyst Center
<a href="#">CSCwj93153</a>	Controller becomes unresponsive during WNCd process
<a href="#">CSCwk05030</a>	Controller becomes unresponsive due to critical software exception
<a href="#">CSCwj40202</a>	Controller does not send RADIUS accounting messages WLAN with PSK/MAB authentication
<a href="#">CSCwj60910</a>	Controller and PI report observe RRM message mismatch
<a href="#">CSCwh88246</a>	AP does not allow you to apply URL filter after invalid configuration
<a href="#">CSCwi01382</a>	5-GHz and 2.4-GHz radios remain non-operational in an AP
<a href="#">CSCwj67158</a>	Controller does not send mobile address to AP if the CoA is received when the user is in the ip_learn state
<a href="#">CSCwj72370</a>	Controller uses incorrect username for "show platform" command when logging in GUI
<a href="#">CSCwi47294</a>	Per client rate limit with FlexConnect AP is not functioning
<a href="#">CSCwi48980</a>	Controller local password policy does not take effect on GUI login as expected
<a href="#">CSCwi50732</a>	VLAN group support for DHCP and static IP clients feature does not work on FlexConnect Central Switching mode
<a href="#">CSCwi64010</a>	Controller accepts the reserved IPv6 multicast address to be configured as a mobility multicast IPv6 address
<a href="#">CSCwi66582</a>	Controller returns with error while uploading backup file with FTP on GUI

Identifier	Headline
<a href="#">CSCwi69093</a>	Controller GUI shows incorrect number of clients connected to the AP
<a href="#">CSCwj76892</a>	Controller configures aggregation scheduler parameter incorrectly, causing low downlink speed
<a href="#">CSCwi83124</a>	Pop-ups are not displayed correctly in dark mode in the controller
<a href="#">CSCwj00465</a>	Active controller becomes ActiveRecovery when the redundancy port link is down
<a href="#">CSCwj01446</a>	Personal Identity Verification (PIV) authentication requires an additional backslash in the redirection URL to work successfully
<a href="#">CSCwj04177</a>	AP undergoing Extensible Authentication Protocol (EAP) fails if the password is more than 31 characters
<a href="#">CSCwj15376</a>	Cisco NMSP runs into security protocol issues
<a href="#">CSCwj25110</a>	Controller reports incorrect values during SNMP polling
<a href="#">CSCwj77128</a>	URL filter allows only letters as the first character
<a href="#">CSCwj33376</a>	Incorrect selection of APs in load balancing
<a href="#">CSCwj94201</a>	Controller experiences unresponsiveness CPUHOG
<a href="#">CSCwj68763</a>	Enhanced URL is missing after FlexConnect AP CAPWAP flap
<a href="#">CSCwk35891</a>	Controller experiences unresponsiveness after displaying "\clear ap geolocation derivation\" message
<a href="#">CSCwj42562</a>	GUI does not display PC analytics statistics
<a href="#">CSCwk44459</a>	Loadbalancer server holds incorrect AP IP address and stale entries
<a href="#">CSCwi44211</a>	The "show run" command results are different from restore configuration
<a href="#">CSCwj29406</a>	The "show ap summary sort descending client-count" command shows wrong client count
<a href="#">CSCwi29216</a>	Unsupportive characters in the description field prevents re-sync
<a href="#">CSCwj83935</a>	Controller shows tech X is empty when previous tech X term length stop didn't finish before SSH close
<a href="#">CSCwi70760</a>	Controller encrypts ApDnaGlobalCfg token when the password encryption is configured using AES
<a href="#">CSCwj96620</a>	Syntax errors observed in CISCO-LWAPP-DOT11-CLIENT-MIB
<a href="#">CSCwj96666</a>	Syntax errors observed in CISCO-LWAPP-DOT11-MIB
<a href="#">CSCwj97107</a>	Standby controller does not take active role after reloading the active controller with "reload slot" command

Identifier	Headline
<a href="#">CSCwk02633</a>	An RSA key pair is configured in the truspoint configuration when an EC keypair is selected when creating a trustpoint on the controller
<a href="#">CSCwk25182</a>	Controller throws password policy alert while logging in GUI using TACACS+ credentials after upgrading to Cisco IOS XE 17.14
<a href="#">CSCwk28680</a>	Controller unexpectedly reloads due to Cisco QuantumFlow Processor (QFP) ucode while updating the drop statistics
<a href="#">CSCwj33979</a>	Output for the <b>show ap summary</b> command takes lengthy duration to complete
<a href="#">CSCwk14917</a>	Controller reloads unexpectedly

## Troubleshooting

For the most up-to-date, detailed troubleshooting information, visit the Cisco TAC website at:

<https://www.cisco.com/en/US/support/index.html>

Go to **Product Support** and select your product from the list, or enter the name of your product. Look under **Troubleshoot and Alerts** to find information about the problem that you are experiencing.

## Related Documentation

Information about Cisco IOS XE is available at:

<https://www.cisco.com/c/en/us/products/ios-nx-os-software/ios-xe/index.html>

All the support documentation for Cisco Catalyst 9100 Access Points are available at: <https://www.cisco.com/c/en/us/support/wireless/catalyst-9100ax-access-points/tsd-products-support-series-home.html>

Cisco Validated Designs documents are available at:

<https://www.cisco.com/go/designzone>

### Cisco Embedded Wireless Controller on Catalyst Access Points

For support information, see the following documents:

- [Cisco Wireless Solutions Software Compatibility Matrix](#)
- [Cisco Embedded Wireless Controller on Catalyst Access Points Software Configuration Guide](#)
- [Cisco Embedded Wireless Controller on Catalyst Access Points Command Reference Guide](#)

Installation guides for Catalyst Access Points are available at:

<https://www.cisco.com/c/en/us/support/wireless/catalyst-9100ax-access-points/products-installation-guides-list.html>

For all Cisco Wireless Controller software-related documentation, see:

<https://www.cisco.com/c/en/us/support/wireless/catalyst-9800-series-wireless-controllers/tsd-products-support-series-home.html>

### Wireless Products Comparison

- Use this tool to compare the specifications of Cisco wireless APs and controllers:

<https://www.cisco.com/c/en/us/products/wireless/wireless-lan-controller/product-comparison.html>

- Product Approval Status:

[https://prdapp.cloudapps.cisco.com/cse/prdapp/jsp/externalsearch.do?action=externalsearch&page=EXTERNAL\\_SEARCH](https://prdapp.cloudapps.cisco.com/cse/prdapp/jsp/externalsearch.do?action=externalsearch&page=EXTERNAL_SEARCH)

- Wireless LAN Compliance Lookup:

<https://www.cisco.com/c/dam/assets/prod/wireless/wireless-compliance-tool/index.html>

### Cisco Access Points—Statement of Volatility

The STATEMENT OF VOLATILITY is an engineering document that provides information about the device, the location of its memory components, and the methods for clearing device memory. Refer to the data security policies and practices of your organization and take the necessary steps required to protect your devices or network environment.

The Cisco Aironet and Catalyst AP Statement of Volatility (SoV) documents are available on Cisco Trust Portal at <https://trustportal.cisco.com/c/r/ctp/trust-portal.html#/>.

You can search by the AP model to view the SoV document.

### Cisco Connected Mobile Experiences

[Cisco Connected Mobile Experiences Documentation](#)

### Cisco Catalyst Center

[Cisco Catalyst Center Documentation](#)

## Communications, Services, and Additional Information

- To receive timely, relevant information from Cisco, sign up at [Cisco Profile Manager](#).
- To get the business results you're looking for with the technologies that matter, visit [Cisco Services](#).
- To submit a service request, visit [Cisco Support](#).
- To discover and browse secure, validated enterprise-class apps, products, solutions and services, visit [Cisco DevNet](#).
- To obtain general networking, training, and certification titles, visit [Cisco Press](#).
- To find warranty information for a specific product or product family, access [Cisco Warranty Finder](#).

### Cisco Bug Search Tool

[Cisco Bug Search Tool](#) (BST) is a web-based tool that acts as a gateway to the Cisco bug tracking system that maintains a comprehensive list of defects and vulnerabilities in Cisco products and software. BST provides you with detailed defect information about your products and software.

---

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/c/en/us/about/legal/trademarks.html>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1721R)

© 2024 Cisco Systems, Inc. All rights reserved.