

Risoluzione dei problemi relativi all'intestazione L2 errata per il traffico MPLS in transito

Sommario

[Introduzione](#)

[Problema](#)

[Soluzione](#)

Introduzione

In questo documento viene descritto come risolvere i problemi quando il percorso di inoltro MPLS viene interrotto a causa di un danneggiamento dell'intestazione L2 sul nodo NCS4K (6.5.26).

Problema

In questo scenario, il tunnel TE (Traffic Engineering) è attivo, ma il ping MPLS (Multiprotocol Label Switching) non funziona tramite il tunnel MPLS:

```
tunnel-te5180 10.38.101.62 Up Up default #ping mpls traffic-eng tunnel-te 5180 Thu Jan 5
21:30:29.245 UTC Sending 5, 100-byte MPLS Echos to tunnel-te5180, timeout is 2 seconds, send
interval is 0 msec: Codes: '!' - success, 'Q' - request not sent, '.' - timeout, 'L' - labeled
output interface, 'B' - unlabeled output interface, 'D' - DS Map mismatch, 'F' - no FEC mapping,
'f' - FEC mismatch, 'M' - malformed request, 'm' - unsupported tlvs, 'N' - no rx label, 'P' - no
rx intf label prot, 'p' - premature termination of LSP, 'R' - transit router, 'I' - unknown
upstream index, 'X' - unknown return code, 'x' - return code 0 Type escape sequence to abort.
..... Success rate is 0 percent (0/5)
```

Verranno visualizzati alcuni hop nel traceroute MPLS:

```
#traceroute mpls traffic-eng tunnel-te 5180 Thu Jan 5 21:30:49.405 UTC Tracing MPLS TE Label
Switched Path on tunnel-te5180, timeout is 2 seconds Codes: '!' - success, 'Q' - request not
sent, '.' - timeout, 'L' - labeled output interface, 'B' - unlabeled output interface, 'D' - DS
Map mismatch, 'F' - no FEC mapping, 'f' - FEC mismatch, 'M' - malformed request, 'm' -
unsupported tlvs, 'N' - no rx label, 'P' - no rx intf label prot, 'p' - premature termination of
LSP, 'R' - transit router, 'I' - unknown upstream index, 'X' - unknown return code, 'x' - return
code 0 Type escape sequence to abort. 0 172.16.61.78 MRU 9582 [Labels: 27769 Exp: 0] L 1
172.16.61.79 MRU 9582 [Labels: 28136 Exp: 0] 7 ms . 2 * . 3 * . 4 * . 5 *^C
```

Se si controlla il tunnel MPLS, si osserverà che altri due hop sono segnalati per il router esplicito (ERO):

```
#show mpls traffic-eng tunnels 5180 Thu Jan 5 21:31:11.958 UTC Name: tunnel-te5180 Destination:
10.38.96.1 Ifhandle:0x80002c4 Signalled-Name: MIVLPAMI-0112003A_t5180 Status: Admin: up Oper: up
Path: valid Signalling: connected path option 10, type dynamic (Basis for Setup, path weight
3000) Accumulative metrics: TE 3000 IGP 30 Delay 900000 Path-option attribute: eline-any Number
of affinity constraints: 1 Include bit map : 0x2 Include ext bit map : Length: 256 bits Value :
0x::2 Include affinity name : eline(1) G-PID: 0x0800 (derived from egress interface properties)
Bandwidth Requested: 7 kbps CT0 Creation Time: Thu Nov 10 22:17:55 2022 (7w6d ago) Config
Parameters: Bandwidth: 0 kbps (CT0) Priority: 5 5 Affinity: 0x0/0xffff Metric Type: TE
(interface) Path Selection: Tiebreaker: Min-fill (default) Hop-limit: disabled Cost-limit:
```

disabled Delay-limit: disabled Path-invalidation timeout: 10000 msec (default), Action: Tear (default) AutoRoute: enabled LockDown: disabled Policy class: not set Forward class: 0 (not enabled) Forwarding-Adjacency: disabled Autoroute Destinations: 0 Loadshare: 0 equal loadshares Auto-bw: enabled Last BW Applied: 7 kbps CT0 BW Applications: 29 Last Application Trigger: Periodic Application Bandwidth Min/Max: 0-4294967295 kbps Application Frequency: 60 min Jitter: 0s Time Left: 46m 48s Collection Frequency: 5 min Samples Collected: 2 Next: 1m 3s Highest BW: 0 kbps Underflow BW: 0 kbps Adjustment Threshold: 10% 10 kbps Overflow Detection disabled Underflow Detection disabled Resignal Last-bandwidth Disabled Auto-Capacity: Disabled: Fast Reroute: Enabled, Protection Desired: Any Path Protection: Not Enabled BFD Fast Detection: Disabled Reoptimization after affinity failure: Enabled Soft Preemption: Disabled History: Tunnel has been up for: 7w6d (since Thu Nov 10 22:17:55 UTC 2022) Current LSP: Uptime: 15:09:12 (since Thu Jan 05 06:22:00 UTC 2023) Reopt. LSP: Last Failure: LSP not signalled, identical to the [CURRENT] LSP Date/Time: Thu Jan 05 19:03:33 UTC 2023 [02:27:39 ago] Prior LSP: ID: 32 Path Option: 10 Removal Trigger: reoptimization completed Path info (IS-IS 1 level-2): Node hop count: 3 Hop0: 172.16.61.79 Hop1: 172.16.57.244 Hop2: 172.16.6.59 Hop3: 10.38.96.1

Quando si passa al primo hop sul percorso, viene visualizzata la voce MPLS Label Forwarding Information Base (LFIB) corretta per questo tunnel:

```
#show mpls forwarding labels 27769 Fri Jan 6 06:13:04.220 UTC Local Outgoing Prefix Outgoing
Next Hop Bytes Label Label or ID Interface Switched -----
----- 27769 28136 TE: 5180 Hu0/10/0/11/2.4001 172.16.57.244 0
28136 TE: 5180 tt60409 point2point 0 (!)
```

L'interfaccia in uscita su questo nodo utilizza questo indirizzo MAC, quindi questo può essere utilizzato come indirizzo MAC di origine (SRC) nell'instestazione L2 per i frame L2:

```
#show interfaces hundredGigE 0/10/0/11/2.4001 Fri Jan 6 06:14:45.773 UTC
HundredGigE0/10/0/11/2.4001 is up, line protocol is up Interface state transitions: 79 Hardware
is VLAN sub-interface(s), address is 0c11.67c8.2041 Description: To
HundredGigE1/3/0/10/2.PHLAPALO-12121302A:CID:I1001/GE100/PHLAPALO/SLTNPAST Internet address is
172.16.57.245 MTU 9600 bytes, BW 100000000 Kbit (Max: 100000000 Kbit) reliability 255/255,
txload 0/255, rxload 0/255 Encapsulation 802.1Q Virtual LAN, VLAN Id 4001, loopback not set,
Last link flapped 1w6d ARP type ARPA, ARP timeout 04:00:00 Last input 00:00:00, output 00:00:00
Last clearing of "show interface" counters never 5 minute input rate 64000 bits/sec, 62
packets/sec 5 minute output rate 2198000 bits/sec, 699 packets/sec 4529877895 packets input,
2267795435148 bytes, 6 total input drops 0 drops for unrecognized upper-level protocol Received
124 broadcast packets, 0 multicast packets 3926978895 packets output, 1611587340639 bytes, 0
total output drops Output 0 broadcast packets, 0 multicast packets
```

Tuttavia, sul lato adiacente di **show capture packets into incoming location <VM LC attiva>, viene visualizzata l'etichetta MPLS corretta, ma gli indirizzi MAC L2 SRC e di destinazione (DST) sono completamente errati:**

```
[200] Jan 6 06:10:12.449, len: 103, hits: 1, buffhdr type: 1 i/p i/f: HundredGigE1/3/0/10/2 punt
reason: DROP_PACKET Ingress Headers: port_ifh: 0x8001ae4, sub_ifh: 0x0, bundle_ifh: 0x0
logical_port: 0x6c1, pd_pkt_type: 3 punt_reason: DROP_PACKET (0) payload_offset: 21, l3_offset:
21 FTMH: pkt_size: 0x7e, tc: 0, tm_act_type: 0, ssp: 0x981 PPH: pph_fwd_code: CPU Trap (7),
fwd_hdr_offset: 0 inlif: 0x0, vrf: 0x0, rif: 0x0 FHEI: trap_code: Rx_UNKNOWN_PACKET (63),
trap_qual: 193 [ether dst: 0000.0000.0000 src: 0c11.67c8.2000 type/len: 0x8847] [MPLS label:
28136, exp 0x6, eos 0, ttl 255]
```

L'indirizzo MAC DST è all-0 e l'indirizzo MAC SRC corrisponde all'interfaccia di gestione sul nodo NCS4K:

```
#show interfaces mgmtEth 0/rpl/emS/0 Fri Jan 6 06:15:59.141 UTC MgmtEth0/RP1/EMS/0 is down, line
protocol is down Interface state transitions: 0 Hardware is Management Ethernet, address is
0c11.67c8.2000 (bia 0c11.67c8.2000) Internet address is 10.230.192.86 MTU 1514 bytes, BW 100000
Kbit (Max: 100000 Kbit) reliability 255/255, txload 0/255, rxload 0/255 Encapsulation ARPA,
Full-duplex, 100Mb/s, unknown, link type is autonegotiation loopback not set, ARP type ARPA, ARP
```

timeout 04:00:00 Last input never, output never Last clearing of "show interface" counters never
5 minute input rate 0 bits/sec, 0 packets/sec 5 minute output rate 0 bits/sec, 0 packets/sec 0
packets input, 0 bytes, 0 total input drops 0 drops for unrecognized upper-level protocol
Received 0 broadcast packets, 0 multicast packets 0 runts, 0 giants, 0 throttles, 0 parity 0
input errors, 0 CRC, 0 frame, 0 overrun, 0 ignored, 0 abort 0 packets output, 0 bytes, 0 total
output drops Output 0 broadcast packets, 0 multicast packets 0 output errors, 0 underruns, 0
applique, 0 resets 0 output buffer failures, 0 output buffers swapped out 0 carrier transitions

Soluzione

La causa principale è la presenza di questo DTS - [ID bug Cisco CSCvz9253](#) [ID bug Cisco CSCwa11748](#) duplicato dell'[ID bug Cisco CSCvz9253](#) che è fissato nella release 6.5.32:

```
+++++++ Dec 23 23:24:58.214 ofa_ipnhgroup_event 0/LC1 3235382# t4839
TP3147224,dnxsdk_l3_fec_create,enter,trans_id,357633649,npu_id,0,is_modify,1,use_eei_encoding,0,
dest,0x6052,encap_id,0x4000304a,fec_id,0x2001fe98, Dec 23 15:10:16.787 ofa_ipnh_event 0/LC1
210586# t5614
TP2061,client_ipnh_create,grid_res_id_alloc_req_success,trans_id,357386085,encap_id,0x304a,alloc
_sz,2 Dec 23 15:10:16.787 ofa_ipnh_event 0/LC1 286920# t4857
TP9909,dispatch_ipnh,resolve_refhdl_success,ref_l3intf_trans_id,357386081,hdl,0x87a75238 Dec 23
15:10:16.787 ofa_ipnh_event 0/LC1 172418# t4857
TP9913,dummy_block,trans_id,357386085,wait,duration,time,0.1742 Dec 23 15:10:16.787
ofa_ipnh_event 0/LC1 153352# t4857
TP3149344,srv_ipnh_create,entry,trans_id,357386085,npu_mask,0x100000,l3a_mac_addr,00af.1f18.0043
,l3a_intf_id,28,port_id,0 Dec 23 15:10:16.780 ofa_ipnh_event 0/LC1 258284# t5614
TP2061,client_ipnh_create,grid_res_id_alloc_req_success,trans_id,357386077,encap_id,0x3048,alloc
_sz,2 Dec 23 15:10:16.780 ofa_ipnh_event 0/LC1 105614# t4857
TP9909,dispatch_ipnh,resolve_refhdl_success,ref_l3intf_trans_id,357383451,hdl,0x87a75238 Dec 23
15:10:16.780 ofa_ipnh_event 0/LC1 172408# t4857
TP9913,dummy_block,trans_id,357386077,wait,duration,time,0.1947 Dec 23 15:10:16.780
ofa_ipnh_event 0/LC1 286912# t4857
TP3149344,srv_ipnh_create,entry,trans_id,357386077,npu_mask,0x100000,l3a_mac_addr,00af.1f18.0043
,l3a_intf_id,28,port_id,0 +++++++
```

Come metodo di ripristino, è possibile riconfigurare l'interfaccia secondaria in uscita interessata.

Informazioni su questa traduzione

Cisco ha tradotto questo documento utilizzando una combinazione di tecnologie automatiche e umane per offrire ai nostri utenti in tutto il mondo contenuti di supporto nella propria lingua. Si noti che anche la migliore traduzione automatica non sarà mai accurata come quella fornita da un traduttore professionista. Cisco Systems, Inc. non si assume alcuna responsabilità per l'accuratezza di queste traduzioni e consiglia di consultare sempre il documento originale in inglese (disponibile al link fornito).