

Snort TCP Fast Open File Fingerprinting

Medium [Report](#) [ID](#) : cisco-snort-tfo-bypass-MmzZrtes

[CVE-2021-1224](#)

Published : 2021-01-13 16:00

Updated : 2021-05-20 13:27

Version : 1.2

CVSS : 5.8

Status : Yes

Cisco ID : [CSCvt43136](#) [CSCvu88532](#)

This advisory describes a vulnerability in Cisco Snort that allows an attacker to bypass TCP Fast Open (TFO) protection.

Description

Cisco Snort is a network security monitoring tool that includes support for TCP Fast Open (TFO). TFO is a mechanism that allows a client to establish a connection to a server without having to exchange the initial three-way handshake (SYN, SYN-ACK, ACK) by reusing a previously established connection's state information.

The vulnerability described in this advisory allows an attacker to bypass TFO protection, which can be exploited to perform Denial of Service (DoS) attacks or other malicious activities.

The vulnerability is caused by a bug in the way Snort handles certain types of TCP connections. Specifically, it fails to correctly handle connections that have been closed by the server but still have pending data from the client.

This issue has been assigned the identifier CVE-2021-1224. It is recommended that users of Cisco Snort update to the latest version to fix this vulnerability.

<https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-snort-tfo-bypass-MmzZrtes>

Impact

This vulnerability could allow an attacker to perform Denial of Service (DoS) attacks or other malicious activities.

The affected software is Cisco Snort, which is included in various Cisco products and services.

- 3000 Cisco Firepower Threat Defense (FTD) devices
- Firepower Threat Defense (FTD) 1.4% of devices
- Meraki MX64
- Meraki MX64W

- Meraki MX67
- Meraki MX67C
- Meraki MX67W
- Meraki MX68
- Meraki MX68CW
- Meraki MX68W
- Meraki MX84
- Meraki MX100
- Meraki MX250
- Meraki MX450

å...¬é-<æ™,ç,!ãšä€♦IOS XEç”“ã♦®Cisco UTD Snort

IPSä, “ãƒã,ãƒã,½ãf•ãf^ã,|ã,§ã,çã♦¾ã♦Ýã♦¬IOS XE SD-WANä,½ãf•ãf^ã,|ã,§ã,çç”“ã♦®Cisco

UTDä, “ãƒã,ãƒã♦®æœ€å^♦ã♦®ä¿®æ£æ,^ã♦¿ãf^ãf^ãf^ã,¹ã,^ã,§ã,,å‰♦ã♦®ãf^ãf^ãf^ã,¹ã,’å®

- 1000 ä,·ãf^ãf^ã,º ä,þf^ãf^ã,¹ç¶å♦^åž<ãf«ãf^ã,¿í¼^ISRI^¼‰
- 4000 ä,·ãf^ãf^ã,º ISR
- Catalyst 8000V ä,·ãffä,ä,½ãf•ãf^ã,|ã,§ã,ç
- Catalyst 8200 ä,·ãf^ãf^ã,º ä,·ãffä, ,ãf—ãf©ãffäf^ãf•ã,©ãf^ãf
- Catalyst 8300 ä,·ãf^ãf^ã,º ä,·ãffä, ,ãf—ãf©ãffäf^ãf•ã,©ãf^ãf
- Catalyst 8500Lä,·ãffä, ,ãf—ãf©ãffäf^ãf•ã,©ãf^ãf
- Cloud Services Router 1000V(CSR 1000V)
- ä,þf^ãf^ã,¹ç¶å♦^åž<ãä»®æ£^ãf«ãf^ã,¿í¼^ISRvi^¼‰

è,,†å¼±æ€§ä♦Œå~åœ”ã♦™ä,< Cisco

ä,½ãf•ãf^ã,|ã,§ã,çãf^ãf^ãf^ã,¹ã♦«ã♦¤ã♦,ã♦|ã♦¬ã€♦ã♦“ã♦®ã,çãf‰oãf♦ã,¤ã,¶ãf^ã♦®ã€æID ã♦®è©³ç’ºä,»ã,¬ã,·ãf§äf^ã,’å♦,ç..§ã♦—ã♦|ã♦¤ã♦ã♦ã♦•ã♦,,ã€,

å...¬é-<æ™,ç,!ãšä♦¬ã€♦ã♦“ã♦®è,,†å¼±æ€§ä♦¬ãf^ãf^ãf^ã,¹2.9.17ä,^ã,§ã‰♦ã♦®ã♦™ä♦¹ã♦

è,,†å¼±æ€§ä,’å♦«ã,“ã♦§ä♦,,ã♦¤ã♦,,ã♦“ã♦”ã♦”ã♦Œç¢è^ã♦¤ã♦•ã,Œã♦Ýè£½å”♦

ã♦“ã♦®ã,çãf‰oãf♦ã,¤ã,¶ãf^ã♦®è,,†å¼±æ€§ä♦®ã♦,ã,«è£½å”♦ã,»ã,¬ã,·ãf§äf^ã♦“è”“è¼‰ã♦¤ã

ã,·ã,¹ã,³ã♦¬ã€♦ã♦“ã♦®è,,†å¼±æ€§ä♦Œä»¥ä,«ã♦®ã,·ã,¹ã,³è£½å”♦ã♦“ã♦¬å½±éÝçã,’ä,žã♦^ã♦

- é♦®å¿œåž<ã,»ã,ãf¥ãf^ãftä,F ä,çãf—ãf©ã,¤ã,çãf^ã,¹í¼^ASAí¼‰oã,½ãf•ãf^ã,|ã,§ã,ç
- Catalyst 8500ä,·ãffä, ,ãf—ãf©ãffäf^ãf•ã,©ãf^ãf
- Firepower Management Centerí¼^FMCí¼‰oã,½ãf•ãf^ã,|ã,§ã,ç
- Meraki vMX100ä»®æf^ã,çãf—ãf©ã,¤ã,çãf^ã,¹
- Meraki Z1ä,çãf—ãf©ã,¤ã,çãf^ã,¹
- Meraki Z3ä,·ãf^ãf^ã,ºã,çãf—ãf©ã,¤ã,çãf^ã,¹

å>žé◆?¿ç-

„ä“ „ä“ ®å>žé „ç-ä“ - å°žå...¥ä•ä, €ä | ä Šä, Šä€ „äftä, ‚äfç“ åçfä „§ä“ - å®¥è ..¼æ, ^ä „ä Šä „

Cisco FTD 6.7.0

Cisco FTD, 1/2 af•af^a, |a, §a, c af^a af^a f^1/4 a, 16.7.0 → §a → → Snort

3è ”å®šã, ¨f—ã, ·ãf§ãƒã♦Œæœ‰åŠ¹ã«ã? ¨ã?Fã? | ã? „ã, <å? ^ã? ®å>žé? ¿ç-ã? ”ã? —ã? | ã€

æ¬;ä♦®æ‰é †ä,’ä½ç”“ ä♦—ä♦ | ä€♦Snort

3ã®è”å®šã, ªf—ã, ·ãf§ãf³ã®Œæœ‰oåŠ'ã«ã®ã®fã®|ã®,ã,ã®“ã®”ã, 'ç®èªã®—ã®¾/ã®™

[Firepower Threat Defense Configuration Guide for Firepower Device Manager, Version](#)

[6.7](#) Snort 2.0.0

Зă♦®ă^‡ă, Šăœ›;ă♦ ^ă€♦ă, »ă, -ă, ·ăf§ăf^ă, 'ă♦, ç...Şă♦—ă♦ | ă♦♦ă♦ ă♦•ă♦,,ă€,

1. FTDåŽå...¥ã®ç®¡ç‡†äf¢äf¼ä,¿äf«ä¢«äfä,°ä,¤äf³ä¢—ä¢¾ä¢™ä€,
 2. [Policies] > [Intrusion] ä¢«ç§»å«•ä¢—ä¢¾ä¢™ä€,
 3. äf†äf¼äf—äf«ä¢®ä,Šä¢«ä¢,ä,Snort

äf«äf¼äf«129:2ä,’æœ‰åŠ¹ä♦«ä♦™ä,<ä♦«ä♦-ä€♦æ¬;ä♦®æ‰œé†ä,’å®¥è;Œä♦—ä♦¾ä♦™ä€,è©³ç‘

[Firepower Threat Defense Configuration Guide for Firepower Device Manager, Version](#)

[6.7](#) Changing Intrusion Rule Actions (Snort)

3) ä€♦ä„»ä, -ä, ·äƒ§äƒ³ä,'å♦, ç...§ä♦—ä♦ | ä♦? ä♦? ä♦? ä♦? „ä€,

1. FTDå°Žå...¥ã®ç®;ç†äfãf%4ã,¿äf«ã«äfã,°ã,¤äf³ã—ã¾ã™ã€,
 2. [Policies] > [Intrusion] ä«ç§»å•ã—ã¾ã™ã€,
 3. [Balanced Security and Connectivity]
 ã³ã©ã®ã,·ã,¹ãftäf æ³/4ãfãfã,·ãf%4ã,'é,æŠžã—ã¾ã™ã€,
 4. äf«äf%4äf«**129:2**ã,æœç‘ä—ã¾ã™ã€,
 5. äf«äf%4äf«ã,æœ‰åŠ¹ã«ã™ã,<ã«ä—ã€äf«äf%4äf«ã®æ”“ã«ã,ã,<ãfã,§äffã,—äfœäff
 6. [Action] äf‰äfaffäf—äf€ã,¡äf³äfã,¹äf^ä<ã,%[Drop] ã,'é,æŠžã—ã¾ã™ã€,
 7. ä,çã,~ã,»ã,¹ã,³äf³äf^äf%4äf«äfãfã,·äf%4äf§ã€ä¾µå...¥ãfãfã,·ãf%4ã,'äf«äf%4äf«ã«è½åŠ

ä;®æ£æ, ^ä◊¿ä, ½äƒ•äƒ^ä, | ä, §ä, ¢

ä,½äf•äf^ä,|ä,§ä,cä♦®ä,çäffäf—ä,°äf¬äf¼äf%ä, ’æ¤œé·Žä♦™ä,<éš>ä♦«ä♦—ä€♦ä,·ä,¹ä,³

ã, »ã, ãƒ¥ãƒªãƒ†ã, £ ã, ¢ãƒ%oãƒ?ã, øã, ¶ãƒª

ãfšãf½ã, ã?§å...¥æ‰¤ã?§ã?¤ã,¹ã, ³è£½å“¤ã?¤®ã, çãf‰¤ã?¤ã, ¶ãf¤ã,'¤®šæœŸçš,,ã?¤«å?¤ç

ã,½ãfããf¥ãf¼ã,·ãf§ãf³ã,€å¼◆ã,'ççºèª?ã?—ã?|ã?/?ã?ã?•ã?„ã€,

ä {®æ£æ, ^ä ♦¿ ãƒªãƒªãƒ¼ã, ¹

å...¬é-<æ™,ç,¹ã¤§ã¤¬ã€¤ã¤“ã¤®è,,†å¼±æ€§ã¤®å½±éÝ¿ã,’å¤—ã¤’ã,<èƒ½å”¤ã¤«ã¤¤ã¤„ã¤|
ID

ã®è©³çº°ã, »ã, ¯ã, ·ãƒ§ãƒ³ã, 'å, ç...§ã—ã | ã ¯ã ã ã·ã „ã€, ã, ¨ãƒ¼ãƒ—ãƒ³ã, ½ãƒ¼ã, ªã®Snorta

1. 17.2.1 ä»¥é™ ã€Cisco IOS XE ãŠá, ã€³IOS XE SD-WAN ã€“åŒä~ã, ã€f;ãf½ã, ãf•ã;ã, ã€f«ã,'ä½;ç”“ã—ã€³/ã€™ã€,

ä, ♀æ£å^©ç"“ ä°<ä¾<ä? “ å...¬å¼♀ç™øèí”

Cisco Product Security Incident Response

Team 1/4 PSIR Ti 1/4% 0.9 ♀ - 9.6 ♀ 2.0% - 9. C 9. f% 0.9 f ♀ 9. g 9. 9. f a 9. ♀ « è .. ~ è 1/4% 0.9 ♀ . 9. C 9. ♀ ! 9. ♀ 9. ã è t 9. 1/4 + 2.0% 9. ♀

å†°å...

URL

<https://sec.cloudapps.cisco.com/security/center/content/CiscoSecurityAdvisory/cisco-sa-snort-tfo-bypass-MmzZrtes>

æ”’è..,å±¥æ’

ãf♦ãf¼ã,ãf§ã³	èª¬æ~Ž	
1.2	FTDã♦®äç®æ£æ,^ã♦¿ãfãfãf¼ã,¹æf...å±ã,'æ>'æ-°ã€, äç®æ£æ,^ã♦¿ã,½ãf·ã	
1.1	FTDã♦Šã,^ã♦³Snort 3ã♦®æf...å±ã,'è¿½åŠã€,Catalystè£½å"♦ã,'è¿½åŠã€,Cisco FTDãfãfãf¼ã,¹6.7.0ã♦®å>žé♦¿ç-ã,'è¿½åŠã€,	æ!,è!♦ã€♦è,,†å¼±æ€
1.0	å^♦å>žå...¬é-<ãfãfãf¼ã,¹	-

å^©ç”“è!♦?ç’,,

æœ¬ã,¢äf‰oãf♦ã,¤ã,¶äfªã♦¬ç,,¡ä¿♦è~¹/4ã♦®ã,,ã♦®ã♦~ã♦—ã♦!ã♦"æ♦♦ä¾ã♦—ã♦!ã♦|ã♦Šã,Šã€æœ¬ã,¢äf‰oãf♦ã,¤ã,¶äfªã♦®æf...å±ã♦Šã,^ã♦³ãfªãf³ã,¬ã♦®ä½¿ç~”ã♦«é-¢ã♦™ã,<è²¬ä»»ã♦®ä,€ã♦¾ã♦Ýã€♦ã,·ã,¹ã,³ã~”æœ¬ãf‰oã,ãf¥ãf;ãf³ãf~ã♦®å†...å®¹ã,'ä°~å'Šã♦~ã♦—ã♦«å¤‰oæ>`ã♦—ã♦æœ¬ã,¢äf‰oãf♦ã,¤ã,¶äfªã♦®è~”è¿°å†...å®¹ã♦«é-¢ã♦—ã♦!|æf...å±é...♦ä¿jã♦® URL
ã,'çœ?ç·¥ã♦—ã€♦å♦~ç<-ã♦®è»çè¹/4‰oã,,æ,,?è~³ã,'æ-½ã♦—ã♦Ýã'å♦^ã€♦å½"ç¤¾ã♦Œç®jç♦ã♦“ã♦®ãf‰oã,ãf¥ãf;ãf³ãf~ã♦®æf...å±ã♦~ã€♦ã,·ã,¹ã,³è£½å~”ã♦®ã,“ãf³ãf‰oãf`ãf½ã,¶ã,'å~¾è±;ã

翻訳について

シスコは世界中のユーザにそれぞれの言語でサポート コンテンツを提供するために、機械と人による翻訳を組み合わせて、本ドキュメントを翻訳しています。ただし、最高度の機械翻訳であっても、専門家による翻訳のような正確性は確保されません。シスコは、これら翻訳の正確性について法的責任を負いません。原典である英語版（リンクからアクセス可能）もあわせて参照することを推奨します。