

使用Bidir PIM配置對不通過FTD防火牆的組播流量進行故障排除

目錄

問題

可以看到以下所有症狀：

- 組播流量停止了特定組播組的防火牆威脅防禦(FTD)工作。
- FTD上沒有群組 (此範例中為224.2.2.2) 的多點傳送路由(mroute)。

```
<#root>
```

```
device#
```

```
show mroute 224.2.2.2
```


```
No mroute entries found.
```

```
device#
```

環境

- 在FTD 7.4版中首次出現。包括自適應安全裝置(ASA)在內的其他軟體版本也可能受到影響。
- 防火牆上啟用雙向通訊協定無關多點傳送(PIM)。

拓撲



inline_image_0.png

解析

步驟 1:檢視當前組播配置。

檢查網路路徑中所有裝置的現有組播路由配置，確定可能阻止組播流量通過防火牆的任何配置錯誤或缺少設定。

防火牆上有雙向PIM配置：

```
<#root>
```

```
device#
```

```
show run pim
```

```
pim rp-address 192.0.2.100 bidir
```

步驟 2:檢驗PIM鄰居。

確認防火牆上正確顯示了組播鄰居：

```
<#root>
```

```
device#
```

```
show pim neighbor
```

Neighbor Address	Interface	Uptime	Expires	DR	pri	Bidir
10.0.200.151	INSIDE	19:13:30	00:01:24	1	(DR)	
10.0.201.200	OUTSIDE	00:01:31	00:01:42	1	(DR)	

```
B
```

在輸出中，鄰居10.0.201.200具有Bidir B標誌，而10.0.200.151鄰居沒有。

步驟 3:為組播組224.2.2.2啟用PIM調試：

```
<#root>
```

```
FPR3100-14#
```

```
debug pim group 224.2.2.2
```

```
IPv4 PIM group debugging is on  
for group 224.2.2.2
```

調試顯示，存在因「no bidir df selection」而丟棄的PIM加入/修整資料包：

```
<#root>
```

```
IPv4 PIM: J/P entry: Join root: 192.0.2.100 group: 224.2.2.2 flags: RPT WC S  
IPv4 PIM: (*,224.2.2.2) J/P with RP 192.0.2.100 on INSIDE
```

```
discarded, no bidir df election-state on this intf
```

步驟 4:對10.0.200.151 PIM鄰居啟用PIM捕獲。目標是提高對資料包內容的可視性：

```
<#root>
```

```
device#
```

```
capture CAPI interface INSIDE trace match pim host 10.0.200.151 any
```

步驟 5:從FTD裝置收集防火牆擷取：

```
<#root>
```

```
device#
```


```
copy /pcap capture:CAPI CAPI.pcap
```

```
Source capture name [CAPI]?
Destination filename [CAPI.pcap]?
%Warning:There is a file already existing with this name
Do you want to over write? [confirm]
!
28 packets copied in 0.0 secs
```

使用<https://www.cisco.com/c/en/us/support/docs/security/firepower-ngfw/212474-working-with-firepower-threat-defense-f.html>中所述的步驟從FMC收集pcap檔案

步驟 6:捕獲分析。

PIM Hello資料包包含以下選項：



PIM_Hello_Options_no-bidir-capable.png

請注意沒有支援Bidir的標誌。

步驟 7:在10.0.200.151鄰居上啟用雙向PIM。

現在，將為兩個鄰居顯示PIM Bidir B標誌：

```
<#root>
```

```
device#
```


```
show pim neighbor
```

Neighbor Address	Interface	Uptime	Expires	DR	pri	Bidir
10.0.200.151	INSIDE	19:34:26	00:01:38	1	(DR)	

```
B
```

10.0.201.200	OUTSIDE	00:22:27	00:01:23	1	(DR)	B
--------------	---------	----------	----------	---	------	---

步驟 8:收集新捕獲並檢查鄰居10.0.200.151的PIM Hello選項。顯示PIM選項22 (雙向支援)：



```
77 2026/114 08:50:19.459952 5.000031 10.0.200.151 224.0.0.13 PIMv2 76 62 0x4f65 (20325) Hello
> Frame 77: 76 bytes on wire (608 bits), 76 bytes captured (608 bits)
> Ethernet II, Src: Cisco_71:ab:c0 (b8:38:61:71:ab:c0), Dst: IPv4mcast_0d (01:00:5e:00:00:0d)
> Internet Protocol Version 4, Src: 10.0.200.151, Dst: 224.0.0.13
v Protocol Independent Multicast
  0010 ... = Version: 2
  ... 0000 = Type: Hello (0)
  Reserved byte(s): 00
  Checksum: 0x6f8a [correct]
  [Checksum Status: Good]
  v PIM Options: 6
    > Option 1: Hold Time: 105
    > Option 20: Generation ID: 165045991
    > Option 22: Bidirectional Capable
    > Option 19: DR Priority: 1
    > Option 21: State-Refresh: Version = 1, Interval = 0s
    > Option 65004: RPF Proxy Vector (Cisco proprietary)
```

PIM_Hello_Options_option22.png

步驟 9:驗證組播組224.2.2.2的mroute現在是否顯示：

```
<#root>
```

device#

show mroute

Multicast Routing Table

Flags: D - Dense, S - Sparse, B - Bidir Group, s - SSM Group,
C - Connected, L - Local, I - Received Source Specific Host Report,
P - Pruned, R - RP-bit set, F - Register flag, T - SPT-bit set,
J - Join SPT

Timers: Uptime/Expires

Interface state: Interface, State

(* , 224.0.1.40), 19:41:44/never, RP 0.0.0.0, flags: DPC

Incoming interface: Null

RPF nbr: 0.0.0.0

Immediate Outgoing interface list:

INSIDE, Null, 19:41:44/never

(* , 224.2.2.2)

, 00:06:29/00:02:53, RP 192.0.2.100, flags: B

Bidir-Upstream: OUTSIDE


RPF nbr: 10.0.201.200

Immediate Outgoing interface list:

INSIDE, Forward, 00:06:29/00:02:53

原因

組播流量故障是由相鄰網路裝置上的不正確或不完整組播和雙向PIM配置引起的。特定組態問題導致FTD放棄特定多點傳送群組的PIM加入/修整訊息。因此，防火牆無法為組播流量建立mroute。對於要通過防火牆資料平面的組播資料流量，控制平面(PIM)必須建立正確的路由。



原因.png

相關內容

- <https://datatracker.ietf.org/doc/html/rfc5015#section-3.7.4>

關於此翻譯

思科已使用電腦和人工技術翻譯本文件，讓全世界的使用者能夠以自己的語言理解支援內容。請注意，即使是最佳機器翻譯，也不如專業譯者翻譯的內容準確。Cisco Systems, Inc. 對這些翻譯的準確度概不負責，並建議一律查看原始英文文件（提供連結）。