

Avaya Definity G3 Version CM2.0 to Cisco IOS Voice Gateway using H.323 with T1 DMS100

December 26, 2007

Table of Contents

Introduction	2
Limitations	3
System Components	3
Hardware requirements	
Software Requirements	
Features	
Features Supported	
Features Not Supported	4
Configuration	
Configuring Avaya Definity G3 Version CM 2.0	
Cisco 3825 configuration	
Acronyms	



Introduction

- This Application note provides basic call interoperability and documented steps and configurations necessary for H323 integration between Avaya Definity G3 Version CM 2.0 to Cisco IOS Voice Gateway providing PSTN connectivity via ISDN PRI T1 with DMS100 protocol.
- The H323 protocol is used between Cisco IOS Voice gateway and Avaya Definity G3 Version CM 2.0 The connection between Cisco IOS gateway and PSTN uses T1 PRI with DMS100 protocol.
- Features tested include Basic call, Call Transfer (blind, supervised), Call Forward (All, Busy and No Answer), Three-way Conference, DTMF tones, Caller ID functionality between Avaya Definity G3 Version CM 2.0 users and PSTN users.
- The Cisco IOS Voice Gateway offers the advantage of providing connectivity between Avaya Definity G3 Version CM 2.0 and PSTN by offering H323 to ISDN inter-working functionality.
- The network topology diagram (Figure 1) shows the test setup for end-to-end interoperability with the Cisco IOS Voice Gateway connected to the Ayaya Definity G3 Version CM 2.0 and connected to the PSTN via ISDN PRI T1 with DMS100 protocol.
- This Application Notes uses the C3825 IOS-voice-gateway, however other Cisco voice gateways are also an option to use since the voice gateway implementation does not depend on the platform. Below is a list of Cisco platforms capable of voice gateway functionality: Care must be taken when selecting a voice gateway platform depending on the capacity and capability required for the intended deployment.

Cisco 1861 Integrated Services Router

Cisco IAD2400 Series Integrated Access Device

Cisco 2800 Series Integrated Services Routers

Cisco 3700 Series Multi-service Access Routers

Cisco 3800 Series Integrated Services Routers

Cisco AS5350XM Universal Gateway

Cisco AS5400XM Universal Gateway



Network Topology




Figure 1. Network Topology

Limitations

- DTMF tones using RFC2833 feature does not interoperate due to signaling inconsistencies between the Avaya Definity CM2.0 PBX and the Cisco IOS Voice Gateway.
- Called name was not supported. Notify message with called name was mapped correctly. But, the display name information was dropped at the IOS Gateway.

System Components

Hardware requirements

- Cisco Hardware
 - Cisco 3825 Gateway



- DSP Mod. NM-HDV2-2T1/E1¹
- Cisco Cat 3550 Power Ethernet switch
- Avaya Definity CM Hardware
 - Avaya Definity G3 Version CM 2.0.

Software Requirements

- IOS Software releases: c3825-ipvoiceek9-mz.124-11.xj.bin
- PBX Software: Avaya Definity G3 Version CM 2.0

Features

Features Supported

- Calling Name Identification Restriction
- Calling Number Identification Restriction
- Codec G.711 ulaw
- Codec G.729
- Codec G.723
- Calling name
- Calling number
- Call Transfer blind
- Call Transfer Supervised
- Call Conference
- Call on-hold
- Call Forward No Reply
- Call Forward all
- Call Forward Busy
- DTMF tones using In-Band and Out-Of-Band (DTMF with H245 signaling) signaling
- Digit translation The voice gateway can modify the digits of the called digit number sent by Avaya Definity G3 Version CM 2.0 and PSTN

Features Not Supported

• DTMF tones using RFC2833


¹ G.723 Codec does not work with DSP module NM-HDV and work with NM-HDV2-2T1/E1.



Configuration


Configuring Avaya Definity G3 Version CM 2.0

Trunk Group





Trunk Group Cont'd




Trunk Group Cont'd






Trunk Group Cont'd




Signaling Group






Node Name IP




IP Network Region 1






IP Network Region cont'd




IP Codec Set 12




² Change Audio Codec to match with the IOS Media Gateway configuration when testing Codecs.



Station 2010 Configuration




Station Configuration cont'd






Station Configuration cont'd




Station Configuration cont'd






ARS Analysis 4



Route Pattern 91





Cisco 3825 configuration

Router#sh ver
Cisco IOS Software, 3800 Software (C3825-IPVOICEK9-M), Version 12.4(11)XJ, RELEA SE SOFTWARE (fc1)
Synched to technology version 12.4(11)T
Technical Support: http://www.cisco.com/techsupport
Copyright (c) 1986-2006 by Cisco Systems, Inc.
Compiled Fri 22-Dec-06 04:46 by prod_rel_team

ROM: System Bootstrap, Version 12.3(11r)T2, RELEASE SOFTWARE (fc1)

Router uptime is 3 weeks, 5 days, 22 hours, 36 minutes System returned to ROM by reload at 22:51:20 UTC Thu Dec 6 2007 System image file is "flash:c3825-ipvoicek9-mz.124-11.XJ.bin"

This product contains cryptographic features and is subject to United States and local country laws governing import, export, transfer and use. Delivery of Cisco cryptographic products does not imply third-party authority to import, export, distribute or use encryption. Importers, exporters, distributors and users are responsible for compliance with U.S. and local country laws. By using this product you agree to comply with applicable laws and regulations. If you are unable to comply with U.S. and local laws, return this product immediately.

A summary of U.S. laws governing Cisco cryptographic products may be found at: http://www.cisco.com/wwl/export/crypto/tool/stqrg.html

If you require further assistance please contact us by sending email to export@cisco.com.

Cisco 3825 (revision 1.0) with 226304K/35840K bytes of memory. Processor board ID FTX0946A1BV 2 Gigabit Ethernet interfaces 24 Serial interfaces 1 Channelized T1/PRI port 2 Voice FXO interfaces 2 Voice FXS interfaces DRAM configuration is 64 bits wide with parity enabled. 479K bytes of NVRAM. 62720K bytes of ATA System CompactFlash (Read/Write)

Configuration register is 0x2102

Router#sh run
Building configuration...

Current configuration: 2145 bytes!
version 12.4
service timestamps debug datetime msec
service timestamps log datetime msec
no service password-encryption!
hostname Router!
boot-start-marker
boot-end-marker



```
no logging buffered
no aaa new-model
no network-clock-participate slot 1
voice-card 0
no dspfarm
voice-card 1
dspfarm
ip cef
multilink bundle-name authenticated
isdn switch-type primary-dms100
voice service voip
h323
voice translation-rule 1<sup>3</sup>
rule 1 /41/ /20\1/
rule 2 /31477122/ /41\1/
voice translation-rule 2
rule 1 /40/ /22\1/
rule 2 /20/ /41\1/
voice translation-profile pots
translate calling 1
translate called 1
voice translation-profile voip
translate calling 2
translate called 2
```

³ The voice gateway manipulates the called and calling digits to match configured dial-peers and to route calls appropriately. For example: Digit manipulation rule 1 of voice translation rule 1 instructs IOS gateway that when it receives 41xx, IOS gateway is to strip 41, and add digit 20 as leading number to the remaining digits xx (xx in this case are either 10 or 12) and send them to the appropriate dial-peer.



```
!
archive
log config
 hidekeys
controller T1 1/0/0
framing esf
linecode b8zs
pri-group timeslots 1-24
vlan internal allocation policy ascending
interface GigabitEthernet0/0
ip address 172.20.192.102 255.255.255.0
duplex auto
speed auto
media-type rj45
no keepalive
interface GigabitEthernet0/1
no ip address
shutdown
duplex auto
speed auto
media-type rj45
no keepalive
interface Serial1/0/0:23
no ip address
encapsulation hdlc
isdn switch-type primary-dms100<sup>4</sup>
isdn protocol-emulate network
isdn incoming-voice voice
isdn supp-service name calling ie 40 cs 0
isdn channel-id invert extend-bit
no cdp enable
ip default-gateway 172.20.192.1
ip route 0.0.0.0 0.0.0.0 172.20.192.1
ip http server
no ip http secure-server
control-plane
```

⁴ Specify T1-ISDN interface.



```
voice-port 0/0/0
voice-port 0/0/1
voice-port 0/2/0
voice-port 0/2/1
voice-port 1/0/0:23
dial-peer voice 2210 pots<sup>5</sup>
translation-profile incoming pots
destination-pattern 22..
incoming called-number 41..
direct-inward-dial
port 1/0/0:23
forward-digits all
dial-peer voice 4100 voip<sup>6</sup>
description call in H323 voip
translation-profile incoming voip
destination-pattern 20..
session target ipv4:172.20.232.254
session transport tcp
incoming called-number 40..
dtmf-relay h245-alphanumeric h245-signal<sup>7</sup>
codec g711ulaw
!
line con 0
stopbits 1
line aux 0
stopbits 1
line vty 04
login
scheduler allocate 20000 1000
end
Router#
```

⁵ Dial-peer voice toward PSTN

⁶ Dial-peer voice toward PBX

⁷ Insert this command for DTMF using Out-Of-Band (DTMF with H245 signaling) signaling. This command specified the IOS gateway to transports DTMF tones generated after call establishment out of band using a standard H.245 out-of-band method.



Acronyms

Acronym	Definitions
Cisco IOS	Cisco Internetwork Operating System
PSTN	Public switched Telephone Network

Important Information

THE SPECIFICATIONS AND INFORMATION REGARDING THE PRODUCTS IN THIS MANUAL ARE SUBJECT TO CHANGE WITHOUT NOTICE. ALL STATEMENTS, INFORMATION, AND RECOMMENDATIONS IN THIS MANUAL ARE BELIEVED TO BE ACCURATE BUT ARE PRESENTED WITHOUT WARRANTY OF ANY KIND, EXPRESS OR IMPLIED. USERS MUST TAKE FULL RESPONSIBILITY FOR THEIR APPLICATION OF ANY PRODUCTS.

IN NO EVENT SHALL CISCO OR ITS SUPPLIERS BE LIABLE FOR ANY INDIRECT, SPECIAL, CONSEQUENTIAL, OR INCIDENTAL DAMAGES, INCLUDING, WITHOUT LIMITATION, LOST PROFITS OR LOSS OR DAMAGE TO DATA ARISING OUT OF THE USE OR INABILITY TO USE THIS MANUAL, EVEN IF CISCO OR ITS SUPPLIERS HAVE BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.





Corporate Headquarters

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706 USA

www.cisco.com Tel: 408 526-4000

800 553-NETS (6387) Fax: 408 526-4100

European Headquarters

Cisco Systems International

BV

Haarlerberg park Haarlerbergweg 13-19 1101 CH Amsterdam The Netherlands www-europe.cisco.com

Tel: 31 0 20 357 1000 Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc. 170 West Tasman Drive San Jose, CA 95134-1706

USA

www.cisco.com Tel: 408 526-7660 Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc. Capital Tower 168 Robinson Road #22-01 to #29-01 Singapore 068912 www.cisco.com Tel: +65 317 7777

Fax: +65 317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the Cisco Web site at www.cisco.com/go/offices.

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal • Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan • Thailand • Turkey Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe © 2007-2008 Cisco Systems, Inc. All rights reserved.

CCDE, CCENT, Cisco Eos, Cisco Lumin, Cisco StadiumVision, the Cisco logo, DCE, and Welcome to the Human Network are trademarks; Changing the Way We Work, Live, Play, and Learn is a service mark; and Access Registrar, Aironet, AsyncOS, Bringing the Meeting To You, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, CCSP, CCVP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Collaboration Without Limitation, EtherFast, EtherSwitch, Event Center, Fast Step, Follow Me Browsing, FormShare, GigaDrive, HomeLink, Internet Quotient, IOS, iPhone, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, iQuick Study, IronPort, the IronPort logo, LightStream, Linksys, MediaTone, MeetingPlace, MGX, Networkers, Networking Academy, Network Registrar, PCNow, PIX, PowerPanels, ProConnect, ScriptShare, SenderBase, SMARTnet, Spectrum Expert, StackWise, The Fastest Way to Increase Your Internet Quotient, TransPath, WebEx, and the WebEx logo are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0804R)

Printed in the USA