

# Compatible Systems Tech Notes: UDP Relays and the MR1000R

Document ID: 17660

---

**Introduction**  
**Prerequisites**  
    Requirements  
**Affected Products**  
**Affected Versions**  
**More Information**  
**Related Information**

---

## Introduction

Version 3.04 code of the MR1000R does not support UDP Relays. Interim code does support UDP Relays.

## Prerequisites

### Requirements

There are no specific requirements for this document.

## Affected Products

1000R

## Affected Versions

Specific Version v3.04

## More Information

The MR1000R does not support UDP Relays in code v3.04

This Interim code does:

- m10f3091.dld supports Frame Relay and UDP Relays
  - m10p3091.dld supports PPP connections and UDP Relays
- 

## Related Information

- **Technical Support & Documentation – Cisco Systems**
- 

All contents are Copyright © 2006–2007 Cisco Systems, Inc. All rights reserved. Important Notices and Privacy Statement.

