

Release Notes for Cisco WAP150 and WAP361 Firmware Version (1.0.1.7-1.0.0.16)

Contents

This document includes the following topics:

- Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points Firmware Version, 1.0.1.7, page 1
- Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points Firmware Version, 1.0.1.6, page 2
- Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points Firmware Version, 1.0.1.2, page 2
- Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points Firmware Version, 1.0.0.16, page 3
- Related Information, page 4

Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points Firmware Version, 1.0.1.7

October 2016

These release notes describe the known issues in the Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points firmware version 1.0.1.7.

Resolved Issues

The following issue has been fixed in the firmware version 1.0.1.7:

Corrected Japanese localization issue.

Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points Firmware Version, 1.0.1.6

September 2016

These release notes describe the known issues in the Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points firmware version 1.0.1.6.

New Features and Enhancements

Added Online Help for JP SKU

Resolved Issues

The following issues have been fixed in the firmware version 1.0.1.6

Ref Number	Description
CSCus33017	"Traffic Statistics" doesn't display statistic number for LAN Port 3/4 on WAP361.
CSCvb01402	Some egress packets from tagged VLAN are untagged.

Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points Firmware Version, 1.0.1.2

June 2016

These release notes describe the known issues in the Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points firmware version 1.0.1.2.

New Features and Enhancements

- Added Japanese support and localized GUI
- Upgraded OpenSSL to 1.0.2d and added TLSv1.2 support

Known Issues

The following table lists the known issues in firmware version 1.0.1.2:

Ref Number	Description
CSCus33017	"Traffic Statistics" doesn't display statistic number for LAN Port 3/4 (WAP361 ONLY). Workaround None.

Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points Firmware Version, 1.0.0.16

January 2016

These release notes describe the known issues in the Cisco WAP150 and WAP361 Wireless-N Dual Radio Access Points firmware version 1.0.0.16.

Known Issues

The following table lists the known issues in firmware version 1.0.1.2:

Ref Number	Description	
CSCus33017	"Traffic Statistics" doesn't display statistic number for LAN Port 3/4 (WAP361 ONLY).	
	Workaround None.	

Related Information

Support			
Cisco Support Community	www.cisco.com/go/smallbizsupport		
Cisco Support and Resources	www.cisco.com/go/smallbizhelp		
Phone Support Contacts	www.cisco.com/en/US/support/ tsd_cisco_small_business _support_center_contacts.html		
Cisco Firmware Downloads	www.cisco.com/go/smallbizfirmware Select a link to download firmware for Cisco Products. No login is required.		
Cisco Open Source Requests	www.cisco.com/go/ smallbiz_opensource_request		
Cisco Partner Central (Partner Login Required)	www.cisco.com/web/partners/sell/smb		
Product Documentation			
Cisco WAP150 and WAP361	www.cisco.com/go/100_wap_resources www.cisco.com/go/300_wap_resources		
Regulatory Compliance and Safety Information	www.cisco.com/en/US/docs/switches/lan/ csb_switching_general/rcsi/ Switch_ClassA_RCSI.pdf		
Warranty Information	www.cisco.com/go/warranty		

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: www.cisco.com/go/trademarks. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)

© 2020 Cisco Systems, Inc. All rights reserved.