



New and Changed ROMMON Features

This table summarizes the new and changed feature information for the *Cisco IOS XR ROM Monitor Guide for the Cisco XR 12000 Series Router*, and tells you where they are documented.

For a complete list of new and changed features in *Cisco IOS XR Software, Release 4.3.x*, see the [New and Changed Features in Cisco IOS XR Software, Release 4.3.x for Cisco XR 12000 Series Router](#) document.

- [New and Changed Features in ROMMON, page 1](#)

New and Changed Features in ROMMON

Feature	Description	Introduced/Changed in Release	Where Documented
Boothelper for PRP-2 cards	The version of boothelper for PRP-2 cards was updated to c12kprp-boot-mz.120-33.S11.	Release 4.3.1	<p><i>Router Recovery with ROM Monitor</i> chapter:</p> <ul style="list-style-type: none"> • Locating Installable Files • About Boothelper in Cisco XR 12000 Series Routers • Reinstalling to a Cisco XR 12000 Series Router from a TFTP Server Image <p><i>Upgrading and Downgrading ROM Monitor and Boothelper</i> chapter:</p> <ul style="list-style-type: none"> • Upgrading or Downgrading Boothelper

Feature	Description	Introduced/Changed in Release	Where Documented
ROMMON	ROMMON version updates	Release 4.3.0	<i>Upgrading and Downgrading ROM Monitor and Boothelper</i> chapter. Refer <i>Software/Firmware Compatibility Matrix</i> information at http://www.cisco.com/web/Cisco_IOS_XR_Software/index.html link, for details of minimum ROMMON requirements.