

# Cisco IP Conference Phone 7832 Release Notes for Firmware Release 14.2(1)SR1

---

# Contents

<b>Cisco IP Conference Phone 7832 Release Notes for Firmware Release 14.2(1)SR1</b> .....	3
<b>New and Changed Features</b> .....	3
<b>Features Available with the Firmware Release</b> .....	3
<b>Caveats</b> .....	3
<b>View Caveats</b> .....	3
<b>Cisco IP Phone Firmware Support Policy</b> .....	4

---

# Cisco IP Conference Phone 7832 Release Notes for Firmware Release 14.2(1)SR1

These release notes support the Cisco IP Phone 7832 running SIP Firmware Release 14.2(1)SR1.

## New and Changed Features

### Features Available with the Firmware Release

The following sections describe the features available with the Firmware Release.

#### Multi-server (SAN) Tomcat Certificate with Cisco UCM

Starting from this release, the phone supports Cisco UCM with Multi-server (SAN) Tomcat Certificates configured. The TFTP server address can still be found in the phone ITL file.

This feature requires:

- Cisco Unified Communication Manager Release: 14 or later

#### Where to Find More Information

- [How To Configure Multi-server \(SAN\) Tomcat certificate with Cisco UCM](#)
- [Security Guide for Cisco Unified Communications Manager Release 14 and SUs](#)
- [Cisco IP Conference Phone 7832 Administration Guide](#)

#### Localization Improvement on Enhanced Survivability

The feature Enhanced Survivability only applies to **Webex Calling Dedicated Instance**. Since from this release, the phone improves the localization support on this feature. The supported languages can be referred to [Cisco IP Phone 7800 Series Data Sheet](#).

#### Where to Find More Information

- [Enhanced Survivability for Webex Calling Dedicated Instance](#)

#### S6 Enhancement

- CSCuv46831 Improve NTP accuracy

## Caveats

### View Caveats

We report open and resolved customer-found bugs of severity 1 to 3. You can find details about listed bugs and search for other bugs by using the Cisco Bug Search Tool. For more info on using the Bug Search, see [Bug Search Tool Help](#).

- Use this URL for all caveats:

[https://bst.cloudapps.cisco.com/bugsearch/search?kw=\\*&pf=prdNm&pfVal=284883944&rls=14.2\(1\)SR1&sb=anfr&svr=3nH&bt=custV](https://bst.cloudapps.cisco.com/bugsearch/search?kw=*&pf=prdNm&pfVal=284883944&rls=14.2(1)SR1&sb=anfr&svr=3nH&bt=custV)

- 
- Use this URL for all open caveats:  
[https://bst.cloudapps.cisco.com/bugsearch/search?kw=\\*&pf=prdNm&pfVal=284883944&rls=14.2\(1\)SR1&sb=af&sts=open&svr=3nH&bt=custV](https://bst.cloudapps.cisco.com/bugsearch/search?kw=*&pf=prdNm&pfVal=284883944&rls=14.2(1)SR1&sb=af&sts=open&svr=3nH&bt=custV)
  - Use this URL for all resolved caveats:  
[https://bst.cloudapps.cisco.com/bugsearch/search?kw=\\*&pf=prdNm&pfVal=284883944&rls=14.2\(1\)SR1&sb=fr&svr=3nH&bt=custV](https://bst.cloudapps.cisco.com/bugsearch/search?kw=*&pf=prdNm&pfVal=284883944&rls=14.2(1)SR1&sb=fr&svr=3nH&bt=custV)

## Cisco IP Phone Firmware Support Policy

For information on the support policy for phones, see <https://cisco.com/go/phonefirmwaresupport>.

**Americas Headquarters**  
Cisco Systems, Inc.  
San Jose, CA

**Asia Pacific Headquarters**  
Cisco Systems (USA) Pte. Ltd.  
Singapore

**Europe Headquarters**  
Cisco Systems International BV Amsterdam,  
The Netherlands

Cisco has more than 200 offices worldwide. Addresses, phone numbers, and fax numbers are listed on the Cisco Website at <https://www.cisco.com/go/offices>.

Cisco and the Cisco logo are trademarks or registered trademarks of Cisco and/or its affiliates in the U.S. and other countries. To view a list of Cisco trademarks, go to this URL: <https://www.cisco.com/go/trademarks>. Third-party trademarks mentioned are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (1110R)