



Caveats Resolved for Release 12.1(5)YB4

July 2, 2001

Caveats describe unexpected behavior in Cisco IOS software releases. Severity 1 caveats are the most serious caveats, severity 2 caveats are less serious, and severity 3 caveats are the least serious of these three severity levels.

Caveats in Cisco IOS Releases 12.2 and 12.2 T are also in Cisco IOS “special” releases (such as Release 12.2(2)XH). For information on caveats in Cisco IOS Release 12.2, see *Caveats for Cisco IOS Release 12.2*. For information on caveats in Cisco IOS Release 12.2 T, see *Caveats for Cisco IOS Release 12.2 T*. These two documents list severity 1 and 2 caveats and are located on CCO and the Documentation CD-ROM.



Note

If you have an account with Cisco.com, you can use Bug Navigator II to find caveats of any severity for any release. To reach Bug Navigator II, **Login** to Cisco.com and click **Software Center: Cisco IOS Software: Cisco Bugtool Navigator II**. Another option is to go directly to <http://www.cisco.com/support/bugtools>.

Caveats Resolved in Release 12.1(5)YB4

This section describes possibly unexpected behavior by software Release 12.1(5)YB4.

CSCdt36204

Telnet not working through the tunnel using the VPN Module on 1700.

CSCdt03449

ISDN BRI callout results in VOICE ERROR when ALERTING is received.

CSCdt41384

Router Crash at CCBNET3_add_bchan.



Corporate Headquarters:
Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

Copyright © 2001. Cisco Systems, Inc. All rights reserved.

CSCdu12757

1750 crashes after configuring service-policy under ATM interface.

CSCds92106

Router hang after repeatedly power cycle.

CSCdu37345

AAA commands are not active for 811/813.

CSCdt57231

SSH SSH_MSG_IGNORE messages for terminal echo tests.

CSCdt93866

Unchecked limits in NTP.

CSCdt93862

Access level issue while using Web interface.

CSCdt46181

Redzone corruption in ptp_tcp_readf().

CSCdu04329

if_dslsar_rcv.c:possible deferencing NULL pointer.

CSCdt92629

Incorrect txbuffers calculation in if_dslsar_tx.c.

CSCdt78390

ADSL Phy retrains on an LOM defect condition.

CSCdt41633

Autoinstall not working.

CSCds59167

Transmt error seen while doing a sh run/version or write mem

CSCds90931

With 2 UBR and 1 VBR PVCs, reset ATM int, UBR PVC unable to transmit.

CSCdu38421

The 827 router crashes when unconfiguring the ATM/Dialer interface.

CSCdt67817

Not passing data well after change to higher profile from dslam side.

CSCdt11503

IOS crashes when large OID (>256 fields) is received.

CSCds56041

Chassis cardTable not populating.

CSCdt85979

PQUICC-1-TOOBIG:PQUICC(0/1), packet too big with WIC-1ASDL.

CSCds85371

Adding new crypto map instance causes all clear traffic to stop.

CSCds37028

Low performance-on GRE+IPSec /w HW enc card compared to IPSec direct.

CSCdu43931

sv3y image doesnt boot with 32MB DRAM and default 25% iomem config.

CSCdt96253

CRC-32 compensation vulnerability.

CSCds69577

Connectivity to some WEB sites is lost when router terminates PPPoE.

CSCdt96253

CRC-32 compensation vulnerability.

CSCdt11503

IOS crashes when large OID (>256 fields) is received.

CSCdt03962

ATM interface takes long time to get up.

CSCds69577

Connectivity to some WEB sites is lost when router terminates PPPoE.

CSCdt73791

No IPSEC traffic if PAT/NAT public addr are included in crypto ACLs.

AccessPath, AtmDirector, Browse with Me, CCDE, CCIP, CCSI, CD-PAC, *CiscoLink*, the Cisco NetWorks logo, the Cisco *Powered* Network logo, Cisco Systems Networking Academy, the Cisco Systems Networking Academy logo, Fast Step, Follow Me Browsing, FormShare, FrameShare, GigaStack, IGX, Internet Quotient, IP/VC, iQ Breakthrough, iQ Expertise, iQ FastTrack, the iQ Logo, iQ Net Readiness Scorecard, MGX, the Networkers logo, *Packet*, RateMUX, ScriptBuilder, ScriptShare, SlideCast, SMARTnet, TransPath, Unity, Voice LAN, Wavelength Router, and WebViewer are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, Discover All That's Possible, and Empowering the Internet Generation, are service marks of Cisco Systems, Inc.; and Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, the Cisco IOS logo, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Enterprise/Solver, EtherChannel, EtherSwitch, FastHub, FastSwitch, IOS, IP/TV, LightStream, MICA, Network Registrar, PIX, Post-Routing, Pre-Routing, Registrar, StrataView Plus, Stratm, SwitchProbe, TeleRouter, and VCO are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the U.S. and certain other countries.

All other trademarks mentioned in this document or Web site are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0105R)

Copyright © 2000–2001, Cisco Systems, Inc.
All rights reserved.