

# Release Notes for SR 520-T1

These Release Notes describe the known issues with the SR 520-T1.

This document includes the following topics:

- [Open Issues](#)
- [Resolved Issues](#)
- [Related Information](#)

## Open Issues

The following issues are known in Release 1.1:

- When Dynamic IP is selected on the T1 Wan IP Address Method page, the Static IP address may appear on the Apply Settings page. Ignore the setting summary and continue. The dynamic IP address function is not affected. (CSCtc21172).
- Not all possible files are shown in the Manage Flash Files page. Critical files are not displayed to protect from accidental file deletion. (CSCtc29242).
- After configuring the SR520-T1 using its setup wizard, the CCA may only show factory default settings for the SR520-T1. This is an issue on the CCA only and does not affect the operational behavior of the SR520-T1. (CSCta11419).

## Resolved Issues

The following issues are resolved with this release.

- For T1 PPP CHAP dynamic, the wizard failed to add the username to the configuration file. As the result, the CHAP authentication failed. (CSCta01870).
- If using the wizard to configure static PPP CHAP to applied and then reconfigure to negotiate ppp chap to applied, the configuration was invalid. (CSCta02302).
- The wizard failed to redefine the number of timeslots. (CSCta04932).
- IP negotiate PPP failed DNS name translation. (CSCta06914).
- The IP address found was unassigned when AMI Line Encoding was selected with IP negotiate PPP. (CSCta09438).
- On the Advance page of the wizard, one half of the T1 interface screen could not be scrolled down. (CSCta40514).
- Validation was needed when there was no entry for CHAP/PAP. (CSCta47278).
- All buttons were not disabled when “Apply and Test” was in progress. (CSCta47404).
- Specify the version number during upgrade. (CSCta75682).
- Apply Settings button should not get enabled if there was no change in the wizard. (CSCta96010).
- The configuration utility did not allow a user to enter a host IP address for static route configuration. (CSCtb20323).
- The configuration utility did not validate the entered value before allowing the user to submit. (CSCtb48647).
- Access list 100 blocked the local network. (CSCtb51121).
- The software upgrade process did not allow the hostname as part of the URL. (CSCtb58964).
- There was no provision for dynamic IP address for PPP encapsulation. (CSCtb87239).
- The Save & Reload button did not work when upgrading. (CSCtb98736).

- The PPP sub-panel did not display when entering the setup page. (CSCtb99035).
- The first page of the wizard displayed the default gateway when changed. (CSCtc06438).
- Static IP address did not check for valid IP address. (CSCtc06455).

## Related Information

Resource	Location
Product Documentation	<a href="http://www.cisco.com/go/sr500">www.cisco.com/go/sr500</a>
Customer Support	<a href="http://www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html">www.cisco.com/en/US/support/tsd_cisco_small_business_support_center_contacts.html</a>
Support Bugtool	<a href="http://www.cisco.com/cgi-bin/Support/Bugtool/launch_bugtool.pl">http://www.cisco.com/cgi-bin/Support/Bugtool/launch_bugtool.pl</a>
Warranty and End User License Agreement	<a href="http://www.cisco.com/go/warranty">www.cisco.com/go/warranty</a>
Cisco Partner Central site for Small Business	<a href="http://www.cisco.com/web/partners/sell/smb">www.cisco.com/web/partners/sell/smb</a>

Cisco, Cisco Systems, the Cisco logo, and the Cisco Systems logo are registered trademarks or trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries. All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0705R)

© 2009 Cisco Systems, Inc. All rights reserved.

**OL-20334-01**