

## Sercomm Corporation

WVC2300/PVC2300 Release Note for Linksys  
2008/07/31, version: V1.0.1

1. Remove VLAN ID 0 and 4095, which are reserved
2. Remove improper descriptions on GUI help files
3. String title on OCX warning message is being truncated.
4. Remove inappropriate description of NTP from help file.
5. IE will pop-up a warning message on PCs having sound card problems.
6. Stream server will stop streaming MPEG4 video.
7. Fix disconnection problem
8. Fix disconnection problem
9. "High/Low" is inverted on video quality setting
10. Fix bluish issue
11. Fix timestamp on frames to solve "too many users" problems
12. Enlarge buffer size to solve disconnection issue
13. VLC can't play 2300's video streaming (video + audio case).
14. Change a time zone "Caracas" from GMT-4:00 to GMT-4:30
15. Can't connect to WAP2000 with WPA mode.
16. Update timezones of Daylight saving.
17. Reject invalid email url: "@xxx".
18. Change Authentication: "Not Require" to "Not Required" in Web GUI
19. Enable UPnP discovery by default
20. Add "Both" option for QoS bug issue.
21. Fix RTCP handling on RTP over UDP.
22. Add Keep-alive mechanism on RTSP to detect connection status issue.
23. Quality value of MPEG4 and MJPEG doesn't follow up the SPEC. (sequence is reversed )
24. Fix bug on audio play under RTSP over HTTP.
25. CGIs on HTTP API SPEC will not be locked out.
26. Fix close handling in RTP.
27. Add DSCP value for QoS feature issue.
28. Can't connect to WAP2000 with WPA mode
29. Change company name to Linksys from Cisco in util/query.cgi
30. Can't play RTSP streaming on the internet
31. Fix Multicast Group Support
32. Change the G.726 bit rate from 16Kbps to 32Kbps.
33. Upgrading to newer FW will not cause camera restore to default configuration.
34. Prolong LAN detection time to 20 secs. Sercomm Corporation
35. Update Viewer OCX to version 2.0.0.16 to solve problems in IE7.
36. OCXs have digital signatures signed by Linksys.

- 37. Wireless couldn't set connections when users disabled broadcast SSID in AP
- 38. Fix "HTTP upgrade" to bootloader and update configuration file in case of firmware upgrade failure.
- 39. Time problem when Time zone is Central and daylight saving enabled
- 40. Fixed DMAPAPI 1.1 feature support

2007/07/30 V1.0.0R47

1. First Mass Production firmware  
Sercomm Corporation