



Information Relocated - Fax, Modem, and TDD Handling Feature Module

Revised: August 14, 2007

For the latest information on this Cisco BTS 10200 Softswitch feature, see:

Information	Link to Information in the Standard Documentation Set	Document Name
Description of feature, including supported modes	http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/feature/description/fd5010nf.html#wp1201237	<i>Network and Subscriber Feature Descriptions</i>
Modem and TDD fields descriptions in CDR	http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/billing/guide/bl_ApA50.html	<i>Billing Interface Guide</i>
Provisioning procedures for T.38 fax relay	T.38 Fax relay procedure - http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/command/guide/feature.html#wp836259 H.323 provisioning procedure - http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/protocol/guide/h323r50.html#wp1092823 SIP provisioning procedure - http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/protocol/guide/35trk.html#wp1045714	<i>5.0 Provisioning Guide</i>
Information for T.38 fax relay over H.323	http://www.cisco.com/en/US/docs/voice_ip_comm/bts/5.0/protocol/guide/h323r50.html#wp1177356	<i>H.323 Provisioning, Operating, and Troubleshooting Guide for the Cisco BTS 10200 Softswitch, Release 5.0</i>



Americas Headquarters:
Cisco Systems, Inc., 170 West Tasman Drive, San Jose, CA 95134-1706 USA

© 2007 Cisco Systems, Inc. All rights reserved.

