



Product Bulletin No. EOL5023

End-of-Sale and End-of-Life Announcement for the Cisco MDS 9000 SAN-OS Release 1.3(x)

Cisco Systems® announces the end-of-sale and end-of life dates for the Cisco MDS 9000 SAN-OS Release 1.3(x). The last day to order the affected product is March 2, 2007. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) as shown in Table 1 in EoL product bulletin. Table 1 describes the end-of-life milestones, definitions, and dates for the Cisco MDS 9000 SAN-OS Release 1.3(x). Table 2 lists the product part numbers affected by this announcement.

Table 1. End-of-Life Milestones and Dates for the Cisco MDS 9000 SAN-OS Release 1.3(x)

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	September 1, 2006
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	March 2, 2007
Last Ship Date: OS SW	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	May 31, 2007
End of Software Maintenance Releases Date: OS SW	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	March 1, 2008
End of Service Contract Renewal Date: OS SW	The last date to extend or renew a service contract for the product.	May 28, 2011
Last Date of Support: OS SW	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	February 29, 2012

HW = Hardware, OS SW = Operating System Software, App SW = Application Software

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
M91S1K9-1.3.1	MDS 9100 Supervisor/Fabric-I, Enterprise SW, Release 1.3.1	M91S1K9-3.0.2A	MDS 9100 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M91S1K9-1.3.2	MDS 9100 Supervisor/Fabric-I, Enterprise SW, Release 1.3.2	M91S1K9-3.0.2A	MDS 9100 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M91S1K9-1.3.3	MDS 9100 Supervisor/Fabric-I, Enterprise SW, Release 1.3.3	M91S1K9-3.0.2A	MDS 9100 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M91S1K9-1.3.3C	MDS 9100 Supervisor/Fabric-I, Enterprise SW, Release 1.3.3c	M91S1K9-3.0.2A	MDS 9100 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M91S1K9-1.3.4	MDS 9100 Supervisor/Fabric-I, Enterprise SW, Release 1.3.4	M91S1K9-3.0.2A	MDS 9100 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M91S1K9-1.3.5	MDS 9100 Supervisor/Fabric-I, Enterprise SW, Release 1.3.5	M91S1K9-3.0.2A	MDS 9100 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M92S1K9-1.3.1	MDS 9216 Supervisor/Fabric-I, Enterprise SW, Release 1.3.1	M92S1K9-3.0.2A	MDS 9200 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M92S1K9-1.3.2	MDS 9216 Supervisor/Fabric-I, Enterprise SW, Release 1.3.2	M92S1K9-3.0.2A	MDS 9200 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M92S1K9-1.3.3	MDS 9216 Supervisor/Fabric-I, Enterprise SW, Release 1.3.3	M92S1K9-3.0.2A	MDS 9200 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
M92S1K9-1.3.3C	MDS 9216 Supervisor/Fabric-I, Enterprise SW, Release 1.3.3c	M92S1K9-3.0.2A	MDS 9200 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M92S1K9-1.3.4	MDS 9216 Supervisor/Fabric-I, Enterprise SW, Release 1.3.4	M92S1K9-3.0.2A	MDS 9200 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M92S1K9-1.3.5	MDS 9216 Supervisor/Fabric-I, Enterprise SW, Release 1.3.5	M92S1K9-3.0.2A	MDS 9200 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M95S1K9-1.3.1	MDS 9500 Supervisor/Fabric-I, Enterprise SW, Release 1.3.1	M95S1K9-3.0.2A	MDS 9500 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M95S1K9-1.3.2	MDS 9500 Supervisor/Fabric-I, Enterprise SW, Release 1.3.2	M95S1K9-3.0.2A	MDS 9500 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M95S1K9-1.3.3	MDS 9500 Supervisor/Fabric-I, Enterprise SW, Release 1.3.3	M95S1K9-3.0.2A	MDS 9500 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M95S1K9-1.3.3C	MDS 9500 Supervisor/Fabric-I, Enterprise SW, Release 1.3.3c	M95S1K9-3.0.2A	MDS 9500 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M95S1K9-1.3.4	MDS 9500 Supervisor/Fabric-I, Enterprise SW, Release 1.3.4	M95S1K9-3.0.2A	MDS 9500 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a
M95S1K9-1.3.5	MDS 9500 Supervisor/Fabric-I, Enterprise SW, Release 1.3.5	M95S1K9-3.0.2A	MDS 9500 Supervisor/Fabric-I, SAN-OS Software Release 3.0.2a

PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco MDS 9000 SAN-OS Release 1.3(x) is the Cisco MDS 9000 SAN-OS Release 3.0(2a).

Customers are encouraged to migrate to the Cisco MDS 9000 SAN-OS Release 3.0(2a). Information about this product can be found at:

http://www.cisco.com/en/US/products/ps5989/prod_release_notes_list.html

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

Customers may be able to continue to purchase the end-of-sale product through Cisco's Authorized Refurbished Equipment program. Refurbished units of the end-of-sale product are available in limited supply for sale in certain countries on a first-come, first-served basis. For information about the refurbished equipment program, go to:

http://www.cisco.com/en/US/ordering/or6/or17/order_refurbished_equipment_high_level_listing.html

FOR MORE INFORMATION

For more information about the Cisco MDS 9000 SAN-OS Release 1.3(x), visit

http://www.cisco.com/en/US/products/hw/ps4159/ps4358/prod_eol_notices_list.html or contact your local account representative.

For more information about the Cisco End-of-Life Policy, go to: http://www.cisco.com/en/US/products/prod_end_of_life.html

To subscribe to receive end-of-life/end-of-sale information, go to: <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>



Corporate Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters
Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters
Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters
Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on the **Cisco.com Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus • Czech Republic
Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel • Italy
Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden
Switzerland • Taiwan • Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2006 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0601R)