



PRODUCT BULLETIN NO. 3113

END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO 1-PORT OC-48 POS LINE CARD FOR THE CISCO 7304 WITH SINGLE-MODE SHORT-REACH OPTICS

Cisco Systems® announces the end-of-sale and end-of-life dates for the Cisco® 1-Port OC-48 Packet over SONET/SDH (POS) Line Card for the Cisco 7304 with single-mode short-reach (SR) optics. The last day to order the affected product is June 30, 2006. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until June 30, 2011.

Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to the Cisco 1-Port OC-48 Packet over SONET/SDH (POS) Line Card for the Cisco 7304 with single-mode intermediate-reach (IR) optics. Table 3 provides relevant information for migrating to the replacement product.

Table 1. End-of-Life Milestones and Dates for Cisco 1-Port OC-48 Packet over SONET/SDH (POS) Line Card for the Cisco 7304 with Single-Mode Short-Reach (SR) Optics

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	September 30, 2005
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	June 30, 2006
Last Shipment Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	September 30, 2006
End of Software Maintenance Releases Date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	June 30, 2007
End of Routine Failure Analysis Date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	June 30, 2007
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	June 30, 2007
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product.	December 30, 2010
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	June 30, 2011

Table 2. Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
7300-1OC48POS-SMS	1-port OC-48 POS line card for Cisco 7304 with single-mode SR	7300-1OC48POS-SMI	1-port OC-48 POS line card for Cisco 7304 with single-mode IR
7300-1OC48POS-SMS=	1-port OC-48 POS line card for Cisco 7304 with single-mode SR, spare	7300-1OC48POS-SMI=	1-port OC-48 POS line card for Cisco 7304 with single-mode IR, spare

PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco 1-Port OC-48 POS Line Card for the Cisco 7304 with single-mode SR is the 1-Port OC-48 POS Line Card for the Cisco 7304 with single-mode IR (Table 3).

Table 3. Product Comparisons

Feature	Cisco 1-Port OC-48 POS Line Card for Cisco 7304 with Single-Mode SR	Cisco 1-Port OC-48 POS Line Card for Cisco 7304 with Single-Mode IR
Number of interface ports	1	1
Maximum Nominal Distance	1.2 mi (2km)	9 mi (15 km)
Loss Budget	0 to 7 dB	0 to 12 dB
Wavelength	1266nm to 1360 nm	1260nm to 1360 nm

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

FOR MORE INFORMATION

For more information about the Cisco 7304 routers, visit <http://www.cisco.com/en/US/products/hw/routers/ps352/index.html> or contact your local Cisco account representative.

For more information about the Cisco End-of-Life Policy, go to http://www.cisco.com/en/US/products/prod_end_of_life.html.

To subscribe to receive end-of-life/end-of-sale information, go to <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.

**Corporate Headquarters**

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-4000
800 553-NETS (6387)
Fax: 408 526-4100

European Headquarters

Cisco Systems International BV
Haarlerbergpark
Haarlerbergweg 13-19
1101 CH Amsterdam
The Netherlands
www-europe.cisco.com
Tel: 31 0 20 357 1000
Fax: 31 0 20 357 1100

Americas Headquarters

Cisco Systems, Inc.
170 West Tasman Drive
San Jose, CA 95134-1706
USA
www.cisco.com
Tel: 408 526-7660
Fax: 408 527-0883

Asia Pacific Headquarters

Cisco Systems, Inc.
168 Robinson Road
#28-01 Capital Tower
Singapore 068912
www.cisco.com
Tel: +65 6317 7777
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Website at www.cisco.com/go/offices.**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel
Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) 205388.BN_ETMG_CC_9.05

