



## END-OF-SALE AND END-OF-LIFE ANNOUNCEMENT FOR THE CISCO 4-PORT OC-3 POS LINE CARD FOR THE CISCO 7304 WITH SINGLE-MODE IR

Cisco Systems® announces the end-of-sale and end-of-life dates for the Cisco® 4-Port OC-3 Packet over SONET/SDH (POS) Line Card for the Cisco 7304 with single-mode intermediate reach (IR). The last day to order the affected product is April 30, 2006. Customers with active service contracts will continue to receive support from the Cisco Technical Assistance Center (TAC) until April 30, 2011. Table 1 describes the end-of-life milestones, definitions, and dates for the affected product. Table 2 lists the product part numbers affected by this announcement.

Customers are encouraged to migrate to the Cisco 4-port OC-3/STM-1 POS shared port adapters (SPAs), which provide investment protection, as well as higher interface densities and flexibility. Information about the replacement product can be found at [http://www.cisco.com/en/US/products/ps6267/prod\\_module\\_series\\_home.html](http://www.cisco.com/en/US/products/ps6267/prod_module_series_home.html). Table 3 provides relevant information for migrating to the replacement product.

**Table 1.** End-of-Life Milestones and Dates for Cisco 4-Port OC-3 POS Line Card for Cisco 7304 with Single-Mode IR

Milestone	Definition	Date
End-of-Life Announcement Date	The date the document that announces the end of sale and end of life of a product is distributed to the general public.	October 30, 2005
End-of-Sale Date	The last date to order the product through Cisco point-of-sale mechanisms. The product is no longer for sale after this date.	April 30, 2006
Last Shipment Date	The last-possible ship date that can be requested of Cisco and/or its contract manufacturers. Actual ship date is dependent on lead time.	July 30, 2006
End of Software Maintenance Releases Date	The last date that Cisco Engineering may release any final software maintenance releases or bug fixes. After this date, Cisco Engineering will no longer develop, repair, maintain, or test the product software.	April 30, 2007
End of Routine Failure Analysis Date	The last-possible date a routine failure analysis may be performed to determine the cause of product failure or defect.	April 30, 2007
End of New Service Attachment Date	For equipment and software that is not covered by a service-and-support contract, this is the last date to order a new service-and-support contract or add the equipment and/or software to an existing service-and-support contract.	April 30, 2007
End of Service Contract Renewal Date	The last date to extend or renew a service contract for the product.	October 30, 2010
Last Date of Support	The last date to receive service and support for the product. After this date, all support services for the product are unavailable, and the product becomes obsolete.	April 30, 2011

**Table 2.** Product Part Numbers Affected by This Announcement

End-of-Sale Product Part Number	Product Description	Replacement Product Part Number	Replacement Product Description
7300-4OC3POS-SMI	4-port OC-3 POS line card for Cisco 7304 with single-mode IR	SPA-4XOC3-POS	4-port OC-3/STM-1 POS SPA
7300-4OC3POS-SMI=	4-port OC-3 POS line card for Cisco 7304 with single-mode IR, spare	SPA-4XOC3-POS=	4-port OC-3/STM-1 POS SPA, spare

## PRODUCT MIGRATION OPTIONS

The recommended replacement for the Cisco 4-Port OC-3 POS Line Card for the Cisco 7304 with single-mode IR is the Cisco 4-Port OC-3/STM-1 POS SPA (Table 3). This SPA is available on high-end Cisco Systems routing platforms offering the benefits of network scalability with lower initial costs and ease of upgrades, and it is available with four Small Form-Factor Pluggable (SFP) interfaces. SFP modules are available in multiple optical reaches from 2 to 80 km. A single line-card slot on the Cisco 7304 can support two Cisco 4-port OC-3 POS SPAs, thus increasing the interface density.

**Table 3.** Product Comparisons

Feature	Cisco 4-Port OC-3 POS Line Card for Cisco 7304	Cisco 4-Port OC-3/STM-1 POS SPA
Number of interface ports	4	4
Number of line cards per chassis slot	1	2
Support for SFP interfaces	No	Yes

Customers can use the Cisco Technology Migration Plan (TMP) to trade in products and receive credit toward the purchase of new Cisco equipment. For more information about Cisco TMP, go to: <http://www.cisco.com/go/tradein/>. The Cisco TMP application requires all users to have a Cisco.com user ID.

## FOR MORE INFORMATION

For more information about the Cisco 7304 routers, visit <http://www.cisco.com/en/US/products/hw/routers/ps352/index.html> or contact your local Cisco account representative.

For more information about the Cisco End-of-Life Policy, go to [http://www.cisco.com/en/US/products/prod\\_end\\_of\\_life.html](http://www.cisco.com/en/US/products/prod_end_of_life.html).

To subscribe to receive end-of-life/end-of-sale information, go to <http://www.cisco.com/cgi-bin/Support/FieldNoticeTool/field-notice>.

**Corporate Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-4000  
800 553-NETS (6387)  
Fax: 408 526-4100

**European Headquarters**

Cisco Systems International BV  
Haarlerbergpark  
Haarlerbergweg 13-19  
1101 CH Amsterdam  
The Netherlands  
www-europe.cisco.com  
Tel: 31 0 20 357 1000  
Fax: 31 0 20 357 1100

**Americas Headquarters**

Cisco Systems, Inc.  
170 West Tasman Drive  
San Jose, CA 95134-1706  
USA  
www.cisco.com  
Tel: 408 526-7660  
Fax: 408 527-0883

**Asia Pacific Headquarters**

Cisco Systems, Inc.  
168 Robinson Road  
#28-01 Capital Tower  
Singapore 068912  
www.cisco.com  
Tel: +65 6317 7777  
Fax: +65 6317 7799

Cisco Systems has more than 200 offices in the following countries and regions. Addresses, phone numbers, and fax numbers are listed on **the Cisco Website at [www.cisco.com/go/offices](http://www.cisco.com/go/offices).**

Argentina • Australia • Austria • Belgium • Brazil • Bulgaria • Canada • Chile • China PRC • Colombia • Costa Rica • Croatia • Cyprus  
Czech Republic • Denmark • Dubai, UAE • Finland • France • Germany • Greece • Hong Kong SAR • Hungary • India • Indonesia • Ireland • Israel  
Italy • Japan • Korea • Luxembourg • Malaysia • Mexico • The Netherlands • New Zealand • Norway • Peru • Philippines • Poland • Portugal  
Puerto Rico • Romania • Russia • Saudi Arabia • Scotland • Singapore • Slovakia • Slovenia • South Africa • Spain • Sweden • Switzerland • Taiwan  
Thailand • Turkey • Ukraine • United Kingdom • United States • Venezuela • Vietnam • Zimbabwe

Copyright © 2005 Cisco Systems, Inc. All rights reserved. CCSP, CCVP, the Cisco Square Bridge logo, Follow Me Browsing, and StackWise are trademarks of Cisco Systems, Inc.; Changing the Way We Work, Live, Play, and Learn, and iQuick Study are service marks of Cisco Systems, Inc.; and Access Registrar, Aironet, ASIST, BPX, Catalyst, CCDA, CCDP, CCIE, CCIP, CCNA, CCNP, Cisco, the Cisco Certified Internetwork Expert logo, Cisco IOS, Cisco Press, Cisco Systems, Cisco Systems Capital, the Cisco Systems logo, Cisco Unity, Empowering the Internet Generation, Enterprise/Solver, EtherChannel, EtherFast, EtherSwitch, Fast Step, FormShare, GigaDrive, GigaStack, HomeLink, Internet Quotient, IOS, IP/TV, iQ Expertise, the iQ logo, iQ Net Readiness Scorecard, LightStream, Linksys, MeetingPlace, MGX, the Networkers logo, Networking Academy, Network Registrar, Packet, PIX, Post-Routing, Pre-Routing, ProConnect, RateMUX, ScriptShare, SlideCast, SMARTnet, StrataView Plus, TeleRouter, The Fastest Way to Increase Your Internet Quotient, and TransPath are registered trademarks of Cisco Systems, Inc. and/or its affiliates in the United States and certain other countries.

All other trademarks mentioned in this document or Website are the property of their respective owners. The use of the word partner does not imply a partnership relationship between Cisco and any other company. (0502R) 205290.BS\_ETMG\_CC\_7.05

